NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: [| | | | |] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	I L D R S 2 (2)	0 0 - 0 0 0 0 0 - 0 0 (3)	4 1 1 1 1 (4)	(5)
	LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT

CON'T

0 1	REPORT SOURCE	L (6)	0 5 0 0 0 2 3 7 (7)	1 2 1 7 7 8 (8)	0 1 1 6 7 9 (9)
			DOCKET NUMBER	EVENT DATE	REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation while attempting to put the drywell continuous air monitor
0 3 into service it was discovered that the inboard isolation valve A.O. 2-9207A would
0 4 not close. As required by T.S. Sec 3.7.D.2 the outboard isolation valve was operable
0 5 and closed. This event had minimal safety significance because the line was isola-
0 6 ted by the operable outboard isolation valve. This type of event has occurred before
0 7 at Dresden (R.O. 78-15/03L-0).
0 8

0 9	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
	P B (11)	E (12)	B (13)	V A L V O P (14)	E (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	7 8	—	0 6 7	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
D (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	X (25)	A 4 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Upon investigation of the valve the Asco solenoid valve (CAT #830282 RF) was found to
1 1 be sticking. The cause of the failure was determined to be dirty parts and a small
1 2 amount of water in the valve. The solenoid valve was rebuilt and the valve operated
1 3 satisfactorily.
1 4

1 5	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
	E (28)	0 9 5 (29)	NA	A (31)	Operator Observation

1 6	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

1 7	NUMBER	TYPE	DESCRIPTION (39)
	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

1 8	NUMBER	DESCRIPTION (41)
	0 0 0 (40)	NA

7901230203

LOSS OF OR DAMAGE TO FACILITY (43)

1 9	TYPE	DESCRIPTION
	Z (42)	NA

PUBLICITY

2 0	ISSUED	DESCRIPTION (45)	NRC USE ONLY
	N (44)	NA	

NAME OF PREPARER: M. Korchynsky PHONE: X-422

GPO 917-926