OFFICE OF INSPECTION AND ENFORCEMENT
B&W SITE INSPECTOR DAILY REPORT

Date 4/11/79

Site Crystal River

Inspector(s) McHenry
McDonald

General Plant Status: Plant operating at 75% power with one RCP shutdown due to excessive seal leakage.

a. Review of Similar Transients (Item 2 of IEB 79-05A):

Licensee response to IEB 79-05A expected to be transmitted 4/11/79.

b. Review and Revision of Operating and Maintenance Procedures (Items 3, 4, 5, 7, 8, 9, 10 of IEB 79-05A):

See item 1a.

c. Review and Implementation of Changes in Containment Isolation (Item 6 IEB 79-05A):

See item 1a.

d. Training of Plant Personnel (Items 1, 4, 11 and plant/procedures changes):

See item 1a.

POOR ORIGINAL

7906290099

2. SUMMARY OF NRC INSPECTION ACTIVITY DURING PERIOD 4/10/79
(Address items 1.a thru 2.d above, give other independent/significant effort, identify shifts on which activity was done during past 24 hours)

a. Inspection of control room operation completed on all shifts.

b. Walkdown of both trains of emergency FW completed to verify correct position of system valves, breakers, and switches. No problem identified.

c. Reviewed emergency auxiliary FW alignments procedure with system design drawing. Minor checklist discrepancies were noted and identified to licensee.

d. Reviewed licensee response to items 2 (transients) and 3 (procedures) of IEB 79-05A.

3. STATUS OF INSPECTOR DISCUSSIONS WITH PLANT PERSONNEL:

a. Have briefed 39 of 41 shift operating personnel (includes some nonlicensed personnel). Arrangements to brief day personnel to be setup week of 4/16.

4. DESCRIPTION OF GENERAL PLANT STATUS (i.e., operating power level, planned changes, scheduled outages, ESF out of service, major maintenance, reportable occurrences, etc.).

Plant operating at 75% with one RCP shutdown due to excessive seal leakage. Seal leakage is constant.

Motor operator on inside containment purge valve is inoperable. Valve is closed. Repair in progress. No purge activity while this is in progress.

POOR ORIGINAL