Reactor Facilities

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

APR 1 1976

Metropolitan Edison Company
Attention: Mr. R. C. Arnold
Vice President
P. O. Box 542
Reading, Pennsylvania 19603

License No. DPR-50
Inspection No. 76-01
Docket No. 50-289

Reference: Your letter dated March 22, 1976 and telephone conversation between Mr. Lawyer and Mr. Spessard on March 25, 1976, In response to our letter dated February 27, 1976.

Gentlemen:

Thank you for informing us of the corrective and preventive actions you documented in response to our correspondence. It is our understanding, based on the referenced telephone conversation, that in addition to the Preventive Actions specified in your response, the Manager Operational Quality Assurance will review all TMI-1 inspection reports to ascertain any violations of technical specifications and license requirements delineated therein, and that he will refer all of those so identified to the GORB for their review. These actions will be examined during a subsequent inspection of your licensed program.

Your cooperation with us is appreciated.

Sincerely,

Eldon J. Brunner, Chief
Reactor Operations and Nuclear
Support Branch

cc: J. G. Herbein, Manager, Generation Operations - Nuclear
R. W. Heward, Project Manager, GPUSC
Miss Mary V. Southard, Chairman, Citizens for a Safe Environment

bcc:
IE Mail & Files (For Appropriate Distribution)
PDR
Local PDR
NSIC
TIC
REG:I Reading Room
State of Pennsylvania
J. Sniezek

1413 294

7910150 454 454