UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

26 JAN 1979

Docket No. 99900349/78-01

Corner and Lada Company, Inc.
Attn: Mr. R. W. Rogers
Manager, Quality Assurance
1341 Elmwood Avenue
Cranston, RI 02910

Gentlemen:

Thank you for your letter of January 6, 1979, in response to our letter dated December 6, 1978. As a result of our review, we find that additional information, as discussed with you during a telephone call on January 24, 1979, is needed. Specifically, for items A., B.1., B.2., B.3., J.1., and J.2., corrective actions were not addressed regarding the specifics of the documented deviations. For items H. and I., although you have stated your corrective actions, you have not identified steps taken to prevent recurrence nor the date these steps will be implemented.

In addition, please identify the way in which the stated training sessions of November 20, 26, and 27, 1978, were documented, to provide a record of your corrective actions.

Please provide this additional information within twenty (20) days in order that we may complete our review.

Sincerely,

Uldis Potapovs

Uldis Potapovs, Chief
Vendor Inspection Branch

7903210343