NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | CTMNS2 (2) | 00-0000-00 (3) | 4 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 05000336 (7) | 022879 (8) | 021280 (9)
DOCKET NUMBER (61–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Following a scheduled surveillance on the control room chlorine detection systems, both
03 systems were declared inoperable when the detectors failed calibration procedures. The
04 control room emergency ventilation system was immediately placed in the recirculation
05 mode of operation in accordance with Technical Specification Section 3.3.3.6, Action
06 Statement b. Following recalibration, the detectors were returned to service and
07 control room ventilation restored to normal.
08

09 SYSTEM CODE: IF (11) | CAUSE CODE: X (12) | CAUSE SUBCODE: Z (13) | COMPONENT CODE: ZZZZZZ (14) | COMP. SUBCODE: Z (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 79 (21–22) | — (23) | SEQUENTIAL REPORT NO. 007 (24–26) | / (27) | OCCURRENCE CODE 03 (28–29) | REPORT TYPE X (30) | — (31) | REVISION NO. 1 (32)

ACTION TAKEN: E (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS: 0000 (22) | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: Z (25) | COMPONENT MANUFACTURER: Z999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Inaccurate calibration gas caused inaccurate detector calibration. The gas sample
11 container was returned to the vendor for analysis to determine the cause of
12 inaccuracy but the sample container was lost and analysis was never performed. All
13 subsequent calibrations have proven satisfactory.
14

15 FACILITY STATUS: E (28) | % POWER: 100 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Operator Surveillance

16 ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39): NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41): NA

19 LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION (43): NA

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45): NA

8002150 352

NRC USE ONLY

P. W. Rates — 203 447 1701 Ext. 572

PO 91 7-926