NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| 0 1 | N C B E P 1 (2) LICENSEE CODE | 0 0 - 0 0 0 0 0 - 0 0 (3) LICENSE NUMBER | 4 1 1 1 1 (4) LICENSE TYPE | (5) CAT |

CON'T 0 1 REPORT SOURCE L (6) 0 5 0 - 0 3 2 5 (7) DOCKET NUMBER 0 1 2 1 8 0 (8) EVENT DATE 0 2 1 2 8 0 (9) REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While attempting to run the HPCI auxiliary oil pump for its daily 10 minute run,

0 3 the pump would not continue running when the switch was moved from the "start"

0 4 position to the "auto" position. This makes the HPCI System inoperable.

0 5

0 6

0 7

0 8 Technical Specifications 3.5.1, 6.9.1.9b

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	S F (11)	E (12)	A (13)	I N S T R U (14)	S (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
8 0	—	0 1 1	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
B (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	N (25)	G 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A loose wire was found on the RTGB control switch for the auxiliary pump. The

1 1 wire was reattached and tightened, all other wiring connections on the switch were

1 2 checked (no problems were found), and the pump was successfully run. This is

1 3 considered an isolated event and no further action is required.

1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	E (28)	0 9 7 (29)	N/A	B (31)	Periodic Test

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	N/A

POOR ORIGINAL

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	N/A

PUBLICITY

	ISSUED	DESCRIPTION (45)
2 0	N (44)	N/A

8002200 433

NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr. PHONE: (919) 457-9521