NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 CARSS 1 (2) 00-00000-00 (3) 4 1 1 1 1 (4) (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 REPORT SOURCE L (6) 0 5 0 0 0 3 1 2 (7) 0 1 1 7 8 0 (8) 0 2 1 4 8 0 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On 1-17-80, with the reactor in a CSD condition for the refueling outage,
03 leakage was observed from the outboard seal of the "A" DHR pump, P-261A.
04 The leakage estimated at ~3 gpm was in excess of the 0.63 gph allowed per
05 T.S. Section 4.5.3.1. The "B" DHR system was started to provide RCS recir-
06 culation and the "A" pump was removed from service. Similar seal failures
07 were reported via LER's 76-13, 78-07, and 79-08.
08

09 SYSTEM CODE: CF (11) — CAUSE CODE: E (12) — CAUSE SUBCODE: B (13) — COMPONENT CODE: PUMPXX (14) — COMP. SUBCODE: B (15) — VALVE SUBCODE: Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 80 — SEQUENTIAL REPORT NO. 005 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN: A (18) — FUTURE ACTION: X (19) — EFFECT ON PLANT: Z (20) — SHUTDOWN METHOD: Z (21) — HOURS (22): 0000 — ATTACHMENT SUBMITTED: Y (23) — NPRD-4 FORM SUB: Y (24) — PRIME COMP. SUPPLIER: A (25) — COMPONENT MANUFACTURER: B010 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Upon receipt of a replacement seal, the seal was replaced. Following
11 replacement of the seal, the system was tested per the applicable surveil-
12 lance test. The test results were acceptable and the system declared
13 operable. District engineers are in contact with the seal manufacturer
14 engineers for recommendations to improve the longevity of the seals.

15 FACILITY STATUS: H (28) — % POWER: 000 (29) — OTHER STATUS (30): N/A — METHOD OF DISCOVERY: A (31) — DISCOVERY DESCRIPTION (32): Operator observation

16 ACTIVITY RELEASED: Z (33) — CONTENT OF RELEASE: Z (34) — AMOUNT OF ACTIVITY (35): N/A — LOCATION OF RELEASE (36): N/A

PERSONNEL EXPOSURES
17 NUMBER: 000 (37) — TYPE: Z (38) — DESCRIPTION (39): N/A

POOR ORIGINAL

PERSONNEL INJURIES
18 NUMBER: 000 (40) — DESCRIPTION (41): N/A

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE: Z (42) — DESCRIPTION: N/A

8002250 553

PUBLICITY
20 ISSUED: Y (44) — DESCRIPTION (45): Local newspapers and wire services on 2/14/80 — NRC USE ONLY

NAME OF PREPARER R. W. Colombo — PHONE 916-452-3211