NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 LICENSEE CODE: I L Z I S 2 (2) LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) LICENSE TYPE: 4 1 1 1 1 (4) CAT (5)

CON'T 01 REPORT SOURCE: L (6) DOCKET NUMBER: 0 5 0 0 0 3 0 4 (7) EVENT DATE: 1 1 1 4 7 8 (8) REPORT DATE: 1 2 1 4 7 8 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During surveillance level XMTRS 2 LT-956 and -957 were found out of tolerance
03 low by -4.4 and -4.9 percent respectively in their operating range. This
04 could have resulted in a maximum of 2.23 Cu.Ft. above license limit in
05 accumulator 2B. When discovered, actual levels were within license limit.
06 Accumulator 2A XMTRS were also found out of tolerance low. (LER-304/78-73).
07 However, no event requiring injection occurred so the Health and Safety of
08 the Public was not affected. Previous LER (50-295/78-110)

09 SYSTEM CODE: I B (11) CAUSE CODE: E (12) CAUSE SUBCODE: E (13) COMPONENT CODE: I N S T R U (14) COMP. SUBCODE: E (15) VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR: 7 8 — SEQUENTIAL REPORT NO.: 0 7 4 / OCCURRENCE CODE: 0 3 REPORT TYPE: L — REVISION NO.: 0

ACTION TAKEN: E (18) FUTURE ACTION: X (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS (22): 0 0 0 0 0 ATTACHMENT SUBMITTED: N (23) NPRD-4 FORM SUB.: Y (24) PRIME COMP. SUPPLIER: L (25) COMPONENT MANUFACTURER: M 0 4 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Magnetrol series 82 XMTRS out of tol. due to instrument drift. XMTRS
11 were recalibrated.An investigation is being conducted to determine if
12 present calibration interval is adequate. Data is being compiled on
13 min. sensitivity of electronics and capacitance of probe to ensure
14 stability of both. No further action is required.

15 FACILITY STATUS: E (28) % POWER: 1 0 0 (29) OTHER STATUS (30): NA METHOD OF DISCOVERY: (31) DISCOVERY DESCRIPTION (32): Surveillance

16 ACTIVITY RELEASED: Z (33) CONTENT OF RELEASE: Z (34) AMOUNT OF ACTIVITY (35): NA LOCATION OF RELEASE (36): NA

17 PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION (39): NA

18 PERSONNEL INJURIES NUMBER: 0 0 0 (40) DESCRIPTION (41): NA

19 LOSS OF OR DAMAGE TO FACILITY (43) TYPE: Z (42) DESCRIPTION: NA

20 PUBLICITY ISSUED: N (44) DESCRIPTION (45): NA

790104 0137

NRC USE ONLY

NAME OF PREPARER: John Campbell PHONE: Ext. 244 746-2084