(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N C B E P 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 - 0 3 2 5 (7) | 0 2 1 2 8 0 (8) | 0 3 1 0 8 0 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal full power operation, the control operator received upscale downscale,
03 inoperable, and rod block alarms on Rod Block Monitor "A." No evolutions or testing
04 were in progress at the time.
05
06
07
08 Technical Specifications 3.1.4.3, 6.9.1.9b

09 | SYSTEM CODE R B (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE P (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 8 0 | — | SEQUENTIAL REPORT NO. 0 2 6 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A blown fuse was found in the 28 VDC power supply. The fuse was replaced and the
11 28 VDC power supply was closely monitored for three days, with proper operation
12 observed. No problem could be discovered. Blown fuses on this equipment has not
13 been a problem in the past. This is considered an isolated event and no further
14 action is required.

15 | FACILITY STATUS E (28) | % POWER 0 9 9 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Surveillance

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES
17 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES
18 | NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY (43)
19 | TYPE Z (42) | DESCRIPTION N/A

PUBLICITY
20 | ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr. PHONE: (919) 457-9521

8003180395

GPO 917-926