NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N C B E P 2 (2)	0 0 - 0 0 0 0 0 - 0 0 (3)	4 1 1 1 1 (4)		(5)
7	8	9 LICENSEE CODE 14	15 LICENSE NUMBER 25	26 LICENSE TYPE 30	57 CAT 58	

CON'T

0	1	REPORT SOURCE L (6)	0 5 0 - 0 3 2 4 (7)	0 2 1 3 8 0 (8)	0 3 1 1 8 0 (9)
7	8	60	61 DOCKET NUMBER 68	69 EVENT DATE 74	75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 Following a reactor scram, the suppression pool level exceeded -27 inches due to the

0 3 lifting of three reliefs and the running of HPCI and RCIC. An attempt to pump the

0 4 torus down before the high level setpoint was reached could not be done because the

0 5 E11-F049 valve, RHR to radwaste, could not be opened from the RTGB.

0 6

0 7

0 8 Technical Specifications 3.6.2.1, 6.9.1.9b

0 9	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
	S B (11)	E (12)	A (13)	R E L A Y X (14)	A (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 0	—	0 2 9	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
A (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	N (25)	G 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Contacts on relay B21-K59, Model No. CR120A06002AA, in the opening logic for the

1 1 F049 valve were found burned. The relay was replaced and the valve checked for other

1 2 damage, with none found. The valve was operated satisfactorily and returned to

1 3 service. This is considered an isolated event and no further action is required.

1 4

1 5	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
	G (28)	0 0 0 (29)	N/A	A (31)	Operator Surveillance

1 6	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
	Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

1 7	NUMBER	TYPE	DESCRIPTION (39)
	0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

1 8	NUMBER	DESCRIPTION (41)
	0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

1 9	TYPE	DESCRIPTION
	Z (42)	N/A

PUBLICITY

2 0	ISSUED	DESCRIPTION (45)	NRC USE ONLY
	N (44)	N/A	

NAME OF PREPARER A. C. Tollison, Jr. PHONE: (919) 457-9521

8003180587