NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | CAIRSS1 (2) | 010-00000-00 (3) | 4 1 1 1 1 (4) | 1 (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000312 (7) | 03180 (8) | 04038 0 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing the requirements of I&E Bulletin 79-14, the District con-
03 tracted the A/E to assist in review and analysis. On 3/10/80, the A/E
04 informed the District that the as-built configuration of support Nos.
05 1S-50052-1A, 1S-50062-1A and 1S-23626-1, when seismically reanalyzed,
06 indicated that seismic stress would exceed the allowable stress of upset
07 conditions.
08

09 SYSTEM CODE SB (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE SUPORT (14) | COMP. SUBCODE B (15) | VALVE SUBCODE 2 (16)

(17) LER RO REPORT NUMBER | EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 016 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER B130 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Design documentation and construction drawings were not in complete
11 conformance with the original seismic analyses. All three supports
12 were modified. Modifications consisted of replacing spring hangers with
13 rigid supports and the addition of a lateral restraint.
14

15 FACILITY STATUS H (28) | POWER 000 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY D (31) | DISCOVERY DESCRIPTION (32) Notification from A/E

16 ACTIVITY CONTENT RELEASED OF RELEASE Z (33) | Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

20 PUBLICITY ISSUED Y (44) | DESCRIPTION (45) Local newspaper and wire services. (3/31/80)

NRC USE ONLY

NAME OF PREPARER R. W. Colombo PHONE 916-452-3211

8004140405