NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Value
01	Licensee Code (2)	C O F S V 1
01	License Number (3)	0 0 - 0 0 0 0 0 - 0 0
01	License Type (4)	4 1 1 2 0
01	CAT (5)	
01 (CON'T)	Report Source (6)	L
01	Docket Number (7)	0 5 0 0 0 2 6 7
01	Event Date (8)	0 1 2 7 7 9
01	Report Date (9)	0 4 0 9 8 0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On January 27, 1979, operation in a degraded mode of LCO 4.2.10 and LCO 4.2.11 resulted during repairs to a buffer helium purge valve. Operation in a degraded mode of LCO 4.2.10 again occurred on January 29 and January 30, 1979, during the return to power operation. These events were reported per Fort St. Vrain Technical Specification AC 7.5.2(b)2 in Preliminary Report No. 50-267/79-02/03-L-0

System Code (11)	Cause Code (12)	Cause Subcode (13)	Component Code (14)	Comp. Subcode (15)	Valve Subcode (16)
C B	E	F	V A L V E X	F	D

(17) LER/RO Report Number

Event Year		Sequential Report No.		Occurrence Code	Report Type		Revision No.
7 9	—	0 0 2	/	0 3	X	—	1

Action Taken (18)	Future Action (19)	Effect on Plant (20)	Shutdown Method (21)	Hours (22)	Attachment Submitted (23)	NPRD-4 Form Sub. (24)	Prime Comp. Supplier (25)	Component Manufacturer (26)
D	Z	B	Z	0 0 7 0	Y	N	N	V 0 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Leakage past the valve seat insert required bypass of buffer helium dryer for repair. Subsequent investigation revealed slight misalignment between valve stem and seat was causing seat leakage problem. Valve was disassembled and stem machined. No further action is anticipated or required.

Facility Status (28)	% Power (29)	Other Status (30)	Method of Discovery (31)	Discovery Description (32)
E	0 6 2	N/A	A	Operator Observation

Activity Released (33)	Content of Release (34)	Amount of Activity (35)	Location of Release (36)
Z	Z	N/A	N/A

PERSONNEL EXPOSURES

Number (37)	Type (38)	Description (39)
0 0 0	Z	N/A

PERSONNEL INJURIES

Number (40)	Description (41)
0 0 0	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

Type (42)	Description
Z	N/A

8004150611

PUBLICITY

Issued (44)	Description (45)
N	N/A

NRC USE ONLY

NAME OF PREPARER [signature] PHONE: (303) 785-2253