8005200552

POOR ORIGINAL

NRC FORM 366 (7 77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | LICENSEE CODE: A R A N O 1 (2) | LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) | LICENSE TYPE: 4 1 1 1 1 (4) | CAT (5)

CON'T 0 1 | REPORT SOURCE: L (6) | DOCKET NUMBER: 0 5 0 0 0 3 1 3 (7) | EVENT DATE: 0 4 1 5 8 0 (8) | REPORT DATE: 0 5 1 2 8 0 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 Testing of the Fire & Smoke Detectorsper procedure 1405.13 was not
0 3 completed within the + 25 percent allowable period for completion of
0 4 the procedure. All testing outside the reactor building was completed
0 5 within the allowable period. However, testing within the Reactor building
0 6 was not completed on time. The unit was shutdown because of unrelated
0 7 events and the test was completed seven (7) days after the event date.
0 8 All detectors checked operable. Reportable per T.S.6.12.3.2.(c).

0 9 | SYSTEM CODE: A B (11) | CAUSE CODE: D (12) | CAUSE SUBCODE: Z (13) | COMPONENT CODE: Z Z Z Z Z Z (14) | COMP SUBCODE: Z (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR: 8 0 | — | SEQUENTIAL REPORT NO.: 0 1 4 | / | OCCURRENCE CODE: 0 3 | REPORT TYPE: L | — | REVISION NO.: 0

ACTION TAKEN: X (18) | FUTURE ACTION: G (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: Z (25) | COMPONENT MANUFACTURER: Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The testing within the reactor building could not be completed on time
1 1 because Radiation levels were too high to do testing with radiation
1 2 exposur. considerations. Testing was completed 7 days after the event
1 3 date and with the unit in cold shutdown. A T.S. change has been requested
1 4 to delete the requirement for Reactor Building Testing at Power Operation.

1 5 | FACILITY STATUS: E (28) | % POWER: 0 7 1 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Surveillance Test

1 6 | ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES

1 7 | NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

PERSONNEL INJURIES

1 8 | NUMBER: 0 0 0 (40) | DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43)

1 9 | TYPE: Z (42) | DESCRIPTION: NA

PUBLICITY

2 0 | ISSUED: N (44) | DESCRIPTION (45): NA | NRC USE ONLY

NAME OF PREPARER L. S. Bramlett PHONE: 501/968-2519