NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Entry
0 1	Licensee Code (2)	ILQAD1
	License Number (3)	00-000-000-00
	License Type (4)	41111
	CAT (5)	
CON'T 0 1	Report Source (6)	L
	Docket Number (7)	0500254
	Event Date (8)	011180
	Report Date (9)	020180

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing a Suppression Chamber to Drywell Pressure Separation Test, procedure
0 3 QOS 1600-3, differential pressure transmitter 1-8741-51 was found not to indicate
0 4 properly. A check of the transmitter sensing line revealed that valve 1-1601-85 was
0 5 closed. DP was within limits. The 1-8741-51 suppression chamber to drywell DP
0 6 transmitter is a redundant post accident instrument. Since suppression chamber
0 7 pressure indicator PI 1-1602-1, drywell pressure recorder PR 1-8740-12, and drywell
0 8 pressure indicator PIC-1-8740-11 were operable, system DP was always available.

Line	System Code (11)	Cause Code (12)	Cause Subcode (13)	Component Code (14)	Comp. Subcode (15)	Valve Subcode (16)
0 9	IB	A	X	ZZZZZZ	Z	Z

(17) LER/RO Report Number	Event Year		Sequential Report No.		Occurrence Code	Report Type		Revision No.
	80	—	001	/	03	L	—	0

Action Taken (18)	Future Action (19)	Effect on Plant (20)	Shutdown Method (21)	Hours (22)	Attachment Submitted (23)	NPRD-4 Form Sub. (24)	Prime Comp. Supplier (25)	Component Manufacturer (26)
H	Z	Z	Z	0000	N	N	Z	ZZZZ

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this occurrence was personnel error. Valve 1-1601-85 was not properly
1 1 identified on drawings and valve checklists due to its location, and was not properly
1 2 returned to service after the dp transmitter was installed. Immediate corrective
1 3 action was to open the valve and verify proper operation of the DP transmitter.
1 4 Drawing changes have been initiated, valves have been tagged, and a procedure
change has been initiated to include these valves.

Line	Facility Status (28)	% Power (29)	Other Status (30)	Method of Discovery (31)	Discovery Description (32)
1 5	E	097	NA	B	Routine Test

Line	Activity Released (33)	Content of Release (34)	Amount of Activity (35)	Location of Release (36)
1 6	Z	Z	NA	NA

PERSONNEL EXPOSURES

Line	Number (37)	Type (38)	Description (39)
1 7	000	Z	NA

PERSONNEL INJURIES

Line	Number (40)	Description (41)
1 8	000	NA

LOSS OF OR DAMAGE TO FACILITY (43)

Line	Type (42)	Description
1 9	Z	NA

PUBLICITY

Line	Issued (44)	Description (45)
2 0	N	NA

8002180046

NRC USE ONLY

NAME OF PREPARER J. Swales PHONE: 309-654-2241 ext. 173