LICENSEE EVENT REPORT

CONTROL BLOCK: (1–6)

(PLEASE PRINT ALL REQUIRED INFORMATION)

1	LICENSEE NAME (7–14)	LICENSE NUMBER (15–25)	LICENSE TYPE (26–30)	EVENT TYPE (31–32)
01	FLCRP3	00-00000-00	4 1 1 1 1	0 1

CONT	CATEGORY (57–58)	REPORT TYPE (59)	REPORT SOURCE (60)	DOCKET NUMBER (61–68)	EVENT DATE (69–74)	REPORT DATE (75–80)
01	* *	P	L	0 5 0 - 0 3 0 2	0 2 0 3 7 7	0 2 0 9 7 7

EVENT DESCRIPTION

02 During plant cooldown in Mode 4 (Hot Shutdown), two Decay Heat Valves (DHV-4 and
03 DHV-41) would not open upon remote actuation. They were opened by hand. Redundant
04 systems (atmospheric dump valves) were available. A similar (not reportable)
05 problem occurred to a different valve.
06 (7-9)

	SYSTEM CODE (10)	CAUSE CODE (11)	COMPONENT CODE (12–17)	PRIME COMPONENT SUPPLIER (43)	COMPONENT MANUFACTURER (44–47)	VIOLATION (48)
07	CF	E	VALVEX	A	W030 A20	N

CAUSE DESCRIPTION

08 Valve motor operator would not overcome valve drag. Torque setting was increased
09 on operator. Pressure relief line modification initiated to prevent recurrence.
10

11	FACILITY STATUS (9)	% POWER (10–12)	OTHER STATUS (13–44)	METHOD OF DISCOVERY (45)	DISCOVERY DESCRIPTION (46–80)
	G	000	Mode 4	A	N/A

12	FORM OF ACTIVITY RELEASED (9)	CONTENT OF RELEASE (10)	AMOUNT OF ACTIVITY (11–44)	LOCATION OF RELEASE (45–80)
			N/A	

PERSONNEL EXPOSURES

13	NUMBER (9–11)	TYPE (12)	DESCRIPTION (13–80)
			N/A

PERSONNEL INJURIES

14	NUMBER (9–11)	DESCRIPTION (12–80)
		N/A

OFFSITE CONSEQUENCES

15 N/A

LOSS OR DAMAGE TO FACILITY

16	TYPE (9)	DESCRIPTION (10–80)
		N/A

PUBLICITY

17 N/A

ADDITIONAL FACTORS

N/A

8002270575

19

NAME: W. P. Stewart / R. A. DuBois PHONE: (813) 866-4159

GPO 881-667