LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A L M M F 1 (2)	0 0 - 0 0 0 0 0 - 0 0 (3)	4 1 1 1 1 (4)	(5)
		LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT

CON'T

0	1	REPORT SOURCE	L (6)	0 5 0 0 0 3 4 8 (7)	0 2 2 9 8 0 (8)	(9)
				DOCKET NUMBER	EVENT DATE	REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During the performance of FNP-1-STP-26.0 (Control Room Train A (B) Ventilation
0 3 Operability Test) at 0200 on 2-29-80, the 1B recirc fan failed to start. As a result
0 4 the B Train Control Room Emergency Ventilation System was declared inoperable. T/S
0 5 3.7.7.1 requires that both Control Room Emergency Ventilation Systems be operable.
0 6 T/S 3.7.7.1 action statements were met. The health and safety of the public were
0 7 not affected.
0 8

0 9	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
	S G (11)	E (12)	A (13)	R E L A Y X (14)	A (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 0	—	0 1 9	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
A (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	A (25)	R 3 8 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The failure of the fan to start was caused by a blown control power fuse. The blown
1 1 fuse was caused by a shorted alarm relay coil. The shorted coil and the fuse were
1 2 replaced and the surveillance test successfully completed. The system was returned
1 3 to service at 1400 on 2/29/80.
1 4

1 5	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
	E (28)	1 0 0 (29)	NA	B (31)	Operator observation

1 6	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

1 7	NUMBER	TYPE	DESCRIPTION (39)
	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

1 8	NUMBER	DESCRIPTION (41)
	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

1 9	TYPE	DESCRIPTION
	Z (42)	NA

POOR ORIGINAL

PUBLICITY

2 0	ISSUED	DESCRIPTION (45)	NRC USE ONLY
	N (44)	NA	

8004010513

NAME OF PREPARER W. G. Hairston, III PHONE: (205) 899-5156