NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P A B V S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T 0 1 REPORT SOURCE L (6) | 0 5 0 0 0 3 3 4 (7) | 0 3 1 1 8 0 (8) | 0 3 3 1 8 0 (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While testing the #2 Battery Charger, the AC input breaker tripped. The charger had

0 3 been loaded for approximately 7 minutes in accordance with the load test. The

0 4 breaker was reset and the charger returned to service. No further problems were

0 5 experienced with the breaker. Loose control wiring was found and is being

0 6 investigated. The No. 2 Battery Charger was not needed for Operational Mode 5.

0 7 Associated batteries #1 and 3 were in service to support "Train A Priority".

0 8

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP SUBCODE	VALVE SUBCODE
0 9	E C (11)	X (12)	Z (13)	Z Z Z Z Z Z (14)	Z (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 0	—	0 1 6	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
B (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	Z (25)	Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Loose control wiring has been diagnosed as the cause of the breaker trip. After

1 1 completion of the surveillance test, all wiring was checked and the loose wire was

1 2 re-soldered. The surveillance test was reperformed satisfactorily.

1 3

1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	H (28)	0 0 0 (29)	N/A	B (31)	Surveillance test

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	N/A

POOR ORIGINAL

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	N/A	

NAME OF PREPARER J. A. Werling PHONE 412-643-1258

8004070 375