LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0 1] [C T M N S 2] (2) [0 0 - 0 0 0 0 0 - 0 0] (3) [4 1 1 1 1] (4) [ ] (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

[0 1] REPORT SOURCE [L] (6) [0 5 0 0 0 3 3 6] (7) [0 3 0 3 8 0] (8) [0 4 0 2 8 0] (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0 2] During routine operations, the IBM 1800 Plant Computer analog input values became
[0 3] erratic. The IBM 1800 was taken out of service thus making the Pulse Counting
[0 4] Position Indication System inoperable. Operations continued per Technical Specifi-
[0 5] cation 3.1.3.3d since all reed position indication channels were operable. Power
[0 6] was reduced to less than 89 percent to monitor linear heat rate on the excore nuclear
[0 7] instruments per specification 4.2.1.2.
[0 8]
7 8 9 80

[0 9]
7 8

SYSTEM CODE [I F] (11) 9 10
CAUSE CODE [E] (12) 11
CAUSE SUBCODE [G] (13) 12
COMPONENT CODE [I N S T R U] (14) 13 18
COMP. SUBCODE [X] (15) 19
VALVE SUBCODE [Z] (16) 20

(17) LER/RO REPORT NUMBER: EVENT YEAR [8 0] 21 22 | [—] 23 | SEQUENTIAL REPORT NO. [0 0 8] 24 26 | [/] 27 | OCCURRENCE CODE [0 3] 28 29 | REPORT TYPE [L] 30 | [—] 31 | REVISION NO. [0] 32

ACTION TAKEN [A] (18) 33 | FUTURE ACTION [Z] (19) 34 | EFFECT ON PLANT [B] (20) 35 | SHUTDOWN METHOD [Z] (21) 36 | HOURS (22) [0 0 0 0] 37 40 | ATTACHMENT SUBMITTED [N] (23) 41 | NPRD-4 FORM SUB. [Y] (24) 42 | PRIME COMP. SUPPLIER [X] (25) 43 | COMPONENT MANUFACTURER [I 0 1 0] 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1 0] The IBM 1800 plant computer was shutdown to test for and replace a faulty analog input
[1 1] driver card (IBM part number S-15-TCU). Following completion of repairs the IBM
[1 2] 1800 and Pulse Counting System were restored to normal operation. Total time out of
[1 3] service was 13 hours and 10 minutes.
[1 4]
7 8 9 80

FACILITY STATUS [E] (28) 9 10 | % POWER [1 0 0] (29) 10 12 | OTHER STATUS (30) NA 13 44 | METHOD OF DISCOVERY [A] (31) 45 46 | DISCOVERY DESCRIPTION (32) Operator Observation 46 80

ACTIVITY RELEASED [Z] (33) 9 | CONTENT OF RELEASE [Z] (34) 10 11 | AMOUNT OF ACTIVITY (35) NA 11 44 | LOCATION OF RELEASE (36) NA 45 80

PERSONNEL EXPOSURES
NUMBER [0 0 0] (37) 9 11 | TYPE [Z] (38) 12 13 | DESCRIPTION (39) NA 13 80

PERSONNEL INJURIES
NUMBER [0 0 0] (40) 9 11 | DESCRIPTION (41) NA 12 80

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE [Z] (42) 9 10 | DESCRIPTION NA 10 80

PUBLICITY
ISSUED [N] (44) 9 | DESCRIPTION (45) NA 10 68 | 8004090 311 | NRC USE ONLY 69 80

NAME OF PREPARER Edwin R. Foster PHONE: 203-447-1791 Ext. 542