(7-77)

LICENSEE EVENT REPORT

8005060 298 S

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M D C C N 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 8 (7) | 0 4 1 2 8 0 (8) | 0 4 3 0 8 0 (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Number 23 charging pump was removed from service to repair a weld on a

0 3 | suction relief valve. This charging pump was out of service from 1740 April 12, 1980

0 4 | until 1800 April 15, 1980. The other two redundant charging pumps were operable

0 5 | throughout this event. LER 78-49 (U-2) describes a similar event. (T.S. 6.9.1.9)

0 6 |

0 7 |

0 8 | 7 8 9 80

0 9 | 7 8

SYSTEM CODE: C G (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: C (13) | COMPONENT CODE: P I P E X X (14) | COMP. SUBCODE: B (15) | VALVE SUBCODE: Z (16)

9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 0 (21 22) | — (23) | SEQUENTIAL REPORT NO. 0 2 2 (24 26) | / (27) | OCCURRENCE CODE 0 3 (28 29) | REPORT TYPE L (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN: B (18) | FUTURE ACTION: F (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 (33 40) | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: Y (24) | PRIME COMP. SUPPLIER: Z (25) | COMPONENT MANUFACTURER: S 0 3 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This leak was caused by vibration induced metal fatigue in the heat affected

1 1 | zone of a weld. The leak has been repaired and a new system design, modifying

1 2 | suction and discharge piping of both units' charging pumps, has been approved

1 3 | for modification. We anticipate completion of these modifications during the

1 4 | upcoming refueling outages.

7 8 9 80

1 5 | FACILITY STATUS: E (28) | % POWER: 1 0 0 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: A (31) | DISCOVERY DESCRIPTION (32): Operator Observation

7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES

1 7 | NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

7 8 9 11 12 13 80

PERSONNEL INJURIES

1 8 | NUMBER: 0 0 0 (40) | DESCRIPTION (41): NA

7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY (43)

1 9 | TYPE: Z (42) | DESCRIPTION: NA

7 8 9 10 80

PUBLICITY

2 0 | ISSUED: N (44) | DESCRIPTION (45): NA | NRC USE ONLY

7 8 9 10 68 69 80

NAME OF PREPARER R. P. Heibel/D. F. Huseby PHONE (301)269-4743/4816

GPO 917-925