NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | PABVS1 (2) | 00-000000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T 01 | REPORT SOURCE L (6) | 05000334 (7) | 051280 (8) | 060980 (9)
DOCKET NUMBER (41–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing an air flow surveillance test on the fire suppression system
03 sprinkler nozzles to one train of the Supplementary Leak Collection and Release
04 System (SLCRS), approximately 50% of the nozzles were found to be plugged. The
05 consequences to this problem in case of a fire would have been a decreased spray
06 flow to the charcoal filter bank. The other train of the SLCRS was available for
07 service throughout this incident.
08

09 SYSTEM CODE AB (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE ZZZZZZ (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 034 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER Z999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Samples of the material clogging the spray nozzles were obtained and analyzed;
11 about 50% of the debris clogging the nozzles was found to be rust and the rest of
12 the material has not been identified. The nozzles will be removed and cleaned and
13 the system blown down with air to remove any rust particles. The other train of
14 ventilation will be tested when this train is returned to service.

15 FACILITY STATUS X (28) | POWER 000 (29) | OTHER STATUS (30) Design modification outage | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance procedure results

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION N/A

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER W. S. Lacey PHONE 412-643-1258

8006170563