NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NCBEP1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 050-0325 (7) | 051680 (8) | 060380 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During routine surveillance, position 08 for rod 14-15 did not indicate. All
03 other position indications were normal. This event poses no threat to the
04 public health or safety.
05
06
07
08 Technical Specifications 3.1.3.7, 6.9.1.9b

09 | SYSTEM CODE IB (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE E (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER | EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 049 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 After initial troubleshooting, it is believed the problem is a ground in the
11 PIP probe located inside the drywell. This problem will be corrected during
12 the upcoming refueling outage. Engineering is investigating to determine if
13 a generic problem exists.
14

15 | FACILITY STATUS E (28) | % POWER 043 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Surveillance

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES
17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES
18 | NUMBER 000 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY
19 | TYPE Z (42) | DESCRIPTION (43) N/A

PUBLICITY
20 | ISSUED N (44) | DESCRIPTION (45) N/A

NRC USE ONLY

8006090398

NAME OF PREPARER A. C. Tollison, Jr. PHONE: 919-457-9521

5