NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A R A N 0 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 8 (7) | 0 5 3 1 8 0 (8) | 0 6 2 6 8 0 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During Mode 1 operation, a leak developed on the "B" Charging Pump suc-
03 tion pipe at the coupling for 2 CVC-1168 (a capped test connection line),
04 The leak was isolated. The two remaining charging pumps remained operable
05 meeting the requirements of T.S.3.1.2.4. This occurrence is similar to
06 LER's 50-368/79-031 and 80-019. Reportable per T.S. 6.9.1.9(d).
07
08

09 | SYSTEM CODE P C (11) | CAUSE CODE E (12) | CAUSE SUBCODE C (13) | COMPONENT CODE P I P E X X (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 8 0 | — | SEQUENTIAL REPORT NO 0 3 4 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO 0

ACTION TAKEN A (18) | FUTURE ACTION F (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0 0 0 0 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUBMITTED Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Cause of failure is believed to be vibration induced. The pipe spool
11 piece with the defect will be replaced. A design change has changed the
12 pipe specification from Schedule 10 to Schedule 40 and rotated the pipe
13 to change the plane of vibration.
14

15 | FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) NA

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER Chris N. Shively PHONE 501-968-2519

8007010414