U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/2/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1 (4) / / / (5)

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

/0/1/ REPORT SOURCE /L/ (6) /0/5/0/0/0/3/3/9/ (7) /0/6/2/0/8/0/ (8) /0/7/0/2/8/0 (9)

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On June 20, 1980 with the unit at Startup condition, one of the main steam /

/0/3/ / flow transmitters was found to be inoperable. Since there has been no /

/0/4/ / accumulation of fission products due to reactor power being limited to <5% /

/0/5/ / and since the other main steam flow transmitter for that steam generator was /

/0/6/ / operable, the health and safety of the public were not affected. This is /

/0/7/ / contrary to TS 3.3.2.1 and reportable by T.S. 6.9.1.9.a. /

/0/8/ / /

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

/0/9/ /I/B/ (11) /E/ (12) /A/ (13) /I/N/S/T/R/U/ (14) /T/ (15) /Z/ (16)

(17) LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

/8/0/ /-/ /0/2/7/ / \ / /0/3/ /L/ /-/ /0/

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

/B/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /N/ (23) /N/ (24) /N/ (25) /R/3/6/9/ (26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / A loose connection resulting from a stripped screw was found in the transmitter/

/1/1/ / resulting in zero rathe. than one volt transmitter output at no flow. The flow/

/1/2/ / channel was placed in test within one hour. The screw was replaced, the con- /

/1/3/ / nection tightened and the transmitter calibrated. Channel was verified /

/1/4/ / operable and returned to service within four hours. No generic implication. /

FACILITY STATUS %POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

/1/5/ /B/ (28) /0/0/0/ (29) / NA / /A/ (31) /During Start Up Test/

ACTIVITY RELEASED CONTENT OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

/1/6/ /Z/ (33) /Z/ (34) / NA / / NA /

PERSONNEL EXPOSURES

NUMBER TYPE DESCRIPTION (39)

/1/7/ /0/0/0/ (37) /Z/ (38) / NA /

PERSONNEL INJURIES

NUMBER DESCRIPTION (41)

/1/8/ /0/0/0/ (40) / NA /

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE DESCRIPTION

/1/9/ /Z/ (42) / NA /

PUBLICITY

ISSUED DESCRIPTION (45) NRC USE ONLY

/2/0/ /N/ (44) / NA / / / / / / / / / / / / /

8007090304 NAME OF PREPARER W. R. CARTWRIGHT PHONE (703) 894-5151