LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[1] [C T M N S 1] (2) [0 0 - 0 0 0 0 0 - 0 0] (3) [4 1 1 1 1] (4) [ ] (5)
LICENSEE CODE (14) (15) LICENSE NUMBER (25) (26) LICENSE TYPE (30) (57) CAT (58)

[1] REPORT SOURCE [L] (6) [0 5 0 0 0 2 4 5] (7) [0 6 1 3 8 0] (8) [0 7 1 1 8 0] (9)
(60) (61) DOCKET NUMBER (68) (69) EVENT DATE (74) (75) REPORT DATE (80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[2] During tension testing of penetration anchor X-45 base plate bolts, one bolt broke
[3] and others were found improperly installed. At the time of the event, the reactor
[4] was in the cold shutdown condition, the LPCI System was not required (T.S. 3.5.B.5).
[5]
[6]
[7]
[8]

[9] SYSTEM CODE [S F] (11) CAUSE CODE [B] (12) CAUSE SUBCODE [C] (13) COMPONENT CODE [S U P O R T] (14) COMP. SUBCODE [X] (15) VALVE SUBCODE [Z] (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR [8 0] SEQUENTIAL REPORT NO. [0 1 0] OCCURRENCE CODE [0 3] REPORT TYPE [L] REVISION NO. [0]

ACTION TAKEN [A] (18) FUTURE ACTION [F] (19) EFFECT ON PLANT [C] (20) SHUTDOWN METHOD [Z] (21) HOURS (22) [0 0 0 0] ATTACHMENT SUBMITTED [Y] (23) NPRD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [A] (25) COMPONENT MANUFACTURER [E 0 6 5] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[10] The broken bolt and the improperly installed bolts were removed and replaced. Bolts
[11] on similar penetration anchors were inspected, tested, and found acceptable.
[12]
[13]
[14]

[15] FACILITY STATUS [G] (28) % POWER [0 0 0] (29) OTHER STATUS (30) [N/A] METHOD OF DISCOVERY [C] (31) DISCOVERY DESCRIPTION (32) [IE Bulletin 79-02 Tension Test]

[16] ACTIVITY RELEASED [Z] (33) CONTENT OF RELEASE [Z] (34) AMOUNT OF ACTIVITY (35) [N/A] LOCATION OF RELEASE (36) [N/A]

PERSONNEL EXPOSURES
[17] NUMBER [0 0 0] (37) TYPE [Z] (38) DESCRIPTION (39) [N/A]

PERSONNEL INJURIES
[18] NUMBER [0 0 0] (40) DESCRIPTION (41) [N/A]

LOSS OF OR DAMAGE TO FACILITY (43)
[19] TYPE [Z] (42) DESCRIPTION [N/A]

8007180307

PUBLICITY
[20] ISSUED [Y] (44) DESCRIPTION (45) [Routine notification of local media]

NRC USE ONLY