NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 T N S N P 1 (2) 0 0 - 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 (4) (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE

CON'T
01 REPORT SOURCE L (6) 0 5 0 0 0 3 2 7 (7) 0 6 2 4 8 0 (8) 0 7 1 8 8 0 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During Unit 1 plant heatup a "tee" fitting on the pressurizer pressure
03 sensing line for instrument 1-PI-68-323 failed allowing primary coolant
04 to leak into containment. The potential existed for an incorrect
05 pressurizer pressure to be indicated.
06
07
08

09 SYSTEM CODE C A (11) CAUSE CODE E (12) CAUSE SUBCODE B (13) COMPONENT CODE P I P E X X (14) COMP. SUBCODE A (15) VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 0 — SEQUENTIAL REPORT NO. 0 9 8 — OCCURRENCE CODE 0 3 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN A (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS (22) 0 0 0 0 ATTACHMENT SUBMITTED N (23) NPRDS FORMED N (24) PRIME COMP. SUPPLIER L (25) COMPONENT MANUFACTURER P 0 7 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The leaking tee fitting was replaced after the sense line root valve
11 was shut to isolate the fitting. This action required action statements
12 16 & 22a of LCO 3.3.2.1 to be implemented. When the compression type
13 tee was replaced, it was found that a ferrule ring on the leaking end of
14 the faulty tee had been installed backwards.

FACILITY STATUS B (28) POWER 0 0 0 (29) OTHER STATUS (30) N/A — METHOD OF DISCOVERY C (31) DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY RELEASED OR PRESENT 16 Z (33) LOCATION OF RELEASE (34) Z (35) AMOUNT OF ACTIVITY (36) N/A — LOCATION OF RELEASE (37) N/A

PERSONNEL EXPOSURES NUMBER 0 0 0 (38) TYPE Z (39) DESCRIPTION (40) N/A

PERSONNEL INJURIES NUMBER 0 0 0 (41) DESCRIPTION (42) N/A

LOSS OF OR DAMAGE TO FACILITY TYPE Z (43) DESCRIPTION N/A

PUBLICITY ISSUED (44) N (45) DESCRIPTION N/A — NRC USE ONLY

NAME OF PREPARER Richard M. Emrath PHONE 755-2953