NUREG-0540
Vol. 1, No. 8

Title List of Documents made Publicly Available

August 1 - 31, 1979

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

Office of Administration
U. S. Nuclear Regulatory
Commission

7911140 127

Available from

GPO Sales Program
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

and

National Technical Information Service
Springfield, Virginia 22161

NUREG-0540
Vol. 1, No. 8

Title List of Documents made Publicly Available

August 1 - 31, 1979

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

CONTENTS

Preface v

Arrangements of Items by Docket Number. ix

Arrangement of Docket 50 Facility Name xix

Docketed Items. 1

Low Level Radwaste Disposal Sites - Docket 27. 1

Domestic Licensing of Source Material - Docket 40 2

Domestic Licensing of Production and Utilization Facilities - Docket 50 7

Domestic Licensing of Special Nuclear Material - Docket 70. 331

Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71. 347

Nondocketed Items 365

10CFR – Commission Meeting Records 365
ACRS – Advisory Committee on Reactor Safeguards 367
AGREEMENT – State Agreements and Programs 367
COMMISSION – NRC Commissioners 368
CONTRACT – NRC Contracts and Modifications 371
FOIA – Freedom of Information Act Requests and Releases 377
GEN TECH IS – Generic Technical Issues 383
I&E – Inspection and Enforcement. 384
NUREG – NUREG Reports and Related Correspondence 385
ORG – Correspondence with Other Organizations 388
PR – Proposed Rule 389
PRM – Petition for Rulemaking 390
PROJ – Projects-Predocket Licensing 391
PT21 – Noncompliance Reports and Related Correspondence 393
QA999 – Quality Assurance Inspections 393
REGGD – Regulatory Guides 396
RES – Research and Technical Assistance Reports. 398
REVIEW GRP – NRC Research Review Groups 401
RM – Rulemakings 401
SECY – Position Papers Before the Commission 401
TOPREP – Vendor Reports and Related Correspondence 404
WASTE MGT – Nuclear Waste Management 408
XPORTLIC – Export and Import Licenses 408

Personal Author Index 417

Corporate Source Index - By Corporate Types 455

Report Number Index 483

Cross Reference of Enclosures to Principal Documents 485

Appendix A - Definitions of Docket 50 Categories. 501

Appendix B - Definitions of Nondocketed Categories 509

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commision (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information includes the information formerly issued through the Department of Energy's Technical Information Center under the title *Power Reactor Docket Information* (PRDI) and, in addition, information received or generated on other uses of radioactive materials. The last issue of PRDI, published in January 1979, was an annual cumulation of the information for 1978. The *Title List* series initiated by this document replaces PRDI, which will no longer be prepared. Plans for providing microfiche of the docketed material will be announced in a future issue of the *Title List* and in other mailings and announcements.

We are making the monthly issues produced in 1979 available free to all who subscribed to PRDI in Calendar Year 1978. We are doing this to encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material. Near the end of 1979, subscriptions will be solicited for Calendar Year 1980 at a fee yet to be established.

DOCKETED ITEMS

Beginning with Vol. 1, No. 4, the listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

A. Application/construction stage documents and correspondence
B. Utility Preliminary Safety Analysis Report (PSAR), amendments
C. Utility Environmental Report (ER), amendments and correspondence
D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
E. NRC Safety Evaluation Report (SER), supplements and correspondence
F. Security, medical, emergency and fire-protection plans
G. Adjudicatory correspondence
H. General correspondence
I. Financial information
J. Insurance and indemnity information
K. Utility Final Safety Analysis Report (FSAR) and amendments
L. Limited work authorization and related correspondence
M. Antitrust correspondence
N. Antitrust hearing transcripts
O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
P. Operating license stage documents and correspondence

Q. Inspection reports, IE Bulletins and correspondence
R. Periodic operating reports and related correspondence
S. Reportable occurrences, LERs and related correspondence
T. Hearing transcripts on non-antitrust matters

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:



1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number
3. Description of information contained in the document
4. Personal author. An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source
6. Date of document described
7. Pages in document
8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

Beginning with Vol. 1, No. 6, the nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR – Commission Meeting Records
ACRS – Advisory Committee on Reactor Safeguards
AGREEMENT – State Agreements and Programs
COMMISSION – NRC Commissioners
CONTRACT – NRC Contracts and Modifications
FOIA – Freedom of Information Act Requests and Releases
GEN TECH IS – Generic Technical Issues
I&E – Inspection and Enforcement
NUREG – NUREG Reports and Related Correspondence
ORG – Correspondence with other organizations
PR – Proposed Rule
PRM – Petition for Rulemaking
PROJ – Projects-Predocket Licensing
PT21 – Noncompliance Reports and Related Correspondence

QA999 – Quality Assurance Inspections
REGGD – Regulatory Guides
RES – Research and Technical Assistance Reports
REVIEW GRP – NRC Research Review Groups
RM – Rulemakings
SECY – Position Papers Before the Commission
TOPREP – Vendor Reports and Related Correspondence
WASTE MGT – Nuclear Waste Management
XPORTLIC – Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author
6. Corporate, agency or other nonindividual source
7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
8. Date of document described
9. Pages in document
10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or Available at GPO."

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NTIS is:
   National Technical Information Service
   Springfield, Virginia 22161

   To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

2. The address for GPO is:
   Superintendent of Documents
   Government Printing Office
   Washington, D.C. 20402

   To place orders for or to obtain price information about NRC publications at GPO, either write to GPO or call the Inquiry Desk at (202) 783-3238. Publications can be charged to VISA or Master-charge credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:
   1717 H Street, N.W.
   Washington, D.C. 20555

   To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

   Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of $2.00 plus postage is charged for mail orders.

   Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page
27-039	Sheffield, IL., Nuclear Engineering Co., Inc.	1
27-047	Barnwell, SC., Chem-Nuclear Systems, Inc.	1
27-048	Richland, WA., Nuclear Engineering Co.	1
40-0229	Union Carbide Corp.	2
40-0299	Union Carbide Corp.	2
40-1162	Western Nuclear, Inc.	2
40-1341	Ford Bacon & Davis, Inc.	2
40-2061	West Chicago Facility, Kerr-McGee Corp.	2
40-2259	Pathfinder Mines Corp.	2
40-3453	Atlas Minerals	3
40-4492	Federal American Partners	3
40-6659	Petrotomics Co.	3
40-7580	Fansteel Metals	3
40-7983	NL Industries, Inc.	3
40-8002	Radiology Associates /Albert Einstein Medical Center	3
40-8027	Kerr-McGee Corp.	4
40-8064	Exxon Minerals Co.	4
40-8102	Exxon Minerals Co.	4
40-8305	3M Static Control System	4
40-8380	Rocky Mountain Energy Co.	4
40-8434	Home State Mining Co, LA.	4
40-8452	Bear Creek Uranium Co.	4
40-8477	The Boeing Co.	4
40-8502	Wyoming Mining Corp., Irigary Mine	4
40-8584	Union 76 Minerals Exploration Co.	5
40-8636	Wold Nuclear Co.	5
40-8663	Nuclear Dynamics, Inc.	5
40-8674	Plateau Resource	5
40-8675	Energy Fuels Nuclear, Inc.	5
40-8676	Energy Fuels Nuclear, Inc.	5
40-8681	Energy Fuels Nuclear, Inc.	5
40-8693	Ogle Petroleum, Inc.	5
40-8697	Rocky Mountain Energy Co.	6
40-8698	Plateau Resources, Ltd.	6
40-8712	Gulf Oil Corp.	6
40-8714	Cleveland Cliffs Iron Co.	6
40-8721	Rocky Mountain Energy C.	6
40-8722	Brush-Wellman, Inc.	7
40-8725	Gulf Mineral Resources Co.	7
40-8726	New Mexico Health-Environment Dept.	7
40-8727	Kerr-McGee Nuclear Corp.	7
40-8728	Teton Exploration Drilling Co.	7
50-3	Indian Point Station, Unit 1	7
50-5	Pennsylvania State Univ. Research Reactor	9
50-10	Dresden Nuclear Power Station, Unit 1	9
50-13	Babcock & Wilcox Co. Critical Facility	11
50-16	Enrico Fermi Atomic Power Plant, Unit 1	11
50-18	Vallecitos Boiling Water Reactor	11
50-20	Massachusetts Institute of Technology Research Reactor	12
50-22	Westinghouse Test Reactor	12
50-27	Washington State Univ. Research Reactor	12
50-29	Yankee-Rowe Nuclear Power Station	12

Docket	Name	Page
50-47	Army Materials Research Reactor	14
50-54	Union Carbide Research Reactor	14
50-57	State Univ. of New York Research Reactor	14
50-59	Texas A & M Univ. Research Reactor	14
50-62	Univ. of Virginia Research Reactor	14
50-70	General Electric Test Reactor	14
50-72	Univ. of Utah Research Reactor	15
50-73	General Electric Nuclear Test Reactor	15
50-77	Catholic Univ. of America Research Reactor	15
50-89	General Atomic Co.	15
50-94	Rockwell International Research Reactor	15
50-97	Cornell Univ. Zero Power Reactor	16
50-99	Babcock & Wilcox Test Reactor	16
50-106	Oregon State Univ.	16
50-111	North Carolina State Univ. Research Reactor	16
50-112	Univ. of Oklahoma Research Reactor	16
50-113	Univ. of Arizona Research Reactor	16
50-123	Univ. of Missouri Research Reactor	16
50-124	Virginia Polytech Inst. Training Reactor	16
50-128	Texas A & M Univ. Research Reactor	16
50-131	Omaha Veterans Administration Hospital Research Reactor	16
50-133	Humboldt Bay Power Plant, Unit 3	16
50-134	Worcester Polytech Inst. Research Reactor	18
50-139	Univ. of Washington Research Reactor	18
50-142	UCLA Training Reactor	18
50-146	Saxton Nuclear Experimental Facility	18
50-148	Univ. of Kansas Research Reactor	18
50-151	Univ. of Illinois Research Reactor	18
50-155	Big Rock Point Nuclear Power Plant	18
50-156	Univ. of Wisconsin Research Reactor	21
50-157	Cornell Univ. Research Reactor	21
50-163	General Atomic Co.	21
50-166	Univ. of Maryland Research Reactor	21
50-170	National Naval Medical Center	21
50-171	Peach Bottom Atomic Power Station, Unit 1	22
50-184	National Bureau of Standards Reactor	22
50-186	Univ. of Missouri Research Reactor	22
50-187	Space Radiation Research Reactor	22
50-188	Kansas State Univ. Research Reactor	23
50-192	Univ. of Texas Research Reactor	23
50-193	Rhode Island & Providence Plantations AEC	23
50-199	Manhattan College Research Reactor	23
50-201	West Valley Reprocessing Plant	23
50-206	San Onofre Nuclear Station, Unit 1	24
50-208	Columbia Univ. Research Reactor	26
50-213	Haddam Neck Plant	26
50-219	Oyster Creek Nuclear Power Plant	27
50-220	Nine Mile Point Nuclear Station, Unit 1	30
50-223	Univ. of Lowell Research Reactor	32
50-224	Univ. of California Research Reactor	32
50-225	RPI Critical Experiment	32
50-227	Triga Thermionic Protype Reactor	33
50-228	Aerotest Radiography & Research Reactor	33
50-237	Dresden Nuclear Power Station, Unit 2	33
50-243	Oregon State Univ. Research Reactor	35

Docket	Name	Page
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	35
50-245	Millstone Nuclear Power Station, Unit 1	37
50-247	Indian Point Station, Unit 2	39
50-249	Dresden Nuclear Power Station, Unit 3	42
50-250	Turkey Point Plant, Unit 3	44
50-251	Turkey Point Plant, Unit 4	46
50-252	Univ. of New Mexico Research Reactor	49
50-254	Quad-Cities Station, Unit 1	49
50-255	Palisades Nuclear Plant	51
50-259	Browns Ferry Nuclear Power Station, Unit 1	54
50-260	Browns Ferry Nuclear Power Station, Unit 2	56
50-261	H.B. Robinson Plant, Unit 2	59
50-262	Brigham Young Univ. Research Reactor	61
50-263	Monticello Nuclear Generating Plant	61
50-264	Dow Chemical Co.	63
50-265	Quad-Cities Station, Unit 2	63
50-266	Point Beach Nuclear Plant, Unit 1	65
50-267	Fort St. Vrain Nuclear Generating Station	67
50-269	Oconee Nuclear Station, Unit 1	68
50-270	Oconee Nuclear Station, Unit 2	72
50-271	Vermont Yankee Nuclear Power Station	75
50-272	Salem Nuclear Generating Station, Unit 1	77
50-274	U.S. Geological Survey Research Reactor	80
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	81
50-277	Peach Bottom Atomic Power Station, Unit 2	83
50-278	Peach Bottom Atomic Power Station, Unit 3	84
50-280	Surry Power Station, Unit 1	86
50-281	Surry Power Station, Unit 2	90
50-282	Prairie Island Nuclear Station, Unit 1	95
50-284	Idaho State Univ. Research Reactor	96
50-285	Fort Calhoun Station, Unit 1	97
50-286	Indian Point Station, Unit 3	98
50-287	Oconee Nuclear Station, Unit 3	100
50-288	Reed College Research Reactor	103
50-289	Three Mile Island Nuclear Station, Unit 1	104
50-293	Pilgrim Nuclear Power Station, Unit 1	107
50-295	Zion Nuclear Power Station, Unit 1	109
50-296	Browns Ferry Nuclear Power Station, Unit 3	111
50-297	North Carolina State Univ. PULSTAR Reactor	114
50-298	Cooper Nuclear Station	114
50-301	Point Beach Nuclear Plant, Unit 2	116
50-302	Crystal River Nuclear Plant, Unit 3	118
50-304	Zion Nuclear Power Station, Unit 2	121
50-305	Kewaunee Nuclear Power Plant	123
50-306	Prairie Island Nuclear Station, Unit 2	125
50-309	Maine Yankee Atomic Power Plant	127
50-311	Salem Nuclear Generating Station, Unit 2	130
50-312	Rancho Seco Nuclear Generating Station	132
50-313	Arkansas Nuclear One, Unit 1	134
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	136
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	139
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	142
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	144
50-320	Three Mile Island Nuclear Station, Unit 2	146

Docket	Name	Page
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	160
50-322	Shoreham Nuclear Power Station	164
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	165
50-324	Brunswick Steam Electric Plant, Unit 2	167
50-325	Brunswick Steam Electric Plant, Unit 1	169
50-326	Univ. of California at Irvine Research Reactor	171
50-327	Sequoyah Nuclear Plant, Unit 1	171
50-328	Sequoyah Nuclear Plant, Unit 2	174
50-329	Midland Plant, Unit 1	175
50-330	Midland Plant, Unit 2	178
50-331	Duane Arnold Energy Center	181
50-332	Barnwell Reprocessing Plant	183
50-333	James A. Fitzpatrick Nuclear Power Plant	183
50-334	Beaver Valley Power Station, Unit 1	186
50-335	St. Lucie Plant, Unit 1	189
50-336	Millstone Nuclear Power Station, Unit 2	191
50-338	North Anna Power Station, Unit 1	194
50-339	North Anna Power Station, Unit 2	198
50-341	Enrico Fermi Atomic Power Plant, Unit 2	201
50-344	Trojan Nuclear Plant, Unit 1	202
50-346	Davis-Besse Nuclear Power Station, Unit 1	204
50-348	Joseph M. Farley Nuclear Plant, Unit 1	209
50-352	Limerick Generating Station, Unit 1	211
50-353	Limerick Generating Station, Unit 2	212
50-354	Hope Creek Nuclear Station, Unit 1	212
50-355	Hope Creek Nuclear Station, Unit 2	213
50-356	Univ. of Illinois Lopra Research Reactor	214
50-358	William H. Zimmer Nuclear Station, Unit 1	214
50-361	San Onofre Nuclear Station, Unit 2	216
50-362	San Onofre Nuclear Station, Unit 3	218
50-363	Forked River Nuclear Station, Unit 1	219
50-364	Joseph M. Farley Nuclear Plant, Unit 2	220
50-366	Edwin I. Hatch Nuclear Plant, Unit 2	221
50-367	Bailly Generating Station	225
50-368	Arkansas Nuclear One, Unit 2	226
50-369	William B. McGuire Nuclear Station, Unit 1	228
50-370	William B. McGuire Nuclear Station, Unit 2	229
50-373	LaSalle County Station, Unit 1	230
50-374	LaSalle County Station, Unit 2	231
50-375	Nuclear Examination Reactor	233
50-382	Waterford Generating Station, Unit 3	233
50-383	Waterford Generating Station, Unit 4	234
50-386	NYC Hall of Science Research Reactor	234
50-387	Susquehanna Steam Electric Station, Unit 1	234
50-388	Susquehanna Steam Electric Station, Unit 2	237
50-389	St. Lucie Plant, Unit 2	239
50-390	Watts Bar Nuclear Plant, Unit 1	240
50-391	Watts Bar Nuclear Plant, Unit 2	242
50-394	California State Polytech College Research Reactor	244
50-395	Virgil C. Summer Nuclear Station, Unit 1	244
50-396	Univ. o Virginia Cavalier Reactor	246
50-397	WPPSS Nuclear Project, Unit 2	246
50-400	Shearon Harris Nuclear Power Plant, Unit 1	247
50-401	Shearon Harris Nuclear Power Plant, Unit 2	248
50-402	Shearon Harris Nuclear Power Plant, Unit 3	250
50-403	Shearon Harris Nuclear Power Plant, Unit 4	251

Docket	Name	Page
50-404	North Anna Power Station, Unit 3	252
50-405	North Anna Power Station, Unit 4	253
50-407	Univ. of Utah Research Reactor	254
50-409	La Crosse Boiling Water Reactor	254
50-410	Nine Mile Point Nuclear Station, Unit 2	256
50-412	Beaver Valley Power Station, Unit 2	257
50-413	Catawba Nuclear Station, Unit 1	258
50-414	Catawba Nuclear Station, Unit 2	259
50-416	Grand Gulf Nuclear Station, Unit 1	260
50-417	Grand Gulf Nuclear Station, Unit 2	261
50-423	Millstone Nuclear Power Station, Unit 3	262
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	263
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	264
50-433	UC-Santa Barbara Research Reactor	265
50-434	Surry Power Station, Unit 3	265
50-435	Surry Power Station, Unit 4	265
STN-50-437	Floating Nuclear Plant	265
50-438	Bellefonte Nuclear Plant, Unit 1	266
50-439	Bellefonte Nuclear Plant, Unit 2	267
50-440	Perry Nuclear Power Plant, Unit 1	269
50-441	Perry Nuclear Power Plant, Unit 2	270
50-443	Seabrook Nuclear Station, Unit 1	271
50-444	Seabrook Nuclear Station, Unit 2	272
50-445	Comanche Peak Steam Electric Station, Unit 1	274
50-446	Comanche Peak Steam Electric Station, Unit 2	276
50-452	Greenwood Energy Center, Unit 2	278
50-453	Greenwood Energy Center, Unit 3	278
50-454	Byron Station, Unit 1	279
50-455	Byron Station, Unit 2	280
50-456	Braidwood Station, Unit 1	281
50-457	Braidwood Station, Unit 2	281
50-458	River Bend Station, Unit 1	282
50-459	River Bend Station, Unit 2	283
50-460	WPPSS Nuclear Project, Unit 1	283
50-461	Clinton Power Station, Unit 1	284
50-462	Clinton Power Station, Unit 2	284
50-463	Fulton Generating Station, Unit 1	285
50-464	Fulton Generating Station, Unit 2	285
50-466	Allens Creek Nuclear Station, Unit 1	285
50-467	Allens Creek Nuclear Station, Unit 2	287
50-470	CESSAR System 80	287
50-471	Pilgrim Nuclear Power Station, Unit 2	287
50-472	Pilgrim Nuclear Power Station, Unit 3	288
STN-50-482	Wolf Creek Generating Station	288
STN-50-483	Calloway Plant, Unit 1	289
STN-50-484	Tyrone Energy Park, Unit 1	290
STN-50-485	Sterling Power Project, Nuclear, Unit 1	291
STN-50-486	Calloway Plant, Unit 2	292
STN-50-488	Perkins Nuclear Station, Unit 1	292
STN-50-489	Perkins Nuclear Station, Unit 2	293
STN-50-490	Perkins Nuclear Station, Unit 3	293
STN-50-491	Cherokee Nuclear Station, Unit 1	294
STN-50-492	Cherokee Nuclear Station, Unit 2	295
STN-50-493	Cherokee Nuclear Station, Unit 3	295
STN-50-495	SWESSAR-P1	296
STN-50-498	South Texas Project, Unit 1	296
STN-50-499	South Texas Project, Unit 2	298
50-500	Davis-Besse Nuclear Power Station, Unit 2	300
50-501	Davis-Besse Nuclear Power Station, Unit 3	300
STN-50-502	Haven Nuclear Plant, Unit 1	301
STN-50-503	Haven Nuclear Plant, Unit 2	301
50-504	Koshkonong Nuclear Plant, Unit 1	301
50-505	Koshkonong Nuclear Plant, Unit 2	301
50-506	Koshkonong Nuclear Plant, Unit 3	302

Docket	Name	Page
50-507	Koshkonong Nuclear Plant, Unit 4	302
STN-50-508	WPPSS Nuclear Project, Unit 3	302
STN-50-509	WPPSS Nuclear Project, Unit 5	302
50-510	Blue Hills Station, Unit 1	303
50-511	Blue Hills Station, Unit 2	303
50-513	WPPSS Nuclear Project, Unit 4	304
50-514	Pebble Springs Nuclear Plant, Unit 1	304
50-515	Pebble Springs Nuclear Plant, Unit 2	304
STN-50-516	Jamesport Nuclear Station, Unit 1	305
STN-50-517	Jamesport Nuclear Station, Unit 2	305
STN-50-518	Hartsville Nuclear Plant, Unit 1	306
STN-50-519	Hartsville Nuclear Plant, Unit 2	307
STN-50-520	Hartsville Nuclear Plant, Unit 3	308
STN-50-521	Hartsville Nuclear Plant, Unit 4	309
STN-50-522	Skagit Nuclear Power Project, Unit 1	310
STN-50-523	Skagit Nuclear Power Project, Unit 2	312
50-524	Barton, Unit 1	314
50-525	Barton, Unit 2	314
50-526	Barton, Unit 3	314
50-527	Barton, Unit 4	314
STN-50-528	Palo Verde Nuclear Station, Unit 1	314
STN-50-529	Palo Verde Nuclear Station, Unit 2	315
STN-50-530	Palo Verde Nuclear Station, Unit 3	316
STN-50-536	GASSAR-6	316
50-538	Memphis State Univ. Research Reactor	317
STN-50-546	Marble Hill Nuclear Station, Unit 1	317
STN-50-547	Marble Hill Nuclear Station, Unit 2	318
50-548	Fort Calhoun Station, Unit 2	319
50-549	Greene County Nuclear Power Plant	319
STN-50-553	Phipps Bend Nuclear Plant, Unit 1	319
STN-50-554	Phipps Bend Nuclear Plant, Unit 2	321
STN-50-556	Black Fox Station, Unit 1	322
STN-50-557	Black Fox Station, Unit 2	322
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	323
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	324
STN-50-568	NEP Nuclear, Unit 1	325
STN-50-569	NEP Nuclear, Unit 2	325
STN-50-574	Bagnac Nuclear Power Project	326
STN-50-580	Erie Nuclear Plant, Unit 1	327
STN-50-581	Erie Nuclear Plant, Unit 2	327
STN-50-592	Palo Verde Nuclear Station, Unit 4	327
STN-50-593	Palo Verde Nuclear Station, Unit 5	328
50-596	New Haven, Unit 1	328
50-597	New Haven, Unit 2	329
50-599	Carroll Facility I	330
50-600	Carroll Facility II	331
70-0008	Battelle Columbus Laboratories	331
70-0025	Rockwell International Corp.	331
70-0027	Babcock & Wilcox Co.	332
70-0033	Texas Instruments, Inc.	332
70-0036	Combustion Engineering, Inc.	333
70-0135	Babcock & Wilcox Co.	333
70-0143	Nuclear Fuel Services, Inc.	333
70-0152	Purdue University	335
70-0157	Texas, Univ. of	335
70-0310	Schlumberger Well Services	335
70-0364	Parks Township Site, Babcock & Wilcox Co.	335
70-0371	United Nuclear Corp.	336
70-0572	Monsanto Research Corp.	336
70-0597	Central Michigan Univ.	336
70-0734	General Atomic Co.	336
70-0754	Vallecitos Nuclear Center, General Electric Co.	337
70-0820	United Nuclear Corp.	338
70-0824	Babcock & Wilcox Co.	339
70-0925	Cimarron Facility, Kerr-McGee Corp.	339
70-0959	Nuclear Fuel Services, Inc.	339

Docket	Name	Page
70-0984	Pacific Northwest Laboratory	339
70-1007	General Electric Co.	340
70-1100	Combustion Engineering, Inc.	340
70-1113	General Electric Co.	340
70-1143	Westinghouse Electric Corp.	341
70-1151	Westinghouse Electric Corp.	341
70-1193	Cimarron Facility, Kerr-McGee Corp.	342
70-1201	UF_6 Conversion Facility, Babcock & Wilcox Co.	342
70-1207	Navy, Dept. of	342
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	343
70-1308	Morris Operations, General Electric Co.	343
70-1319	U.S. Nuclear, Inc.	344
70-1379	Parkwell Laboratories, Inc.	344
70-1426	Transnuclear, Inc.	344
70-1489	Goodyear Aerospace Corp.	344
70-1510	Nuclear Assurance Corp.	344
70-1622	Tennessee Valley Authority	344
70-1739	Tri-State Motor Transit Co.	344
70-1810	Westinghouse Electric	344
70-1852	Westinghouse Electric Corp.	344
70-1968	State, Dept. of	345
70-2064	Exxon Nuclear Fuel Fabrication Plant	345
70-2130	Exxon Nuclear Fuel Fabrication Plant	345
70-2155	Westinghouse Electric Corp.	345
70-2201	Westinghouse Electric Corp.	345
70-2219	Exxon Nuclear Co., Inc.	345
70-2319	Our Lady of Lourdes Hosp. Camden NJ	345
70-2443	Tennessee Valley Authority	345
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	345
70-2684	Transnuclear, Inc.	346
70-2696	Albert Einstein Medical Center, Philadelphia, PA	346
70-2804	Transnuclear, Inc.	346
70-2838	Cincinnati Gas & Electric Co.	346
70-2842	Transnuclear, Inc.	347
70-2884	Long Island Lighting Co.	347
70-2910	Tennessee Valley Authority	347
70-2911	Carolina Power and Light Co.	347
70-9021	Tech/Ops Radiation Products Div.	347
71-0005	Magnaflux Corp.	347
71-0009	Isomedix, Inc.	347
71-0010	Gamma Industries	347
71-0013	Navy, Dept. of	347
71-0014	Adirondack Steel Casting Co.	347
71-0016	Northwest Airlines, Inc.	348
71-0018	Nuclear Assurance Corp.	348
71-0020	International Testing Labs	348
71-0024	Hittman Nuclear and Development Corp.	348
71-0030	General Atomic Co.	348
71-0031	Maryland Shipbuilding and Dry Dock Co.	348
71-0033	Ind. Test. Lab. Services Corp.	348
71-0036	ITT Grinnell Corp.	348
71-0040	Technical Operations Inc.	348
71-0044	United Airlines	348
71-0049	Navy, Dept. of	348
71-0053	Boeing Services International Inc.	348
71-0058	Navy, Dept. of	348
71-0064	Peabody Testing/X-Ray Eng. Co.	348
71-0066	Certified Testing Labs, Inc.	348
71-0067	Medi-Physics, Inc.	349
71-0070	General Motors Corp.	349
71-0072	Babcock & Wilcox Co.	349
71-0081	ITT Grinnell Industrial Piping, Inc.	349
71-0084	Huico, Inc.	349
71-0085	Navy, Dept. of	349
71-0091	Eastern Airlines, Inc.	349
71-0092	Eastman Kodak Co.	349
71-0093	Huntington Testing	349

Docket	Name	Page
71-0097	Nondestructive Testing Service	349
71-0099	Foster Wheeler Energy Corp.	349
71-0100	Venegas Ind. Test Labs, Inc.	349
71-0109	Union Carbide Corp.	349
71-0111	Material Testing Lab. of Virginia, Inc.	349
71-0116	Navy, Dept. of	350
71-0117	Abex Corp.	350
71-0125	Testco Inc.	350
71-0126	Stanwick Corp.	350
71-0128	Amoco Oil Co.	350
71-0129	Navy, Dept. of	350
71-0131	Welding Institute of Alaska	350
71-0137	Metals Testing Co., Inc.	350
71-0141	Rockwell International	350
71-0146	Globe X-Ray Services Inc.	350
71-0147	Amoco Oil Co.	350
71-0149	Midwest Inspection Services	350
71-0155	Bath Iron Works Corp.	350
71-0158	X-Ray Industries, Inc.	350
71-0167	Finlay Testing Laboratories	350
71-0172	Empire Steel Castings, Inc.	351
71-0175	QC Services, Inc.	351
71-0176	Navy, Dept. of	351
71-0181	Consolidated X-Ray Service Corp.	351
71-0186	High Steel Structures, Inc.	351
71-0188	Maynard Steel Casting Co.	351
71-0189	Todd Shipyards Corp.	351
71-0190	Texas Instruments, Inc.	351
71-0196	Sooner X-Ray and Mag., Inc.	351
71-0197	Bethlehem Steel Corp.	351
71-0198	Nuclear Fuel Services Inc.	351
71-0199	Navy, Dept. of	351
71-0200	Industrial Inspection and Test Co.	351
71-0201	Duralloy Blaw-Knox, Inc.	351
71-0206	Pryor Foundry, Inc.	351
71-0209	Jacksonville Shipyards, Inc.	351
71-0210	Gulf Oil Corp.	351
71-0212	General Electric Co.	351
71-0213	Intermountain Testing Co.	352
71-0214	Gas Rentals Inc.	352
71-0215	Space Science Services	352
71-0220	General Dynamics Corp.	352
71-0221	Allis Chalmers Corp.	352
71-0222	St. Louis Testing Labs, Inc.	352
71-0223	B.F. Shaw, Inc.	352
71-0224	Guyon Power and Process Piping	352
71-0229	Word Industries Pipe Fabricating, Inc.	352
71-0231	Chem-Nuclear Systems, Inc.	352
71-0232	Lakehead Testing Lab, Inc.	352
71-0233	O'Neill Tank Co., Inc.	352
71-0234	X-Ray, Inc.	352
71-0237	Columbia Gas Transmission Co.	352
71-0238	Agriculture, Dept. of	352
71-0241	United Nuclear Corp.	353
71-0242	Law Engineering Testing Co.	353
71-0243	Transeastern Inspection, Inc.	353
71-0244	NL Industries, Inc.	353
71-0245	Navy, Dept. of	353
71-0246	Inspection Services Corp.	353
71-0247	IRT Corp.	353
71-0248	Monsanto Research Corp.	353
71-0253	Twin Ports Testing, Inc.	353
71-0254	General Electric Co.	353
71-0255	Walworth Co.	353
71-0257	Industrial Labs, Inc.	353
71-0258	Nuclear Engineering Co., Inc.	353
71-0261	Navy, Dept. of	353
71-0264	Automation Industries, Inc.	353
71-0268	Navy, Dept. of	354
71-0269	Lehigh Testing Laboratories, Inc.	354

Docket	Name	Page
71-0270	Factory Mutual Engineering Corp.	354
71-0272	Crane Co.	354
71-0274	Navy, Dept. of	354
71-0276	Navy, Dept. of	354
71-0279	Universal Testing, Inc.	354
71-0280	Abco Perforators, Inc.	354
71-0282	WKM Wellhead Systems, Inc.	354
71-0285	Bell Geophysics	354
71-0286	BPB Instruments, Inc.	354
71-0287	Carson Non-Destructive Testing	354
71-0288	North Dakota State Water Commission	354
71-0289	Terradata Geophysical, Inc.	354
71-0290	United Testing Services, Inc.	354
71-0291	DJ Inspection Services, Inc.	354
71-0293	Brand X Perforators, Inc.	355
71-0295	Acurex Corp.	355
71-0297	E. Lewis Cook and Associates	355
71-0299	Quality Control Services, Inc.	355
71-0300	Independent Testing Laboratories	355
71-0301	CTL Engineering, Inc.	355
71-0302	Johnson Controls	355
71-0303	Memphis Testing Services	355
71-0309	Worthington Pump Corp.	355
71-0311	Logwell, Inc.	355
71-0312	Metalforms, Inc.	355
71-0313	Precision Inspection, Ltd.	355
71-0315	Radiography Inspection, Inc.	355
71-0317	Hudson Products Corp.	355
71-0318	Marathon Oil Co.	355
71-0321	Exam Co.	355
71-0329	Howmet Turbine Components Corp.	355
71-0330	Allied Inspection Services, Inc.	356
71-0331	North Carolina State Univ. at Raleigh	356
71-0332	Florida Power Corp.	356
71-0333	Alabama Power Co.	356
71-0335	City of Burlington, NC	356
71-0336	Cleveland X-Ray Inspection	356
71-0337	Calumet Testing Svc., Inc.	356
71-0338	Metils, Inc.	356
71-0340	Public Service Co. of Colorado	356
71-0341	Arkansas Power and Light Co.	356
71-0342	Wisconsin Industrial Testing, Inc.	356
71-0345	Carolina Power & Light Co.	356
71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	357
71-5026	Model: BC-48-220, Atcor Inc.	357
71-5149	Model: 814A, Babcock & Wilcox Co.	357
71-5274	Model: UNC-1634, United Nuclear Corp.	357
71-5331	Model: BP-2, General Electric Co.	357
71-5364	Model: NPI-67-0442 Neutron Products, Inc.	357
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	357
71-5563	Model: 660C, Babcock & Wilcox Co.	357
71-5597	Model: Tungsten Shielded Cask, Energy, Dept. of	357
71-5754	Model: RMG-172, Nuclear Fuel Services Inc.	357
71-5768	Model: BB-250-2, Combustion Engineering Co., Inc.	357
71-5796	Model: 181361, Picker Corporation	357
71-5901	Model: NFS 100, Nuclear Fuel Services Inc.	357
71-5910	Model: NNFD-SA-2, Babcock & Wilcox Co.	357
71-5926	Model: 100, General Electric Co.	358
71-5950	Model: BCL-4, Battelle Columbus/Labs	358
71-5957	Model: BMI-1, Energy, Dept. of	358
71-5971	Model: GE-200, General Electric Co.	358
71-5980	Model: GE-600, General Electric Co.	358
71-6058	Model: B3-1, Nuclear Engineering Co.	358
71-6144	Model: 6144, Nuclear Engineering Co.	358
71-6172	Model: 961A, Babcock & Wilcox Co.	358

Docket	Name	Page
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	358
71-5272	Model: Poly Panther, Teledyne Energy Systems	358
71-6291	Model: 400	358
71-6346	Model: FSV-1, General Atomic, Co.	358
71-6357	Model: NNFD-10, Babcock & Wilcox Co.	359
71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	359
71-6387	Model: 60, Battelle Memorial Institute	359
71-6400	Model: Super Tiger, Westinghouse Electric Corp.	359
71-6478	Model: 4T, Energy, Dept. of	359
71-6568	Model: LL-60-150, TVA	359
71-6574	Model: HN-200, Hittman Nuclear and Development Corp.	359
71-6581	Model: 51032-1 & 1A, Exxon Nuclear Inc.	358
71-6601	Model: LL-30-100, Chem-Nuclear Systems, Inc.	359
71-6639	Model: MH-1A, Army, Dept. of	360
71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	360
71-6697	Model: 8500 PKG, General Electric Co.	360
71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	360
71-6717	Model: 6717B	360
71-6722	Model: BS-33-180, Tennessee Valley Authority	360
71-6744	Model: Poly Tiger, Nuclear Engineering Co.	360
71-9001	Model: IF-300, General Electric Co.	360
71-9006	Model: 500 SU, Argonne National Laboratory	360
71-9007	Model: 520, Argonne National Laboratory	360
71-9009	Model: FL-10-1, General Electric Co.	360
71-9010	Model: NLI-1/2, NL Industries, Inc.	360
71-9018	Model: BU-6, General Electric Co.	361
71-9019	Model: BU-7, General Electric Co.	361
71-9021	Model: 750, Technical Operations, Inc.	361
71-9022	Model: CE-250-2, Combustion Engineering Co., Inc.	361
71-9023	Model: NLI-10/24, NL Industries Inc.	361
71-9033	Model: 660 & 660E, Technical Operations, Inc.	361
71-9039	Model: 715, Technical Operations, Inc.	361
71-9044	Model: GE-1600, General Electric Co.	361
71-9070	Model: N 55, Energy, Dept. of	361
71-9071	Model: AP-101, Chem-Nuclear Systems, Inc.	361
71-9073	Model: OH-142 Nuclear Packaging, Inc.	361
71-9074	Model: AP-100, Anefco, Inc.	361
71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	362
71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	362
71-9081	Model: CSNI-1600, Chem-Nuclear Systems, Inc.	362
71-9086	Model: HN-100 Series 1, Hittman Nuclear & Development Corp.	362
71-9089	Model: NH-100S, Hittman Nuclear & Development Corp.	362
71-9092	Model: HN-300, Hittman Nuclear & Development Corp.	362
71-9094	Model: CNSI-14-195-H, Chem-Nuclear Systems, Inc.	362
71-9095	Model: CNSI 6-80, Chem-Nuclear Systems, Inc.	362
71-9096	Model: CNSI-21-300, Chem-Nuclear Systems, Inc.	362
71-9097	Model: CNSI-14-195L, Chem-Nuclear Systems, Inc.	362
71-9104	Model: BL-33-90, Atcor, Inc.	362
71-9111	Model: CN6-80A, Chem-Nuclear Systems, Inc.	362
71-9112	Model: AL-31-120, Atcor, Inc.	362
71-9113	Model: 7-100, Chem-Nuclear Systems, Inc.	362
71-9114	Model: NP-50 CFL, Nuclear Packaging, Inc.	363
71-9118	Model: 4 Inch Lead, Protective Packaging, Inc.	363
71-9121	Model: 1.25 Inch Lead, Protective Packaging, Inc.	363

Docket	Name	Page
71-9130	Model: NP-50-XXL, Nuclear Packaging, Inc.	363
71-9132	Model: T-3, Nuclear Packaging, Inc.	363
71-9133	Model: C-10, Gamma Industries	363
71-9134	Model: ETR Fuel Element Shipping Container	362

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page
Aerotest Radiography & Research Reactor	50-228	33
Allens Creek Nuclear Station, Unit 1	50-466	285
Allens Creek Nuclear Station, Unit 2	50-467	286
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	263
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	264
Arkansas Nuclear One, Unit 1	50-313	134
Arkansas Nuclear One, Unit 2	50-368	225
Army Materials Research Reactor	50-470	14
Babcock & Wilcox Co. Critical Facility	50-13	11
Babcock & Wilcox Test Reactor	50-99	16
Bagnac Nuclear Power Project	STN-50-574	326
Bailly Generating Station	50-367	225
Barnwell Reprocessing Plant	50-332	183
Barton, Unit 1	50-524	314
Barton, Unit 2	50-525	314
Barton, Unit 3	50-526	314
Barton, Unit 4	50-527	314
Beaver Valley Power Station, Unit 1	50-334	186
Beaver Valley Power Station, Unit 2	50-412	257
Bellefonte Nuclear Plant, Unit 1	50-438	266
Bellefonte Nuclear Plant, Unit 2	50-439	267
Big Rock Point Nuclear Power Plant	50-155	18
Black Fox Station, Unit 1	STN-50-556	321
Black Fox Station, Unit 2	STN-50-557	322
Blue Hills Station, Unit 1	50-510	303
Blue Hills Station, Unit 2	50-511	303
Braidwood Station, Unit 1	50-456	280
Braidwood Station, Unit 2	50-457	281
Brigham Young Univ. Research Reactor	50-262	61
Browns Ferry Nuclear Power Station, Unit 1	50-259	54
Browns Ferry Nuclear Power Station, Unit 2	50-260	56
Browns Ferry Nuclear Power Station, Unit 3	50-296	111
Brunswick Steam Electric Plant, Unit 1	50-325	169
Brunswick Steam Electric Plant, Unit 2	50-324	167
Byron Station, Unit 1	50-454	278
Byron Station, Unit 2	50-455	279
California State Polytech College Research Reactor	50-394	244
Calloway Plant, Unit 1	STN-50-483	289
Calloway Plant, Unit 2	STN-50-486	291
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	142
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	144
Carroll Facility I	50-599	330
Carroll Facility II	50-600	330
Catawba Nuclear Station, Unit 1	50-413	258
Catawba Nuclear Station, Unit 2	50-414	259
Catholic Univ. of America Research Reactor	50-77	15
CESSAR System 80	50-470	287
Cherokee Nuclear Station, Unit 1	STN-50-491	294
Cherokee Nuclear Station, Unit 2	STN-50-492	295
Cherokee Nuclear Station, Unit 3	STN-50-493	295
Clinton Power Station, Unit 1	50-461	284

Name	Docket	Page
Clinton Power Station, Unit 2	50-462	284
Columbia Univ. Research Reactor	50-208	25
Comanche Peak Steam Electric Station, Unit 1	50-445	274
Comanche Peak Steam Electric Station, Unit 2	50-446	276
Cooper Nuclear Station	50-298	114
Cornell Univ. Research Reactor	50-157	21
Cornell Univ. Zero Power Reactor	50-97	16
Crystal River Nuclear Plant, Unit 3	50-302	118
Davis-Besse Nuclear Power Station, Unit 1	50-346	204
Davis-Besse Nuclear Power Station, Unit 2	50-500	300
Davis-Besse Nuclear Power Station, Unit 3	50-501	300
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	81
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	165
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	136
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	139
Dow Chemical Co.	50-264	63
Dresden Nuclear Power Station, Unit 1	50-10	9
Dresden Nuclear Power Station, Unit 2	50-237	33
Dresden Nuclear Power Station, Unit 3	50-249	42
Duane Arnold Energy Center	50-331	181
Edwin I. Hatch Nuclear Plant, Unit 1	50-321	160
Edwin I. Hatch Nuclear Plant, Unit 2	50-366	221
Enrico Fermi Atomic Power Plant, Unit 1	50-16	11
Enrico Fermi Atomic Power Plant, Unit 2	50-341	201
Erie Nuclear Plant, Unit 1	STN-50-580	326
Erie Nuclear Plant, Unit 2	STN-50-581	327
Floating Nuclear Plant	STN-50-437	265
Forked River Nuclear Station, Unit 1	50-363	219
Fort Calhoun Station, Unit 1	50-285	97
Fort Calhoun Station, Unit 2	50-548	319
Fort St. Vrain Nuclear Generating Station	50-267	67
Fulton Generating Station, Unit 1	50-463	284
Fulton Generating Station, Unit 2	50-464	285
GASSAR-6	STN-50-536	316
General Atomic Co.	50-89	15
General Atomic Co.	50-163	21
General Electric Test Reactor	50-70	14
General Electric Nuclear Test Reactor	50-73	15
Grand Gulf Nuclear Station, Unit 1	50-416	260
Grand Gulf Nuclear Station, Unit 2	50-417	261
Greene County Nuclear Power Plant	50-549	319
Greenwood Energy Center, Unit 2	50-452	278
Greenwood Energy Center, Unit 3	50-453	278
H.B. Robinson Plant, Unit 2	50-261	59
Haddam Neck Plant	50-213	26
Hartsville Nuclear Plant, Unit 1	STN-50-518	306
Hartsville Nuclear Plant, Unit 2	STN-50-519	307
Hartsville Nuclear Plant, Unit 3	STN-50-520	308
Hartsville Nuclear Plant, Unit 4	STN-50-521	309
Haven Nuclear Plant, Unit 1	STN-50-502	301
Haven Nuclear Plant, Unit 2	STN-50-503	301
Hope Creek Nuclear Station, Unit 1	50-354	212
Hope Creek Nuclear Station, Unit 2	50-355	213
Humboldt Bay Power Plant, Unit 3	50-133	16
Idaho State Univ. Research Reactor	50-284	96
Indian Point Station, Unit 1	50-3	7
Indian Point Station, Unit 2	50-247	39
Indian Point Station, Unit 3	50-286	98
James A. Fitzpatrick Nuclear Power Plant	50-333	183
Jamesport Nuclear Station, Unit 1	STN-50-516	304
Jamesport Nuclear Station, Unit 2	STN-50-517	305

Name	Docket	Page
Joseph M. Farley Nuclear Plant, Unit 1	50-348	209
Joseph M. Farley Nuclear Plant, Unit 2	50-364	220
Kansas State Univ. Research Reactor	50-188	23
Kewaunee Nuclear Power Plant	50-305	123
Koshkonong Nuclear Plant, Unit 1	50-504	301
Koshkonong Nuclear Plant, Unit 2	50-505	301
Koshkonong Nuclear Plant, Unit 3	50-506	301
Koshkonong Nuclear Plant, Unit 4	50-507	301
LaCrosse Boiling Water Reactor	50-409	254
LaSalle County Station, Unit 1	50-373	230
LaSalle County Station, Unit 2	50-374	231
Limerick Generating Station, Unit 1	50-352	211
Limerick Generating Station, Unit 2	50-353	212
Maine Yankee Atomic Power Plant	50-309	127
Manhattan College Research Reactor	50-199	23
Marble Hill Nuclear Station, Unit 1	STN-50-546	316
Marble Hill Nuclear Station, Unit 2	STN-50-547	318
Massachusetts Institute of Technology Research Reactor	50-20	12
Memphis State Univ. Research Reactor	50-538	316
Midland Plant, Unit 1	50-329	175
Midland Plant, Unit 2	50-330	178
Millstone Nuclear Power Station, Unit 1	50-245	37
Millstone Nuclear Power Station, Unit 2	50-336	191
Millstone Nuclear Power Station, Unit 3	50-423	262
Monticello Nuclear Generating Plant	50-263	61
National Bureau of Standards Reactor	50-184	22
National Naval Medical Center	50-170	21
NEP Nuclear, Unit 1	STN-50-568	324
NEP Nuclear, Unit 2	STN-50-569	325
New Haven, Unit 1	50-596	328
New Haven, Unit 2	50-597	329
Nine Mile Point Nuclear Station, Unit 1	0-220	30
Nine Mile Point Nuclear Station, Unit 2	50-410	256
North Anna Power Station, Unit 1	50-338	194
North Anna Power Station, Unit 2	50-339	198
North Anna Power Station, Unit 3	50-404	252
North Anna Power Station, Unit 4	50-405	253
North Carolina State Univ. PULSTAR Reactor	50-297	114
North Carolina State Univ. Research Reactor	50-111	16
Nuclear Examination Reactor	50-375	233
NYC Hall of Science Research Reactor	50-386	234
Oconoee Nuclear Station, Unit 1	50-269	68
Oconoee Nuclear Station, Unit 2	50-270	72
Oconoee Nuclear Station, Unit 3	50-287	100
Omaha Veterans Administration Hospital Research Reactor	50-131	16
Oregon State Univ.	50-106	16
Oregon State Univ. Research Reactor	50-243	35
Oyster Creek Nuclear Power Plant	50-219	27
Palisades Nuclear Plant	50-255	51
Palo Verde Nuclear Station, Unit 1	STN-50-528	314
Palo Verde Nuclear Station, Unit 2	STN-50-529	315
Palo Verde Nuclear Station, Unit 3	STN-50-530	316
Palo Verde Nuclear Station, Unit 4	STN-50-592	327
Palo Verde Nuclear Station, Unit 5	STN-50-593	327
Peach Bottom Atomic Power Station, Unit 1	50-171	22
Peach Bottom Atomic Power Station, Unit 2	50-277	83
Peach Bottom Atomic Power Station, Unit 3	50-278	84
Pebble Springs Nuclear Plant, Unit 1	50-514	304
Pebble Springs Nuclear Plant, Unit 2	50-515	304
Pennsylvania State Univ. Research Reactor	50-5	9
Perkins Nuclear Station, Unit 1	STN-50-488	292

Name	Docket	Page
Perkins Nuclear Station, Unit 2	STN-50-489	293
Perkins Nuclear Station, Unit 3	STN-50-490	293
Perry Nuclear Power Plant, Unit 1	50-440	269
Perry Nuclear Power Plant, Unit 2	50-441	270
Phipps Bend Nuclear Plant, Unit 1	50-553	319
Phipps Bend Nuclear Plant, Unit 2	50-554	320
Pilgrim Nuclear Power Station, Unit 1	50-293	107
Pilgrim Nuclear Power Station, Unit 2	50-471	287
Pilgrim Nuclear Power Station, Unit 3	50-472	288
Point Beach Nuclear Plant, Unit 1	50-266	65
Point Beach Nuclear Plant, Unit 2	50-301	116
Prairie Island Nuclear Station, Unit 1	50-282	95
Prairie Island Nuclear Station, Unit 2	50-306	125
Quad-Cities Station, Unit 1	50-254	49
Quad-Cities Station, Unit 2	50-265	63
Rancho Seco Nuclear Generating Station	50-312	132
Reed College Research Reactor	50-288	103
Rhode Island & Providence Plantations AEC	50-193	23
River Bend Station, Unit 1	50-458	282
River Bend Station, Unit 2	50-459	282
Rockwell Intl. Research Reactor	50-94	15
Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	35
RPI Critical Experiment	50-225	32
Salem Nuclear Generating Station, Unit 1	50-272	77
Salem Nuclear Generating Station, Unit 2	50-311	130
San Onofre Nuclear Station, Unit 1	50-206	24
San Onofre Nuclear Station, Unit 2	50-361	216
San Onofre Nuclear Station, Unit 3	50-362	218
Saxton Nuclear Experimental Facility	50-146	18
Seabrook Nuclear Station, Unit 1	50-443	271
Seabrook Nuclear Station, Unit 2	50-444	272
Sequoyah Nuclear Plant, Unit 1	50-327	171
Sequoyah Nuclear Plant, Unit 2	50-328	174
Shearon Harris Nuclear Power Plant, Unit 1	50-400	247
Shearon Harris Nuclear Power Plant, Unit 2	50-401	248
Shearon Harris Nuclear Power Plant, Unit 3	50-402	250
Shearon Harris Nuclear Power Plant, Unit 4	50-403	251
Shoreham Nuclear Power Station	50-322	164
Skagit Nuclear Power Project, Unit 1	STN-50-522	310
Skagit Nuclear Power Project, Unit 2	STN-50-523	312
South Texas Project, Unit 1	STN-50-498	296
South Texas Project, Unit 2	STN-50-499	298
Space Radiation Research Reactor	50-187	22
State Univ. of New York Research Reactor	50-57	14
Sterling Power Project, Nuclear, Unit 1	STN-50-485	291
St. Lucie Plant, Unit 1	50-335	189
St. Lucie Plant, Unit 2	50-389	239
Surry Power Station, Unit 1	50-280	86
Surry Power Station, Unit 2	50-281	90
Surry Power Station, Unit 3	50-434	265
Surry Power Station, Unit 4	50-435	265
Susquehanna Steam Electric Station, Unit 1	50-387	234
Susquehanna Steam Electric Station, Unit 2	50-388	237
SWESSAR-P1	STN-50-495	296
Texas A & M Univ. Research Reactor	50-59	14
Texas A & M Univ. Research Reactor	50-129	16
Three Mile Island Nuclear Station, Unit 1	50-289	104
Three Mile Island Nuclear Station, Unit 2	50-320	146
Triga Thermionic Prototype Reactor	50-227	33
Trojan Nuclear Plant, Unit 1	50-344	202

Name	Docket	Page
Turkey Point Plant, Unit 3	50-250	44
Turkey Point Plant, Unit 4	50-251	46
Tyrone Energy Park, Unit 1	STN-50-484	290
UCLA Training Reactor	50-142	18
UC-Santa Barbara Research Reactor	50-433	265
Union Carbide Research Reactor	50-54	14
Univ. of Arizona Research Reactor	50-113	16
Univ. of California at Irvine Research Reactor	50-326	171
Univ. of California Research Reactor	50-224	32
Univ. of Illinois Research Reactor	50-151	18
Univ. of Illinois Lopra Research Reactor	50-356	214
Univ. of Kansas Research Reactor	50-148	18
Univ. of Lowell Research Reactor	50-223	32
Univ. of Maryland Research Reactor	50-166	21
Univ. of Missouri Research Reactor	50-123	16
Univ. of Missouri Research Reactor	50-186	22
Univ. of New Mexico Research Reactor	50-252	49
Univ. of Oklahoma Research Reactor	50-112	16
Univ. of Texas Research Reactor	50-192	23
Univ. of Utah Research Reactor	50-72	15
Univ. of Utah Research Reactor	50-407	254
Univ. of Virginia Cavalier Reactor	50-396	246
Univ. of Virginia Research Reactor	59-62	14
Univ. of Washington Research Reactor	50-139	18
Univ. of Wisconsin Research Reactor	50-156	21
U.S. Geological Survey Research Reactor	50-274	80
Vallecitos Boiling Water Reactor	50-18	11
Vermont Yankee Nuclear Power Station	50-271	75
Virgil C. Summer Nuclear Station, Unit 1	50-395	244
Virginia Polytech Inst. Training Reactor	50-124	16
Washington State Univ. Research Reactor	50-27	12
Waterford Generating Station, Unit 3	50-382	233
Waterford Generating Station, Unit 4	50-383	234
Watts Bar Nuclear Plant, Unit 1	50-390	240
Watts Bar Nuclear Plant, Unit 2	50-391	242
Westinghouse Test Reactor	50-22	12
West Valley Reprocessing Plant	50-201	23
William B. McGuire Nuclear Station, Unit 1	50-369	228
William B. McGuire Nuclear Station, Unit 2	50-370	229
William H. Zimmer Nuclear Station, Unit 1	50-358	214
Wolf Creek Generating Station	STN-50-482	288
Worcester Polytech Inst. Research Reactor	50-134	18
WPPSS Nuclear Project, Unit 1	50-460	283
WPPSS Nuclear Project, Unit 2	50-397	246
WPPSS Nuclear Project, Unit 3	STN-50-508	302
WPPSS Nuclear Project, Unit 4	50-513	303
WPPSS Nuclear Project, Unit 5	STN-50-509	302
Yankee-Rowe Nuclear Power Station	50-29	12
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	323
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	323
Zion Nuclear Power Station, Unit 1	50-295	109
Zion Nuclear Power Station, Unit 2	50-304	121

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL . NUCLEAR ENGINEERING CO

7908080689 Forwards 790523 ltr from IL Dept of Public Health confirming telcons re D'Appolonia piezometers at low level radioactive waste disposal site.
DRAGONETTE,K S Low Level Waste Licensing Branch 79/06/01 2pp

--7908310065 Confirms NRC 790522 telcons w/IL Geological Survey & J Blackburn re D'Appolonia piezometers at waste disposal site. Favors replacement w/std monitoring wells.
STRATTON,L E Illinois, State of, Dept of Public Health 79/05/23 1p

7908020111 Discusses 790531 vendor ltr objecting to NRC statement of possible financial weakness Explains basis of statement company stressed financial burden in past,attempted to abandon unstabilized site & is being sued.
GOSSICK,L V Office of the Executive Director for Operations 79/06/25 1p

--7908020116 Discusses Nuclear Engineering Co 790308 notice of intention to close waste disposal site Suggests DOE prepare contingency plans re acceptance of commercial low level waste.
MARTIN,T B Division of Waste Management 79/04/05 1p

--7908020120 Objects to NRC statement of uncertain future of licensee Nuclear Engineering Co intends to continue to operate radwaste disposal facilities in future.Financial condition is sound.
NEEL,J N Neco Electrical Products Corp 79/05/31 3pp

7908080419 Forwards ltr responding to JN Neel 790531 ltr re reasons for informing DOE contingency planning staff of concerns about future of Nuclear Engineering Co W/o encl.
GOSSICK,L V Office of the Executive Director for Operations 79/06/25 1p

7908030536 Response by licensee to NRC 790606 notice of hearing Seeks dismissal of show cause order.To extent not dismissed licensee requests evidentiary hearing.Certificate of Svc encl.
CONNER,T B ; RADER,R M Conner, Moore & Corber 79/07/02 5pp

7908030528 Request by intervenor State of IL for denial of licensee 790618 motion re reconsideration & clarification of NRC 790606 order.Licensee reiterated arguments & produced no evidence to support allegation.Certificate of Svc encl.
SCOTT,W J ; SEKULER,S N Illinois, State of 79/07/03 6pp

7908030522 Opposes licensee 790618 motion for reconsideration & clarification of NRC 790606 order.NRC properly ruled on issues & refeired issue framed to ASLB for determination.
Certificate of Svc encl.
REIS,E J Branch 3 79/07/09 14pp

7908030536 Motion submitted by intervenor State of IL to amend June 1978 stipulated revised contentions.Issues have been altered by licensee.Submits Contentions 17-25.Affidavit of SN Sekuler & Certificate of Svc enl.
SEAULER,S N Illinois, State of 79/07/19 7pp

7908030543 Motion submitted by Nuclear Engineering Co to file out of time suppl to 790618 motion for reconsideration & clarification of NRC 790606 order.New info per FOIA request is pertinent to motion.
CONNER,T B Conner, Moore & Corber 79/07/19 4pp

--7908030552 Motion submitted by Nuclear Engineering Co to suppl 790618 motion for reconsideration & clarification of NRC 790606 order.No technical basis for making NRC 790320 order to show cause immediately effective.
CONNER,T B Conner, Moore & Corber 79/07/19 5pp

--7908030560 Forwards draft of NRC 790326 order to show cause.Order should not be issued.Order cannot be enforced,is noncommital on health & safety concerns & fails to require new anchors.
HIGGINBOTHAM,L Division of Fuel Facility & Materials Safety 79/03/27 1p

--7908030568 Order supplementing NRC 790320 show cause order.License must pump water from sumps of trenches 14A & 25 & dispose of water or devise method to prevent migration of water to unrestricted area.Certificate of Svc encl.
DAVIS,J G Office of Inspection & Enforcement, Office of the Director 79/03/26 6pp

7908030574 Requests extension until 790815 to file response to Nuclear Engineering Co 790618 suppl to motion for reconsideration per NRC 790724 order.Certificate of Svc encl.
BRENNER,L Branch 3 79/07/27 3pp

7908030579 Objections submitted by Nuclear Engineering Co to State of IL Contentions 17-25 & motion for prehearing conference. Contentions restate State of IL legal theory.Conference is premature.Certificate of Svc encl.
CONNER,T B ; RADER,R M Conner, Moore & Corber 79/07/30 11pp

DOCKET 27-047 BARNWELL, SC . CHEM-NUCLEAR SYSTEMS

7908080385 Responds to 790511 ltr re amend to License 46-13536-01, authorizing receipt,transport & disposal of bulk loads of waste contaminated w/small amounts of slightly enriched U. Responses to questions incomplete.Addl info needed.
SMITH,R D Low Level Waste Licensing Branch 79/06/21 2pp

7908100358 Forwards Amend 16 to License 46-13536-01.
DRAGONETTE,K S Low Level Waste Licensing Branch 79/06/29 1p

--7908100361 Amend 16 to License 46-13536-01 re radwaste disposal & storage.
DRAGONETTE,K S Low Level Waste Licensing Branch 79/06/29 1p

7908200007 Responds to 790621 request for addl info supporting application for amend to License 46-13536-01 authorizing receipt,transport & disposal of bulk loads of wastes containing low concentrations of U-235.Other ltrs encl.
REYNOLDS,L E Chem-Nuclear Systems, Inc 79/07/26 7pp

7908170181 Requests amend to License 46-13536-01 to increase U-235 possession limit to 4.5 kg & byproduct possession to 50,000 Ci.Proposes several license conditions.
CORBETT,J S Chem-Nuclear Systems, Inc 79/07/30 3pp

DOCKET 27-048 RICHLAND, WA . NUCLEAR ENGINEERING CO.

7908090498 Responds to 790601 ltr re licensee intention to receive, possess & transport radioactive matl in non-agreement states.Pending application renewal,such authority is in full effect,per 10CFR2.109.
BAER,T S Nuclear Engineering Co. 79/06/28 2pp.

DOCKETED ITEMS

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0229 UNION CARBIDE CORP

7908310091 Submits rept on release of radioactive matl per 40CFR65, 780701-790101. No liquid release & only 0.12 lb U per hr airborne release from tailings, ore stock piles & fugitive dust.
REKEMEYER, P. C. Union Carbide Corp. 79/06/19. 1p.

DOCKET 40-0299 UNION CARBIDE CORP

7908170211 Provides supplementary info as Addendum 3 to June 1979 rept "U Tailings Disposal Sys, Present & Proposed." Forwards statement confirming sufficiency of info re "mudstone layer."
SHORTRIDGE, E. W. Union Carbide Corp. 79/07/12. 3pp.

7908130586 Forwards "Addendum 1 to Environ Assessment of Below-Grade U Tailings Disposal in A-9 Open Pit."
WONG, T. Union Carbide Corp. 79/07/13. 8pp.

--7908130589 "Addendum 1 to Environ Assessment of Below-Grade U Tailings Disposal in A-9 Open Pit."
* Dames & Moore. 79/07/02. 17pp.

7908150734 Responds to comments of NRC reviewers of 790228 rept re thickness, continuity & character of mudstone layer beneath A-9 pit. Concern expressed re occurrence of seepage through sides.
MURDOCK, L. T. Dames & Moore. 79/07/17. 34pp.

7908210407 Forwards revised Section 9.0 of June 1979 rept, "U Tailings Disposal Sys, Present & Proposed." Revised map encl.
NRC-DEG-0608-79-1 encl.
WONG, T. Union Carbide Corp. 79/08/01. /pp.

--7908210411 Drawing, "Geology-Monitor Wells Sys."
* Union Carbide Corp. 79/07/23. 1p.

7908220557 Submits response to request for addl info re pit disposal of tailings.
REDEMEYER, P. C. Union Carbide Corp. 79/08/08. 3pp.

DOCKET 40-1162 WESTERN NUCLEAR, INC

7908060285 Clarifies method of assuring sample saturation for cyclic triaxial testing. Forwards revised response to Question 7, summarizing steps taken to assure saturation for samples.
TAYLOR, M. J. Dart Environment & Services Co. ERC/LANCY Div. 79/06/21. 8pp.

7908030566 Requests amend to License Condition, Item 22, reducing min 10-ft freeboard condition to 8-ft. Toe drain will be installed & beach tailings moved to front side of dike pending formal authorization. Class II fee encl.
RANSONE, J. W. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 79/06/25. 1p.

7908140087 Forwards comments on draft environ statement re Split Rock U Mill. Mill has many environ problems. Proposed license renewal neither environmentally sound nor acceptable.
MERSON, A. Environmental Protection Agency. 79/06/25. 14pp.

7908210204 Forwards "Radiation, Perimeter Airborne Dust, Surface Water & Groundwater Repts," Jan 1978-Mar 1979 & "Stack Emissions Survey," Jan & Sept 1978 & Mar 1979.
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 79/07/05. 2pp.

--7908210217 "Radiation Rept," Jan-Mar 1978.
* Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 78/03/31. 15pp.

--7908210221 "Radiation Rept," Apr-June 1978.
* Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 78/06/30. 13pp.

--7908210225 "Radiation Rept," Jul-Sept 1978.
* Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 78/09/30. 14pp.

--7908210228 "Radiation Rept," Oct-Dec 1978.
* Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 78/12/31. 16pp.

--7908210230 "Radiation Rept," Jan-Mar 1979.
* Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 79/03/31. 10pp.

--7908210233 "Stack Emissions Survey," Jan 1978.
* Ecology Audits, Inc. 78/01/31. 9pp.

--7908210240 "Stack Emissions Survey," Sept 1978.
* Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 78/09/30. 7pp.

--7908210244 "Stack Emission Survey," Mar 1979.
* Kumpe & Associates, P.C. 79/03/31. 7pp.

7908170176 Discusses data provided 790205 re location of toe drain. Burial tests to determine pipe specs for toe drain are complete. Submits revised specs.
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 79/07/27. 1p.

DOCKET 40-1341 FORD, BACON & DAVIS, INC

7908090494 Requests that TVA be designated cooperating agency in preparation of EIS re Edgemont U Mill decommissioning plan. Requests NRC response by 790716.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/25. 1p.

7908160123 Responds to 790226 conceptual decommissioning plan & supporting environ rept re License SUA-816. Discusses evaluation of alternative tailings disposal sites & required offsite remedial action program.
MARTIN, J. B. Division of Waste Management. 79/06/29. 3pp.

7908170248 Submits comments re decommissioning plan & environ rept for U mill, submitted by util. Concerned w/avoidance of discussion of offsite windblown tailings & tailings use in & near Cottonwood community.
JANKLOW, W. J. South Dakota, State of. 79/07/20. 2pp.

DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEE CORP

7908080616 Responds to 790305 & 0418 ltrs. City placed on mailing list & will receive advance notice of press releases. Doubts NRC authority to take action re unauthorized movement of matl to offsite location & subsequent contamination.
NIXON, W. A. Fuel Process. & Fab. Branch (Pre 790727). 79/06/04. 3pp.

7908210081 Forwards request for proposal, including radiological evaluation of Reed-Keppler Park. Evaluation expected within 1 yr, w/recommendations to follow.
NIXON, W. A. Fuel Process. & Fab. Branch (Pre 790727). 79/06/21. 1p.

7908210085 Confirms 790620 telcon re addl evaluation of matl in Reed-Keppler Park. Request for proposal was issued & work should be complete within 1 yr, w/recommendations to follow.
NIXON, W. A. Fuel Process. & Fab. Branch (Pre 790727). 79/06/21. 1p.

7908070824 Ack receipt of 790604 ltr. Mayor will take legal action against Kerr-McGee Corp. West Chicago will remove all licensed matl to public landfill by 790801.
SPELMAN, H. J. West Chicago, IL. 79/06/28. 1pp.

7908220184 Forwards application for renewal of License STA-583 & application fee. Detailed decommissioning plan to be sent shortly.
SHELLEY, W. J. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). 79/07/20. 1p.

--7908220192 Application for renewal of License STA-583 authorizing use of natural thorium in solid & liquid form for storage & distribution.
RAINEY, J. L. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). 79/07/25. 5pp.

DOCKET 40-2259 PATHFINDER MINES CORP

7908080265 Submits rept re monitoring of personnel.
DOOLEY, L. G. Pathfinder Mines Corp. 79/02/16. 8pp.

7908310006 Responds to NRC 790601 ltr re source matl license. Forwards addl info re extent of riprap area associated w/runoff flow over reclaimed areas. Two oversized drawings encl.
NUGENT, E. L. Pathfinder Mines Corp. 79/06/08. 8pp.

7908020007 Discusses Amend 5 to License SUA-672, requiring licensee to minimize dispersal of dust from ore piles by water sprinkling & authorizing staged const of Dam 2A to 6,360 ft above mean sea level.
SCARANO, R. A. Uranium Recovery Licensing Branch 79/07/16 5pp.

7908150236 Submits facts & NRC conclusion re Amend 5 to License SUA-672. Issuance of Amend 5 re revised Conditions 36, 40 & 42 & new Conditions 48-52 will not constitute risks to health & safety.
ROSSBACH, L. W. Uranium Recovery Licensing Branch 79/07/16 4pp.

DOCKET 40-3453 ATLAS MINERALS

7908010627 Discusses items for amend of 790430 license, including tailings pond dike, location of monitoring device, dusting from ore piles, individual tank containment sys & emission control equipment.
DEARTH, A. E. Atlas Minerals 79/06/01 3pp.

7908130043 Confirms Jensen to Linehan 790531 telcon re interim measures during flooding of CO River. Monitoring will be conducted daily, tailings will be discharged & photographic record made of flooding situation.
SCARANO, R. A. Uranium Recovery Licensing Branch 79/06/04 2pp.

7908280706 Requests that 741118 application & 780420 submittal be forwarded.
SWANBY, G. T. Atlas Minerals 79/06/06 1p.

7908090473 Confirms 790612 telcon re operating procedures used to ensure compliance w/tailings pond beach embankment requirements.
SWANBY, G. T. Atlas Minerals 79/06/26 1p.

--7908090481 Requests amend to License SUA-917 to incorporate tailings pond embankment design mods & operating controls.
BADGER, W. P. Atlas Minerals 77/06/24 5pp.

--7908090488 Notifies that License SUA-917 is amended, authorizing changes to Item 6, "Design Criteria for Improvements of Tailings Disposal Sys at Atlas Minerals Milling Operations, Moab, UT."
ROUSE, L. C. Fuel Process. & Fab. Branch (Prv 790727) 77/07/21 1p.

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS

7908020029 Forwards "Work Program Relocation of Federal American Partners' Housing Village, Gas Hills, WY." Requests review.
JACKSON, F. D. Federal American Partners 79/06/14 1p.

--7908020035 "Work Program for Relocation of Federal American Partners' Housing Village, Gas Hills, WY."
* Gibbs & Hill, Inc. (subs. of Dravo Corp.) 79/06/06 20pp.

7908020194 Forwards IE Investigation Rept 40-4492/79-02 on 790501. No noncompliance noted.
GROWN, G. D. Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/06/15 1p.

--7908020201 IE Investigation Rept 40-4492/79-02 on 790501. No noncompliance noted. Major areas inspected: bldg purportedly contaminated w/radioactive matl.
WILBURN, L., BROWN, G. D. Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/06/13 4pp.

7908130037 Amend 5 to License SUA-667, authorizing raising of tailings dam 2 by constructing 15-ft lift on existing dam to elevation of 6510 ft.
SCARANO, R. A. Uranium Recovery Licensing Branch 79/07/12 2pp.

7908230172 Reviews licensee application for Amend 5 to License SUA-667 re const of 15-ft lift on tailings dam 2. Recommends approval.
GARCIA, P. J., LINEHAN, J. J. Uranium Recovery Licensing Branch 79/07/12 2pp.

--7908230179 Safety evaluation from Geotechnical Engineering re proposed addition to tailings dam 2. Recommends approval. Hydrologic engineering summary encl.
* Office of Nuclear Material Safety & Safeguards 79/07/12 8pp.

7908290546 Informs of amend to SUA-667 to add Condition 33 replacing bioassay requirements of 780622 ltr.
SCARANO, R. A. Uranium Recovery Licensing Branch 79/07/23 2pp.

--7908290554 "Staff Technical Position re Bioassay at U Mills."
* Fuel Process. & Fab. Branch (Prv 790727) 78/06/30 11pp.

DOCKET 40-6659 PETROTOMICS CO., GETTY OIL

7908090304 Forwards IE Investigation Rept 40-6659/79-01 on 790323-25.
BROWN, G. D. Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/04/13 2pp.

--7908090333 IE Investigation Rept 40-6659/79-01 on 790323-25. Spill of U concentrate on 790322 in KS caused no public health problems. Decontamination worker exposure expected to be minimal.
DANSON, J. M., EVERETT, R. J., BROWN, G. D. Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/04/11 4pp.

7908030590 Amend 4 to Source Matl License SUA-551 re operating pond level & documented program to check upstream face of tailings dam.
SCARANO, R. A. Uranium Recovery Licensing Branch 79/06/20 2pp.

7908170227 Forwards info re downstream toe ditch design & upstream slope protection as requested in 790518 ltr. Pitch design for downstream toe of dam was done by Banner & Associates. Requested map encl.
HAUTALA, R. L. Petrotomics, Inc. 79/07/11 21pp.

DOCKET 40-7580 FANSTEEL METALS

79083006_5 Responds to D Nussbaumer 790223 technical assistance request re license for waste retention pond for storage of tailings containing source matl. Forwards draft safety evaluation rept.
JACKSON, R. E. Geosciences Branch 79/08/08 2pp.

--7908300608 Draft safety evaluation rept re renewal of & amend to Fansteel Metals, Inc license to store waste containing source matl. Improvement retaining pond meets intent of Reg Guide 3.11.
* Licensing Management Branch 79/08/08 8pp.

DOCKET 40-7983 NL INDUSTRIES, INC

7908160545 Discusses IE insp of License SUB-972 on 790510. No noncompliance noted. Major areas inspected: progress in decontamination prior to release of Wilmington, DE facility for unrestricted use.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director 79/06/20 1p.

DOCKET 40-8002 RADIOLOGY ASSOCIATES/ALBERT EINSTEIN MEDICAL CTR

7908240082 Ack receipt of 790517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 40-8002/79-01 & 70-2696/79-01.
MCCLINTOCK, R. O. Region 1, Philadelphia, Safeguards Branch 79/06/15 1p.

--7908240088 Responds to NRC 790508 ltr re violations noted in IE Insp Repts 40-8002/79-01 & 70-2696/79-01. Corrective actions: proposal submitted for const of barrier which will seal corridor to storage area.
BAKER, A. S. Albert Einstein Medical Center 79/05/17 1p.

--7908240099 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 40-8002/79-01 & 70-2696/79-01. Addl info required re periodic audits of every authorized user & limits on continuous individual exposure.
MCCLINTOCK, R. O. Region 1, Philadelphia, Safeguards Branch 79/05/08 1p.

--7908240113 Responds to NRC 790320 ltr re violations noted in IE Insp Repts 40-8002/79-01 & 70-2696/79-01. Corrective actions: procedures explained to technician, "hot trash" to be monitored & lead bricks properly replaced.
BAKER, A. S. Albert Einstein Medical Center 79/04/03 2pp.

--7908240117 Forwards notice of violation from IE Insp Repts 40-8002/79-01 & 70-2696/79-01.
SMITH, Q. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/20 3pp.

--7908240122 Notice of violation from IE insp on 790215-16. Items of noncompliance: failure to adequately evaluate quantity & distribution of contamination on hands of nuclear medicine technician & failure to properly survey trash cans.
* Region 1, Philadelphia, Office of the Director 79/03/20 2pp.

DOCKETED ITEMS

DOCKET 40-8027 KERR-MCGEE CORP

7908010071 Submits notification of noncompliance re outfall of suspended solids exceeding effluent guidelines for NPDES permit. Forwards 790601 ltr identifying nature of violation & requesting EPA guidance.
SHELLEY, W. J. Kerr-McGee Nuclear Corp. 79/06/05 1p.

7908140502 Notifies of violation re pH value.
SHELLEY, W. J. Kerr-McGee Corp. 79/06/06 1p.

--7908140507 Notifies that pH value of 9.2 was recorded for grab sample. Earlier sample taken was pH value 7.1. Unexplained pH increase being investigated.
SHELLEY, W. J. Kerr-McGee Corp. 79/07/05 1p.

7908090638 Forwards 790625 ltr to EPA requesting mod of NPDES Permit OK0000191 re guidelines for total suspended solids outfall.
SHELLEY, W. J. Kerr-McGee Corp. 79/06/26 4pp.

7908210041 Amends License SUB-1010 to authorize remodeling of raffinate storage pond 1 & installation of clarifier-A. Forwards related safety evaluation.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727) 79/07/20 2pp.

--7908210048 Safety evaluation supporting license amend to authorize remodeling of raffinate Storage Pond 1.
SOONG, A. L. Fuel Process. & Fab. Branch (Pre 790727) 79/07/20 3pp.

DOCKET 40-8064 EXXON MINERALS CO. USA; EXXON CORP.

7908130580 Forwards documents re WY State Dept of Environ Quality approval of pilot projects.
FREEMAN, M. D. Exxon Minerals Co., USA 79/07/06 119 pp.

7908170150 Submits info re request for amend to SUA-1064. Differences in monitor well excursion parameters are due to different methods for calculating parameters. Chart of parameters encl.
FREEMAN, M. D. Exxon Minerals Co., USA 79/07/06 2pp.

7908270502 Forwards summaries of individual monitor well sample analyses for second quarter. Discusses fluid volumes processed in solution mine pilot operation & total project during second quarter 1979.
FREEMAN, M. D. Exxon Minerals Co., USA 79/07/24 15pp.

DOCKET 40-8102 EXXON MINERALS CO. USA; EXXON CORP.

7908240169 Forwards IE Investigation Rept 40-8120/79-01. No noncompliance noted.
BROWN, G. D. Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/04/30 2pp.

--7908240172 IE Investigation Rept 40-8120/79-01 on 790328. No noncompliance noted. Major areas inspected reported airborne exposures of two welders to soluble U in Glenrock, WY.
WILBORN, L. Region 4, Dallas, Office of the Director. BROWN, G. D. Region 4, Dallas, Fuel Facility & Materials Safety Branch. 79/04/25 6pp.

7908030016 Discusses submittal of info requested by NRC 790523 ltr re application for renewal of source matl license. Requests data used by NRC for radiological assessment in NUREG-0489 & NUREG-0532.
ORTLOFF, G. D. Exxon Minerals Co., USA 79/06/15 1p.

7908210138 Ack receipt of 790615 ltr requesting confirmation of licensee response dates for addl meteorological & population distribution data in support of License SUA-1139 renewal. Forwards meteorological data needed.
LINEHAN, J. J. Uranium Recovery Licensing Branch 79/07/16 4pp.

DOCKET 40-8305 3M STATIC CONTROL SYS

7908310064 Notifies of RO leakage in excess of .005 uCi limit of two Model 210 & one Model 315 generally licensed static eliminators. Caused by removal of protective screens in front of Po-210 sources. Rept made on behalf of licensee Budd Co.
LAHR, T. N. 3M Co., Minnesota Mining & Mfg. Co. 79/05/24 2pp.

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO.

7908210084 Forwards semiannual effluent monitoring rept for Jan-June 1979 for Nine Mile Lake Project.
SPIELES, P. Rocky Mountain Energy Co. 79/07/31 1p.

--7908210087 Semiannual effluent monitoring rept for Jan-June 1979 for Nine Mile Lake Project.
* Rocky Mountain Energy Co. 79/07/31 5pp.

DOCKET 40-8434 HOME STAKE MINING CO. LA

7908030586 Forwards renewal application for Source Matl License SUA-1249.
POWERS, H. A. Homestake Mining Co. 79/05/30 1p.

--7908030593 Application for renewal of License SUA-1249 to authorize upgrading of 44,000 lb solution containing no more than 500 lb U for further upgrading in conventional mill.
POWERS, H. A. Homestake Mining Co. 79/05/30 4pp.

7908010609 Ack receipt of 790530 application for renewal of License SUA-1249. Requests payment of renewal fee.
WEISS, D. License Fee Management Branch 79/06/13 1p.

DOCKET 40-8452 BEAR CREEK URANIUM CO.

7908010322 Forwards Semiannual Operating Rept, Jul-Dec 1978.
BLOSSOM, J. N. Bear Creek Uranium Co. 79/02/28 1p.

--7908010331 Semiannual Operating Rept, July-Dec 1978.
* Bear Creek Uranium Co. 78/12/31 12pp.

7908130363 Notifies that review of Sept 1978 request for license amend indicates need for addl info. Request for info re inplant safety, environ data & Questions 1-4 re proposed tailings dam raise encl.
LINEHAN, J. J. Fuel Process. & Fab. Branch (Pre 790727). 79/03/19 13pp.

7908030003 Forwards response to questions posed by NRC during review of mill expansion amend request. Provides info re computed water surface profiles during PMF, rip rap specs for final reclamation & potential effects of tailing line rupture.
ANDREWS, R. D. Rocky Mountain Energy Co. 79/06/22 2pp.

--7908030006 "Bear Creek Tailings Reclamation Drainage Study."
* Rocky Mountain Energy Co. 79/06/18 131pp.

7908060503 Forwards Page 17 of "Bear Creek Tailings Reclamation Drainage Study." Page was inadvertently omitted from original rept.
ANDREWS, R. D. Rocky Mountain Energy Co. 79/06/26 2pp.

7908100584 Forwards summary of water quality data for tailing area monitor wells & water well permits for mill water supply. Area of tailing beach & pool at 5,150-ft elevation will be 132 acres.
ANDREWS, R. D. Rocky Mountain Energy Co. 79/06/29 8pp.

DOCKET 40-8477 THE BOEING CO.

7908010253 Informs that symbol XTS has been assigned as reporting identification symbol for License SUB-1301.
SPARKS, E. Technical Planning & Information Branch 79/06/13 1p.

DOCKET 40-8502 IRIGARY MINE, WYOMING MINING CORP.

7908140027 Forwards rept "Environ Evaluation of License SL--1341." Encl withheld (ref 10CFR2.790).
SCHENDEL, K. R. Wyoming Mineral Corp. 79/06/29 1p.

7908200071 Serves as 90-day notification prior to startup operations w/calcining & packaging equipment per 781117 request. Requests acknowledgement of receipt of ltr.
SCHENDEL, K. R. Wyoming Mineral Corp. 79/07/17 1p.

7908140147 Requests submittal of addl fee for amend to License SUA-1341 to expand well field.
WEISS, D. License Fee Management Branch 79/07/19 1p.

7908240622 Forwards attachments omitted from Schendel 790730 ltr.
HARGRAVE, J. Wyoming Mineral Corp. 79/07/31 1p.

--7908240623 Forwards biweekly notifications to State of WY & supporting analytical data per recent telcons.
SCHENDEL, K. R. Wyoming Mineral Corp. 79/07/30 15pp.

DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO

7908160005 Notifies that tailings embankment fill placement started on 790415. Placement will be 70% complete by 791015.
ACOSTA, A. P. Union Minerals 79/07/25 1p.

7908080175 Notifies that NRC will refund excess fee from review of 790307 application for amend to License SUA-1350.
MILLER, W. O. License Fee Management Branch 79/07/30 1p.

DOCKET 40-8636 WOLD NUCLEAR CO

7908010675 Advises that company has sold & assigned interest in certain mining claims & leases to Minerals Exploration Co. Requests NRC transfer Byproduct/Matl License SUA-1329 to Minerals Exploration Co.
BELING, D. C. Wold Nuclear Co. 79/06/06 2pp.

7908130290 Forwards Wold Nuclear request to transfer Byproduct/Matl License SUA-1329, confirming Mineral Exploration Co desire to become licensee.
CARLOS, P. C. Union Minerals 79/06/20 1p.

7908170191 Clarifies correspondence re transfer of source matl licenses from WOLD Nuclear Co to Minerals Exploration Co. NRC correspondence re SUA-1329 should be directed to author.
CARLOS, P. C. Union Minerals 79/07/18 2pp.

DOCKET 40-8663 NUCLEAR DYNAMICS, INC

7908090364 Forwards documentation & updated info re leak in surface of casing of well T-1. No contaimination associated w/incident. Well is back in operation under procedures which allow restoration to continue.
STOICK, A. F. Nuclear Dynamics 79/06/20 8pp.

7908140188 Forwards ltr of notification of well restoration activities.
STOICK, A. F. Nucor Corp. 79/07/13 2pp.

--7908140191 Outlines well restoration activities. Supporting tables encl.
CANNADAY, F. X. Nuclear Dynamics 79/07/09 6pp.

DOCKET 40-8674 PLATEAU RESOURCE

7908300714 Forwards results of chemical analyses conducted on composite ore sample purchased at Plateau Resources Ltd Blanding Ore-Buying Station.
BAILY, T. O. Woodward-Clyde Consultants 79/06/11 6pp.

7908310060 Forwards application for amend to License SUA-1326 re address change.
SEWELL, R. B. Plateau Resources, Ltd. 79/06/12 1p.

--7908310081 Application for amend to License SUA-1326 re address change.
SEWELL, R. B. Plateau Resources, Ltd. 79/06/12 2pp.

7908300710 Notifies that as means to better control access to protect individuals from exposure to radiation, plant restricted area will be redesigned to exclude administrative bldgs indicated in attachments.
SEWELL, R. B. Plateau Resources, Ltd. 79/06/19 3pp.

7908310055 Summarizes 790607 meeting w/ORNL in Oak Ridge, TN re ORNL draft EIAs for ore-buying stations located in Hanksville & Blanding, UT.
PERSON, L. S. Uranium Recovery Licensing Branch 79/07/12 2pp.

DOCKET 40-8675 ENERGY FUELS NUCLEAR, INC

7908010433 Ack receipt of 790509 ltr informing NRC of steps taken to correct violations noted during insp on 790417-19.
BROWN, G. D. Region 4, Dallas, Office of the Director 79/05/31 1p.

--7908010439 Responds to NRC 790504 ltr re violations noted. Corrective action taken, regulations & notice posted on 790417. Personnel monitoring repts for 1978 & 1979 sent to NRC on 790420.
VINCELETTE, M. D. Energy Fuels Nuclear, Inc. 79/05/09 2pp.

--7908010442 Forwards notices of violation from insp on 790417-19.
BROWN, G. D. Region 4, Dallas, Office of the Director 79/05/04 2pp.

--7908010446 Notice of violation from insp on 790417. 10CFR regulations not posted & personnel monitoring rept for CY78 not submitted promptly.
* Region 4, Dallas, Office of the Director 79/05/04 1p.

--7908010453 Notice of violation from insp on 790418. personnel monitoring rept for CY79 not submitted promptly.
* Region 4, Dallas, Office of the Director 79/05/04 1p.

7908310055 Summarizes 790607 meeting w/ORNL in Oak Ridge, TN re ORNL draft EIAs for ore-buying stations located in Hanksville & Blanding, UT.
PERSON, L. S. Uranium Recovery Licensing Branch 79/07/12 2pp.

DOCKET 40-8676 ENERGY FUELS NUCLEAR, INC

7908010433 Ack receipt of 790509 ltr informing NRC of steps taken to correct violations noted during insp on 790417-19.
BROWN, G. D. Region 4, Dallas, Office of the Director 79/05/31 1p.

--7908010439 Responds to NRC 790504 ltr re violations noted. Corrective action taken, regulations & notice posted on 790417. Personnel monitoring repts for 1978 & 1979 sent to NRC on 790420.
VINCELETTE, M. D. Energy Fuels Nuclear, Inc. 79/05/09 2pp.

--7908010442 Forwards notices of violation from insp on 790417-19.
BROWN, G. D. Region 4, Dallas, Office of the Director 79/05/04 2pp.

--7908010446 Notice of violation from insp on 790417. 10CFR regulations not posted & personnel monitoring rept for CY78 not submitted promptly.
* Region 4, Dallas, Office of the Director 79/05/04 1p.

--7908010453 Notice of violation from insp on 790418. personnel monitoring rept for CY79 not submitted promptly.
* Region 4, Dallas, Office of the Director 79/05/04 1p.

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC

7908090494 Requests that TVA be designated cooperating agency in preparation of EIS re Edgemont U Mill decommissioning plan. Requests NRC response by 790716.
GILLELAND, J. E. Tennessee Valley Authority 79/06/25 1p.

7908060491 Comments on FES. State regulations revised Feb 1979 require best available discharge control technology.
BRIGGS, K. Utah, State of 79/06/27 1p.

7908130408 Forwards revision to 780926 application for source matl license.
BAKER, C. E. Energy Fuels Nuclear, Inc. 79/07/06 1p.

--7908130412 Revision to 780926 application for source matl license. Contains several oversize drawings.
* Energy Fuels Nuclear, Inc. 79/07/06 83pp.

7908200415 Discusses EIS for decommissioning of Edgemont U Mill. NRC is amending License SUA-816 to authorize decommissioning. Util will not be designated as cooperating agency in proceeding.
SCARANO, R. A. Uranium Recovery Licensing Branch 79/07/11 1p.

7908140512 Forwards addl revisions to application for source matl license.
BAKER, C. E. Energy Fuels Nuclear, Inc. 79/07/16 2pp.

--7908140514 Revised application for source matl license.
* Energy Fuels Nuclear, Inc. 79/07/16 69pp.

7908210209 Submits info in support of application for source matl license for White Mesa Project. Discusses alternative sites selected for control measurements of particulates, radon, direct radiation & sails. Oversized drawing encl.
BAKER, C. E. Energy Fuels Nuclear, Inc. 79/08/03 6pp.

DOCKET 40-8693 OGLE PETROLEUM, INC

7908170307 Forwards SER for Minerals Exploration Co Sweetwater U Mill.
LINEHAN, J. J. Uranium Recovery Licensing Branch 79/02/16 1p.

DOCKETED ITEMS

--7908170312 SER for Minerals Exploration Co Sweetwater U Mill
* Uranium Recovery Licensing Branch 79/02/16 37pp

7908[illegible]517 Submits Amend 2 to License SUA-1336 authorizing 24-h air recirculate sampling at quarterly intervals for Ra-226, Th-230 & U air sampling for Rn-222 for 48-h per quarter & discontinuing groundwater sampling.
SCARANO, R A Uranium Recovery Licensing Branch 79/06/21 1p

7908090348 Discusses Ogle Petroleum, Inc 790322 request for mod of initial environ monitoring program commitments. Amend should be granted.
COOPERSTEIN, R Uranium Recovery Licensing Branch 79/06/21 3pp

7908030094 Accepts ground water restoration plan submitted 790608 as meeting requirement of Condition 32 of License SUA-1336.
SCARANO, R A Low Level Waste Licensing Branch 79/06/25 1p

7908080258 Submits operational water quality data for Monitor Wells 303-6-M 2 & 303-6-M 3.
CATCHPOLE, G J Ogle Petroleum, Inc 79/06/27 7pp

7908140175 Discusses radiological monitoring program, including groundwater sampling, prepared by Ogle Petroleum, inadvertently submitted to NRC. NRC matl being corrected by deletion. Deletion does not affect sampling program.
FRANCIS, E Wyoming, State of 79/07/05 2pp

--7908140187 Summarizes NRC assessment of licensee request to modify air particulate monitoring for 48-h period on quarterly basis for Ra-226, Th-230 & U & to have quarterly groundwater sampling taken upstream & downstream from site.
COOPERSTEIN, R Uranium Recovery Licensing Branch 79/06/21 3pp

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO.

7908230035 Submits quarterly rept for operations through 790630 for License SUA-1338. Documentation encl.
SPIELES, P Rocky Mountain Energy Co 79/07/31 5pp

7908230227 Forwards semiannual effluent monitoring rept for Jan-June 1979 for Reno Ceek project.
SPIELES, P Rocky Mountain Energy Co 79/07/31 1p

--7908230233 Semiannual effluent monitoring rept f r Jan-June 1979 for Reno Creek project.
* Rocky Mountain Energy Co 79/07/31 5pp

DOCKET 40-8698 PLATEAU RESOURCES, LTD

7908170183 Forwards notice of availability of NUREG-0583, "FES re Operation of Shootering Canyon U Project."
FISHER, B P Uranium Recovery Licensing Branch 79/07/31 1p

--7908170185 Notice of availabitity of NUREG-0583, "FES re Operation of Shootering Canyon U Project."
SCARANO, R A Uranium Recovery Licensing Branch 79/07/26 9pp

--7908170187 "FES re Operation of Shootering Canyon U Project."
* Office of Nuclear Material Safety & Safeguards NUREG-0583 79/07/31 280 pp

7908010655 Forwards rept "Groundwater Monitoring Wells" prepared by Woodward-Clyde Consultants.
SEWELL, R B Plateau Resources, Ltd 79/06/16 1p

--7908010665 Forwards addl copies of "Groundwater Monitoring Wells," prepared by Woodward-Clyde Consultants.
BENNEDSEN, M B Woodward-Clyde Consultants 79/06/07 1p

--7908010672 "Groundwater Monitoring Wells," prepared by Woodward-Clyde Consultants. W/oversized drawings.
* Woodward-Clyde Consultants 79/06/01 11pp

7908010659 Summarizes results of site surveys re endangered species listed in US Fish & Wildlife Svc 790522 ltr. Species sought were not in survey area. Concludes that Shootaring Canyon U Project has no impact on endangered species.
SEWELL, R B Plateau Resources, Ltd 79/06/11 2pp

7908290097 Responds to 790522 ltr re proposed Shcotering Canyon U project. Forwards endangered & threatened species assessment.
ROTHFLEISCH, J Uranium Recovery Licensing Branch 79/07/02 9pp

7908140368 Notifies of review of 790216 SER re source matl license for Minerals Exploration Co Sweetwater Mill & 780505 application for license. W/suppl info required by Reg Guide 3.5. Indicates commitments re restrictive elements in SER.
SEWELL, R B Plateau Resources, Ltd 79/07/09 7pp

7908200077 Responds to NRC 790702 ltr re Shootering Canyon U Project. Concurs w/NRC findings that project will not adversely affect any listed or proposed fish or wildlife species.
GODBY, W A Interior, Dept of, Fish & Wildlife Service 79/07/25 1p

DOCKET 40-8712 GULF OIL CORP.

7908070007 Discusses 790510 withdrawal of 781026 application for R&D in situ U license. Ofc of Controller notified to refund $176 for review fee.
MILLER, W O License Fee Management Branch 79/06/25 1p

DOCKET 40-8714 CLEVELAND CLIFFS IRON CO.

7908160102 Submits safety & environ rept on Cleveland Cliffs Iron Co application for source matl license for R&D studies on U solution extraction & recovery at Collins Draw Site, Campbell County, WY. Recommends license approval. License encl.
COOPERSTEIN, R Fuel Process & Fab. Branch (Pre 790727) 79/06/29 6pp

--7908160109 Forwards License SUA-1352.
SCARANO, R A Uranium Recovery Licensing Branch 79/06/29 2pp

--7908160115 License SUA-1352 for Cleveland Cliffs Iron Co, authorizing use of natural U in dewatered/dried ammonium uranyl carbonate for use in U recovery from U solution extraction studies.
SCARANO, R A Uranium Recovery Licensing Branch 79/06/29 5pp

DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO.

7908020128 Forwards FR notice of intent to prepare DES re issuance of source matl license.
SCARANO, R A Uranium Recovery Licensing Branch 79/06/20 1p

--7908020134 FR notice of intent to prepare DES re issuance of source matl license.
SCARANO, R A Uranium Recovery Licensing Branch 79/06/13 2pp

7908150539 Forwards preliminary questions, comments & requests for addl info re 790212 application for source matl license.
ROTHFLEISCH, J Uranium Recovery Licensing Branch 79/06/22 15pp

7908020543 Responds to NRC 790615 ltr re proposed Nine Mile Lake U recovery project. Lists species which may be found in project area. Endangered Species Act Amend, Section 7(c), requires preparation of biological assessment.
REGAN, D M Interior, Dept of, Fish & Wildlife Service 79/06/02 1p

7908140195 Forwards Jan 1979 Environ Rept & draft cover ltr per NRC instructions for distribution. Rept submitted per 790212 application for source matl license. Rept not encl.
LUCK, A D Rocky Mountain Energy Co 79/07/03 2pp

7908230275 Requests extension to 790731 for submission of written comments re notice of availability of environ rept & intent to prepare draft EIS on issuance of source matl license.
EAST, D J Wyoming Outdoor Council 79/07/12 1p

7908170133 Recommends full evaluation of project radiological impact.
LOCHSTET, W A Environmental Coalition on Nuclear Power 79/07/16 1p

7908220215 Responds to 790622 questions, comments & request for addl info re application for source matl license. Forwards rept, "Suppl to Environ Rept, Winter Wildlife Survey," re wildlife data collected during winter of 1978.
LUCK, A D Rocky Mountain Energy Co 79/07/16 200pp

--7908220220 "Suppl to Environ Rept, Winter Wildlife Survey."
* Dames & Moore 79/03/20 15pp

7908140408 Advises that no existing units of Natl Park Svc will be affected by facility. Urges application of best available technology to control air quality emissions.
STRAIT, R. A. Interior, Dept. of, National Park Service 79/07/17 1p.

7908090015 Comments on proposed Nine Mile Lake mine & plant supports project. US must continue to develop natural resources.
* Affiliation Unknown. 79/07/20 1p.

7908200083 Comments on 790724 EIS scoping meeting for Rocky Mountain Energy Co project basis for project provided by preceeding 3-yr pilot project. Will provide comments on draft EIS upon availability.
HALL, J. D. Interior, Dept. of, Bureau of Reclamation 79/07/30 1p.

DOCKET 40-8722 BRUSH-WELLMAN, INC.

7908210031 Forwards Licence SUA-1354, authorizing recovery of U from beryllium mill tailings solution, & pertinent NRC regulations.
SCARANO, R. A. Uranium Recovery Licensing Branch 79/06/06 6pp.

--7908210034 License SUA-1354 for Brush Wellman, Inc, authorizing recovery of natural U in U peroxide wet-cake form from beryllium mill tailings.
SCARANO, R. A. Uranium Recovery Licensing Branch 79/06/06 5pp.

DOCKET 40-8725 GULF MINERAL RESOURCES CO.

7908270519 Forwards application for byproduct matl license for Mt Taylor U Mill Application should be considered withdrawn if Congress eliminates need for separate NRC & state licensing.
MOONEY, F. S. Gulf Oil Corp., Gulf Mineral Resources Co. 79/08/02 1p.

--7908270523 Byproduct matl license application & executive summary re Mt Taylor U Mill project. Vol 1 of 4-vol application.
* Gulf Oil Corp., Gulf Mineral Resources Co. 79/08/22 100pp.

--7908270531 "Environ Rept, Part 1," for Mt Taylor U Mill project. Vol 2 of 4-vol byproduct matl license application.
* Gulf Oil Corp., Gulf Mineral Resources Co. 79/08/02 250pp.

--7908270536 "Environ Rept, Part 2," for Mt Taylor U Mill project. Vol 3 of 4-vol byproduct matl license application.
* Gulf Oil Corp., Gulf Mineral Resources Co. 79/08/02 250pp.

--7908270546 "Radiation Safety Program & Appendices," for Mt Taylor U Mill project. Vol 4 of 4-vol byproduct matl license application.
* Gulf Oil Corp., Gulf Mineral Resources Co. 79/08/02 250pp.

7908130571 Discusses 790620 meeting in Denver w/NRC re licensing & EIS process for Mt Taylor U Mill project. EIS licensing process was detailed by NRC. Provisions made for scoping meeting to present proposed alternative tailings mgt plans.
RASMUSSEN, K. H. Gulf Oil Corp., Gulf Mineral Resources Co. 79/06/28 2pp.

7908090430 Discusses initiation of program to obtain addl data & perform addl analyses re below grade burial options. Target date to complete work is 790830.
ROGERS, W. L. Gulf Oil Corp., Gulf Mineral Resources Co. 79/07/05 3pp.

7908170252 Proposes 790731 meeting between State of NM, NRC & vendor to discuss progress of addl work implementation of mill tailings mgt plan described in Attachment 2 to minutes of 790619 joint meeting. Forwards proposed agenda.
ROGERS, W. L. Gulf Oil Corp., Gulf Mineral Resources Co. 79/07/19 2pp.

DOCKET 40-8726 NEW MEXICO HEALTH - ENVIRONMENT DEPT.

7908020401 Forwards 13 pages to be substituted & four pages to be added to Bokum Resources Corp application for radioactive matl license.
TOPP, A. A. New Mexico, State of. 79/06/11 1p.

--7908020404 Addl pages to be substituted or added to Bokum Resources Corp application for radioactive mtl license.
* New Mexico, State of. 79/06/11 18pp.

7908060484 Forwards 790621 press release re disapproval of Bokum Resources Corp discharge plan. Copy of St of NM Environ Improvement Div 790621 ltr to Bokum encl.
TOPP, A. A. New Mexico, State of. 79/06/25 9pp.

7908060511 Forwards 790620 & 21 ltrs to Bokum Resources Corp, disapproving proposed discharge plan.
BACA, T. E. New Mexico, State of. 79/06/25 4pp.

7908230029 Forwards substitute pages 10 & 11 for Bokum Resources Corp application.
TOPP, A. A. New Mexico, State of. 79/07/24 3pp.

DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP.

7908310551 Environ rept in support of license application for U recovery operation. Assesses site location, plant operation & environ & safety considerations.
* Kerr-McGee Corp. 79/06/07 14pp.

7908310109 Application for source matl license authorizing U recovery activities utilizing ion exchange techniques on minewater.
SHELLEY, W. J. Kerr-McGee Corp. 79/06/06 1p.

--7908310540 Application for source matl license authorizing U recovery activities utilizing ion exchange techniques on minewater.
SHELLEY, W. J. Kerr-McGee Corp. 79/06/07 2pp.

DOCKET 40-8728 TETON EXPLORATION DRILLING CO., INC.

7908280277 Forwards application for source matl licence, environ rept & application fee for R&D test for in situ recovery of U.
MELROSE, T. G. Teton Exploration Drilling Co., Inc. 79/07/30 1p.

--7908280290 Application for source matl license authorizing possession & use for R&D of 3,000 kg U-308 in form of slurry.
LISCO, R. K. Teton Exploration Drilling Co., Inc. 79/07/30 2pp.

--7908280299 "Environ Rept for Source Matl License" re U in situ leaching. Thirteen oversized drawings encl.
* Teton Exploration Drilling Co., Inc. 79/07/30 233pp.

7908310047 Requests 790618 meeting to discuss licensing requirements for R&D U in situ test in South Powder River Basin, WY.
HERLIHY, D. M. Teton Exploration Drilling Co., Inc. 79/05/31 1p.

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7908060168 Requests prompt forwarding of Class III fee for 790322 safeguards contingency plan.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp.

7908070598 Forwards modified physical security plan. Plan withheld (ref 10CFR2.790).
CAHILL, W. J. Consolidated Edison Co. of New York. 79/08/01 1p.

7908210015 Forwards security force qualification & training plan. Plan withheld (ref 10CFR2.790).
ZARAKAS, P. Consolidated Edison Co. of New York. 79/08/17 1p.

G. Adjudicatory correspondence

7908160111 Responds to 790323 request for assessment of reactor earthquake resistence & re-examination of computer codes used for seismic analyses nuclear plants. Re-examinations undertaken; no basis found for restricting operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/25 2pp.

--7908160114 Requests assessment of resistance of reactor to earthquake & re-examination of computer codes used for seismic analyses of nuclear power plants.
DICKINSON, I. P. Citizens Committee for Protection of the Environment. 79/03/23 1p.

7908220409 Memo submitting opinion of MC Farrar re dissenting vote concerning portions of ALAB-422 & ALAB-436. Majority will respond after review.
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 79/08/03 58pp.

H. General correspondence

7908230242 Responds to 790323 ltr requesting info re assessment of reactor earthquake resistance & re-examination of computer codes used for seismic analyses Re-examinations found no basis for discontinuing operation of facilities.
DENTON, H.R. Office of Nuclear Reactor Regulation 79/07/25 2pp

J. Insurance & indemnity information

7908090375 Forwards 790731 projection for 790801-800731, demonstrating that util will have available cash flow &/or cash reserves sufficient to pay max $20 million retrospective premium.
CAHILL, W.J. Consolidated Edison Co. of New York 79/08/01 2pp

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors 79/06/04 52pp

7908220302 Forwards Amends 26 & 57 to Licenses DPR-5 & DPR-26, respectively & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1 79/07/11 3pp

--7908220309 Amends 26 & 57 to Licenses DPR-5 & DPR-26, respectively, revising Tech Specs to consolidate all ref to thermal plume mapping.
SCHWENCER, A. Operating Reactors Branch 1 79/07/11 15pp

--7908220314 Notice of issuance & availability of Amends 26 & 57 to Licenses DPR-5 & DPR-26, respectively.
SCHWENCER, A. Operating Reactors Branch 1 79/07/11 2pp

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W.P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908010343 Notifies that new milk sampling location has been chosen per ETS. New site is Hilltop Hanover Farm.
CAHILL, W.J. Consolidated Edison Co. of New York 79/07/19 2pp

7908080527 Forwards 790720 application for amend to License DPR-26. Application requests amend to App B Tech Specs re requirements for radiological effluents & radiological environ monitoring. Proposed changes respond to Grimes ltr.
CAHILL, W.J. Consolidated Edison Co. of New York 79/07/20 3pp

--7908080529 Application for amend to License DPR-26, App A & B Tech Specs, consisting of page revisions re radiological effluents & environ monitoring.
* Consolidated Edison Co. of New York 79/07/31 142pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W.P. Quality Assurance Branch 79/07/24 1p

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D.G. Division of Operating Reactors 79/08/03 53pp

7908310478 FOIA request for meteorological data, including wind direction & velocity, precipitation, relative humidity & barometric pressure, collected for past five years by facilities.
ROACH, R. Malcolm & Purnie, Inc. 79/08/03 1p

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W.P. Assistant Director for Operating Reactor Projects 79/08/09 5pp

7908240372 Notifies that 1980 aquatic surveillance program will be modified: river population studies of entrainable size organisms will not be conducted & mark-recapture studies will be limited to yearling & older fish in 1980.
CAHILL, W.J. Consolidated Edison Co. of New York 79/08/20 3pp

7908310485 Responds to FOIA request for meteorological data collected for past five years by facilities. Info located in Table 4A of "Effluent & Waste Disposal Semi-Annual Rept" available at specified LPDR.
FELTON, J.M. Division of Rules and Records 79/08/21 1p

Q. Inspection reports, IE Bulletins & correspondence

7908080501 Responds to IE Bulletin 79-10 re util requalification training programs. Forwards operator & senior operator examination data.
CAHILL, W.J. Consolidated Edison Co. of New York 79/05/21 3pp

7908070778 Interim rept "Concrete Expansion Anchor Verification Program."
* Consolidated Edison Co. of New York 79/07/31 29pp

7908070198 Responds to IE Bulletin 79-01 re environ qualification for Class IE equipment. Forwards tables indicating scope of review & list of document ref. Info re Unit 1 will be forwarded when unit is returned to svc.
ZARAKAS, P. Consolidated Edison Co. of New York 79/06/13 31pp.

7908070775 Responds to IE Bulletin 79-02 & Revision 1 re pipe support base plate designs. Forwards interim rept, "Concrete Expansion Anchor Verification Program."
CAHILL, W.J. Consolidated Edison Co. of New York 79/07/06 4pp

7908090671 Responds to IE Bulletin 79-11 Westinghouse Types DB-50 & DB-75 circuit breakers w/overcurrent trip devices used in safety-related sys & in spares at Unit 2, but not in Unit 1. Details encl.
CAHILL, W.J. Consolidated Edison Co. of New York 79/07/09 6pp

7908170368 Forwards response to IE Bulletin 79-13 for Unit 1. Unit 2 in shutdown mode since 741031 pending company decision re installation of ECCS.
CAHILL, W.J. Consolidated Edison Co. of New York 79/07/16 4pp.

7908010422 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/17 1p

7908060211 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908030229 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/19 1p

7908100219 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908100330 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908090287 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/30 1p

7908280060 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/07 1p

7908230295 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/08 1p

7908270540 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908280255 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/13 1p

7908310259 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/14 1p

7908300113 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/15 1p

7908290584 Forwards "Steam Generator Operating History Questionnaire for Steam Generator Inservice Insp from Mar 1975-Mar 1978" in response to 771209 & 780210 ltrs.
CAHILL, W.J. Consolidated Edison Co. of New York 79/08/23 1p

--7908290592 "Steam Generator Operating History Questionnaire for Steam Generator Inservice Insp from Mar 1975-Mar 1978."
* Consolidated Edison Co. of New York 79/08/31 51pp

R Periodic operating reports & related correspondence

7908170399 Forwards species code list & info re circulating water temp, gross electrical output & river water discharge for Jul 1979 for Permit NY0004472.
MONTI, W.A. Consolidated Edison Co. of New York 79/08/10 17pp

7908220391 Forwards tabulation of daily record of fish collection for Jul 1979.
ZARAKAS, P. Consolidated Edison Co. of New York 79/08/15 4pp

DOCKET 50-5 PENNSYLVANIA STATE UNIV. RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

7908310350 Responds to NRC 790730 request for info re physical protection measures taken to detect theft of SNM of moderate & low strategic significance & effects of changes on univ reactor.
CUNNINGHAM, R.G. Pennsylvania State Univ 79/08/15 1p

G Inspection reports, IE Bulletins & correspondence

7908070110 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/06/22 1p

7908280272 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/10 1p

7908310240 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/14 1p

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

D NRC Draft/Final Environmental Statements, supps & correspondence

7908270098 Responds to 790705 ltr to JM Hendrie requesting preparation of EIS prior to decontamination of facility as result of K Drey 790310 petition. Decontamination will not start until need for EIS is resolved.
DENTON, H.R. Office of Nuclear Reactor Regulation 79/07/31 1p

--7908270104 Requests EIS re proposal to flush chemical solvent through reactor piping at facility. Radionuclide migration & other related matters must be determined.
MCAVOY, S. Illinois Environmental Council 79/07/05 1p

F Security, medical, emergency & fire protection plans

7908130159 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch 79/07/03 2pp

7908160367 Forwards request for addl info re contingency plans. Encl withheld (ref 10CFR2.790).
ZIEMANN, D.L. Operating Reactors Branch 2 79/07/19 2pp

7908270139 Forwards BNL 790703 ltr re SER of fire protection program at facility.
LAINAS, G. Plant Systems Branch 79/07/25 3pp

7908210284 Forwards addl info requested on fire protection mod re firewater sys feeds & exposed structural steel reviews in progress. Two oversized drawings encl.
JANECEK, R.F. Commonwealth Edison Co. 79/08/02 5pp

7908200216 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/08/16 1p

G Adjudicatory correspondence

7908170069 Responds to 790515 postcard. Reviews purpose of application for storage of spent fuel at either plant. Risks are well-known & very low. Hearing will be held soon.
IPPOLITO, T.A. Operating Reactors Branch 3 79/08/03 1p

7908170285 Responds to 790531 ltr opposing transport of spent fuel between plants. Explains purpose of util application. Risks are well-known & very low. Public hearing will be held soon.
IPPOLITO, T.A. Operating Reactors Branch 3 79/08/03 1p

7908170292 Responds to 790507 ltr opposing transport of spent fuel between plants. Explains purpose of util application. Risks are well-known & very low. Public hearing will be held soon.
IPPOLITO, T.A. Operating Reactors Branch 3 79/08/03 1p

7908170297 Responds to 790514 ltr opposing transport of spent fuel between plants. Explains purpose of util application to allow storage. Risks are well known & very low. Public hearing will be held soon.
IPPOLITO, T.A. Operating Reactors Branch 3 79/08/03 1p

7908200010 Responds to 790524 ltr opposing transport of spent fuel between plants. Explains purpose of application. Risks are well known & very low. Public hearing will be held soon.
IPPOLITO, T.A. Operating Reactors Branch 3 79/08/03 1p

7908200035 Responds to 790510 ltr opposing transportation of spent fuel. Public hearing will be held on shipment in Fall 1979.
IPPOLITO, T.A. Operating Reactors Branch 3 79/08/03 1p

7908200039 Responds to 790507 postcard expressing opposition to transportation of spent fuel. Public hearing on proposed shipment will be held Fall 1979.
IPPOLITO, T.A. Operating Reactors Branch 3 79/08/03 1p

7908290108 Responds to 790502 & 12 ltrs re hearing on spent fuel transfer. Hearing will be held no earlier than Sept 1979.
IPPOLITO, T.A. Operating Reactors Branch 3 79/08/03 1p

H General correspondence

7908210498 Expresses concern re upcoming decontamination of facility prior to completion of EIS & disposal of highly corrosive & radioactive solvent remaining after decontamination completed. Requests info.
BERK, A.J. Affiliation Unknown 79/08/08 1p

P Operating license stage documents & correspondence

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH, H. Operating Reactors Branch 2 (Pre 790625). 79/04/19. 5pp.

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project.
LEVIN, H.A. Systematic Evaluation Programs Bran. (Pre 790625). 79/03/08. 10pp.

7908140498 Forwards responses to 790418 questions re chemical decontamination of primary cooling sys.
DENTON, H.R. Office of Nuclear Reactor Regulation 79/05/21 16pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors 79/06/04 52pp.

7908070652 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/06/22 3pp.

DOCKETED ITEMS

7908080047 Notification of 790629 meeting w/Mark I owners group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program proposed agenda encl
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908130310 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires NRC initial notification.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/09. 1p.

7908080719 Confirms that meeting at util corporate office has been rescheduled for 790719 at 3 PM Location, purpose & attendees discussed in NRC 790612 ltr.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/10. 1p.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908070769 Summary of 790613 meeting w/util & Sargent & Lundy engineers re technical questions related to SEP seismic DBE review.
CHENG, T. M. Systematic Evaluation Program Branch. 79/07/12. 4pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908160092 Forwards request for addl info re requirements for preparation of NRC generic rept on BWRs.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/17. 19pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. VASSALLO, D. B. Division of Project Management. 79/07/18. 58pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070332 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/19. 1p.

7908170468 Forwards summary of 790628 meeting re NRC evaluation program for operating BWR plants & near-term OLs.
* Office of Nuclear Reactor Regulation. 79/07/19. 3pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908010445 Responds to NRC 790618 ltr re SEP. Forwards addl info re Topic VIII-3.B, onsite dc battery sys.
JANECEK, R. F. Commonwealth Edison Co. 79/07/25. 3pp.

7908010470 Responds to informal info request re SEP review of new fuel storage areas.
JANECEK, R. F. Commonwealth Edison Co. 79/07/25. 2pp.

7908020025 Responds to 790625 ltr to JM Hendrie requesting EIS prior to chemical decontamination. Currently reviewing need for statement as result of Drey 790319 petition.
EISENHUT, D. G. Division of Operating Reactors. 79/07/25. 2pp.

--7908020027 Notice of Drey 790319 petition requesting EIS be prepared on proposed decontamination experiments. Petition being treated per 10CFR2.206.
BOYD, R. S. Office of Nuclear Reactor Regulation. 79/04/09. 1p.

--7908020031 Urges that EIA be prepared prior to chemical decontamination.
VON ZELLEN, S. W. Northern Illinois Univ. 79/06/25. 1p.

7908170265 Responds to 790625 ltr requesting that EIS be prepared prior to chemical decontamination. As result of petition by K Drey, need for impact statement is under review. FR notice & response to K Drey encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/25. 2pp.

--7908170271 Ack receipt of 790319 petition requesting that EIS be prepared on proposed decontamination experiments. Forwards FR request.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/04/09. 1p.

--7908170275 Notice of petition by K Drey requesting that EIS be prepared on proposed decontamination experiments. Petition treated as request for action.
BOYD, R. S. Office of Nuclear Reactor Regulation. 79/04/09. 1p.

--7908170280 Expresses concern re proposed decontamination & requests vigorous environ assessment. Primary concern involves leakage of chelating agents contained in solvent into disposal ground sediments. Suggests chemical degradation.
CRERAR, D. A. Princeton Univ. 79/06/25. 1p.

7908280242 Responds to 790625 ltr to Hendrie requesting that EIS be prepared prior to chemical decontamination. Need for statement under review as result of 790310 petition. Provides answers to questions in ltr.
EISENHUT, D. G. Division of Operating Reactors. 79/07/25. 3pp.

--7908280264 Notice of K Drey 790319 request for preparation of EIS.
BOYD, R. S. Office of Nuclear Reactor Regulation. 79/04/09. 2pp.

7908020419 Responds to 790606 ltr re SEP Topic VI-4. Forwards tables & answers to Questions 1-7 re major protective coating sys in containment, pipe & hanger surface & amounts of organic matl inside containment.
JANECEK, R. F. Commonwealth Edison Co. 79/07/27. 4pp.

7908020460 Submits schedule for addl response to NRC issues re containment purging during normal plant operation.
REED, C. Commonwealth Edison Co. 79/07/30. 2pp.

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co. 79/07/30. 2pp.

7908210022 Responds to 790622 ltr to Hendrie requesting that EIS be prepared prior to chemical decontamination. Need for EIS currently being reviewed as result of Drey 790310 petition. Forwards 790409 ltr to Drey & 790409 FR notice.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/30. 3pp.

7908230676 Forwards safety evaluation supporting util 770318 evaluation of postulated fuel handling accident inside containment. Potential consequences are within exposure guidelines.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/08/01. 2pp.

--7908230680 Safety evaluation supporting util 770318 submittal re postulated fuel handling accident inside containment. Environ impacts of accident addressed in Section 7.1 of Nov 1973 FES.
* Office of Nuclear Reactor Regulation. 79/08/01. 3pp.

7908200287 Ack receipt of 790709 ltr requesting info re operation of isolation (emergency) condensers. Submits station procedures defining proper methods of initiating makeup to condenser shell.
JANECEK, R. F. Commonwealth Edison Co. 79/08/03. 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908200336 Discusses status of progress towards completion of HPCI sys. Requests meeting w/NRC to discuss technique & scope of analysis re App. K calculations.
JANECEK, R. F. Commonwealth Edison Co. 79/08/07. 1p.

7908270099 Notification of 790815 meeting w/representatives of Mark I containment owners group re NRC acceptance criteria for implementation of Mark I containment long-term program & schedule for generic program closure.
GRIMES, C. I. Plant Systems Branch. 79/08/07. 2pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. P. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908200358 Forwards responses to NRC 790720 questions re seismic analysis of reactor & steam drum support structure inside containment & calculation of local stresses of primary containment penetrations.
JANECEK, R.F. Commonwealth Edison Co. 79/08/13. 8pp.

7908200380 Forwards info requested in NRC 790629 & 0724 ltrs re capabilities & technical resources available to handle unusual events.
JANECEK, R.F. Commonwealth Edison Co. 79/08/13. 1100pp.

7908210256 Forwards requested info re seismic analysis per 790720 telcon between util, Sargent & Lundy & NRC.
JANECEK, R.F. Commonwealth Edison Co. 79/08/13. 8pp.

7908240447 Forwards revised list of welds to be inspected prior to chemical cleaning of primary sys. Replaces info in 790205 ltr, due to inaccessibility & radiation exposure problems.
JANECEK, R.F. Commonwealth Edison Co. 79/08/16. 2pp.

7908230420 Informs that GE rept NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs" was submitted to NRC by TD Keenan 790817 ltr to D Ross. Remainder of info follows in 791116 rept.
JANECEK, R.F. Commonwealth Edison Co. 79/08/20. 1p.

9. Inspection reports, IE Bulletins & correspondence

7908020548 Forwards IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06 on 790326-28, notice of violation & notice of deviation.
HEISHMAN, R.F. Region 3, Chicago. Reactor Operations Nuclear Support Branch. 79/05/10. 2pp.

--7908020555 Notice of violation from insp on 790326-28.
* Region 3, Chicago, Office of the Director. 79/05/09. 1p.

--7908020566 Notice of deviation from insp on 790326-28.
* Region 3, Chicago, Office of the Director. 79/05/09. 1p.

--7908020572 IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06 on 790326-28. Noncompliance noted: failure to conduct five brigade training sessions on quarterly basis & failure to develop procedure for control of combustibles.
RIDEN, M.D., LITTLE, W.S. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/05/09. 5pp.

7908010223 Forwards IE Insp Repts 50-010/79-12, 50-237/79-15 & 50-249/79-13 on 790501-0601 & notice of violation.
HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/15. 2pp.

--7908010227 Notice of violation from insp on 790501-0601.
* Region 3, Chicago, Office of the Director. 79/06/13. 1p.

--7908010231 IE Insp Repts 50-010/79-12, 50-237/79-15 & 50-249/79-13 on 790501-0601. Noncompliance noted: reactor was started using battery not connected to bus.
SARKER, S.L., SPESSARD, R.L. Region 3, Chicago, Office of the Director. 79/06/13. 11pp.

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790828 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T.A. Operating Reactors Branch 3 (Prev 790625). 79/06/20. 44pp.

7908100298 Advises that IE Circular 79-09, "Occurences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus," was issued to listed licensees.
PAPPAS, I. Region 3, Chicago, Office of the Director. 79/06/25. 3pp.

7908080523 Responds to IE Bulletin 79-11. No Westinghouse DB-50 & DB-75 circuit breakers used in safety-related sys.
REED, C. Commonwealth Edison Co. 79/07/02. 1p.

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co. 79/07/05. 9pp.

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc. 79/05/31. 24pp.

7908150349 Supplements response to IE Bulletin 79-11. Westinghouse DB-50 & DB-75 circuit breakers are neither used in safety-related sys nor stored as spares at facilities.
REED, C. Commonwealth Edison Co. 79/07/12. 2pp.

7908020279 Advises that IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys," was issued to listed utils.
PAPPAS, I. Region 3, Chicago, Office of the Director. 79/07/20. 2pp.

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908240513 Responds to IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." Procedures involving reactor criticality, control rod withdrawal sequences & operator training program were modified in 1977.
REED, C. Commonwealth Edison Co. 79/07/30. 9pp.

7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED, C. Commonwealth Edison Co. 79/08/01. 2pp.

7908170019 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/08/08. 1p.

7908300242 Lists util recipients of IE Circular 79-17, "Contact Problem in SB-12 Switches on GE Metalclad Circuit Breakers."
PAPPAS, H. Region 3, Chicago, Office of the Director. 79/08/15. 3pp.

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908300459 Forwards semiannual "Rept of Radioactive Effluent Discharges & Solid Radwaste" for Jan-June 1979.
STEPHENSON, B.B. Commonwealth Edison Co. 79/08/14. 1p.

--7908300466 "Rept of Radioactive Effluent Discharges & Solid Radwaste" for Jan-June 1979.
* Commonwealth Edison Co. 79/06/30. 15pp.

DOCKET 50-13 BABCOCK & WILCOX CO. CRITICAL FACILITY

P. Operating license stage documents & correspondence

7908310410 Responds to 790730 ltr requesting info from nonpower reactor licensees re effect of safeguards rule. Upgrade rule necessitates protection of reactor as Category I facility for physical protection purposes.
OLSEN, A.F. Babcock & Wilcox Co. 79/08/15. 3pp.

DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908140624 Notifies that utils have formed intermediate BWR plant owners group to coordinate evaluation of knowledge & experience gained & lessons learned from TMI. Requests meeting on 790816 to discuss proposed actions.
JENS, J.H. Detroit Edison Co. 79/08/09. 2pp.

DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

P. Operating license stage documents & correspondence

7908300421 Forwards Preprint Special Publication 56, "Geological Evaluation of GE Test Reactor Site, Vallecitos, Alameda County, CA."
DAVIS, J.F. California, State of. 79/08/16. 1p.

DOCKETED ITEMS

--7908300433 Preprint Special Publication 56, "Geological Evaluation of GE Test Reactor Site, Vallecitos, Alameda County, CA."
RICE, S., STEPHEN, E., REAL, C. California, State of 79/08/31
28pp.

DOCKET 50-20 MASSACHUSETTS INST. OF TECH. RES. REACTOR

P. Operating license stage documents & correspondence

7908170136 Responds to 790504 ltr re plan to increase activities involving metals & alloys to be activated at facility or received from other reactors License R-37 must be amended to permit receipt & possession of byproduct matl.
REID, R. W. Operating Reactors Branch 4 79/07/31 2pp.

7908310402 Ack receipt of 790730 ltr re impact of safeguards upgrade rule Provides info re costs for shutdown hardware & security upgrade, annual maint costs, effect of loss on US industry, medical research & treatment & educational programs.
CLARK, L. Massachusetts Institute of Technology 79/08/20 9pp.

G. Inspection reports, IE Bulletins & correspondence

7908280269 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/10 1p.

7908310239 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/14 1p.

DOCKET 50-22 WESTINGHOUSE TEST REACTOR

G. Inspection reports, IE Bulletins & correspondence

7908070091 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/06/22 1p.

7908280249 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/10 1p.

7908310224 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/14 1p.

DOCKET 50-27 WASHINGTON STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

7908020593 Forwards Amend 9 to License R-76 & safety evaluation.
REID, R. W. Operating Reactors Branch 4 79/07/02 3pp.

--7908020599 Amend 9 to License R-76, increasing percent enrichment of U-235, amount of SNM exempt & how exempt.
REID, R. W. Operating Reactors Branch 4 79/07/02 4pp.

--7908020603 Safety evaluation supporting Amend 9 to License R-76.
* Operating Reactors Branch 4 79/07/02 3pp.

7908080259 Forwards notice of proposed renewal of amended facility OL. Notice relates to 790515 application for amend to renew License R-76.
REID, R. W. Operating Reactors Branch 4 79/07/09 2pp.

--7908080267 Notice of proposed renewal of amended facility operating license Renewal would extend expiration date to Jul 8, 2019.
REID, R. W. Operating Reactors Branch 4 79/07/09 3pp.

7908230167 Determines that operator requalification program continues to meet requirements of Section 50.54(i-1) of 10CFR50 & App A of 10CFR55.
COLLINS, P. F. Operator Licensing Branch 79/07/27 1p.

G. Inspection reports, IE Bulletins & correspondence

7908170032 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action require[d]
ENGELKEN, R. H. Region 5, San Francisco, Office of the [D]irector
79/08/10 1p.

7908310198 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/08/14 1p.

R. Periodic operating reports & related correspondence

7908140712 Forwards annual operating rept for period 780701 to 790630.
WILSON, W. E. Washington State Univ. 79/08/08 1p.

--7908140717 Annual operating rept for period 780701-790630.
HAWLEY, S. C. Washington State Univ. 79/08/08 7pp.

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

7908060155 Requests prompt forwarding of Class III fee for 790322, 23 & 0430 safeguards contingency plans.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp.

7908170421 Forwards preliminary physical security plan. Plan withheld (ref 10CFR2.790).
GROCE, R. H. Yankee Atomic Electric Co. 79/08/13 1p.

P. Operating license stage documents & correspondence

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH, H. Operating Reactors Branch 2 (Pre 790625) 79/04/19
5pp.

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project.
LEVIN, H. A. Systematic Evaluation Programs Branch (Pre 790625)
79/03/08 10pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed ag[a]inst any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors [7]/06/04 52pp.

7908070474 Notifies of intent to install second communications sys. linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/06/22 3pp.

7908230104 Responds to 790531 ltr & 790613 telcon re SEP Topic III-5.A, high energy line breaks inside containment. Discusses nine conditions established to determine piping & equipment which must remain available for high energy line break.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/09 2pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors, VASSALLO, D. B. Division of Project Management 79/07/18 58pp.

7908070269 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/18 1p.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors
79/07/18 1p.

7908170201 Forwards model license condition requiring implementation of secondary water chemistry monitoring & control program. Condition replaces 1975 proposed Tech Spec changes re corrosion of steam generator tubes.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/23 4pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908080222 Responds to 780202 ltr re reactor cavity annulus seal ring. Requests analysis of seal ring effect on other containment safety components should ring become missile. Statement promising seal ring removal before next refueling outage.
ZIEMANN, D L. Operating Reactors Branch 2 79/07/26 2pp

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J P. Standardization Branch 79/07/30 64pp

7908170088 Finds basis unacceptable for not proposing design mod to electrical power distribution sys undervoltage protection. Requests design mod & changes in Tech Specs based on positions in 770603 ltr.
ZIEMANN, D L. Operating Reactors Branch 2 79/07/31 2pp

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D G. Division of Operating Reactors 79/08/03 53pp

7908140550 Forwards info re mgt & technical resources available to handle unusual events, in response to NRC 790724 ltr.
GROCE, R H. Yankee Atomic Electric Co. 79/08/08 24pp

7908230155 Requests util's provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W P. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908240460 Forwards rept, "Assessment of Effect of Increased Fuel Rod Fill Gas Pressure on Core XIV ECCS Performance Analysis."
VANDENBURGH, D. Yankee Atomic Electric Co. 79/08/21 2pp

--7908240463 "Assessment of Effect of Increased Fuel Rod Fill Gas Pressure on Core XIV ECCS Performance Analysis."
* Yankee Atomic Electric Co. 79/08/21 8pp

9. Inspection reports, IE Bulletins & correspondence

7908030172 Submits addl info in response to IE Bulletin 79-06a. Emergency procedures revised to address symptoms of loss of cooling & also direct operator to consult saturation pressure curve which is now part of affected procedures.
MOODY, D E. Yankee Atomic Electric Co. 79/06/20 4pp

7906130626 Forwards IE Insp Rept 50-029/79-03 on 790422-25. No noncompliance noted.
BRUNNER, E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/20 2pp

--7908130638 IE Insp Rept 50-029/79-03 on 790422-25. No noncompliance noted. Major areas inspected: shift logs & operating records, operability of emergency safeguard sys & followup of LERs.
LAZARUS, W J. Region 1, Philadelphia, Office of the Director
KEIMIG, R R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/19 10pp

7908130652 Forwards IE Insp Rept 50-029/79-04 on 790424-27. No noncompliance noted.
BRUNNER, E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/22 2pp

--7908130660 IE Insp Rept 50-029/79-04 on 790424-27. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, administrative controls for surveillance procedures & surveillance testing.
BAUNACK, W H., ZIMMERMAN, R P. Region 1, Philadelphia, Office of the Director. KISTER, H B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/19 11pp

7908070673 Responds to IE Bulletin 79-11 re faulty overcurrent trip devices in Westinghouse circuit breakers. Westinghouse Type DB circuit breakers are not used in safety-related Class IE circuits.
GROCE, R H. Yankee Atomic Electric Co. 79/07/07 1p

7908160563 Advises that util is presently compiling addl data to suppl response to IE Bulletin 79-02. Addl info will be submitted before 790720.
MOODY, D E. Yankee Atomic Electric Co. 79/07/11 1p

7908070712 Responds to IE Bulletin, Item 5. Steam generator feedwater nozzles shall be performed in mid-Sept 1979. Three emergency methods are available to provide diverse indications of leakage in case of feedwater leak in containment.
MOODY, D E. Yankee Atomic Electric Co. 79/07/16 2pp

7908010528 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/07/17 1p

7908060507 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908270511 Responds to IE Bulletin 79-14. Proper support location & design of piping sys is evidenced by lack of any piping or support distress when constantly loaded.
GRACE, R H. Yankee Atomic Electric Co. 79/07/18 1p

7908030289 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/07/19 1p

7908200004 Responds to IE Bulletin 79-02 & 790621 request for addl info re visual insps on hangers & restraints for ECCS vapor container long-term recirculation sys & pressurizer safety & relief valve discharge line.
MOODY, D E. Yankee Atomic Electric Co. 79/07/20 2pp

7908100285 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908100353 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908090340 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/07/30 1p

7908280203 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/08/07 1p

7908300782 Requires addl info re IE Bulletins 79-06A & 79-06A, Revision 1.
ZIEMANN, D L. Operating Reactors Branch 2 79/08/07 3pp

7908230369 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/08/08 1p

7908280031 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908280362 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/08/13 1p

7908310308 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

7908300475 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director 79/08/15 1p

DOCKETED ITEMS

R Periodic operating reports & related correspondence

7908140365 Forwards monthly operating rept for July 1979.
MOODY, D E Yankee Atomic Electric Co. 79/08/10 1p

--7908140373 Monthly operating rept for July 1979.
SJOGREN, R M Yankee Atomic Electric Co. 79/08/10 5pp

S Reportable occurrences/ LERs & related correspondence

7908020440 Forwards LER 79-015/00X-0.
AUTIG, H A Yankee Atomic Electric Co. 79/07/30 1p

--7908020445 LER 79-015/00X-0 on 790501 during collection of direct external radiation monitors,monitors at stations 12 & 21 were found missing.Cause of loss unknown.Monitors replaced.
LONG, D G Yankee Atomic Electric Co. 79/07/30 1p

7908030204 RO 50-29/79-18 errors found in Exxon fuel rod pre-pressurization that could permit less conservative operation than assumed in analysis.CAPCON-THERMAL-2 computer calculation performed to access impact.
MOODY, D E Yankee Atomic Electric Co. 79/07/30 2pp

7908140661 Forwards LER 79-018/01T-0.
AUTIG, H A Yankee Atomic Electric Co. 79/08/10 1p

--7908140666 LER 79-018/01T-0 on 790727 informed of deviation from specified value in fuel pin pressure.Caused by mfg techniques.Mfg changed method of prepressurization employed at fabrication facility.
MAY, E L Yankee Atomic Electric Co. 79/08/10 2pp

DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7908070094 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p

7908280048 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310227 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/14 1p

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

7908310333 Responds to 790730 ltr.Safeguards upgrade rule will not have significant impact on facility operation.
GEORGE, K D Union Carbide Corp. 79/08/15 2pp

P Operating license stage documents & correspondence

7908140282 Discusses clarification of environ considerations of Section C of safety evaluation.Environ portions of Tech Specs Amend 14 should be implemented within specified time period.
REID, R W Operating Reactors Branch 4 79/07/13 2pp

Q Inspection reports, IE Bulletins & correspondence

7908290201 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310222 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/14 1p

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7908070081 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p

7908290278 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310245 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/14 1p

R Periodic operating reports & related correspondence

7908150643 Forwards Annual Operating Rept & finanical 1978 & financial statements for 780401-790331.
CHON, W Y New York State Univ. of, Buffalo 79/08/07 1p

--7908150647 Annual Operating Rept 1978 & financial statements for 780401-790331.
* New York State Univ. of, Buffalo 79/08/07 43pp

DOCKET 50-59 TEXAS A&M UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7908010013 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/06 1p

7908160087 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/08/10 1p

DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

7908310547 Responds to 790730 ltr.Upgrade of rule security requirements are not necessary.Requirements of 10CFR73.67 will apply in lieu of rule.Major changes to facility are to be undertaken if compliance w/rule is deemed necessary.
SHRIVER, B L Virginia, Univ. of 79/08/15 6pp

Q Inspection reports, IE Bulletins & correspondence

7908010078 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 2pp

S Reportable occurrences, LERs & related correspondence

7908020515 Forwards RO on 790613 re fuel element releasing small amounts of fission products to reactor coolant.
SHRIVER, B L Virginia, Univ. of 79/06/26 1p

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

F Security, medical, emergency & fire protection plans

7908310354 Responds to 790730 request for info re impact of compliance w/proposed safeguards upgrade rule.Implementation cost of upgrade rule may imperil continued operation.
DARMITZEL, R W General Electric Co.,Nuclear Energy Products Div. 79/08/20 4pp

G Adjudicatory correspondence

7908080058 Intervenors RV Dellums & Friends of Earth response to ASLB 790618 questions re standing to participate in proceeding & possible violation of 18USC203 & 205.Certificate of Svc encl.
ALDWIN, W A Balough, R C 79/07/13 4pp

7908080061 GE response to ASLB 790618 order containing three questions re participation of intervenor RV Dellums by virtue of congressional status.Certificate of Svc encl.
EDGAR, G L Morgan, Lewis & Bockius 79/07/13 9pp

H General correspondence

7908210530 Repts on study of possible faults at Vallecitos site.Present data suggests at least three branches of Verona fault zone at proposed site.Questions inadequacy of guidelines for siting reactor near capable fault.
SLEMMONS, D B Affiliation Unknown 79/01/07 3pp

P Operating license stage documents & correspondence

7908020486 Protests NRC inaction re undue prolongation & postponement of SER completion & issuance. Requests expeditious conclusion to NRC review.
BEATON, R H. General Electric Co., Nuclear Energy Products Div
79/05/31 2pp

7908010257 Forwards request for addl info re geologic investigations, to complete safety evaluation w/respect to 771024 show cause order.
REID, R W Operating Reactors Branch 4 79/06/08 7pp

7908020323 Forwards trip rept re 790618 GETR site visit.
REID, R W. Operating Reactors Branch 4 79/06/27 2pp

--7908020328 Discusses 790618 GETR site visit to review layouts of completed & proposed mods for facility seismic upgrade. Submits resulting list of questions posed to GE.
HERRING, K S Engineering Branch 79/06/26 4pp

7908140242 Forwards request for addl info re seismic design to complete review of repts submitted in response to 771024 order to show cause.
REID, R W Operating Reactors Branch 4 79/07/09 6pp

7908240454 Forwards ltrs & repts re resumption of operation, including 781110 & 1211 ltrs from Krueger Enterprises, Inc & 781115 ltr from Teledyne Isotopes re radiocarbon age determination data.
HOGGATT, G D. General Electric Co., Nuclear Energy Products Div
79/08/21 14pp

7908240475 Forwards Special Publication 56, "Geologic Evaluation of GETR Site," issued by CA Div of Mines & Geology. Affidavit encl.
DARMITZEL, R W. General Electric Co., Nuclear Energy Products Div
79/08/21 2pp

--7908240482 "Geologic Evaluation of GETR Site," Special Publication 56, prepared by CA Div of Mines & Geology for GE during Aug 1979.
RICE, S., STEPHENS, E., REAL, C. California, State of 79/08/24 28pp

7908280433 Submits schedule for responses to NRC request for addl info re resumption of reactor operations.
DARMITZEL, R W. General Electric Co., Nuclear Energy Products Div
79/08/23 1p

G Inspection reports, IE Bulletins & correspondence

7908140080 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R H. Region 5, San Francisco, Office of the Director
79/08/10 1p

7908310172 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R H. Region 5, San Francisco, Office of the Director
79/08/14 1p

DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7908010021 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K V. Region 4, Dallas, Office of the Director 79/07/06
1p

7908160098 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K V. Region 4, Dallas, Office of the Director 79/08/10
1p

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

F Security, medical, emergency & fire protection plans

7908310354 Responds to 790730 request for info re impact of compliance w/proposed safeguards upgrade rule. Implementation cost of upgrade rule may imperil continued operation.
DARMITZEL, R W. General Electric Co., Nuclear Energy Products Div
79/08/20 4pp

G Inspection reports, IE Bulletins & correspondence

7908140080 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R H. Region 5, San Francisco, Office of the Director
79/08/10 1p

7908310172 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R H. Region 5, San Francisco, Office of the Director
79/08/14 1p

S Reportable occurrences, LERs & related correspondence

7908230580 Discusses RO on 790806 during measurement of four safety rods prior to startup, response time exceeded Tech Specs 6.2.1. Caused by slow release of safety rod electromagnet.
DARMITZEL, R W. General Electric Co. 79/08/16 2pp

DOCKET 50-77 CATHOLIC UNIV OF AMERICA RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7908280254 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director
79/08/10 1p

7908310231 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director
79/08/14 1p

DOCKET 50-89 GENERAL ATOMIC CO

J Insurance & indemnity information

7908140618 Forwards Endorsements 48 & 49 to MAELU Policy MF-59.
CORREA, C. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc., Div. 79/08/08 3pp

P Operating license stage documents & correspondence

7908140493 Forwards revised contingency plan. Plan supersedes 780919 version. Plan withheld (ref 10CFR2.790).
MOWRY, W R. General Atomic Co. (subs. of Gulf Oil Corp.). 79/06/29
2pp

7908240387 Forwards revised Page 1-1 of revised contingency plan. Change substitutes word "armed" for "unarmed" in Paragraph 2. Info withheld (ref 10CFR2.790).
MOWRY, W R. General Atomic Co. (subs. of Gulf Oil Corp.). 79/07/20
1p

G Inspection reports, IE Bulletins & correspondence

7908170466 Forwards IE Insp Repts 50-089/79-01 & 50-163/79-01 on 790514-18. No noncompliance noted.
BOOK, H E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/05/30 2pp

--7908170472 IE Insp Repts 50-089/79-01 & 50-163/79-01 on 790514-18. No noncompliance noted. Major areas inspected: radiation protection, environ monitoring & emergency planning aspects of TRIGA Mark I & M F reactors.
CURTIS, J R. Region 5, San Francisco, Office of the Director
BOOK, H E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/05/30 4pp

7908140078 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R H. Region 5, San Francisco, Office of the Director
79/08/10 1p

7908310171 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R H. Region 5, San Francisco, Office of the Director
79/08/14 1p

DOCKET 50-94 ROCKWELL INTERNATIONAL RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7908310168 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R H. Region 5, San Francisco, Office of the Director
79/08/14 1p

DOCKETED ITEMS

DOCKET 50-97 CORNELL UNIV. ZERO POWER REACTOR

G Inspection reports. IE Bulletins & correspondence

7908280263 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310235 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/14 1p

DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR

P Operating license stage documents & correspondence

7908060222 Forwards, per S Ramos request, analyses of design basis accident & LOCA in support of renewal of License R-47.
OLSEN, A F Babcock & Wilcox Co 79/08/01 7pp

7908310410 Responds to 790730 ltr requesting info from nonpower reactor licensees re effect of safeguards rule. Upgrade rule necessitates protection of reactor as Category I facility for physical protection purposes.
OLSEN, A F Babcock & Wilcox Co 79/08/15 3pp

DOCKET 50-106 OREGON STATE UNIV.

G Inspection reports. IE Bulletins & correspondence

7908170041 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/10 1p

7908310180 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/14 1p

DOCKET 50-111 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

P Operating license stage documents & correspondence

7908090393 Requests listing as user of BMI-1 cask. QA program will be forwarded.
ELLEMAN, T S North Carolina State Univ 79/06/13 1p

7908280390 Forwards QA procedure for shipment of R-63 reactor fuel to DOE, Savannah River operations, Aiken, SC. Forwards 790613 ltr requesting registration as user of BMI-1 cask.
ELLEMAN, T S North Carolina State Univ 79/06/13 1p

--7908280396 Requests that NC State Univ nuclear operations administrator, JR Bohannon, be listed as user of BMI-1 cask.
ELLEMAN, T S North Carolina State Univ 79/06/13 1p

--7908280403 QA procedure re shipment of R-63 reactor fuel elements to DOE in Aiken, SC.
* North Carolina State Univ 79/06/13 6pp

DOCKET 50-112 UNIV. OF OKLAHOMA RESEARCH REACTOR

G Inspection reports. IE Bulletins & correspondence

7908010019 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/06 1p

7908160094 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/08/10 1p

DOCKET 50-113 UNIV. OF ARIZONA RESEARCH REACTOR

G Inspection reports. IE Bulletins & correspondence

7908170044 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/10 1p

7908310185 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/14 1p

DOCKET 50-123 UNIV. OF MISSOURI RESEARCH REACTOR

G Inspection reports. IE Bulletins & correspondence

7908030540 Ack receipt of IE Info Notice 79-12 Potential for occurrence & hazards being assessed.
PLANJE, T J Missouri, Univ. of, at Rolla 79/05/16 1p

7908280497 Ack receipt of 790709 ltr re IE Info Notice 79-18.
PLANJE, T J Missouri, Univ. of, at Rolla 79/07/24 1p

DOCKET 50-124 VIRGINIA POLYTECH INST. TRAINING REACTOR

G Inspection reports. IE Bulletins & correspondence

7908210567 Forwards IE Insp Rept 50-124/79-05 on 790328-29. No noncompliance noted.
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/04 2pp

--7908210573 IE Insp Rept 50-124/79-05 on 790328-29. No noncompliance noted. Major areas inspected emergency plans & procedures, emergency equipment, offsite agency support & drills & exercises.
GIBSON, G T., HUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/11 4pp

DOCKET 50-128 TEXAS A&M UNIV. RESEARCH REACTOR

P Operating license stage documents & correspondence

7908290421 Responds to 790821 telcon request for change to Tech Specs for license amend. In interest of industrial safety & protection of equipment, implementation of smoke detector sys presently under study.
RANDALL, J D Texas A & M Univ. 79/08/21 1p

G Inspection reports. IE Bulletins & correspondence

7908010013 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/06 1p

7908160087 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/08/10 1p

DOCKET 50-131 OMAHA VET. ADMIN. HOSP. RESEARCH REACTOR

P Operating license stage documents & correspondence

7908070060 Advises that info submitted w/application for OL renewal meets 10CFR50 & 10CFR55 requirements for approval.
COLLINS, P F Operator Licensing Branch 79/06/25 1p

G Inspection reports. IE Bulletins & correspondence

7908140047 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/08/10 1p

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

G Adjudicatory correspondence

7905200047 Forwards Woodward-Clyde Consultants 790703 status rept re geologic investigations per 790619 order. Will forward outline of complete investigative program. Certificate of Svc & digitized accelerometer earthquake data encl.
LOCKE, R F., MORRISSEY, J C., FURBUSH, M H Pacific Gas & Electric Co 79/07/05 6pp

P Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque,NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER,J. Assistant Director for Site & Safeguards 79/03/22 7pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation W/o encl.
EISENHUT,D.G. Division of Operating Reactors 79/06/04 52pp

7908060209 Summary of 790628 meeting w/BWR licensees,applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE,W.F. Standardizati,n Branch 79/07/11 26pp

7908170523 Forwards Amend 18 to License DPR-7, safety evaluation & notice of issuance & availability.
I ..ITO,T.A. Operating Reactors Branch 3 79/07/13 3pp

--7908170528 Amend 18 to License DPR-7, changing Tech Specs to permit containment integrated leak rate test immediately prior to returning-to-power operation.
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/13 14pp

--7908170' '2 Safety evaluation supporting Amend 18 to License DPR-7
* Of: ' Nuclear Reactor Regulation 79/07/13 3pp

---7908170536 Notice of issuance & availability of Amend 18 to License DPR-7.
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/13 2pp

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves W/o encl.
GRIMES,B.K. Assistant Director for Systems Engineering 79/07/16 4pp

7906 00290 Forwards NUREG-0472,Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL,W.P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908150520 Requests registration as user of Model CNSI 14-195H.
CRANE,P.A. Pacific Gas & Electric Co 79/07/18 1p

7908090552 Requests 40 copies . response to 790629 request for info re corporate mgt & technical ca,,..'.ities to cope w/TMI-2 type events.Requests addl five copies of response for each addl unit.
HAASS,W.P. Quality Assurance Branch 79/07/24 1p

7908010462 Responds to NRC 790629 request for info re corporate capabilities & techincal & mgt resources.Info requested in Sections I & II.B will be developed & submitted at later date.Preliminary plan encl.
CRANE,P.A. Pacific Gas & Electric Co. 79/07/31 37pp

7908210351 Notifies that no licensing activities initiated by util are currently under review.Allows 30-day period for response to items requiring review action.
IPPOLITO,T.A. Operating Reactors Branch 3 79/08/03 2pp

7908230217 Notification of regional meetings w/all power reacto licensees & applicants to discuss recent impacts on emergency planning & current regulations,guidance documents & repts re emergency planning.
EISENHUT,D.G. Division of Operating Reactors 79/08/03 53pp

7908290319 Forwards request for addl info by 790817 re sys group & small break LOCA analysis.
IPPOLITO,T.A. Operating Reactors Branch 3 79/08/03 19pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL,W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908300713 Forwards "Rept on Radioactive Effluent Releases & Waste Disposal." Rept summarizes quantity of each principal radionuclide released to unrestricted areas in liquids & gaseous effluents Jan-June 1979.
CRANE,P.A. Pacific Gas & Electric Co 79/08/28 1p

--7908200718 "Rept on Radioactive Effluent Releases & Waste Disposal," Jan-June 1979.
Pacific Gas & Electric Co 79/06/30 15pp

--7908300722 "Rept 72,Environ Radiation Study in Vicinity of Humboldt Bay Power Plant,Eureka,CA," Jan-Mar 1979.
CAYOT,R.F. ; BROWNRIGG,D.L. ; LORENZ,R.W. Pacific Gas & Electric Co 79/03/31 22pp

--7908300725 "Rept 71,Environ Radiation Study in Vicinity of Humboldt Bay Power Plant,Eureka,CA," Oct-Dec 1978.
CAYOT,R.F. ; ANDREW,C.H. ; LORENZ,R.W. Pacific Gas & Electric Co 79/04/17 20pp

Q Inspection reports, IE Bulletins & correspondence

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08.Requests attendance at 790628 meeting in Bethesda,MD re info needed by NRC to complete review.
IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625) 79/06/20 44pp

7908280427 Responds to IE Bulletin 79-11 re use of Westinghouse Type DB-75 circuit breakers.No f' ..kers in use or planned for use in any electrical sys.
CRANE,P.A. Pacific Gas & Electric Co. 79/06/22 1p

7908010389 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/07/17 1p

7908020494 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/07/18 1p

7908020405 Forwards corrected copy of IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/07/19 1p

7908080336 Requests addl info to suppl previous response to IE Bulletin 79-08 to enable NRC to complete safety evaluation.
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/20 4pp

7908060049 Forwards IE Bulletin 79-16, "Vital Area Acces, ntrol." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/07/26 1p

7908060144 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/07/26 1p

7908100175 Forwards addl info requested in 790720 ltr re IE Bulletin 79-08.Operability of redundant safety-related components & sys presently verified by surveillance testing.
CRANE,P.A. Pacific Gas & Electric Co 79/08/06 12pp

7908210488 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/08/07 1p

7908170034 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/08/10 1p

7908170035 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/08/10 1p

7908280376 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER,B.H. Region 5, San Francisco, Office of the Director 79/08/13 1p

7908310148 Forwards IE Info Notice 79-20, "NRC Enforcement P licy - NRC Licensed Individuals." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/08/14 1p

DOCKETED ITEMS

7908300225 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/15 1p

R Periodic operating reports & related correspondence

7908210384 Forwards monthly operating rept for Jul 1979.
WEEKS, E D Pacific Gas & Electric Co. 79/08/13 2pp

--7908210387 Monthly operating rept for Jul 1979.
GETTY, B C Pacific Gas & Electric Co. 79/08/02 3pp

S Reportable occurrences, LERs & related correspondence

7908020527 Forwards PNO-79-67AW.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/10 1p

7908020026 Forwards PNO-79-67AX.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/17 1p

DOCKET 50-134 WORCESTER POLYTECH INST. RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7908070106 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p

7908290286 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310250 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/14 1p

DOCKET 50-139 UNIV. OF WASHINGTON RESEARCH REACTOR

P Operating license stage documents & correspondence

7908310405 Responds to 790730 ltr. Will recommend to univ administration that facility be decommissioned & used for other purposes, if reactor is not exempted from 10CFR73.67 requirements.
BABB, A L Washington, Univ. of 79/08/14 2pp

G Inspection reports, IE Bulletins & correspondence

7908170051 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/10 1p

7908310196 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/14 1p

DOCKET 50-142 UCLA TRAINING REACTOR

P Operating license stage documents & correspondence

7908130327 Notifies that License R-71 expires 800330. Discusses general requirements for renewal & filing date. Forwards outline of license renewal review items.
REID, R W Operating Reactors Branch 4 79/06/13 8pp

7908290527 FOIA request for bibliography & files re UCLA Nuclear Energy Lab.
VOELZKE, D Affiliation Unknown 79/08/07 1p

G Inspection reports, IE Bulletins & correspondence

7908170050 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/10 1p

7908310192 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/14 1p

DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY

H General correspondence

7908160044 Responds to 790411 request to allow news reporters to accompany inspector at facility during next insp. NRC has no objection but invitation must come from licensee.
BAUGHMAN, J D Broad Top Bulletin SA, Pennsylvania 79/07/09 1p

G Inspection reports, IE Bulletins & correspondence

7908230619 Responds to 790411 ltr re facility. NRC cannot extend invitation to accompany inspectors; invitation must come from licensee. Forwards IE Insp Repts 50-146/71-02 & 50-146/70-02 re releases of radioactive matl from facility.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 2pp

--7908230624 IE Insp Rept 50-146/71-03 on 711127-29. Noncompliance noted: accidental releases of gaseous activity from plant stack in excess of specified limit; sys mod w/o written safety evaluation & failure to follow written emergency procedure.
SPESSARD, R L ; MADSEN, G L Region 1, Philadelphia, Office of the Director 72/02/09 15pp

--7908230635 IE Insp Rept 50-146/70-02 on 700901-03. Noncompliance noted: min qualifications re experience & licensing not maintained & stack monitor indicated excess radioactive concentration resulting from accidental gaseous release.
MCDERMOTT, R T ; SPESSARD, R L ; CARLSON, R T Region 1, Philadelphia, Office of the Director 70/10/02 19pp

DOCKET 50-148 UNIV. OF KANSAS RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7908010017 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/06 1p

7908160091 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/08/10 1p

DOCKET 50-151 UNIV. OF ILLINOIS RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7908010353 Forwards IE Insp Repts 50-151/79-01 & 50-346/79-01 on 790604-05. Details & notice of violation withheld (ref 10CFR2.790).
HIND, J A Region 3, Chicago, Safeguards Branch 79/06/20 2pp

--7908010356 IE Insp Repts 50-151/79-01 & 50-356/79-01 on 790604-05. Noncompliance noted: surveillance. Details withheld (ref 10CFR2.790).
HOWELL, J C ; SCHEFFER, J C Region 3, Chicago, Office of the Director ; HIND, J A Region 3, Chicago, Safeguards Branch 79/06/14 1p

7908170099 Ack receipt of 790713 ltr informing NRC of steps taken to correct violation noted in IE insp rept & 790620 ltr.
HIND, J A Region 3, Chicago, Safeguards Branch 79/07/25 1p

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

E NRC Safety Evaluation Report (SER), suppls & correspondence

7908080128 Forwards revised safety assessment of SEP Topic V-10.A re residual heat removal sys heat exchanger tube failure. Revision includes consideration of comments received on assessment issued by NRC 790306 ltr.
ZIEMANN, D L Operating Reactors Branch 2 79/07/12 6pp

F Security, medical, emergency & fire protection plans

7908130119 Forwards "Evaluation of Min Fire Brigade Shift Size." Min size should be five persons.
LAINAS, G Plant Systems Branch 79/06/28 2pp

--7908130122 "Evaluation of Min Fire Brigade Shift Size."
* Plant Systems Branch 79/06/08 32pp

7908130167 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee Plans should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch 79/07/03 2pp

7908280025 Forwards suitability, training & qualification plans for security personnel. Plans withheld (ref 10CFR2.790). Class II amend fee encl.
HOFFMAN, D.P. Consumers Power Co. 79/08/23 1p

H. General correspondence

7908140600 Rejects 790412 request re assignment of resident inspector at facility for 1979.
HENDRIE, J.M. Commission 79/07/05 2pp

--7908140606 Requests assignment of resident inspector at facility.
MILLIKEN, M.G. Michigan, State of 79/04/12 1p

7908150084 Ack receipt of correspondence re status of spent fuel storage at six operating facilities near Lake MI. Responds to 790429 ltr.
DENTON, H.R. Office of Nuclear Reactor Regulation 79/07/26 2pp

--7908150107 Discusses spent fuel storage capability at Big Rock Point. NUREG-[illegible] indicates authorized capacity of 120 spent fuel assemblies, while DOE indicates capacity of 365. Requests clarification.
SCHAEFER, J. Lake Michigan Federation 79/05/20 1p

--7908150125 Ack receipt of info re nuclear power plants near Lake MI. Forwards rept re status of spent fuel storage at plants. Requests comments re rept.
SCHAEFER, J. Lake Michigan Federation 79/06/21 1p

--7908150139 "Status of Spent Fuel Storage at the Six Nuclear Plants Located on Shore of Lake MI."
SCHAEFER, J. Lake Michigan Federation 79/05/31 20pp

7908140773 Submits info in response to NRC 790629 & 0724 ltrs re mgt & technical resources available to handle unusual everts. Encl available in Central Files only.
HOFFMAN, D.P. Consumers Power Co. 79/08/09 1p

7908150593 Forwards chart showing QA program organizational change in production & transportation dept, effective 790711.
HOFFMAN, D.P. Consumers Power Co. 79/08/10 3pp

P. Operating license stage documents & correspondence

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH, H. Operating Reactors Branch 2 (Pre 790625) 79/04/19 5pp

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project.
LEVIN, H.A. Systematic Evaluation Programs Branch (Pre 790625) 79/03/08 10pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors 79/06/04 52pp

7908070660 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/06/22 3pp

7908010345 Responds to util 790614 request for technical assistance re degraded grid voltage. Addl info is necessary to complete review of request. Request for addl info encl.
LAINAS, G. Plant Systems Branch 79/07/02 3pp

7908070013 Notification of 790713 meeting w/util in Bethesda, MD to discuss facility control rod drive housing penetration leak.
SILVER, R.D. Operating Reactors Branch 2 79/07/02 2pp

7908130500 Summary of 790427 meeting w/util re small primary coolant sys leak.
NOWICKI, S.J. Operating Reactors Branch 2 79/07/05 4pp

7908080688 Forwards request for addl info re degraded grid voltage. Response requested within 45 days.
ZIEMANN, D.L. Operating Reactors Branch 2 79/07/09 3pp

7908130323 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires initial NRC notification.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/09 1p

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W.F. Standardization Branch 79/07/11 26pp

7908030088 Updates 790504 response to IE Bulletin 79-08, "Events Relevant to BWRs Identified During TMI Incident." Clarifies Question 7 re qualification of high radiation interlock in containment.
HOFFMAN, D.P. Consumers Power Co. 79/07/12 1p

7908160335 Forwards request for addl info re sys area & small break LOCA analysis.
ZIEMANN, D.L. Operating Reactors Branch 2 79/07/17 19pp

7908280168 Notice of proposed issuance of amend to License DPR-6 allowing mod to spent fuel pool to increase spent fuel storage capacity.
SILVER, R.D. Operating Reactors Branch 2 79/07/17 4pp

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D.G. Division of Operating Reactors VASSALLO, D.B. Division of Project Management 79/07/18 58pp

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W.P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908070336 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/19 1p

7908170468 Forwards summary of 790628 meeting re NRC evaluation program for operating BWR plants & near-term OLs.
* Office of Nuclear Reactor Regulation 79/07/19 3pp

7908160037 Notification of 790726 meeting w/util in Bethesda, MD to discuss licensee seismic reanalysis program.
LEVIN, H.A. Systematic Evaluation Program Branch 79/07/20 1p

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W.P. Quality Assurance Branch 79/07/24 1p

7908010507 Forwards rept "Hydraulic Evaluation of ECCS."
BIXEL, D.A. Consumers Power Co. 79/07/25 1p

--7908010512 "Hydraulic Evaluation of ECCS."
* MPR Associates, Inc. 77/08/01 181pp

7908170095 Forwards Amend 28 to License DPR-6, safety evaluation & notice of issuance & availability.
ZIEMANN, D.L. Operating Reactors Branch 2 79/07/26 2pp

--7908170098 Amend 28 to License DPR-6, implementing NRC fire protection position re shutdown cooling sys isolation, revising requirements on use & testing of fire suppression water sys & deleting updated ECCS Tech Specs.
ZIEMANN, D.L. Operating Reactors Branch 2 79/07/26 8pp

--7908170101 Safety evaluation supporting Amend 28 to License DPR-6.
* Office of Nuclear Reactor Regulation 79/07/26 4pp

--7908170106 Notice of issuance & availability of Amend 28 to License DPR-6.
ZIEMANN, D.L. Operating Reactors Branch 2 79/07/26 2pp

7908010436 Forwards fee for steam generator tube surveillance Tech Spec change, inadvertently omitted from 790726 submittal.
CASHELL, S. Consumers Power Co. 79/07/27 1p

7908060349 Forwards update to proposed change to Tech Specs Section 6 re administrative controls. Clarification provided to identify util organization position re ANSI N18.1-1971.
HOFFMAN, D.P. Consumers Power Co. 79/08/03 4pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D.G. Division of Operating Reactors 79/08/03 53pp.

7908070350 "Deviation of Floor Responses Reactor Bldg."
* D'Appolonia Consulting Engineers, Inc. 79/08/06 60pp.

7908310004 Summary of 790726 meeting w/util & consultants in Bethesda, MD re seismic design. List of attendees & viewgraphs of SEP encl.
WETMORE, J. Operating Reactors Branch 2 79/08/07 18pp.

7908210068 Advises that proposed amends in 781113 & 790312 submittals do not cover items of model radiological effluent Tech Specs sent to util in 781115 ltr. Forwards request for addl info & guidelines. Revisions should be submitted by 790914.
ZIEMANN, D.L. Operating Reactors Branch 2 79/08/08 13pp.

7908170387 Forwards requested info re mgt & technical resources available to handle unusual events similar to TMI incident. Info withheld (ref 10CFR2.790).
HOFFMAN, D.P. Consumers Power Co. 79/08/09 1p.

7908210165 Forwards draft evaluation of SEP Topic V-12.A re water purity of PWR primary coolant. Examination of facts & response requested within 30 days.
ZIEMANN, D.L. Operating Reactors Branch 2 79/08/09 13pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908210353 Forwards hazards analysis rept for State of MI.
JURY, M.J. Consumers Power Co. 79/08/16 1p.

--7908210355 Hazards analysis rept for State of MI, by MI Dept of State Police. Oversized map encl.
* Michigan: State of 74/05/31 49pp.

7908220321 Discusses response to NRC request for info for staff generic rept on effect of TMI accident on BWRs. GE generic rept, NEDE-24078, "Addl Info Required for NRC Staff Generic Rept on BWRs" being transmitted. Forwards addl info.
BIXEL, D.A. Consumers Power Co. 79/08/17 4pp.

7908280566 Responds to 790709 request for addl info re proposed second level of undervoltage protection. Will provide requested info by 800115.
BIXEL, D.A. Consumers Power Co. 79/08/23 1p.

7908280007 Discusses incorporation of alternate shutdown sys design & installation into SEP efforts. Requests issuance of suppl to fire protection SER, Table 3.1 suggests prompt action.
BIXEL, D.A. Consumers Power Co. 79/08/24 2pp.

7908300449 Forwards addl info on SEP Topic VIII-2 re onsite emergency power sys for diesel generators & comments on draft evaluation, in response to NRC 780814 request. Revision of diesel generator loads also encl.
BIXEL, D.A. Consumers Power Co. 79/08/28 54pp.

7908280154 Forwards FR notice of proposed issuance of amend to DL re proposed mod of spent fuel pool.
ZIEMANN, D.L. Operating Reactors Branch 2 79/07/17 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908020272 Responds to IE Bulletin 79-03 re defects in logitudinal welds in ASME SA-312 Type 304 stainless steel pipe spools. Preliminary review identified nonsafety-related use of pipe at Palisades; not in use at Big Rock Point.
BIXEL, D.A. Consumers Power Co. 79/05/30 1p.

7908010072 Forwards IE Insp Rept 50-155/79-07 on 790423-25. No noncompliance noted.
DAVIS, A.B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/13 2pp.

--7908010074 IE Insp Rept 50-155/79-07 on 790423-25. No noncompliance noted. Major areas inspected: environ protection & monitoring program results, emergency planning, records of tests, drills & training & internal audits.
OESTMANN, M.J.; ESSIG, T.H. Region 3, Chicago, Office of the Director 79/06/12 7pp.

7908130339 Notifies all BWR licensees of status of NRC review of licensee respons. to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625) 79/06/20 44pp.

7908280204 Forwards IE Insp Rept 50-155/79-10 on 790506-10 & 0611-13. No noncompliance noted.
HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/27 2pp.

--7908280214 IE Insp Rept 50-155/79-10 on 790506-10 & 0611-13. No noncompliance noted. Major areas inspected: licensee activities in response to IE Bulletin 79-08.
RIDGWAY, R.R.; BOYD, D.C. Region 3, Chicago, Office of the Director 79/06/25 7pp.

7908070376 Responds to IE Bulletin 79-02, "Pipe Support Baseline Designs Using Concrete Expansion Bolts." Forwards rept describing program initiated to address concerns raised by bulletin.
HOFFMAN, D.P. Consumers Power Co. 79/07/06 1p.

--7908070382 Testing/insp program for pipe support base space plates using concrete expansion anchor bolts.
* Consumers Power Co. 79/07/06 5pp.

7908090586 Responds to IE Bulletin 79-11. Westinghouse circuit breakers are not in use at facility.
HOFFMAN, D.P. Consumers Power Co. 79/07/12 1p.

7908170165 Forwards Special Rept 28 re inservice insp.
BIXEL, D.A. Consumers Power Co. 79/07/18 1p.

--7908170169 "Special Rept 28 re 1979 Inservice Insp 6" on 790202-0413.
* Consumers Power Co. 79/07/18 28pp.

7908100155 Ack receipt of 790705 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/79-07.
DAVIS, A.B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/07/19 1p.

--7908100172 Responds to NRC 790613 ltr re violations noted in IE Insp Rept 50-155/79-07. Corrective actions: backup battery-powered portable air sampler expected on site by 790915.
HOFFMAN, D.P. Consumers Power Co. 79/07/05 1p.

7908080295 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
ZIEMANN, D.L. Operating Reactors Branch 2 79/07/20 4pp.

7908290349 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/26 1p.

7908300399 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/26 1p.

7908240523 Responds to IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." Instrumentation does provide for scram in event of short reactor period & operating procedures already require estimate of critical rod pattern.
BIXEL, D.A. Consumers Power Co. 79/07/30 3pp.

7908240529 Submits addl response to IE Bulletin 79-03. Further review has not identified any use of piping types discussed.
BIXEL, D.A. Consumers Power Co. 79/07/30 1p.

7908240501 Responds to IE Bulletin 78-12B, "Atypical Weld Matl in Reactor Pressure Welds." Util has no addl archive matl relating to weld matl.
BIXEL, D.A. Consumers Power Co. 79/07/31 1p.

--7908240505 Responds to IE Bulletins 78-12, 12A & 12B re review of archive records of weld matl used in reactor pressure vessel welds. No records were required to be maintained by code or contract.
COHN, W.C. General Electric Co., Nuclear Energy Products Div. 79/04/26 2pp.

7908160359 Responds to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping Forwards insp plan.
BIXEL, D A Consumers Power Co 79/08/01 5pp

7908140539 Forwards addl info re IE Bulletin 79-08 events concerning BWRs identified during TMI incident, as requested in NRC 790720 ltr
BIXEL, D A Consumers Power Co 79/08/07 14pp

7908150342 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/08/07 1p

7908240[illegible] Forwards addl response to IE Bulletin 79-08 re events relevant to BWRs identified during TMI incident Supplements 790504 response.
BIXEL, D A Consumers Power Co 79/08/07 14pp

7908170021 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/08/08 1p

7908300483 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/08/15 1p

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

P Operating license stage documents & correspondence

7908140607 Responds to 790730 ltr re changes in 10CFR70 & 73 Info supplied prior to issuance of Amend 14 to License R-74 is sufficient Amend w/exemption status of various types of SNM accomplishes intent of 790730 ltr.
CASHWELL, R J Wisconsin, Univ of, Madison 79/06/09 1p

7908310298 Responds to 790730 request for info re implementation of new portions of 10CFR73 No addl const features will be required at facility Provides info on budget, facility, students, experiments & radiation levels.
CASHWELL, R J Wisconsin, Univ of, Madison 79/08/09 4pp

R Periodic operating reports & related correspondence

7908010542 Forwards annual operating rept for License R-74 for FY78-79.
CASHWELL, R J Wisconsin, Univ of, Madison 79/07/25 1p

--7908010549 Annual Operating Rept FY78-79.
CASHWELL, R J Wisconsin, Univ of, Madison 79/07/25 15pp

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

7908020187 Notifies of 800629 OL expiration OL renewal requires submission of application demonstrating ability to operate reactor safely over term of renewal License renewal review items encl.
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/25 8pp

G Inspection reports, IE Bulletins & correspondence

7908280263 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310235 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/14 1p

DOCKET 50-163 GENERAL ATOMIC COMPANY

J Insurance & indemnity information

7908140618 Forwards Endorsements 48 & 49 to MAELU Policy MF-59.
CORREA, C Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc., Div 79/08/08 3pp

P Operating license stage documents & correspondence

7908140493 Forwards revised contingency plan Plan supersedes 780919 version Plan withheld (ref 10CFR2 790).
MOWRY, W R General Atomic Co (subs of Gulf Oil Corp.) 79/06/29 2pp

7908240387 Forwards revised Page 1-1 of revised contingency plan change substitutes word "armed" for "unarmed" in Paragraph 2 Info withheld (ref 10CFR2 790).
MOWRY, W R General Atomic Co (subs of Gulf Oil Corp.) 79/07/20 1p

7908280[illegible] of 790628 meeting w/GA Co in Bethesda, MD re revised design of gas cooled fast breeder.
WILLIAMS, P M Division of Project Management 79/08/02 25pp

G Inspection reports, IE Bulletins & correspondence

7908170466 Forwards IE Insp Repts 50-089/79-01 & 50-163/79-01 on 790514-18 No noncompliance noted.
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/05/30 2pp

--7908170472 IE Insp Repts 50-089/79-01 & 50-163/79-01 on 790514-18 No noncompliance noted Major areas inspected radiation protection, environ monitoring & emergency planning aspects of TRIGA Mark I & M F reactors.
CURTIS, J R Region 5, San Francisco, Office of the Director
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/05/30 4pp

7908140078 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/10 1p

7908310171 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/14 1p

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

P Operating license stage documents & correspondence

7908070036 Forwards list of specific items that will be reviewed prior to renewal of License R-70, expiring on 800629 Licensee reminded of procedural requirements for submittal of application.
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/21 9pp

G Inspection reports, IE Bulletins & correspondence

7908070085 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p

7908280284 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310248 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 79/08/14 1p

R Periodic operating reports & related correspondence

7908170395 Submits annual operating rept for 780630-790630.
BELCHER, R L Maryland, Univ of 79/07/23 4pp

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

P Operating license stage documents & correspondence

7908170619 Ack receipt of 790702 proposed changes to Tech Specs, forwarded for review Requests submittal per 10CFR50 90.
REID, R W Operating Reactors Branch 4 79/07/20 1p

7908100457 Submits info requested in 790730 ltr re License R-84, covering total inventory of U-235 fuel loading in core, fuel in storage, ceiling for possession & exempted fuel.
TYLER, P. E. Army, Dept. of 79/08/07 1p

7908100493 Responds to 790720 request for resubmittal of proposed Tech Specs. Notarized request was missing item. Signature of military officer is considered notarized sworn statement.
TYLER, P. E. Army, Dept. of 79/08/07 1p

7908240430 Forwards rept of reactor exhaust sys malfunction on 790809. electrical fire in EF-1 cubicle of motor control ctr. Caused by power surge due to failed transformer. Motor control contact replaced.
TYLER, P. E. Defense, Dept. of, Defense Nuclear Agency 79/08/15 2pp

G. Inspection reports, IE Bulletins & correspondence

7908070092 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 1p

7908280046 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310225 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

S. Reportable occurrences, LERs & related correspondence

7908100479 Forwards amended deficiency rept re malfunction of pool water level sensing switch, submitted by Defense Nuclear Agency.
TYLER, P. E. Army, Dept. of 79/07/31 1p

--7908100483 Amended deficiency rept re malfunction of pool water level sensing switch, submitted by Defense Nuclear Agency. Switch unit replaced & addl sleeving placed at wear point.
* Army, Dept. of 79/07/31 2pp.

7908100439 Forwards deficiency rept re malfunction of fuel element temp sensing circuit.
TYLER, P. E. Defense, Dept. of 79/08/01 1p

--7908100448 Deficiency rept re malfunction of fuel element temp sensing circuit. Grounding strap installed at main ground to lock signal & sys ground together.
* Defense, Dept. of 79/08/01 1p

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

P. Operating license stage documents & correspondence

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908170274 Forwards description of acoustic monitoring sys for relief valve position monitoring.
MCELTOY, J. W. Philadelphia Electric Co. 79/07/30 4pp.

7908290583 Forwards revision of 790719 annual rept for decommissioned plant.
ALDEN, W. M. Philadelphia Electric Co. 79/08/17 1p

--7908290589 Annual rept, Revision 1, for decommissioned plant.
* Philadelphia Electric Co. 79/08/17 1p.

R. Periodic operating reports & related correspondence

7908300691 Forwards revision of "Decommission Annual Rept" submitted 790719.
ALDEN, W. M. Philadelphia Electric Co. 79/08/17 1p

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

F. Security, medical, emergency & fire protection plans

7908310553 Responds to 790730 ltr. Upgrade rule is impossible to apply because of logistic & physical requirements. Major mods to installations & communication sys in addition to const of new physical security control ctr would be required.
CARTER, R. S. Commerce, Dept. of, National Bureau of Standards 79/08/24 3pp.

P. Operating license stage documents & correspondence

7908290490 Discusses irregularities in regulatory rod movements. Cause is unknown but short range binding in neighborhood of 25 degrees may result from faulty bearings on shim arm shaft. Further tests are planned. Reactor will remain shut down.
CARTER, R. S. Commerce, Dept. of, National Bureau of Standards 79/08/15 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908070098 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 1p

7908280050 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310230 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

DOCKET 50-186 UNIV. OF MISSOURI RESEARCH REACTOR

P. Operating license stage documents & correspondence

7908070237 Forwards Amend 12 to License R-103, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4 79/07/05 2pp.

--7908070252 Amend 12 to License R-103, changing limitations on fueled gaseous radioactivitiy release experiments specified in Section 3.7a of Tech Specs.
REID, R. W. Operating Reactors Branch 4 79/07/05 4pp.

--7908070261 Safety evaluation supporting Amend 12 to License R-103.
* Operating Reactors Branch 4 79/07/05 7pp.

--7908070270 Notice of issuance & availability of Amend 12 to License R-103.
REID, R. W. Operating Reactors Branch 4 79/07/05 2pp.

7908140377 Forwards request for approval of route between Columbia, MD & Savannah River Plant, SC for fourth spent fuel shipment, planned for 790730.
ALGER, D. Missouri, Univ. of, Columbia 79/07/12 21pp.

7908310507 Ack receipt of NRC 790730 request for info re upgrade rule. Research reactors are operated in safe manner. Facility meets Category II conditions. Forwards "Univ of MO Research, Its Fuel & Productivity" rept & Annual Rept Jul 1977-June 1978.
BRUGGER, R. M. Missouri, Univ. of, at Rolla 79/08/15 6pp.

-7908310512 "Univ of MO Research Reactor, Its Fuel & Productivity," presented at ANL 781108-09 meeting.
BRUGGER, R. M.; SCHLAPPER, G. A.; ALGER, D. M. Missouri, Univ. of, at Rolla 78/11/09 26pp.

--7908310516 "Univ of Mo Research Reactor (MURR) Annual Rept," Jul 1977 - June 1978.
* Missouri, Univ. of, at Rolla 78/06/30 64pp.

G. Inspection reports, IE Bulletins & correspondence

7908080402 Submits change per IE Insp Rept 50-186/79-03 to Reactor Operations Annual Rept 1977-78, Page 27, reflecting calculation of min detectable sample value times total vol released to sanitary sewer via secondary cooling sys.
OLSON, O. L.; BRUGGER, R. M. Missouri, Univ. of, at Rolla 79/06/30 1p

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

J. Insurance & indemnity information

7908220430 Forwards Endorsement 13 to Indemnity Agreement B-26.
STRANG, J. P. Northrop Corp. 79/08/16 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908170032 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/10 1p

7908310175 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/08/14 1p

DOCKET 50-188 KANSAS STATE UNIV. RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

7908010012 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/06 1p

7908160062 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/10 1p

DOCKET 50-192 UNIV. OF TEXAS RESEARCH REACTOR

P. Operating license stage documents & correspondence

7908030542 Notifies of expiration of License R-92 on 800212. Requests early submittal of application for renewal if renewal of license is desired. Forwards license renewal review items.
REID,R.W. Operating Reactors Branch 4 (Pre 790625) 79/06/15 8pp

G. Inspection reports, IE Bulletins & correspondence

7908030575 Ack receipt of 790507 ltr responding to 790410 notice of violation. Corrective actions will be reviewed during next insp. Corrective actions withheld (ref 10CFR2.790).
NORDERHAUG,L.R. Region 5, San Francisco, Office of the Director 79/06/08 1p

7908010020 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/06 1p

7908160097 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/10 1p

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

F. Security, medical, emergency & fire protection plans

7908310533 Responds to 790730 ltr. Upgrade rule will not imply significant changes in RI Atomic Energy Commission Nuclear Science Ctr. Operating data for Jul 1977-June 1978 encl.
DIMEGLIO,A.F. Rhode Island, State of 79/08/17 2pp

--7908310536 RI Atomic Energy Commission Nuclear Science Ctr operating statistics for Jul 1977-June 1978.
DIMEGLIO,A.F. Rhode Island, State of 79/02/28 29pp

G. Inspection reports, IE Bulletins & correspondence

7908070101 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/06/22 1p

7908280033 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310218 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

7908280265 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310238 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

F. Security, medical, emergency & fire protection plans

7908030537 Responds to 790221 ltr transmitting, "Security Personnel Training & Qualification Plan." Forwards list of changes & additions to be made before plan is acceptable.
MCCORKLE,G.W. Physical Security Licensing Branch 79/06/20 3pp

7908140367 Forwards page 45 of revised safeguards contingency plan. Withheld (ref 10CFR2.790).
CLARK,J.R. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/07/23 2pp

G. Adjudicatory correspondence

7908140301 Discusses vitrification problems. Vitrification is better method of long-term radwaste containment than shale fracturing or in-tank solidification.
VAUGHAN,R.C. West Valley Nuclear Sites 79/06/11 32pp

H. General correspondence

7908140143 Discusses possible risks resulting from air crash into reprocessing plant. Probability ranges between one collision in one million years & one collision in 100 million years for sites located at least five miles from airport.
HAUGHNEY,C.J. Fuel Reprocess. & Recycle Branch (Pre 790727) 79/06/18 2pp

J. Insurance & indemnity information

7908290511 Forwards Amend 10 Indemnity Agreement B-29.
CONTI,P.L. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/08/27 2pp

P. Operating license stage documents & correspondence

7908030126 "Seismic Analysis of High Level Neutralized Liquid Waste at Western NY State Nuclear Svc Ctr."
* Lawrence Livermore Laboratory UCRL-52485 79/05/31 590pp

7908140459 Forwards results & flow measurements for May 1979, radioactivity results for Mar & Apr 1979 & discharge results for Jan-June 1979, for Permit NY0000973.
OLDHAM,W.A. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/06/11 5pp

7908030508 Forwards LLL rept re effect of earthquake on neutralized high level liquid waste storage tanks at West Valley, NY. W/WJ Hall Consultant 790302 review comments & NRC evaluation encl. W/o rept.
ROUSE,L.C. Fuel Reprocess. & Recycle Branch (Pre 790727) 79/06/20 1p

--7908030521 Submits review comments re results of seismic evaluation studies by LLL on high level neutralized liquid waste tanks at West Valley, NY.
HALL,W.J. N.M. Newmark Consulting Engineering Services 79/03/02 5pp

--7908030534 Branch comments & consequence analysis of earthquake risk from neutralized liquid waste tanks at reprocessing plant in West Valley, NY. Carbon steel tanks would withstand earthquake & airborne release would be within limits.
* Fuel Reprocess. & Recycle Branch (Pre 790727) 79/06/20 6pp

7908070369 Notifies of intent to install second communications sys. linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp

7908070813 Notification that 790711 meeting w/NFS in Bethesda, MD to discuss future decontamination and decommissioning of facility is rescheduled for 790708.
HAUGHNEY,C.J. Fuel Reprocess. & Recycle Branch (Pre 790727) 79/07/02 2pp

DOCKETED ITEMS

7908070213 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

G. Inspection reports, IE Bulletins & correspondence.

7908280157 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/10. 1p.

7908310221 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

R. Periodic operating reports & related correspondence.

7908220679 Forwards results & flow measurements 790601-30.
DUCKWORTH, J. P. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 79/07/11. 6pp.

7908230653 Forwards quarterly monitoring rept for 790401-0630.
DUCKWORTH, J. P. Nuclear Fuel Services, Inc., West Valley Reprocessing Plant. 79/07/24. 1p.

--7908230656 Quarterly monitoring rept for 790401-0630.
* Nuclear Fuel Services, Inc., West Valley Reprocessing Plant. 79/07/24. 11pp.

U. Congressional/Executive Correspondence.

7908150068 Provides input re Commissioner Kennedy 790620 memo concerning Congressman Udall questions about NRC authority at West Valley facility. Forwards WJ Dircks 790531 testimony before Subcommittee on Energy & Environ.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/07/03. 3pp.

--7908150072 Testimony before Subcommittee on Energy & Environ, Committee on Interior & Insular Affairs, re solidification of liquid high level waste stored at NFS.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/05/31. 9pp.

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans.

7908130206 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908290474 Remits license amend fee for safeguards contingency plan submitted on 790323.
BASKIN, K. P. Southern California Edison Co. 79/08/22. 3pp.

H. General correspondence.

7908130405 Notifies of retirement effective 790831. A Arenal will assume all responsibilities during Aug.
MOORE, J. B. Southern California Edison Co. 79/08/06. 1p.

7908230376 Forwards info re mgt & technical capabilities to cope w/events similar to TMI. Oversize chart encl.
BASKIN, K. P. Southern California Edison Co. 79/08/20. 60pp.

P. Operating license stage documents & correspondence.

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH, H. Operating Reactors Branch 2 (Pre 790625). 79/04/19. 5pp.

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project.
LEVIN, H. A. Systematic Evaluation Programs Branch (Pre 790625). 79/03/08. 10pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908030202 Responds to 790605 ltr & 790608 telcon re unacceptable indications in welds in main feedwater piping sys. Facility will not resume power operation prior to presentation of written rept & NRC concurrence w/corrective actions taken.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/06/08. 1p.

7908070822 Forwards Amend 42 to License DPR-13 & notice of issuance & availability.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/06. 4pp.

--7908070827 Amend 42 to License DPR-13, reflecting changes in corporate & facility organizational structure & change in onsite review committee.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/06. 8pp.

--7908070832 Notice of issuance & availability of Amend 42 to License DPR-13.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/06. 2pp.

7908030160 Forwards preliminary version of radiological effluent Tech Specs. Formal proposed Tech Spec change will be submitted by 790831.
BASKIN, K. P. Southern California Edison Co. 79/07/12. 1p.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 58pp.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908160210 Forwards Amend 43 to License DPR-13, safety evaluation & notice of issuance & availability.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 2pp.

--7908160216 Amend to License DPR-13 changing provisions of App A Tech Specs to restrict operation w/less than all reactor coolant loops in svc.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 9pp.

--7908160220 Safety evaluation supporting Amend 43 to License DPR-13.
* Operating Reactors Branch 2. 79/07/19. 3pp.

--7908160226 Notice of issuance & availability of Amend 43 to License DPR-13.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 2pp.

7908170090 Forwards Amend 44 to License DPR-13, safety evaluation & notice of issuance & availability.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 3pp.

--7908170092 Amend 44 to License DPR-13, incorporating Tech Spec changes re fire protection sys operability & surveillance & fire protection program responsibility.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 9pp.

--7908170094 Safety evaluation supporting Amend 44 to License DPR-13.
* Office of Nuclear Reactor Regulation. 79/07/19. 46pp.

--7908170097 Notice of issuance & availability of Amend 44 to License DPR-13.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 3pp.

7908170193 Forwards model license condition requiring implementation of secondary water chemistry monitoring & control program. Condition replaces Aug 1976 proposed Tech Specs changes re corrosion of steam generator tubes.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/23. 4pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp.

7908030182 Forwards Amend 81 to License DPR-13 proposing Change 82 to Tech Specs to allow simultaneous chlorination of both halves of condenser in order to perform fish impingement studies.
DRAKE, J. H. Southern California Edison Co. 79/07/31 2pp.

--7908030186 Amend 81 to License DPR-13 proposing Change 82 to Tech Specs. Certificate of Svc encl.
DRAKE, J. H. Southern California Edison Co. 79/07/24 9pp.

7908170198 Notifies of review of 771104 submittal re degraded grid voltage. Util claim that grid voltage does not degrade below 90% of normal voltage is unacceptable as basis for not proposing mod to undervoltage protection sys. Requests mod.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/31 2pp.

7908080394 Submits addl info re SEP Topic VIII-3B, "DC Power Sys Voltage Monitoring & Annunciation," in response to 790618 request. Discusses encl listing of 125-volt dc sys annunciators & uninterruptible power sys.
HAYNES, J. G. Southern California Edison Co. 79/08/01 2pp.

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp.

7908100490 Forwards info per 790606 request in order to continue review of SEP Topic VI-1, Organic Matls & Post-Accident Chemistry. Info re Topic VI-5, Control Inside Containment encl.
HAYNES, J. G. Southern California Edison Co. 79/08/03 6pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908150253 Responds to NRC 781026 request for addl info re SEP Topics VI-7.B, VII-1.A & VII-2. Forwards ref oversized drawings.
HAYNES, J. G. Southern California Edison Co. 79/08/09 112pp.

790F J0155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908200153 Forwards requested info & drawings for systematic evaluation review.
HAYNES, J. G. Southern California Edison Co. 79/08/14 5pp.

8. Inspection reports, IE Bulletins & correspondence

7908280410 Responds to IE Bulletin 79-09 re use of GE Type AK-2 circuit breakers. No breakers in use, in spares inventory or on order.
HEAD, J. T. Southern California Edison Co. 79/05/17 1p.

7908020219 Responds to IE Bulletin 79-10. Forwards info re operator requalification examinations.
HEAD, J. T. Southern California Edison Co. 79/05/24 3pp.

7908010392 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/17 1p.

7908020503 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/18 1p.

7908020409 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/19 1p.

7908060027 Forwards IE Bulletins 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/26 1p.

7908060067 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/26 1p.

7908060153 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/26 1p.

7908220183 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/07 1p.

7908300780 Requests addl info re IE Bulletins 79-06A & 79-06A, Revision 1.
ZIEMANN, D. L. Operating Reactors Branch 2 79/08/07 3pp.

7908170038 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/10 1p.

7908170039 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/10 1p.

7908280393 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director 79/08/13 1p.

7908310155 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/14 1p.

7908300249 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/15 1p.

9. Periodic operating reports & related correspondence

7908140487 Forwards monthly operating rept for Jul 1979 & corrected first pages May & June repts.
CURRAN, J. M. Southern California Edison Co. 79/08/09 1p.

--7908140494 Monthly operating rept for Jul 1979 & corrected first pages of May & Jun 1979 repts.
NEAL, R. A. Southern California Edison Co. 79/08/09 7pp.

7908210395 Forwards semiannual environ operating rept for Jan-June 1979.
OTTOSON, H. L. Southern California Edison Co. 79/08/15 1p.

--7908210398 Semiannual environ operating rept for Jan-June 1979.
* Southern California Edison Co. 79/06/30 6pp.

10. Reportable occurrences, LERs & related correspondence

7908020532 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/10 1p.

7908020030 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/17 1p.

7908300154 Responds to 790621 ltr & forwards interim rept re generator hot leg piping insp, corrective action & related LER.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/20 1p.

--7908300215 Deficiency rept re nondestructive examination of generator feedwater nozzle to reducer. Insp revealed flaws in piping. Caused by crack formation due to stress corrosion. Welds will be subject to post-weld heat treatment.
* Southern California Edison Co. 79/06/13 20pp.

--7908300230 Requests rept re pipe cracks resulting in plant shutdown.
SIEGEL, S. M. Toward Utility Rate Normalization 79/06/21 1p.

DOCKETED ITEMS

DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

H. General correspondence

7908060035 FOIA request for documents re TRIGA nuclear reactor at Columbia Univ, New York, NY
NYMAN, B. M. Affiliation Unknown 79/07/09 1p

7908060040 Responds to FOIA request for documents re TRIGA nuclear reactor at Columbia Univ, New York, NY
FELTON, J. M. Division of Rules and Records 79/07/30 1p

Q. Inspection reports, IE Bulletins & correspondence

7908280261 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908310233 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

DOCKET 50-213 HADDAM NECK PLANT

E. NRC Safety Evaluation Report (SER), suppls & correspondence

7908020519 "Inservice Insp & Testing Program Recommendations to NRC for Plant SER," interim rpt
RESTIVO, T., LETTIERI, V., HALL, R. E. Brookhaven National Laboratory
FIN A-3117 7908020519 79/02/20 50pp

F. Security, medical, emergency & fire protection plans

7908030015 Notifies that util scheduled general emergency drill on 790720.
GRAVES, R. H. Connecticut Yankee Atomic Power Co 79/03/22 1p

7908270213 Ack receipt of 790723 ltr transmitting safeguards contingency plan for facility Class III fee required.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp

7908080476 Forwards requested fire protection info re alternate means of safe shutdown independent of control room & switchgear room sys which could be damaged by fire.
COUNSIL, W. G. Northeast Utilities 79/07/31 33pp

7908210401 Forwards amend approval fee in connection w/790323 submittal of safeguards contingency plans.
COUNSIL, W. G., FEE, W. F. Northeast Utilities 79/08/15 1p

P. Operating license stage documents & correspondence

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH, H. Operating Reactors Branch 2 (Pre 790625) 79/04/19 5pp

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project.
LEVIN, H. A. Systematic Evaluation Programs Branch (Pre 790625) 79/03/08 10pp

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp

7908030232 Summarizes status of five overpressure protection & three flooding reviews evaluated by LLL in response to Eisenhut 790604 memo.
SHEMANSKI, P. Plant Systems Branch 79/06/12 2pp

--7908030256 Requests status of LLL electrical staff overpressure & flooding reviews.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 1p

7908070430 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/18 58pp

7908070232 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908170210 Forwards model license condition that requiring implementation of secondary water chemistry monitoring & control program. Condition replaces Aug 1976 proposed Tech Specs changes re corrosion of steam generator tubes.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/23 4pp

7908010529 Informs NRC that personnel hatch assembly shall be leak tested at peak accident pressure at 6-month intervals. During intervals, airlock door seals will be leak-tested within 72-h of every series of openings.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co 79/07/24 2pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908220529 Requests addl info re degraded grid voltage for review of 770721 submittal concerning generic issue of onsite power sys.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/24 3pp

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp

7908070542 Forwards revisions to radiological effluent Tech Specs & Offsite Dose Calculation Manual Process control program & value/impact appraisal of alternate spent resin disposal to be submitted 790817.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co 79/08/01 153pp

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees, for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

790823015* Requests utils provide description of methods to verify that [illegible] power sys & onsite distribution sys are capable of [illegible]ically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908210589 Responds to 790611 request that CT Yankee Atomic Power Co & Northeast Nuclear Energy Co review Reg Guide 1.114, Revision 1 as part of SEP. Current operating procedures are consistent w/guidance.
COUNSIL, W. A., FEE, W. F. Northeast Nuclear Energy Co (Northeast Utilities) 79/08/13 1p

7908240458 Discusses proposed radiological effluent Tech Specs & Offsite Dose Calculation Manual. Forwards proposed solid waste process control program & discusses value/impact appraisal of alternate spent resin disposal method.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co 79/08/17 3pp

--7908240459 Proposed solid waste process control program.
* Connecticut Yankee Atomic Power Co. 79/08/17. 8pp.

Q. Inspection reports: IE Bulletins & correspondence

7908060477 Forwards supplemental responses to IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
COUNSIL, W G. Connecticut Yankee Atomic Power Co. 79/06/26. 7pp.

7908080343 Responds to IE Bulletin 79-11 Type DB-50 & DB-75 circuit breakers w/overcurrent trip devices are used in Class IE sys; non-Class IE sys & as spares.
COUNSIL, W G. Connecticut Yankee Atomic Power Co. 79/07/06. 2pp.

7908220613 Responds to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Generic program description & plant-specific program repts encl.
COUNSIL, W G. Northeast Utilities. 79/07/06. 2pp.

--7908220618 "Generic Program Description," discussing finite element model, shear-tension interaction tests & cyclic load tests.
* Northeast Utilities. 79/07/06. 2pp.

--7908220622 "Plant-Specific Programs."
* Northeast Utilities. 79/07/06. 6pp.

7908200253 Advises that C-E generic rept responding to IE Bulletin 78-12 adequately represents reactor pressure vessel data for Facility.
COUNSIL, W G. Northeast Utilities. 79/07/12. 1p.

7908210175 Updates 790611 response to IE Bulletin 79-01. Forwards addl documentation re equipment environ qualification in reactor bldg. Response to IE Bulletin 79-01A re solenoid valves will be forwarded by 790912.
SCHNEIDER, R R. Niagara Mohawk Power Corp. 79/07/12. 18pp.

--7908210183 Forwards addl info to suppl util 771208 & 780113 ltrs re environ qualification of terminal blocks mounted inside junction boxes.
SWITZER, D C. Connecticut Yankee Atomic Power Co. 78/03/29. 14pp.

7908010423 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060366 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908080237 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908100221 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908100332 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908090291 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908280069 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908230297 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/08/08. 1p.

7908280257 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310261 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300114 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908200322 Forwards monthly operating rept for Jul 1979.
GRAVES, R H. Connecticut Yankee Atomic Power Co. 79/08/10. 1p.

--7908200325 Monthly operating rept for Jul 1979.
* Connecticut Yankee Atomic Power Co. 79/08/10. 9pp.

S. Reportable occurrences: LERs & related correspondence

7908280686 Forwards LER 77-027/99X-0.
GRAVES, R H. Connecticut Yankee Atomic Power Co. 77/02/06. 1p.

--7908280692 LER 77-027/99X-0 on 771103 while moving fuel during core 7 refueling outage, rod cluster control spider assembly vane w/two attached absorber rodlets found separated from hub. Caused by faulty braze joint. Faulty control rod replaced.
EPPINGER, R L. Connecticut Yankee Atomic Power Co. 77/12/06. 1p.

7908060304 Forwards LER 79-001/99X-1.
GRAVES, R H. Connecticut Yankee Atomic Power Co. 79/07/31. 1p.

--7908060311 LER 79-001/99X-1 on 790214. Updates RO 79-01/1T on 790228 re Batch B fuel failures. Most defective assemblies removed from core. Cause of fuel failure still unknown. Discusses status of current & planned investigations.
DEROY, J P. Connecticut Yankee Atomic Power Co. 79/07/24. 9pp.

7908100438 Reportable Occurrence 79-08/1P while performing insp of seismic Category I piping sys, discovered one pipe support on residual heat removal sys not installed per design drawing. Addl support added.
GRAVES, R H. Connecticut Yankee Atomic Power Co. 79/08/03. 1p.

7908210333 Forwards LER 79-008/01T-0.
GRAVES, R H. Connecticut Yankee Atomic Power Co. 79/08/14. 1p.

--7908210336 LER 79-008/01T-0 on 790803 seismic-type pipe support AC-ER-31 found missing on residual heat removal piping sys RWL-152-7. Caused by oversight during const. Support installed.
THOMAS, R H. Connecticut Yankee Atomic Power Co. 79/08/14. 2pp.

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

7908130656 Notifies that refund of Class II amend fee for 790601 application on fire protection is being processed.
MILLER, W O. Licensing Management Branch. 79/07/16. 1p.

7908210033 Forwards request for addl info re 780303 fire protection safety evaluation. Incomplete info sent in 780407 & 0922 ltrs. Response should be provided w/Section 3.1 data, scheduled to be sent to NRC by 790831.
ZIEMANN, D L. Operating Reactors Branch 2. 79/08/08. 3pp.

7908210012 Forwards security officer training & qualification plan. Plan withheld (ref 10CFR2.790).
FINFROCK, I R. Jersey Central Power & Light Co. 79/08/17. 1p.

7908280017 Forwards Revision 7 to physical security plan. Plan withheld (ref 10CFR2.790).
FINFROCK, I R. Jersey Central Power & Light Co. 79/08/21. 1p.

Q. Adjudicatory correspondence

7908220675 Ack receipt of resolution re accident prevention & safety procedures for nuclear plants. Resolution will be forwarded to IE for consideration & action & to CR Stevens for docketing. Resolution encl.
SNYDER, G L. Region 1, Philadelphia, Office of the Director. 79/06/26. 3pp.

DOCKETED ITEMS

H. General correspondence

7908090408 Forwards info re corporate mgt & technical abilities available to anticipate,preclude & respond to events such as TMI-2, in response to 790629 request Radiation Mgt Corp provides necessary personnel to meet radiation incident
FINFROCK, I. R. Jersey Central Power & Light Co. 79/08/06 188pp

J. Insurance & indemnity information

7908230375 Forwards Endorsements 50-52 to MAELU Policy MF-44
GERETY, H. F. GPU Service Corp. 79/08/15 4pp

7908210440 Forwards requested 790718 ltr to J Saltzman re Huey claim Summons & complaint by J O'Mallon re suit against Westinghouse encl
ALTON, C. G. American Nuclear Insurers 79/08/16 1p

P. Operating license stage documents & correspondence

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project
SMITH, H. Operating Reactors Branch 2 (Pre 790625) 79/04/19 5pp

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project
LEVIN, H. A. Systematic Evaluation Programs Branch (Pre 790625) 79/03/08 10pp

7907190641 Safety evaluation supporting Amend 36 to License DPR-16
* Operating Reactors Branch 2 (Pre 790625) 79/05/30 3pp

7908080653 Confirms 790801 meeting w/util in King of Prussia,PA re radiation safety program at facility
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/01 1p

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation W/o encl
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp

7908030355 Responds to request for info re unscheduled shutdowns Forwards Gray Book Sheets & NRC Chron Sheets 790401-770131 W/o encl
ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625) 79/06/05 1p

7908070436 Notifies of intent to install second communications sys linking facilities w/NRC regional ofc & main Bethesda,MD , ofc Second line will be used to relay radiologic & environ data during emergencies Testing procedures encl
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp

7908080047 Notification of 790629 meeting w/Mark I owners group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program proposed agenda encl
GRIMES, C. I. Plant Systems Branch 79/06/27 2p

7908100211 Forwards Amend 38 to License DPR-16, safety evaluation & notice of issuance & availability
ZIEMANN, D. L. Operating Reactors Branch 2 79/06/29 2pp

--7908100214 Amend 38 to License DPR-16, authorizing limited extension for certain plant mods required to improve fire protection
ZIEMANN, D. L. Operating Reactors Branch 2 79/06/29 2pp

--7908100218 Safety evaluation supporting Amend 38 to License DPR-16
* Operating Reactors Branch 2 79/06/29 7pp

--7908100223 Notice of issuance & availability of Amend 38 to License DPR-16
ZIEMANN, D. L. Operating Reactors Branch 2 79/06/29 2pp

7908280874 Confirms 790626 meeting w/util & NRC in King of Prussia, PA re planned improvements in facility radiation protection program
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/03 1p

7908080064 Notifies that supporting safety evaluation for Amend 35 to License DPR-16 supersedes evaluation of SEP Topic IV-1.A issued by NRC 790208 ltr
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/10 2pp

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI
KANE, W. F. Standardization Branch 79/07/11 26pp

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves W/o encl
GRIMES, B. K. Assistant Director for Systems Engineering 79/07/16 4pp

7908280569 Forwards request for addl info required for review of SEP structural topics Response requested within 30 days
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/16 3pp

7908020034 Forwards requests for info re sys capable of providing post-accident & transient core cooling & containment isolation sys
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/17 19pp

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda,MD to discuss status of TMI-2 activities by NRC task force groups Meeting agenda & list of attendees encl
EISENHUT, D. G. Division of Operating Reactors 79/07/18 58pp

7908070240 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors Info requests will not be made while plant is in shutdown mode
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908170468 Forwards summary of 790628 meeting re NRC evaluation program for operating BWR plants & near-term OLs
* Office of Nuclear Reactor Regulation 79/07/19 3pp

7908160161 Forwards Amend 39 to License DPR-16, safety evaluation & issuance & availability
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/23 2pp

--7908160169 Amend 39 to License DPR-16, adding limiting safety sys setting for automatic initiation of isolation condenser & assembly average power void relationship for all types in reactor
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/23 8pp

--7908160179 Safety evaluation supporting Amend 39 to License DPR-16
* Office of Nuclear Reactor Regulation 79/07/23 5pp

--7908160189 Notice of issuance & availability of Amend 39 to License DPR-16
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/23 2pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events Requests addl five copies of response for each addl unit
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

7908300620 Forwards Amend 40 to License DPR-16, safety evaluation & notice of issuance & availability
ZIEMANN, D. L. Operating Reactors Branch 2 79/08/06 2pp

--7908300621 Amend 40 to License DPR-16, revising administrative controls
ZIEMANN, D. L. Operating Reactors Branch 2 79/08/06 21pp

--7908300629 Safety evaluation supporting Amend 40 to License DPR-16
* Operating Reactors Branch 2 79/08/06 3pp

--7908300634 Notice of issuance & availability of Amend 40 to License DPR-16
ZIEMANN, D. L. Operating Reactors Branch 2 79/08/06 2pp

7908140378 Forwards Nonroutine Environ Operating Rept 50-219/79-01
FINFROCK, I. R. Jersey Central Power & Light Co. 79/08/07 1p

--7908140391 Nonroutine Environ Operating Rept 50-219/79-01 on 790725-26 discrepancy found between condenser discharge temp recorder & output of microprocessor used to provide thermal logging & alarms. Microprocessor reprogrammed.
* Jersey Central Power & Light Co. 79/08/07. 2pp.

7908270099 Notification of 790815 meeting w/representatives of Mark I containment owners group re NRC acceptance criteria for implementation of Mark I containment long-term program & schedule for generic program closure.
GRIMES, C. I. Plant Systems Branch. 79/08/07. 2pp.

7908230681 Notification of 790913 meeting w/JCP&L in Bethesda, MD to discuss problems & schedule of putting augmented off-gas sys in svc; results of review & completeness of radiological effluent Tech Specs.
NOWICKI, S. J. Operating Reactors Branch 2. 79/08/08. 2pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 5pp.

7908240539 Forwards Nonroutine Environ Operating Rept 50-219/79-2.
ROSS, D. A. Jersey Central Power & Light Co. 79/08/10. 1p.

--7908240543 Nonroutine Environ Operating Rept 50-219/79-2 on 790606 revised monitoring sys installed per Tech Specs proved inaccurate. Analog & digital convertors ordered & will be installed. Full compliance expected by 791115.
* Jersey Central Power & Light Co. 79/08/08. 2pp.

7908210300 Forwards Nonroutine Environ Operating Rept 50-219/79-03.
FINFROCK, J. R. Jersey Central Power & Light Co. 79/08/14. 1p.

--7908210307 Nonroutine Environ Operating Rept 50-219/79-03 on 790719 dilution pump 3 tripped out of svc & pump 2 was not started for 18 minutes. Caused by seaweed buildup in seal water pump sections. Pump cleared.
* Jersey Central Power & Light Co. 79/08/14. 2pp.

7908240519 Forwards Nonroutine Environ Opeerating Rept 50-219/79-3.
FINFROCK, J. R. Jersey Central Power & Light Co. 79/08/14. 1p.

--7908240522 Nonroutine Environ Rept 50-219/79-3 on 790719 Dilution pump tripped & delay in placing reserve pump in operation exceeded 15 minutes. Pump trip caused by low seal water pressure resulting from seaweed buildup in pump sections.
* Jersey Central Power & Light Co. 79/08/14. 2pp.

7908270469 Notifies that util has submitted NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWR Reactors," in response to NRC 790717 request. Later revision will include remainder of requested info.
FINFROCK, J. R. Jersey Central Power & Light Co. 79/08/17. 1p.

7908270399 Forwards Nonroutine Environ Operating Rept 50-219/79-4, re dilution pump 2 trip.
ROSS, D. A. Jersey Central Power & Light Co. 79/08/21. 1p.

--7908270402 Nonroutine Environ Operating Rept 50-219/79-4 on 790801 dilution pump 2 tripped due to high lube oil temp. Caused by pump oil temp switch being out of calibr. Switch was recalibr.
* Jersey Central Power & Light Co. 79/08/21. 2pp.

7908310340 Forwards Nonroutine Environ Operating Rept 50-219/74-04 on 790801.
ROSS, D. A. Jersey Central Power & Light Co. 79/08/21. 1p.

--7908310343 Nonroutine Environ Operating Rept 50-219/79-04 on 790801 dilution pump 2 tripped due to high lube oil temp & could not be restarted. Caused by component failure. Lube oil temp was recalibr & memo issued.
* Jersey Central Power & Light Co. 79/08/21. 2pp.

9. Inspection reports, IE Bulletins & correspondence

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790828 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 79/06/20. 44pp.

7908130386 Forwards IE Insp Rept 50-219/79-08 on 790419-20. No noncompliance noted.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/06/21. 2pp.

--7908130390 IE Insp Rept 50-219/79-08 on 790419-20. No noncompliance noted. Major areas inspected: containment integrated leak rate test rept & licensee actions on previous insp findings.
SMITH, T. H., REKITO, W. A., CAPHTON, D. L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/06/19. 9pp.

7908130410 Forwards IE Insp Rept 50-219/79-09 on 790424-26. No noncompliance noted.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/06/21. 2pp.

--7908130422 IE Insp Rept 50-219/79-09 on 790424-26. No noncompliance noted. Major areas inspected: post-refueling startup testing for Cycle 8, including control rod sequence & reactivity checks & core power distribution.
BETTENHAUSEN, L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. CAPHTON, D. L. Region 1, Philadelphia, Office of the Director. 79/06/20. 6pp.

7908010678 Ack receipt of 790604 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/79-06.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/07/03. 1p.

--7908010686 Responds to NRC 790517 ltr re violations noted in IE Insp Rept 50-219/79-06. Corrective actions: lifted lead log corrected to reflect replacement of wide range level lead.
FINFROCK, J. R. Jersey Central Power & Light Co. 79/06/04. 1p.

--7908010697 Forwards IE Insp Rept 50-219/79-06 on 790410-12 & notice of violation.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/05/17. 2pp.

--7908010704 Notice of violation from insp of 790410-12.
* Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/05/17. 1p.

--7908010712 IE Insp Rept 50-219/79-06 Noncompliance noted: failure to follow lifted lead & jumper procedures.
MCCABE, E. C., BRIGGS, L. E., COWGILL, C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/05/16. 6pp.

7908070643 Responds to IE Bulletin 79-11 re potential failure of Westinghouse circuit breakers. Discusses test procedures & test schedules for all safety-related circuit breakers. No Westinghouse switchgear used in safety-related sys.
ROSS, D. A. Jersey Central Power & Light Co. 79/07/03. 2pp.

7908070845 Forwards response to IE Bulletin 79-02 re reliability of pipe support base plates that use concrete expansion anchor bolts in seismic sys. Reviews base plate flexibility & bolt min factor of safety. Test program in progress.
ROSS, D. A. Jersey Central Power & Light Co. 79/07/06. 14pp.

7908010426 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060373 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030246 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908080300 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/20. 5pp.

7908280100 Ack receipt of 790430 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-219/78-04 & 50-219/79-05.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/07/23. 1p.

--7908280106 Responds to NRC 790403 ltr re violations noted in IE Insp Repts 50-219/78-04 & 50-219/79-05. Corrective actions: all single copy records moved to records vault. New single copy records will be sent to vault within 6 month period.
ROSS, D. A. Jersey Central Power & Light Co. 79/04/30. 2pp.

--7908280109 Ack receipt of 790228 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-219/78-04 & 50-219/79-05. Requests schedule of milestones for completing corrective actions.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/03. 2pp.

DOCKETED ITEMS

--7908280111 Reports on status of steps taken to correct noncompliance noted in IE Insp Repts 50-219/78-04 Corrective action single record storage facility established in bank vault. Document center record retention sys being upgraded.
ROSS, D. A. Jersey Central Power & Light Co. 79/02/28. 2pp.

7908100229 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908090296 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908130259 Responds to IE Bulletins 79-14 & 79-14, Revision 1, re seismic analysis for as-built safety-related piping. Insp program has been initiated on safety-related sys w/criteria specified in bulletin.
FINFROCK, I. R. Jersey Central Power & Light Co. 79/08/01. 1p.

7908280088 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908230302 Forwards IE Circular 79-15, "Bursting of High Pressure Hosu & Malfunctir of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/08. 1p.

7908160436 Forwards addl response to IE Bulletin 79-08 requested in in 790720 ltr. Revisions to administrative procedures provide assurance that retesting of sys is completed prior to need for operability.
FINFROCK, I. R. Jersey Central Power & Light Co. 79/08/09. 7pp.

7908270544 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/10. 1p.

7908280273 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908300124 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelrhia, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908060247 Forwards Addendum 1 to Semi-Annual Effluent Release Rept 78-2, Jul-Dec 1978.
ROSS, D. A. Jersey Central Power & Light Co. 79/08/01. 1p.

--7908060255 Addendum 1 to Semi-Annual Effluent Release Rept 78-2, Jul-Dec 1978.
ROSS, D. A. Jersey Central Power & Light Co. 79/08/01. 6pp.

7908210426 Forwards monthly operating data submitted for Gray Book.
FINFROCK, I. R. Jersey Central Power & Light Co. 79/08/14. 9pp.

S. Reportable occurrences, LERs & related correspondence

7908080428 Forwards RO 50/219/79/20-1P.
CARROLL, J. T. Jersey Central Power & Light Co. 79/06/14. 1p.

--7908080432 RO 50/219/79/20-1P on 790613 secondary containment integrity not maintained for 11 minutes when both reactor bldg railroad airlock doors were open. Caused by inadequate procedure for operating airlock doors.
MCNAIR, R. C. Jersey Central Power & Light Co. 79/06/14. 2pp.

7908070584 Forwards LER 79-022/03L-0.
ROSS, D. A. Jersey Central Power & Light Co. 79/07/27. 1p.

--7908070589 LER 79-022/03L-0 on 790627: leak detected on emergency svc water side of containment spray heat exchanger 1-2. Caused by leaking nipple connection between water box & piping to valve V-3-83 due to corrosion. Nipple replaced.
ROSS, D. A. Jersey Central Power & Light Co. 79/07/27. 3pp.

7908060223 Forwards LER 79-023/01T-0.
FINFROCK, I. R. Jersey Central Power & Light Co. 79/08/02. 1p.

--7908060229 LER 79-023/01T-0 on 790719 reactor power was reduced above value for removal of "A" feedwater string. Caused by removal of recirculating pump reactor for maint. Inboard & outboard collector rings resurfaced & pump returned to svc.
ROSS, D. A. Jersey Central Power & Light Co. 79/08/02. 3pp.

7908140670 Forwards RO 50-219/79-25-1P.
CARROLL, J. T. Jersey Central Power & Light Co. 79/08/07. 1p.

--7908140676 RO 50-219/79-25-1P on 790806, 1-inch isolation valve on torus sample line was found in open position. Caused by failure of technician to close isolation valve after sampling torus water. Valve closed.
MCNAIR, R. C. Jersey Central Power & Light Co. 79/08/07. 2pp.

7908230353 Forwards RO 79-27/01P.
CARROLL, J. T. Jersey Central Power & Light Co. 79/08/08. 1p.

--7908230355 RO 79-27/01P on 790807, four seismic restraints for 6-inch core spray test line failed or were in positions other than required by design criteria. Caused by component failure. Investigation in progress.
QUINTENZ, T. E. Jersey Central Power & Light Co. 79/08/08. 1p.

7908280689 Forwards LER 79-027/01T-0.
ROSS, D. A. Jersey Central Power & Light Co. 79/08/21. 1p.

--7908280701 LER 79-027/01T-0 on 790807, four seismic restraints, NZ-2-R5 NZ-2R7, NZ-2-R8 & NZ-2-R9, in positions other than required by original design. Caused by improper installation & damage due to unrestrained pipe movement.
ROSS, D. A. Jersey Central Power & Light Co. 79/08/21. 3pp.

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7908030377 Forwards 790625 fire protection QA program per request.
DISE, D. P. Niagara Mohawk Power Corp. 79/07/31. 1p.

--7908030385 Fire protection QA program.
BRYANT, W. H., CORCORAN, J. R., HOWLETT, D. B. Niagara Mohawk Power Corp. 79/06/25. 8pp.

7908240464 Reviews 790726 fire protection safety evaluation rept for facility & provides info requested. Includes tables re 690224 & 790706 diesel fire pump tests & fire pump.
DISE, D. P. Niagara Mohawk Power Corp. 79/08/17. 5pp.

7908240496 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
BARTLETT, T. Niagara Mohawk Power Corp. 79/08/17. 1p.

I. Financial information

7908030305 Forwards Annual Financial Rept 1978 & associated cash flow & earnings data.
RUSHMORE, J. W. Niagara Mohawk Power Corp. 79/07/31. 1p.

--7908030309 "1978 Annual Rept." Associated cash flow & earnings data encl.
* Niagara Mohawk Power Corp. 78/12/31. 33pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908010449 Forwards FSAR Suppl 13, updating QA program.
SCHNEIDER, R. R. Niagara Mohawk Power Corp. 79/07/30. 1p.

--7908010451 FSAR Suppl 13.
* Niagara Mohawk Power Corp. 79/07/30. 64pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp

7908070459 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & envir_n data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp

7908080047 Notification of 790629 meeting w/Mark I owners group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program proposed agenda encl.
GRIMES, C. I. Plant Systems Branch 79/06/27 2p

7908130298 Requests that util propose changes to Tech Specs re responsibilities of senior reactor operator. All core operations should be directly supervised by senior reactor operator who has no other responsibilities during operation.
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/06 2pp

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch 79/07/11 26pp

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering 79/07/16 4pp

7908070248 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908270164 Forwards input to safety evaluation re proposed mods per technical assistance contract 7442 to spent fuel storage racks for facility.
LAINAS, G. Plant Systems Branch 79/07/19 2pp

--7908270207 Safety evaluation input re application for amend to OL to increase authorized space capacity of spent fuel pool at facility.
LAINAS, G. Plant Systems Branch 79/07/19 5pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908220373 Forwards Amend 33 to License DPR-63, safety evaluation & notice of issuance & availability.
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/26 3pp

--7908220378 Amend 33 to License DPR-63, adding license conditions re completion of facility mods for fire protection.
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/26 2pp

--7908220382 Fire protection safety evaluation supporting Amend 33 to License DPR-63.
* Office of Nuclear Reactor Regulation 79/07/26 78pp

--7908220387 Notice of issuance & availability of Amend 33 to License DPR-63.
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/26 2pp

7908010362 Informs that radwaste reduction sys is being deferred, as current schedule for demonstration does not provide timely review of results prior to installation.
RHODE, G. K. Niagara Mohawk Power Corp 79/07/27 2pp

7908030500 Discusses reasons for plant safety review & audit board changing annual audit on ETS from third quarter to fourth quarter of year.
DISE, D. P. Niagara Mohawk Power Corp 79/07/31 1p

7908070620 Notifies of plan to submit requested info by 790810 re mgt & technical resources available to util.
DISE, D. P. Niagara Mohawk Power Corp 79/07/31 1p

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

7908230155 Requests util provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 5pp

7908130364 Submits info re mgt & technical resources available to respond to unusual events, in response to NRC 790629 request.
DISE, D. P. Niagara Mohawk Power Corp 79/08/10 47pp

7908220381 Notifies that info requested in NRC 790713 ltr re safety sys is in NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs," transmitted to D. Ross on 790817. Rept suppl will be submitted by 791116.
DISE, D. P. Niagara Mohawk Power Corp 79/08/17 1p

7908310414 Responds to 790402 ltr. Forwards "Startup Physics Test Results - Cycle 6, June 1979."
DISE, D. P. Niagara Mohawk Power Corp 79/08/27 1p

--7908310416 "Startup Physics Test Results - Cycle 6, June 1979."
* Niagara Mohawk Power Corp 79/06/30 15pp

G. Inspection reports, IE Bulletins & correspondence

7908010720 Forwards IE Insp Rept 50-220/79-10 on 790315. No noncompliance noted.
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/06/11 2pp

--7908010722 IE Insp Rept 50-220/79-10 on 790315. No noncompliance noted. Rept contains results of effluent sample split between licensee & Region I during previous insp of 780925-27.
KOTTAN, J. J.; STOHR, J. P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/06/06 4pp

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625) 79/06/20 44pp

7908070311 Responds to IE Bulletin 78-12. No archive weld matl in Unit 1 for verification. C-E generic rept re atypical weld matl in reactor pressure vessel welds addressed facility data. C-E certification & GE 790620 ltr to plant superintendent encl.
SCHNEIDER, R. R. Niagara Mohawk Power Corp. 79/06/28 3pp

--7908070324 Forwards C-E rept, "Info Requested by IE Bulletin 78-12, Atypical Weld Matl in Reactor Pressure Vessel Welds."
SCHERER, A. E. Combustion Engineering, Inc 79/06/08 1p

7908070743 Responds to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion anchor bolts. Discusses status of insp, testing & repair program re base plate dimensional checks & anchor bolt examination.
LEMPGES, T. E. Niagara Mohawk Power Corp 79/07/06 8pp

7908070661 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breakers of engineered safety sys. Plant does not use Westinghouse Type DB-50 & DB-75 circuit breakers in any safety sys.
LEMPGES, T. E. Niagara Mohawk Power Corp 79/07/09 1p

7908210175 Updates 790611 response to IE Bulletin 79-01. Forwards addl documentation re equipment environ qualification in reactor bldg. Response to IE Bulletin 79-01A re solenoid valves will be forwarded by 790912.
SCHNEIDER, R. R. Niagara Mohawk Power Corp 79/07/12 18pp

--7908210183 Forwards addl info to suppl util 771208 & 780113 ltrs re environ qualification of terminal blocks mounted inside junction boxes.
SWITZER, D. C. Connecticut Yankee Atomic Power Co 78/03/29 14pp

7908010509 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/17 1p

DOCKETED ITEMS

7908060385 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/07/18 1p

7908030257 Notifies that written responses to IE Bulletin 79-15, Suppl 1,should be directed to IE Div of Reactor Const Insp.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/07/19 1p

7908080321 Requests addl info to suppl previous response to IE Bulletin 79-08,to enable NRC to complete safety evaluation.
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/20 4pp

7908100247 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/07/26 1p

7908090314 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/07/30 1p

7908240583 Responds to IE Bulletin 79-12 re short period scrams at BWR facilities.Describes procedural restrictions which limit use of notch override feature during approach to criticality.
RHODE,G.K. Niagara Mohawk Power Corp 79/07/30 2pp

7908070657 Forwards addl info in response to IE Bulletin 79-08 re review of TMI-2 events,redundant instrumentation to determine reactor coolant inventory,procedures involved in overriding automatic safety actions & valve check-off lists.
BARTLETT,J. Niagara Mohawk Power Corp. 79/08/03 10pp

7908280149 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/07 1p

7908230347 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/08 1p

7908270554 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste For Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/10 1p

7908280306 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/13 1p

7908310287 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/14 1p

7908300153 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/15 1p

R Periodic operating reports & related correspondence

7908150630 Forwards monthly operating rept for Jul 1979.
LEMPGES,T.E.; SCHNEIDER,R.R. Niagara Mohawk Power Corp. 79/08/10
1p

--7908150633 Monthly operating rept for Jul 1979.
PERKINS,T.J. Niagara Mohawk Power Corp. 79/08/10 4pp

S Reportable occurrences, LERs & related correspondence

7908140651 Forwards LER 79-018/03L-0.
LEMPGES,T.E. Niagara Mohawk Power Corp. 79/08/10 1p

--7908140655 LER 79-018/03L-0 on 790726,vacuum relief sys switch 68-128 failed to open at proper setpoint.No cause identified.Switch adjusted to proper setpoint.
DUDA,E. Niagara Mohawk Power Corp. 79/08/10 1p

DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

J Insurance & indemnity information

7908280600 Forwards executed Amend 8 to Indemnity Agreement E-54.
WALLACE,T.J. Lowell Technological Institute. 79/08/22 2pp

Q Inspection reports, IE Bulletins & correspondence

7908070084 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/06/22 1p

7908090693 Forwards IE Insp Rept 50-223/79-01 on 790418-20.No noncompliance noted.
BRUNNER,E.J. Region 1, Philadelphia, Office of the Director.
79/06/22 2pp

--7908090694 IE Insp Rept 50-223/79-01 on 790418-20.No noncompliance noted.Major areas inspected:logs & records,organization & administration,operator licenses & operator requalification program.
STETKA,T.P.; MCCABE,E.C. Region 1, Philadelphia, Office of the Director. 79/06/21 6pp

7908280280 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/10 1p

7908310246 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/14 1p

S Reportable occurrences, LERs & related correspondence

7908013533 Responds to 790703 telcon re Dec 1978 hand exposure incident.Reactor safety committee met on 790719 & concluded matter was properly reported,as violation was fault of one individual.
CHABOT,G.E. Lowell, Univ. of. 79/07/20 2pp

DOCKET 50-224 UNIV. OF CALIFORNIA RESEARCH REACTOR

P Operating license stage documents & correspondence

7908060359 Forwards new revised "A-B-C List Personnel," "Entry & Authorization List A" & "Emergency Call List."
LIM,T.M. California, Univ. of, Berkeley 79/07/16 4pp

Q Inspection reports, IE Bulletins & correspondence

7908170046 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director.
79/08/10 1p

7908310188 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director.
79/08/14 1p

DOCKET 50-225 RPI CRITICAL EXPERIMENT

Q Inspection reports, IE Bulletins & correspondence

7908070077 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/06/22 1p

7908280274 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/10 1p

7908310243 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/14 1p

DOCKET 50-227 TRIGA THERMIONIC PROTOTYPE REACTOR

J. Insurance & indemnity information

7908140618 Forwards Endorsements 48 & 49 to MAELU Policy MF-59.
CORREA,C. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc., Div. 79/08/08 3pp.

P. Operating license stage documents & correspondence

7908250801 Summary of 790628 meeting w/GA Co in Bethesda,MD re revised design of gas cooled fast breeder.
WILLIAMS,P.M. Division of Project Management 79/08/02 25pp.

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

7908170267 Forwards Amend 3 to Facility License R-98.
REID,R.W. Operating Reactors Branch 4 79/07/18 2pp.

--7908170272 Amend 3 to Facility License R-98 re physical security plan. Plan withheld (ref 10CFR2.790).
REID,R.W. Operating Reactors Branch 4 79/07/18 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908140076 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/08/10 1p.

7908310166 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/08/14 1p.

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

7908130159 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS,R.M. License Fee Management Branch 79/07/03 2pp.

7908160367 Forwards request for addl info re contingency plans. Encl withheld (ref 10CFR2.790).
ZIEMANN,D.L. Operating Reactors Branch 2 79/07/19 2pp.

7908010300 Forwards info to suppl fire protection safety evaluation rept.
JANECEK,R.F. Commonwealth Edison Co 79/07/20 6pp.

7908030478 Forwards Automatic Sprinkler Corp Drawing 26-1790,Revision 2 & associated hydraulic calculations as mod to fire protection sys.
JANECEK,R.F. Commonwealth Edison Co 79/07/27 17pp.

7908200216 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED,C. Commonwealth Edison Co 79/08/16 1p.

G. Adjudicatory correspondence

7907110499 State of IL opposition to NRC 790504 motion & Comm Ed 790507 motion for reconsideration &/or clarification & referral of ASLB 790419 memo & order admitting Contentions 6 & 11.
SEKULER,S.N. Illinois, State of 79/05/17 6pp.

7908200010 Responds to 790524 ltr opposing transport of spent fuel between plants. Explains purpose of application. Risks are well known & very low. Public hearing will be held soon.
IPPOLITO,T.A. Operating Reactors Branch 3 79/08/03 1p.

7908200035 Responds to 790510 ltr opposing transportation of spent fuel. Public hearing will be held on shipment in Fall 1979.
IPPOLITO,T.A. Operating Reactors Branch 3 79/08/03 1p.

7908200039 Responds to 790507 postcard expressing opposition to transportation of spent fuel. Public hearing on proposed shipment will be held Fall 1979.
IPPOLITO,T.A. Operating Reactors Branch 3 79/08/03 1p.

7908290108 Responds to 790502 & 12 ltrs re hearing on spent fuel transfer. Hearing will be held no earlier than Sept 1979.
IPPOLITO,T.A. Operating Reactors Branch 3 79/08/03 1p.

7908220204 Forwards ASLB 790730 notice of reconstitution of Board re spent fuel pool mod proceeding.
* Operating Reactors Branch 2 79/08/07 2pp.

--7908220208 Notice of reconstitution of Board. JF Wolf replaces E Luton as ASLB chairman.
LAZO,R.M. Atomic Safety and Licensing Board Panel 79/07/30 3pp.

P. Operating license stage documents & correspondence

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH,H. Operating Reactors Branch 2 (Pre 790625) 79/04/19 5pp.

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project.
LEVIN,H.A. Systematic Evaluation Programs Branch (Pre 790625) 79/03/08 10pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT,D.G. Division of Operating Reactors 79/06/04 52pp.

7908070652 Notifies of intent to install second communications sys linking facilities w/NRC regional ofc & main Bethesda,MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/06/22 3pp.

7908140280 Notifies that fees quoted in 790416 ltr will not be required.
MILLER,W.O. Office of Administration 79/06/27 1p.

7908130310 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill; if drill scenario requires NRC initial notification.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/09 1p.

7908080719 Confirms that meeting at util corporate office has been rescheduled for 790719 at 3 PM. Location, purpose & attendees discussed in NRC 790612 ltr.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/10 1p.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE,W.F. Standardization Branch 79/07/11 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES,B.K. Assistant Director for Systems Engineering 79/07/16 4pp.

7908160050 Forwards request for addl info to suppl 790530 response re spent fuel pool mod.
ZIEMANN,D.L. Operating Reactors Branch 2 79/07/16 3pp.

7908160092 Forwards request for addl info re requirements for preparation of NRC generic rept on BWRs.
ZIEMANN,D.L. Operating Reactors Branch 2 79/07/17 19pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda,MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT,D.G. Division of Operating Reactors 79/07/18 58pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL,W.P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908070332 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/19 1p.

DOCKETED ITEMS

7908170468 Forwards summary of 790628 meeting re NRC evaluation program for operating BWR plants & near-term OLs.
* Office of Nuclear Reactor Regulation 79/07/19 3pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W.P. Quality Assutance Branch 79/07/24 1p

7908010445 Responds to NRC 790618 ltr re SEP. Forwards addl info re Topic VIII-3.B, onsite dc battery sys.
JANECEK, R.F. Commonwealth Edison Co 79/07/25 3pp

7908010470 Responds to informal info request re SEP review of new fuel storage areas.
JANECEK, R.F. Commonwealth Edison Co 79/07/25 2pp

7908020419 Responds to 790606 ltr re SEP Topic VI-1. Forwards tables & answers to questions 1-7 re major protective coating sys in containment, pipe & hanger surface & amounts of organic matl inside containment.
JANECEK, R.F. Commonwealth Edison Co 79/07/27 4pp

7908030302 Submits revised schedule for mod to diesel generator annunciator sys schedule. Updates schedule in util 790202 ltr.
JANECEK, R.F. Commonwealth Edison Co 79/07/27 2pp

7908020460 Submits schedule for addl response to NRC issues re containment purging during normal plant operation.
REED, C. Commonwealth Edison Co 79/07/30 2pp

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co 79/07/30 2pp

7908030140 Forwards addl info re SEP seismic review in response to 790621 request. Info includes reactor internal stress analysis & turbine-to-reactor bldg junction design computations.
JANECEK, R.F. Commonwealth Edison Co 79/07/31 108pp

7908200287 Ack receipt of 790709 ltr requesting info re operation of isolation (emergency) condensers. Submits station procedures defining proper methods of initiating makeup to condenser shell.
JANECEK, R.F. Commonwealth Edison Co 79/08/03 2pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D.G. Division of Operating Reactors 79/08/03 53pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908160456 Forwards addl copy of design control summary by Sargent & Lundy re reactor bldg-turbine bldg junction, per 790810 request.
SMITH, N.P. Commonwealth Edison Co 79/08/10 8pp

7908200380 Forwards info requested in NRC 790629 & 0724 ltrs re capabilities & technical resources available to handle unusual events.
JANECEK, R.F. Commonwealth Edison Co 79/08/13 1100pp

7908280392 Submits addl info in response to NRC 790621 ltr re seismic design of control rod drive hydraulic tube. Drawings of cable trays & supports encl.
JANECEK, R.F. Commonwealth Edison Co 79/08/15 22pp

7908280575 Forwards response to DL Ziemann 790716 ltr to C Reed requesting addl info re fuel pool mods.
JANECEK, R.F. Commonwealth Edison Co 79/08/17 8pp

7908230420 Informs that GE rept NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs" was submitted to NRC by TD Keenan 790817 ltr to D Ross. Remainder of info follows in 791116 rept.
JANECEK, R.F. Commonwealth Edison Co 79/08/20 1p

8. Inspection reports, IE Bulletins & correspondence

7908020548 Forwards IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06 on 790326-28, notice of violation & notice of deviation.
HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/10 2pp

--7908020555 Notice of violation from insp on 790326-28.
* Region 3, Chicago, Office of the Director 79/05/09 1p

--7908020566 Notice of deviation from insp on 790326-28.
* Region 3, Chicago, Office of the Director 79/05/09 1p

--7908020572 IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06 on 790326-28. Noncompliance noted: failure to conduct five brigade training sessions on quarterly basis & failure to develop procedure for control of combustibles.
RIDEN, M.D., LITTLE, W.S. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/09 5pp

7908010223 Forwards IE Insp Repts 50-010/79-12, 50-237/79-15 & 50-249/79-13 on 790501-0601 & notice of violation.
HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/15 2pp

--7908010227 Notice of violation from insp on 790501-0601.
* Region 3, Chicago, Office of the Director 79/06/13 1p

--7908010231 IE Insp Repts 50-010/79-12, 50-237/79-15 & 50-249/79-13 on 790501-0601. Noncompliance noted: reactor was started w/no battery not connected to bus.
BARKER, S.L., SPESSARD, R.L. Region 3, Chicago, Office of the Director 79/06/13 11pp

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625) 79/06/20 44pp

7908080523 Responds to IE Bulletin 79-11. No Westinghouse DB-50 & DB-75 circuit breakers used in safety-related sys.
REED, C. Commonwealth Edison Co 79/07/02 1p

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co 79/07/05 9pp

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc 79/05/31 24pp

7908060703 Submits addl response to IE Bulletins 78-12 & 12B. Requested vessel evaluation completed & certification by manufacturer & supplier submitted to NRC.
REED, C. Commonwealth Edison Co 79/07/09 2pp

7908150349 Supplements response to IE Bulletin 79-11. Westinghouse DB-50 & DB-75 circuit breakers are neither used in safety-related sys nor stored as spares at facilities.
REED, C. Commonwealth Edison Co 79/07/12 2pp

7908080306 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO, T.A. Operating Reactors Branch 3 79/07/20 4pp

7908150286 Ack receipt of 790703 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/79-13 & 50-249/79-11.
HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/07/23 2pp

--7908150299 Responds to NRC 790613 ltr re violations noted in IE Insp Repts 50-237/79-13 & 50-249/79-11. Corrective actions: valve & breaker switch alignment checklists are being reviewed & corrected.
REED, C. Commonwealth Edison Co 79/07/03 3pp

7908170[illegible] Submits Spring 1979 Inservice Insp Rept for reactor pressure vessel, rl & primary sys piping.
STEPHENSON, B.B. Commonwealth Edison Co 79/07/23 1p

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908240513 Responds to IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." Procedures involving reactor criticality, control rod withdrawal sequences & operator training program were modified in 1977.
REED, C. Commonwealth Edison Co. 79/07/30 9pp.

7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED, C. Commonwealth Edison Co. 79/08/01 2pp.

7908080530 Forwards addl info re responses to IE Bulletin 79-08, per 790720 request.
REED, C. Commonwealth Edison Co. 79/08/03 6pp.

7908170019 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08 1p.

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15 1p.

R. Periodic operating reports & related correspondence

7908300459 Forwards semiannual "Rept of Radioactive Effluent Discharges & Solid Radwaste" for Jan-June 1979.
STEPHENSON, B. B. Commonwealth Edison Co. 79/08/14 1p.

--7908300466 "Rept of Radioactive Effluent Discharges & Solid Radwaste" for Jan-June 1979.
* Commonwealth Edison Co. 79/06/30 15pp.

S. Reportable occurrences, LERs & related correspondence

7908080383 Forwards LER 79-044/03L-0.
STEPHENSON, B. B. Commonwealth Edison Co. 79/08/03 1p.

--7908080387 LER 79-044/03L-0 on 790709 w/unit at steady power & performing surveillance test on diesel generator & generator cooling water pump, trouble alarms were activated. Cause not determined.
CHAN, J. Commonwealth Edison Co. 79/08/03 1p.

7908220397 Forwards LER 79-010/01X-1.
STEPHENSON, B. B. Commonwealth Edison Co. 79/08/10 1p.

--7908220400 LER 79-010/01X-1 on 790202 section of blowout panel west side of refueling floor was blown out, breaching secondary containment. Caused by ventilation sys malfunction & improper design of explosion bolts. Vent control mod being evaluated.
CHAN, J. Commonwealth Edison Co. 79/08/15 2pp.

7908280640 Forwards LER 79-045/03L-0.
STEPHENSON, B. B. Commonwealth Edison Co. 79/08/21 1p.

--7908280646 LER 79-045/03L-0 on 790724 diesel coolant surge tank dropped one inch from previous day, causing leakage into lube oil. Caused by worn O-ring in head cooling water flange outlet. O-ring replaced & diesel tested operable.
DOYLE, J. E. Commonwealth Edison Co. 79/08/21 1p.

DOCKET 50-243 OREGON STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

7908170223 Requests addl info re calibr circuits for linear & log power & burn-in procedures to be used for instrumentation. Schedule for providing addl info expected within 30 days.
REID, R. W. Operating Reactors Branch 4. 79/07/20 3pp.

7908240488 Forwards addl info requested in NRC 790720 ltr re amend to Tech Specs. Withdraws 790416 request for proposed Change 15 & requests approval for electronic mod to console by 790915 in order to begin fall term.
SMITH, C. V. Oregon State Univ. 79/08/17 18pp.

Q. Inspection reports, IE Bulletins & correspondence

7908170041 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10 1p.

7908310180 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14 1p.

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

7908270203 Ack receipt of 790323 ltr transmitting safeguards contingency plan for facility Class III fee required.
DIGGS, R. M. License Fee Management Branch. 79/07/03 2pp.

7908010551 Forwards review fee for safeguards contingency plan submitted on 790323.
WHITE, L. D. Rochester Gas & Electric Corp. 79/07/25 2pp.

7908030383 Discusses reasons for delay from July 1979 to 791001 for installation of curbs in screenhouse around diesel fire pump area.
WHITE, L. D. Rochester Gas & Electric Corp. 79/07/27 1p.

7908210001 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
WHITE, L. D. Rochester Gas & Electric Corp. 79/08/17 1p.

Q. Adjudicatory correspondence

7908090510 Forwards util 790731 response to NRC 790712 request re undervoltage protection. Requests info be withheld (ref 10CFR2.790).
FARON, R. S. LeBoeuf, Lamb, Leiby & MacRae. 79/08/03 2pp.

--7908090511 Responds to NRC 790717 request for info re undervoltage protection. Forwards "Single Line Diagram Train A for Existing Undervoltage Sys" & "Ongoing Evaluation of Safety Integrity." Info withheld (ref 10CFR2.790).
WHITE, L. D. Rochester Gas & Electric Corp. 79/07/31 7pp.

H. General correspondence

7908010496 Confirms 790724 telcon. Compilation of info re mgt & technical staffs will be completed by 790814.
WHITE, L. D. Rochester Gas & Electric Corp. 79/07/25 1p.

7908240391 Forwards statement released to media on 790815 re claim brought against util by contractor employee claiming injury due to overexposure to radiation. Damages of $5 million sought.
LOHRMANN, A. A. Rochester Gas & Electric Corp. 79/08/16 2pp.

J. Insurance & indemnity information

7908140570 Forwards Endorsement 62 to NELIA Policy NF-170 & Endorsement 52 to MAELU Policy MF-52.
WHITE, L. D. Rochester Gas & Electric Corp. 79/08/10 3pp.

P. Operating license stage documents & correspondence

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH, H. Operating Reactors Branch 2 (Pre 790625). 79/04/19 5pp.

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project.
LEVIN, H. A. Systematic Evaluation Programs Branch (Pre 790625). 79/03/08 10pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04 52pp.

7908300185 Ack receipt of 771222 licensee submittal. Forwards request for addl info re degraded grid voltage (request TAC 10024).
LAINAS, G. Plant Systems Branch. 79/06/19 3pp.

7908010319 Notifies of review of util 790607 request for amend to License DPR-18, as result of mod proposed in IE Bulletin 79-06A. Mod to safety injection actuation sys logic & Tech Specs acceptable. Forwards safety evaluation.
LAINAS, G. Plant Systems Branch. 79/06/20 2pp.

DOCKETED ITEMS

--7908010327 Safety evaluation of amend to License DPR-18 re safety injection actuation sys logic & changes to Tech Specs. Mod acceptable.
* Plant Systems Branch 79/06/20 1p

7908070469 Notifies of intent to install second communications sys, linking Facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp

7908080081 Requests addl info in order to complete review of 771222 submittal re degraded grid voltage.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/12 2pp

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/18 58pp

7908070263 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908170196 Forwards model license condition that requiring implementation of secondary water chemistry monitoring & control program. Condition replaces Aug 1976 proposed Tech Specs re corrosion of steam generator tubes.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/23 4pp

7908170251 Notification of 790724 meeting w/util & Westinghouse in Bethesda, MD to discuss investigations & repairs resulting from cracks in feedwater line nozzles & elbows.
SHEA, J. J. Operating Reactors Branch 2 79/07/23 1p

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908010379 Responds to NRC 790611 ltr requesting addl info re Westinghouse small break LOCA analysis. Relevant Westinghouse rept was transmitted to NRC w/C Reed 790629 ltr to DF Ross.
WHITE, L. D. Rochester Gas & Electric Corp 79/07/26 1p

7908230070 Forwards Amend 28 to License DPR-18, safety evaluation & notice of issuance & availability.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/26 2pp

--7908230072 Amend 28 to License DPR-18 changing Tech Specs re overpressure protection sys requirements.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/26 4pp

--7908230074 Safety evaluation supporting Amend 28 to License DPR-18.
* Operating Reactors Branch 2 79/07/26 3pp

--7908230076 Notice of issuance & availability of Amend 28 to License DPR-18.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/26 2pp

7908223523 Forwards request for addl info within 45 days re 790323 contingency plan. W/o encl.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/27 2pp

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp

7908200176 Forwards request for addl info re structural topics in SEP. Requests response within 30 days.
ZIEMANN, D. L. Operating Reactors Branch 2 79/08/01 3pp

7908080441 Forwards util 790731 application for amend to OL re undervoltage protection. Tech Spec changes, safety evaluation & info on changes in amount of effluents & power level. Certificate of Svc encl.
LARSON, L. K. LeBoeuf, Lamb, Leiby & MacRae 79/08/03 2pp

--7908080446 Application for amend to License DPR-18 re undervoltage protection.
WHITE, L. D. Rochester Gas & Electric Corp 79/07/31 14pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908200346 Responds to request for info re Tech Spec changes. Forwards dc single line diagram, maint procedures M-38 & M-38.7, Revision 1 & aperture cards of drawings SS-201-041 through 045.
WHITE, L. D. Rochester Gas & Electric Corp 79/08/10 9pp

7908170385 Forwards info requested in HR Denton 790629 ltr. Includes charts of senior mgt structure, facility organization & offsite engineering organization.
WHITE, L. D. Rochester Gas & Electric Corp 79/08/14 60pp

7908210490 Response to conversation w/NRC re dependence of turbine driven auxiliary feedwater sys on ac power & request to commit to demonstrate operability of sys w/o reliance on ac power. Believes no sys changes necessary.
WHITE, L. D. Rochester Gas & Electric Corp 79/08/16 2pp

G. Inspection reports, IE Bulletins & correspondence

7908090330 Responds to IE Bulletins 79-06A & 06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
WHITE, L. D. Rochester Gas & Electric Corp 79/06/22 31pp

7908080671 Responds to IE Bulletin 79-11 re faulty overcurrent trip devices in Westinghouse Type DB-75 & DB-50 circuit breakers for engineered safety sys. Numerous devices presently installed at plant.
WHITE, L. D. Rochester Gas & Electric Corp 79/06/25 2pp

7908070634 Responds to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion anchor bolts. Discusses base plate flexibility, safety factors, cyclical loads & QC documentation.
WHITE, L. D. Rochester Gas & Electric Corp 79/07/06 9pp

7908070452 Responds to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." Item 5 Feedwater nozzle inspected & evaluated. Emergency procedures adequately cover feedwater line break accident.
WHITE, L. D. Rochester Gas & Electric Corp 79/07/12 2pp

7908060012 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/17 1p

7908060499 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908030285 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/19 1p

7908100282 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908100350 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908230107 Forwards supplemental response to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion bolts. Submits info re testing & replacement program, base plate flexibility & replacement program.
WHITE, L. D. Rochester Gas & Electric Corp 79/07/26 9pp

7908290174 Submits further response to IE Bu... in 79-07 to suppl initial 790425 response re seismic stress an lysis of safety-related piping.
WHITE,L.D. Rochester Gas & Electric Corp. 79/07/26 17pp

7908230093 Forwards response to IE Bulletin 79-13 re cracking in feedwater piping.Forwards 30-day rept on examination, evaluation & corrective action taken at plant.
WHITE,L.D. Rochester Gas & Electric Corp. 79/07/27 19pp

7908090335 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/30 1p

7908280190 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/07 1p

7908230364 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/08 1p

7908280028 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908290343 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/13 1p

7908310302 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

7908300199 Forwards IE Bulletin 7[illegible]-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping s." Action required.
GRIER,B.H. Region 1, Philade..phia, Office of the Director 79/08/15 1p

R Periodic operating reports & related correspondence

7908210369 Forwards monthly operating rept for Jul 1979.
SNOW,B.A. Rochester Gas & Electric Co... 79/08/13 1p

--7908210370 Monthly operating rept for Jul 1979.
MCNAMARA,A.E. Rochester Gas & Electric Corp. 79/08/09 5pp

S Reportable occurrences, LERs & related correspondence

7908210437 Confirms 790710 telcon rept re cracking found in feedwater lines.Final rept will be submitted within 30 days.
SNOW,B.A. Rochester Gas & Electric Corp. 79/07/11 4pp

7908270521 Confirms discussion w/D Beckman & R Markowsky re 790724 rept of LER 79-015.Pipe supports in containment vessel identified as nonconforming to original design drawings.Supports to be reworked to original design requirements.
SNOW,B.A. Rochester Gas & Electric Corp. 79/07/24 2pp

7908100471 Forwards LER 79-015/01T-0.
WHITE,L.D. Rochester Gas & Electric Corp. 79/08/07 1p

--7908100475 LER 79-015/01T-0 on 790724 discovered pipe supports not meeting design specs of IE Bulletin 79-14.Caused by lack of documented approvals for field changes & nonconformance during plant const.Supports reworked.
HUTTON,J.C. Rochester Gas & Electric Corp. 79/08/01 2pp

7908140788 Forwards LER 79-014/03L-0.
WHITE,L.D. Rochester Gas & Electric Corp. 79/08/08 1p

--7908140800 LER 79-014/03L-0 on 790709 during RCS cooldown,operator noted channel P-452 overpressurization alarm not in correct state.Caused by bistable setpoint drift.Alarm unit replaced.
EDGAR,E.C. Rochester Gas & Electric Corp. 79/08/08 1p

7908210515 Forwards LER 79-016/01T-0.
WHITE,L.D. Rochester Gas & Electric Corp. 79/08/16 1p

--7908210524 LER 79-016/01T-0 on 790804 14-h interval of reactor operation lapsed prior to trip during trip testing following maint outage & restoration of criticality.Caused by unclear checkoff procedure.On-shift training held.
PECK,C.H. Rochester Gas & Electric Corp. 79/08/16 2pp

7908280725 Forwards LER 79-008/03X-1.
WHITE,L.D. Rochester Gas & Electric Corp. 79/08/21 1p

--7908280731 LER 79-008/03X-1 on 790406 during maint on boric acid flow control valve,leaks noted on valve outlet 1-inch nipple.Caused by external caustic pitting.Actions to minimize caustics & chlorides are being taken.
SPECTOR,S. Rochester Gas & Electric Corp. 79/08/21 2pp

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7908130196 Notifies that review of safeguards contingency plan involves consideration of safeguards issue,requiring payment of Class III fee.Plans should be submitted by 790823.
DIGGS,R.M. License Fee Management Branch 79/07/03 2pp

7908080476 Forwards requested fire protection info re alternate means of safe shutdown independent of control room & switchgear room sys,which could be damaged by fire.
COUNSIL,W.G. Northeast Utilities 79/07/31 33pp

7908240592 Submits chronological data re NRC policy concerning implementation of General Design Criterion 3 for fire protection.Urges maint of mod schedules set for Oct 1980.
EISENHUT,D.G. Division of Operating Reactors 79/08/09 2pp

7908210401 Forwards amend approval fee in connection w/790323 submittal of safeguards contingency plans.
COUNSIL,W.G.; FEE,W.F. North[illegible]st Utilities 79/08/15 1p

P Operating license stage documents & correspondence

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH,H. Operating Reactors Branch 2 (Pre 790625) 79/04/19 5pp

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re [illegible]chnical details of site-specific spectra project.
LEVIN,H.A. Systematic Evaluation Programs Branch (Pre 790625) 79/03/08 10pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation.W/o encl.
EISENHUT,D.G. Division of Operating Reactors 79/06/04 52pp

7908030617 Requests addl info necessary for continuing review of 770801 submittal re degraded grid voltage.Proposed Tech Specs should include trip point on second level voltage protection & description of how voltage monitors comply w/IEEE 279.
ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790625) 79/06/21 2pp

7908070456 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda,MD ofc.Second line will be used to relay radiologic & environ data during emergencies.Testing procedures encl.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp

7908060209 Summary of 790628 meeting w/BWR licensees,applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE,W.F. Standardization Branch [illegible]/07/11 26pp

7908080350 Forwards NUREG-0462, "Technic..[illegible]ept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves.W/o encl.
GRIMES,B.K. Assistant Director for Systems Engineering 79/07/16 4pp

7908090648 Forwards revised safety assessment of SEP Topic III-10.C, "Surveillance Requirements on BWR Recirculation Pump Discharge Valves."
ZIEMANN,D.L. Operating Reactors Branch 2 79/07/16 6pp

7908160057 Forwards request for addl info on SEP structural topics.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/16 3pp

7908280580 Forwards requests for addl info re sys & analysis areas required for NRC generic rept on BWRs. Info in question was discussed at 790628 meeting & responses are requested by 790817.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/17 19pp

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/18 58pp

7908070245 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908170076 Forwards Amends 63 & 54 to Licenses DPR-21 & DPR-65, respectively, & notice of issuance & availability.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/19 3pp

--7908170081 Amends 63 & 54 to Licenses DPR-21 & DPR-65, respectively, incorporating Tech Spec changes re organizational structure, retraining & replacement training program & plant operations review committee.
SIEMANN, D. L. Operating Reactors Branch 2 REID, R. W. Operating Reactors Branch 4 79/07/19 14pp

--7908170086 Notice of issuance & availability of Amends 63 & 54 to Licenses DPR-21 & DPR-65, respectively.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/19 2pp

7908170468 Forwards summary of 790628 meeting re NRC evaluation program for operating BWR plants & near-term OLs.
* Office of Nuclear Reactor Regulation 79/07/19 3pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908160446 Responds to 790621 request for addl info on degraded grid voltage. Proposed voltage trip point is high enough to permit starting of safeguards load while normal operating loads remain connected.
COUNCIL, W. G., FEE, W. F. Northeast Utilities 79/08/10 3pp

7908210589 Responds to 790611 request that CT Yankee Atomic Power Co & Northeast Nuclear Energy Co review Reg Guide 1.114, Revision 1 as part of SEP. Current operating procedures are consistent w/guidance.
COUNSIL, W. A., FEE, W. F. Northeast Nuclear Energy Co. (Northeast Utilities) 79/08/13 1p

7908300349 Notifies of receipt of Classes I & II fee payment for 790702 application for review of proposed amends to Sections 3 & 4 of ETS. Payment should have been for Classes I & III fees. Balance of payment requested.
DIGGS, R. M. License Fee Management Branch 79/08/13 1p

7908280568 Forwards response to 790716 request for info re Target Rock safety-relief valves. Long-term program to improve valve reliability per GE recommendations fully implemented at facility.
COUNSIL, W. G. Northeast Utilities 79/08/20 2pp

G. Inspection reports, IE Bulletins & correspondence

7908130046 Responds to IE Bulletin 79-11. Westinghouse Types DB-50 & DB-75 circuit breakers are not used in safety-related Class IE sys.
COUNSIL, W. G. Northeast Nuclear Energy Co. (Northeast Utilities) 79/05/29 1p

7908030196 Submits clarifying info re 790424 response to IE Bulletin 79-08. Required containment isolation does occur in parallel w/automatic initiation of safety injection sys. Reactor vessel water level in BWR continuously monitored.
COUNSIL, W. G. Northeast Utilities 79/06/15 4pp

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Prev 790625) 79/06/20 44pp

7908200062 Forwards IE Insp Repts 50-245/79-12 & 50-336/79-15 on 790507-11. No noncompliance noted.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/25 2pp

--7908200066 IE Insp Repts 50-245/79-12 & 50-336/79-15 on 790507-11. No noncompliance noted. Major areas inspected: activities related to inservice insp & IE Bulletins 79-02 & 03.
SANDERS, W. F. Region 1, Philadelphia, Office of the Director
TRIPP, L. E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/15 5pp

7908020076 Ack receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/79-02 & 50-336/79-01.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/07/06 1p

--7908020083 Responds to NRC 790321 ltr re violations noted in IE Insp Repts 50-245/79-02 & 50-336/79-01. Corrective actions withheld (ref 10CFR2.790).
COUNSIL, W. G. Northeast Nuclear Energy Co. (Northeast Utilities) 79/04/11 2pp

--7908020088 Forwards IE Insp Repts 50-245/79-02 & 50-336/79-01 on 790106-0209 & notice of violation.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/21 2pp

--7908020094 Notice of violation from insp on 790106-0209. Details withheld (ref 10CFR2.790).
* Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/16 1p

--7908020099 IE Insp Repts 50-245/79-02 & 50-336/79-01 on 790106-0209. Noncompliance noted: facility access control inadequacy. Portions withheld (ref 10CFR2.790).
MCCABE, E. C., SHEDLOSKY, J. T. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/16 22pp.

7908220613 Responds to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Generic program description & plant-specific program repts encl.
COUNSIL, W. G. Northeast Utilities 79/07/06 2pp

--7908220618 "Generic Program Description," discussing finite element model, shear-tension interaction tests & cyclic load tests.
* Northeast Utilities 79/07/06 2pp

--7908220622 "Plant-Specific Programs."
* Northeast Utilities 79/07/06 6pp

7908200253 Advises that C-E generic rept responding to IE Bulletin 78-12 adequately represents reactor pressure vessel data for facility.
COUNSIL, W. G. Northeast Utilities 79/07/12 1p

7908010504 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/17 1p

7908060393 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908030255 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908270525 Responds to IE Bulletin 79-12 by describing actions taken to reduce probability of BWR scrams. Rod withdrawal sequence modified. Adequate training provided to reactor & senior reactor operators.
COUNSIL,W G. Northeast Utilities. 79/07/23. 3pp.

7908100240 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908090310 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908280135 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908230346 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/08. 1p.

7908270552 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/10. 1p.

7908280292 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310286 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300146 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

7908310382 Requests that BWR operating plant owners group GE Rept, NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWR Reactors," submitted in 790817 ltr be included in docket.
COUNSIL,W G. Northeast Nuclear Energy Co. (Northeast Utilities). 79/08/23. 1p.

R. Periodic operating reports & related correspondence

7908210549 Forwards monthly operating rept for Jul 1979.
OPEKA,J F. Northeast Utilities. 79/08/15. 1p.

--7908210552 Monthly operating rept for Jul 1979.
YOUNG,R H. Northeast Utilities. 79/08/09. 7pp.

S. Reportable occurrences, LERs & related correspondence

7908070573 Forwards LER 79-018/01T-0.
OPEKA,J F. Northeast Utilities. 79/07/26. 1p.

--7908070579 LER 79-018/01T-0 on 790713 during chemical analysis, concentration of sodium pentaborate in standby liquid control storage tank found below min. Caused by error in analytical procedure.
YOUNG,R H. Northeast Utilities. 79/07/26. 3pp.

7908100445 Forwards LER 79-019/03L-0.
OPEKA,J F. Northeast Utilities. 79/08/06. 5pp.

--7908100452 LER 79-019/03L-0 on 790628 two feedwater sys check valves, one inboard & one outboard (1-FW-9A,10A), found leaking in excess of Tech Specs. Caused by normal deterioration of seating surface. Seal ring wear valves reworked.
PRZEKOP,P J. Northeast Utilities. 79/08/03. 1p.

7908160409 Forwards LER 79-020/03L-0.
OPEKA,J F. Northeast Utilities. 79/08/09. 1p.

--7908160413 LER 79-020/03L-0 on 790711 during routine surveillance, level switch found tripping outside allowable band. Caused by setpoint drift. All switches in initiation l[illegible] checked. Subj switch adjusted & tested satisfactorily.
YOUNG,R H. Northeast Utilities. 79/08/09. 2pp.

7908160471 Forwards LER 79-021/03L-0.
OPEKA,J F. Northeast Utilities. 79/08/10. 1p.

--7908160477 LER 79-021/03L-0 on 790712 level switch would not trip at any level signal. Caused by foreign particles binding magnetic shaft assembly portion of switch. Switch cleaned, adjusted & satisfactorily tested.
YOUNG,R H. Northeast Utilities. 79/08/10. 2pp.

7908280711 Forwards LER 79-022/03L-0.
OPEKA,J F. Northeast Utilities. 79/08/22. 1p.

--7908280724 LER 79-022/03L-0 on 790723, vent bypass valve 1-AC-12, used for venting, failed to close after venting pressure suppression chamber. Caused could not be identified. Valve operator disassembled, inspected, lubricated & bench tested.
[illegible] Northeast Utilities. 79/08/22. 2pp.

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

7908060168 Requests prompt forwarding of Class III rev for 790322 safeguards contingency plan.
DIGGS,R H. [illegible] License Rev Management Branch. 79/07/03. 2pp.

7908070598 Forwards modified physical security plan. Plan withheld (ref 10CFR2.790).
CAHILL,W J. Consolidated Ed[illegible] of New York. 79/08/01. 1p.

7908210015 Forwards security force qualification & training plan. Plan withheld (ref 10CFR2.790).
ZARAKAS,P. Consolidated Edison Co. of New York. [illegible]. 2p.

G. Adjudicatory correspondence

7908210030 Forwards vtl 790504 ltr re review of cooling tower env, Clean Air Act guidelines. Requests info re amount of particulates emitted w/o drift eliminators & division of regulatory authority.
LEWIS,E H. Branch 2, NRC. 79/06/01. 1p.

7908160111 Responds to 790323 request for assessment of reactor earthquake resistance & re-examination of computer codes used for seismic analyses nuclear plants. Re-examinations undertaken on basis found for restricting operation.
DENTON,H R. Office of Nuclear Reactor Regulation. 79/07/25. 2pp.

--7908160114 Requests assessment of resistance of reactor to earthquake & re-examination of computer codes used for seismic analyses of nuclear power plants.
DIGKINSON,I F. Citizens Committee for Protection of the Environment. 79/03/23. 1p.

7908300025 Responds to 790518 ltr re plant shutdown. Forwards 790606 memo re creation of hydrogen IE Bulletin 79-06A addressed review of operation modes & procedures re hydrogen generated during transient. W/o encl.
GAMMILL,W P. Assistant Director for Operating Reactor Projects. 79/07/30. 3pp.

7908220409 Memo submitting opinion of MC Farrar re dissenting vote concerning portions of ALAB-422 & ALAB-436. Majority will respond after revie[illegible].
BISHOP,C J. Atomic Safety and Licensing Appeal Panel. 79/08/03. 58pp.

H. General [illegible]

7908230244 Responds to 790323 ltr requesting info re assessment of reactor earthquake res[illegible]tance & re-examination of computer codes used for seismic analyses. Re-examinations found no basis for discontinuing operation of facilities.
DENTON,H R. Office of Nuclear Reactor Regulation. 79/07/25. 2pp.

J. Insurance & indemnity information

7908090375 Forwards 790731 projection for 790801-800731, demonstrating that util will have available cash flow &/or cash reserves sufficient to pay max $20 million retrospective premium.
CAHILL,W J. Consolidated Edison Co. of New York. 79/08/01. 2pp.

DOCKETED ITEMS

P Operating license stage documents & correspondence

7907190774 FOIA request for NRC Annual Rept 1978, rev ent studies by NRC of TMI, rept indicating methods to cool down TMI core & environ impact studies of Indian Point facility, Brookhaven Natl Lab & West Valley nuclear fuel reprocessing plant RADNOR Affiliation Unknown 79/09/02 1p

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines STELLO,V Division of Operating Reactors 79/05/25 3pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl. EISENHUT,D G Division of Operating Reactors 79/06/04 52pp

7908020177 Discusses review of 790416 ltr re valves proposed to be removed from inservice testing program. Lists ten valves which should be removed SCHWENCER,A Operating Reactors Branch 1 (Pre 790625) 79/06/07 2pp

7908030232 Summarizes status of five overpressure protection & three flooding reviews evaluated by LLL in response to Eisenhut 790604 memo SHEMANSKI,P Plant Systems Branch 79/06/12 2pp

--7908030256 Requests status of LLL electrical staff overpressure & flooding reviews. EISENHUT,D G Division of Operating Reactors 79/06/04 1p

7908010307 Notifies of review of util 790529 request for amend to License DPR-26 as result of mod proposed in IE Bulletin 79-06A. Mod to safety injection actuation sys logic & Tech Specs acceptable. Forwards safety evaluation. LAINAS,G Plant Systems Branch 79/06/15 2pp

--7908010311 Safety evaluation of amend to License DPR-26 re safety injection actuation sys & changes to Tech Specs. Mod acceptable. * Plant Systems Branch 79/06/15 2pp

7908070428 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl. GRIER,B H Region 1, Philadelphia, Office of the Director 79/06/22 3pp

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl. GRIMES,C I Plant Systems Branch 79/06/27 2p

7908200218 Notifies of review of 740312, 0830, 750725 & 790113 submittals re provisions for avoiding water hammer events. Provisions are acceptable pending stress analysis review of mod to feedwater lines. Forwards safety evaluation. SCHWENCER,A Operating Reactors Branch 1 79/07/06 3pp

--7908200225 Safety evaluation re water hammer in feedwater piping. Provisions for reducing potential steam generator water hammer adequate. Technical evaluation by EG&G, Inc encl. SCHWENCER,A Operating Reactors Branch 1 79/07/06 2pp

--7908200230 Technical evaluation re effectiveness of means to reduce potential for water hammer at facility. Corrective measures acceptable. * EG & G, Inc 78/12/31 16pp

7908080186 Forwards Amend 56 to License DPR-26, safety evaluation & notice of issuance & availability. SCHWENCER,A Operating Reactors Branch 1 79/07/10 2pp

--7908080191 Amend 56 to License DPR-26, deleting pressurizer level as input to safety injection & requiring safety injection on two of three low pressurizer pressure channels. SCHWENCER,A Operating Reactors Branch 1 79/07/10 9pp

--7908080637 Safety evaluation supporting Amend 56 to License DPR-26. * Office of Nuclear Reactor Regulation 79/07/10 3pp

--7908080644 Notice of issuance & availability of Amend 56 to License DPR-26. SCHWENCER,A Operating Reactors Branch 1 79/07/10 2pp

7908220302 Forwards Amends 26 & 57 to Licenses DPR-5 & DPR-26, respectively, & notice of issuance & availability. SCHWENCER,A Operating Reactors Branch 1 79/07/11 3pp

--7908220309 Amends 26 & 57 to Licenses DPR-5 & DPR-26, respectively, revising Tech Specs to consolidate all ref to thermal plume mapping. SCHWENCER,A Operating Reactors Branch 1 79/07/11 15pp

--7908220314 Notice of issuance & availability of Amends 26 & 57 to Licenses DPR-5 & DPR-26, respectively. SCHWENCER,A Operating Reactors Branch 1 79/07/11 2pp

7908220586 Ack receipt of accelerograph network layout & offers suggestions. Util response spectra & table of damping values used encl. REITER,L Geosciences Branch 79/07/17 4pp

7908070231 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode. GRIER,B H Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs." GAMMILL,W P Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908270355 Forwards request for addl info to be sent to licensee in order to complete review of 770829 submittal re Technical Assistance Contracts 10029 & 10029. Response required within 45 days. LAINAS,G Plant Systems Branch 79/07/18 3pp

7908010343 Notifies that new milk sampling location has been chosen per ETS. New site is Hilltop Hanover Farm. CAHILL,W J Consolidated Edison Co of New York 79/07/19 2pp

7908080527 Forwards 790720 application for amend to License DPR-26. Application requests amend to App B Tech Specs re requirements for radiological effluents & radiological environ monitoring. Proposed changes respond to Grimes ltr. CAHILL,W J Consolidated Edison Co of New York 79/07/20 3pp

--7908080529 Application for amend to License DPR-26, App A & B Tech Specs, consisting of page revisions re radiological effluents & environ monitoring. * Consolidated Edison Co of New York 79/07/31 142pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit. HAASS,W P Quality Assurance Branch 79/07/24 1p

7908070475 Forwards supplemental response to V Stello 790525 request for addl info re PWR feedwater lines. CAHILL,W J Consolidated Edison Co of New York 79/07/27 10pp

7908090392 Forwards application for amend to License DPR-26, consisting of changes to Tech Specs re requirements for addl fire detectors for cable spreading room Halon sys & safety evaluation. Affidavit of Svc encl. CAHILL,W J Consolidated Edison Co of New York 79/07/27 3pp

--7908090404 Application for amend to License DPR-26 to modify Tech Specs to incorporate limiting conditions for operation & surveillance requirements for addl fire detectors in cable spreading room Halon sys. Safety evaluation encl. * Consolidated Edison Co of New York 79/07/27 12pp

7908130044 Notifies that undervoltage protection sys design does not comply w/intent of NRC degraded grid voltage position as stated in 770603 ltr. Proposal must be resubmitted, addressing points 2 & 3 of 770603 ltr. SCHWENCER,A Operating Reactors Branch 1 79/07/27 3pp

7908030174 Responds to 790629 requests for info on mgt & technical resources for facility support during unusual events or accidents. Forwards description of mgt & technical resources. CAHILL,W J Consolidated Edison Co of New York 79/07/30 31pp

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants. O'REILLY,J P Standardization Branch 79/07/30 64pp

7908130570 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/01. 4pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908310478 FOIA request for meteorological data, including wind direction & velocity, precipitation, relative humidity & barometric pressure, collected for past five years by facilities.
ROACH, K. Malcolm & Purnie, Inc. 79/08/03. 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908240372 Notifies that 1980 aquatic surveillance program will be modified; river population studies of entrainable size organisms will not be conducted & mark-recapture studies will be limited to yearling & older fish in 1980.
CAHILL, W. J. Consolidated Edison Co. of New York. 79/08/20. 3pp.

7908310485 Responds to FOIA request for meteorological data collected for past five years by facilities. Info located in Table 4A of "Effluent & Waste Disposal Semi-Annual Rept" available at specified LPDR.
FELTON, J. M. Division of Rules and Records. 79/08/21. 1p.

7908280704 Forwards "Steam Generator Insp Program & Results, Jul 1979," per Amend 40 to License DPR-26, & Class III fee.
CAHILL, W. J. Consolidated Edison Co. of New York. 79/08/23. 1p.

--7908280707 "Steam Generator Insp Program & Results, Jul 1979." Photographs encl.
* Consolidated Edison Co. of New York. 79/07/23. 45pp.

9. Inspection reports, IE Bulletins & correspondence

7908080501 Responds to IE Bulletin 79-10 re util requalification training programs. Forwards operator & senior operator examination data.
CAHILL, W. J. Consolidated Edison Co. of New York. 79/05/21. 3pp.

7908080507 Forwards addl response to IE Bulletin 79-07 per NRC 790522 request. Confirmatory reanalysis data for pressurizer relief lines encl.
ZARAKAS, P. Consolidated Edison Co. of New York. 79/05/25. 5pp.

7908020092 Forwards IE Insp Rept 50-247/79-05 on 790304-31. No noncompliance noted.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/06/04. 2pp.

--7908020100 IE Insp Rept 50-247/79-05 on 790304-31. No noncompliance noted. Major areas inspected: physical protection in areas of access control, barriers, search, escort communications & compensatory measures.
REBELOWSKI, T., KEIMIG, R. R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/05/30. 9pp.

7908070778 Interim rept "Concrete Expansion Anchor Verification Program."
* Consolidated Edison Co. of New York. 79/07/31. 29PP.

7908070043 Supplements 790501 response to IE Bulletin 79-04. Velan check valves used for facility are within normal acceptance tolerances. Listing of valves encl.
CAHILL, W. J. Consolidated Edison Co. of New York. 79/06/08. 2pp.

7908070198 Responds to IE Bulletin 79-01 re environ qualification for Class 1E equipment. Forwards tables indicating scope of review & list of document ref. Info re Unit 1 will be forwarded when unit is returned to svc.
ZARAKAS, P. Consolidated Edison Co. of New York. 79/06/13. 31pp.

7908020596 Forwards supplemental response to IE Bulletin 79-06A, Revision 1. Discusses actions required by operating procedures for coping w/transients & accidents, training instructions, maint & test procedure.
ZARAKAS, P. Commonwealth Edison Co. 79/06/22. 26pp.

7908070775 Responds to IE Bulletin 79-02 & Revision 1 re pipe support base plate designs. Forwards interim rept, "Concrete Expansion Anchor Verification Program."
CAHILL, W. J. Consolidated Edison Co. of New York. 79/07/06. 4pp.

7908090671 Responds to IE Bulletin 79-11 Westinghouse Types DB-50 & DB-75 circuit breakers w/overcurrent trip devices used in safety-related sys & in spares at Unit 2, but not in Unit 1. Details encl.
CAHILL, W. J. Consolidated Edison Co. of New York. 79/07/09. 6pp.

7908170368 Forwards response to IE Bulletin 79-13 for Unit 1. Unit 2 in shutdown mode since 741031 pending company decision re installation of ECCS.
CAHILL, W. J. Consolidated Edison Co. of New York. 79/07/16. 4pp.

7908010422 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060211 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030229 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908100219 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908100330 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908090287 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908070609 Forwards update of 790718 response to IE Bulletins 79-01 & DIA Degradation of solenoid valve internals would not cause safeguard component to fail in unsafe mode.
CAHILL, W. J. Consolidated Edison Co. of New York. 79/08/01. 4pp.

7908280060 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908230295 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/08. 1p.

7908270540 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/10. 1p.

7908280255 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310259 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300113 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

7908290584 Forwards "Steam Generator Operating History Questionnaire for Steam Generator Inservice Insp from Mar 1975-Mar 1978" in response to 771209 & 780210 ltrs.
CAHILL, W. J. Consolidated Edison Co. of New York. 79/08/23. 1p.

--7908290592 "Steam Generator Operating History Questionnaire For Steam Generator Inservice Insp From Mar 1975-Mar 1978."
* Consolidated Edison Co. of New York. 79/08/31. 51pp.

R Periodic operating reports & related correspondence

7908160466 "Efficiency of 1.0 m2 Epibentic Sled For Collecting Young-of-the-Year Stripped Bass,White Perch & Atlantic Tomcod in Hudson River Estuary,1978." Affidavit of JR Jannarone encl.
* Texas Instruments, Inc. 79/06/30. 19pp.

7908170399 Forwards species code list & [illegible]e circulating water temp, gross electrical output & river water [illegible]harge for Jul 1979 for Permit NY0004472.
MONTI,W.A. Consolidated Edison Co. of New York. 79/08/10. 17pp.

7908200342 Forwards monthly operating rept for Jul 1979.
PARAKAS,P. Consolidated Edison Co. of New York. 79/08/13. 1p.

--7908200345 Monthly operating rept for Jul 1979.
KAWULA,L. Consolidated Edison Co. of New York. 79/08/03. 8pp.

7908220391 Forwards tabulation of daily record of fish collection for Jul 1979.
ZARAKAS,P. Consolidated Edison Co. of New York. 79/08/15. 4pp.

S Reportable occurrences, LERs & related correspondence

7908070353 RO 79-018/01 on 790626 advised by Westinghouse that for high energy line breaks inside containment, potential water level bias could result in delayed protection signals.Evaluation under way.
MONTI,W.A. Consolidated Edison Co. of New York. 79/06/28. 1p.

7908140826 Forwards LER 79-020/03L-0.
CAHILL,W.J. Consolidated Edison Co. of New York. 79/08/03. 1p.

--7908140831 LER 79-020/03L-0 on 790704 during refueling outage,leak was identified at socket weld connection of vent S-7 to discharge header of pump 22.Cause is believed to be vibration-induced stress.Leak repaired.
MAKEPEACE,J.M. Consolidated Edison Co. of New York. 79/08/03. 1p.

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

7908130159 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee.Plans should be submitted by 790823.
DIGGS,R.M. License Fee Management Branch. 79/07/03. 2pp.

7908160367 Forwards request for addl info re contingency plans.Encl withheld (ref 10CFR2.790).
ZIEMANN,D.L. Operating Reactors Branch 2. 79/07/19. 2pp.

7908010300 Forwards info to suppl fire protection safety evaluation rept.
JANECEK,R.F. Commonwealth Edison Co. 79/07/20. 6pp.

7908200216 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED,C. Commonwealth Edison Co. 79/08/16. 1p.

G Adjudicatory correspondence

7908280266 Responds to 790514 ltr opposing authorization for increase in spent fuel storage capacity.No application from util filed.Util request to allow storage of spent fuel in spent fuel pools at either site currently under review.
EISENHUT,D.G. Division of Operating Reactors. 79/07/31. 1p.

7908200010 Responds to 790524 ltr opposing transport of spent fuel between plants.Explains purpose of application.Risks are well known & very low.Public hearing will be held soon.
IPPOLITO,T.A. Operating Reactors Branch 3. 79/08/03. 1p.

7908200035 Responds to 790510 ltr opposing transportation of spent fuel.Public hearing will be held on shipment in Fall 1979.
IPPOLITO,T.A. Operating Reactors Branch 3. 79/08/03. 1p.

7908200039 Responds to 790507 postcard expressing opposition to transportation of spent fuel.Public hearing on proposed shipment will be held Fall 1979.
IPPOLITO,T.A. Operating Reactors Branch 3. 79/08/03. 1p.

7908290108 Responds to 790502 & 12 ltrs re hearing on spent fuel transfer.Hearing will be held no earlier than Sept 1979.
IPPOLITO,T.A. Operating Reactors Branch 3. 79/08/03. 1p.

7908220204 Forwards ASLB 790730 notice re reconstitution of Board re spent fuel pool mod proceeding.
* Operating Reactors Branch 2. 79/08/07. 2pp.

--7908220208 Notice of reconstitution of Board.JF Wolf replaces E Luton as ASLB chairman.
LAZO,R.M. Atomic Safety and Licensing Board Panel. 79/07/30. 3pp.

H General correspondence

7908210445 Responds to 790522 ltr opposing moving of spent fuels between stations.Discusses concerns expressed re proposed high density fuel storage.
IPPOLITO,T.A. Operating Reactors Branch 3. 79/08/03. 1p.

7908210453 Responds to 790430 ltr & recent telcons.Notice will be made re time & place of hearings on spent fuel transfer between stations.Discusses rules re shipment of spent fuel.
IPPOLITO,T.A. Operating Reactors Branch 3. 79/08/03. 2pp.

P Operating license stage documents & correspondence

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation.W/o encl.
EISENHUT,D.G. Division of Operating Reactors. 79/06/04. 52pp.

7908070652 Notifies of intent to install second communications sys. linking facilities w/NRC regional ofc & main Bethesda,MD ofc.Second link will be used to relay radiologic & environ data during emergencies.Testing procedures encl.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/06/22. 3pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program.Proposed agenda encl.
GRIMES,C.I. Plant Systems Branch. 79/06/27. 2p.

7908140280 Notifies that fees quoted in 790416 ltr will not be required.
MILLER,W.O. Office of Administration. 79/06/27. 1p.

7908130310 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill if drill scenario requires NRC initial notification.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/07/09. 1p.

7908080719 Confirms that meeting at util corporate office has been rescheduled for 790719 at 3 PM.Location,purpose & attendees discussed in NRC 790612 ltr.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/07/10. 1p.

7908060209 Summary of 790628 meeting w/BWR licensees,applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE,W.F. Standardization Branch. 79/07/11. 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves.W/o encl.
GRIMES,B.K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908160050 Forwards request for addl info to suppl 790530 response re spent fuel pool mod.
ZIEMANN,D.L. Operating Reactors Branch 2. 79/07/16. 3pp.

7908100290 Forwards NUREG-0472,Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL,W.P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070332 Requests cooperation in data-gathering activities to provide NRC Commissioners,public & media w/up-to-date operating status of power reactors.Info requests will not be made while plant is in shutdown mode.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/07/19. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events Requests addl five copies of response for each addl unit
HAASS,W.P. Quality Assurance Branch 79/07/24 1p

7908030302 Submits revised schedule for mod to diesel generator annunciator sys schedule Updates schedule in util 790202 ltr
JANECEK,R.F. Commonwealth Edison Co. 79/07/27 2pp

7908020460 Submits schedule for addl response to NRC issues re containment purging during normal plant operation
REED,C. Commonwealth Edison Co. 79/07/30 2pp

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete
LEE,B. Commonwealth Edison Co. 79/07/30 2pp

7908200287 Ack receipt of 790709 ltr requesting info re operation of isolation (emergency) condensers Submits station procedures defining proper methods of initiating makeup to condenser shell
JANECEK,R.F. Commonwealth Edison Co. 79/08/03 2pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations,guidance documents & repts re emergency planning
EISENHUT,D.G. Division of Operating Reactors 79/08/03 53pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power
GAMMILL,W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908200380 Forwards info requested in NRC 790629 & 0724 ltrs re capabilities o technical resources available to handle unusual events
JANECEK,R.F. Commonwealth Edison Co. 79/08/13 1100pp

7908280575 Forwards response to DL Ziemann 790716 ltr to C Reed requesting addl info re fuel pool mods
JANECEK,R.F. Commonwealth Edison Co. 79/08/17 8pp

7908230420 Informs that GE rept NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs" was submitted to NRC by TD Keenan 790817 ltr to D Ross Remainder of info follows in 791116 rept
JANECEK,R.F. Commonwealth Edison Co. 79/08/20 1p

9. Inspection reports, IE Bulletins & correspondence

7908020548 Forwards IE Insp Repts 50-010/79-06,50-237/79-07 & 50-249/79-06 on 790326-28 notice of violation & notice of deviation
HEISHMAN,R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/10 2pp

--7908020555 Notice of violation from insp on 790326-28
* Region 3, Chicago, Office of the Director 79/05/09 1p

--7908020566 Notice of deviation from insp on 790326-28
* Region 3, Chicago, Office of the Director 79/05/09 1p

--7908020572 IE Insp Repts 50-010/79-06,50-237/79-07 & 50-249/79-06 on 790326-28 Noncompliance noted failure to conduct five brigade training sessions on quarterly basis & failure to develop procedure for control of combustibles
RIDEN,M.D., LITTLE,W.S. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/09 5pp

7908010223 Forwards IE Insp Repts 50-010/79-12,50-237/79-15 & 50-249/79-13 on 790501-0601 & notice of violation
HEISHMAN,R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/15 2pp

--7908010227 Notice of violation from insp on 790501-0601
* Region 3, Chicago, Office of the Director 79/06/13 1p

--7908010231 IE Insp Repts 50-010/79-12,50-237/79-15 & 50-249/79-13 on 790501-0601 Noncompliance noted re [illegible] started using battery not connected to bus
BARKER,S.L., SPESSARD,R.L. Regio[illegible] Chicago, Office of the Director 79/06/13 11pp

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08 Requests attendance at 790628 meeting in Bethesda,MD re info needed by NRC to complete review
IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625) 79/06/20 44pp

7908080523 Responds to IE Bulletin 79-11 re Westinghouse DB-50 & DB-75 circuit breakers used in safety-related sys
REED,C. Commonwealth Edison Co. 79/07/02 1p

7908060111 Responds to IE Bulletin 79-02 Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin Bolt torque audit in progress
REED,C. Commonwealth Edison Co. 79/07/05 9pp

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc 79/05/31 24pp

7908080703 Submits addl response to IE Bulletins 78-12 & 12B Requested vessel evaluation completed & certification by manufacturer & supplier submitted to NRC
REED,C. Commonwealth Edison Co. 79/07/09 2pp

7908150349 Supplements response to IE Bulletin 79-11 Westinghouse DB-50 & DB-75 circuit breakers are neither used in safety-related sys nor stored as spares at facilities
REED,C. Commonwealth Edison Co. 79/07/12 2pp

7908080306 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/20 4pp

7908150286 Ack receipt of 790703 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/79-13 & 50-249/79-11
HEISHMAN,R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/07/23 2pp

--7908150299 Responds to NRC 790613 ltr re violations noted in IE Insp Repts 50-237/79-13 & 50-249/79-11 Corrective actions valve & breaker switch alignment checklists are being reviewed & corrected
REED,C. Commonwealth Edison Co. 79/07/03 3pp

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908240513 Responds to IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." Procedures involving reactor criticality, control rod withdrawal sequences & operator training program were modified in 1977
REED,C. Commonwealth Edison Co. 79/07/30 9pp

7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys Forwards lists of design documents which were sources of input info for seismic analysis of facilities W/o encl
REED,C. Commonwealth Edison Co. 79/08/01 2pp

7908080530 Forwards addl info re responses to IE Bulletin 79-08, per 790720 request
REED,C. Commonwealth Edison Co. 79/08/03 6pp

7908170019 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/08/08 1p

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/08/15 1p

R. Periodic operating reports & related correspondence

7908300459 Forwards semiannual "Rept of Radioactive Effluent Discharges & Solid Radwaste" for Jan-June 1979
STEPHENSON,B.B. Commonwealth Edison Co. 79/08/14 1p

DOCKETED ITEMS

--7908300466 "Rept of Radioactive Effluent Discharges & Solid Radwaste" for Jan-June 1979.
* Commonwealth Edison Co. 79/06/30. 15pp.

S Reportable occurrences, LERs & related correspondence

7908080404 Forwards LER 79-017/03L-0.
STEPHENSON, B B. Commonwealth Edison Co. 79/08/01. 1p.

--7908080405 LER 79-017/03L-0 on 790713 channel A fuel pool area radiation monitor failed due to loose connector. Caused by repetitive handling of cable corrector, causing wires to loosen inside. Corrector replaced.
JANSEN, T. Commonwealth Edison Co. 79/08/01. 1p.

7908080500 Forwards LER 79-018/03L-0.
STEPHENSON, B B. Commonwealth Edison Co. 79/08/03. 1p.

--7908080508 LER 79-018/03L-0 on 790706 primary containment vacuum relief & isolation valve AO-3-1601-20B found open & inoperable. Caused by electricians incorrectly identifying 1601-20B valve as 1601-56. Equipment tags to be improved.
MEADOWS, R. Commonwealth Edison Co. 79/08/03. 3pp.

7908140615 Forwards LER 79-015/03L-0.
STEPHENSON, B B. Commonwealth Edison Co. 79/08/06. 1p.

--7908140629 LER 79-015/03L-0 on 790719 source-range monitor 21 initiated rod block during source range monitor calibr at rate unconservative to Tech Spec limit. Caused by electronics drift of high alarm setpoint potentiometer.
LINDBERG, C. Commonwealth Edison Co. 79/08/07. 1p.

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

7908130185 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R M. License Fee Management Branch. 79/07/03. 2pp.

7908220005 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
UHRIG, R E. Florida Power & Light Co. 79/08/17. 1p.

7908280027 Forwards cover sheet to Revision 0 of security training & qualification plan. Plan withheld (ref 10CFR2.790). Cover sheet not encl.
UHRIG, R E. Florida Power & Light Co. 79/08/22. 1p.

G Adjudicatory correspondence

7908290079 Notification of appearance in proceeding on behalf of MP Oncavage. Certificate of Svc encl.
LUMER, J V. Lumer, J V. LUMER, J V. Florida Power & Light Co. 79/06/20. 3pp.

7908150001 Forwards EIA for facility.
GOLDBERG, S C. Branch 2. 79/06/29. 1p.

--7908150002 EIA for facility.
* Office of Nuclear Reactor Regulation. 79/06/29. 34pp.

I Financial information

7908070375 Forwards Annual Financial Rept 1978, consolidated financial statements, June 1979 (unaudited) & cash flow projections.
UHRIG, R E. Florida Power & Light Co. 79/07/31. 1p.

P Operating license stage documents & correspondence

7908080633 Forwards documents on file re seismic pipe stresses at Robinson facility. Forwards info re resolution of problem at Turkey Point.
LEWIS, S H. Branch 2. 79/04/25. 24pp.

--7908080656 Recommends IE Bulletin 79-07 & IE Info Notice 79-06, re seismic stress analysis of safety-related piping, be provided to Boards listed. Bulletin & info notice encl.
STELLO, V. Division of Operating Reactors. 79/04/19. 2pp.

7908010630 Forwards safety evaluation re steam generator repair program.
GOLDBERG, S C. Branch 2. 79/05/15. 1p.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D G. Division of Operating Reactors. 79/06/04. 52pp.

7907260035 Requests registration as user of Model NLI-1/2.
UHRIG, R E. Florida Power & Light Co. 79/06/11. 1p.

7908030232 Summarizes status of five overpressure protection & three flooding reviews evaluated by LLL in response to Eisenhut 790604 memo.
SHEMANSKI, P. Plant Systems Branch. 79/06/12. 2pp.

--7908030256 Requests status of LLL electrical staff overpressure & flooding reviews.
EISENHUT, D G. Division of Operating Reactors. 79/06/04. 1p.

7908090266 Forwards EIA & FR notice of availability re steam generator repair program, per 770920 submittal.
SCHWENCER, A. Operating Reactors Branch 1. 79/06/29. 2pp.

--7908090271 Notice of issuance & availability of EIA.
SCHWENCER, A. Operating Reactors Branch 1. 79/06/29. 2pp.

--7908090279 EIA supporting proposed steam generator repair action & amend to Licenses DPR-31 & DPR-41.
* Office of Nuclear Reactor Regulation. 79/06/29. 34pp.

7908030356 Finds unacceptable proposed cycling test for check valves submitted on 790823. Requests licensee response within 30 days to encl NRC position re cycling test for check valves.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/07/05. 3pp.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908160296 Forwards request for addl info to complete review of licensee 770721 submittal re graded grid voltage.
LAINAS, G. Plant Systems Branch. 79/07/18. 3pp.

7908070315 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908210291 Determines that deviations for IE Insp Repts 50-250/79-16, noted w/applications for renewal of two NRC operators licenses, did not occur as stated. Min requalification program met.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/23. 2pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W P. Quality Assurance Branch. 79/07/24. 1p.

7908210169 Forwards request for addl info to suppl 770721 response re low voltage protection sys.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/07/26. 3pp.

7908030330 Submits Revision 3 to App C to QA topical rept 1-76A, providing alternative to requirement for insp of rigging & handling equipment.
UHRIG, R E. Florida Power & Light Co. 79/07/30. 2pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J P. Standardization Branch. 79/07/30. 64pp.

7908030171 Responds to 790525 request for info re fabrication, insp & operating history of feedwater lines.
UHRIG, R E. Florida Power & Light Co. 79/07/31. 7pp.

7908130576 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A Operating Reactors Branch 1 79/08/01 4pp.

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees, for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G Plant Systems Branch 79/08/02 7pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D G Division of Operating Reactors 79/08/03 53pp.

7908140458 Requests amend to Licenses DPR-31 & DPR-41 to allow 10 effective month's of operation prior to performance of next steam generator insp.
UHRIG, R E Florida Power & Light Co 79/08/07 3pp.

7908140435 Submits proposed amend to Licenses DPR-31 & DPR-41 to increase min low-low steam generator water level reactor trip setpoint to 15% of narrow range instrument scale. Safety evaluation encl.
UHRIG, R E Florida Power & Light Co 79/08/09 4pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908160408 Ack 790713 telcon & 790705 ltr re pump & valve test program. All outstanding issues have been resolved.
SCHWENCER, A Florida Power & Light Co 79/08/10 1p.

7908160362 Discusses full load test of emergency diesel generators. Forwards graphs showing parameters monitored at various levels.
UHRIG, R E Florida Power & Light Co 79/08/13 6pp.

7908210265 Responds to 790625 ltr re QA reg guides & ANSI stds. Topical QA rept FPLTQAR 1-76A proposed Revision 3 satisfies requirements of 10CFR50 App B. Util will comply w/reg guides.
UHRIG, R E Florida Power & Light Co 79/08/13 2pp.

7908240635 Forwards request for addl info re containment purge sys.
LAINAS, G Plant Systems Branch 79/08/14 3pp.

G. Inspection reports, IE Bulletins & correspondence

7908030576 Forwards IE Insp Repts 50-250/79-14 & 50-251/79-14 on 790508-11. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/30 1p.

--7908030584 IE Insp Repts 50-250/79-14 & 50-251/79-14 on 790508-11. No noncompliance noted. Major areas inspected: steam generator replacement for facilities.
WILCOX, J D ; HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 3pp.

7908210270 Forwards IE Insp Repts 50-250/79-17 & 50-251/79-17 on 790523-25. No noncompliance noted.
MURPHY, C E NRC Regional Offices 79/06/11 2pp.

--7908210279 IE Insp Repts 50-250/79-17 & 50-251/79-17 on 790523-25. No noncompliance noted. Major areas inspected: concrete expansion anchor testing & repair program.
MADENDS, L ; VALLISH, E ; HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/07 3pp.

7908160460 Forwards IE Insp Repts 50-250/79-15 & 50-251/79-15 on 790515-17. No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/15 2pp.

--7908160465 IE Insp Repts 50-250/79-15 & 50-251/79-15 on 790515-17. No noncompliance noted. Major areas inspected: restoration of plant sys following refueling & safety & operating procedures.
VERDERY, E H Region 2, Atlanta, Office of the Director.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/15 7pp.

7908020354 Updates earlier response to IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
UHRIG, R E Florida Power & Light Co 79/06/18 4pp.

7908140729 Forwards supplementary response to IE Bulletin 79-06A re operating procedures for transients & accidents.
UHRIG, R E Florida Power & Light Co 79/06/25 4pp.

7908100117 Advises that B&W rept "Records Investigation Rept re Off-Chemistry Welds in Matl Surveillance Specimens & Response to IE Bulletins 78-12 & 78-12A" & util 771021 ltr adequately represent facility reacctor vessels data.
UHRIG, R E Florida Power & Light Co 79/06/29 1p.

7908160175 Summary of 790312-16 & 19-21 insp re participation of util in QA program.
SPRAUL, J G Quality Assurance Branch 79/07/02 1p.

--7908160181 Forwards IE Insp Rept 50-250/79-11 & 50-251/79-11 on 790312-16 & 19-21 & notice of violation.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 2pp.

--7908160185 Notice of violation from insp on 790312-16 & 19-21.
* Region 2, Atlanta, Office of the Director 79/06/20 8pp.

--7908160194 IE Insp Rept 50-250/79-11 & 50-251/79-11 on 790312-16 & 19-21. Noncompliance noted: failure to follow QA program procedures; failure to perform required Tech Spec tests & failure to provide safety evaluation bases.
ASHENDEN, M C ; BROWNLEE, V L ; KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/20 33pp.

7908090238 Responds to IE Bulletin 79-01 re environ qualification of Class IE equipment. Forwards detailed test documentation package. Solenoid valves, limit switches & magnetrol level switches will be replaced.
UHRIG, R E Florida Power & Light Co 79/07/03 54pp.

7908240107 Forwards IE Insp Repts 50-250/79-18 & 50-251/79-18 on 791610-14. No noncompliance noted.
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/07/03 1p.

--7908240110 IE Insp Repts 50-250/79-18 & 50-251/79-18 on 790610-14. No noncompliance noted. Major areas inspected: security plan, security program audits, lighting & access control. Six pages of insp repts withheld (ref 10CFR2.790).
MOORE, D E ; TOBIN, W J Region 2, Atlanta, Office of the Director 79/07/03 1p.

7908010029 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 2pp.

7908090541 Responds to IE Bulletin 79-11. Twelve DB-50 overcurrent trip devices w/dashpots are in use in nonsafety-related sys. DB-50 overcurrent trip devices w/o dashpots are used for reactor trip & bypass functions.
OHRIG, R E Florida Power & Light Co 79/07/09 1p.

7908310032 Forwards final rept responding to IE Bulletins 79-02 & 02, Revision 1, re pipe support base plate designs using concrete expansion anchor bolts. Table encl w/results of insp & testing, nonconformances & deficiencies.
UHRIG, R E Florida Power & Light Co 79/07/09 15pp.

7908270281 Submits correction to page 2 of IE Insp Repts 50-250/79-21 50-251/79-21, transmitted per 790625 ltr.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/10 3pp.

7908030132 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/13 2pp.

7908010412 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/17 2pp.

7908160458 Forwards response to Item 5 of IE Bulletin 79-13 re action required for feedwater sys.
UHRIG, R E Florida Power & Light Co 79/07/17 2pp.

7908030009 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/18 2pp.

DOCKETED ITEMS

7908080043 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/18 2pp.

7908130112 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/19 2pp.

7908210119 Responds to IE Bulletin 79-13. No improper welds were discovered between steam generators & first piping support or snubber on each feedwater line.
UHRIG, R. E. Florida Power & Light Co. 79/07/23 2pp.

7908060518 Forwards IE Bulletin 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/26 1p.

7908070754 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/26 2pp.

7908080715 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/26 2pp.

7908160232 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/27 2pp.

7908200030 Ack receipt of 790712 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-11 & 50-251/79-11.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/08/01 1p.

--7908200034 Responds to NRC 790620 ltr re violations noted in IE Insp Repts 50-250/79-11 & 50-251/79-11. Corrective actions: QA activity audits revised & strengthened.
UHRIG, R. E. Florida Power & Light Co. 79/07/12 22pp.

7908170049 Forwards response to IE Bulletin 79-14 re seismic analysis of as-built safety-related piping sys. Requests NRC concurrence for performance of Item B insps during next extended outage of each unit.
UHRIG, R. E. Florida Power & Light Co. 79/08/02 23pp.

7908160146 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/08/07 2pp.

7908170012 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/08/08 2pp.

7908290146 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/08/10 2pp.

7908240467 Notifies that final submittal of inservice insp program & pump & valve test program will take place on 790831 & 0914, respectively.
UHRIG, R. E. Florida Power & Light Co. 79/08/14 1p.

S. Reportable occurrences, LERs & related correspondence

7908140616 Forwards LER 79-023/03L-0.
SCHMIDT, A. D. Florida Power & Light Co. 79/07/31 1p.

--7908140625 LER 79-023/03L-0 on 790701 during power operation, 3B charging pump experienced package failure & excessive seal leakage. Caused by failure of primary & secondary packing. Packing was replaced & pump tested.
SCHOPPMAN, M. A. Florida Power & Light Co. 79/07/31 1p.

7908200279 Forwards update to LER 79-002/03X-1.
SCHMIDT, A. D. Florida Power & Light Co. 79/08/03 1p.

--7908200282 Update to LER 79-002/03X-1 on 790226 during refueling shutdown, crack found in weld on drain line in B accumulator discharge piping. Caused by stress due to line vibration. Elbows & welds replaced.
SCHOPPMAN, M. A. Florida Power & Light Co. 79/08/03 2pp.

7908300675 Forwards LER 79-010/03X-1.
SCHMIDT, A. D. Florida Power & Light Co. 79/08/06 1p.

--7908300681 LER 79-010/03X-1 on 790319, excessive leakage noted at inner personnel airlock door/bulkhead. Caused by packing leak along operating shaft at inner bulkhead. Local leak test completed successfully.
SCHOPPMAN, M. A. Florida Power & Light Co. 79/08/06 2pp.

7908290424 Forwards LER 78-017/03X-1.
SCHMIDT, A. D. Florida Power & Light Co. 79/08/10 1p.

--7908290429 LER 78-017/03X-1 on 781218 during normal operation, efforts were made to determine source of intermittent radioactive gas leak. Caused by possible deformation of small section of tank shell. Defect will be repaired.
SCHOPPMAN, M. A. Florida Power & Light Co. 79/08/10 2pp.

U. Congressional/Executive Correspondence

7908140470 Forwards 790622 ltr & supplemental submittal of petitioner MP Oncavage for review & comment.
STONE, R. Senate 79/07/05 3pp.

--7908140488 Suppl submission of MP Oncavage requesting intervenor status in hearing re steam generator repair program.
ROGOW, B. S. Rogow, B. 79/06/22 9pp.

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F. Security, medical, emergency & fire protection plans

7908130185 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp.

7908220005 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
UHRIG, R. E. Florida Power & Light Co. 79/08/17 1p.

7908280027 Forwards cover sheet to Revision 0 of security training & qualification plan. Plan withheld (ref 10CFR2.790). Cover sheet not encl.
UHRIG, R. E. Florida Power & Light Co. 79/08/22 1p.

G. Adjudicatory correspondence

7908290079 Notification of appearance in proceeding on behalf of MP Oncavage. Certificate of Svc encl.
LUMER, J. V. Lumer, J. V. LUMER, J. V. Florida Power & Light Co.
79/06/20 3pp.

7908150001 Forwards EIA for facility.
GOLDBERG, S. C. Branch 2 79/06/29 1p.

--7908150002 EIA for facility.
* Office of Nuclear Reactor Regulation 79/06/29 34pp.

I. Financial information

7908070375 Forwards Annual Financial Rept 1978, consolidated financial statements, June 1979 (unaudited) & cash flow projections.
UHRIG, R. E. Florida Power & Light Co. 79/07/31 1p.

P. Operating license stage documents & correspondence

7908080633 Forwards documents on file re seismic pipe stresses at Robinson facility. Forwards info re resolution of problem at Turkey Point.
LEWIS, S. H. Branch 2 79/04/25 24pp.

--7908080656 Recommends IE Bulletin 79-07 & IE Info Notice 79-06, re seismic stress analysis of safety-related piping, be provided to Boards listed. Bulletin & info notice encl.
STELLO, V. Division of Operating Reactors 79/04/19 2pp.

7908010630 Forwards safety evaluation re steam generator repair program.
GOLDBERG, S. C. Branch 2. 79/05/15. 1p.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908030232 Summarizes status of five overpressure protection & three flooding reviews evaluated by LLL in response to Eisenhut 790604 memo.
SHEMANSKI, P. Plant Systems Branch. 79/06/12. 2pp.

--7908030256 Requests status of LLL electrical staff overpressure & flooding reviews.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 1p.

7908090266 Forwards EIA & FR notice of availability re steam generator repair program per 770920 submittal.
SCHWENCER, A. Operating Reactors Branch 1. 79/06/29. 2pp.

--7908090271 Notice of issuance & availability of EIA.
SCHWENCER, A. Operating Reactors Branch 1. 79/06/29. 2pp.

--7908090279 EIA supporting proposed steam generator repair action & amend to Licenses DPR-31 & DPR-41.
* Office of Nuclear Reactor Regulation. 79/06/29. 34pp.

7908030356 Finds unacceptable proposed cycling test for check valves submitted on 790823. Requests licensee response within 30 days to encl NRC position re cycling test for check valves.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/07/05. 3pp.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908160296 Forwards request for addl info to complete review of licensee 770721 submittal re graded grid voltage.
LAINAS, G. Plant Systems Branch. 79/07/18. 3pp.

7908070315 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908210291 Determines that deviations for IE Insp Repts 50-250/79-16, noted w/applications for renewal of two NRC operators licenses did not occur as stated. Min requalification program met.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/31. 2pp.

7908090555 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908210167 Forwards request for addl info to suppl 770721 response re low voltage protection sys.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/07/26. 3pp.

7908030330 Submits Revision 3 to App C to GA topical rept 1-76A, providing alternative to requirement for insp of rigging & handling equipment.
UHRIG, R. E. Florida Power & Light Co. 79/07/30. 2pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch. 79/07/30. 64pp.

7908030171 Responds to 790525 request for info re fabrication, insp & operating history of feedwater lines.
UHRIG, R. E. Florida Power & Light Co. 79/07/31. 7pp.

7908130576 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/01. 4pp.

7908\290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch. 79/08/02. 7pp.

7908140372 Forwards graph showing max predicted Fq for remainder of Cycle 6. No augmented surveillance is required per Tech Specs.
UHRIG, R. E. Florida Power & Light Co. 79/08/03. 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908140458 Requests amend to Licenses DPR-31 & DPR-41 to allow 10 effective months of operation prior to performance of next steam generator insp.
UHRIG, R. E. Florida Power & Light Co. 79/08/07. 3pp.

7908140435 Submits proposed amend to Licenses DPR-31 & DPR-41 to increase min low-low steam generator water level reactor trip setpoint to 15% of narrow range instrument scale. Safety evaluation encl.
UHRIG, R. E. Florida Power & Light Co. 79/08/09. 4pp.

7908230155 Requests ut ls provide description of methods to verify that offsite power sys & unsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908160408 Ack 790713 telcon & 790705 ltr re pump & valve test program. All outstanding issues have been resolved.
SCHWENCER, A. Florida Power & Light Co. 79/08/10. 1p.

7908170352 Forwards proposed changes to pump & valve test program.
UHRIG, R. E. Florida Power & Light Co. 79/08/10. 44pp.

7908160362 Discusses full load test of emergency diesel generators. Forwards graphs showing parameters monitored at various levels.
UHRIG, R. E. Florida Power & Light Co. 79/08/13. 6pp.

7908210265 Responds to 790625 ltr re GA reg guides & ANSI stds. Topical GA rept FPLTQAR 1-76A, proposed Revision 3, satisfies requirements of 10CFR50 App B. Util will comply w/reg guides.
UHRIG, R. E. Florida Power & Light Co. 79/08/13. 2pp.

7908240635 Forwards request for addl info re containment purge sys.
LAINAS, G. Plant Systems Branch. 79/08/14. 3pp.

G. Inspection reports, IE Bulletins & correspondence

7908030576 Forwards IE Insp Repts 50-250/79-14 & 50-251/79-14 on 790508-11. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/30. 1p.

--7908030584 IE Insp Repts 50-250/79-14 & 50-251/79-14 on 790508-11. No noncompliance noted. Major areas inspected: steam generator replacement for facilities.
WILCOX, J. D.; HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/24. 3pp.

7908210270 Forwards IE Insp Repts 50-250/79-17 & 50-251/79-17 on 790523-25. No noncompliance noted.
MURPHY, C. E. NRC Regional Offices. 79/06/11. 2pp.

--7908210279 IE Insp Repts 50-250/79-17 & 50-251/79-17 on 790523-25. No noncompliance noted. Major areas inspected: concrete expansion anchor testing & repair program.
MADENOS, L.; VALLISH, E.; HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/07. 3pp.

7908160460 Forwards IE Insp Repts 50-250/79-15 & 50-251/79-15 on 790515-17. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/15. 2pp.

DOCKETED ITEMS

--7908160465 IE Insp Repts 50-250/79-15 & 50-251/79-15 on 790515-17. No noncompliance noted. Major areas inspected: restoration of plant sys following refueling & safety & operating procedures.
VERDERY, E. H. Region 1, Atlanta, Office of the Director.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/15. 7pp.

7908020354 Updates earlier response to IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
UHRIG, R. E. Florida Power & Light Co. 79/06/18. 4pp.

7908140729 Forwards supplementary response to IE Bulletin 79-06A re operating procedures for transients & accidents.
UHRIG, R. E. Florida Power & Light Co. 79/06/25. 4pp.

7908100117 Advises that B&W rept "Records Investigation Rept re Off-Chemistry Welds in Matl Surveillance Specimens & Response to IE Bulletins 78-12 & 78-12A" & util 771021 ltr adequately represent facility reactor vessels data.
UHRIG, R. E. Florida Power & Light Co. 79/06/29. 1p.

7908160175 Summary of 790312-16 & 19-21 insp re participation of util in QA program.
SPRAUL, J. J. Quality Assurance Branch. 79/07/02. 1p.

--7908160181 Forwards IE Insp Rept 50-250/79-11 & 50-251/79-11 on 790312-16 & 19-21 & notice of violation.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/20. 2pp.

--7908160185 Notice of violation from insp on 790312-16 & 19-21.
* Region 2, Atlanta, Office of the Director. 79/06/20. 8pp.

--7908 60194 IE Insp Rept 50-250/79-11 & 50-251/79-11 on 790312-16 & 19-21. Noncompliance noted: failure to follow QA program procedures; failure to perform required Tech Spec tests & failure to provide safety evaluation bases.
ASHENDEN, M. C.; BROWNLEE, V. L.; KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20. 33pp.

7908090238 Responds to IE Bulletin 79-01 re environ qualification of Class 1E equipment. Forwards detailed test documentation package. Solenoid valves, limit switches & magnetrol level switches will be replaced.
UHRIG, R. E. Florida Power & Light Co. 79/07/03. 54pp.

7908240107 Forwards IE Insp Repts 50-250/79-18 & 50-251/79-18 on 791610-14. No noncompliance noted.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/07/03. 1p.

--7908240110 IE Insp Repts 50-250/79-18 & 50-251/79-18 on 790610-14. No noncompliance noted. Major areas inspected: security plan, security program audits, lighting & access control. Six pages of insp rept withheld (ref 10CFR2.790).
MOORE, D. E.; TOBIN, W. J. Region 2, Atlanta, Office of the Director. 79/07/03. 1p.

7908010029 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908090541 Responds to IE Bulletin 79-11. Twelve DB-50 overcurrent trip devices w/dashpots are in use in nonsafety-related sys. DB-50 overcurrent trip devices w/o dashpots are used for reactor trip & bypass functions.
UHRIG, R. E. Florida Power & Light Co. 79/07/09. 1p.

7908310032 Forwards final rept responding to IE Bulletins 79-02 & 02, Revision 1, re pipe support base plate designs using concrete expansion anchor bolts. Table encl w/results of insp & testing, nonconformances & deficiencies.
UHRIG, R. E. Florida Power & Light Co. 79/07/09. 15pp.

7908270281 Submits correction to page 2 of IE Insp Repts 50-250/79-21 & 50-251/79-21, transmitted per 790625 ltr.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/10. 3pp.

7908030132 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010412 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908160458 Forwards response to Item 5 of IE Bulletin 79-13 re action required for feedwater sys.
UHRIG, R. E. Florida Power & Light Co. 79/07/17. 2pp.

7908030009 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080043 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130112 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908210119 Responds to IE Bulletin 79-13. No improper welds were discovered between steam generators & first piping support or snubber on each feedwater line.
UHRIG, R. E. Florida Power & Light Co. 79/07/23. 2pp.

7908060518 Forwards IE Bulletin 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 1p.

7908070754 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908080715 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160232 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908200030 Ack receipt of 790712 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-11 & 50-251/79-11.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/08/01. 1p.

--7908200034 Responds to NRC 790620 ltr re violations noted in IE Insp Repts 50-250/79-11 & 50-251/79-11. Corrective actions: QA activity audits revised & strengthened.
UHRIG, R. E. Florida Power & Light Co. 79/07/12. 22pp.

7908170049 Forwards response to IE Bulletin 79-14 re seismic analysis of as-built safety-related piping sys. Requests NRC concurrence for performance of Item B insps during next extended outage of each unit.
UHRIG, R. E. Florida Power & Light Co. 79/08/02. 23pp.

7908160146 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

7908170012 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08. 2pp.

7908290196 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/10. 2pp.

7908280681 Discusses 790509 reactor vessel loose parts insp. No loose parts observed. Proprietary insp rept not forwarded.
UHRIG, R. E. Florida Power & Light Co. 79/08/20. 1p.

S. Reportable occurrences, LERs & related correspondence

7908070510 Forwards LER 79-011/03L-0.
SCHMIDT, A. D. Florida Power & Light Co. 79/07/23. 1p.

--7909070517 LER 79-011/03L-0 on 790622 during startup, charging sys performance was degraded due to air inleakage into charging pump suction header. Caused by ruptured diaphragm w/damaged ring on valve FCV-3-113B. Valve repaired & pumps vented.
SCHOPPMAN, M. A. Florida Power & Light Co. 79/06/22. 1p.

7908200284 Forwards LER 79-008/03X-1.
SCHMIDT, A. D. Florida Power & Light Co. 79/08/03. 1p.

--7908200286 LER 79-008/03X-1 on 790526 while safeguards sys was being tested, 4A 4,160-volt bus failed to strip in required time, causing emergency diesel generator to stop. Cause not determined. Testing procedures revised.
SCHOPPMAN, M. A. Florida Power & Light Co. 79/08/03. 1p.

7908160463 Forwards update to LER 78-008/01X-1.
SCHMIDT, A. D. Florida Power & Light Co. 79/08/06. 1p.

--7908160468 Update to LER 78-008/01X-1 on 780828, restricting orifices not installed in branch connections from containment spray headers to emergency containment filter spray sys. Caused by inadvertent omission. QC/QA program initiated.
SCHOPPMAN, M. A. Florida Power & Light Co. 79/08/06. 2pp.

U. Congressional/Executive Correspondence

7908140488 Suppl submission of MP Oncavage requesting intervenor status in hearing re steam generator repair program.
ROGOW, B. S. Rogow, B. 79/06/22. 9pp.

7908140470 Forwards 790622 ltr & supplemental submittal of petitioner MP Oncavage for review & comment.
STONE, R. Senate. 79/07/05. 3pp.

DOCKET 50-252 UNIV. OF NEW MEXICO RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

7908010018 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/07/06. 1p.

7908080244 Forwards IE Insp Rept 50-252/79-01 on 790612-13. No noncompliance noted.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/07/17. 2pp.

--7908080251 IE Insp Rept 50-252/79-01 on 790612-13. No noncompliance noted. Major areas inspected: security plan, protection of SNM, security organization, access control & alarm sys.
CALDWELL, R. A.; EVANS, C. R.; MADSEN, G. L. Region 4, Dallas, Office of the Director. 79/07/17. 2pp.

7908160093 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/08/10. 1p.

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7908130162 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908160367 Forwards request for addl info re contingency plans. Encl withheld (ref 10CFR2.790).
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 2pp.

7908200335 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/08/16. 1p.

G. Adjudicatory correspondence

7908190266 Responds to 790514 ltr opposing authorization for increase in spent fuel storage capacity. No application from util filed. Util request to allow storage of spent fuel in spent fuel pools at either site currently under review.
EISENHUT, D. G. Division of Operating Reactors. 79/07/31. 1p.

7908170069 Responds to 790515 postcard. Reviews purpose of application for storage of spent fuel at either plant. Risks are well-known & very low. Hearing will be held soon.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908170285 Responds to 790531 ltr opposing transport of spent fuel between plants. Explains purpose of util application. Risks are well-known & very low. Public hearing will be held soon.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908170292 Responds to 790507 ltr opposing transport of spent fuel between plants. Explains purpose of util application. Risks are well-known & very low. Public hearing will be held soon.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908170297 Responds to 790514 ltr opposing transport of spent fuel between plants. Explains purpose of util application to allow storage. Risks are well known & very low. Public hearing will be held soon.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908200035 Responds to 790510 ltr opposing transportation of spent fuel. Public hearing will be held on shipment in Fall 1979.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908200039 Responds to 790507 post card expressing opposition to transportation of spent fuel. Public hearing on proposed shipment will be held Fall 1979.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908290108 Responds to 790502 & 12 ltrs re hearing on spent fuel transfer. Hearing will be held no earlier than Sept 1979.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

H. General correspondence

7908210445 Responds to 790522 ltr opposing moving of spent fuels between stations. Discusses concerns expressed re proposed high density fuel storage.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908210453 Responds to 790430 ltr & recent telcons. Notice will be made re time & place of hearings on spent fuel transfer between stations. Discusses rules re shipment of spent fuel.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 2pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7cp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 12pp.

7908070652 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/22. 3pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
ORIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908130310 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill; if drill scenario requires NRC initial notification.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/09. 1p.

7908080719 Confirms that meeting at util corporate office has been rescheduled for 790719 at 3 PM. Location, purpose & attendees discussed in NRC 790612 ltr.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/10. 1p.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves W/o encl.
GRIMES, B.K. Assistant Director for Systems Engineering 79/07/16 4pp.

7908100124 Supports util 780202 request for ETS changes, eliminating 2 F per hour temp change limit during changes in mode of condenser cooling. EIA endorsing proposed changes encl.
LEAR, G. Environmental Specialists Branch 79/07/16 1p.

--7908100140 EIA supporting proposed ETS change to eliminate 2 F per hour temp change requirement in mode of condenser cooling.
* Environmental Specialists Branch 79/07/16 2pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W.P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908070332 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/19 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W.P. Quality Assurance Branch 79/07/24 1p.

7908170602 Forwards Amends 52 & 49 to Licenses DPR-29 & DPR-30, respectively, safety evaluation & notice of issuance & availability.
IPPOLITO, T.A. Operating Reactors Branch 3 79/07/27 3pp.

--7908170604 Amends 52 & 49 to Licenses DPR-29 & DPR-30, respectively, adding license conditions re completion of facility mods & implementing administrative controls for fire protection.
IPPOLITO, T.A. Operating Reactors Branch 3 79/07/27 4pp.

--7908170608 Fire protection safety evaluation supporting Amends 52 & 49 to Licenses DPR-29 & DPR-30, respectively.
* Office of Nuclear Reactor Regulation 79/07/27 54pp.

--7908170611 Notice of issuance & availability of Amends 52 & 49 to Licenses DPR-29 & DPR-30, respectively.
IPPOLITO, T.A. Operating Reactors Branch 3 79/07/27 2pp.

7908020460 Submits schedule for addl response to NRC issues re containment purging during normal plant operation.
REED, C. Commonwealth Edison Co. 79/07/30 2pp.

7908070617 Notifies that average release rate of radioiodine & radioactive matls in particulate form, w/half-lives greater than 8 days, exceeded Tech Spec limits.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/07/30 8pp.

7908160376 Forwards table showing manning of technical positions by technical graduates is virtually complete.
LEE, R. Commonwealth Edison Co. 79/07/30 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D.G. Division of Operating Reactors 79/08/03 53pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908200380 Forwards info requested in NRC 790629 & 0724 ltrs re capabilities & technical resources available to handle unusual events.
JANECEK, R.F. Commonwealth Edison Co. 79/08/13 1100pp.

7908230420 Informs that BWR operating plant owners group GE rept, NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs" was submitted to NRC by 790817 ltr from RD Keenan to D Ross. Remainder of info follows in 791116 rept.
JANECEK, R.F. Commonwealth Edison Co. 79/08/20 1p.

Q. Inspection reports, IE Bulletins & correspondence

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790828 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 79/06/20 44pp.

7908150364 Forwards IE Insp Repts 50-254/79-14 & 50-265/79-12 on 790530. No noncompliance noted.
DAVIS, A.B. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/29 2pp.

--7908150375 IE Insp Repts 50-254/79-14 & 50-265/79-12 on 790530. No noncompliance noted. Major areas inspected: response during scheduled drill conducted by util emergency medical contractor.
JANUSKA, A.G., GEER, H.J., ESSIG, T.H. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/28 4pp.

7908080523 Responds to IE Bulletin 79-11. No Westinghouse DB-50 & DB-75 circuit breakers used in safety-related sys.
REED, C. Commonwealth Edison Co. 79/07/02 1p.

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co. 79/07/05 9pp.

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc. 79/05/31 24pp.

7908080703 Submits addl response to IE Bulletins 70-12 & 128. Requested vessel evaluation completed & certification by manufacturer & supplier submitted to NRC.
REED, C. Commonwealth Edison Co. 79/07/09 2pp.

7908150349 Supplements response to IE Bulletin 79-11. Westinghouse DB-50 & DB-75 circuit breakers are neither used in safety-related sys nor stored as spares at facilities.
REED, C. Commonwealth Edison Co. 79/07/12 2pp.

7908080306 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO, T.A. Operating Reactors Branch 3 79/07/20 4pp.

7908060225 Forwards "Inservice Insp & Testing Program" & color-coded piping & instrument diagrams.
JANECEK, R.F. Commonwealth Edison Co. 79/07/25 1p.

--7908060231 "Inservice Insp & Testing Program."
* Commonwealth Edison Co. 79/07/18 200pp.

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/26 1p.

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/26 1p.

7908240513 Responds to IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." Procedures involving reactor criticality, control rod withdrawal sequences & operator training program were modified in 1977.
REED, C. Commonwealth Edison Co. 79/07/30 9pp.

7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists & isos of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED, C. Commonwealth Edison Co. 79/08/01 2pp.

7908240640 Forwards corrected copy of page two of 790716 ltr accompanied by IE Insp Rept 50-254/79-17 re 790626-29 insp.
HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/08/02 2pp.

7908080530 Forwards addl info re responses to IE Bulletin 79-08, per 790720 request.
REED, C. Commonwealth Edison Co. 79/08/03 6pp.

7908170019 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/08 1p.

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/15 1p.

R Periodic operating reports & related correspondence

7908230431 Forwards monthly operating rept for Jul 1979.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/08/06 1p.

--7908230439 Monthly operating rept for Jul 1979.
* Commonwealth Edison Co. 79/08/06 24pp.

7908280570 Forwards semiannual repts re radioactive effluent discharge & solid radioactive waste.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/08/21 1p.

--7908280573 Semiannual rept re radioactive effluent discharges & solid radioactive waste, Jan-Jun 1979.
* Commonwealth Edison Co. 79/08/21 20pp.

S Reportable occurrences, LERs & related correspondence

7908140680 Forwards LER 79-023/03L-0.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/07/30 1p.

--7908140690 LER 79-023/03L-0 on 790717 high pressure switch in safety relief valve controller found inoperable during reactor high pressure automatic blowdown functional test, GIS-40 Caused by loosened lead wire from switch to terminal.
CLARK, D. Commonwealth Edison Co. 79/07/30 3pp.

DOCKET 50-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

7908130119 Forwards "Evaluation of Min Fire Brigade Shift Size." Min size should be five persons.
LAINAS, G. Plant Systems Branch 79/06/28 2pp.

--7908130122 "Evaluation of Min Fire Brigade Shift Size."
* Plant Systems Branch 79/06/08 32pp.

7908130167 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee Plans should be submitted by 790823.
DIGGS, P. M. License Fee Management Branch 79/07/03 2pp.

7908280025 Forwards suitability, training & qualification plans for security personnel Plans withheld (ref 10CFR2.790). Class II amend fee encl.
HOFFMAN, D. P. Consumers Power Co. 79/08/23 1p.

G Adjudicatory correspondence

7906110169 Forwards revision 1 to steam generator repair rept.
BARTH, C. A. Branch 3 79/04/19 1p.

7908130021 Forwards notice of hearing, dtd 790723.
* Operating Reactors Branch 2 79/07/26 2pp.

--7908130023 Notice of hearing re Consumer Power Co request for amend to OL permitting steam generators removal & replacement.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel 79/07/23 3pp.

H General correspondence

7908150084 Ack receipt of correspondence re status of spent fuel storage at six operating facilities near Lake MI. Responds to 790429 ltr.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/26 2pp.

--7908150107 Discusses spent fuel storage capability at Big Rock Point. NUREG-0020 indicates authorized capacity of 120 spent fuel assemblies, while DOE indicates capacity of 385 Requests clarification.
SCHAEFER, J. Lake Michigan Federation 79/05/20 1p.

--7908150125 Ack receipt of info re nuclear power plants near Lake MI. Forwards rept re status of spent fuel storage at plants. Requests comments re rept.
SCHAEFER, J. Lake Michigan Federation 79/06/21 1p.

--7908150139 "Status of Spent Fuel Storage at the Six Nuclear Plants Located on Shore of Lake MI."
SCHAEFER, J. Lake Michigan Federation 79/05/31 20pp.

7908140773 Submits info in response to NRC 790629 & 0724 ltrs re mgt & technical resources available to handle unusual events. Encl available in Central Files only.
HOFFMAN, D. P. Consumers Power Co 79/08/09 1p.

7908150593 Forwards chart showing QA program organizational change in production & transportation dept, effective 790711.
HOFFMAN, D. P. Consumers Power Co 79/08/10 3pp.

P Operating license stage documents & correspondence

7906110175 Forwards Revision 1 to steam generator repair rept.
BARTH, C. A. Branch 3 79/04/19 1p.

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH, H. Operating Reactors Branch 2 (Pre 790625) 79/04/19 5pp.

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project.
LEVIN, H. A. Systematic Evaluation Programs Branch (Pre 790625) 79/03/08 10pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908130359 Notifies all operating plants using C-E-designed reactors of generic review re TMI. Requests attendance at 790612 meeting in Bethesda, MD re info needed by NRC to complete review.
STOLZ, J. F. Light Water Reactors Branch 1 79/06/05 16pp.

7908030232 Summarizes status of five overpressure protection & three flooding reviews evaluated by LLL in response to Eisenhut 790604 memo.
SHEMANSKI, P. Plant Systems Branch 79/06/12 2pp.

--7908030256 Requests status of LLL electrical staff overpressure & flooding reviews.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 1p.

7908130647 Notifies of two suggested changes for Tech Specs. Committees must formally convene quorum to act on issues. Core alteration should be directly supervised by senior reactor operator. Suggested Tech Spec changes encl.
ZIEMANN, D. L. Operating Reactors Branch 2 79/06/12 5pp.

7908030571 Notifies completion of safety evaluation of postulated fuel handling accident inside containment. Doses for one & two assembly failures are appropriately within 10CFR100 guidelines & are acceptable.
ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625) 79/06/21 2pp.

--7908030580 Safety evaluation of postulated fuel handling accident inside containment. Doses for one & two assembly failures are appropriately within 10CFR100 & are acceptable.
* Office of Nuclear Reactor Regulation 79/06/21 4pp.

7908070660 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/22 3pp.

7908130323 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires initial NRC notification.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/09 1p.

DOCKETED ITEMS

7908080682 Requests, within 60 days, submission of info providing assurance that water hole peaking has been considered in calculation of flux distribution.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/11 2pp.

7908090012 Requests review of latest dosimetry calculations, w/verification of results by comparison w/latest C-E calculational methods.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/11 2pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC Task Force groups. Meeting agenda ... list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/14 58pp.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908070334 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/19 1p.

7908170506 Summary of 790614-15 site visit of SEP seismic review team. Forwards util supplemental response to seismic question, Item 2.4, preliminary list of equipment to be evaluated per SEP Topic III-1 & addl info required re seismic resistance.
SILVER, R. D. Operating Reactors Branch 2 79/07/19 20pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908010436 Forwards Fee for steam generator tube surveillance Tech Spec change, inadvertently omitted from 790726 submittal.
CASHELL, S. Consumers Power Co. 79/07/27 1p.

7908230646 Forwards Amend 50 to License DPR-20, safety evaluation & notice of issuance & availability.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/27 2pp.

--7908230654 Amend 50 to License DPR-20, allowing use of new incore detector sys.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/27 6pp.

--7908230660 Safety evaluation supporting Amend 50 to License DPR-20.
* Office of Nuclear Reactor Regulation 79/07/27 2pp.

--7908230663 Notice of issuance & availability of Amend 50 to License DPR-20.
SILVER, R. D. Operating Reactors Branch 2 79/07/27 2pp.

7908240256 Forwards info re temporary storage of QA records & evaluation of QA program. NRC must develop realistic regulatory requirements re fire protection & max time records can be held in temporary storage.
BRYAN, S. E. Division of Reactor Operations Inspections 79/06/27 5pp.

7908070606 Responds to 790606 request re SEP Topic VI-1, "Organic Matls & Post-Accident Chemistry." Estimates areas & thicknesses of major protective coating sys inside containment. Reg Guide 1.54 not used to qualify coating sys.
HOFFMAN, D. P. Consumers Power Co. 79/07/30 3pp.

7908030424 Forwards request for change to Tech Specs of License DPR-20 re auxiliary feedwater sys operability.
HOFFMAN, D. P. Consumers Power Co. 79/07/31 1p.

--7908030430 Request for change to Tech Specs of License DPR-20 re auxiliary feedwater sys operability.
DEWITT, R. B. Consumers Power Co. 79/07/31 4pp.

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees, for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp.

7908060349 Forwards update to proposed change to Tech Specs Section 6 re administrative controls. Clarification provided to identify util organization position re ANSI N18.1-1971.
HOFFMAN, D. P. Consumers Power Co. 79/08/03 4pp.

7908070536 Forwards Revision 3 to steam generator repair rept.
BIXEL, D. A. Consumers Power Co. 79/08/03 2pp.

--7908070561 Revision 3 to steam generator repair rept. Contains responses to requests for addl info.
* Consumers Power Co. 79/07/31 63pp.

7908090350 Forwards Revision 3 to plant steam generator repair rept, in response to 790516 request for addl info.
BIXEL, D. A. Consumers Power Co. 79/08/03 1p.

--7908090354 Revision 3 to plant steam generator repair rept.
YOUNGDAHL, R. C. Consumers Power Co. 79/08/03 65p.

7908100458 Forwards proprietary & non-proprietary versions of Amend 1 to CEN-114, "Review of Small Break Transients in C-E NSSS." LIEBLER, G. E. C-E Operating Plants Owners Group 79/08/03 6pp.

--7908100465 Amend 1-NP to CEN-114-NP, "Review of Small Break Transients in C-E NSSS." CEN-144-P withheld (ref 10CFR2.790).
* Combustion Engineering, Inc. CEN-114-P 79/07/31 111Opp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908210161 Summary of 790711 meeting w/util in Bethesda, MD re high energy linebreak inside containment.
JABBOUR, K. N. Assistant Director for Systematic Evaluation Program 79/08/06 4pp.

7908210068 Advises that proposed amends in 781113 & 790312 submittals do not cover items of model radiological effluent Tech Specs sent to util in 781115 ltr. Forwards request for addl info & guidelines. Revisions should be submitted by 790914.
ZIEMANN, D. L. Operating Reactors Branch 2 79/08/08 13pp.

7908170387 Forwards requested info re mgt & technical resources available to handle unusual events similar to TMI incident. Info withheld (ref 10CFR2.790).
HOFFMAN, D. P. Consumers Power Co. 79/08/09 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908170428 Forwards CEN-114-NP, Amend 1, "Review of Small Break Transients in C-E Nuclear Steam Supply Sys." Proprietary version, CEN-114-P, withheld (ref 10CFR2.790).
SCHERER, A. E. C-E Power Systems 79/08/10 1p.

7908200386 Informs of delay in forwarding seismic info requested by NRC on 790815, due to work load resulting from IE Bulletin 79-14. Complete info package will be forwarded 790829.
BECKIUS, W. J. Consumers Power Co. 79/08/14 1p.

7908210353 Forwards hazards analysis rept for State of MI.
JURY, M. J. Consumers Power Co. 79/08/16 1p.

--7908210355 Hazards analysis rept for State of MI, by MI Dept of State Police. Oversized map encl.
* Michigan, State of. 74/05/31 49pp.

7908230473 Forwards request for change to License DPR-20 Tech Specs re hydrogen recombiners Class III amend fee encl.
HOFFMAN, D. P. Consumers Power Co. 79/08/20 7pp.

7908240455 Responds to 790525 ltr & provides updated description of feedwater chemistry controls & summary of chemistry data re PWR feedwater line.
BIXEL, D. A. Consumers Power Co. 79/08/21 2pp.

7908270447 Submits addl info to NRC 790808 ltr re electrical supply to pressurizer heaters.
HOFFMAN, D. P. Consumers Power Co. 79/08/21 1p.

7908280004 Explains that CEN-114-P, Amend 1-P, was forwarded 790803 in response to NRC 790605 request for info.
HOFFMAN, D. P. Consumers Power Co. 79/08/22 1p.

G. Inspection reports, IE Bulletins & correspondence

7908020272 Responds to IE Bulletin 79-03 re defects in logitudinal welds in ASME SA-312 Type 304 stainless steel pipe spools. Preliminary review identified nonsafety-related use of pipe at Palisades; not in use at Big Rock Point.
BIXEL, D. A. Consumers Power Co. 79/05/30 1p.

7908030597 Responds to IE Bulletin 79-06B re addl actions requested of util. Submits info re training of operators, safety injection sys, waste handling sys, operation of charging pumps & safety-related valves.
HOFFMAN, D. P. ; DEWITT, R. B. Consumers Power Co. 79/06/05 7pp.

7908030027 Responds to IE Bulletins 78-12, 78-12A & 78-12B. Ref GE rept, "Atypical Weld Matl in Reactor Pressure Vessel Welds." No archive weld matl discovered in reactor vessel.
HOFFMAN, D. P. Consumers Power Co. 79/06/27 1p.

7908280228 Forwards IE Insp Rept 50-255/79-09 on 790611-14 & 20-22. No noncompliance noted.
HEISHMAN, R. F. Region 3, Chicago. Reactor Operations Nuclear Support Branch 79/06/29 2pp.

--7908280233 IE Insp Rept 50-255/79-09 on 790611-14 & 20-22. No noncompliance noted. Major areas inspected: operations, fire protection, reportable events & licensee action on IE bulletin.
JORGENSEN, B. L. ; BOYD, D. C. Region 3, Chicago. Office of the Director 79/06/27 7pp.

7908080309 Responds to IE Bulletin 79-11. No Westinghouse Type DB-50 or DB-75 circuit breakers used in safety-related sys.
HOFFMAN, D. P. Consumers Power Co. 79/07/03 2pp.

7908090654 Responds to NRC 790430 rejection of util 790329 response to IE Bulletin 79-02. Provides interim rept on hanger unit insp, permanent maint procedures, snubber testing insp & recent pipe support mods re anchor bolts.
HOFFMAN, D. P. Consumers Power Co. 79/07/06 25pp.

7908140099 Responds to IE Bulletin 79-13, Item 5. Emergency procedures for feedwater line break accident have been reviewed & detection of feedwater leaks accomplished. Final rept will be submitted within 90 days.
HOFFMAN, D. P. Consumers Power Co. 79/07/13 2pp.

7908080103 Ack receipt of 790627 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/79-06.
KEPPLER, J. G. Region 3, Chicago. Office of the Director 79/07/18 1p.

--7908080107 Responds to NRC 790606 ltr re violations noted in IE Insp Rept 50-255/79-06. Corrective actions: method of controlling entry to high radiation areas is as required. Survey procedures corrected.
HOFFMAN, D. P. Consumers Power Co. 79/06/27 3pp.

7908160329 Discusses review of response to IE Bulletin 79-06B. Addl info required.
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/25 4pp.

7908200309 Submits final response to IE Bulletin 79-03 re welded SA-312 Type 304 stainless steel piping. Piping used only in nonsafety-related sys.
HOFFMAN, D. P. Consumers Power Co. 79/07/26 1p.

7908290287 Forwards IE Bulletins 79-05C & 06C: "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER, J. G. Region 3, Chicago. Office of the Director 79/07/26 1p.

7908290349 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago. Office of the Director 79/07/26 1p.

7908300450 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER, J. G. Region 3, Chicago. Office of the Director 79/07/26 1p.

7908240533 Submits addl info in response to IE Bulletin 79-13. Certain insps listed in schedule for completion of IE Bulletin 79-13 are unnecessary.
HOFFMAN, D. P. Consumers Power Co. 79/07/30 4pp.

7908150342 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago. Office of the Director 79/08/07 1p.

7908170021 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago. Office of the Director 79/08/08 1p.

7908300483 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago. Office of the Director 79/08/15 1p.

7908220311 Lists corrections to 790605 & 07 responses to IE Bulletin 79-06B. Forwards revised pages re containment isolation.
HOFFMAN, D. P. Consumers Power Co. 79/08/16 4pp.

7908280005 Submits response to Item 1 of IE Bulletin 79-17 re review of safety-related stainless steel piping. Responses to Items 2-7 will be submitted by 791025.
HOFFMAN, D. P. Consumers Power Co. 79/08/24 10pp.

R. Periodic operating reports & related correspondence

7908140536 Forwards monthly operating rept for July 1979.
ADAMS, W. E. Consumers Power Co. 79/08/07 1p.

--7908140538 Monthly operating rept for July 1979.
BODTKE, P. J. Consumers Power Co. 79/08/06 4pp.

S. Reportable occurrences: LERs & related correspondence

7908J10503 Forwards LER 79-029/03L-0.
HOFFMAN, D. P. Consumers Power Co. 79/07/26 1p.

--7908010508 LER 79-029/03L-0 on 790628: conductivity & sodium concentrations in A steam generator increased in excess of Tech Spec limits. Caused by leakage in condenser tube & chemical hideout return as result of power reduction.
* Consumers Power Co. 79/07/26 1p.

7908060421 Forwards LER 79-030/03L-0.
HOFFMAN, J. G. Consumers Power Co. NRC 79/07/31 1p.

--7908060428 LER 79-030/03L-0 on 790702: conductivity & sodium concentration in steam generator A increased. Caused by chemical hideout return as result of rapid power reduction. Corrected through increased steam generator blowdown.
* Consumers Power Co. 79/07/31 1p.

7908060432 Forwards LER 79-031/03L-0.
HOFFMAN, D. P. Consumers Power Co. 79/07/31 1p.

--7908060438 LER [illegible]31/03L-0 on 790628: uncontrolled release of fission gases occurred during power reduction. Caused by gases escaping through relief valve removed from T-101368 (WADT) for repair & testing. Relief valve repaired.
* Consumers Power Co. 79/07/31 1p.

7908170401 Forwards LER 79-032/03L-0.
HOFFMAN, D. P. Consumers Power Co. 79/08/14 1p.

--7908170402 LER 79-032/03L-0 on 790725: conductivity & sodium concentration in steam generator A exceeded Tech Specs limit. Caused by chemical hideout return as result of rapid power reduction. Corrected through steam generator blowdown.
* Consumers Power Co. 79/08/14 1p.

7908230407 Forwards LER 79-033/03L-0.
HOFFMAN, D. P. Consumers Power Co. 79/08/16 1p.

--7908230410 LER 79-033/03L-0 on 790730: I-beam to which snubber is anchored was twisted approx 20 degrees at spot where snubber bracket connected. Cause undetermined. Defective I-beam segment replaced & snubber fully compressed.
* Consumers Power Co. 79/08/16 1p.

7908270389 Forwards LERs 79-025/01X-1 & 79-031/03X-1.
HOFFMAN, D. P. Consumers Power Co. 79/08/20 1p.

--7908270394 LER 79-025/01X-1 on 790619: heat transfer coefficients of component cooling water heat exchanger were less than required. Caused by fouled tube sides. Tubes will be cleaned more frequently.
* Consumers Power Co. 79/08/20 1p.

--7908270396 LER 79-031/03X-1 on 790628: uncontrolled release of gase occurred during power reduction. Caused by removal of relief valve for repair. Valve repaired & replaced.
* Consumers Power Co. 79/08/20 1p.

7908280663 Forward NPDES noncompliance notification re special radioactive environ noncompliance.
HOFFMAN, D. P. Consumers Power Co. 79/08/24 1p.

--7908280668 Noncompliance Notification PAL-79-07-NC2B on 790731 weekly sampling & analysis for sulfate in cooling tower blowdown was not performed during Jul 1979 Caused by technician error Sulfate analysis performed.
FORBES, R. L. Consumers Power Co. 79/08/20. 1p.

U. Congressional/Executive Correspondence

7908200239 Responds to 790518 ltr to Senator Levin re publicity for 790509 plant public hearing Discusses FR notices, news clips & broadcasts announcing hearing.
SHAPAR, H. K. Office of the Executive Legal Director. 79/07/16. 1p.

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

P. Security, medical, emergency & fire protection plans

7908130208 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908220054 Confirms 790724 mgt meeting in Bethesda, MD to discuss security program.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/07/17. 3pp.

7908060437 Forwards amended physical security plan Plan withheld (ref 10CFR2.790).
MILLS, L. M. Tennessee Valley Authority. 79/07/30. 1p.

7908210314 Forwards security personnel training & qualification plans Plans withheld (ref 10CFR2.790).
MILLS, L. M. Tennessee Valley Authority. 79/08/17. 1p.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L. M. Tennessee Valley Authority. 79/08/07. 2pp.

7908270268 Summarizes 790724 mgt meeting in Bethesda, MD re activities authorized by OLs DPR-33, DPR-52 & DPR-68 Info withheld (ref 10CFR2.790).
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08. 2pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908070357 Forwards Amend 69 to FSAR.
MILLS, L. M. Tennessee Valley Authority. 79/08/02. 2pp.

--7908070366 Amend 69 to FSAR.
* Tennessee Valley Authority. 79/08/02. 32pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908030123 Requests addl justification re acceptable temp tolerances for connectors prior to approval of SANDIA qualification tests Requests clarification of purpose of immersion heater in autoclave.
VOLLMER, R. Division of Operating Reactors. 79/06/14. 2pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908300054 Responds to 790223 & 0309 ltrs re stem-mounted limit switches installed on MSIV Analysis must be provided re MSIV closure input & schematic drawings regarding circuits w/inputs from switches & interposing relay.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/12. 3pp.

7908080350 Forwards NUREG-0462 Technical Rept on Operating Experience w/BWR Pressure Relief Sys Requests info re Target Rock safety relief valves. W/ encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070317 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908130498 Notice of receipt of 790629 application for amend to Licenses DPR-33, DPR-52 & DPR-68 Application subj to $4,000 Class III fee & two $800 Class I amend fees.
MILLER, W. O. License Fee Management Branch. 79/07/20. 1p.

7908150132 Forwards request for addl info re 790323 submittal concerning contingency plan Encl withheld (ref 10CFR2.790).
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/20. 2pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908160033 Responds to 790308 ltr which requested refund of fees paid for Tech Spec changes Fee for Change 110 refunded 780825. Since review of Change 111 began shortly after receipt, refund is not in order.
DIGGS, R. M. License Fee Management Branch. 79/07/25. 2pp.

7908300213 Responds to 790315 ltr re amend to Licenses DPR-33, DPR-52 & DPR-68 Forwards legal opinion that revisions are not necessary Code provides adequate authority re shipment of unirradiated & spent fuels.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/25. 2pp.

--7908300226 Responds to 790405 memo re revision of std NRC license authorizing shipment of unirradiated & spent fuel Revisions are not necessary.
MALSCH, M. G. Regulations Division. 79/04/13. 6pp.

7908060245 Discusses delay in LCP1 power supply mods due to matl delivery problems Outlines schedule for completion of power supply mods.
MILLS, L. M. Tennessee Valley Authority. 79/07/31. 1p.

7908060417 Responds to NRC 790712 ltr re environ qualification of stem-mounted limit switches installed on MSIVs Will replace unqu'.fied limit switches on inboard MSIVs during next refueling outage.
MILLS, L. M. Tennessee Valley Authority. 79/07/31. 1p.

7908270089 Approves util 790711 request to change Tech Specs re surveillance testing of solenoid operated air/nitrogen valves in containment atmosphere dilution sys Forwards safety evaluation.
LAINAS, G. Plant Systems Branch. 79/08/02. 2pp.

--7908270095 Review of util 790711 request for changes to Tech Specs re surveillance requirements for containment atmosphere dilution sys solenoid operated air valves Approves mods Will continue review of generic purge valve bypass issue.
* Plant Systems Branch. 79/08/02. 1p.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908140552 Forwards proposed amend to Tech Specs for Licenses DPR-33, DPR-52 & DPR-68.
MILLS, L. M. Tennessee Valley Authority. 79/08/06. 2pp.

--7908140556 Proposed Tech Spec changes to allow partial tensioning of reactor pressure vessel head bolts at 70 F & allow nuclear heat to be utilized above 100 F, thus decreasing heatup time.
* Tennessee Valley Authority 79/08/06 15pp

7908140565 Forwards addl info on proposed Tech Spec change re reduction of scram tiling pressure restrictions.
MILLS, L. M. Tennessee Valley Authority 79/08/07 7pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09 56pp

7908170334 Submits info in response to NRC 790629 ltr re corporate capability.
MILLS, L. M. Tennessee Valley Authority 79/08/15 29pp

9. Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority 79/05/29 3pp

7908170138 Forwards IE Insp Repts 50-259/79-15, 50-260/79-15 & 50-296/79-15 on 790529-31. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/12 2pp

--7908170147 IE Insp Repts 50-259/79-15, 50-260/79-15 & 50-296/79-15 on 790529-31. No noncompliance noted. Major areas inspected: response to bulletins.
PRICE, D. S. Region 2, Atlanta, Office of the Director.
DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/11 3pp

7908270326 Forwards response to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion anchor bolts. Where necessary, plant operators instructed to replace self-drilling anchors w/wedge bolts.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/19 97pp

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 79/06/20 44pp

7908020536 Discusses several errors in NRC 790509 ltr re recent IE insp repts. First docket number should be 50-259 & rept number for all units should be 79-09.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/21 1p

7908060001 Forwards IE Insp Repts 50-259/79-12, 50-260/79-12 & 50-296/79-12 on 790402-27. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/21 2pp

--7908060002 IE Insp Repts 50-259/79-12, 50-260/79-12 & 296/79-12 on 790402-27. No noncompliance noted. Major areas inspected: plant operation, followup to reportable occurrences, offsite safety & plant protection.
SULLIVAN, R. F., DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20 4pp

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26 3pp

7908010032 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06 2pp

7908140334 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 circuit breakers used at facility.
MILLS, L. M. Tennessee Valley Authority 79/07/06 1p

7908020023 Responds to 790413 ltr transmitting IE Bulletin 79-08. Forwards revision to page 13 of 790424 response.
MILLS, L. M. Tennessee Valley Authority 79/07/11 2pp

7908230571 Forwards IE Insp Repts 50-259/79-13, 50-260/79-13 & 50-296/79-13 on 790430-0615. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/11 2pp

--7908230578 IE Insp Repts 50-259/79-13, 50-260/79-13 & 50-296/79-13 on 790430-0615. No noncompliance noted. Major areas inspected: plant operation, RDs, organization & maint & radiation area controls.
SULLIVAN, R. F. Region 2, Atlanta, Office of the Director.
DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/10 6pp

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17 3pp

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 3pp

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 3pp

7908080338 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/20 4pp

7908080721 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26 2pp

7908080746 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26 2pp

7908290636 Forwards suppl response to IE Bulletin 79-01A, identifying safety sys involved in use of ASCO solenoid valves. Stainless steel seated valve should remain operable even if Buna N gasket becomes brittle.
MILLS, L. M. Tennessee Valley Authority 79/07/26 3pp

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27 3pp

7908230475 Responds to IE Bulletin 79-14. Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L. M. Tennessee Valley Authority 79/07/27 1p

7908160070 Forwards response to IE Bulletin 79-12. Discusses review of methods & procedures concerning rod withdrawal during startup, in attempt to eliminate fast reactor periods in future.
MILLS, L. M. Tennessee Valley Authority 79/07/30 4pp

7908160304 Ack receipt of 790706 IE Insp Repts 50-259/79-16, 50-260/79-16 & 50-296/79-16. No proprietary info.
MILLS, L. M. Tennessee Valley Authority 79/07/30 3pp

7908240228 Ack receipt of 790508 & 0611 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 79/07/30 1p

--7908240243 Responds to NRC 790416 ltr re violations noted in IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06. Revises 790508 response. Corrective actions contain physical security info. Attached response withheld (ref 10CFR2.790).
GILLELAND, J. E. Tennessee Valley Authority. 79/06/11 1p.

--7908240254 Responds to NRC 790416 ltr re violations noted in IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06. Corrective actions contain physical security info. Attached response withheld (ref 10CFR2.790).
GILLELAND, J. E. Tennessee Valley Authority. 79/05/08. 1p.

DOCKETED ITEMS

--7908240277 Forwards IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06 on 790228-0302 & notice of violation. Notice of violation & insp repts withheld (ref 10CFR2.790). Summaries of insp repts not exempt.
KENNA, W.B. Region 2, Atlanta, Safeguards Branch 79/04/16 2pp.

--7908240290 IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06 on 790228-3020. Noncompliance noted: security organization, detection aids & deficient locks & keys. Eight pages of insp repts withheld (ref 10CFR2.790).
* Region 2, Atlanta, Safeguards Branch 79/04/16 1p.

7908100487 Responds to 790720 ltr & forwards addl response to IE Bulletin 79-08 re initiation of containment isolation.
MILLS, L.M. Tennessee Valley Authority 79/08/06 9pp.

7908160151 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/07 2pp.

7908270177 Ack receipt of 790720 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14.
LEWIS, R.C. Region 2, Atlanta, Office of the Director 79/08/07 1p.

--7908270185 Responds to NRC 790625 ltr re violation noted in IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14. Corrective actions: essential raw cooling water RHR pump seal heat exchanger valves will be locked.
MILLS, L.M. Tennessee Valley Authority 79/08/20 2pp.

--7908270193 Forwards IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14 on 790521-25 & notice of violation.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/25 2pp.

--7908270199 Notice of violation from insp on 790521-25.
* Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/25 1p.

--7908270209 IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14 on 790521-25. Noncompliance noted: failure to follow plant procedures re locking of RHR pump seal heat exchanger valves.
MOON, B.T. Region 2, Atlanta, Office of the Director.
RUHLMAN, W.A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/25 6pp.

7908170015 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/08 2pp.

7908290217 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/10 2pp.

R Periodic operating reports & related correspondence

7908070671 Forwards fish impingement rept for second quarter 1979.
MILLS, L.M. Tennessee Valley Authority 79/07/30 5pp.

7908140532 Amends 790730 fish impingement rept. Matl encl supersedes previously-submitted data for second quarter 1979.
MILLS, L.M. Tennessee Valley Authority 79/08/09 14pp.

7908140445 Forwards monthly operating rept for Jul 1979.
ALENCOURT, H. Tennessee Valley Authority 79/08/10 1p.

--7908140451 Monthly operating rept for Jul 1979.
ALENCOURT, H., THOM, T., GREEN, D. Tennessee Valley Authority. 79/08/02 30pp.

S Reportable occurrences, LERs & related correspondence

7908030378 Notifies of RO 50-259/79-15 on 790723 during field insp bolts were found to be not installed in accordance w/design specs. Insp & evaluation continues.
DEWEASE, J.O. Tennessee Valley Authority 79/07/24 2pp.

7908010548 Forwards LER 79-011/03L-0.
FOX, H.S. Tennessee Valley Authority 79/07/27 1p.

--7908010552 LER 79-011/03L-0 on 790628 scram discharge level switch, LS-85-45B, found failed in unsafe direction. Caused by buildup of foreign matl in pivot pin area which prevented movement of switch actuator rod. Swich was cleaned.
* Tennessee Valley Authority 79/07/27 2pp.

7908100425 Forwards LER 79-013/01T-0.
CALHOUN, J.R. Tennessee Valley Authority 79/08/06 1p.

--7908100432 LER 79-013/01T-0 on 790723 in response to IE Bulletin 79-02, 44 anchors on safety-related piping were visually inspected. Two were 1/2 inch short. On non safety-related piping, two slipped & two pulled out. Caused by rebar interference.
* Tennessee Valley Authority 79/08/06 2pp.

7908140807 Forwards LER 79-012/03L-0.
CALHOUN, J.R. Tennessee Valley Authority 79/08/08 1p.

--7908140816 LER 79-012/03L-0 on 790710 w/unit in normal operation, HPCI failed to come to rated speed & flow within required time limit while SI 4.5.E.1.d & e were being performed. Caused by stop valve FCV 73-18 not opening fully due to loose screw.
* Tennessee Valley Authority 79/08/08 1p.

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

7908130208 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch 79/07/03 2pp.

7908220054 Confirms 790724 mgt meeting in Bethesda, MD to discuss security program.
KENNA, W.B. Region 2, Atlanta, Safeguards Branch 79/07/17 3pp.

7908060437 Forwards amended physical security plan. Plan withheld (ref 10CFR2.790).
MILLS, L.M. Tennessee Valley Authority 79/07/30 1p.

7908210314 Forwards security personnel training & qualification plans. Plans withheld (ref 10CFR2.790).
MILLS, L.M. Tennessee Valley Authority 79/08/17 1p.

H General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L.M. Tennessee Valley Authority 79/08/07 2pp.

7908270268 Summarizes 790724 mgt meeting in Bethesda, MD re activities authorized by OLs DPR-33, DPR-52 & DPR-68. Info withheld (ref 10CFR2.790).
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/08 2pp.

K Utility Final Safety Analysis Report (FSAR) & amends

7908070357 Forwards Amend 69 to FSAR.
MILLS, L.M. Tennessee Valley Authority 79/08/02 2pp.

--7908070366 Amend 69 to FSAR.
* Tennessee Valley Authority 79/08/02 32pp.

P Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards 79/03/22 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors 79/06/04 52pp.

7908030123 Requests addl justification re acceptable temp tolerances for connectors prior to approval of SANDIA qualification tests Requests clarification of purpose of immersion heater in autoclave
VOLLMER,R. Division of Operating Reactors 79/06/14 2pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program Proposed agenda encl
GRIMES,C.I. Plant Systems Branch 79/06/27 2p

7908080209 Summary of 790628 meeting w/BWR licensees,applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI
KANE,W.F. Standardization Branch 79/07/11 26pp.

7908080054 Responds to 790223 & 0309 ltrs re stem-mounted limit switches installed on MSIV Analysis must be provided re MSIV closure input & schematic drawings regarding circuits w/inputs from switches & interposing relay
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/12 3pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves W/o encl
GRIMES,B.K. Assistant Director for Systems Engineering 79/07/16 4pp.

7908100290 Forwards NUREG-0472,Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL,W.P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908070317 Requests cooperation in data-gathering activities to provide NRC Commissioners,public & media w/up-to-date operating status of power reactors Info requests will not be made while plant is in shutdown mode
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/19 1p

7908130498 Notice of receipt of 790629 application for amend to Licenses DPR-33,DPR-52 & DPR-68 Application subj to $4,000 Class III Fee & two $800 Class I amend fees
MILLER,W.O. License Fee Management Branch 79/07/20 1p

7908150132 Forwards request for addl info re 790323 submittal concerning contingency plan Encl withheld (ref 10CFR2.790)
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/20 2pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events Requests addl five copies of response for each addl unit
HAASS,W.P. Quality Assurance Branch 79/07/24 1p

7908160033 Responds to 790308 ltr which requested refund of fees paid for Tech Spec changes Fee for Change 110 refunded 780825 Since review of Change 111 began shortly after receipt, refund is not in order
DIGGS,R.M. License Fee Management Branch 79/07/25 2pp.

7908300213 Responds to 790315 ltr re amend to Licenses DPR-33,DPR-52 & DPR-68 Forwards legal opinion that revisions are not necessary Code provides adequate authority re shipment of unirradiated & spent fuels
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/25 2pp.

--7908300226 Responds to 790405 memo re revision of std NRC license authorizing shipment of unirradiated & spent fuel Revisions are not necessary.
MALSCH,M.G. Regulations Division 79/04/13 6pp.

7908060245 Discusses delay in LCPI power supply mods due to matl delivery problems Outlines schedule for completion of power supply mods
MILLS,L.M. Tennessee Valley Authority 79/07/31 1p

7908060417 Responds to NRC 790712 ltr re environ qualification of stem-mounted limit switches installed on MSIVs Will replace unqulified limit switches on inboard MSIVs during next refueling outage
MILLS,L.M. Tennessee Valley Authority 79/07/31 1p

7908270089 Approves util 790711 request to change Tech Specs re surveillance testing of solenoid operated air/nitrogen valves in containment atmosphere dilution sys Forwards safety evaluation
LAINAS,G. Plant Systems Branch 79/08/02 2pp.

--7908270095 Review of util 790711 request for changes to Tech Specs re surveillance requirements for containment atmosphere dilution sys solenoid operated air valves Approves mods Will continue review of generic purge valve bypass issue.
* Plant Systems Branch 79/08/02 1p.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss re:ent impacts on emergency planning & current regulations,guidance documents & repts re emergency planning
EISENHUT,D.G. Division of Operating Reactors 79/08/03 53pp.

7908140552 Forwards proposed amend to Tech Specs for Licenses DPR-33, DPR-52 & DPR-68
MILLS,L.M. Tennessee Valley Authority 79/08/06 2pp.

--7908140556 Proposed Tech Spec changes to allow partial tensioning of reactor pressure vessel head bolts at 70 F & allow nuclear heat to be utilized above 100 F,thus decreasing heatup time.
* Tennessee Valley Authority 79/08/06 15pp.

7908140565 Forwards addl info on proposed Tech Spec change re reduction of scram timing pressure restrictions.
MILLS,L.M. Tennessee Valley Authority 79/08/07 7pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power
GAMMILL,W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908170334 Submits info in response to NRC 790629 ltr re corporate capability.
MILLS,L.M. Tennessee Valley Authority 79/08/15 29pp.

G. Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12,12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts Westinghouse generic rept due Oct 1979
GILLELAND,J.E. Tennessee Valley Authority 79/05/29 3pp.

7908170138 Forwards IE Insp Repts 50-259/79-15,50-260/79-15 & 50-296/79-15 on 790529-31 No noncompliance noted
LEWIS,R.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/12 2pp.

--7908170147 IE Insp Repts 50-259/79-15,50-260/79-15 & 50-296/79-15 on 790529-31 No noncompliance noted Major areas inspected: response to bulletins.
PRICE,D.S. Region 2, Atlanta, Office of the Director
DANCE,H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/11 3pp.

7908270326 Forwards response to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion anchor bolts Where necessary,plant operators instructed to replace self-drilling anchors w/wedge bolts.
GILLELAND,J.E. Tennessee Valley Authority 79/06/19 97pp.

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08 Requests attendance at 790628 meeting in Bethesda,MD re info needed by NRC to complete review.
IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625) 79/06/20 44pp.

7908020536 Discusses several errors in NRC 790509 ltr re recent IE insp repts First docket number should be 50-259 & rept number for all units should be 79-09
LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/21 1p

7908060001 Forwards IE Insp Repts 50-259/79-12,50-260/79-12 & 50-296/79-12 on 790402-27 No noncompliance noted.
LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/21 2pp.

--7908060002 IE Insp Repts 50-259/79-12,50-260/79-12 & 296/79-12 on 790402-27 No noncompliance noted Major areas inspected: plant operation,followup to reportable occurrences,offsite safety & plant protection.
SULLIVAN,R.F., DANCE,H.C. Region 2, Atlanta, Reactor Oper., Nuclear Support Branch 79/06/20 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/06/26 3pp.

DOCKETED ITEMS

7908010032 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908140334 Responds to IE Bulletin 79-11 No Westinghouse DB-50 or DB-75 circuit breakers used at facility.
MILLS, L M. Tennessee Valley Authority. 79/07/06. 1p.

7908020023 Responds to 790413 ltr transmitting IE Bulletin 79-08. Forwards revision to page 13 of 790424 response.
MILLS, L M. Tennessee Valley Authority. 79/07/11. 2pp.

7908230571 Forwards IE Insp Repts 50-259/79-13, 50-260/79-13 & 50-296/79-13 on 790430-0615. No noncompliance noted.
LEWIS, R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/11. 2pp.

--7908230578 IE Insp Repts 50-259/79-13, 50-260/79-13 & 50-296/79-13 on 790430-0615. No noncompliance noted. Major areas inspected: plant operation, ROs, organization & maint & radiation area controls.
SULLIVAN, R F. Region 2, Atlanta, Office of the Director.
DANCE, H C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/10. 6pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/17. 3pp.

7908C00316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908080338 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO, T A. Operating Reactors Branch 3. 79/07/20. 4pp.

7908080721 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908080746 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908290636 Forwards suppl response to IE Bulletin 79-01A identifying safety sys involved in use of ASCO solenoid valves. Stainless steel seated valve should remain operable even if Buna N gasket becomes brittle.
MILLS, L M. Tennessee Valley Authority. 79/07/26. 3pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L M. Tennessee Valley Authority. 79/07/27. 1p.

7908160070 Forwards response to IE Bulletin 79-12 Discusses review of methods & procedures concerning rod withdrawal during startup, in attempt to eliminate fast reactor periods in future.
MILLS, L M. Tennessee Valley Authority. 79/07/30. 4pp.

7908160304 Ack receipt of 790706 IE Insp Repts 50-259/79-16, 50-260/79-16 & 50-296/79-16. No proprietary info.
MILLS, L M. Tennessee Valley Authority. 79/07/30. 3pp.

7908240228 Ack receipt of 790508 & 0611 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06.
KENNA, W B. Region 2, Atlanta, Safeguards Branch. 79/07/30. 1p.

--7908240243 Responds to NRC 790416 ltr re violations noted in IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06. Revises 790508 response. Corrective actions contain physical security info. Attached response withheld (ref 10CFR2.790).
GILLELAND, J E. Tennessee Valley Authority. 79/06/11. 1p.

--7908240254 Responds to NRC 790416 ltr re violations noted in IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06. Corrective actions contain physical security info. Attached response withheld (ref 10CFR2.790).
GILLELAND, J E. Tennessee Valley Authority. 79/05/08. 1p.

--7908240277 Forwards IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06 on 790228-0302 & notice of violation. Notice of violation & insp repts withheld (ref 10CFR2.790). Summaries of insp repts not exempt.
KENNA, W B. Region 2, Atlanta, Safeguards Branch. 79/04/16. 2pp.

--7908240290 IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06 on 790228-3020. Noncompliance noted: security organization, detection aids & deficient locks & keys. Eight pages of insp repts withheld (ref 10CFR2.790).
*. Region 2, Atlanta, Safeguards Branch. 79/04/16. 1p.

7908100487 Responds to 790720 ltr & forwards addl response to IE Bulletin 79-08 re initiation of containment isolation.
MILLS, L M. Tennessee Valley Authority. 79/08/06. 9pp.

7908160151 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

7908270177 Ack receipt of 790720 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14.
LEWIS, R C. Region 2, Atlanta, Office of the Director. 79/08/07. 1p.

--7908270185 Responds to NRC 790625 ltr re violation noted in IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14. Corrective actions: essential raw cooling water RHR pump seal heat exchanger valves will be locked.
MILLS, L M. Tennessee Valley Authority. 79/08/20. 2pp.

--7908270193 Forwards IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14 on 790521-25 & notice of violation.
LEWIS, R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 2pp.

--7908270199 Notice of violation from insp on 790521-25.
*. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 1p.

--7908270209 IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14 on 790521-25. Noncompliance noted: failure to follow plant procedures re locking of RHR pump seal heat exchanger valves.
MOON, B T. Region 2, Atlanta, Office of the Director.
RUHLMAN, W A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 6pp.

7908170015 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/08/08. 2pp.

7908290217 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/08/10. 2pp.

R. Periodic operating reports & related correspondence

7908070671 Forwards fish impingement rept for second quarter 1979.
MILLS, L M. Tennessee Valley Authority. 79/07/30. 5pp.

7908140532 Amends 790730 fish impingement rept. Matl encl supersedes previously-submitted data for second quarter 1979.
MILLS, L M. Tennessee Valley Authority. 79/08/09. 14pp.

7908140445 Forwards monthly operating rept for Jul 1979.
ALENCOURT, H. Tennessee Valley Authority 79/08/10 1p

--7908140451 Monthly operating rept for Jul 1979.
ALENCOURT, H. ; THOM, T. ; GREEN, D. Tennessee Valley Authority
79/08/02 30pp

5 Reportable occurrences, LERs & related correspondence

7908020447 Forwards LER 78-022/03L-1.
FOX, H. S. Tennessee Valley Authority 79/07/27 1p.

--7908020451 LER 78-022/03L-1 on 781202 during normal operation, reactor bldg, turbine bldg & refueling zone ventilation exhaust monitor RM-90-250 became inoperable. Caused by collection of moisture in sampling line of monitor. Sampling line dried
* Tennessee Valley Authority 79/07/27 1p

7908020496 Forwards LER 79-014/03L-1.
FOX, H. S. Tennessee Valley Authority 79/07/30 1p.

--7908020502 LER 79-014/03L-1 on 790526 while in cold shutdown for refueling, local leak rate testing revealed that total leak rate exceeded allowable 60% Caused by deterioration of valve seats on main steam sys. Valves repaired.
* Tennessee Valley Authority 79/07/30 1p

7908280732 Forwards LER 79-018/03L-0.
CALHOUN, J. R. Tennessee Valley Authority 79/08/24 1p

--7908280742 LER 79-018/03L-0 on 790727 indicating lights failed for reactor bldg to torus vacuum breaker, FCV 2-64-21 Valve inoperative contrary to Tech Specs Caused by control circuit fuse blowing due to failure of coil for relay 16A-K40.
* Tennessee Valley Authority 79/08/24 2pp

DOCKET 50-261 H. B. ROBINSON PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

7908130180 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp

7908100163 Forwards approval fees for contingency plans. Since plan is site-specific document, requests refund of duplicate fee.
UTLEY, E. E. Carolina Power & Light Co. 79/07/30 1p

7908230399 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
UTLEY, E. E. Carolina Power & Light Co. 79/08/17 2pp

H. General correspondence

7908010269 Expresses appreciation for prompt action re 790629 issuance of Amend 39 to License DPR-23 authorizing operation at 2,300 MW.
UTLEY, E. E. Carolina Power & Light Co. 79/07/25 1p

J. Insurance & indemnity information

7908290388 Forwards Endorsements 47-49 to MAELU Policy MF-49.
GRAHAM, W. E. Carolina Power & Light Co. 79/08/21 4pp

P. Operating license stage documents & correspondence

7908080633 Forwards documents on file re seismic pipe stresses at Robinson facility. Forwards info re resolution of problem at Turkey Point.
LEWIS, S. H. Bran: 79/04/25 24pp

--7908080656 Recommends IE Bulletin 79-07 & IE Info Notice 79-06, re seismic stress analysis of safety-related piping, be provided to Boards listed. Bulletin & info notice encl.
STELLO, V. Division of Operating Reactors 79/04/19 2pp

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp

7908030319 Forwards 790522 Board notification, recommendation, trip rept & IE Bulletin 79-04 re poss. ble incorrect weights assigned to valves in running pipe stress analysis. Licensee reanalysis determined piping stresses still acceptable.
LEWIS, S. H. Branch 2 79/06/04 1p

--7908030324 Board notification incorrect weights for valves mfg by Velan Corp. Recommends that IE Bulletin 79-04 & Clemson 790409 memo to Noonan be provided to Robinson Board.
STELLO, V. Division of Operating Reactors 79/05/22 1p

--7908030329 Discusses 790402-04 trip to Velan Engineering Corp re reported weight discrepancies of swing check valves per IE Bulletin 79-04.
CLEMENSON, F. Plant Systems Branch 79/04/09 4pp

--7908030332 Discusses IE Bulletin 79-04 re incorrect Velan swing check valve weights. Requests encl bulletin be forwarded to all reactor facilities w/OL or CP.
MOSELEY, N. C. Division of Reactor Operations Inspections
79/03/30 1p

7908030232 Summarizes status of five overpressure protection & three flooding reviews evaluated by LLL in response to Eisenhut 790604 memo.
SHEMANSKI, P. Plant Systems Branch 79/06/12 2pp

--7908030256 Requests status of LLL electrical staff overpressure & flooding reviews.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 1p

7908100579 Responds to 790124 ltr & forwards request for addl info re degraded grid voltage.
SCHWENCER, A. Operating Reactors Branch 1 79/07/02 3pp.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors
79/07/18 1p

7908070305 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/19 1p

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908150368 Confirms 790720 telcon re schedule for returning reactor to svc. Concurrence based on 790709 & 20 ltrs concerning testing of anchor bolts & response to IE Bulletin 79-02.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/24 1p

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp.

7908160100 Notifies that util intends to apply accepted 10CFR50, App. A, QA program to use of radioactive matl packages. Forwards summary of applicability of portions of App E, 10CFR71.
UTLEY, E. E. Carolina Power & Light Co. 79/07/30 3pp

7908060457 Notifies that evaluation to justify unlimited purging will not be available by 790731. Requests extension to 790930.
UTLEY, E. E. Carolina Power & Light Co. 79/07/31 1p.

7908130572 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 4pp.

7908230690 Ack 770914, 790214 & 0423 ltrs changing or clarifying QA programs. Revised provisions of programs acceptable.
IPPOLITO, T. A. Operating Reactors Branch 3 79/08/01 2pp.

7908240645 Requests addl info in order to complete review of 790323 contingency plan. Requests that info identified in encl be provided. Encl withheld (ref 10CFR2.790).
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 2pp.

DOCKETED ITEMS

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned
LAINAS, G Plant Systems Branch 79/08/02 7pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning
EISENHUT, D G Division of Operating Reactors 79/08/03 53pp

790813035/ Forwards isothermal moderator temp coefficient data as suppl to 790418 request for license amend
UTLEY, E E Carolina Power & Light Co 79/08/08 3pp

7908200090 Ack receipt of 790531 application for license amend re radiological effluent Tech Specs Application not exempt from fee requirements Class III amend fee should be forwarded
MILLER, W O License Fee Management Branch 79/08/08 1p

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power
GAMMILL, W Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908270446 Approves NRC 790820 request to provide NC Governor J Hunt w/proprietary matl & technical capability matl filed in response to HR Denton 790629 request
UTLEY, E E Carolina Power & Light Co 79/08/20 1p

7908310421 Remits fee for 790531 application for license amend re radiological effluents, in response to 790808 request
FURR, B J Carolina Power & Light Co 79/08/22 2pp

9 Inspection reports, IE Bulletins & correspondence

7908170456 Forwards IE Insp Rept 50-261/79-09 on 790507-09 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/22 2pp

--7908170461 IE Insp Rept 50-261/79-09 on 790507-09 No noncompliance noted Major areas inspected hydraulic shock suppressors, battery load testing & followup of inspector-identified items
WHITENER, H L Region 2, Atlanta, Office of the Director
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/21 3pp

7908070126 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7908130295 Forwards supplemental info, in response to IE Bulletin 79-06A re transient/accident conditions, pressurizer level signal, emergency instructions, operating work permits, transfer of radioactive gases & removal of hydrogen from coolant sys
UTLEY, E E Carolina Power & Light Co 79/06/28 11pp

7908010025 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 2pp

7908180356 Responds to IE Bulletin 79-02 Describes verification, insp & testing program for pipe support base plates using concrete expansion anchor bolts Specific responses included in Ebasco Svcs final rept
UTLEY, E E Carolina Power & Light Co 79/07/09 6pp

7908230657 Forwards IE Insp Rept 50-261/79-13 on 790620-22 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 2pp

--7908230662 IE Insp Rept 50-261/79-13 on 790620-22 No noncompliance noted Major areas inspected steam generator feedwater line cracking & control rod drive mechanism weld leaks per LER 79-11
CROWLEY, B R , HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 5pp

7908180142 Supplements 790424 & 0628 responses to IE Bulletin 79-06A Addl info provided re review of operating procedures, methods of shift turnover & valve lineup review
UTLEY, E E Carolina Power & Light Co 79/07/12 4pp

7908030105 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/13 2pp

7908010401 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/17 2pp

7908200258 Responds to IE Bulletin 79-13 Cracks found in feedwater reducers were reported in 790710 ltr Weld joints radiographed & analyzed Emergency procedures for feedwater line break revised Remaining info will be forwarded
UTLEY, E E Florida Power Corp 79/07/17 3pp

7908020552 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/18 2pp

7908130045 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/18 2pp

7908130095 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/18 2pp

7908220031 Confirms 790719 telcon re requirements for testing anchor bolts on safety-related sys per IE Bulletin 79-02 Plant will not return to power w/o concurrence of NRC, based on results of testing program
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/19 1p

7908090412 Forwards supplemental response to IE Bulletin 79-02 re numerical data & plant operability & safety Numerical data accumulated during insp program is accurate Plant is safe for continued escalation to power operation
FURR, B J Carolina Power & Light Co 79/07/20 5pp

7908070124 Ack receipt of 790712 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/79-10
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/23 1p

--7908070133 Responds to NRC 790620 ltr re violations noted in IE Insp Rept 50-261/79-10 Corrective actions, calibr data for each instrument is reviewed by technician doing actual calibr, by foreman accepting work & by QA personnel
FURR, B J Carolina Power & Light Co 79/07/12 2pp

--7908070139 Forwards IE Insp Rept 50-261/79-10 on 790521-25 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/20 2pp

--7908070145 Notice of violation from insp on 790521-25
* Region 2, Atlanta, Office of the Director 79/06/20 1p

--7908070155 IE Insp Rept 50-261/79-10 on 790521-25 Noncompliance noted failure to calibr safety-related instruments
MESSITT, B R , FORD, E J Region 2, Atlanta, Office of the Director RUHLMAN, W A Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/20 6pp

7908230585 Responds to IE Bulletin 79-13 re insp of feedwater sys piping Lines were inspected & corrective actions documented in 790710 ltr Response to Item 5 of IE Bulletin 79-13 documented in 790718 ltr
FURR, B J Carolina Power & Light Co 79/07/24 1p

7908070727 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/26 2pp

7908080645 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/26 1p

7908080704 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/26 2pp

7908160201 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/07/27 2pp.

7908170062 Submits response to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys verification program. Forwards design documents which identify seismic input info.
FURR, B.J. Carolina Power & Light Co. 79/08/02 13pp.

7908160369 Responds to IE Bulletin 78-12B re atypical weld matl in reactor pressure vessel welds. Provides refs to relevant matl in NRC possession.
FURR, B.J. Carolina Power & Light Co. 79/08/03 2pp.

7908160134 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/07 2pp.

7908170009 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/08 2pp.

7908210428 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/08 1p.

7908290187 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/10 2pp.

7908280414 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B.H. Region 2, Atlanta, Office of the Director 79/08/13 2pp.

R Periodic operating reports & related correspondence

7908200359 Forwards monthly operating rept for Jul 1979.
BANKS, H.R. Carolina Power & Light Co. 79/08/10 1p.

--7908200360 Monthly operating rept for Jul 1979.
WATFORD, M.L. Carolina Power & Light Co. 79/08/02 3pp.

S Reportable occurrences, LERs & related correspondence

7908060335 Responds to 790525 ltr re info on PWR feedwater lines. Summary of info re cracks discovered in feedwater reducers forwarded 790710.
UTLEY, E.E. Carolina Power & Light Co. 79/07/30 14pp.

7908210419 Forwards LER 79-011/01X-1.
BANKS, H.R. Carolina Power & Light Co. 79/08/15 1p.

--7908210422 LER 79-011/01X-1 on 790426 pinhole leaks found on four canopy seal welds at locations K6, L5, M6 & N7. Possibly caused by weld degradation in places where min amount of filler metal may have been deposited. Defects repaired.
STARKEY, R.B. Carolina Power & Light Co. 79/08/15 3pp.

7908290436 Forwards LER 79-025/03L-0.
BANKS, H.R. Carolina Power & Light Co. 79/08/23 1p.

--7908290449 LER 79-025/03L-0 on 790730 during period when fire detection sys was inoperable on 790730, hourly fire patrols were not performed. Caused by day patrol not reporting to work & night shift leaving. Day shift worker being replaced.
STARKEY, R.B. Carolina Power & Light Co. 79/08/23 2pp.

7908300655 Forwards LER 79-024/03L-0.
BANKS, H.R. Carolina Power & Light Co. 79/08/23 1p.

--7908300663 LER 79-024/03L-0 on 790724 hourly fire patrols not performed as required for 8-h period. Caused by failure of fire patrol shift to report for duty & failure of previous shift patrol to notify supervisors prior to leaving duty.
STARKEY, R.B. Carolina Power & Light Co. 79/08/23 2pp.

DOCKET 50-262 BRIGHAM YOUNG UNIV. RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7908010008 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/07/06 1p.

7908160059 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/08/10 1p.

S Reportable occurrences, LERs & related correspondence

7908060534 Forwards LER 79-012/03L-0.
MAYER, L.O. Northern States Power Co. 79/08/01 1p.

--7908060541 LER 79-012/03L-0 on 790702 during reactor core isolation cooling sys test, governor end-bearing temp alarm received & bearing exhibited high vibration. Sys inoperative. Caused by turbine oil pump drive gear failure. Gears replaced.
HAMMER, S.J. Northern States Power Co. 79/08/01 1p.

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

7908130200 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch 79/07/03 1p.

7908010584 Forwards appropriate licensing fee for safeguards contingency plan, in response to 790703 request.
MAYER, L.O. Northern States Power Co. 79/07/20 4pp.

7908230316 Forwards security force training & qualification plan. Plan withheld (ref 10CFR2.790).
MAYER, L.O. Northern States Power Co. 79/08/17 1p.

7908280555 Forwards appropriate licensing fee for NRC review & approval of util 790817 security force training & qualification plans.
MAYER, L.O. Northern States Power Co. 79/08/23 3pp.

G Adjudicatory correspondence

7906060188 Forwards 790316 memo re Board notification on nonsafety-grade equipment to mitigate transients.
LEWIS, S.H. Branch 2 79/04/18 1p.

--7906060192 Sys design criteria must be established to judge reliability of nonsafety-grade equipment used to mitigate transients per general design criteria 29. More info is needed for further study. Boards should be notified.
TEDESCO, R.L. Assistant Director for Plant Systems 79/03/16 3pp.

H General correspondence

7908210319 Forwards "Mgt & Technical Resources, Jul 1979," per NRC 790629 info request re util ability to handle emergency situations financially.
MAYER, L.O. Northern States Power Co. 79/08/10 1p.

--7908210321 "Mgt & Technical Resources, Jul 1979."
* Northern States Power Co. 79/08/31 225pp.

P Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards 79/03/22 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors 79/06/04 52pp.

DOCKETED ITEMS

7908150335 Intends to ship radioactive matl from facilities using Package PB-1.
MAYER, L. O. Northern States Power Co. 79/06/08. 1p.

7908300194 Ack receipt of 780424 licensee submittal. Forwards request for addl info re degraded grid voltage (request TAC 10034).
LAINAS, G. Plant Systems Branch. 79/06/13. 3pp.

7908060179 Discusses review of util 790421 submittal re degraded voltage protection. Requests addl info by 790915.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 79/06/18. 3pp.

7908130402 Notifies of intent to ship radioactive matl using certified shipping package Model 7-100.
MAYER, L. O. Northern States Power Co. 79/06/19. 1p.

7908070674 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/22. 3pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908020208 Responds to 790612 ltr. Disagrees w/acceptability of proposed use of bioassay measurements to show that individual intake of radioactive matl is less than that initially estimated from air samples.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/02. 2pp.

--7908020214 Advises of intended methods of providing personnel respiratory protection & determining personnel exposure to airborne radioactive matls during resurfacing of condensate storage tanks. Program expected to begin 790702.
WACHTER, L. J. Northern States Power Co. 79/06/12. 2pp.

7908140309 Notifies of intent to ship radioactive matl in Model GE-600.
MAYER, L. O. Northern States Power Co. 79/07/05. 1p.

7908130306 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill; if drill scenario requires initial notification of NRC.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/09. 1p.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070343 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/19. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908170149 Notification of 790731 meeting w/MN Pollution Control Agency & Northern States Power Co in Minneapolis, MN to discuss ETS.
KEBLUSEK, S. Environmental Projects Branch 2. 79/07/24. 1p.

7908080455 Confirms delay until 790813 to respond to 790629 request & WP Haass ltr re info on mgt & technical resources available to licensees for response to nuclear plant emergencies.
MAYER, L. O. Northern States Power Co. 79/08/02. 1p.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

Q. Inspection reports, IE Bulletins & correspondence

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 79/06/20. 44pp.

7908070370 Responds to IE Bulletin 79-02, Revision 1. Anchor bolt loads in Seismic Category I sys were recalculated by Bechtel using method which accounts for base plate flexibility.
WACHTER, L. J. Northern States Power Co. 79/07/06. 4pp.

7908100160 Responds to IE Bulletin 79-11. Westinghouse Type DB-75 & DB-50 circuit breakers not used in safety-related Class 1E svc or spares.
WACHTER, L. J. Northern States Power Co. 79/07/06. 1p.

7908020342 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908080327 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/20. 4pp.

7908290370 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300419 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908070482 Forwards Revision 4 of "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Section XI Requirements."
MAYER, L. O. Northern States Power Co. 79/07/27. 2pp.

--7908030489 Revision 4 of "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements."
* Northern States Power Co. 79/07/27. 7pp.

7908240628 Responds to IE Bulletin 79-12. Operating procedures require estimate of critical rod pattern prior to each criticality. All rod withdrawal sequences are analyzed using three-dimensional BWR simulator.
WACHTER, L. J. Northern States Power Co. 79/07/30. 2pp.

7908130439 Forwards revised response to IE Bulletin 79-08, containing addl info requested 780720.
MAYER, L. O. Northern States Power Co. 79/08/07. 1p.

--7908130444 Responds to request for addl info re IE Bulletin 79-08. Personnel w/operational responsibilities have reviewed TMI-2 event. Discusses initial core cooling, containment cooling & extended core cooling.
WACHTER, L. J. Northern States Power Co. 79/08/07. 15pp.

7908150371 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908220227 Forwards addl info in response to IE Bulletin 79-08.
MAYER, L. O. Northern States Power Co. 79/08/07. 1p.

--7908220243 Submits info in response to Items 1-10 of IE Bulletin 79-08 & TA Ippolito 790720 request for addl info. Discusses initial core cooling, containment cooling & extended core cooling.
WACHTER, L. J. Northern States Power Co. 79/08/07. 15pp.

7908170024 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08. 1p.

7908300290 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

7908270463 Forwards revised page for Attachment 1 of response to IE Bulletin 79-01.
WACHTER, L. J. Northern States Power Co. 79/08/21. 2pp.

R. Periodic operating reports & related correspondence

7908010554 Forwards "1978 Environ Monitoring & Ecological Studies Program Rept."
WARD, E. C. Northern States Power Co. 79/07/27. 1p.

--7908010560 "1978 Environ Monitoring & Ecological Studies Program Rept."
* Northern States Power Co. 79/07/27. 89pp.

7908140766 Forwards monthly operating rept for Jul 1979.
MAYER, L. O. Northern States Power Co. 79/08/08. 1p.

--7908140769 Monthly operating rept for Jul 1979.
MYRABO, A. L. Northern States Power Co. 79/08/02. 4pp.

7908310544 Forwards "Effluent & Waste Disposal Semiannual Rept." for Jan-June 1979.
MAYER, L. O. Northern States Power Co. 79/08/29. 1p.

--7908310549 "Effluent & Waste Disposal Semiannual Rept." for Jan-June 1979.
* Northern States Power Co. 79/08/29. 13pp.

S. Reportable occurrences: LERs & related correspondence

7908090560 Forwards LER 79-014/03L-0.
MAYER, L. O. Northern States Power Co. 79/08/06. 1p.

--7908090565 LER 79-014/03L-0 on 790709 water leak discovered in 1/2 inch instrument line from reactor water cleanup sys nonregenerative heat exchanger. Cause not determined. Leaking line isolated & will be further investigated & repaired.
NOLAN, L. L. Northern States Power Co. 79/08/06. 1p.

7908100429 Forwards LER 79-013/03L-0.
MAYER, L. O. Northern States Power Co. 79/08/07. 1p.

--7908100435 LER 79-013/03L-0 on 790708 motor operator failed, rendering torus cooling injection valve inoperable during normal operation. Caused by failure of motor winding due to limit switch not de-energizing motor. Switch replaced.
OVERLID, T. W. Northern States Power Co. 79/08/07. 1p.

7908140775 Forwards LER 79-015/03L-0.
MAYER, L. O. Northern States Power Co. 79/08/10. 1p.

--7908140783 LER 79-0[illegible]/03L-0 on 790712 discovered steam leak from intermediate press... feedwater heater. Cause undetermined. Temporary patch installed pending replacement of heater shell.
HAMMER, S. J. Northern States Power Co. 79/08/10. 1p.

7908240508 Forwards LER 79-016/03L-0.
MAYER, L. O. Northern States Power Co. 79/08/21. 1p.

--7908240511 LER 79-016/03L-0 on 790731 turbine tripped on low oil pressure. Caused by clogged lube oil filter. Sys drained, inspected & flushed.
OVERLID, T. W. Northern States Power Co. 79/08/21. 1p.

DOCKET 50-264 DOW CHEMICAL CO.

F. Security: medical, emergency & fire protection plans

7908140219 Forwards Amend 4 to License R-108.
REID, R. W. Operating Reactors Branch 4. 79/06/28. 2pp.

--7908140231 Amend 4 to License R-108. Details of revision to security plan withheld (ref 10CFR2.790).
REID, R. W. Operating Reactors Branch 4. 79/06/28. 2pp.

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908080719 Confirms that meeting at util corporate office has been rescheduled for 790719 at 3 PM. Location, purpose & attendees discussed in NRC 790612 ltr.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/10. 1p.

F. Security: medical, emergency & fire protection plans

7908130162 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908160367 Forwards request for addl info re contingency plans. Encl withheld (ref 10CFR2.790).
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 2pp.

7908200335 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/08/16. 1p.

G. Adjudicatory correspondence

7908280266 Responds to 790514 ltr opposing authorization for increase in spent fuel storage capacity. No application from util filed. Util request to allow storage of spent fuel in spent fuel pools at either site currently under review.
EISENHUT, D. G. Division of Operating Reactors. 79/07/31. 1p.

7908200035 Responds to 790510 ltr opposing transportation of spent fuel. Public hearing will be held on shipment in Fall 1979.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908200039 Responds to 790507 post card expressing opposition to transportation of spent fuel. Public hearing on proposed shipment will be held Fall 1979.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908290108 Responds to 790502 & 12 ltrs re hearing on spent fuel transfer. Hearing will be held no earlier than Sept 1979.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

H. General correspondence

7908210445 Responds to 790522 ltr opposing moving of spent fuels between stations. Discusses concerns expressed re proposed high density fuel storage.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 1p.

7908210453 Responds to 790430 ltr & recent telcons. Notice will be made re time & place of hearings on spent fuel transfer between stations. Discusses rules re shipment of spent fuel.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/03. 2pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908070652 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/22. 3pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908130310 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires NRC initial notification.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/09. 1p.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves w/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908100124 Supports util 780202 request for ETS changes, eliminating 2 F per hour temp change limit during changes in mode of condenser cooling. EIA endorsing proposed changes encl.
LEAR, G. Environmental Specialists Branch. 79/07/16. 1p.

--7908100140 EIA supporting proposed ETS change to eliminate 2 F per hour temp change requirement in mode of condenser cooling.
* Environmental Specialists Branch. 79/07/16. 2pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070332 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/19. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908170602 Forwards Amends 52 & 49 to Licenses DPR-29 & DPR-30, respectively, safety evaluation & notice of issuance & availability.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/27. 3pp.

--7908170604 Amends 52 & 49 to Licenses DPR-29 & DPR-30, respectively, adding license conditions re completion of facility mods & implementing administrative controls for fire protection.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/27. 4pp.

--7908170608 Fire protection safety evaluation supporting Amends 52 & 49 to Licenses DPR-29 & DPR-30, respectively.
* Office of Nuclear Reactor Regulation. 79/07/27. 54pp.

--7908170611 Notice of issuance & availability of Amends 52 & 49 to Licenses DPR-29 & DPR-30, respectively.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/27. 2pp.

7908020460 Submits schedule for addl response to NRC issues re containment purging during normal plant operation.
REED, C. Commonwealth Edison Co. 79/07/30. 2pp.

7908070617 Notifies that average release rate of radioiodine & radioactive matls in particulate form, w/half-lives greater that 8 days, exceeded Tech Spec limits.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/07/30. 8pp.

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co. 79/07/30. 2pp.

7908100440 Advises that review of Amend 49 to License DPR-30 disclosed discrepancy in paragraph numbers. Submits info to correct discrepancy.
REED, C. Commonwealth Edison Co. 79/08/03. 1p.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 5pp.

7908200380 Forwards info requested in NRC 790629 & 0724 ltrs re capabilities & technical resources available to handle unusual events.
JANECEK, R. F. Commonwealth Edison Co. 79/08/13. 1100pp.

7908230420 Informs that BWR operating plant owners group GE rept, NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs" was submitted to NRC by 790817 ltr from RD Keenan to D Ross. Remainder of info follows in 791116 rept.
JANECEK, R. F. Commonwealth Edison Co. 79/08/20. 1p.

G. Inspection reports, IE Bulletins & correspondence

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 79/06/20. 44pp.

7908150364 Forwards IE Insp Repts 50-254/79-14 & 50-265/79-12 on 790530. No noncompliance noted.
DAVIS, A. B. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/29. 2pp.

--7908150375 IE Insp Repts 50-254/79-14 & 50-265/79-12 on 790530. No noncompliance noted. Major areas inspected: response during scheduled drill conducted by util emergency medical contractor.
JANUSKA, A. G., GEER, R. J., ESSIG, T. H. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/28. 4pp.

7908080523 Responds to IE Bulletin 79-11. No Westinghouse DB-50 & DB-75 circuit breakers used in safety-related sys.
REED, C. Commonwealth Edison Co. 79/07/02. 1p.

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co. 79/07/05. 9pp.

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc. 79/05/31. 24pp.

7908150349 Supplements response to IE Bulletin 79-11 Westinghouse DB-50 & DB-75 circuit breakers are neither used in safety-related sys nor stored as spares at facilities.
REED, C. Commonwealth Edison Co. 79/07/12. 2pp.

7908080306 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/20. 4pp.

7908060225 Forwards "Inservice Insp & Testing Program" & color-coded piping & instrument diagrams.
JANECEK, R. F. Commonwealth Edison Co. 79/07/25. 1p.

--7908060231 "Inservice Insp & Testing Program."
* Commonwealth Edison Co. 79/07/18. 200pp.

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908240513 Responds to IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." Procedures involving reactor criticality, control rod withdrawal sequences & operator training program were modified in 1977.
REED, C. Commonwealth Edison Co. 79/07/30. 9pp.

7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED, C. Commonwealth Edison Co. 79/08/01. 2pp.

7908080530 Forwards addl info re responses to IE Bulletin 79-08 per 790720 request.
REED, C. Commonwealth Edison Co. 79/08/03. 6pp.

7908170019 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/08/08 1p.

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/08/15 1p.

R Periodic operating reports & related correspondence

7908230431 Forwards monthly operating rept for Jul 1979.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/08/06 1p.

--7908230439 Monthly operating rept for Jul 1979.
* Commonwealth Edison Co. 79/08/06 24pp.

7908280570 Forwards semiannual rept re radioactive effluent discharge & solid radioactive waste.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/08/21 1p.

--7908280573 Semiannual rept re radioactive effluent discharges & solid radioactive waste, Jan-June 1979.
* Commonwealth Edison Co. 79/08/21 20pp.

S Reportable occurrences, LERs & related correspondence

7908140604 Forwards LER 79-014/03L-0.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/08/01 1p.

--7908140612 LER 79-014/03L-0 on 790723 steam inlet valve MO 2-1301-16 failed to close during reactor core isolation cooling monthly valve operability test. Caused by component failure of torque switch on valve MO 2-1301-16. Switch replaced.
LEECH, K. Commonwealth Edison Co. 79/08/01 3pp.

7908140582 Forwards LER 79-013/03L-0.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/08/03 1p.

-- 9140588 LER 79-013/03L-0 on 790712 while performing motor operated ive operability test thermal overload relay for pump ction valve 1C RHR tripped & could not be reopened. Caused by loose electrical connections at breaker.
HOELLER, J. Commonwealth Edison Co. 79/08/03 1p.

7908140623 Forwards LER 79-015/01T-0.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/08/03 1p.

--7908140628 LER 79-015/01T-0 on 790724 pressure switches PS2-1622A & PS2-1622B were found to actuate less conservatively than Tech Specs required. Caused by ... rument setpoint drift. Instruments recalibr.
TIETZ, G. Commonwealth Edison Co. 79/08/03 2pp.

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

7908130119 Forwards "Evaluation of Min Fire Brigade Shift Size." Min size should be five persons.
LAINAS, G. Plant Systems Branch. 79/06/28 2pp.

--7908130122 "Evaluation of Min Fire Brigade Shift Size."
* Plant Systems Branch. 79/06/08 32pp.

7908130222 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plan should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch. 79/07/03 2pp.

7908020437 Forwards amended additions to modified amended physical security plan & contingency plan. Plan withheld (ref 10CFR2.790).
BURSTEIN, S. Wisconsin Electric Power Co. 79/08/01 1p.

7908290411 Forwards training & qualification plan. Plan withheld (ref 10CFR2.790.)
BURSTEIN, S. Wisconsin Electric Power Co. 79/08/21 1p.

H General correspondence

7908150084 Ack receipt of correspondence re status of spent fuel storage at six operating facilities near Lake MI. Responds to 790429 ltr.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/07/26 2pp.

--7908150107 Discusses spent fuel storage capability at Big Rock Point. NUREG-0020 indicates authorized capacity of 120 spent fuel assemblies, while DOE indicates capacity of 365. Requests clarification.
SCHAEFER, J. Lake Michigan Federation. 79/05/20 1p.

--7908150125 Ack receipt of info re nuclear p[lant]s near Lake MI. Forwards rept re status of spent fuel sto[rage] at plants. Requests comments re rept.
SCHAEFER, J. Lake Michigan Federation. 79/06/21 1p.

--7908150139 "Status of Spent Fuel Storage at the Six Nuclear Plants Located on Shore of Lake MI."
SCHAEFER, J. Lake Michigan Federation. 79/05/31 20pp.

7908020423 Requests extension of time beyond 790730 response date to supply info re capability of mgt & technical staffs to react to accident of TMI type. One copy will be submitted due to proprietary nature of data.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/30 1p.

P Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors. 79/06/04 52pp.

7908030232 Summarizes status of five overpressure protection & three flooding reviews evaluated by LLL in response to Eisenhut 790604 memo.
SHEMANSKI, P. Plant Systems Branch. 79/06/12 2pp.

--7908030256 Requests status of LLL electrical staff overpressure & flooding reviews.
EISENHUT, D.G. Division of Operating Reactors. 79/06/04 1p.

7908010270 Corrects 790511 ltr re ref to Amend 42 to License DPR-27. Ltr should have referred to Amend 43.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/06/18 2pp.

7908160561 Responds to 770314 ltr re analysis of radiological consequences of postulated fuel handling accident inside containment. Potential consequences within exposure guidelines of 10CFR100. Safety evaluation encl.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/06/20 2pp.

--7908160566 Safety evaluation re fuel handling accident inside containment. Radiological consequences to person located at exclusion area boundary are within dosage guideline values of 10CFR100.
* Office of Nuclear Reactor Regulation. 79/06/20 4pp.

7908060542 Forwards request for addl info re proposed changes to nonradiological ETS. Requests response within 60 days.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/06/22 5pp.

7908070679 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/06/22 3pp.

7908020285 Discusses util 770728 ltr re degraded grid voltage generic issues. Forwards request for addl info re trip setpoint time delay, voltage monitor verification of IEEE requirements & channel functional tests.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/07/03 3pp.

7908100534 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill; if drill scenario requires initial notification of NRC.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/09 1p.

7908150547 Requests registration as user of Model LL-50-100.
FAY, C.W. Wisconsin Electric Power Co. 79/07/16 1p.

DOCKETED ITEMS

7908060070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W.P. Assistant Director for Standard & Advanced Reactors. 79/07/18 1p

7908070347 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/19 1p

7908200138 Responds to 790409 request re evacuation plans in event of radiation problem. Forwards NUREG-0396 & Reg Guide 1.101 w/o encl.
KNIGHTON, G.W. Environmental Evaluation Branch 79/07/19 1p

7908010383 Requests that WCAP-9600, "Rept on Small Break Accidents for Westinghouse NSSS Sys" be included in dockets.
FAY, C.W. Wisconsin Electric Power Co 79/07/23 1p

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W.P. Quality Assurance Branch 79/07/24 1p

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE Bulletins which apply to Westinghouse-designed plants.
O'REILLY, J.P. Standardization Branch 79/07/30 64pp

7908130584 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 4pp

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp

7908140687 Discusses procedures & plans re Cycle 8 startup expected to commence 791102. Results of startup physics rod worth measurements will be submitted within 45 days following verification of shutdown margin.
FAY, C.W. Wisconsin Electric Power Co 79/08/03 2pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D.G. Division of Operating Reactors 79/08/03 53pp

7908200326 Describes re-evaluation of potential steam generator water hammer. Forwards table of operating experience & feedwater piping configurations. Water hammer not likely to occur under any conditions.
DEARIEN, J.A. EG & G, Inc. 79/08/06 3pp

7908290561 Requests clarification of fee classification for radiation protection manager qualification Tech Spec changes.
MILLER, W.O. License Fee Management Branch 79/08/07 2pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908140760 Appreciates prompt approval of request to purge containment. Approval reduced personnel inconvenience & man-rem exposure. Will pursue review of containment purge sys.
BURSTEIN, S. Wisconsin Electric Power Co 79/08/10 1p

7908270473 Responds to NRC 790622 request for additional info re changes to nonradiological environ surveillance program for facility.
BURSTEIN, S. Wisconsin Electric Power Co 79/08/22 18pp

G Inspection reports, IE Bulletins & correspondence

7908060537 Forwards addl info in response to IE Bulletin 79-04 in light of Velan check valve reanalysis. Mods to piping sys or pipe supports not required. All pipe support loads less than max specified by design.
BURSTEIN, S. Wisconsin Electric Power Co 79/05/25 3pp

7908150225 Forwards IE Insp Repts 50-266/79-08 & 50-301/79-10 on 790612-14. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/25 2pp

--7908150232 IE Insp Repts 50-266/79-08 & 50-301/79-10 on 790612-14. No noncompliance noted. Major areas inspected: followup on IE Bulletin 79-02, pipe support base plate designs using concrete expansion bolts & review of test program.
GALLAGHER, E.J., HAYES, D.W. Region 3, Chicago, Office of the Director 79/06/21 5pp

7908080553 Responds to IE Bulletin 79-11 re Westinghouse Type DB-50 & DB-75 breakers in safety-related sys. Review of tests & calibr records indicates no recent failures. Problem & corrective action explained in 14R 79-004/01T-0.
FAY, C.W. Wisconsin Electric Power Co 79/06/29 2pp

7908150230 Discusses 781026 response to IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessel Welds," & modified requirements in IE Bulletins 78-12A & 12B Certification, Westinghouse 790625 ltr & C-E 790605 ltr encl.
BURSTEIN, S. Wisconsin Electric Power Co 79/07/06 6pp

7908090416 Responds to IE Bulletin 79-13 re radiographic examinations of feedwater nozzle-to-piping welds & adjacent pipe & nozzle areas. Unit 2 feedline welds are being repaired. Unit 1 will be inspected during fall refueling outage.
BURSTEIN, S. Wisconsin Electric Power Co 79/07/12 48pp

7908020359 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/20 1p

7908290309 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908290377 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908300437 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908080473 Responds to IE Bulletin 79-14, "Seismic Analyses for As-Built Safety Related Piping Systems." All acceptable piping will be inspected as soon as practicable & Unit 1 containment will be inspected during Fall 1979 refueling.
BURSTEIN, S. Wisconsin Electric Power Co 79/08/01 36pp

7908210329 Forwards request for addl info, in response to IE Bulletins 79-06A & 79-06A Revision 1 Needed info includes review completion date, containment isolation procedures & procedures controlling manipulation of safety valves.
SCHWENCER, A. Operating Reactors Branch 1 79/08/03 4pp

7908150398 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/08/07 1p

7908300789 Determines that reanalysis of safety-related piping lines affected by IE Bulletin 79-07 has been performed w/acceptable computer program which does not use algebraic summation & that results are acceptable.
SCHWENCER, A. Operating Reactors Branch 1 79/08/07 2pp

7908170027 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/08/08 1p

7908300307 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/08/15 1p

7908300740 Responds to NRC 790803 ltr requesting addl info re IE Bulletins 79-06A & 79-06A Revision 1. Summary of owners group review of emergency procedures & intended procedural revisions will be submitted by 791231.
FAY, C.W. Wisconsin Electric Power Co 79/08/23 11pp

R Periodic operating reports & related correspondence

7908140401 Forwards monthly operating rept for Jul 1979.
BURSTEIN,S Wisconsin Electric Power Co 79/08/09 1p

--7908140409 Monthly operating rept for Jul 1979.
* Wisconsin Electric Power Co 79/08/03 8pp

7908160448 Forwards monthly operating rept for Jul 1979.
BURSTEIN,S Wisconsin Electric Power Co 79/08/09 1p

S Reportable occurrences, LERs & related correspondence

7908270420 Discusses LER 79-012/01T-0 re steam generator tube deterioration from caustic corrision in tubesheet crevice. Matter is of low safety importance. Investigation continues re deep crevice corrosion phenomena.
BURSTEIN,S Wisconsin Electric Power Co 79/08/20 1p

--7908270427 Forwards LER 79-012/01T-0.
FAY,C W Wisconsin Electric Power Co 79/08/15 1p

--7908270434 LER 79-012/01T-0 on 790805 primary to secondary leak noted in steam generator A Caused by defective tubes in steam generators A & B Leaking & defective tubes plugged.
FAY,C W Wisconsin Electric Power Co 79/08/15 7pp

DOCKET 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

7908240499 Forwards draft App B to physical security plan. Plan withheld (ref 10CFR2.790).
WAREMBOURG,D Public Service Co of Colorado 79/08/17 1p

P Operating license stage documents & correspondence

7908020385 Ack telcons re 790615 shutdown due to expiration of 790525 extension of temporary relief from Limiting Condition of Operation 4.3.10. Grants addl temporary relief until 790623 to clean up primary coolant sys.
GAMMILL,W P Assistant Director for Standard & Advanced Reactors 79/06/20 1p

7908210050 Requests registration as user of Model FSV-1.
FULLER,J K Public Service Co of Colorado 79/06/27 2pp

7908070359 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/07/18 1p

7908010448 Forwards list of outstanding ltrs & requests for Tech Spec changes.
WAREMBOURG,D Public Service Co of Colorado 79/07/24 3pp

7908010480 Discusses indications of higher-than-expected failure rate of outer pyrolytic carbon fuel particle coating. Fuel particle microporosity does not create substantial safety hazard. Supporting documentation encl.
SWART,F E Public Service Co of Colorado 79/07/24 72pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS,W P Quality Assurance Branch 79/07/24 1p

7908010501 Requests specific licensing approval to use grade H-451 graphite in fuel & reflector elements in selected regions of reload Segment 9 & to use grade H-451 graphite in all regions of subsequent reload segments by 791001.
FULLER,J K Public Service Co of Colorado 79/07/25 1p

7908140597 Updates status of installation of security sys hardware. Vikonics equipment repaired & reinstalled. Testing in progress. Until sys is fully operable, compensatory measures extended.
WAREMBOURG,D Public Service Co of Colorado 79/08/03 1p

7908140599 Ack receipt of ltr requesting info re mgt & technical resources available to handle unusual events of type experienced by TMI-2. Currently finalizing emergency response plan. Requests response delay until 791001.
WAREMBOURG,D Public Service Co of Colorado 79/08/10 1p

7908200381 Forwards proposed amend to Tech Specs for License DPR-34.
MILLEN,C K Public Service Co of Colorado 79/08/13 3pp

--7908200388 Application to amend App A of License DPR-34, proposing Tech Spec amend re fire protection sys.
* Public Service Co of Colorado 79/08/13 31pp

7708220296 Forwards revised test rept RT-500F incorporating changes to fluctuation tests discussed during 790813 site visit. Responses to NRC questions encl.
WAREMBOURG,D Public Service Co of Colorado 79/08/20 25pp

7908310404 Forwards list of outstanding ltrs & requests for Tech Specs changes. Some items will be included in Amend 22.
WAREMBOURG,D Public Service Co of Colorado 79/08/22 4pp

7908310458 Forwards for review progress repts on inservice insp & testing program review conducted per Tech Specs surveillance requirements. NRC concurrence on proposed methodology requested by 790915.
FULLER,J K Public Service Co of Colorado 79/08/28 2pp

--7908310464 "Progress Rept on Program to Review Facility Inservice Insp & Testing - Preliminary Development Phase."
* Public Service Co of Colorado 79/08/28 56pp

G Inspection reports, IE Bulletins & correspondence

7908010066 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Summation methods listed were used in computer design programs.
SWART,F E Public Service Co of Colorado 79/05/15 2pp

7908080399 Responds to IE Bulletin 79-11. Circuit breakers described in bulletin not used or carried as spares.
MILLEN,C K Public Service Co of Colorado 79/06/01 1p

7908080470 Responds to IE Bulletin 79-01. Forwards list of documents previously submitted to NRC re environmental qualification program & environ qualifications of connectors, penetrations, terminal blocks & limit switches.
FULLER,J K Public Service Co of Colorado 79/06/12 2pp

7908300060 Forwards IE Insp Rept 50-267/79-12 on 790612-15 & notice of violation.
MADSEN,G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/29 2pp

--7908300064 Notice of violation from insp on 790612-15.
* Region 4, Dallas, Office of the Director 79/06/29 1p

--7908300069 IE Insp Rept 50-267/79-12 on 790612-15. Noncompliance noted: failure to comply w/Tech Specs requirements re operating procedures.
DICKERSON,M W ; WESTERMAN,F F Region 4, Dallas, Office of the Director 79/06/28 6pp

7908140199 Responds to IE Bulletins 79-02 & 02, Revision 1. No problem exists w/design or installation of concrete expansion anchors.
SWART,F E Public Service Co of Colorado 79/07/03 2pp

7908010005 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/07/06 1p

7908010667 Forwards IE Insp Rept 50-267/79-11 on 790521-25. Notice of violation withheld (ref 10CFR2.790).
MADSEN,G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/10 2pp

--7908010679 IE Insp Rept 50-267/79-11 on 790521-25. Noncompliance noted: untrained persons used as watchmen, security records maintained offsite & physical access to reactor not positively controlled. Details withheld(ref 10CFR 2.790).
CALDWELL,R A ; EVANS,C A ; MADSEN,G L Region 4, Dallas, Office of the Director 79/07/05 2pp

7908020400 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/07/18 1p

7908060045 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/07/26 1p

7908060131 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/26 1p

7908080465 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-related Piping Sys." Major insp elements to be used are contained in seismic & gravity load piping isometrics for each sys & Ielco-Grinnell drawings.
PILANT,J.M. Nebraska Public Power District 79/08/01 48pp

7908080491 Responds to IE Bulletin 79-14 Forwards justifying documentation, pipe support & restraint review log & typical ASME Section 3 & ANSI B31.1 sheets verifying that seismic analysis applies to safety-related sys.
TRIMBLE,D.C. Arkansas Power & Light Co 79/08/01 62pp

7908160054 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/10 1p

R Periodic operating reports & related correspondence

7908130430 Forwards "Semiannual Effluent Release Rept." for 790101-0630.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/03 3pp

--7908130432 "Semiannual Effluent Release Rept." For 790101-0630
* Public Service Co. of Colorado 79/08/01 36pp.

7908140499 Forwards monthly operating rept for Jul 1979.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/09 1p

--7908140504 Monthly operating rept for Jul 1979.
GAHM,J.W. Public Service Co. of Colorado 79/08/01 6pp

7908160337 Forwards monthly operating rept for June 1979.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/10 1p

--7908160345 Monthly operating rept for June 1979.
GAHM,J.W. Public Service Co. of Colorado 79/07/01 8pp

7908290605 Forwards progress rept prepared by Thorne Ecological Inst. for ecological monitoring program for period 790101-0630.
SWART,F.E. Public Service Co. of Colorado 79/08/22 1p

--7908290616 Progress rept for ecological monitoring program for period 790101-0630, prepared for Public Svc Co of Co.
GLOVER,F.A.; ALEXANDER,D.R.; HOLMES,M.H. Thorne Ecological Institute 79/06/30 119pp

S Reportable occurrences, LERs & related correspondence

7908080442 Responds to 790508 ltr re shock suppressors installed at facility. Approves request for time to ascertain nature of problems w/suppressors prior to submitting RO.
MADSEN,G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/04 1p

--7908080445 Requests time to ascertain nature of problem re shock suppressors, prior to submitting RO.
WAREMBOURG,D. Public Service Co. of Colorado 79/05/09 1p

7908010705 Forwards PNO-79-67AX.
MADSEN,G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/20 1p

7908070500 Forwards LER 79-018/03L-0.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/01 3pp

--7908070518 LER 79-018/03L-0 on 790630 one motor-operated butterfly valve found inoperable by remote manual control. Cause is unknown. Cause & corrective action to be reported in future suppl.
GAHM,J.W. Public Service Co. of Colorado 79/07/30 1p

7908070684 Forwards LER 79-019/03L-0.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/01 1p

--7908070686 LER 79-019/03L-0 on 790711 during normal operation, weekly functional test of area radiation monitors not performed for 1 wk. Caused by misfiling of card for surveillance test. Computer readout will be used as cross check on card sys.
GAHM,J.W. Public Service Co. of Colorado 79/08/01 3pp.

7908310328 Forwards LER 79-021/03L-0.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/10 4pp.

--7908310331 LER 79-021/03L-1 on 790720 during review of surveillance tests, discovered that Halon fire suppression sys surveillance test for second quarter not performed. Caused by inadequate control & direction re refueling work load.
GAHM,J.W. Public Service Co. of Colorado 79/08/10 1p.

7908310347 Forwards LER 79-020/03L-0.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/10 1p.

--7908310353 LER 79-020/03L-0 on 790717 during normal plant operation, engine failed to start. Caused by failure of emergency diesel temp switch C. Switch replaced.
GAHM,J.W. Public Service Co. of Colorado 79/08/10 3pp.

7908200392 Fowards LER 78-027/03X-5.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/13 1p.

7908200394 LER 78-027/03X-5 on 790718 during May, June & Jul 1979 testing, 3 of 9 helium circulator seal malfunction differential pressure switches tripped outside limits. Caused by dirt accumulation. Problem under investigation.
GAHM,J.W. Public Service Co. of Colorado 79/08/13 10pp.

7908220370 Forwards LER 79-022/03L-0.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/17 1p.

--7908220376 LER 79-022/03L-0 on 790720 lack of aquatic macroinvertebrate sample collection. Caused by oversight of field sampling personnel employed by contract agent. Agent indicated program was resumed & will continue biweekly.
GAHM,J.W. Public Service Co. of Colorado 79/08/17 3pp.

7908310320 Forwards LER 79-022/03L-0.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/17 1p.

--7908310325 LER 79-022/03L-0 on 790720 during performance of surveillance requirement SR NR 2.1, ecological monitoring aquatic macroinvertebrate samples not collected from S. Vrain River. Caused by oversight of contract personnel.
GAHM,J.W. Public Service Co. of Colorado 79/08/17 3pp.

7908300529 Forwards LER 79-023/03L-0.
WAREMBOURG,D. Public Service Co. of Colorado 79/08/24 1p.

--7908300539 LER 79-023/03L-0 on 790727 while performing normal surveillance, fixed feedwater low flow switch found inoperable. Caused by component failure from normal wear. Module was repaired, reinstalled & retested satisfactorily.
REED,A.B. Public Service Co. of Colorado 79/08/24 3pp.

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7908060146 Requests prompt forwarding of Class III fees for 790323 safeguards contingency plan.
DIGGS,R.M. License Fee Management Branch 79/07/03 2pp

7908010377 Submits followup to 790629 ltr re status of fire protection mods. Greenfield penetration inside conduit not sealed as required per upgrading commitment. Error corrected & work completed on 790720.
PARKER,W.O. Duke Power Co 79/07/26 1p

7908060517 Forwards amended safeguards contingency plan. Plan withheld (ref 10CFR2.790).
PARKER,W.O. Duke Power Co 79/08/03 1p

7908210045 Submits facts re NRC policy concerning implementation of General Design Criterion 3 for fire protection. Urges completion of mods prior to Oct 1980. Submittal of info re open items & design details should be expedited.
EISENHUT,D.G. Division of Operating Reactors 79/08/09 2pp

7908210004 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
PARKER,W.O. Duke Power Co 79/08/17 1p

H General correspondence

7907060448 Summarizes 790502-07 t ;p rept Emergency feedwater test & NAC-1 fuel shipment cask measurements observed.
HARDIN,A.K. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 3pp

7908210223 Ack receipt of 790530 ltr. Outlines objectives of NRC review of plants Util has satisfactorily complied w/short-term requirements, permitting resumption or continuation of operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/14 1p.

--7908210236 Expresses concern re possible shutdown of Duke Power Co units & resulting higher util costs, unreliability of power & inadequate energy to operate mills. Strongly urges continuing generation of nuclear electricity.
DIXON, C. B. Clinton Mills 79/05/30 1p.

7908010286 Responds to 790427 ltr. Special document collection at Clemson Univ library will consist of RDs & monthly operating repts for plant.
SOUDER, J. L. Division of Rules and Records 79/06/15 1p.

7908230487 Forwards addl response to NR Denton 790629 ltr re qualifications & experience of steam production dept as of 790730. Resumes, summaries & organizational charts encl.
PARKER, W. O. Duke Power Co 79/08/16 400pp.

O. Advisory Committee on Reactor Safeguards reports & correspondence

7908210013 Discusses scram breaker failures which occurred over 3-wk period.
EPLER, P. Affiliation Unknown 79/06/18 8pp.

P. Operating license stage documents & correspondence

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability would be weighed against any adverse impacts from implementation W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch 79/06/27 2p.

7908080438 Ack 790321 application re qualifications of site health physicist. Requests remittance of Class III amend fee which applicant incorrectly determined was not applicable.
DIGGS, R. M. License Fee Management Branch 79/06/28 1p.

7908030413 FOIA request for documents prepared by NRC re alternatives to Duke Power proposal to ship spent fuel from Oconee plant to McGuire plant.
ROISMAN, A. Z. Natural Resources Defense Council 79/07/02 1p.

7908290508 Submits review of fee considerations re feedwater sys & responses to IE Bullet 79-05D regarding valve setpoints. Suggests fee schedule for each unit be determined in consistent manner.
MILLER, W. O. License Fee Management Branch 79/07/05 2pp.

7908080111 Forwards Amends 74, 74 & 71 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4 79/07/10 2pp.

--7908080116 Amends 74, 74 & 71 to License DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs by deleting hydraulic suppressors replaced by mechanical suppressors.
REID, R. W. Operating Reactors Branch 4 79/07/10 11pp.

--7908080126 Safety evaluation supporting Amends 74, 74 & 71 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation 79/07/10 2pp.

--7908080134 Notice of issuance & availability of Amends 74, 74 & 71 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R. W. Operating Reactors Branch 4 79/07/10 2pp.

7908080266 Forwards Amends 75, 75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4 79/07/12 2pp.

--7908080283 Amends 75, 75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively, deleting Tech Spec 4.13 re fuel surveillance.
REID, R. W. Operating Reactors Branch 4 79/07/12 9pp.

--7908080298 Safety evaluation supporting Amends 75, 75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Operating Reactors Branch 4 79/07/12 2pp.

--7908080311 Notice of issuance & availability of Amends 75, 75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R. W. Operating Reactors Branch 4 79/07/12 2pp.

7908080331 Forwards Amends 76, 76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4 79/07/16 3pp.

--7908080348 Amends 76, 76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively, deleting obsolete requirements from surveillance program re reactor bldg & substituting alternate surveillance tendon in reactor bldg dome.
REID, R. W. Operating Reactors Branch 4 79/07/16 11pp.

--7908080362 Safety evaluation supporting Amends 76, 76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Operating Reactors Branch 4 79/07/06 2pp.

--7908080373 Notice of issuance & availability of Amends 76, 76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R. W. Operating Reactors Branch 4 79/07/16 2pp.

7908150720 Requests evaluation of semiscale small break experiment w/small break computer program by 790901.
ROSS, D. F. TMI-2 Unresolved Safety Issues 79/07/16 7pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC Task Force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/18 58pp.

7908170084 Discusses review of 780202 ltr re potential of reactor cavity annulus seal ring to become destructive missile. Requests demonstration that seal ring is not destructive or removal of seal ring no later than next refueling outage.
REID, R. W. Operating Reactors Branch 4 79/07/18 2pp.

7908030435 Responds to FOIA request for documents prepared by NRC &/or NRC consultants re alternatives to Duke Power proposal to ship spent fuel from Oconee to McGuire.
FELTON, J. M. Division of Rules and Records 79/07/19 2pp.

--7908030452 Requests that questions be transmitted to Duke Power Co re present March 1979 status of fuel storage capacity & present design heat removal capacity under normal & max conditions.
GLENN, R. D. Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/22 1p.

--7908030462 Forwards questions for approval re proposed licensing of shipment of Oconee spent fuel to McGuire nuclear station.
GLENN, R. D. Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/22 14pp.

--7908030461 EIA re storage of Oconee spent fuel at McGuire spent fuel pool. W/marked-up copy.
* Office of Nuclear Material Safety & Safeguards 78/12/31 212pp.

--7908030474 EIA re storage of Oconee spent fuel at McGuire spent fuel pool.
* Office of Nuclear Material Safety & Safeguards 78/11/30 76pp.

7908070306 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/19 1p.

7908210052 Forwards Amends 77, 77 & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4 79/07/20 2pp.

--7908210057 Amends 77, 77 & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively, upgrading qualifications of site health physicist.
REID, R. W. Operating Reactors Branch 4 79/07/20 12pp.

--7908210062 Safety evaluation supporting Amends 77, 77 & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation 79/07/20 2pp.

--7908210064 Notice of issuance & availability of Amends 77, 77, & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R. W. Operating Reactors Branch 4 79/07/20 2pp.

DOCKETED ITEMS

7908130003 Requests util submit proposed amend to delete existing Tech Specs on secondary water chemistry monitoring & incorporate new requirements to inhibit steam generator tube degradation Model license condition encl
REID,T.W. Operating Reactors Branch 4 79/07/23 4pp

7908170089 Requests util submit proposed secondary water chemistry program for incorporation in new license condition Current STS re steam generator tube degradation are ineffective for all PWRs Model license condition encl
REID,R.W. Operating Reactors Branch 3 79/07/23 4pp

7908010467 Responds to NRC 790627 request for description of util mgt & technical resources to support facility Forwards Section 13.1 of topical rept DUKE-2 re conduct of operations
PARKER,W.O. Duke Power Co 79/07/24 3pp

--7908010474 Topical rept DUKE-2,Section 13.1 re conduct of operations
* Duke Power Co 79/07/24 42pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events Requests addl five copies of response for each addl unit
HuMASS,W.P. Quality Assurance Branch 79/07/24 1p

7908230056 Requests results of semiscale small break experiment be compared w/small break computer program being used by C-E in support of owners group To date,evaluations of latter have been inconclusive
ROSS,D.F. TMI-2 Bulletins & Orders 79/07/25 8pp

7908010371 Responds to 790622 ltr Info re model used in potential small break analysis ref in util 790507 ltr,will be submitted by 790914
PARKER,W.O. Duke Power Co 79/07/26 1p

7908010441 Forwards requested info re PWR feedwater lines,in response to V Stello 790525 ltr
PARKER,W.O. Duke Power Co 79/07/27 81pp

7908300599 Summary of 790719 meeting w/utils in Bethesda,MD to discuss outstanding items from NRC orders & IE Bulletins generic to all B&W facilities
CAPRA,R.A. TMI-2 Bulletins & Orders 79/07/31 24pp

7908300618 Ack receipt of 780104 ltr,supplemented by 790717 ltr, requesting license amend re area surrounding Warehouse 4 Actions in compliance w/10CFR20 Amend unnecessary
REID,R.W. Operating Reactors Branch 4 79/08/02 2pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations,guidance documents & repts re emergency planning
EISENHUT,D.G. Division of Operating Reactors 79/08/03 53pp

7908100270 Forwards proposed Tech Specs changes required to support operation at full rated power during Cycle 6 Class IV amend & Cycle 6 reload rept encl
PARKER,W.O. Duke Power Co 79/08/06 3pp

--7908100275 Proposed Tech Spec revision to support operation at full rated power during Cycle 6
* Duke Power Co 79/08/06 27pp

--7908100287 "Cycle 6 Reload Rept."
* Babcock & Wilcox Co BAW-1552 79/07/31 44pp

7908160339 Notification of 790809 meeting w/B&W owners group in Bethesda,MD to discuss long-term generic requirements for B&W operating plants
CAPRA,R.A. TMI-2 Unresolved Safety Issues 79/08/06 2pp

7908290561 Requests clarification of fee classification for radiation protection manager qualification Tech Spec changes
MILLER,W.O. License Fee Management Branch 79/08/07 2pp

7908270092 Forwards request for addl info re containment purge sys
LAINAS,G. Plant Systems Branch 79/08/08 3pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power
GAMMILL,W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908220340 Forwards summary of 790810 meeting w/NRC to discuss potential OBE/DBE design deficiency
PARKER,W.O. Duke Power Co 79/08/17 8pp

7908230470 Forwards summary of 790810 meeting w/NRC re potential OBE/DBE design deficiency & responds to areas of concern raised during meeting
PARKER,W.O. Duke Power Co 79/08/17 8pp

7908280658 Submits progress rept on long-term mods,including two motor-driven emergency feedwater pumps Two-pump test noted in NRC 790518 ltr should no longer be required
PARKER,W.O. Duke Power Co 79/08/22 2pp

7908280669 Forwards revised Tech Specs re auxiliary electrical sys & emergency power periodic testing
PARKER,W.O. Duke Power Co 79/08/22 1p

--7908280672 Revised Tech Specs re auxiliary electrical sys & emergency power periodic testing
* Duke Power Co 79/08/22 12pp

7908300735 Forwards revised Tech Spec page which contains changes not included in original 790806 submittal re proposed amends to support operation at full-rated power during Cycle 6
PARKER,W.O. Duke Power Co 79/08/22 2pp

8. Inspection reports, IE Bulletins & correspondence

7908090018 Forwards IE Insp Repts 50-269/79-10,50-270/79-10 & 50-287/79-10 on 790402-06 & notice of violation
LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/07 2pp

--7908090020 Notice of violation from insp on 790402-06
* Region 2, Atlanta, Office of the Director 79/06/07 3pp

--7908090025 IE Insp Repts 50-269/79-10,50-270/79-10 & 50-287/79-10 on 790402-06 Noncompliance noted failure to follow procedures in QA program,failure to conduct audits & failure to review revised design changes
RUHLMAN,W.A.; KELLOGG,P.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch ASHENDEN,M.C. Region 2, Atlanta, Office of the Director 79/06/05 26pp

7908010265 Forwards responses to IE Bulletins 79-01 & 01A re environ qualification of Class IE equipment & use of stem-mounted limit switches One valve motor operator on Unit 2 & aluminum limit switch gear frame did not meet environ qualifications
PARKER,W.O. Duke Power Co 79/06/12 7pp

7908170515 IE Insp Repts 50-269/79-12,50-270/79-12 & 50-287/79-12 on 790401-30 No noncompliance noted Major areas inspected: followup of IE Bulletin 79-05 & 05A & physical measurements on spent fuel shipping casks
JAPE,F. Region 2, Atlanta, Office of the Director 79/06/15 2pp

7908030038 Clarifies 790612 responses to IE Bulletin 79-01 Statements re completion of corrective actions in context of current refueling outage on Unit 3 Mods will be completed prior to return to power operation
PARKER,W.O. Duke Power Co 79/06/19 1p

7908070135 Supplements 790530 response to IE Bulletin 70-04 Discusses reanalysis of piping w/Velan check valves & mod to cross-connect HPI headers
PARKER,W.O. Duke Power Co 79/06/26 1p

7908220281 Responds to NRC 790607 ltr re violations noted in IE Insp Repts 50-269/79-10,50-270/79-10 & 50-287/79-10 Corrective actions necessary work to correct leakage into warehouse completed
PARKER,W.O. Duke Power Co 79/06/29 8pp

7908010026 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/06 2pp

7908210379 Responds to IE Bulletins 79-02 & 79-02,Revision 1 Seismic Category I piping sys operability is not jeopardized by improperly installed expansion anchors Continued operation is justified
PARKER,W.O. Duke Power Co 79/07/06 6pp

7908030611 Ack receipt of 790621 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-09, 50-270/79 & 50-287/79-09
KENNA,W.B. Region 2, Atlanta, Safeguards Branch 79/07/09 1p

--7908030620 Responds to NRC 790525 ltr re violations noted in IE Insp Repts 50-269/79-09, 50-270/79-09 & 50-287/79-09. Responses withheld (ref 10CFR2.790(d)).
PARKER, W.O. Duke Power Co. 79/06/21 1p.

--7908030626 Forwards IE Insp Repts 50-269/79-09, 50-270/79-09 & 50-287/79-09 on 790409-13&notice of violation. Notice of Violation withheld (ref 10CFR2.790).
KENNA, W.B. Region 2, Atlanta, Office of the Director. 79/05/25 2pp.

--7908030632 IE Insp Repts 50-269/79-09, 50-270/79-09 & 50-287/79-09 on 790409-13. Noncompliance noted failure to control vehicles& deficiency in detection aids. Details withheld(ref 10 cfr 2.790).
FUCHKO, J.M. ; TOBIN, W.J. Region 2, Atlanta, Safeguards Branch. 79/05/24 1p.

--7908030632 IE Insp Repts 50-269/79-09, 50-270/79-09 & 50-287/79-09 on 790709-13. Noncompliance noted failure to control vehicles & deficiency in detection aids. Details withheld (ref 10CFR2.790).
FUCHKO, J.M. Region 2, Atlanta, Office of the Director.
TOBIN, W.J. Region 2, Atlanta, Safeguards Branch. 79/05/24 1p.

7908240303 Forwards IE Insp Repts 50-269/79-13, 50-270/79-13 & 50-287/79-14 on 790529-0601 & 05-06. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10 2pp.

--7908240311 IE Insp Repts 50-269/79-13, 50-270/79-13 & 50-287/79-14 on 790529-0601 & 05-06. No noncompliance noted. Major areas inspected: emergency feedwater & high pressure injection mod.
ECONOMOS, N. ; HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/06 8pp.

7908160569 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/78-28, 50-270/78-27 & 50-287/78-28.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/12 1p.

7908030114 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/13 2pp.

7908070805 Responds to IE Bulletin 79-11 re use of D-75 circuit breakers. Notifies that Westinghouse Type DB-75 circuit breakers are installed in Keowee Hydro Station. Rept re items 2,3 & 4 will be provided by 790815.
PARKER, W.O. Duke Power Co. 79/07/13 1p.

7908070815 Responds to IE Bulletin 79-13 re feedwater sys welds. Insp of welds will be conducted at next refueling outage for each unit. Final evaluation & review to be completed by 790720.
PARKER, W.O. Duke Power Co. 79/07/13 1p.

7908010405 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/17 2pp.

7908030002 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908080038 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908130106 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908220673 Supplements response to IE Bulletin 79-13 re feedwater line breaks. Feedwater leaks in containment may be detected & confirmed by several parameters.
PARKER, W.O. Duke Power Co. 79/07/23 1p.

7908150408 Submits addl info re 790713 ltr concerning IE Bulletin 79-11. Correct designation of breakers is Type DB-50.
PARKER, W.O. Duke Power Co. 79/07/24 1p.

7908080647 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/26 2pp.

7908090369 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/26 2pp.

7908220222 Ack receipt of 790629 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-10, 50-270/79-10 & 50-287/79-10.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/26 1p.

7908160207 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/27 2pp.

7908130039 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/31 1p.

7908160271 Ack receipt of IE Insp Repts 50-269/79-13, 50-270/79-13 & 50-287/79-14. No proprietary info.
PARKER, W.O. Duke Power Co. 79/08/01 1p.

7908300524 Ack receipt of IE Insp Repts 50-269/79-16, 50-270/79-15 & 50-287/79-17 on 790601-30.
PARKER, W.O. Duke Power Co. 79/08/06 1p.

--7908300534 Forwards IE Insp Repts 50-269/79-16, 50-270/79-15 & 50-287/79-17 on 790601-30. No noncompliance noted.
LEWIS, R. Region 2, Atlanta, Reactor Operations Nuclear Support b...ch. 79/07/25 2pp.

--7908300544 IE Insp Repts 50-269/79-16, 50-270/79-15 & 50-287/79-17 on 790601-30. No noncompliance noted. Major areas inspected: plant operations, maint, security, training, LER followup, radiation protection & strike planning.
JAPE, F. ; BRADFORD, W.H. ; ELISLE, G.A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/23 12pp.

7908160137 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/08/07 2pp.

7908170010 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/08/08 2pp.

7908290190 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/08/10 2pp.

7908280431 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B.H. Region 2, Atlanta, Office of the Director. 79/08/13 2pp.

R Periodic operating reports & related correspondence

7908210529 Forwards monthly operating rept for Jul 1979.
PARKER, W.O. Duke Power Co. 79/08/15 1p.

--7908210532 Monthly operating rept for Jul 1979.
REAVIS, J.A. Duke Power Co. 79/08/15 5pp.

S Reportable occurrences, LERs & related correspondence

7908270324 Forwards list of ROs & monthly operating rept for Apr 1979 being made available to library W/o encl.
SOUDER, J.L. Division of Rules and Records. 79/06/18 2pp.

7908140581 Modifies statement made in RO-269/78-27, submitted on 790115, re potentially-malfunctioning valves FDW-47 & FDW-48. Valves are no longer used.
PARKER, W.O. Duke Power Co. 79/07/18 1p.

DOCKETED ITEMS

7908140608 Advises that further info re leakage from low pressure injection cooler to condenser cooling water sys, due by 790718 as RO-269/79-21, will be submitted by 790730.
PARKER, W. O. Duke Power Co. 79/07/18 1p

7908140827 Supplements corrective actions outlined in RO 269/78-27. All Bailey wide-range recorder cables replaced after two addl cable faults identified. Actions taken considered sufficient to mitigate potential difficulties.
PARKER, W. O. Duke Power Co. 79/07/20 2pp

7908140723 RO-269/79-23 on 790723: steam generator tube leak discovered in steam generator 1B. Investigation initiated immediately after shutdown.
VITO, D. J. Duke Power Co. 79/07/24 1p

7908020463 Advises that RO-269/79-20 re inoperable hydraulic shock suppressors will be submitted by 790810; investigation is not completed.
PARKER, W. O. Duke Power Co. 79/07/27 1p

7908060508 Forwards LER 79-021/01T-0.
PARKER, W. O. Duke Power Co. 79/07/30 3pp

--7908060512 LER 79-021/01T-0 on 790704: leak in low power injection cooler A released 456 uCi of corrosion & fission product into Lake Keowee. Caused by cooler overpressurization. Five degraded tubes plugged.
LEWIS, S. R. Duke Power Co. 79/07/30 1p

7908070646 Forwards LER 79-022/03L-0.
PARKER, W. O. Duke Power Co. 79/08/02 3pp

--7908070656 LER 79-022/03L-0 on 790703: high pressure svc water pump A removed from svc to repair leakage from pump motor cooler. Cause of leak undetermined. Pump joint resoldered & cooler pressurized.
LEWIS, S. R. Duke Power Co. 79/08/02 1p

7908100499 Submits preliminary details of leakage leading to shutdown of facility, first reported 790724. Anticipates RO-269/79-^4 by 790820.
PARKER, W. O. Duke Power Co. 79/08/06 1p

7908160374 Forwards LER 79-020/03L-0.
PARKER, W. O. Duke Power Co. 79/08/10 3pp

--7908160379 LER 79-020/03L-0 on 790628: during insp of inaccessible suppressors, three hydraulic suppressors were declared inoperable. Caused by inadequate base plate Hanger redesigned.
LEWIS, S. R. Duke Power Co. 79/08/10 1p

7908240639 Recommends further IE investigation re coil failure, per LER forwarded 790706.
GRIMES, B. Assistant Director for Systems Engineering 79/08/14 2pp

7908230323 Forwards LER 79-023/03L-0.
PARKER, W. O. Duke Power Co. 79/08/17 1p

--7908230327 LER 79-023/03L-0 on 790718: penetration room ventilation sys declared inoperable because of high humidity. Caused by steam leakage during once-through generator blowdown. Leaks repaired & operability verified.
LEWIS, S. R. Duke Power Co. 79/08/17 3pp

7908240389 Forwards LER 79-024/01T-0.
PARKER, W. O. Duke Power Co. 79/08/20 1p

--7908240394 LER 79-024/01T-0 on 790723: once-through steam generator 1B tube leakage exceeded Tech Spec limit. Caused by erosion/corrosion degradation of peripheral tube 73-130. Tube repaired.
LEWIS, S. R. Duke Power Co. 79/08/20 3pp

7908280630 Forwards LER 79-025/03L-0.
PARKER, W. O. Duke Power Co. 79/08/23 4pp

--7908280635 LER 79-025/03L-0 on 790724: during transfer of auxiliary power from normal to startup transformer, breaker on one 4160 volt main feedr bus failed to close. Caused by short circuit due to damaged wire. Damaged wire replaced.
LEWIS, S. R. Duke Power Co. 79/08/23 3pp

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

7908060146 Requests prompt forwarding of Class III fees for 790323 safeguards contingency plan.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp

7908010377 Submits followup to 790629 ltr re status of fire protection mods. Greenfield penetration inside conduit not sealed as required per upgrading commitment. Error corrected & work completed on 790720.
PARKER, W. O. Duke Power Co. 79/07/26 1p

7908060517 Forwards amended safeguards contingency plan. Plan withheld (ref 10CFR2.790).
PARKER, W. O. Duke Power Co. 79/08/03 1p

7908210045 Submits facts re NRC policy concerning implementation of General Design Criterion 3 for fire protection. Urges completion of mods prior to Oct 1980. Submittal of info re open items & design details should be expedited.
EISENHUT, D. G. Division of Operating Reactors 79/08/09 2pp

7908210004 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
PARKER, W. O. Duke Power Co. 79/08/17 1p

H. General correspondence

7908210223 Ack receipt of 790530 ltr. Outlines objectives of NRC review of plants. Util has satisfactorily complied w/short-term requirements, permitting resumption or continuation of operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/14 1p

--7908210236 Expresses concern re possible shutdown of Duke Power Co units & resulting higher util costs, unreliability of power & inadequate energy to operate mills. Strongly urges continuing generation of nuclear electricity.
DIXON, C. B. Clinton Mills 79/05/30 1p

7908010286 Responds to 790427 ltr. Special document collection at Clemson Univ library will consist of ROs & monthly operating repts for plant.
SOUDER, J. L. Division of Rules and Records 79/06/15 1p

7908230487 Forwards addl response to HR Denton 790629 ltr re qualifications & experience of steam production dept as of 790730. Resumes, summaries & organizational charts encl.
PARKER, W. O. Duke Power Co. 79/08/16 400pp

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp

7908080438 Ack 790321 application re qualifications of site health physicist. Requests remittance of Class III amend fee which applicant incorrectly determined was not applicable.
DIGGS, R. M. License Fee Management Branch 79/06/26 1p

7908030413 FOIA request for documents prepared by NRC re alternatives to Duke Power proposal to ship spent fuel from Oconee plant to McGuire plant.
ROISMAN, A. Z. Natural Resources Defense Council 79/07/02 1p

7908290508 Submits review of fee considerations re feedwater sys & responses to IE Bulletin 79-05B regarding valve setpoints. Suggests fee schedule for each unit be determined in consistent manner.
MILLER, W. O. License Fee Management Branch 79/07/05 2pp

7908080111 Forwards Amends 74, 74 & 71 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4 79/07/10 2pp

--7908080116 Amends 74, 74 & 71 to License DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs by deleting hydraulic suppressors replaced by mechanical suppressors.
REID, R. W. Operating Reactors Branch 4 79/07/10 11pp

--7908080126 Safety evaluation supporting Amends 74, 74 & 71 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation 79/07/10 2pp

--7908080134 Notice of issuance & availability of Amends 74, 74 & 71 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R. W. Operating Reactors Branch 4 79/07/10 2pp

7908080266 Forwards Amends 75,75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R W Operating Reactors Branch 4 79/07/12 2pp

--7908080283 Amends 75,75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively, deleting Tech Spec 4.13 re fuel surveillance.
REID, R W Operating Reactors Branch 4 79/07/12 9pp

--7908080298 Safety evaluation supporting Amends 75,75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Operating Reactors Branch 4 79/07/12 2pp

--7908080311 Notice of issuance & availability of Amends 75,75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R W Operating Reactors Branch 4 79/07/12 2pp

7908080331 Forwards Amends 76,76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R W Operating Reactors Branch 4 79/07/16 3pp

--7908080348 Amends 76,76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively, deleting obsolete requirements from surveillance program re reactor bldg & substituting alternate surveillance tendon in reactor bldg dome.
REID, R W Operating Reactors Branch 4 79/07/16 11pp

--7908080362 Safety evaluation supporting Amends 76,76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Operating Reactors Branch 4 79/07/06 2pp

--7908080373 Notice of issuance & availability of Amends 76,76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R W Operating Reactors Branch 4 79/07/16 2pp

7908150720 Requests evaluation of semiscale small break experiment w/small break computer program by 790901.
ROSS, D F TMI-2 Unresolved Safety Issues 79/07/16 7pp

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D G Division of Operating Reactors 79/07/18 56pp

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W P Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908170084 Discusses review of 780202 ltr re potential of reactor cavity annulus seal ring to become destructive missile. Requests demonstration that seal ring is not destructive or removal of seal ring no later than next refueling outage.
REID, R W Operating Reactors Branch 4 79/07/19 2pp

7908030435 Responds to FOIA request for documents prepared by NRC &/or NRC consultants re alternatives to Duke Power proposal to ship spent fuel from Oconee to McGuire.
FELTON, J M Division of Rules and Records 79/07/19 2pp

--7908030452 Requests that questions be transmitted to Duke Power Co re present March 1979 status of fuel storage capacity & present design heat removal capacity under normal & max conditions.
GLENN, R D Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/22 1p

--7908030462 Forwards questions for approval re proposed licensing of shipment of Oconee spent fuel to McGuire nuclear station.
GLENN, R D Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/22 14pp

--7908030461 EIA re storage of Oconee spent fuel at McGuire spent fuel pool W/marked-up copy.
* Office of Nuclear Material Safety & Safeguards 78/12/31 212pp

--7908030474 EIA re storage of Oconee spent fuel at McGuire spent fuel pool.
* Office of Nuclear Material Safety & Safeguards 78/11/30 7pp

7908070306 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O REILLY, J P Region 2, Atlanta, Office of the Director 79/07/19 1p

7908210052 Forwards Amends 77,77 & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R W Operating Reactors Branch 4 79/07/20 2pp

--7908210057 Amends 77,77 & 74 to Licenses DPR-38, DPR-47 & DPR-55 respectively, upgrading qualifications of site health physicist.
REID, R W Operating Reactors Branch 4 79/07/20 12pp

--7908210062 Safety evaluation supporting Amends 77,77 & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation 79/07/20 2pp

--7908210064 Notice of issuance & availability of Amends 77,77 & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R W Operating Reactors Branch 4 79/07/20 2pp

7908130003 Requests util submit proposed amend to delete existing Tech Specs on secondary water chemistry monitoring & incorporate new requirements to inhibit steam generator tube degradation Model license condition encl.
REID, T W Operating Reactors Branch 4 79/07/23 4pp

7908170089 Requests util submit proposed secondary water chemistry program for incorporation in new license condition. Current STS re steam generator tube degradation are ineffective for all PWRs Model license condition encl.
REID, R W Operating Reactors Branch 3 79/07/23 4pp

7908010467 Responds to NRC 790629 request for description of util mgt & technical resources to support facility. Forwards Section 13.1 of topical rept DUKE-2 re conduct of operations.
PARKER, W O Duke Power Co 79/07/24 3pp

--7908010474 Topical rept DUKE-2, Section 13.1 re conduct of operations.
* Duke Power Co 79/07/24 42pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W P Quality Assurance Branch 79/07/24 1p

7908230056 Requests results of semiscale small break experiment be compared w/small break computer program being used by C-E in support of owners group. To date, evaluations of latter have been inconclusive.
ROSS, D F TMI-2 Bulletins & Orders 79/07/25 8pp

7908010371 Responds to 790622 ltr. Info re model used in potential small break analysis, ref in util 790507 ltr, will be submitted by 790914.
PARKER, W O Duke Power Co 79/07/26 1p

7908010441 Forwards requested info re PWR feedwater lines, in response to V Stello 790525 ltr.
PARKER, W O Duke Power Co 79/07/27 81pp

7908300599 Summary of 790719 meeting w/utils in Bethesda, MD to discuss outstanding items from NRC orders & IE Bulletins generic to all B&W facilities.
CAPRA, R A TMI-2 Bulletins & Orders 79/07/31 24pp

7908300618 Ack receipt of 780104 ltr, supplemented by 790717 ltr, requesting license amend re area surrounding Warehouse 4. Actions in compliance w/10CFR20 Amend unnecessary.
REID, R W Operating Reactors Branch 4 79/08/02 2pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D G Division of Operating Reactors 79/08/03 53pp

7908160239 Notification of 790809 meeting w/B&W owners group in Bethesda, MD to discuss lo g-term generic requirements for B&W operating plants.
CAPRA, R A TMI-2 Unresolved Safety Issues 79/08/06 2pp

7908290561 Requests clarification of fee classification for radiation protection manager qualification Tech Spec changes.
MILLER, W C License Fee Management Branch 79/08/07 2pp

7908270092 Forwards request for addl info re containment purge sys.
LAINAS, G Plant Systems Branch 79/08/08 3pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power. GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 5pp.

7908220340 Forwards summary of 790810 meeting w/NRC to discuss potential OBE/DBE design deficiency. PARKER, W. O. Duke Power Co. 79/08/17. 8pp.

7908230470 Forwards summary of 790810 meeting w/NRC re potential OBE/DBE design deficiency & responds to areas of concern raised during meeting. PARKER, W. O. Duke Power Co. 79/08/17. 8pp.

7908280658 Submits progress rept on long-term mods, including two motor-driven emergency feedwater pumps. Two-pump test, noted in NRC 790518 ltr, should no longer be required. PARKER, W. O. Duke Power Co. 79/08/22. 2pp.

7908280669 Forwards revised Tech Specs re auxiliary electrical sys & emergency power periodic testing. PARKER, W. O. Duke Power Co. 79/08/22. 1p.

--7908280672 Revised Tech Specs re auxiliary electrical sys & emergency power periodic testing. + Duke Power Co. 79/08/22. 12pp.

9. Inspection reports: IE Bulletins & correspondence

7908090018 Forwards IE Insp Repts 50-269/79-10, 50-270/79-10 & 50-287/79-10 on 790402-06 & notice of violation. LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/07. 2pp.

--7908090020 Notice of violation from insp on 790402-06. + Region 2, Atlanta, Office of the Director. 79/06/07. 3pp.

--7908090025 IE Insp Repts 50-269/79-10, 50-270/79-10 & 50-287/79-10 on 790402-06 Noncompliance noted: failure to follow procedures in QA program; failure to conduct audits & failure to review revised design changes. RUHLMAN, W. A., KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. ASHENDEN, M. C. Region 2, Atlanta, Office of the Director. 79/06/05. 26pp.

7908010265 Forwards responses to IE Bulletins 79-01 & 01A re environ qualification of Class IE equipment & use of stem-mounted limit switches. One valve motor operator on Unit 2 & aluminum limit switch gear frame did not meet environ qualifications. PARKER, W. O. Duke Power Co. 79/06/12. 7pp.

7908030038 Clarifies 790612 responses to IE Bulletin 79-01. Statements re completion of corrective actions in context of current refueling outage on Unit 3. Mods will be completed prior to return to power operation. PARKER, W. O. Duke Power Co. 79/06/19. 1p.

7908070735 Supplements 790530 response to IE Bulletin 70-04. Discusses reanalysis of piping w/Velan check valves & mod to cross-connect HPI headers. PARKER, W. O. Duke Power Co. 79/06/26. 1p.

7908220281 Responds to NRC 790607 ltr re violations noted in IE Insp Repts 50-269/79-10, 50-270/79-10 & 50-287/79-10. Corrective actions: necessary work to correct leakage into warehouse completed. PARKER, W. O. Duke Power Co. 79/06/29. 8pp.

7908010026 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908210379 Responds to IE Bulletins 79-02 & 79-02, Revision 1. Seismic Category I piping sys operability is not jeopardized by improperly installed expansion anchors. Continued operation is justified. PARKER, W. O. Duke Power Co. 79/07/06. 6pp.

7908030611 Ack receipt of 790621 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-09, 50-270/79-9 & 50-287/79-09. KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/07/09. 1p.

--7908030620 Responds to NRC 790525 ltr re violations noted in IE Insp Repts 50-269/79-09, 50-270/79-09 & 50-287/79-09. Responses withheld (ref 10CFR2.790(d)). PARKER, W. O. Duke Power Co. 79/06/21. 1p.

--7908030626 Forwards IE Insp Repts 50-269/79-09, 50-270/79-09 & 50-287/79-09 on 790409-13&notice of violation. Notice of Violation withheld (ref 10CFR2.790). KENNA, W. B. Region 2, Atlanta, Office of the Director. 79/05/25. 2pp.

--7908030632 IE Insp Repts 50-269/79-09, 50-270/79-09 & 50-287/79-09 on 790409-13. Noncompliance noted: failure to control vehicles& deficiency in detection aids. Details withheld(ref 10 cfr 2.790). FUCHKO, J. M., TOBIN, W. J. Region 2, Atlanta, Safeguards Branch. 79/05/24. 1p.

7908240303 Forwards IE Insp Repts 50-269/79-13, 50-270/79-13 & 50-287/79-14 on 790529-0601 & 05-06. No noncompliance noted. MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 2pp.

--7908240311 IE Insp Repts 50-269/79-13, 50-270/79-13 & 50-287/79-14 on 790529-0601 & 05-06. No noncompliance noted. Major areas inspected: emergency feedwater & high pressure injection mod. ECONOMOS, N., HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/06. 8p.

7908160569 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/78-28, 50-270/78-27 & 50-287/78-28. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/12. 1p.

7908030114 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908070805 Responds to IE Bulletin 79-11 re use of D-75 circuit breakers. Notifies that Westinghouse Type DB-75 circuit breakers are installed in Keowee Hydro Station. Rept re items 2, 3 & 4 will be provided by 790815. PARKER, W. O. Duke Power Co. 79/07/13. 1p.

7908070815 Responds to IE Bulletin 79-13 re feedwater sys welds. Insp of welds will be conducted at next refueling outage for each unit. Final evaluation & review to be completed by 790720. PARKER, W. O. Duke Power Co. 79/07/13. 1p.

7908010405 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030002 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080038 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130106 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908220673 Supplements response to IE Bulletin 79-13 re feedwater line breaks. Feedwater leaks in containment may be detected & confirmed by several parameters. PARKER, W. O. Duke Power Co. 79/07/23. 1p.

7908150408 Submits addl info re 790713 ltr concerning IE Bulletin 79-11. Correct designation of breakers is Type DB-50. PARKER, W. O. Duke Power Co. 79/07/24. 1p.

7908080647 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908090369 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908220222 Ack receipt of 790629 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-10, 50-270/79-10 & 50-287/79-10. LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/26. 1p.

7908160207 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/27 2pp.

7908130039 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/31 1p.

7908160271 Ack receipt of IE Insp Repts 50-269/79-13, 50-270/79-13 & 50-287/79-14 No proprietary info.
PARKER, W.O. Duke Power Co. 79/08/01 1p.

7908300524 Ack receipt of IE Insp Repts 50-269/79-16, 50-270/79-15 & 50-287/79-17 on 790601-30.
PARKER, W.O. Duke Power Co. 79/08/06 1p.

--7908300534 Forwards IE Insp Repts 50-269/79-16, 50-270/79-15 & 50-287/79-17 on 790601-30 No noncompliance noted.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/25 2pp.

--7908300544 IE Insp Repts 50-269/79-16, 50-270/79-15 & 50-287/79-17 on 790601-30 No noncompliance noted. Major areas inspected: plant operations, maint, security, training, LER followup, radiation protection & strike planning.
JAPE, F., BRADFORD, W.H., ELISLE, G.A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/23. 12pp.

7908160137 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/07 2pp.

7908170010 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/08. 2pp.

7908290190 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/10. 2pp.

7908280431 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B.H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

R Periodic operating reports & related correspondence

7908210529 Forwards monthly operating rept for Jul 1979.
PARKER, W.O. Duke Power Co. 79/08/15. 1p.

--7908210532 Monthly operating rept for Jul 1979.
REAVIS, J.A. Duke Power Co. 79/08/15. 5pp.

S Reportable occurrences, LERs & related correspondence

7908270324 Forwards list of ROs & monthly operating rept for Apr 1979 being made available to library. W/o encl.
SOUDER, J.L. Division of Rules and Records. 79/06/18. 2pp.

7908020428 RO-270/79-05 on 790630: condenser cooling water emergency discharge valves found locked closed. Caused by either personnel error or procedural problem. Valves opened.
* Duke Power Co. 79/07/04. 1p.

7908140501 Discusses incident re locking of five emergency condenser cooling water valves. Caused by failure of operator to properly perform assigned task. Program of valve verification will be implemented.
PARKER, W.O. Duke Power Co. 79/07/16. 2pp.

7908140827 Supplements corrective actions outlined in RO 269/78-27. All Bailey wide-range recorder cables replaced after two addl cable faults identified. Actions taken considered sufficient to mitigate potential difficulties.
PARKER, W.O. Duke Power Co. 79/07/20. 2pp.

7908070646 Forwards LER 79-022/03L-0.
PARKER, W.O. Duke Power Co. 79/08/02. 3pp.

--7908070656 LER 79-022/03L-0 on 790703: high pressure svc water pump A removed from svc to repair leakage from pump motor cooler. Cause of leak undetermined. Pump joint resoldered & cooler pressurized.
LEWIS, S.R. Duke Power Co. 79/08/02. 1p.

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

7908060155 Requests prompt forwarding of Class III fee for 790322, 23 & 0430 safeguards contingency plans.
DIGGS, R.M. License Fee Management Branch. 79/07/03. 2pp.

7908140443 Submits Proposed Change 82, modifying App A of fire protection Tech Specs re fire brigade size.
VANDENBURGH, D.E. Vermont Yankee Nuclear Power Corp. 79/08/10. 3pp.

7908220306 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
VANDENBURGH, D. Vermont Yankee Nuclear Power Corp. 79/08/17. 2pp.

G Adjudicatory correspondence

7908020550 Responds to 790515 request for plant shutdown until labor dispute is resolved. Forwards "Training & Qualification of Nuclear Power Plant Personnel" & copy of 10CFR2.206. Present staffing at plant is sufficient.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/06/14. 5pp.

--7908020554 Requests plant shutdwon until labor dispute is solved. Plant is notorious for radiation leakage & other hazards.
KOSKI, G. Affiliation Unknown. 79/05/15 1p.

H General correspondence

7908010581 Confirms request to extend response date until 790820 to NRC 790629 ltr re mgt & tech resources available to handle unusual events.
BECK, J.W. Vermont Yankee Nuclear Power Corp. 79/07/27. 1p.

P Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors. 79/06/04. 52pp.

7908070472 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/06/22. 3pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C.I. Plant Systems Branch. 79/06/27. 2p.

7908080073 Forwards rewritten ETS for review purposes.
IPPOLITO, T.A. Operating Reactors Branch 3. 79/07/03. 3pp.

--7908080317 Rewritten nonradiological ETS for facility.
* Yankee Atomic Electric Co. 79/07/03. 27pp.

7908060176 Forwards Amend 53 to License DPR-28, safety evaluation & notice of issuance & availability.
EISENHUT, D.G. Division of Operating Reactors. 79/07/09. 4pp.

--7908060182 Amend 53 to License DPR-28, granting six month delay for implementing inservice testing program.
EISENHUT, D.G. Division of Operating Reactors. 79/07/09. 2pp.

--7908060186 Safety evaluation supporting Amend 53 to License DPR-28.
* Division of Operating Reactors. 79/07/09. 5pp.

DOCKETED ITEMS

--7908060191 Notice of issuance & availability of Amend 53 to License DPR-28.
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/09 2pp.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch 79/07/11 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering 79/07/16 4pp.

7908070266 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908010277 Explains structure, present work scope, personnel involved & method of communication of recently-formed BWR Operating Plants Owners Group. Forwards list of util representatives, organizational chart & list of working group members.
KEENON, T. D. Vermont Yankee Nuclear Power Corp. 79/07/24 9pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908170228 Requests payment of Class II amend fee for proposed Amend 78 to License DPR-28.
MILLER, W. O. License Fee Management Branch 79/07/31 2pp.

7908270228 Forwards request for addl info re 790518 submittal requesting amends to OL DPR-28 Tech Specs on ECCS actuation logic.
LAINAS, G. Plant Systems Branch 79/08/02 3pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908130440 Summarizes util corporate structure & contractual arrangements for technical support available to handle unusual events. Resumes of top mgt personnel encl.
BECK, J. W. Vermont Yankee Nuclear Power Corp. 79/08/10 22pp.

7908220350 Describes generic response to NRC 790713 request for info re NEDO-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs."
KEENAN, T. D. Vermont Yankee Nuclear Power Corp. 79/08/17 2pp.

7908230436 Discusses Tech Spec Change Request 83 re prepressurized 8*8R fuel changes requested for incorporation into Tech Specs by 791103.
VANDENBURGH, D. Vermont Yankee Nuclear Power Corp. 79/08/21 6pp.

9. Inspection reports, IE Bulletins & correspondence

7908200419 Responds to IE Bulletin 79-01 re environ qualification of Class 1E equipment. Provides written evidence of electrical equipment required to function under accident conditions.
MOODY, D. E. Vermont Yankee Nuclear Power Corp. 79/06/15 4pp.

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625) 79/06/20 44pp.

7908130288 Forwards IE Insp Rept 50-271/79-07 on 790501-03. No noncompliance noted.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/21 2pp.

--7908130291 IE Insp Rept 50-271/79-07 on 790501-03. No noncompliance noted. Major areas inspected: startup test program, core power distribution, core thermal power evaluation & determination of reactor shutdown margin.
BETTENHAUSEN, L. , CAPHTON, D. L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/19 6pp.

7908080181 Provides addl info in response to IE Bulltin 79-07 re seismic stress analysis of safety-related piping. EDS Nuclear, Inc computer programs PISOL & SUPERPIPE verified.
MOODY, D. E. Vermont Yankee Nuclear Power Corp. 79/06/25 2pp.

7908270058 Forwards IE Insp Rept 50-271/79-05 on 790319-23. No noncompliance noted.
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/07/02 2pp.

--7908270069 IE Insp Rept 50-271/79-05 on 790319-23. No noncompliance noted. Major areas inspected: radiation insp during refueling including qualifications of personnel, training, exposure control, posting & control & surveys.
THONUS, L. H. Region 1, Philadelphia, Office of the Director.
CROCKER, H. W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/06/27 7pp.

7908070653 Responds to NRC 790621 ltr re IE Bulletin 79-02, Revision 1. Discusses reanalysis of generic base plate stresses & anchor bolts applied loads, insp of concrete expansion anchor bolts & base plate flexibility computer analysis.
GRACE, R. H. Vermont Yankee Nuclear Power Corp. 79/07/06 4pp.

7908090001 Responds to IE Bulletin 79-11. Westinghouse DB-50 circuit breakers are istalled in safety-related dc distribution sys. Breakers cannot be tested w/o de-energizing dc buses. No spare Type DB breakers.
GRACE, R. H. Vermont Yankee Nuclear Power Corp. 79/07/06 2PP.

7908060014 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/17 1p.

7908060505 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p.

7908030286 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/19 1p.

7908080340 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/20 4pp.

7908100284 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/26 1p.

7908170214 Discusses 790726 telcon re test results & analyses obtained per IE Bulletin 79-02, Revision 1. Requires written evaluation prior to use of epoxy resin as fix for anchor bolts.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/26 2pp.

7908230130 Responds to IE Bulletin 79-12 re short period scrams at BWR facilities. Proposes two mods to rod withdrawal sequences which minimize notch worths.
MOODY, D. E. Vermont Yankee Nuclear Power Corp. 79/07/27 3pp.

7908090338 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/30 1p.

7908240580 Submits supplemental info to IE Bulletin 79-02, Revision 1, re piping supports & expansion type anchor bolts. Forwards interim results of continuing program of insp, test & analysis of Category I piping supports & anchor bolts.
MOODY, D. E. Vermont Yankee Nuclear Power Corp. 79/07/31 5pp.

7908280200 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/07 1p.

7908300414 Notification of 790808 meeting w/licensee in Bethesda, MD to discuss response to IE Bulletin 79-02, Revision 1.
JORDON, E. L. Division of Reactor Operations Inspections 79/08/07 1p

7908230368 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/08 1p

7908280030 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908280355 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/13 1p

7908310306 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

7908300207 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/15 1p

R Periodic operating reports & related correspondence

7908140429 Forwards monthly operating rept for Jul 1979.
MOODY, D. E. Vermont Yankee Nuclear Power Corp. 79/08/10 1p

--7908140437 Monthly operating rept for Jul 1979.
SJOGREN, R. H. Vermont Yankee Nuclear Power Corp. 79/08/10 6pp

S Reportable occurrences, LERs & related correspondence

7908060440 Forwards LER 79-013/03L-0.
CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 79/08/03 1p

--7908060444 LER 79-013/03L-0 on 790710 during testing of RHR subsys logic A relay 10A-K46A failed to energize. Caused by disconnected lead of contact to relay coils control circuit. Wire was reconnected & sys returned to operation.
CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 79/08/03 2pp

7908140648 Forwards LER 79-014/03L-0.
CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 79/08/09 1p

--7908140658 LER 79-014/03L-0 on 790712 during surveillance testing of drywell to torus vacuum breakers, loss of containment air monitor occurred. Caused by corrosion seizure of vanes. Spare pump was installed & failed pump repaired.
CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 79/08/09 2pp

7908210414 Forwards LER 79-016/03L-0.
CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 79/08/16 1p

--7908210417 LER 79-016/03L-0 on 790717, redundant containment isolation capability not available. Caused by requirement to disassemble valve for maint. Valve cleaned, reassembled, tested & returned to svc.
CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 79/08/16 2pp

7908280604 Forwards LER 79-017/03L-0.
CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 79/08/23 1p

--7908280616 LER 79-017/03L-0 on 790731 during normal operations, containment air monitor pump found inoperable. Caused by corrosion seizure of vanes. Spare pump installed & failed pump overhauled. Engineering review in progress.
CONWAY, W. E. Vermont Yankee Nuclear Power Corp. 79/08/23 2pp

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

7908220443 FOIA request for access to Public Svc Electric & Gas documents responding to NRC questions re population data & spent fuel pool.
COLEMAN, A. C. Affiliation Unknown 79/07/23 1p

7908220458 FOIA request for access to documents of Public Svc Electric & Gas re estimated annual cost for operating facility.
COLEMAN, A. C. Affiliation Unknown 79/07/23 1p

7908220446 Responds to FOIA request re Public Svc Electric & Gas responses to NRC questions re population data & spent fuel pool. Info is available in LPDR in Amends 14, 18, 20, 23, 27, 36 & 38 to application.
FELTON, J. M. Division of Rules and Records 79/08/17 1p

7908220464 Responds to FOIA request for access to Public Svc Electric & Gas documents re estimated annual cost for operating facility. Info is available in LPDR as 731112 Amend 25 to application.
FELTON, J. M. Division of Rules and Records 79/08/20 1p

E NRC Safety Evaluation Report (SER), suppls & correspondence

7906020619 Forwards 781201 safety evaluation & EIA re mod of spent fuel storage pool.
MOORE, J. E. Branch 2 79/04/17 1p

F Security, medical, emergency & fire protection plans

7908200194 Forwards preliminary security training & qualification plan. Plan withheld (ref 10CFR2.790).
LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey 79/08/16 1p

G Adjudicatory correspondence

7908080136 Testimony of RE Webb on contentions re accident hazards of spent fuel storage. Storage is unsafe due to possibility of loss-of-water accidents. Reactors should be closed down.
WEBB, R. E. Lower Alloways Creek, NJ. 79/02/27 40pp

--7908080144 "Analysis of Accident Hazards of Storing Highly Radioactive Spent Fuel Rods in Spent Fuel Storage Pools at Nuclear Power Plants & At Other Offsite Storage Facilities."
WEBB, R. E. Lower Alloways Creek, NJ. 79/04/03 42pp

7906250396 Objects to ASLB 790418 Question 3 re effect of explosion on spent fuel pool. NRC case law & policy prohibit consideration of Class 9 accidents. Certificate of Svc encl.
SMITH, B. H. , MOORE, J. E. Branch 2 79/06/01 11pp

7908080130 Forwards NRC partial response to ASLB questions.
SMITH, B. H. Branch 2 79/06/19 1p

--7908080137 Transcript of 790619 NRC partial response to ASLB questions * Atomic Safety and Licensing Board Panel. 79/06/19 6pp

7908100162 Forwards NUREG-0560, "Staff Rept On Generic Assessment of Feedwater Transients In PWRs Designed By B&W" per 790619 ltr re amend to License DPR-70. W/o encl.
SMITH, B. H. Branch 2 79/06/20 14p

7908100153 Requests ASLB reveal intentions re testimony filed by Township of Lower Alloways Creek on Class 9 accidents if Board overrules NRC objections at resumption of spent fuel proceeding on 790710.
SMITH, B. H. Branch 2 79/06/22 1pp

7908130251 Brief submitted by intervenor Colemans in response to util opposition to ASLB consideration of Class 9 accident & certification of issue. ASLB is required to review Class 9 accidents. Certification is not appropriate.
ONSDORFF, K. A. New Jersey, State of 79/06/22 7pp

7908300050 Opposes OL for facility. Nuclear power is not safe. Region will not suffer power shortage w/o facility. Safety should be first concern to those entrusted w/health & safety of public.
ZITZER, P. Committee for Application of Nuremberg Principles to US Nuclear Power Production 79/06/25 3pp

7908170433 Forwards 790626 New Castle County, DE Council Resolution 79-194 requesting denial of util proposal to expand allowable capacity for storage of spent nuclear fuel rods at facility.
FARLEY, J. P. New Castle County, DE. 79/06/28 3pp

7908220152 Objections & motion to strike portions of Webb & Gulbransen testimony on behalf of intervenor Township of Lower Alloways Creek re ASLB 790418 order. Testimony concerns Class 9 accidents, not explosions.
SMITH, B. H. , MOORE, J. E. Branch 2 79/06/29 6pp

--7908220157 Outline of cross-examination of intervenor Township of Lower Alloways Creek witnesses Webb & Gulbransen re ASLB 790514 order. Certificate of svc encl.
SMITH, B. H. Branch 2 79/06/29 3pp.

7908030529 Outline of cross-examination submitted by util to be used to extent that util 790630 objections to intervenor Lower Alloways Creed Township testimony are not sustained. Certificate of Svc encl.
WETTERHAHN, M. J. Conner, Moore & Corber 79/06/30 6pp.

7908220039 Outline of cross-examination of intervenors Coleman. Questions relate to initial events for TMI incident, operation of reactor containment sys during loss of feedwater transient & operation of auxiliary bldg.
ONSDORFF, K. A. ; VANNESS, S. C. New Jersey, State of 79/07/02 3pp.

7908150023 Forwards L. ' 79-044/03L as exhibit in support of intervenors motion fo supplementation of answers. Full rept on incident & implica.. is re spent fuel pool is warranted.
ONSDORFF, K. A. New Jersey, State of 79/07/03 2pp.

7908090438 Confirms 790703 telcon re radioactive debris clogging pipe. Series of equipment failures were detected during initial refueling outage. Requests updated estimate on date for resumption of operations.
ONSDORFF, K. A. New Jersey, State of 79/07/05 2pp.

7908220113 Request submitted by util for denial of intervenors Coleman 790626 request that ASLB compel licensee to suppl responses to Interrogatories 1, 3 & 6. Questions have no relation to grid strap problem.
WETTERHAHN, M. J. Conner, Moore & Corber 79/07/06 4pp.

--7908220143 Request submitted by util for denial of intervenors Coleman 790625 request for reconsideration of dismissal of Coleman Contention 7. NRC must remand matter to ASLB. Certificate of Svc encl.
WETTERHAHN, M. J. Conner, Moore & Corber 79/07/06 6pp.

7908220508 Forwards info re vented spent fuel storage racks per 790703 telcon. Submits 790410 insp rept summary of 790516 meeting, LD Mayer 790521 ltr & transcript of 790614 public meeting.
MOORE, J. A. Branch 2 79/07/06 1p.

--79082 0524 Summary of 790516 meeting with util & MN Pollution Control Agency in Roseville, MN re high density fuel storage sys. Forwards J Stensvaag 790502 r & T Hoffman 790511 ltr.
KE WN, T. A. Operating Reactors Branch 3 (Pre 790625)
79/06/08 2pp.

79 , 8000. Response submitted by intervernor Township of Lower Alloways Creek to NRC motion to strike portions of ME Webb & L. Gulbransen testimony re ASLB 790418 order. Affidavit o. EA Gulbransen & Certificate of Svc encl.
VALORE, C. Va' re, C. 79/07/09 5pp.

H. General correspondence

7908280056 Responds to request for addl info re event at unit as repo. ed in 790629 issue of Philadelphia Bulletin. Resin particles were displaced from resin bed & spread throughout pipe running to water storage tank.
EISENHUT, D. G. Division of Operating Reactors 79/07/26 2pp.

7908200298 Forwards corporate capabilities re mgt & technical resource. Encl available in Centr' Files.
LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey
79/08/09 1p.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 F. NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Gen.. Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908030614 Notifies of completion of review of 790215 ECCS analysis. Plant is in conformance w/10CFR50.46 per NRC 780427 order. Forwards safety evalution.
SCHWENCE' , A. Operating Reac'ors Branch 1 (Pre 790625) 79/06/04
2pp.

--7908030622 Safety evaluatio\ rept for Zr-water correction to ECCS analysis for OL DPR-70.
* Office of Nuclea' Reactor Regulation 79/06/06 3pp.

7908030232 Sur .. s status of five overpressure protection & three flooding re .ews evaluated by LLL in response to Eisenhut 790604 me' .
SHEMANSKI, P. Plant Systems Branch 79/06/12 2pp.

--7908030256 Requests status of LLL electrical staff overpressure & flooding reviews.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 1p.

7908020336 Forwards summary of 790525 meeting w/Westinghouse & util re damage to fuel grid assemblies observed during refueling outage.
MOORE, J. E. Branch 2 79/06/21 1p.

7908070467 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologi. & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/06/22 3pp.

7908140734 Informs that Amend 17 to License DPR-70, transmitted by 790607 ltr, was incomplete. Forwards complete set of Amend 17 changes to Tech Specs.
SCHWENCER, A. Operating Reactors Branch 1 79/06/25 2pp.

--7908140741 Revised pages for Tech Specs per Amend 17 to License DPR-70.
* Operating Reactors Branch 1 79/06/25 11pp.

7908090419 Notifies that licensee has revised schedule for discharge of fuel. Licensee will provide info for record during upcoming hearing.
WETTERHAHN, M. J. Conner, Moore & Corber 79/07/05 2pp.

7908170582 Notifies of fee exemption approval for license amends in Classes I, II & III re upgraded STS bases program. Reactor vendors will be notified.
SCHWENCER, A. Operating Reactors Branch 1 79/07/09 2pp.

7908240044 Discusses program to upgrade bases section of STS. Amends in fee Classes I-III will be fee-exempt.
SCHWENCER, A. Operating Reactors Branch 1 79/07/09 2pp.

7908070262 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/18 1p.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors
79/07/18 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908150737 Requests addl info re structural computer codes used for static & dynamic analysis of nuclear piping sys beyond current plant level. Info needed to continue review of request to continue operation.
SCHWENCER, A. Operating Reactors Branch 1 79/07/24 95pp.

7908220266 Summary of 790717 meeting w/util to discuss startup of facility for second operating cycle.
ROSS, W. J. Operating Reactors Branch 1 79/07/25 5pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp.

7908290655 Notifies that util conclusion that station grid voltage does not degrade below 90% of normal voltage is unacceptable. Design mods & Tech Spec changes should be proposed for undervoltage protection scheme.
SCHWENCER, A. Operating Reactors Branch 1 79/07/30 2pp.

7908130582 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 4pp.

7908100156 Forwards description of Cycle 2 startup physics test program & augmented surveillance program for detection of dropped control rod rodlets, requested by M Chatterton.
LIBRIZZI, F P Public Service Electric & Gas Co. of New Jersey.
79/08/03 10pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D G Division of Operating Reactors 79/08/03 53pp

7908140404 Forwards correction to power coefficient startup test for Cycle 2 reload analysis originally submitted 790803.
LIBRIZZI, F P Public Service Electric & Gas Co. of New Jersey.
79/08/08 1p

--7908140419 Corrected startup test power coefficients for Cycle 2 reload originally submitted 790803.
* Public Service Electric & Gas Co. of New Jersey. 79/08/08 1p

7908140732 Forwards request for amend to License DPR-70. Request contains revisions to Tech Specs changes re heat flux hot channel factor & nuclear enthalpy hot channel factor.
LIBRIZZI, F P Public Service Electric & Gas Co. of New Jersey.
79/08/09 2pp

--7908140738 Proposed changes to License DPR-70, Tech Specs re heat flux hot channel factor & nuclear enthalpy hot channel factor.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey.
79/08/10 11pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects
79/08/09 56pp

7908200339 Forwards fee for ETS change to increase condenser delta to 18.5 F.
LIBRIZZI, F P Public Service Electric & Gas Co. of New Jersey.
79/08/15 1p

0. Inspection reports, IE Bulletins & correspondence

7908010149 Responds to IE Bulletin 79-06A, Revision 1. Changes in Tech Spec Tables 3.3-3, 3.3-6, 3.3-5 & 4.3-2, forwarded 790516, reflect deletion of coincident pressurizer low pressure signals & changes incorporated since TMI.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey.
79/06/01 2pp

7908020139 Forwards IE Insp Repts 50-272/79-12 & 50-311/79-24 on 790325-0421. No noncompliance noted.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/01 2pp

--7908020154 IE Insp Repts 50-272/79-12 & 50-311/79-24 on 790325-0421. No noncompliance noted. Major areas inspected: logs & records, preparations for refueling outage, followup on licensee events & licensed operator training.
KEIMIG, R R ; NOIRHELM, L J ; NICHOLAS, H H Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/30 15pp

7908020052 Ack receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-272/79-02.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/06/27 1p

--7908020057 Responds to NRC 790315 ltr re violations noted in IE Insp Rept 50-272/79-02. Corrective actions: recorder will be installed to supplement computer printouts & ETS will be changed.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey.
79/04/06 7pp

--7908020060 Forwards IE Insp Rept 50-272/79-02 on 790108-12 & 15-17 & notice of violation.
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/03/15 3pp

--7908020064 Notice of violation from insp on 790108-12 & 15-17.
* Region 1, Philadelphia, Office of the Director 79/03/06 3pp

--7908020070 IE Insp Rept 50-272/79-02 on 790108-12 & 15-17. Noncompliance noted: exceeded condenser temp change limits, failed to review chlorination procedures & failed to collect & analyze river samples.
STOHR, J P ; SHANBAKY, M M Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/06 18pp

7908080277 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 circuit breakers used in safety-related sys. End caps inspected & found satisfactory.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey.
79/07/03 3pp

7908020163 Notification of 790712 meeting w/util in Silver Spring, MD to discuss feedwater line crack insp.
ROSS, W J Operating Reactors Branch 1 79/07/05 1p

7908020281 Discusses 790619 meeting w/util re plant operation pending completion of IE Bulletin 79-07 requirements. Forwards request for addl info re reanalysis effort & computer code verification requirements.
SCHWENCER, A Operating Reactors Branch 1 79/07/05 3pp

7908070785 Responds to IE Bulletins 78-12, 12A & 12B re atypical weld matl C-E generic rept: "Atypical Weld Matl in Reactor Pressure Vessels," which was forwarded to NRC on 790608; addresses Items 1-4.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey.
79/07/06 2pp

7908170471 Responds to IE Bulletin 79-02. No deficiencies in pipe support base plates. Other supports show deficiences re embedment. Corrective action in progress.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey.
79/07/06 5pp

7908220634 Responds to Items 5a-c of IE Bulletin 79-13. Schedule of insp for Item 5a encl. Feedwater line break in Item 5b is addressed in three separate emergency instructions. Procedures provided for feedwater leak detection, Item 5c.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey.
79/07/12 4pp

7908220631 Submits supplemental response to IE Bulletin 79-06A, Revision 1. Briefing presented by NRC to licensed station personnel on 790420 constitutes adequate review of accident sequence. Engineering safety features procedures tightened.
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey.
79/07/13 19pp

7908060010 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/07/17 1p

7908060495 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/07/18 1p

7908030279 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/07/19 1p

7908100269 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/07/26 1p

7908100349 Forwards IE Bulletins 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/07/26 1p

7908090331 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/07/30 1p

7908280180 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/08/07 1p

7908230363 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/08/08 1p

7908280024 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/08/10 1p

7908280335 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/13 1p

7908310301 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/14 1p

7908300187 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/15 1p

7908310395 Submits addl info to 790306 & 0615 responses to IE Bulletin 79-01.Forwards revised table re safety-related equipment inside containment updated to include recent tests on cable qualification.
SCHNEIDER,F.W. Public Service Electric & Gas Co. of New Jersey
79/08/22 2pp

R Periodic operating reports & related correspondence

7908010495 Forwards June 1979 wastewater treatment rept for sewage treatment plant at facility.
MIDURA,H.J. Public Service Electric & Gas Co. of New Jersey
79/07/06 2pp

7908010537 Forwards rept on diversion of water from wells & chloride analysis of Wells 1-3 & 6 for quarter ending June 1979.
MIDURA,H.J. Public Service Electric & Gas Co. of New Jersey
79/07/09 3pp

7908010540 Forwards operating rept of industrial waste treatment plant for June 1979.
MIDURA,H.J. Public Service Electric & Gas Co. of New Jersey
79/07/09 2pp

7908030151 Forwards June 1979 impingement monitoring program Rept 27.
LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey
79/07/20 1p

--7908030163 Impingement Monitoring Program Rept 27,June,1979.
* Public Service Electric & Gas Co. of New Jersey 79/07/20
57pp

7908010450 Forwards discharging monitoring repts for June 1979.
MIDURA,H.J. Public Service Electric & Gas Co. of New Jersey
79/07/24 13pp

7908200366 Forwards monthly operating rept for Jul 1979.
MIDURA,H.J. Public Service Electric & Gas Co. of New Jersey
79/08/10 1p

--7908200367 Monthly operating rept for Jul 1979.
MILLER,L.K. Public Service Electric & Gas Co. of New Jersey
79/08/10 12pp

7908280636 Forwards "Impingement Monitoring Program Rept Number 28,Jul 1979."
LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey
79/08/20 1p

--7908280643 "Impingement Monitoring Program Rept Number 28,Jul 1979."
* Public Service Electric & Gas Co. of New Jersey 79/08/20
68pp

S Reportable occurrences, LERs & related correspondence

7908010329 RO 79-48/01P on 790709 wall thickness degradation found in steam generator tubes adjacent to tube lane blocking devices in Generators 11,13 & 14.Degradation exceeded 40% limit in six of 60 tubes inspected.
MIDURA,H.J. Public Service Electric & Gas Co. of New Jersey
79/07/09 1p

7908010315 RO 79-50/01P notified by Westinghouse of possible delays in reactor trip & auxiliary feedwater initiation in event of main feedline rupture inside containment.Caused by heatup of generator ref leg.
MIDURA,H.J. Public Service Electric & Gas Co. of New Jersey
79/07/10 1p

7908010336 RO 79-49/01P on 790710 improper concrete anchor embedments discovered in pipe supports other than those specified in IE Bulletins 79-02 & 02A.Corrective actions implemented.
* Public Service Electric & Gas Co. of New Jersey 79/07/10 1p

7908160039 Summary of 790712 meeting w/util & Westinghouse re feedwater line cracks.
ROSS,W.J. Operating Reactors Branch 1 79/07/27 5pp

7908030215 Forwards LER 79-044/03L-1.
LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey
79/07/30 1pp

--7908030221 LER 79-044/03L-1 on 790506 during refueling,grid strap damage was observed on 31 fuel assemblies consisting of pieces missing or grid matl ripped & laid over.Caused by interaction of grid straps of adjacent fuel assemblies.
KAPPLE,A.W. Public Service Electric & Gas Co. of New Jersey
79/07/30 1p

7908030455 Forwards LER 79-047/03L-0.
LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey
79/07/30 1p

--7908030463 LER 79-047/03L-0 on 790531 broken rodlets found in control rods RCCA during refueling outage.Caused by failure of spider fingers resulting from stress corrosion cracking. Rodlets replaced.Flux maps will be monitored.
KAPPLE,A.W. Public Service Electric & Gas Co. of New Jersey
79/07/30 4pp

7908140810 Forwards LER 79-051/03L-0.
LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey
79/08/10 1p

--7908140820 LER 79-051/03L-0 on 790715 leakage greater than range of test equipment appeared in eight containment isolation valves.Caused by normal degradation & buildup in valves during plant operation.Valves restroked.
KAPPLE,A.W. Public Service Electric & Gas Co. of New Jersey
79/08/10 2pp

7908300546 Forwards LER 79-053/01T-0.
LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey
79/08/23 1p

--7908300557 LER 79-053/01T-0 on 790810 upon review of all pipe supports within sample of stress calculations for safety-related piping,rejection rate found to be outside normal limits of statistical sampling techniques.Evaluation underway.
KAPPLE,A.W. Public Service Electric & Gas Co. of New Jersey
79/08/23 2pp

7908300628 Forwards LER 79-052/01T-0.
LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey
79/08/23 3pp

--7908300636 LER 79-052/01T-0 on 790809 review of DL Amend 4 indicates that 12 inch per minute rise rate restriction may reduce margin for loss of normal feedwater & main feedline rupture accident.NRC should issue DL mod.
KAPPLE,A.W. Public Service Electric & Gas Co. of New Jersey
79/08/23 1p

T Hearing transcripts on non-antitrust matters

7908030287 Transcript of 790710 hearing in Salem,NJ re proposed issuance of amend to License DPR-70 Pp 919-1127.
MILHOLLIN,G.L.; LAMB,J.C.; SHON,F. Atomic Safety and Licensing Board Panel 79/07/10 209pp

7908030621 Transcript of 790711 hearing in Salem,NJ Pp 1,128-1,351. Testimony of licensee & NRC encl.
MILHOLLIN,G.L.; LAMB,J.C.; SHON,F. Atomic Safety and Licensing Board Panel 79/07/11 238pp

U Congressional/Executive Correspondence

7908010224 Responds to 790330 ltr re integrity of facility & request for insp.Resident inspector has been on assignment at plant since July 1978.Forwards IE Bulletin 79-06A,requiring various reviews & evaluations in light of TMI event.
HENDRIE,J.M. Commission 79/06/05 2pp

DOCKET 50-274 U.S. GEOLOGICAL SURVEY RESEARCH REACTOR

P Operating license stage documents & correspondence

7908080068 Forwards Amend 3 to License R-113, safety evaluation & notice of issuance & availability.
REID,R.W. Operating Reactors Branch 4 79/07/10 2pp

--7908080091 Amend 3 to License R-113 to increase max of contained U-235 to 5 kg.
REID, R. W. Operating Reactors Branch 4 79/07/10 2pp.

--7908080096 Safety evaluation supporting Amend 3 to License R-113.
* Office of Nuclear Reactor Regulation 79/07/10 2pp.

9 Inspection reports, IE Bulletins & correspondence

7908160045 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste For Transportation & Burial." Action required.
SEYFRIT, R. V. Region 4, Dallas, Office of the Director 79/08/10 1p.

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908020041 Summary of 790613 meeting w/util in Bethesda, MD re current NRC CP & OL application review policies & criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

7908060092 Forwards order extending const completion date to 791231 & staff evaluation of extension 790716 transmittal notice encl.
STOLZ, J. F. Light Water Reactors Branch 1 79/07/11 3pp.

--7908060096 Order extending const completion date from 790631 to 791231.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/07/11 1p.

--7908060101 Evaluation of request for extension of const completion date & potential environ impacts.
BUCKLEY, B. C. ; STOLZ, J. F. Light Water Reactors Branch 1 79/07/11 2pp.

--7908060106 Forwards FR notice of 790711 order extending const completion date to 791231 W/o encl.
* Office of Nuclear Reactor Regulation 79/07/16 1p.

7908200318 Responds to 790524 request NRC has issued order extending completion date to 791231 to allow for contingencies arising from TMI incident. Forwards order.
STOLZ, J. F. Light Water Reactors Branch 1 79/07/11 3pp.

--7908200321 Order extending const completion date to 791231.
VASSALLO, D. B. Division of Project Management 79/07/11 4pp.

7908030128 Notification of 790718-19 meeting w/util in Bethesda, MD to discuss radiological effluent Tech Specs & electric issues.
BUCKLEY, B. C. Light Water Reactors Branch 1 79/07/17 4pp.

7908130540 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
STOLZ, J. F. Light Water Reactors Branch 1 79/08/02 6pp.

7908170353 Forwards request for addl info required for reviewing application.
STOLZ, J. F. Light Water Reactors Branch 1 79/08/02 4pp.

7908210342 Forwards request for addl info re single rod drop event Tech Specs, evaluation of higher fission gas release, fuel design criteria & avoiding fuel spacer grid damage.
STOLZ, J. F. Light Water Reactors Branch 1 79/08/02 4pp.

7908230687 Ack receipt of 781207 & 19 LOCA reanalyses w/corrected metal/water reaction model. Forwards request for addl info to ascertain worst break was analyzed. FSAR update necessary re organizational change.
STOLZ, J. F. Light Water Reactors Branch 1 79/08/03 4pp.

F Security, medical, emergency & fire protection plans

7908220428 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
CRANE, P. A. Pacific Gas & Electric Co. 79/08/16 1p.

G Adjudicatory correspondence

7906070320 Forwards errata sheet w/suggested mod to proposed findings of fact & conclusions of law Served on 790410.
KETCHEN, E. G. Branch 4 79/04/19 3pp.

7908020376 Ack receipt of 790425 ltr to JM Hendrie opposing facility licensing due to proximity of Hosgri fault. Discusses NRC/Westinghouse public hearings & plant mods to withstand seismic activities.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/14 2pp.

--7908020381 Opposes facility licensing due to proximity of Hosgri fault.
WALACHA, E. Affiliation Unknown 79/04/25 1p.

7908140048 Board notification forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1 79/06/29 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment.
SCINTO, J. F. Hearings Division 79/03/05 1p.

7908210133 Ack receipt of 790423 & 0621 ltrs requesting info re actions to be taken by ASLB Ruling on reopening of hearings has been deferred until further action & evaluations are made re safety of nuclear reactors.
ENGELHARDT, T. F. Deputy Executive Legal Director 79/07/05 2pp.

7908220030 Requests denial of intervenor San Luis Obispo Mothers for Peace motion to reopen record re security plans. Motion has no factual or legal basis. Certificate of Svc encl.
NORTON, B. Portland General Electric Co. 79/07/06 6pp.

7908210416 Requests that OL proceedings be reviewed because of large active earthquake fault near site. Believes facility is huge mistake & should not be licensed.
BOBCZYNSKI, N. I. Affiliation Unknown 79/08/13 3pp.

7908310390 Opposes licensing of facility. Expresses concern re safety, waste disposal, U mining & control of power by large corporations.
PALTIN, S. Affiliation Unknown 79/08/20 1p.

H General correspondence

7908150201 Ack receipt of 790622 ltr & Jul 1979 "Rept to NRC From PG&E Describing Response Programs Following Accident at TMI." NRC priority review will encompass requirements from TMI-2 task forces.
VASSALLO, D. B. Division of Project Management 79/07/20 1p.

7908150273 Responds to 790607 ltr to Chairman Hendrie. Full-time task force has been re established to prepare emergency plans & Governor Brown has appointed emergency review panel to mitigate consequences of accident.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/23 2pp.

--7908150279 Advises that Santa Barbara City Council has endorsed D Yager 790508 ltr sent to Chairman Hendrie.
SHIFFMAN, D. I. Santa Barbara County, CA 79/06/07 1p.

--7908150287 Requests that NRC require adequate emergency plan in conjunction w/facility.
YAGER, D. Santa Barbara County, CA 79/05/08 2pp.

K Utility Final Safety Analysis Report (FSAR) & amends

7908230612 Forwards Amends 79 & 80 to FSAR, including matl for Hosgri rept.
CRANE, P. A. Pacific Gas & Electric Co. 79/08/20 2pp.

--7908230615 Amends 79 & 80 to FSAR.
* Pacific Gas & Electric Co. 79/08/20 110pp.

P Operating license stage documents & correspondence

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. C. Division of Operating Reactors 79/07/18 58pp.

7908010462 Responds to NRC 790629 request for info re corporate capabilities & technical & mgt resources. Info requested in Sections I & II.B will be developed & submitted at later date. Preliminary plan encl.
CRANE, P. A. Pacific Gas & Electric Co. 79/07/31 37pp.

DOCKETED ITEMS

8. Inspection reports, IE Bulletins & correspondence

7908080675 Forwards unsolicited response to IE Bulletin 79-06A, requesting that holders of OLs for Westinghouse PWRs respond to 13 issues resulting from TMI incident.
GORMLY, H. J. Pacific Gas & Electric Co. 79/05/25 14pp.

7908150222 Forwards IE Insp Repts 50-275/79-12 & 50-323/79-07 on 790430-0503 & notice of violation.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/01 2pp.

--7908150226 Notice of violation from insp on 790430-0503.
* Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/01 2pp.

--7908150233 IE Insp Repts 50-275/79-12 & 50-323/79-07 on 790430-0503. Noncompliance noted: tubing support installed on another support exceeded max specified weight limit & conduits not installed as required by procedures & drawings.
KIRSCH, D. F., HUTSON, T. W. Region 5, San Francisco, Office of the Director. DODDS, R. T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/01 7pp.

--7908150246 Ack receipt of 790706 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/79-12 & 50-323/79-07.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/07/24 1p.

--7908150241 Responds to NRC 790601 ltr re violations noted in IE Insp Repts 50-275/79-12 & 50-323/79-07. Corrective actions: minor variation repts issued, tubing supports reinspected & nonvital raceways resupported.
CRANE, P. A. Pacific Gas & Electric Co. 79/07/06 3pp.

7908130421 Forwards response to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-related piping." None of methods specified in bulletin are used.
CRANE, P. A. Pacific Gas & Electric Co. 79/06/12 2pp.

7908200229 Forwards IE Insp Repts 50-275/79-13 & 50-323/79-08 on 790604-07 & 20. No noncompliance noted.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/07/06 2pp.

--7908200235 IE Insp Repts 50-275/79-13 & 50-323/79-08 on 790604-07 & 20. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, pipe supports & restraints & nonconformance reporting sys.
KIRSCH, D. F., HUTSON, T. W., DODDS, R. T. Region 5, San Francisco, Office of the Director. 79/07/05 9pp.

7908270006 Forwards IE Insp Rept 50-275/79-15 on 790601-22 & notice of violation.
CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/07/06 2pp.

--7908270009 Notice of violation from insp on 79601-22 Noncompliance noted: training coordinator did not maintain records of physical force personnel training of general nature.
* Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/07/06 1p.

--7908270011 IE Insp Rept 50-275/79-15 on 790601-22. Noncompliance noted: failure by training director to keep adequate records.
YOUNG, T., STERNBERG, D. M. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/07/06 4pp.

7908010389 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17 1p.

7908020495 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18 1p.

7908160018 Responds to IE Bulletin 79-01A re solenoid valves. All acetal plastic parts in Class 1E ASCO solenoid valves inside containment were replaced. Seals & O-rings made of Buna-N will be replaced.
CRANE, P. A. Pacific Gas & Electric Co. 79/07/18 1p.

7908020406 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/19 1p.

7908170596 Forwards to files unsolicited Pacific GAs & Electric Co responses to IE Bulletin 79-06A.
BUCKLEY, B. C. Light Water Reactors Branch 1. 79/07/24 pp.

7908210261 Forwards IE Insp Rept 50-275/79-16 on 790629-30. No noncompliance noted. W/o encl.
NORDERHAUG, L. R. Region 5, San Francisco, Safeguards Branch. 79/07/24 1p.

7908060054 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26 1p.

7908060145 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26 1p.

7908210493 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07 1p.

7908170034 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10 1p.

7908280379 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13 1p.

7908310148 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14 1p.

7908300240 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Relcted Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15 1p.

9. Reportable occurrences, LERs & related correspondence

7908090200 Ack receipt of 790522 ltr re discrepancy in raceway saddle bolting requirements.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/06/08 1p.

--7908090227 Responds to 790502 notice of violation re lack of specific bolt mounting requirements in raceway detail drawings. Corrective action: accessible supports reinspected & discrepant drawing details corrected.
CRANE, P. A. Pacific Gas & Electric Co. 79/05/22 2pp.

7908100029 Confirms 790608 telcon re potential safety hazard from deficiency identified in procedure to verify performance characteristics of Barton Lot 1 transmitters. List of affected plants encl. None in operation.
ANDERSON, T. M. Westinghouse Electric Corp. 79/06/11 4pp.

7908020527 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10 1p.

7908020026 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17 1p.

7908150715 Forwards Yankee Atomic Electric Co 781128 deficiency rept, "Refueling Water Storage Tank Design Deficiency," & request for addl info.
STOLZ, J. F. Light Water Reactors Branch 1. 79/07/20 4pp.

7908170144 Ack receipt of 790713 ltr re adequacy of design of lateral seismic bracing supporting electrical conduits & raceways.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/01 1p.

--7908170526 Discusses deficiency re adequacy of design of lateral seismic bracing supporting electrical conduits & raceways. Audit is in progress. Deficient supports will be modified as identified. Personnel will be reinstructed in procedures.
CRANE, P. A. Pacific Gas & Electric Co. 79/07/13 2pp.

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

7908140454 Forwards modified physical security plan. Plan withheld (ref 10CFR2.790).
BRADLEY,E.J. Philadelphia Electric Co. 79/08/08 2pp.

7908230335 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
BRADLEY,E.J. Philadelphia Electric Co. 79/08/20 1p.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque,NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER,J. Assistant Director for Site & Safeguards 79/03/22 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT,D.G. Division of Operating Reactors 79/06/04 52pp.

7908150762 Notifies of typographical errors in licensee joint motion for summary disposition of radon issues. Certificate of Svc encl.
SILBERG,J.E. Shaw, Pittman, Potts, & Trowbridge 79/06/05 9pp.

7908010432 Responds to IE Bulletin 79-01 re environ qualification of safety-related electrical equipment. Unable to furnish info requested until 791015 b/c some data required from manufacturer is unavailable.
DALTROFF,S.L. Philadelphia Electric Co. 79/06/13 11pp.

7908070466 Notifies of intent to install second communications sys linking facilities w/NRC regional ofc & main Bethesda,MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES,C.I. Plant Systems Branch 79/06/27 2p.

7908060209 Summary of 790628 meeting w/BWR licensees,applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE,W.F. Standardization Branch 79/07/11 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES,B.K. Assistant Director for Systems Engineering 79/07/16 4pp.

7908070256 Requests cooperation in data-gathering activities to provide NRC Commissioners,public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/18 1p.

7908100290 Forwards NUREG-0472,Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL,W.P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each addl unit.
HAASS,W.P. Quality Assurance Branch 79/07/24 1p.

7908170274 Forwards description of acoustic monitoring sys for relief valve position monitoring.
MCELTOY,J.W. Philadelphia Electric Co. 79/07/30 4pp.

7908030133 Forwards application for amend of Licenses DPR-44 & DPR-56, requesting changes to Tech Specs re containment purging.
BRADLEY,E.J. Philadelphia Electric Co. 79/07/31 1p.

--7908030141 Application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs re containment purging.
* Philadelphia Electric Co. 79/07/27 10pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT,D.G. Division of Operating Reactors 79/08/03 53pp.

7908300783 FOIA request for all radiological monitoring repts showing radiation levels at each level & depth recorded during Jul 1979 reracking & first & second quarter 1979 repts on exposure of personnel in excess of 3 rems per quarter limit.
COLEMAN,A.C. Affiliation Unknown 79/06/06 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL,W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908150581 Forwards info re mgt & technical resources available to respond to unusual events,in response to 790679 request.
DALTROFF,S.L. Philadelphia Electric Co. 79/08/10 2pp.

--7908150588 "Technical-Managerial Resources."
* Philadelphia Electric Co. 79/08/10 153pp.

7908240405 Notifies that initial response to NRC 790713 request for addl info re BWRs has been transmitted in GE Rept NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs," on 790817. Later revision expected 791116.
DALTROFF,S.L. Philadelphia Electric Co. 79/08/17 1p.

7908230479 Forwards application for amend of Licenses DPR-44 & DPR-56, changing Tech Specs re environ study programs & filing fee.
BRADLEY,E.J. Philadelphia Electric Co. 79/08/20 1p.

--7908230482 Application for amend of Licenses DPR-44 & DPR-56. Certificate of Svc encl.
BAUER,E.G. , BRADLEY,E.J. Philadelphia Electric Co. 79/08/23 12pp.

7908240466 Forwards application for amend of Licenses DPR-44 & DPR-56, re administrative & editorial changes in specified sections of Tech Specs & filing fee.
BRADLEY,E.J. Philadelphia Electric Co. 79/08/21 1p.

--7908240470 Application for amend of Licenses DPR-44 & DPR-56, making administrative & editorial changes in specified sections of Tech Specs. Includes Certificate of Svc & pages affected.
DALTROFF,S. Philadelphia Electric Co. 79/08/21 8pp.

7908300787 Responds to FOIA request for radiological monitoring repts showing radiation levels recorded during Jul 1979 spent fuel pool reracking & first & second quarter 1979 repts re exposure of personnel. No documents have been located.
FELTON,J.M. Division of Rules and Records 79/08/23 1p.

7908290575 Forwards application for amend of Licenses DPR-44 & DPR-56.
BRADLEY,E.J. Philadelphia Electric Co. 79/08/27 1p.

--7908290571 Application for amend of DPR-44 & DPR-56 changing Tech Specs re spent fuel discharge rates & proposed mods to control rod drive sys. Certificate of Svc encl.
DALTROFF,S. Philadelphia Electric Co. 79/08/23 21pp.

G. Inspection reports, IE Bulletins & correspondence

7908080628 Response to IE Bulletin 79-04. Performed seismic analysis for control rod drive return line outboard isolation valve piping,using correct valve weight. Piping supports found unsatisfactory. Corrective mods to be completed by 790601.
DALTROFF,S.L. Philadelphia Electric Co. 79/05/31 2pp.

7908130339 Notifies all BWR licensees status of NRC review of licensee response to IE bulletin 79-08. Requests attendance at 790628 meeting in Bethesda,MD re info needed by NRC to complete review.
IPPOLITO,T.A. Operating Reactors Branch 2 (See 790625).
79/03/20 44pp.

7908070698 Responds to IE Bulletin 79-11 re failures of Westinghouse circuit breakers in safety-related sys. Westinghouse Type DB-50 & DB-75 breakers are not used in safety-related Class IE svc.
DALTROFF,S.L. Philadelphia Electric Co. 79/07/03 2pp.

7908160565 Responds to IE Bulletin 79-02,Revision 1 Final rept will be issued when testing & insp program is completed Completion date is 791231
DALTROFF,S.L. Philadelphia Electric Co. 79/07/06 7pp

7908010519 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/17 1p

7908060400 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/18 1p

7908030270 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/19 1p

7908080334 Requests addl info to suppl previous response to IE Bulletin 79-08,to enable NRC to complete safety evaluation
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/20 4pp

7908200002 Responds to IE Bulletin 79-01A re deficiencies in environ qualification of ASCO solenoid valves Supplements 790613 response to IE Bulletin 79-01
DALTROFF,S.L. Philadelphia Electric Co. 79/07/20 3pp

7908100261 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/26 1p

7908230135 Responds to IE Bulletin 79-12 re short period scram at BWR facilities Submits info re estimates of critical rod pattern,control rod withdrawal sequences,emergency rod in switch & reactor operator training program
DALTROFF,S.L. Philadelphia Electric Co. 79/07/27 5pp

7908090322 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/30 1p

7908130277 Responds to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys Describes actions to be taken to verify that seismic analysis input info conforms to actual configuration of safety-related sys.
DALTROFF,S.L. Philadelphia Electric Co. 79/08/01 8pp

7908230161 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/07 1p

7908230362 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/08 1p

7908270558 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/10 1p

7908290322 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/13 1p

7908310292 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/14 1p

7908300172 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/15 1p

R Periodic operating reports & related correspondence

7908020431 Forwards "Monthly Rept 71,Thermal & Biological Monitoring Programs," May 1979
WILLSEY,W.B. Philadelphia Electric Co. 79/07/25 1p

--7908020436 "Monthly Rept 71,Thermal & Biological Monitoring Programs," May 1979
WILLSEY,W.B. Philadelphia Electric Co. 79/07/25 11pp

7908160447 Forwards monthly operating rept for Jul 1979
COONEY,M.J. Philadelphia Electric Co. 79/08/10 1p

--7908160451 Monthly operating rept for Jul 1979
ALDEN,W.M. Philadelphia Electric Co. 79/08/10 9pp

S Reportable occurrences, LERs & related correspondence

7908010456 Notifies of RO 2-79-35/1P on 790706 per IE Bulletin 79-02 insp,found 13 failures of shell-type anchors associated w/horizontal supports on emergency cooling water piping Caused by improper installation Anchors replaced
ULLRICH,W.T. Philadelphia Electric Co. 79/07/09 2pp

7908010312 RO 2-79-33/1P on 790712 failure identified in support associated w/emergency cooling water lines in area of emergency cooling tower valve room Caused by improper installation of anchor bolts Anchors replaced
ULLRICH,W.T. Philadelphia Electric Co. 79/07/13 2pp

7908010536 Forwards LER 79-035/01T-0
COONEY,M.J. Philadelphia Electric Co. 79/07/20 1p

--7908010546 LER 79-035/01T-0 on 790706 insp program performed in response to IE Bulletin 79-02 revealed 18 shell-type anchors which failed to torque properly Caused by incorrect installation Anchors properly replaced
COONEY,M.J. Philadelphia Electric Co. 79/07/20 3pp

7908020465 Forwards LER 79-033/01T-0
COONEY,M.J. Philadelphia Electric Co. 79/07/26 2pp

--7908020469 LER 79-033/01T-0 on 790712 two shell-type anchors failed torque test Caused by improper installation Bolts replaced & successfully tested
COONEY,M.J. Philadelphia Electric Co. 79/07/26 1p

7908100492 LER 79-034/03L-0 on 790703 following surveillance flow test, core spray loop A test valve MO2-14-26A failed to fully close Caused by backed-out & distorted valve seat ring Pipe hanger repaired Valve repair delayed pending unit outage
COONEY,M.J. Philadelphia Electric Co. 79/08/02 1p

7908150506 Forwards LER 79-023/01T-0
COONEY,M.J. Philadelphia Electric Co. 79/08/07 3pp

--7908150511 LER 79-023/01T-0 on 790724 insp program performed in response to IE Bulletin 79-02 identified two anchors in one support which failed to torque test properly Caused by improper installation Anchors replaced
COONEY,M.J. Philadelphia Electric Co. 79/08/07 1p

7908150600 LER 79-036/03L-0 on 790720 setpoint of differential pressure injection sys 2-14-43B exceeded Tech Specs Caused by differential pressure switch out of calibr due to setpoint drift Instrument recalibr & returned to svc
COONEY,M.J. Philadelphia Electric Co. 79/08/07 1p

7908290444 Forwards LER 79-032/01T-1
COONEY,M.J. Philadelphia Electric Co. 79/08/20 3pp

--7908270455 LER 79-032/01T-1 on 790626 insp of Seismic Class I supports revealed 92 w/safety factors of less than 5,w/8 having safety factors of less than 1.Caused by inadequate design All mods completed by 790719
COONEY,M.J. Philadelphia Electric Co. 79/06/26 1p

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

7908140454 Forwards modified physical security plan.Plan withheld (ref 10CFR2.790)
BRADLEY,E.J. Philadelphia Electric Co. 79/08/08 2pp

7908230335 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
BRADLEY,E.J. Philadelphia Electric Co. 79/08/20 1p

P Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque,NM to discuss implementation of physical security requirements for power reactors.Meeting agenda & blank registration forms encl.
MILLER,J. Assistant Director for Site & Safeguards 79/03/22
7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp

7908150762 Notifies of typographical errors in licensee joint motion for summary disposition of radon issues Certificate of Svc encl
SILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge 79/06/05 9pp

7908010432 Responds to IE Bulletin 79-01 re environ qualification of safety-related electrical equipment Unable to furnish info requested until 791015 because data required from manufacturer is unavailable
DALTROFF, S. L. Philadelphia Electric Co. 79/06/13 11pp

7908070466 Notifies of intent to install second communications system linking facilities w/NRC regional ofc & main Bethesda, MD ofc Second line will be used to relay radiologic & environ data during emergencies Testing procedures encl
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program Proposed agenda encl
GRIMES, C. I. Plant Systems Branch 79/06/27 2p

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI
KANE, W. F. Standardization Branch 79/07/11 26pp

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves W/o encl
GRIMES, B. K. Assistant Director for Systems Engineering 79/07/16 4pp

7908070258 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors Info requests will not be made while plant is in shutdown mode
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events Requests addl five copies of response for each unit, if more than one is owned & operated
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908170274 Forwards description of acoustic monitoring sys for relief valve position monitoring
MCELTOY, J. W. Philadelphia Electric Co. 79/07/30 4pp

7908030133 Forwards application for amend of Licenses DPR-44 & DPR-56, requesting changes to Tech Specs re containment purging
BRADLEY, E. J. Philadelphia Electric Co. 79/07/31 1p

--7908030141 Application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs re containment purging.
* Philadelphia Electric Co. 79/07/27 10pp

7908060387 Forwards application for amend to Tech Specs for License DPR-56 to reflect third refueling of reactor core NEDO-24204A re Reload 3 & NEDO-21363-2A concerning fast scram control rod drive encl
BRADLEY, E. J. Philadelphia Electric Co. 79/08/02 1p

--7908060397 Application for amend of License DPR-56 Tech Specs to reflect third core refueling.
BAUER, E. G., BRADLEY, E. J. Philadelphia Electric Co. 79/08/02 46pp

7908060403 "GE BWR Reload 1 Licensing Amend for Fast Scram Control Rod Drive System Suppl 2."
FORDFORD, J. V., BRUGGE, R. D. General Electric Co., Nuclear Energy Products Div. NEDO-21363-2A 79/07/31 12pp

--7908060407 "Supplemental Reload Licensing Submittal for Reload 3."
ERVIN, A. M., BRUGGE, R. D. General Electric Co., Nuclear Energy Products Div. NEDO-24204-A 79/07/31 31pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

7908300783 FOIA request for all radiological monitoring repts showing radiation levels at each level & depth recorded during Jul 1979 reracking & first & second quarter 1979 repts on exposure of personnel in excess of 3 rems per quarter limit
COLEMAN, A. C. Affiliation Unknown 79/08/06 1p

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908150581 Forwards info re mgt & technical resources available to respond to unusual events, in response to 790629 request
DALTROFF, S. L. Philadelphia Electric Co. 79/08/10 2pp

--7908150588 "Technical-Managerial Resources."
* Philadelphia Electric Co. 79/08/10 153pp

7908240405 Notifies that initial response to NRC 790713 request for addl info re BWRs has been transmitted in GE Rept NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs," on 790817 Later revision expected 791116
DALTROFF, S. L. Philadelphia Electric Co. 79/08/17 1p

7908230479 Forwards application for amend of Licenses DPR-44 & DPR-56, changing Tech Specs re environ study programs & filing fee
BRADLEY, E. J. Philadelphia Electric Co. 79/08/20 1p

--7908230482 Application for amend of Licenses DPR-44 & DPR-56
Certificate of Svc encl
BAUER, E. G., BRADLEY, E. J. Philadelphia Electric Co. 79/08/23 12pp

7908240466 Forwards application for amend of Licenses DPR-44 & DPR-56, re administrative & editorial changes in specified sections of Tech Specs & filing fee
BRADLEY, E. J. Philadelphia Electric Co. 79/08/21 1p

--7908240470 Application for amd of Licenses DPR-44 & DPR-56, making administrative & editorial changes in specified sections of Tech Specs Includes Certificate of Svc & pages affected
DALTROFF, S. Philadelphia Electric Co. 79/08/21 8pp

7908300787 Responds to FOIA request for radiological monitoring repts showing radiation levels recorded during Jul 1979 spent fuel pool reracking & first & second quarter 1979 repts re exposure of personnel No documents have been located
FELTON, J. M. Division of Rules and Records 79/08/23 1p

7908290575 Forwards application for amend of Licenses DPR-44 & DPR-56
BRADLEY, E. J. Philadelphia Electric Co. 79/08/27 1p

--7908290571 Application for amend of DPR-44 & DPR-56 changing Tech Specs re spent fuel discharge rates & proposing mods to control rod drive sys Certificate of Svc encl
DALTROFF, S. Philadelphia Electric Co. 79/08/23 21pp

G. Inspection reports, IE Bulletins & correspondence

7908080628 Responds to IE Bulletin 79-04 Performed seismic analysis for control rod drive return line outboard isolation valve piping, using correct valve weight Piping supports found unsatisfactory Corrective mods to be completed by 790601
DALTROFF, S. L. Philadelphia Electric Co. 79/05/31 2pp

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08 Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625) 79/06/20 44pp

7908070698 Responds to IE Bulletin 79-11 re failures of Westinghouse circuit breakers in safety-related sys Westinghouse Type DB-50 & DB-75 breakers are not used in safety-related Class IE svc
DALTROFF, S. L. Philadelphia Electric Co. 79/07/03 2pp

7908160565 Responds to IE Bulletin 79-02, Revision [illegible] Final rept will be issued when testing & insp program is completed Completion date is 791231
DALTROFF, S. L. Philadelphia Electric Co. 79/07/06 7pp

DOCKETED ITEMS

7908010519 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/17 1p

7908060400 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/18 1p

7908030270 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/19 1p

7908080334 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO,T.A. Operating Reactors Branch 3 79/07/20 4pp

7908200002 Responds to IE Bulletin 79-01A re deficiencies in environ qualification of ASCO solenoid valves.Supplements 790613 response to IE Bulletin 79-01.
DALTROFF,S.L. Philadelphia Electric Co. 79/07/20 3pp

7908100261 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/26 1p

7908230135 Responds to IE Bulletin 79-12 re short period scram at BWR facilities.Submits info re estimates of critical rod pattern, control rod withdrawal sequences, emergency rod in switch & reactor operator training program.
DALTROFF,S.L. Philadelphia Electric Co. 79/07/27 5pp

7908090322 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/30 1p

7908130277 Responds to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys; describes actions to be taken to verify that seismic analysis input info conforms to actual configuration of safety-related sys.
DALTROFF,S.L. Philadelphia Electric Co. 79/08/01 8pp

7908280161 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/07 1p

7908230362 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/08 1p

7908270558 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/10 1p

7908280322 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/13 1p

7908310292 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/14 1p

7908300172 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/08/15 1p

R. Periodic operating reports & related correspondence

7908020431 Forwards "Monthly Rept 71,Thermal & Biological Monitoring Programs," May 1979.
WILLSEY,W.B. Philadelphia Electric Co. 79/07/25 1p

--7908020436 "Monthly Rept 71,Thermal & Biological Monitoring Programs," May 1979.
WILLSEY,W.B. Philadelphia Electric Co. 79/07/25 11pp

7908160447 Forwards monthly operating rept for Jul 1979.
COONEY,M.J. Philadelphia Electric Co. 79/08/10 1p

--7908160451 Monthly operating rept for Jul 1979.
ALDEN,W.M. Philadelphia Electric Co. 79/08/10 9pp

S. Reportable occurrences: LERs & related correspondence

7907240386 LER 79-017/03L-0 on 790615 while reactor subcritical, D main steam line radiation monitor Hi-Hi trip failed.Caused by dirty trip relay or dirty test switch contacts. Condition corrected by repeated testing.
COONEY,M.J. Philadelphia Electric Co. 79/07/09 2pp

7908010456 Notifies of RO 2-79-35/1P on 790706 per IE Bulletin 79-02 insp.found 13 failures of shell-type anchors associated w/horizontal supports on emergency cooling water piping. Caused by improp installation.Anchors replaced.
ULLRICH,W.T. Philadelphia Electric Co. 79/07/09 2pp

7908010312 RO 2-79-33/1P on 790712 failure identified in support associated w/emergency cooling water lines in area of emergency cooling tower valve room.Caused by improper installation of anchor bolts.Anchors replaced.
ULLRICH,W.T. Philadelphia Electric Co. 79/07/13 2pp

7908010536 Forwards LER 79-035/01T-0.
COONEY,M.J. Philadelphia Electric Co. 79/07/20 1p

--7908010546 LER 79-035/01T-0 on 790706 insp program performed in response to IE Bulletin 79-02 revealed 18 shell-type anchors which failed to torque properly.Caused by incorrect installation.Anchors properly replaced.
COONEY,M.J. Philadelphia Electric Co. 79/07/20 3pp

7908130461 RO 3-79-23/1P on 790724 anchor support on emergency svc water piping in RHR room failed.Apparently caused by improper installation.Anchors & bolts replaced & satisfactorily tested.
ULLRICH,W.T. Philadelphia Electric Co. 79/07/25 2pp

7908020465 Forwards LER 79-033/01T-0.
COONEY,M.J. Philadelphia Electric Co. 79/07/26 2pp

--7908020469 LER 79-033/01T-0 on 790712 two shell-type anchors failed torque test.Caused by improper installation.Bolts replaced & successfully tested.
COONEY,M.J. Philadelphia Electric Co. 79/07/26 1p

7908100484 LER 79-021/03L-0 on 790630 during surveillance testing, main steam sample line inboard isolation valve,AO-3-2-316,failed to close.Cause under investigation.Problem will be resolved during next scheduled outage.
COONEY,M.J. Philadelphia Electric Co. 79/07/30 1p

7908150506 Forwards LER 79-023/01T-0.
COONEY,M.J. Philadelphia Electric Co. 79/08/07 3pp

--7908150511 LER 79-023/01T-0 on 790724 insp program performed in response to IE Bulletin 79-02 identified two anchors in one support which failed to torque test properly.Caused by improper installation.Anchors replaced.
COONEY,M.J. Philadelphia Electric Co. 79/08/07 1p

7908210531 LER 79-022/03L-0 on 790719 annunciator sys II drywell pressure permits containment spray alarmed during routine startup.Caused by failure of diaphragm on PS-3-10-119D. Switch repaired,tested & returned to svc within five days.
COONEY,M.J. Philadelphia Electric Co. 79/08/13 1p

7908290444 Forwards LER 79-032/01T-1.
COONEY,M.J. Philadelphia Electric Co. 79/08/20 3pp

--7908290455 LER 79-032/01T-1 on 790626 insp of Seismic Class I supports revealed 92 w/safety factors of less than 5,w/8 having safety factors of less than 1.Caused by inadequate design. All mods completed by 790719.
COONEY,M.J. Philadelphia Electric Co. 79/06/26 1p

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7908130218 Notifies that review of safeguards contingency plan involves consideration of safeguards issue;requiring payment of Class III fee.Plans should be submitted by 790823.
DIGGS,R.M. License Fee Management Branch 79/07/03 2pp

7908220488 Requests addl info re contingency plan submitted by 790323 ltr Encl withheld (ref 10CFR2.790).
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 2pp.

7908210002 Forwards security personnel training & qualification program Plan withheld (ref 10CFR2.790).
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/17 1p.

7908210420 Forwards agreement to implement previously proposed fire protection mods & technical evaluations documented in Sections 3.1 & 3.2 of SER All mods to be implemented by Mar 1981 refueling outage.
STALLINGS, C. N. Virginia Electric & Power Co. 79/08/17 5pp.

G. Adjudicatory correspondence

7907120284 Ack receipt of 790313 ltr commenting on shutdown of five nuclear power plants in eastern US Objective is to review situation in expedited & disciplined manner so that plants can be returned to operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/22 1p.

7908170219 Forwards transcript of 790502 steam generator repair program briefing Discusses amount of water processed through liquid radwaste sys resulting from plant shutdowns necessary to plug leaking steam generator tubes.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/31 74pp.

H. General correspondence

7908100055 Responds to 790313 ltr opposing shutdown of five plants due to questions re ability of piping sys to withstand earthquakes Earthquake maps of eastern OH & western PA encl.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/09 3pp.

--7908100066 Opposes plant shutdown due to earthquake concerns.
CAMPBELL, W. R. Affiliation Unknown 79/03/17 2pp.

7908200012 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200046 Commends NRC shutdown of five nuclear plants.
BORTIN, B. Affiliation Unknown 79/03/17 1p.

--7908200063 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200065 Commends NRC move to shut down five plants.
MARSCHARK, E. D. Affiliation Unknown 79/03/16 2pp.

--7908200070 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200073 Applauds NRC shutdown of five plants due to seismic inadequacy.
FUSCO, G. Affiliation Unknown 79/03/27 1p.

--7908200078 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200080 Thanks NRC for closing down unsafe plants.
THOMSON, J. Affiliation Unknown 79/05/17 1p.

--7908200087 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200091 Applauds NRC shutdown of five nuclear power plants.
COLEMAN, E. Affiliation Unknown 79/03/28 1p.

7908170488 Responds to 790613 ltr expressing concern re adequacy of supply of electric power in light of unavailability of plants Reanalysis & investigation of both stations necessary to assure health & safety of public.
GOSSICK, L. V. Office of the Executive Director for Operations 79/07/24 2pp.

--7908170496 Requests that NRC lift 3-month moratorium on issuance of permits & allow VEPCO plants to be licensed Otherwise State of VA will suffer from blackouts & excessive rate increases North Anna Unit 2 design entirely different than TMI.
EDMUNDS, J. T. Virginia, State of 79/06/13 1p.

7908010515 Informs NRC that info required for review of corporate capabilities will be submitted by 790817.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/30 1p.

P. Operating license stage documents & correspondence

7908080633 Forwards documents on file re seismic pipe stresses at Robinson facility Forwards info re Turkey Point resolution of problem.
LEWIS, S. H. Branch 2 79/04/25 24pp.

--7908080656 Recommends IE Bulletin 79-07 & IE Info Notice 79-06, re seismic stress analysis of safety-related piping, be provided to Boards listed Bulletin & info notice encl.
STELLO, V. Division of Operating Reactors 79/04/19 2pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908170157 Summary of 790531 meeting w/util & S&W in Boston, MA re review of pipe stress & pipe support analyses.
NEIGHBORS, J. D. Operating Reactors Branch 1 (Pre 790625) 79/06/07 5pp.

7908010294 Responds to util 770926 request for technical assistance re degraded grid voltage Util must supply addl info for NRC to complete review Request for addl info encl.
LAINAS, G. Plant Systems Branch 79/06/29 3pp.

7908140097 Notifies of review of util analysis, data & test program re mod to 480-volt Class 1E power sys Proposed mod ensures capacity of sys to meet safety functions SER encl.
LAINAS, G. Plant Systems Branch 79/07/10 2pp.

--7908140105 Proposed mod re 480-volt emergency power sys is acceptable.
* Plant Systems Branch 79/07/10 3pp.

7908020268 Notification of 790718-19 meeting w/util & S&W to discuss pipe stress analysis for facility.
NEIGHBORS, J. D. Operating Reactors Branch 1 79/07/13 2pp.

7908070758 Summary of 790621-22 meeting w/util & S&W re review of mods required to pipe supports resulting from pipe stress reanalyses or "as-built" verification.
NEIGHBORS, J. D. Operating Reactors Branch 1 79/07/13 7pp.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908070322 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/19 1p.

7908010354 Forwards Class III fees for NRC review of safeguards contingency plans.
BAUM, E. A. Virginia Electric & Power Co. 79/07/24 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908140463 Forwards safety evaluation re environ qualification of Continental Wire & Cable Co instrument cables used in safety-related areas.
SCHWENCER, A. Operating Reactors Branch 1 79/07/25 2pp.

--7908140467 Safety evaluation supporting environ qualification of safety-related electrical instrument cables mfg by Continental Wire & Cable Corp.
* Office of Nuclear Reactor Regulation 79/07/25 9pp.

DOCKETED ITEMS

7908200016 Forwards Amends 50 & 49 to Licenses DPR-32 & DPR-37, respectively; safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1 79/07/25 2pp.

--7908200019 Amends 50 & 49 to Licenses DPR-32 & DPR-37, respectively, authorizing removal of all part-length control rods from both reactors.
SCHWENCER, A. Operating Reactors Branch 1 79/07/25 13pp.

--7908200024 Safety evaluation supporting Amends 50 & 49 to Licenses DPR-32 & DPR-37, respectively.
* Office of Nuclear Reactor Regulation 79/07/25 3pp.

--7908200027 Notice of issuance & availability of Amends 50 & 49 to Licenses DPR-32 & DPR-37, respectively.
GROTENHUIS, M. M. Operating Reactors Branch 1 79/07/25 3pp.

7908300096 Forwards Amends 51 & 50 to Licenses DPR-32 & DPR-37, respectively; safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1 79/07/27 2pp.

--7908300108 Amends 51 & 50 to Licenses DPR-32 & DPR-37, respectively, eliminating rod bowing penalty.
SCHWENCER, A. Operating Reactors Branch 1 79/07/27 2pp.

--7908300148 Safety evaluation supporting Amends 51 & 50 to Licenses DPR-32 & DPR-37, respectively.
* Office of Nuclear Reactor Regulation 79/07/27 3pp.

--7908300164 Notice of issuance & availability of Amends 51 & 50 to Licenses DPR-32 & DPR-37, respectively.
GROTENHUIS, M. Operating Reactors Branch 1 79/07/27 2pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp.

7908210348 Updates info re admittance of addl NRC personnel to Facility Requests site orientation for AB Ruff.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/30 2pp.

7908220263 Summary of 790718-19 meeting w/util, S&W & Nuclear Svc Corp re mod required to pipe supports resulting from pipe stress reanalysis.
NEIGHBORS, J. D. Operating Reactors Branch 1 79/07/30 6pp.

7908030349 Requests that "Rept on Small Break Accident for Westinghouse NSSS Sys," submitted in response to NRC 790604 request, be included in dockets.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/31 1p.

7908020478 Forwards "Revised Rept on Reanalysis of Safety-Related Piping Sys." Rept contains info based on completion of pipe stress reanalyses for pipe problems, completion of support analysis & tabulation of loads for outside supports.
SPENCER, W. C. Virginia Electric & Power Co. 79/08/01 2pp.

--7908020481 "Revised Rept on Reanalysis of Safety-Related Piping Sys."
* Stone & Webster Engineering Corp. 79/08/31 80pp.

7908130583 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation mode. License condition encl.
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 4pp.

7908080683 Responds to FOIA request for documents re North Anna nuclear power plants.
FELTON, J. M. Division of Rules and Records 79/08/03 2pp.

--7908080692 Responds to 770401 request for info re investigations of allegations of withholding of steam generator info. Technical staff responses encl.
SHAPAR, H. K. Office of the Executive Legal Director 77/05/05 12pp.

--7908080724 Forwards draft Investigation Rept 50-280/79-01 & civil penalty package for action. Noncompliance noted: failure of licensee to submit unusual safety-related event rept & to review question required by Tech Spec 6.1.C.2.F.8.
MOSELEY, N. C. Region 2, Atlanta, Office of the Director. 79/06/06 1p.

--7908080730 Discusses civil sanction for failure to rept differential settlement of Class 1 structures. Returns case for reconsideration of sanction in light of Seyfrit 750626 memo to Thornburg & Shapar 750623 memo to Knuth.
THORNBURG, H. D. Office of Inspection & Enforcement, Office of the Director 79/07/02 1p.

--7908080732 Resubmits civil penalty package for consideration. Does not believe civil penalty is warranted.
MOSELEY, N. C. Region 2, Atlanta, Office of the Director. 79/07/30 1p.

--7908080693 Believes imposition of civil penalties re settlement of containment & auxiliary bldg structures would be inappropriate. No safety problem requiring reporting was detected by Licensing Technical Review Group.
THORNBURG, H. D. Office of Inspection & Enforcement, Office of the Director 79/09/24 1p.

--7908080701 Responds to 751112 ltr re Investigation Repts 50-280/75-01 & 50-281/75-01. Following actions taken by VEPCO: communications improved between officials responsible for insurance matters & those responsible for operations.
MOSELEY, N. C. Region 2, Atlanta, Office of the Director. 75/12/24 1p.

7906230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations/guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908150509 Response to FOIA request for documents relating to alleged withholding of info re nuclear plants operated by VEPCO. Requested documents encl.
FELTON, J. M. Division of Rules and Records 79/08/06 1p.

7908160223 Notification of 790808 meeting w/util in Bethesda, MD to discuss feedwater nozzle cracking & repairs.
NEIGHBORS, J. D. Operating Reactors Branch 1 79/08/06 2pp.

7908130465 Forwards amend to Licenses DPR-32 & DPR-37 re Tech Spec change covering safety injection sys actuation. Amend fee encl.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/08 7pp.

7908130452 Forwards final design basis for mod to auxiliarry bldg ventilation sys & justification for deviations from Reg Guide 1.52, Revision 2. Const should be completed during Unit 1 repair outage.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/09 52pp.

7908140438 Submits correction to transcription error in 790620 ltr re dates of chemistry control method change. Unit 1 changed to all-volatile treatment on 750102 & Unit 2 on 750104.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/09 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09 56pp.

7908160467 Forwards "GE Vertical Induction Motors Inside Containment Recirculation Spray Pumps." Mods made will not affect previously demonstrated qualification of motors.
BROWN, S. C. Virginia Electric & Power Co. 79/08/14 1p.

--7908160472 "GE Vertical Induction Motors Inside Containment Recirculation Spray Pumps."
SHEETS, M. W. General Electric Co., Nuclear Energy Products Div. 491HA689 79/07/23 41pp.

7908230050 Determines that administration of operator examinations will resume. Bulletin & Orders Task Force is satisfied w/short term mod proposed by licensee. Completed & reviewed by IE.
COLLINS, P. F. Operator Licensing Branch 79/08/15 1p.

7908230467 Informs that analysis of designated supports outside containment has been completed. Requests immediate consideration of previous requests for interim operation. Supporting documents encl.
SPENCER, W. C. Virginia Electric & Power Co. 79/08/21 16pp.

G. Inspection reports, IE Bulletins & correspondence.

7908160454 Forwards IE Insp Repts 50-280/79-22 & 50-281/79-34 on 790514-18. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/12 2pp.

--7908160457 IE Insp Repts 50-280/79-22 & 50-281/79-34 on 790514-18 No noncompliance noted Major areas inspected licensee operator training, operating procedures & seismic reanalysis of safety-related piping.
ELROD, S A Region 2, Atlanta, Office of the Director
KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/08 6pp

7908280162 Forwards IE Insp Repts 50-280/79-27 & 50-281/79-44 on 790531-0601 No noncompliance noted.
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/20 2pp

--7908280171 IE Insp Repts 50-280/79-27 & 50-281/79-44 on 790531-0601 No noncompliance noted Major areas inspected emergency tests & drills.
PERROTTI, D J Region 2, Atlanta, Office of the Director
HUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/19 4pp

7908230672 Forwards IE Insp Repts 50-280/79-29 & 50-281/79-46 on 790605-08 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/25 2pp

--7908230674 IE Insp Repts 50-280/79-29 & 50-281/79-46 on 790605-08 No noncompliance noted Major areas inspected fire protection & prevention.
MILLER, W H Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/22 7pp

7908C70178 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7908150528 Forwards IE Insp Repts 50-280/79-31 & 50-281/79-49 on 790430-0601 No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/26 2pp

--7908150533 IE Insp Repts 50-280/79-31 & 50-281/79-49 on 790430-0601 No noncompliance noted Major areas inspected plant operations & maint, including Unit 2 steam generator replacement outage work & followup on previously identified items.
BURKE, D J Region 2, Atlanta, Office of the Director
KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/26 4pp

7908220025 Submits addl info re Items 2-4 & 7-11 of IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
STALLINGS, C M Virginia Electric & Power Co 79/06/26 6PP

7908240208 Forwards IE Insp Repts 50-280/79-28 & 50-281/79-45 on 790604-08 No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/26 2pp

--7908240213 IE Insp Repts 50-2[illegible]79-28 & 50-281/79-45 on 790604-08 No noncompliance noted Major a[illegible] inspected seismic reanalysis of safety-related piping.
ELROD, S A ; KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/26 4pp

7908240187 Forwards IE Insp Repts 50-280/79-34 & 50-281/79-52 on 790611-13 No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/27 2pp

--7908240196 IE Insp Repts 50-280/79-34 & 50-281/79-52 on 790611-13 No noncompliance noted Major areas inspected licensed operator requalification training program & licensee response to IE Bulletin 79-06A in areas of training.
TAYLOR, P A FORD, E J Region 2, Atlanta, Office of the Director HUHLMAN, W A Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/25 4pp

7908080678 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 2pp

7908240317 Forwards IE Insp Repts 50-280/79-33 & 50-281/79-51 on 790611-14 No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/02 2pp

--7908240326 IE Insp Repts 50-280/79-33 & 50-281/79-51 on 790611-14 No noncompliance noted Major areas inspected IE Bulletin 79-03 followup re weld defects in stainless steel pipe spools mfg by Youngstown Welding & Engineering Co.
SKOLDS, J D ; KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/29 5pp

7908010035 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 2pp

7908150187 Ack receipt of 790705 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/79-24 & 50-281/79-42.
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/12 1p

--7908150200 Responds to NRC 790620 ltr re violation noted in IE Insp Repts 50-280/79-24 & 50-281/79-42 Corrective actions: svc desk manned by health physics personnel has been set up & QA manual change submitted.
STALLINGS, C M Virginia Electric & Power Co 79/07/05 2pp

--7908150206 Forwards IE Insp Repts 50-280/79-24 & 50-281/79-42 on 790529-31 & notice of violation.
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/20 2pp

--7908150210 Notice of violation from insp on 790529-31.
* Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/20 1p

--7908150216 IE Insp Repts 50-280/79-24 & 50-281/79-42 on 790529-31 Noncompliance noted failure to follow radiation work permit requirements.
EWALD, S C Region 2, Atlanta, Office of the Director
JENKINS, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/20 5pp

7908170160 Responds to IE Bulletin 79-13 re feedwater welds inside containment. Notifies that two rejectable weld indications have been found to date.
STEWART, W L Virginia Electric & Power Co 79/07/12 1p

7908030144 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/13 2pp

7908070743 Responds to IE Bulletin 79-11 re use of Westinghouse DB-50 & DB-75 circuit breakers Notifies that specified circuit breakers are in use, but w/o overcurrent trip feature.
STALLINGS, C M Virginia Electric & Power Co 79/07/13 2pp

7908080151 Responds to IE Bulletin 79-13, Item 5.re cracking in feedwater sys piping Discusses schedule for insp of feedwater piping welds & procedures to identify & respond to feedwater line break accident.
STALLINGS, C M Virginia Electric & Power Co 79/07/13 4pp

7908060243 Responds to IE Bulletin 79-13 re feedwater welds inside containment Lists welds having rejectable indications Weld radiography is about 75% complete.
WILSON, J Virginia Electric & Power Co 79/07/16 1p

7908010418 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/17 2pp

7908060362 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/17 2pp

7908150238 Ack receipt of 790629 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/79-23 & 50-281/79-35.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/17 1p

--7908150247 Responds to NRC 790605 ltr re violation noted in IE Insp Repts 50-280/79-23 & 50-281/79-35 Corrective actions: drawings found not to be of latest revision were reissued & controlled drawing sets reduced in number.
STALLINGS, C M Virginia Electric & Power Co 79/06/29 2pp

--7908150254 Forwards IE Insp Repts 50-280/79-23 & 50-281/79-35 on 790509-11 & notice of violation.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/05 2pp

--7908150264 Notice of violation from insp on 790509-11.
* Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/05 1p

DOCKETED ITEMS

--7908150274 IE Insp Rept 50-280/79-23 & 50-281/79-35 on 790509-10. Noncompliance noted: failure to follow procedures for drawings.
BROWNLEE, V. L. ; KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/05. 5pp.

7908020036 Forwards G Lainas 790709 memo to D Eisenhut re effect of high environ temp steam generator water level instrumentation. IE action planned to assure Westinghouse licensees take appropriate action.
LAINAS, G. Plant Systems Branch. 79/07/18. 1p.

--7908020038 Advises that Westinghouse informed all customers re possible inaccuracies in steam generator water level indication & subsequent corrections that should be applied. Recommends that item be subj of Board notification.
LAINAS, G. Plant Systems Branch. 79/07/09. 2pp.

--7908020044 PND-79-185 nonconservative analysis results of high energy line break inside containment discovered per Westinghouse 790621 notification. Info being evaluated. Supplemental orders will be generated to customers.
KLINGLER, G. R. ; NOLAN, F. ; BRYAN, S. Office of Inspection & Enforcement, Office of the Director. 79/06/22. 1p.

7908070042 Forwards IE Circular 78-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908070789 Responds to IE Bulletin 79-13 & supplements 790712 & 16 repts re feedwater sys welds. Lists rejectable weld indications detected to date. Feedwater weld radiography is about 80% complete.
STEWART, W. L. Virginia Electric & Power Co. 79/07/18. 1p.

7908080063 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130281 Notifies that IE Bulletin 79-14 is revised to limit scope of required work. Forwards replacement page.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908230239 Submits suppl to earlier repts in accordance w/IE Bulletin 79-13 re defective feedwater welds. Lists welds w/rejectable indications. Radiography 99% complete.
STEWART, W. L. Virginia Electric & Power Co. 79/07/23. 2pp.

7908060003 Updates 790604 response to IE Bulletin 79-02, "Pipe Support Base Plate Design Concrete Expansion Anchor Bolts." Bolt testing program detected no structural failures but several minor deficiencies noted re installation.
SPENCER, W. C. Virginia Electric & Power Co. 79/07/24. 3pp.

7908090489 Responds to IE Bulletin 79-13. Supplements earlier repts w/listing of 12 welds having rejectable indications. Repair work in progress.
STEWART, W. L. Virginia Electric & Power Co. 79/07/24. 2pp.

7908060524 Forwards IE Bulletin 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 1p.

7908070761 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908080728 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160276 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908310018 Responds to IE Bulletins 79-14 & 14, Revision 1, re seismic analysis for as-built safety-related piping sys. Discusses progress of verification program for design criteria. Lists of design documents encl.
SPENCER, W. C. Virginia Electric & Power Co. 79/08/01. 100pp.

7908220655 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

7908100464 Forwards corrections to 790517 request for relief from inservice insp & testing requirements of ASME Boiler & Pressure Vessel Code, 1974 Edition.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/08. 37pp.

7908170016 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08. 2pp.

7908290225 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/10. 2pp.

R. Periodic operating reports & related correspondence

7908160348 Forwards monthly operating rept for Jul 1979.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/13. 1p.

--7908160352 Monthly operating rept for Jul 1979.
COSTELLO, D. J. Virginia Electric & Power Co. 79/08/02. 43pp.

S. Reportable occurrences, LERs & related correspondence

7908030448 Forwards LER 79-004/01X-1.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/01. 1p.

--7908030456 LER 79-004/01X-1 on 790309 notification received of possible errors in pipe stress code analyses in some facility piping sys. Inaccurate value weights were also identified. Plants are shut down pending evaluation.
STEWART, W. L. Virginia Electric & Power Co. 79/07/31. 4pp.

7908160479 Forwards update to LER 78-034/01X-2.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/13. 1p.

--7908160484 Update to LER 78-034/01X-2 on 781101. 17 spare process piping containment penetrations were not capped. Condition has been overlooked since const. Design change approved to weld caps on open ends.
STEWART, W. L. Virginia Electric & Power Co. 79/08/10. 2pp.

7908200368 Forwards LER 79-022/01X-1.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/15. 1p.

--7908200376 LER 79-022/01X-1 on 790621: increase in steam generator ref leg temp resulting in rise in containment temp not accounted for by Westinghouse accident analysis. Long-term action under evaluation.
STEWART, W. L. Virginia Electric & Power Co. 79/08/10. 3pp.

7908280660 Forwards LER 79-011/03X-1.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/23. 1p.

--7908280667 LER 79-011/03X-1 on 790828: process & ventilation particulates & gaseous monitors were w/o power on two occasions. Caused by loose lug connection on power supply cable. Loose connection repaired & plants restored to svc.
STEWART, W. L. Virginia Electric & Power Co. 79/08/21. 2pp.

U. Congressional/Executive Correspondence

7908020232 Ack receipt of 790318 ltr to President Carter re NRC order to shut down five nuclear plants for seismic reasons. Review of piping sys is in progress. Forwards earthquake map for VA.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/06. 3pp.

--7908020241 Forwards CJ Hemmer 790318 ltr for response. Ltr protests closing of five nuclear power plants for seismic reasons.
ZINN, P. K. President of US & Executive Offices. 79/03/21. 2pp.

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

7908130218 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7900220480 Requests addl info re contingency plan submitted by 790323 ltr. Encl withheld (ref 10CFR2.790).
SCHWENCER, A. Operating Reactors Branch 1. 79/08/01. 2pp.

7908210002 Forwards security personnel training & qualification program Plan withheld (ref 10CFR2.790).
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/17. 1p.

7908210420 Forwards agreement to implement previously proposed fire protection mods & technical evaluations documented in Sections 3.1 & 3.2 of SER. All mods to be implemented by Mar 1981 refueling outage.
STALLINGS, C. N. Virginia Electric & Power Co. 79/08/17. 5pp.

G. Adjudicatory correspondence

7908170219 Forwards transcript of 790502 steam generator repair program briefing. Discusses amount of water processed through liquid radwaste sys resulting from plant shutdowns necessary to plug leaking steam generator tubes.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/31. 74pp.

H. General correspondence

7908100055 Responds to 790313 ltr opposing shutdown of five plants due to questions re ability of piping sys to withstand earthquakes. Earthquake maps of eastern OH & western PA encl.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/09. 3pp.

--7908100066 Opposes plant shutdown due to earthquake concerns.
CAMPBELL, W. R. Affiliation Unknown. 79/03/17. 2pp.

7908200012 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200046 Commends NRC shutdown of five nuclear plants.
BORTIN, S. Affiliation Unknown. 79/03/17. 1p.

--7908200063 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200065 Commends NRC move to shut down five plants.
MARSCHARK, E. D. Affiliation Unknown. 79/03/16. 2pp.

--7908200070 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200073 Applauds NRC shutdown of five plants due to seismic inadequacy.
FUSCO, G. Affiliation Unknown. 79/03/27. 1p.

--7908200078 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200080 Thanks NRC for closing down unsafe plants.
THOMSON, J. Affiliation Unknown. 79/05/17. 1p.

--7908200087 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200091 Applauds NRC shutdown of five nuclear power plants.
COLEMAN, E. Affiliation Unknown. 79/03/28. 1p.

7908010515 Informs NRC that info required for review of corporate capabilities will be submitted by 790817.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/30. 1p.

J. Insurance & indemnity information

7908010431 Forwards fee for extending indemnity agreement for period 790820 through 800819.
PROFFITT, W. L. Virginia Electric & Power Co. 79/07/27. 1p.

P. Operating license stage documents & correspondence

7908080633 Forwards documents on file re seismic pipe stresses at Robinson facility. Forwards info re Turkey Point resolution of problem.
LEWIS, S. H. [illegible] 2. 79/04/25. 24pp.

--7908080656 Recommends IE Bulletin 79-07 & IE Info Notice 79-06, re seismic stress analysis of safety-related piping, be provided to boards listed. Bulletin & info notice encl.
STELLO, V. Division of Operating Reactors. 79/04/19. 2pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908010294 Responds to util 770926 request for technical assistance re degraded grid voltage. Util must supply addl info for NRC to complete review. Request for addl info encl.
LAINAS, G. Plant Systems Branch. 79/06/29. 3pp.

7908060147 Requests prompt forwarding of Class III amend fee for 790531 proposed Tech Spec Change 78.
MILLER, W. O. License Fee Management Branch. 79/07/03. 1p.

7908070322 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908070724 Requests response to encl questions re reactor coolant pump supports.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/20. 3pp.

7908010354 Forwards Class III fees for NRC review of safeguards contingency plans.
BAUM, E. A. Virginia Electric & Power Co. 79/07/24. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908140463 Forwards safety evaluation re environ qualification of Continental Wire & Cable Co instrument cables used in safety-related areas.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/25. 2pp.

--7908140467 Safety evaluation supporting environ qualification of safety-related electrical instrument cables mfg by Continental Wire & Cable Corp.
* Office of Nuclear Reactor Regulation. 79/07/25. 9pp.

7908200016 Forwards Amends 50 & 49 to Licenses DPR-32 & DPR-37, respectively, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/25. 2pp.

--7908200019 Amends 50 & 49 to Licenses DPR-32 & DPR-37, respectively, authorizing removal of all part-length control rods from both reactors.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/25. 13pp.

--7908200024 Safety evaluation supporting Amends 50 & 49 to Licenses DPR-32 & DPR-37, respectively.
* Office of Nuclear Reactor Regulation. 79/07/25. 3pp.

--7908200027 Notice of issuance & availability of Amends 50 & 49 to Licenses DPR-32 & DPR-37, respectively.
GROTENHUIS, M. M. Operating Reactors Branch 1. 79/07/25. 3pp.

7908300096 Forwards Amends 51 & 50 to Licenses DPR-32 & DPR-37, respectively, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1. 9/07/27. 2pp.

--7908300108 Amends 51 & 50 to Licenses DPR-32 & DPR-37, respectively, eliminating rod bowing penalty.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/27. 2pp.

DOCKETED ITEMS

--7908300148 Safety evaluation supporting Amends 51 & 50 to Licenses DPR-32 & DPR-37, respectively.
* Office of Nuclear Reactor Regulation 79/07/27 3pp.

--7908300164 Notice of issuance & availability of Amends 51 & 50 to Licenses DPR-32 & DPR-37, respectively.
GROTENHUIS, M. Operating Reactors Branch 1 79/07/27 2pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp.

7908210348 Updates info re admittance of addl NRC personnel to facility. Requests site orientation for AB Ruff.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/30 2pp.

7908030348 Requests that "Rept on Small Break Accident for Westinghouse NSSS Sys." submitted in response to NRC 790604 request, be included in dockets.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/31 1p.

7908130583 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 4pp.

7908080683 Responds to FOIA request for documents re North Anna nuclear power plants.
FELTON, J. M. Division of Rules and Records 79/08/03 2pp.

--7908080692 Responds to 770401 request for info re investigations of allegations of withholding of steam generator info. Technical staff responses encl.
SHAPAR, H. K. Office of the Executive Legal Director 77/05/05 12pp.

--7908080724 Forwards draft Investigation Rept 50-280/79-01 & civil penalty package for action. Noncompliance noted: failure of licensee to submit unusual safety-related event rept & to review question required by Tech Spec 6.1.C.2.F.8.
MOSELEY, N. C. Region 2, Atlanta, Office of the Director 79/06/06 1p.

--7908080730 Discusses civil sanction for failure to rept differential settlement of Class 1 structures. Returns case for reconsideration of sanction in light of Seyfrit 750626 memo to Thornburg & Shapar 750623 memo to Knuth.
THORNBURG, H. D. Office of Inspection & Enforcement, Office of the Director 79/07/02 1p.

--7908080732 Resubmits civil penalty package for consideration. Does not believe civil penalty is warranted.
MOSELEY, N. C. Region 2, Atlanta, Office of the Director 79/07/30 1p.

--7908080693 Believes imposition of civil penalties re settlement of containment & auxiliary bldg structures would be inappropriate. No safety problem requiring reporting was detected by Licensing Technical Review Group.
THORNBURG, H. D. Office of Inspection & Enforcement, Office of the Director 79/09/24 1p.

--7908080701 Responds to 751112 ltr re Investigation Repts 50-280/75-01 & 50-281/75-01. Following actions taken by VEPCO: communications improved between officials responsible for insurance matters & those responsible for operations.
MOSELEY, N. C. Region 2, Atlanta, Office of the Director 75/12/24 1p.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908150509 Responds to FOIA request for documents relating to alleged withholding of info re nuclear plants operated by VEPCO. Requested documents encl.
FELTON, J. M. Division of Rules and Records 79/08/06 1p.

7908160223 Notification of 790808 meeting w/util in Bethesda, MD to discuss feedwater nozzle cracking & repairs.
NEIGHBORS, J. D. Operating Reactors Branch 1 79/08/06 2pp.

7908130465 Forwards amend to Licenses DPR-32 & DPR-37 re Tech Spec change covering safety injection sys actuation. Amend fee encl.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/08 7pp.

7908130452 Forwards final design basis for mod to auxiliarry bldg ventilation sys & justification for deviations from Reg Guide 1.52, Revision 2. Const should be completed during Unit 1 repair outage.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/09 52pp.

7908140438 Submits correction to transcription error in 790620 ltr re dates of chemistry control method change. Unit 1 changed to all-volatile treatment on 750102 & Unit 2 on 750104.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/09 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908280588 Submits addl info to suppl 790531 ltr re potential deficiency in bolt holes on helicoils of steam generator. Helicoils replaced.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/10 2pp.

7908160354 Forwards "Integrated Startup Test Program" following steam generator repairs in compliance w/License DPR-37, Amend 46.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/13 6pp.

--7908160355 "Integrated Startup Test Program."
* Virginia Electric & Power Co. 79/08/13 4opp.

7908160467 Forwards "GE Vertical Induction Motors Inside Containment Recirculation Spray Pumps." Mods made will not affect previously demonstrated qualification of motors.
BROWN, S. C. Virginia Electric & Power Co. 79/08/14 1p.

--7908160472 "GE Vertical Induction Motors Inside Containment Recirculation Spray Pumps."
SHEETS, M. W. General Electric Co., Nuclear Energy Products Div. 491HA689 79/07/23 41pp.

9. Inspection reports, IE Bulletins & correspondence

7908160454 Forwards IE Insp Repts 50-280/79-22 & 50-281/79-34 on 790514-18. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/12 2pp.

--7908160457 IE Insp Repts 50-280/79-22 & 50-281/79-34 on 790514-18. No noncompliance noted. Major areas inspected: licensee operator training, operating procedures & seismic reanalysis of safety-related piping.
ELROD, S. A. Region 2, Atlanta, Office of the Director
KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/08 6pp.

7908280162 Forwards IE Insp Repts 50-280/79-27 & 50-281/79-44 on 790531-0601. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/20 2pp.

--7908280171 IE Insp Repts 50-280/79-27 & 50-281/79-44 on 790531-0601. No noncompliance noted. Major areas inspected: emergency tests & drills.
PERROTTI, D. J. Region 2, Atlanta, Office of the Director
HUFHAM, J. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/19 4pp.

7908280174 Forwards IE Insp Rept 50-281/79-36 on 790417-20. No noncompliance noted.
MURPHY, C. E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/20 2pp.

--7908280182 IE Insp Rept 50-281/79-36 on 790417-20. No noncompliance noted. Major areas inspected: licensee work plans & progress of steam generator replacement.
SANDERS, W. F. Region 1, Philadelphia, Office of the Director
TRIPP, L. E., HERDT, A. R. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/20 3pp.

7908230672 Forwards IE Insp Repts 50-280/79-29 & 50-281/79-46 on 790605-08. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/25 2pp.

--7908230674 IE Insp Repts 50-280/79-29 & 50-281/79-46 on 790605-08. No noncompliance noted. Major areas inspected: fire protection & prevention.
MILLER, W. H. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/22 7pp.

7908070178 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/06/26 2pp

7908150528 Forwards IE Insp Repts 50-280/79-31 & 50-281/79-49 on 790430-0601. No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/26 2pp

--7908150533 IE Insp Repts 50-280/79-31 & 50-281/79-49 on 790430-0601. No noncompliance noted. Major areas inspected: plant operations & maint, including Unit 2 steam generator replacement outage work, & followup on previously identified items.
BURRE, D J Region 2, Atlanta, Office of the Director
KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/26 4pp

7908220025 Submits addl info re Items 2-4 & 7-11 of IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
STALLINGS, C M Virginia Electric & Power Co 79/06/26 6PP

7908240147 Forwards IE Insp Rept 50-281/79-41 on 790529-0601. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/26 2pp

--7908240151 IE Insp Rept 50-281/79-41 on 790529-0601. No noncompliance noted. Major areas inspected: steam generator replacement, welding & associated activities & nondestructive examinations.
KLEINSORGE, W P Region 2, Atlanta, Office of the Director
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/26 6pp

7908240208 Forwards IE Insp Repts 50-280/79-28 & 50-281/79-45 on 790604-08. No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/26 2pp

--7908240213 IE Insp Repts 50-280/79-28 & 50-281/79-45 on 790604-08. No noncompliance noted. Major areas inspected: seismic reanalysis of safety-related piping.
ELROD, S A, KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/26 4pp

7908240187 Forwards IE Insp Repts 50-280/79-34 & 50-281/79-52 on 790611-13. No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/27 2pp

--7908240196 IE Insp Repts 50-280/79-34 & 50-281/79-52 on 790611-13. No noncompliance noted. Major areas inspected: licensed operator requalification training program & licensee response to IE Bulletin 79-06A in areas of training.
TAYLOR, P A, FORD, E J Region 2, Atlanta, Office of the Director RUHLMAN, W A Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/25 4pp

7908080678 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/02 2pp

7908240275 Forwards IE Insp Rept 50-281/79-40 on 790521-25. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/02 2pp

--7908240284 IE Insp Rept 50-281/79-40 on 790521-25. No noncompliance noted. Major areas inspected: machining of weld prep for third generator shell & fit-up, welding level tap nozzle, & weld & post-weld heat treat procedures.
ERB, C M, DANIELSON, D H, HERDT, A R Region 2, Atlanta, Office of the Director 79/06/29 4pp

7908240317 Forwards IE Insp Repts 50-280/79-33 & 50-281/79-51 on 790611-14. No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/02 2pp

--7908240326 IE Insp Repts 50-280/79-33 & 50-281/79-51 on 790611-14. No noncompliance noted. Major areas inspected: IE Bulletin 79-03 followup re weld defects in stainless steel pipe spools mfg by Youngstown Welding & Engineering Co.
SKOLDS, J O, KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/29 5pp

7908010035 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/06 2pp

7908230688 Forwards IE Insp Rept 50-281/79-39 on 790619-22. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/09 2pp

--7908270691 IE Insp Rept 50-281/79-39 on 790619-22. No noncompliance noted. Major areas inspected: steam generator replacement program QA audits, control of nonconformance repts & welding activities.
GOUGE, M J, CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/06 4pp

7908010688 Ack receipt of 790627 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-281/79-33.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 1p

--7908010701 Responds to NRC 790604 ltr re violations noted in IE Insp Rept 50-281/79-33. Corrective actions: requisitions corrected, key returned to proper authority & identification sketch corrected.
STALLINGS, C M Virginia Electric & Power Co 79/06/27 3pp

--7908010709 Forwards IE Insp Rept 50-281/79-33 on 790507-10 & notice of violation.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/04 2pp

--7908010715 Notice of violation from insp on 790507-10.
* Region 2, Atlanta, Office of the Director 79/05/30 2pp

--7908010721 IE Insp Rept 50-281/79-33 on 790507-10. Noncompliance noted: failure to maintain receipts of insp results & to follow procedure re control of welding electrodes.
KLEINSORGE, W P, CONLON, T E Region 2, Atlanta, Office of the Director 79/05/30 5pp

7908240194 Forwards IE Insp Rept 50-281/79-48 on 790611-14. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 2pp

--7908240202 IE Insp Rept 50-281/79-48 on 790611-14. No noncompliance noted. Major areas inspected: nondestructive test results on weld buildup for hot & cold leg recirculation fittings & main steam welds.
ERB, C M, HERDT, A R Region 2, Atlanta, Office of the Director
DANIELSON, D H Region 3, Chicago, Office of the Director
79/07/09 4pp

7908150187 Ack receipt of 790705 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/79-24 & 50-281/79-42.
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/12 1p

--7908150200 Responds to NRC 790620 ltr re violation noted in IE Insp Repts 50-280/79-24 & 50-281/79-42. Corrective actions: svc desk manned by health physics personnel has been set up & QA manual change submitted.
STALLINGS, C M Virginia Electric & Power Co 79/07/05 2pp

--7908150206 Forwards IE Insp Repts 50-280/79-24 & 50-281/79-42 on 790529-31 & notice of violation.
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/20 2pp

--7908150210 Notice of violation from insp on 790529-31.
* Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/20 1p

--7908150216 IE Insp Repts 50-280/79-24 & 50-281/79-42 on 790529-31. Noncompliance noted: failure to follow radiation work permit requirements.
EWALD, S C Region 2, Atlanta, Office of the Director
JENKINS, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/20 5pp

7908030144 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/13 2pp

7908070743 Responds to IE Bulletin 79-11 re use of Westinghouse DB-50 & DB-75 circuit breakers. Notifies that specified circuit breakers are in use, but w/o overcurrent trip feature.
STALLINGS, C M Virginia Electric & Power Co 79/07/13 2pp

7908080151 Responds to IE Bulletin 79-13, Item 5, re cracking in feedwater sys piping. Discusses schedule for insp of feedwater piping welds & procedures to identify & respond to feedwater line break accident.
STALLINGS, C M Virginia Electric & Power Co 79/07/13 4pp

DOCKTED ITEMS

7908010418 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/17 2pp

7908060362 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/17 2pp

7908150238 Ack receipt of 790629 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/79-23 & 50-281/79-35.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/17 1p

--7908150247 Responds to NRC 790605 ltr re violation noted in IE Insp Repts 50-280/79-23 & 50-281/79-35. Corrective actions: drawings found not to be of latest revision were reissued & controlled drawing sets reduced in number.
STALLINGS, C M Virginia Electric & Power Co 79/06/29 2pp

--7908150254 Forwards IE Insp Repts 50-280/79-23 & 50-281/79-35 on 790509-11 & notice of violation.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/05 2pp

--7908150264 Notice of violation from insp on 790509-11.
* Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/05 1p

--7908150274 IE Insp Rept 50-280/79-23 & 50-281/79-35 on 790509-10. Noncompliance noted: failure to follow procedures for drawings.
BROWNLEE, V L / KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/05 5pp

7908030042 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908080063 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908130281 Notifies that IE Bulletin 79-14 is revised to limit scope of required work. Forwards replacement page.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908060524 Forwards IE Bulletin 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/26 1p

7908070761 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/26 2pp

7908080728 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/26 2pp

7908160276 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/27 2pp

7908240140 Ack receipt of 790719 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-281/79-38.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/30 1p

--7908240156 Responds to NRC 790629 ltr re violation noted in IE Insp Rept 50-281/79-38. Corrective actions: contractor instructed to use only written instructions in proper format w/required approval signatures.
STALLINGS, C M Virginia Electric & Power Co 79/07/19 2pp

--7908240159 Forwards IE Insp Rept 50-281/79-38 on 790522-25 & notice of violation.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/29 2pp

--7908240162 Notice of violation from insp on 790522-25.
* Region 2, Atlanta, Office of the Director 79/06/11 1p

--7908240168 IE Insp Rept 50-281/79-38 on 790522-25 Noncompliance noted: steam generator support feet helicoil replacement.
WILCOX, J D Region 2, Atlanta, Office of the Director
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/11 3pp

7908310018 Responds to IE Bulletins 79-14 & 14, Revision 1, re seismic analysis for as-built safety-related piping sys. Discusses progress of verification program for design criteria. Lists of design documents encl.
SPENCER, W C Virginia Electric & Power Co 79/08/01 100pp

7908220655 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/08/07 2pp

7908170016 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/08/08 2pp

7908290225 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/08/10 2pp

7908240594 Discusses special insp on 790415-19 as result of employee exposure in excess of 10 rems & forwards notices of violation & proposed imposition of civil penalties.
STELLO, V Office of Inspection & Enforcement, Office of the Director 79/08/15 2pp

--7908240598 Notice of violation from insp on 790415-19 Details imposition of civil penalties.
* Region 2, Atlanta, Office of the Director 79/08/15 2pp

--7908240600 Notice of proposed imposition of civil penalties in amount of $15,000. Violation involved employee overexposure due to lack of warning notices in high radiation areas.
* Region 2, Atlanta, Office of the Director 79/08/15 1p

R Periodic operating reports & related correspondence

7908160348 Forwards monthly operating rept for Jul 1979.
STALLINGS, C M Virginia Electric & Power Co 79/08/13 1p

--7908160352 Monthly operating rept for Jul 1979.
COSTELLO, D J Virginia Electric & Power Co 79/08/02 43pp

S Reportable occurrences, LERs & related correspondence

7908160479 Forwards update to LER 78-034/01X-2.
STALLINGS, C M Virginia Electric & Power Co 79/08/13 1p

--7908160484 Update to LER 78-034/01X-2 on 781101. 17 spare process piping containment penetrations were not capped. Condition has been overlooked since const. Design change approved to weld caps on open ends.
STEWART, W L Virginia Electric & Power Co 79/08/10 2pp

7908280660 Forwards LER 79-011/03X-1.
STALLINGS, C M Virginia Electric & Power Co 79/08/23 1p

--7908280667 LER 79-011/03X-1 on 790828 process & ventilation particulates & gaseous monitors were w/o power on two occasions. Caused by loose lug connection on power supply cable. Loose connection repaired & plants restored to svc.
STEWART, W L Virginia Electric & Power Co 79/08/21 2pp

U Congressional/Executive Correspondence

7908020232 Ack receipt of 790318 ltr to President Carter re NRC order to shut down five nuclear plants for seismic reasons. Review of piping sys is in progress. Forwards earthquake map for VA.
DENTON, H R Office of Nuclear Reactor Regulation 79/06/06 3pp

--7908020241 Forwards CJ Hemmer 790318 ltr for response. Ltr protests closing of five nuclear power plants for seismic reasons.
ZINN, P K President of US & Executive Offices 79/03/21 2pp

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7908130200 Notifies that review of safeguards contingency plan involves consideration of safeguards issue; requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch 79/07/03 1p.

7908010584 Forwards appropriate licensing fee for safeguards contingency plan, in response to 790703 request.
MAYER, L. O. Northern States Power Co. 79/07/20 4pp.

7908230311 Forwards security force training & qualification plan. Plan withheld (ref 10CFR2.790).
MAYER, L. O. Northern States Power Co. 79/08/17 1p.

7908280555 Forwards appropriate licensing fee for NRC review & approval of util 790817 security force training & qualification plans.
MAYER, L. O. Northern States Power Co. 79/08/23 3pp.

G. Adjudicatory correspondence

7908170289 Urges NRC to reject 790618 request of MN Pollution Control Agency to reopen record of spent fuel pool mod proceeding. Matter can be resolved by generic rulemaking rather than piecemeal adjudication.
REYNOLDS, W. B. Shaw, Pittman, Potts, & Trowbridge 79/06/29 2pp.

H. General correspondence

7908210319 Forwards "Mgt & Technical Resources, Jul 1979," per NRC 790629 info request re util ability to handle emergency situations financially.
MAYER, L. O. Northern States Power Co. 79/08/10 1p.

--7908210321 "Mgt & Technical Resources, Jul 1979."
* Northern States Power Co. 79/08/31 225pp.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908150335 Intends to ship radioactive matl from facilities using Package PB-1.
MAYER, L. O. Northern States Power Co. 79/06/08 1p.

7908130402 Notifies of intent to ship radioactive matl using certified shipping package Model 7-100.
MAYER, L. O. Northern States Power Co. 79/06/19 1p.

7908070674 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/22 3pp.

7908230647 Forwards "Steam Generator Water Hammer Technical Evaluation." Recommends installation of top discharge feedrings in all steam generators & test program to qualify effect of auxiliary feedwater on water hammer.
DEARIEN, J. A. EG & G, Inc. 79/06/27 2pp.

--7908230650 "Steam Generator Water Hammer Technical Evaluation."
* EG & G, Inc. 79/06/30 17pp.

7908140309 Notifies of intent to ship radioactive matl in Model QE-600.
MAYER, L. O. Northern States Power Co. 79/07/05 1p.

7908130306 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires initial notification of NRC.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/09 1p.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908070343 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/19 1p.

7908270303 Forwards request for addl info re degraded grid voltage to be sent to licensee in order to complete review of 780504 submittal. Response required within 45 days.
LAINAS, G. Plant Systems Branch 79/07/23 3pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp.

7908290646 Forwards request for addl info to util 790504 submittal re potential equipment failure due to degraded grid voltage.
SCHWENCER, A. Operating Reactors Branch 1 79/07/30 3pp.

7908060375 Forwards "Cycle 5 Startup Physics Test Rept."
MAYER, L. O. Northern States Power Co. 79/08/01 1p.

--7908060379 "Cycle 5 Startup Physics Test Rept."
* Northern States Power Co. 79/08/01 9pp.

7908080455 Confirms delay until 790813 to respond to 790629 request & WP Haass ltr re info on mgt & technical resources available to licensees for response to nuclear plant emergencies.
MAYER, L. O. Northern States Power Co. 79/08/02 1p.

7908170318 Ack receipt of 790702 application for proposed changes to Tech Spec Section 2.3 re exclusion of certain valve exercising tests during plant operation. Application involves safety issue; therefore, Class 3 amend fee required.
MILLER, W. O. License Fee Management Branch 79/08/02 2pp.

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees, for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp.

7908290260 Forwards Amends 37 & 31 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1 79/08/02 2pp.

--7908290269 Amends 37 & 31 to Licenses DPR-42 & DPR-60 changing Tech Specs in Apps A & B.
SCHWENCER, A. Operating Reactors Branch 1 79/08/02 2pp.

--7908290294 Safety evaluation supporting Amends 37 & 31 to Licenses DPR-42 & DPR-60, respectively.
* Office of Nuclear Reactor Regulation 79/08/02 6pp.

--7908290303 Notice of issuance & availability of Amends 37 & 31 to Licenses DPR-42 & DPR-60, respectively.
SCHWENCER, A. Operating Reactors Branch 1 79/08/02 2pp.

7908160118 Forwards Amends 38 & 32 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1 79/08/03 2pp.

--7908160129 Amends 38 & 32 to Licenses DPR-42 & DPR-60, respectively, incorporating new definitions, limiting conditions for operation & adding surveillance requirement for reactor cooling sys overpressure protection sys.
SCHWENCER, A. Operating Reactors Branch 1 79/08/03 10pp.

--7908160138 Safety evaluation supporting Amends 38 & 32 to Licenses DPR-42 & DPR-60, respectively.
* Office of Nuclear Reactor Regulation 79/08/03 14pp.

--7908160143 Notice of issuance & availability of Amends 38 & 32 to Licenses DPR-42 & DPR-60, respectively.
SCHWENCER, A. Operating Reactors Branch 1 79/08/03 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & rapts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7906200326 Describes re-evaluation of potential steam generator water hammer. Forwards table of operating experience & feedwater piping configurations. Water hammer not likely to occur un[der] any conditions.
DEARIEN, J. A. EG & G, Inc. 79/08/06 3pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09 56pp.

9. Inspection reports, IE Bulletins & correspondence

7908070048 Responds to IE Bulletin 79-11. Reactor trip breakers are used in safety-related sys. Breakers do not have overtrip feature.
WACHTER, L. J. Northern States Power Co. 79/06/04 1p.

7908160117 Forwards IE Insp Repts 50-282/79-13 & 50-306/79-10 on 790501-31 & notice of violation.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/27 2pp.

--7908160120 Notice of violation from insp on 790501-31.
* Region 3, Chicago, Office of the Director. 79/06/26 1p.

--7908160130 IE Insp Repts 50-282/79-13 & 50-306/79-10 on 790501-31. Noncompliance noted: failure to perform quarterly exercise test of two valves.
FEIERABEND, C. D.; DANIELS, F. T.; WARNICK, R. F. Region 3, Chicago, Office of the Director. 79/06/26 13pp.

7908080538 Submits schedule for response to IE Bulletins 78-12, 12A & 12B. Info will be available by 790731.
WACHTER, L. J. Northern States Power Co. 79/06/29 1p.

7908150080 Ack receipt of 790531 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-282/79-01 & 50-306/79-01.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/29 1p.

--7908150090 Responds to NRC 790215 ltr re violations noted in IE Insp Repts 50-282/79-01 & 50-306/79-01. Corrective actions: general review of methods undertaken to assure prompt identification of def ciencies & subsequent corrections.
WACHTER, L. J. Northern States Power Co. 79/05/31 4pp.

7908140319 Responds to IE Bulletin 79-02. Analytical & experimental generic program used for baseplate analysis. Reviewed all Seismic Category I pipe supports & found expansion anchor bolts are shell type.
WACHTER, L. J. Northern States Power Co. 79/07/06 3pp.

7908090595 Submits further response to IE Bulletin 79-06A, Revision 1, Item 10. All safety-related maint procedures were reviewed. Procedures will be improved by independent verification.
WACHTER, L. J. Northern States Power Co. 79/07/13 1p.

7908130407 Responds to IE Bulletin 79-13 re feedwater cracks. No cracks in Unit 1. Emergency procedures are adequate to recognize & respond to feedwater line breaks.
WACHTER, L. J. Northern States Power Co. 79/07/13 2pp.

7908020342 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20 1p.

7908290291 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26 1p.

7908290370 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26 1p.

7908300446 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26 1p.

7908160363 Responds to IE Bulletin 79-14, Item 1. Discusses insp elements & approach, design documents & insp program timetable.
WACHTER, L. J. Northern States Power Co. 79/08/01 4pp.

7908150371 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07 1p.

7908170024 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08 1p.

7908300290 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15 1p.

R. Periodic operating reports & related correspondence

7908060267 Submits Environ Event Rept 79-06 re cooling tower operations for July 1979. Average daily blowdown flow in excess of 150 cubic ft per second was required for only nine days because Unit 1 was removed from svc.
WARD, E. C. Northern States Powr 79/08/01 1p.

7906140759 Forwards "Effluent & Waste Disposal Semiannual Rept" for Jan-June 1979.
MAYER, L. O. Northern States Power Co. 79/08/10 1p.

--7908140765 "Effluent & Waste Disposal Semiannual Rept" for Jan-June 1979.
* Northern States Power Co. 79/06/30 9pp.

7908160437 Forwards monthly operating rept for Jul 1979.
MAYER, L. O. Northern States Power Co. 79/08/13 1p.

--7908160440 Monthly operating rept for Jul 1979.
HUNSTAD, A. A. Northern States Power Co. 79/08/01 8pp.

S. Reportable occurrences, LERs & related correspondence

7908200290 Forwards LER 79-022/03L-0.
MAYER, L. O. Northern States Power Co. 79/08/15 1p.

--7908200293 LER 79-022/03L-0 on 790716: bistable in steam exclusion actuation sys tripped three degrees above limit during surveillance test. Caused by drift of Foxboro bistable Model 63U-CC-OHDR-F. Bistable inspected & recalibr.
HUNSTAD, A. A. Northern States Power Co. 79/08/15 1p.

7908280540 Forwards LER 79-023/03L-0.
MAYER, L. O. Northern States Power Co. 79/08/24 1p.

--7908280542 LER 79-023/03L-0 on 790726: design deficiency was found in motor driven auxiliary feedwater pump low lube oil pressure circuitry in each unit. Redundant turbine driven pumps are unaffected. Design change has been initiated.
HUNSTAD, A. A. Northern States Power Co. 79/08/24 1p.

7908280586 Forwards LER 79-024/03L-0.
MAYER, L. O. Northern States Power Co. 79/08/24 1p.

--7908280591 LER 79-024/03L-0 on 790731: safety injection pump test SP 1088 was not completed during hot shutdown as required. Caused by personnel error.
HUNSTAD, A. A. Northern States Power Co. 79/08/24 1p.

DOCKET 50-284 IDAHO STATE UNIV. RESEARCH REACTOR

9. Inspection reports, IE Bulletins & correspondence

7908010010 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/07/06 1p.

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7908270221 Ack receipt of 790320 ltr transmitting safeguards contingency plan for facility Class III fee required.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp.

7908220300 Forwards revised physical security plan Plan withheld (ref 10CFR2.790).
SHORT, T. E. Omaha Public Power District 79/08/17 1p.

H. General correspondence

7908010553 Responds to NRC 790629 ltr requesting info re organization & qualifications of util personnel Organizational chart, mgt responsibilities & resumes encl Encl withheld (ref 10CFR2.790).
SHORT, T. E. Omaha Public Power District 79/07/27 1p.

P. Operating license stage documents & correspondence

7908030136 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908130359 Notifies all operating plants using C-E-designed reactors of generic review re TMI Requests attendance at 790612 meeting in Bethesda, MD re info needed by NRC to complete review.
STOLZ, J. F. Light Water Reactors Branch 1 79/06/05 16pp.

7908140294 Summary of 790327 meeting w/util in Bethesda, MD re stretch power primary pressure increase & conversion to Exxon fuel.
CONNER, E. L. Operating Reactors Branch 4 79/06/28 14pp.

7908030422 Forwards Amend 46 to License DPR-40, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4 79/07/02 3pp.

--7908030428 Amend 46 to License DPR-40 incorporating surveillance requirements for inservice insp on steam generator tubes.
REID, R. W. Operating Reactors Branch 4 79/07/02 15pp.

--7908030433 Safety evaluation supporting Amend 46 to License DPR-40.
* Office of Nuclear Reactor Regulation 79/07/02 49pp.

--7908030438 Notice of issuance & availability of Amend 46 to License DPR-40.
REID, R. W. Operating Reactors Branch 4 79/07/02 3pp.

7908010498 Forwards completed steam generator operating history questionnaire, including updated info re generator tube during 1978 refueling outage.
SHORT, T. E. Omaha Public Power District 79/07/18 23pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/18 58pp.

7908070358 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors Info requests will not be made while plant is in shutdown mode.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/07/18 1p.

7908200105 Requests submittal of proposed amend to license to delete Tech Specs re secondary water chemistry monitoring program & to incorporate requirements of encl model license condition. Requests submittal within 60 days.
REID, R. W. Operating Reactors Branch 4 79/07/23 4pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908070631 Responds to NRC 770927 ltr Forwards info re long-term core cooling, long-term ECCS realignment following LOCA & long-term cooling plan & performance evaluation.
SHORT, T. E. Omaha Public Power District 79/07/30 27pp.

7908070651 Submits justification demonstrating that deleting all nonradiological water quality monitoring & reporting requirements for App B of Tech Specs will not result in adverse environ impact.
SHORT, T. E. Omaha Public Power District 79/08/01 12pp.

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees, for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp.

7908 00458 Forwards proprietary & non-proprietary versions of Amend 1 to CEN-114, "Review of Small Break Transients in C-E NSSS." LIEBLER, G. E. C-E Operating Plants Owners Group 79/08/03 6pp.

--7908100465 Amend 1-NP to CEN-114-NP, "Review of Small Break Transient in C-E Nuclear Steam Supply Sys." CEN-144-P withheld (ref 10CFR2.790).
* Combustion Engineering, Inc. CEN-114-P A 01 79/07/31 111Opp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 50pp.

7908140603 Responds to request for info re operation of pressurizer heaters Provides breakdown of 12 groups of heaters & discusses motor control ctrs.
SHORT, T. E. Omaha Public Power District 79/08/06 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 5pp.

7908140394 Forwards addl info re PWR feedwater sys in response to NRC 790525 request Details of process used to make nozzle-to-pipe & pipe-to-sparger welds encl.
SHORT, T. E. Omaha Public Power District 79/08/10 2pp.

7908170428 Forwards CEN-114-NP Amend 1, "Review of Small Break Transients in C-E Nuclear Steam Supply Sys." Proprietary version CEN-114 P withheld (ref 10CFR2.790).
SCHERER, A. E. C-E Power Systems 79/08/10 1p.

7908270405 Responds to NRC 790605 ltr re small break LOCA analysis C-E rept, "Review of Small Break Transients in C-E Nuclear Steam Supply Sys," CEN-114-P, constitutes response to request for addl info.
SHORT, T. E. Omaha Public Power District 79/08/14 1p.

7908300630 Forwards required Class III license fee payment re util 790702 appl for amend to OL.
SHORT, T. E. Omaha Public Power District 79/08/22 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908020102 Forwards IE Insp Rept 50-285/79-07 on 790430-0503 & 0505-10. No noncompliance noted.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/25 2pp.

--7908020105 IE Insp Rept 50-285/79-07 on 790430-0503 & 0505-10 No noncompliance noted Major areas inspected: licensee response to IE Bulletin 79-06B, operator & staff training, review of surveillance & emergency procedures & operator interviews.
KELLEY, D. L. Region 4, Dallas, Office of the Director. WESTERMAN, T. F., MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/24 11pp.

7908080406 Submits addl facts in response to IE Bulletin 79-06B re util 790423 ltr committing station to posting of individual in main control room w/duty of initiating auxiliary feedwater. Relief from commitment requested.
SHORT, T. E. Omaha Public Power District 79/05/25 2pp.

DOCKETED ITEMS

7908030201 Forwards IE Insp Rept 50-285/79-08 on 790520-24. No noncomliance noted.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/08 2pp.

--7908030206 IE Insp Rept 50-285/79-08 on 790520-24. No noncompliance noted. Major areas inspected design changes & mod program, procedures & records.
KELLEY, D. L. ; WESTERMAN, T. F Region 4, Dallas, Office of the Director 79/06/08 3pp.

7908090459 Responds to IE Bulletin 79-01A. Environmentally unqualified ASCO solenoid valves were reported by 790515, 790529 & 790613 ltrs. Preventive maint program will be developed to replace unqualified valves.
SHORT, T. E. Omaha Public Power District 79/06/26 2pp.

7908170239 Responds to IE Bulletin 79-11 request for info re use of Westinghouse DB-50 & DB-75 circuit breakers. None installed or in storage at facility.
SHORT, T. E. Omaha Public Power District 79/06/26 1p.

7908160041 Responds to IE Bulletins 79-12, 12A & 12B. Forwards C-E 790608 ltr which submitted generic rept, "Info Requested by IE Bulletin 79-12, Atypical Weld Matl in Reactor Pressure Vessel Welds," & vendor certification.
SHORT, T. E. Omaha Public Power District 79/06/27 2pp.

7908010003 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/07/06 1p.

7908290244 Forwards response to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion anchor bolts. Final rept will be submitted by 790815.
SHORT, T. E. Omaha Public Power District 79/07/06 27pp.

--7908290267 "Base Plate Structural Analysis Sys, Ansys Pre- & Post-Processors for Finite Element Data Generation & Load Summary," Revision B.
* Teledyne Engineering Services 79/06/11 41pp.

7908160038 Responds to IE Bulletin 79-13 re feedwater line break accidents. Submits info re insp schedule, adequacy of operating & emergency procedures & methods & sensitivity of detection of leaks in containment.
SHORT, T. E. Omaha Public Power District 79/07/13 2pp.

7908170524 Requests extension of time to provide info & perform insp per IE Bulletin 79-14 re seismic analyses for Category 1 piping sys.
SHORT, T. E. Omaha Public Power District 79/07/16 1p.

7908020399 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/07/18 1p.

7908060021 Forwards IE Bulletins 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/07/26 1p.

7908060043 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/07/26 1p.

7908060128 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/07/26 1p.

7908130036 Requests addl info to suppl previous response to IE Bulletin 79-06B. Addl info necessary for completion of safety evaluation.
REID, R. W. Operating Reactors Branch 4 79/07/26 3pp.

7908230668 Ack receipt of 790625 & 0711 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/79-05.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/26 1p.

--7908230671 Responds to NRC 790606 ltr re violations noted in IE Insp Rept 50-285/79-05. Corrective actions, any altered barrier will receive initial insp before declared operable.
SHORT, T. E. Omaha Public Power District 79/06/25 1p.

7908080531 Forwards response to IE Bulletin 79-14, Item 1 re seismic analysis for as-built safety-related piping sys.
SHORT, T. E. Omaha Public Power District 79/08/03 1500pp.

7908140683 Requests extension of deadline to inspect feedwater nozzle-to-pipe area as specified by IE Bulletin 79-13. Proposed date of insp is Jan 1980, during next scheduled refueling outage. Study encl.
SHORT, T. E. Omaha Public Power District 79/08/08 6pp.

--7908140695 "Study of Crack Growth Rate in Fort Calhoun Feedwater Nozzle."
KUSHNER, A. S. Pacifica Technology NICKELL, R. E. ; DUNHAM, R. S. Affiliation Unknown PT-U79-0357 79/07/31 81pp.

7908160053 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/08/10 1p.

7908160439 Forwards responses to IE Bulletin 79-06B re review of operating procedures in light of TMI incident. Hydrogen purge sys procedure reviewed.
SHORT, T. E. Omaha Public Power District 79/08/10 5pp.

R. Periodic operating reports & related correspondence

7908140755 Forwards monthly operating rept for Jul 1979.
SHORT, T. E. Omaha Public Power District 79/08/09 1p.

--7908140758 Monthly operating rept for Jul 1979.
HICKLE, B. J. Omaha Public Power District 79/08/09 8pp.

S. Reportable occurrences, LERs & related correspondence

7908010703 Forwards PNO-79-67AX.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/20 1p.

7908210441 Forwards LER 79-017/03L-0.
ANDREWS, R. J. Omaha Public Power District 79/08/17 1p.

--7908210450 LER 79-017/03L-0 on 790724 during normal operation, D channel wide range nuclear instrumentation failed w/complete loss of power. Caused by blown main power fuses. Fuses replaced & instrumentation placed in svc.
KUSIK, L. T. Omaha Public Power District 79/08/06 4pp.

7908210587 Forwards LER 79-018/03L-0.
ANDREWS, R. L. Omaha Public Power District 79/08/17 1p.

--7908210465 LER 79-018/03L-0 on 790724: steam generator A pressure indicator ccontroller for C channel would not reset. Caused by failure of sigma meter integrally installed trip setpoint. Trip circuit replaced & meter calibr.
KUSEK, L. T. Omaha Public Power District 79/08/09 4pp.

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

7908130202 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp.

7908010489 Discusses revised emergency plan submitted to NRC on 790329. Revision 1 to plan will be in effect on 790820.
BAYNE, J. P. Power Authority State of New York 79/07/26 1p.

7908280020 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
BERRY, G. T. Power Authority State of New York 79/08/20 1p.

Q. Adjudicatory correspondence

7908160111 Responds to 790323 request for assessment of reactor earthquake resistence & re-examination of computer codes used for seismic analyses nuclear plants. Re-examinations undertaken; no basis found for restricting operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/25 2pp.

--7908160114 Requests assessment of resistance of reactor to earthquake & re-examination of corputer codes used for seismic analyses of nuclear power plants.
DICKINSON, I. P. Citizens Committee for Protection of the Environment 79/03/23 1p.

7908300025 Responds to 790518 ltr re plant shutdown. Forwards 790606 memo re creation of hydrogen IE Bulletin 79-06A addressed review of operation modes & procedures re hydrogen generated during transient. W/o encl.
GAMMILL, W. P. Assistant Director for Operating Reactor Projects. 79/07/30 3pp.

7908220409 Memo submitting opinion of MC Farrar re dissenting vote concerning portions of ALAB-422 & ALAB-436. Majority will respond after review.
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 79/08/03 58pp.

H. General correspondence

7908230242 Responds to 790323 ltr requesting info re assessment of reactor earthquake resistance & re-examination of computer codes used for seismic analyses. Re-examinations found no basis for discontinuing operation of facilities.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/25 2pp.

P. Operating license stage documents & correspondence

7905150673 Responds to 790413 request. Forwards "Comparision of Simulation Models Used in Assessing Effects of Power Plant Induced Mortality on Fish Populations." W/o encl.
MOORE, J. E. Branch 2 79/04/18 1p.

7907190774 FOIA request for NRC Annual Rept 1978, recent studies by NRC of TMI rept indicating methods to cool down TMI core & environ impact studies of Indian Point facility, Brookhaven Natl Lab & West Valley nuclear fuel reprocessing plant.
RADNOR Affiliation Unknown 79/05/02 1p

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908060538 Authorizes continued unit operation based on util 790524 & 31 ltrs in response to NRC seismic concerns expressed in 790522 & 23 meetings re IE Bulletin 79-07.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625) 79/06/22 2pp.

7908070463 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp.

7908220229 Forwards Amend 27 to License DPR-64 & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1 79/07/11 4pp.

--7908220235 Amend 27 to License DPR-64 revising Tech Specs to consolidate all ref to thermal plume mapping into Section 4.1.1.a without changing scope of survey program.
SCHWENCER, A. Operating Reactors Branch 1 79/07/11 13pp.

--7908220239 Notice of issuance & availability of Amend 27 to License DPR-64.
SCHWENCER, A. Operating Reactors Branch 1 79/07/11 2pp.

7908220586 Ack receipt of accelerograph network layout & offers suggestions. Util response spectra & table of damping values used encl.
REITHER, L. Geosciences Branch 79/07/17 4pp.

7908070251 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908270355 Forwards request for addl info to be sent to licensee in order to complete review of 770829 submittal re Technical Assistance Concracts 10028 & 10029. Response required within 45 days.
LAINAS, G. Plant Systems Branch 79/07/18 3pp.

7908010343 Notifies that new milk sampling location has been chosen per ETS. New site is Hilltop Hanover Farm.
CAHILL, W. J. Consolidated Edison Co. of New York 79/07/19 2pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908220288 Notifies that 770829 ltr from Con Ed re degraded grid voltage does not comply w/intent of positions in NRC 770603 ltr. Submits request for addl info re degraded grid voltage. Requests response within 60 days.
SCHWENCER, A. Operating Reactors Branch 1 79/07/27 3pp.

7908230689 Notification of 790307 meeting w/Public Svc Electric & Gas Co in Bethesda, MD to discuss feasibility of using heat from garbage incinerators.
ROSS, W. J. Operating Reactors Branch 1 79/07/27 2pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp.

7908130579 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 4pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908310478 FOIA request for meteorological data, including wind direction & velocity, precipitation, relative humidity & barometric pressure, collected for past five years by facilities.
ROACH, K. Affiliation Unknown 79/08/03 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09 56pp.

7908170324 Forwards response to NRC 790629 request for info on mgt & technical resources.
EARLY, P. J. Power Authority State of New York 79/08/13 1p.

--7908170328 "Mgt & Technical Resources."
* Power Authority State of New York 79/08/13 200pp.

7908240372 Notifies that 1980 aquatic surveillance program will be modified; river population studies of entrainable size organisms will not be conducted & mark-recapture studies will be limited to yearling & older fish in 1980.
CAHILL, W. J. Consolidated Edison Co. of New York 79/08/20 3pp.

7908310485 Responds to FOIA request for meteorological data collected for past five years by facilities. Info located in Table 4A of "Effluent & Waste Disposal Semi-Annual Rept" available at specified LPDR.
FELTON, J. M. Division of Rules and Records 79/08/21 1p.

7908280700 Advises that util is eliminating administrative restrictions on fuel rod bowing limiting peaking factors in facility Tech Specs.
EARLY, P. J. Power Authority State of New York 79/08/22 2pp.

7908310564 Forwards Suppl 1 to application for amend to License DPR-64.
EARLY, P. J. Power Authority State of New York 79/08/24 4pp.

--7908310568 Suppl 1 to application for amend to License DPR-64. Revises App A Tech Specs to include results of pressurizer bubble analysis & core reactivity balance comparison limitations.
EARLY, P. J. Power Authority State of New York 79/08/24 33pp.

G. Inspection reports, IE Bulletins & correspondence

7908080152 Ack receipt of 790308 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/78-31. Withdraws second notice of violation.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/07/06 2pp.

--7908080160 Forwards IE Insp Rept 50-286/78-31 on 781126-1223 & notices of violation.
BRUNNER,E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/02/15. 3pp.

--7908080166 Notice of violation from insp on 781126-1223. Details withheld (ref 10CFR2.790).
* Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/02/09. 2pp.

--7908080171 Notice of violation from insp on 781126-1223.
* Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/02/09. 1p.

--7908080178 IE Insp Rept 50-286/78-31 on 781126-1223 Noncompliance noted: Failure to maintain limiting condition of operation as required by Tech Specs & failure to control vital area as required by security plan.
REBELOWSKI,T J; KEIMIG,R R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/02/09. 11pp.

7908160568 Responds to IE Bulletin 79-02,Revision 1. Support/anchor bolt analysis & random field survey efforts provide sufficient evidence that anchor bolts will be acceptable to bulletin requirements.
EARLY,P J. Power Authority State of New York. 79/07/06. 6pp.

7908160570 Responds to IE Bulletin 79-13.Feedwater nozzle-to-piping welds nondestructive examination will be performed during 790915 refueling outage.Operating & emergency procedures reviewed & determined to be adequate.
BAYNE,J P. Power Authority State of New York. 79/07/13. 2pp.

7908010514 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908020044 PNO-79-185 nonconservative analysis results of high energy line break inside containment discovered per Westinghouse 790621 notification.Info being evaluated & suppl orders will be generated to customers.
KLINGLER. Office of Inspection & Enforcement, Office of the Director. 79/06/22. 1p.

7908060393 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030267 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908100253 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908100347 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908020420 Forwards IE Bulletin 79-07 & weekly status rept as of 790727 on United Engineers & Constructors pipe stress analysis for critical lines.
EARLY,P J. Power Authority State of New York. 79/07/27. 2pp.

7908090316 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908280152 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908140564 Forwards weekly status rept as of 790803 on pipe stress analysis per IE Bulletin 79-07.
EARLY,P J. Power Authority State of New York. 79/08/08. 2pp.

7908230356 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/08. 1p.

7908270555 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/10. 1p.

7908280310 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310288 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908230360 Forwards weekly status rept as of 790810 on United Engineers & Constructors pipe stress reanalysis per IE Bulletin 79-07. Critical lines are being analyzed per 790531 ltr.
EARLY,P J. Power Authority State of New York. 79/08/15. 2pp.

7908300157 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

7908210539 Forwards notes of 790816-17 telcon between NRC & R Rigamonti of United Engineers & Constructors re IE Bulletin 79-07.
BERRY,G T. Power Authority State of New York. 79/08/17. 7pp.

7908280551 Forwards weekly status rept as of 790820 re United Engineers & Const piping reanalysis efforts for critical lines per 790531 ltr.
EARLY,P J. Power Authority State of New York. 79/08/21. 2pp.

R Periodic operating reports & related correspondence

7908160466 "Efficiency of 1.0 m2 Epibentic Sled for Collecting Young-of-the-Year Striped Bass,White Perch & Atlantic Tomcod in Hudson River Estuary,1978." Affidavit of JR Jannarone encl.
* Texas Instruments, Inc. 79/06/30. 19pp.

7908140510 Forwards monthly operating rept for Jul 1979.
BAYNE,J P. Power Authority State of New York. 79/08/08. 1p.

--7908140516 Monthly operating rept for Jul 1979.
CONNELL,C. Power Authority State of New York. 79/08/03. 6pp.

7908170399 Forwards species code list & info re circulating water temp, grc;s electrical output & river water discharge for Jul 1979 for Permit NY0004472.
MONTI,W A. Consolidated Edison Co. of New York. 79/08/10. 17pp.

7908220391 Forwards tabulation of daily record of fish collection for Jul 1979.
ZARAKAS,P. Consolidated Edison Co. of New York. 79/08/15. 4pp.

S Reportable occurrences, LERs & related correspondence

7908070362 RO 79-006/01T-0 on 790621 advised by Westinghouse that for high energy line breaks inside containment, potential water level bias could result in delayed protection signals. Setpoints adjusted.
BAYNE,J P. Power Authority State of New York. 79/06/22. 2pp.

7908170432 Forwards LER 79-007/03L-0.
BAYNE,J P. Power Authority State of New York. 79/08/13. 1p.

--7908170435 LER 79-007/03L-0 on 790715 during 70% power, observed mechanical seal leak on boric acid transfer pump due to unknown causes.Standby pump placed in svc while defective pump repaired.Returned to svc within 48 hours.
GUMBLE,F W. Power Authority State of New York. 79/08/13. 1p.

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

7908060146 Requests prompt forwarding of Class III fees for 790323 safeguards contingency plan.
DIGGS,R M. License Fee Management Branch. 79/07/03. 2pp.

7908010377 Submits followup to 790629 ltr re status of fire protection mods.Greenfield penetration inside conduit not sealed as required per upgrading commitment.Error corrected & work completed on 790720.
PARKER,W O. Duke Power Co. 79/07/26. 1p.

7908060517 Forwards amended safeguards contingency plan. Plan withheld (ref 10CFR2.790).
PARKER, W.O. Duke Power Co. 79/08/03. 1p.

7908210045 Submits facts re NRC policy concerning implementation of General Design Criterion 3 for fire protection. Urges completion of mods prior to Oct 1980. Submittal of info re open items & design details should be expedited.
EISENHUT, D.G. Division of Operating Reactors. 79/08/09. 2pp.

7908210004 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
PARKER, W.O. Duke Power Co. 79/08/17. 1p.

H. General correspondence

7908210023a Expresses concern re possible shutdown of Duke Power Co units & resulting higher util costs, unreliability of power & inadequate energy to operate mills. Strongly urges continuing generation of nuclear electricity.
DIXON, C.B. Clinton Mills. 79/05/30. 1p.

7908010286 Responds to 790427 ltr. Special document collection at Clemson Univ library will consist of ROs & monthly operating repts for plant.
SOUDER, J.L. Division of Rules and Records. 79/06/15. 1p.

7908230487 Forwards addl response to HR Denton 790629 ltr re qualifications & experience of steam production dept as of 790730. Resumes, summaries & organizational charts encl.
PARKER, W.O. Duke Power Co. 79/08/16. 400pp.

O. Advisory Committee on Reactor Safeguards reports & correspondence

7908210023 Discusses scram breaker failures which occurred over 3-wk period.
EPLER, E.P. Affiliation Unknown. 79/06/18. 8pp.

P. Operating license stage documents & correspondence

7908100400 Forwards chronologies of 770924 Davis-Besse & 750613 Oconee events. In both cases steam formed in RCS analogously to TMI event.
WRIGHT, R.L. ACRS - Advisory Committee on Reactor Safeguards. 79/05/03. 3pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors. 79/06/04. 52pp.

7909080436 Ack 790321 application re qualifications of site health physicist. Requests remittance of Class III amend fee which applicant incorrectly determined was not applicable.
DIGGS, R.M. License Fee Management Branch. 79/06/28. 1p.

7908030413 FOIA request for documents prepared by NRC re alternatives to Duke Power Co proposal to ship spent fuel from Oconee plant to McGuire plant.
ROISMAN, A.Z. Natural Resources Defense Council. 79/07/02. 1p.

7908290508 Submits review of fee considerations re feedwater sys & responses to IE Bulletin 79-05B regarding valve setpoints. Suggests fee schedule for each unit be determined in consistent manner.
MILLER, W.O. License Fee Management Branch. 79/07/05. 2pp.

7908080111 Forwards Amends 74, 74 & 71 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R.W. Operating Reactors Branch 4. 79/07/10. 2pp.

--7908080116 Amends 74, 74 & 71 to License DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs by deleting hydraulic suppressors replaced by mechanical suppressors.
REID, R.W. Operating Reactors Branch 4. 79/07/10. 11pp.

--7908080126 Safety evaluation supporting Amends 74, 74 & 71 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation. 79/07/10. 2pp.

--7908080134 Notice of issuance & availability of Amends 74, 74 & 71 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R.W. Operating Reactors Branch 4. 79/07/10. 2pp.

7908080266 Forwards Amends 75, 75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R.W. Operating Reactors Branch 4. 79/07/12. 2pp.

--7908080283 Amends 75, 75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively, deleting Tech Spec 4.13 re fuel surveillance.
REID, R.W. Operating Reactors Branch 4. 79/07/12. 9pp.

--7908080298 Safety evaluation supporting Amends 75, 75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Operating Reactors Branch 4. 79/07/12. 2pp.

--7908080311 Notice of issuance & availability of Amends 75, 75 & 72 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R.W. Operating Reactors Branch 4. 79/07/12. 2pp.

7908080331 Forwards Amends 76, 76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R.W. Operating Reactors Branch 4. 79/07/16. 3pp.

--7908080348 Amends 76, 76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively, deleting obsolete requirements from surveillance program re reactor bldg & substituting alternate surveillance tendon in reactor bldg dome.
REID, R.W. Operating Reactors Branch 4. 79/07/16. 11pp.

--7908080362 Safety evaluation supporting Amends 76, 76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Operating Reactors Branch 4. 79/07/06. 2pp.

--7908080373 Notice of issuance & availability of Amends 76, 76 & 73 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R.W. Operating Reactors Branch 4. 79/07/16. 2pp.

7908150720 Requests evaluation of semiscale small break experiment w/small break computer program by 790901.
ROSS, D.F. TMI-2 Unresolved Safety Issues. 79/07/16. 7pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D.G. Division of Operating Reactors. 79/07/18. 58pp.

7908170084 Discusses review of 780202 ltr re potential of reactor cavity annulus seal ring to become destructive missile. Requests demonstration that seal ring is not destructive or removal of seal ring no later than next refueling outage.
REID, R.W. Operating Reactors Branch 4. 79/07/18. 2pp.

7908030435 Responds to FOIA request for documents prepared by NRC &/or NRC consultants re alternatives to Duke Power Co proposal to ship spent fuel from Oconee to McGuire.
FELTON, J.M. Division of Rules and Records. 79/07/19. 2pp.

--7908030452 Requests that questions be transmitted to Duke Power Co re present March 1979 status of fuel storage capacity & present design heat removal capacity under normal & max conditions.
GLENN, R.D. Battelle Memorial Institute, Pacific Northwest Laboratory. 79/03/22. 1p.

--7908030462 Forwards questions for approval re proposed licensing of shipment of Oconee spent fuel to McGuire nuclear station.
GLENN, R.D. Battelle Memorial Institute, Pacific Northwest Laboratory. 79/03/22. 14pp.

--7908030474 EIA re storage of Oconee spent fuel at McGuire spent fuel pool.
* Office of Nuclear Material Safety & Safeguards. 78/11/30. 76pp.

7908070306 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908210052 Forwards Amends 77, 77 & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R.W. Operating Reactors Branch 4. 79/07/20. 2pp.

--7908210057 Amends 77,77 & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively, upgrading qualifications of site health physicist.
REID, R. W. Operating Reactors Branch 4 79/07/20 12pp.

--7908210062 Safety evaluation supporting Amends 77,77 & 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation 79/07/20 2pp.

--7908210064 Notice of issuance & availability of Amends 77,77,& 74 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R. W. Operating Reactors Branch 4 79/07/20 2pp.

7908130003 Requests util submit proposed amend to delete existing Tech Specs on secondary water chemistry monitoring & incorporate new requirements to inhibit steam generator tube degradation. Model license condition encl.
REID, T. W. Operating Reactors Branch 4 79/07/23 4pp.

7908170089 Requests util submit proposed secondary water chemistry program for incorporation in new license condition. Current STS re steam generator tube degradation are ineffective for all PWRs. Model license condition encl.
REID, R. W. Operating Reactors Branch 3 79/07/23 4pp.

7908010467 Responds to NRC 790629 request for description of util mgt & technical resources to support facility. Forwards Section 13.1 of topical rept DUKE-2 re conduct of operations.
PARKER, W. O. Duke Power Co. 79/07/24 3pp.

--7908010474 Topical rept DUKE-2, Section 13.1 re conduct of operations.
* Duke Power Co. 79/07/24 42pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908230056 Requests results of semiscale small break experiment be compared w/small break computer program being used by C-E in support of owners group. To date, evaluations of latter have been inconclusive.
ROSS, D. F. TMI-2 Bulletins & Orders 79/07/25 8pp.

7908010371 Responds to 790622 ltr. Info re model used in potential small break analysis, ref in util 790507 ltr, will be submitted by 790914.
PARKER, W. O. Duke Power Co. 79/07/26 1p.

7908010441 Forwards requested info re PWR feedwater lines, in response to V Stello 790525 ltr.
PARKER, W. O. Duke Power Co. 79/07/27 81pp.

7908300599 Summary of 790719 meeting w/utils in Bethesda, MD to discuss outstanding items from NRC orders & IE Bulletins generic to all B&W facilities.
CAPRA, R. A. TMI-2 Bulletins & Orders 79/07/31 24pp.

7908300618 Ack receipt of 780104 ltr, supplemented by 790717 ltr, requesting license amend re area surrounding Warehouse 4. Actions in compliance w/10CFR20. Amend unnecessary.
REID, R. W. Operating Reactors Branch 4 79/08/02 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908160239 Notification of 790809 meeting w/B&W owners group in Bethesda, MD to discuss long-term generic requirements for B&W operating plants.
CAPRA, R. A. TMI-2 Unresolved Safety Issues 79/08/06 2pp.

7908290561 Requests clarification of fee classification for radiation protection manager qualification Tech Spec changes.
MILLER, W. O. License Fee Management Branch 79/08/07 2pp.

7908270092 Forwards request for addl info re containment purge sys.
LAINAS, G. Plant Systems Branch 79/08/08 3pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908220340 Forwards summary of 790810 meeting w/NRC to discuss potential OBE/DBE design deficiency.
PARKER, W. O. Duke Power Co. 79/08/17 8pp.

7908230470 Forwards summary of 790810 meeting w/NRC re potential OBE/DBE design deficiency & responds to areas of concern raised during meeting.
PARKER, W. O. Duke Power Co. 79/08/17 8pp.

7908280658 Submits progress rept on long-term mods, including two motor-driven emergency feedwater pumps. Two-pump test, noted in NRC 790518 ltr, should no longer be required.
PARKER, W. O. Duke Power Co. 79/08/22 2pp.

7908280669 Forwards revised Tech Specs re auxiliary electrical sys & emergency power periodic testing.
PARKER, W. O. Duke Power Co. 79/08/22 1p.

--7908280672 Revised Tech Specs re auxiliary electrical sys & emergency power periodic testing.
* Duke Power Co. 79/08/22 12pp.

9. Inspection reports, IE Bulletins & correspondence

7907020065 Forwards IE site inspector daily repts for B&W reactors for 790419.
DAVIS, J. G. Office of Inspection & Enforcement, Office of the Director 79/04/20 1p.

7908090018 Forwards IE Insp Repts 50-269/79-10, 50-270/79-10 & 50-287/79-10 on 790402-06 & notice of violation.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/07 2pp.

--7908090020 Notice of violation from insp on 790402-06.
* Region 2, Atlanta, Office of the Director 79/06/07 3pp.

--7908090025 IE Insp Repts 50-269/79-10, 50-270/79-10 & 50-287/79-10 on 790402-06. Noncompliance noted: failure to follow procedures in QA program, failure to conduct audits & failure to review revised design changes.
RUHLMAN, W. A., KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch ASHENDEN, M. C. Region 2, Atlanta, Office of the Director 79/06/05 26pp.

7908010265 Forwards responses to IE Bulletins 79-01 & 01A re environ qualification of Class IE equipment & use of stem-mounted limit switches. One valve motor operator on Unit 2 & aluminum limit switch gear frame did not meet environ qualifications.
PARKER, W. O. Duke Power Co. 79/06/12 7pp.

7908030038 Clarifies 790612 responses to IE Bulletin 79-01. Statements re completion of corrective actions in context of current refueling outage on Unit 3. Mods will be completed prior to return to power operation.
PARKER, W. O. Duke Power Co. 79/06/19 1p.

7908070735 Supplements 790530 response to IE Bulletin 70-04. Discusses reanalysis of piping w/Velan check valves & mod to cross-connect HPI headers.
PARKER, W. O. Duke Power Co. 79/06/26 1p.

7908220281 Responds to NRC 790607 ltr re violations noted in IE Insp Repts 50-269/79-10, 50-270/79-10 & 50-287/79-10. Corrective actions: necessary work to correct leakage into warehouse completed.
PARKER, W. O. Duke Power Co. 79/06/29 8pp.

7908010026 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/06 2pp.

7908210379 Responds to IE Bulletins 79-02 & 79-02, Revision 1. Seismic Category I piping sys operability is not jeopardized by improperly installed expansion anchors. Continued operation is justified.
PARKER, W. O. Duke Power Co. 79/07/06 6pp.

7908030611 Ack receipt of 790621 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-09, 50-270/79 & 50-287/79-09.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 79/07/09 1p.

--7908030626 Forwards IE Insp Repts 50-269/79-09, 50-270/79-09 & 50-287/79-09 on 790409-13&notice of violation. Notice of Violation withheld (ref 10CFR2.790).
KENNA, W. B. Region 2, Atlanta, Office of the Director 79/05/25 2pp.

--7908030632 IE Insp Repts 50-269/79-09, 50-270/79-09 & 50-287/79-09 on 790409-13. Noncompliance noted: failure to control vehicles& deficiency in detection aids. Details withheld(ref 10 cfr 2.790).
FUCHKO, J. ; TOBIN, W. J. Region 2, Atlanta, Safeguards Branch. 79/05/24. 1p.

7908240303 Forwards IE Insp Repts 50-269/79-13, 50-270/79-13 & 50-287/79-14 on 790529-0601 & 05-06. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 2pp.

--7908240311 IE Insp Repts 50-269/79-13, 50-270/79-13 & 50-287/79-14 on 790529-0601 & 05-06. No noncompliance noted. Major areas inspected: emergency feedwater & high pressure injection mod.
ECONOMOS, N. ; HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/06. 8pp.

7908160569 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/78-28, 50-270/78-27 & 50-287/78-28.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/12. 1p.

7908030114 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7906070805 Responds to IE Bulletin 79-11 re use of D-75 circuit breakers. Notifies that Westinghouse Type DB-75 circuit breakers are installed in Keowee Hydro Station. Rept re items 2, 3 & 4 will be provided by 790815.
PARKER, W. O. Duke Power Co. 79/07/13. 1p.

7908070815 Responds to IE Bulletin 79-13 re feedwater sys welds. Insp of welds will be conducted at next refueling outage for each unit. Final evaluation & review to be completed by 790720.
PARKER, W. O. Duke Power Co. 79/07/13. 1p.

7908010405 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030002 Forwards IE Circular 78-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080038 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130108 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908220673 Supplements response to IE Bulletin 79-13 re feedwater line breaks. Feedwater leaks in containment may be detected & confirmed by several parameters.
PARKER, W. O. Duke Power Co. 79/07/23. 2pp.

7908150408 Submits addl info re 790713 ltr concerning IE Bulletin 79-11. Correct designation of breakers is Type DB-50.
PARKER, W. O. Duke Power Co. 79/07/24. 1p.

7908080647 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908090369 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908220222 Ack receipt of 790629 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-10, 50-270/79-10 & 50-287/79-10.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/26. 1p.

7908160207 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908130039 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/31. 1p.

7908160271 Ack receipt of IE Insp Repts 50-269/79-13, 50-270/79-13 & 50-287/79-14. No proprietary info.
PARKER, W. O. Duke Power Co. 79/08/01. 1p.

7908300024 Ack receipt of IE Insp Repts 50-269/79-16, 50-270/79-15 & 50-287/79-17 on 790601-30.
PARKER, W. O. Duke Power Co. 79/08/06. 1p.

--7908300534 Forwards IE Insp Repts 50-269/79-16, 50-270/79-15 & 50-287/79-17 on 790601-30. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/25. 2pp.

--7908300544 IE Insp Repts 50-269/79-16, 50-270/79-15 & 50-287/79-17 on 790601-30. No noncompliance noted. Major areas inspected: plant operations, maint, security, training, LER followup, radiation protection & strike planning.
JAPE, F. ; BRADFORD, W. H. ; ELISLE, G. A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/23. 12pp.

7908160137 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

7908170010 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08. 2pp.

7908290190 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/10. 2pp.

7908280431 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

R. Periodic operating reports & related correspondence

7908210529 Forwards monthly operating rept for Jul 1979.
PARKER, W. O. Duke Power Co. 79/08/15. 1p.

--7908210532 Monthly operating rept for Jul 1979.
REAVIS, J. A. Duke Power Co. 79/08/15. 5pp.

S. Reportable occurrences, LERs & related correspondence

7908270324 Forwards list of ROs & monthly operating rept for Apr 1979 being made available to library W/o encl.
SOUDER, J. L. Division of Rules and Records. 79/06/18. 2pp.

7908140827 Supplements corrective actions outlined in RO 269/78-27. All Bailey wide-range recorder cables replaced after two addl cable faults identified. Actions taken considered sufficient to mitigate potential difficulties.
PARKER, W. O. Duke Power Co. 79/07/20. 2pp.

7908070646 Forwards LER 79-022/03L-0.
PARKER, W. O. Duke Power Co. 79/08/02. 3pp.

--7908070656 LER 79-022/03L-0 on 790703 high pressure svc water pump A removed from svc to repair leakage from pump motor cooler. Cause of leak undetermined. Pump joint resoldered & cooler pressurized.
LEWIS, S. R. Duke Power Co. 79/08/02. 1p.

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

7908170043 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10. 1p.

DOCKETED ITEMS

7908310183 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
FOLKEN, R.H. Region 5, San Francisco, Office of the Director.
79/08/14 1p

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7908130195 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch. 79/07/03. 2pp.

7908170354 Forwards proprietary version of "TMI Guard Force Training & Qualification Plan." Plan withheld (ref 10CFR2.790).
HERBEIN, J.G. Metropolitan Edison Co. 79/08/15. 1p.

G. Adjudicatory correspondence

7908030565 Orders unit to remain in shutdown condition due to issues raised during TMI incident. Hearing will precede restart. NRC will issue order within 30 days specifying concerns & procedures in proceeding.
HOYLE, J.C. Office of the Secretary of the Commission. 79/07/02. 2pp.

7908150740 Ack request to be apprised of hearings & legal actions re TMI-1 restart. Forwards NRC 790702 order requiring that facility remain shut down until further order & that public hearings be held.
CUNNINGHAM, G.H. Branch 2. 79/07/05. 2pp.

7908150730 Forwards draft order specifying bases for NRC concerns & procedures to govern hearing to be held prior to TMI-1 restart.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/07/20. 1p.

--7908150753 Draft order specifying basis for NRC concerns & procedures to govern further proceedings.
* Office of Nuclear Reactor Regulation. 79/07/20. 8pp.

7908150752 Responds to 790629 request for show cause hearing to revoke TMI-1 OL. NRC has ordered plant shutdown until further order. License revocation would be premature.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/07/20. 2pp.

7908240154 Submits NRC responses to interrogatories submitted by Susquehanna Valley Alliance.
COLLINS, J.T. TMI-2 Operations/Support. 79/07/30. 37pp.

7908200029 Ack receipt of 790613 ltr to HR Denbton re potential plans to restart TMI-1. Authorization to restart will not be allowed until technical issues & concerns have been addressed, discussed in public hearing & reviewed by NRC.
HELTEMES, C.J. Standardization Branch. 79/08/03. 2pp.

7908200048 Ack receipt of 790612 ltr re potential plans to restart TMI-1. Authorization to restart will not be allowed until technical issues & concerns have been addressed, discussed in public hearing & reviewed by NRC.
HELTEMES, C.J. Standardization Branch. 79/08/03. 2pp.

7908200014 Summarizes status regarding potential plans to restart plant. Discusses 790611 meeting w/Met Ed. Forwards NRC 790702 order requiring shutdown until after public hearing.
HELTEMES, C.J. Standardization Branch. 79/08/06. 2pP.

--7908200017 Directs continuation of shutdown until further order by NRC. Hearing should precede facility restart.
HOYLE, J.C. Office of the Secretary of the Commission. 79/07/02. 2pp.

7908270140 Responds to 790716 request to participate in proceedings re possible opening of TMI-1. Upon publication of notice of hearing, interested parties will be able to petition to intervene.
ENGELHARDT, T.F. Deputy Executive Legal Director. 79/08/06. 2pp.

--7908270148 Requests permission to participate in proceedings re hearings for possible opening of TMI-1. Questions actual need for TMI & feels that psychological & physical health of local residents should be chief concern.
HOSSLER, D.E. Affiliation Unknown. 79/07/16. 7pp.

H. General correspondence

7908150731 Responds to request for info. Discusses TMI production capacity & costs.
BELLS, D.E. Division of Site Safety & Environmental Analysis. 79/07/19. 1p.

7908150449 Responds to 790518 ltr expressing concern re site flooding. Discusses NRC flood risk assessment methodology. Estimate of PMF is adequately conservative. NRC does not require alternate site consideration.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/07/26. 4p.

--7908150463 Expresses concern re TMI flood risk. Requests info re NRC flood risk assessment methodology. Suggests Hill Island as a safer alternative site. Forwards related journal articles.
WALLIS, J.R. American Geophysical Union. 79/05/18. 24pp.

--7908150466 "Guantile Estimation W/More or Less Flood-Like Distributions."
LANDWEHR, J.M., MATALAS, N.C. Interior, Dept. of, U.S. Geological Survey. WALLIS, J.R. IBM Corp. 79/04/27. 34pp.

7908220010 Submits response to NRC 790629 ltr requesting details of licensee mgt/technical resource organization. Response to NRC 790724 ltr will be submitted under separate cover.
Descriptive documentation encl.
HERBEIN, J.G. Metropolitan Edison Co. 79/08/06. 170pp.

7908140515 Advises that RC Arnold has been named senior vice president of util & will retain present position of vice president of GPU Svc Corp.
CREITZ, W.M. Metropolitan Edison Co. 79/08/09. 2pp.

J. Insurance & indemnity information

7908200247 Forwards Endorsement 39 to ANI Policy NF-220.
GERRETY, H.F. GPU Service Corp. 79/08/13. 2pp.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908150582 Ack receipt of 790418 ltr re possible matl substitution for tank at TMI. Cognizant field ofc will investigate & forward rept when complete.
THORNBURG, H.D. Division of Reactor Construction Inspection. 79/06/01. 2pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors. 79/06/04. 52pp.

7908070450 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/06/22. 3pp.

7908070481 Comments on trip rept to TMI. Rept failed to mention that need was expressed for definitive criteria for shallow land burial grounds. W/o criteria, decisions are based on engineering judgments. Requests development of criteria.
COLLINS, J.T. TMI-2 Operations/Support. 79/06/23. 8pp.

--7908070487 Forwards trip report re TMI trip made by NMSS representatives to review planning for processing wastes, specifically waste disposal & transportation. Recommends pursuing method of converting waste to solid matrix.
DIRCKS, W.J. Office of Nuclear Material Safety & Safeguards. 79/06/18. 1p.

--7908070488 Submits trip rept re 790605 TMI trip by NMSS to review waste disposal & transportation. Forwards GPU 790511 Svc memo from McGoey to Rusche.
BROWNING, R.E. Division of Waste Management. 79/06/13. 10pp.

7908150717 Summary of 790611 meeting re open items & proposed changes for TMI-1 restart.
DIIANNI, D.C. Operating Reactors Branch 4. 79/06/28. 35pp.

7908150743 Discusses upgraded standard Tech Specs bases program. Amends in Classes I-III will be fee-exempt.
REID, R.W. Operating Reactors Branch 4. 79/07/05. 2pp.

7908150742 Recommends resolution of containment purge issue prior to TMI-1 operation. Licensee response to generic ltr should be evaluated & resolved prior to operation.
LAINAS, G. Plant Systems Branch. 79/07/09. 1p.

7908150720 Requests evaluation of semiscale small break experiment w/small break computer program by 790901.
ROSS, D. F. TMI-2 Unresolved Safety Issues. 79/07/16. 7pp.

7908010505 Submits status of piping cracks investigation, in response to C Nelson 790712 request. Six of 15 visual leaks discovered through wall pipe cracks. Five of six cracks were in spent fuel cooling sys & one in decay heat removal sys.
HERBEIN, J. G. Metropolitan Edison Co. 79/07/17. 1p.

7908150741 Discusses planned 790730-0810 site visit to discuss vital area analysis of facilities.
REID, R. W. Operating Reactors Branch 4. 79/07/17. 2pp.

7908170502 Transcript of 790717 meeting in Washington, DC re further proceedings concerning restart of TMI-1. Pp 1-59.
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission. 79/07/17. 60pp.

--7908170505 Forwards draft of procedural portions of NRC order in TMI-1 suspension proceedings. Order provides for hearing before ASLB & permits licensee to begin mods immediately.
SHAPAR, H. K. Office of the Executive Legal Director. 79/07/16. 10pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 58pp.

7908170216 Responds to 790629 request for show cause proceeding to revoke OL permanently. Discusses NRC 790702 order shutting down TMI-1 until further NRC order. Forwards JP Murray 790709 memo.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/20. 2pp.

--7908170221 Forwards Environ Coalition on Nuclear Power request to initiate show cause proceeding to revoke TMI-1 OL.
MURRAY, J. P. Rulemaking & Enforcement Division. 79/07/09. 1p.

--7908170224 Requests initiation of show cause proceeding per 10CFR2.206 for permanent revocation of TMI-1 OL.
JOHNSRUD, J. H. Environmental Coalition on Nuclear Power. 79/06/29. 10pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908220401 Transcript of 790724 briefing by NRC in Washington, DC on technical issues re restart of facility. Pp 1-117.
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission. 79/07/24. 118pp.

7908010260 Notifies of new completion date of July 1980 for Phase II of multi-phase program to evaluate effect of asymmetric LOCA loads, due to analyses resulting from TMI-2 incident.
HERBEIN, J. G. Metropolitan Edison Co. 79/07/25. 2pp.

7908230056 Requests results of semiscale small break experiment be compared w/small break computer program being used by C-E in support of owners group. To date, evaluations of latter have been inconclusive.
ROSS, D. F. TMI-2 Bulletins & Orders. 79/07/25. 8pp.

7908010367 Responds to NRC 790507 request for info re adequacy of station electric distribution sys voltages. Analysis & consequent info cannot be committed due to resource limitations.
HERBEIN, J. G. Metropolitan Edison Co. 79/07/26. 1p.

7908060251 Notifies that response to NRC 790507 ltr re adequacy of electric distribution sys voltages will not be submitted by 790801 due to limited resources following TMI-2 incident. Response will be sent prior to startup.
HERBEIN, J. G. Metropolitan Edison Co. 79/07/26. 1p.

7908080486 Forwards fee for amend per 790703 ltr.
HERBEIN, J. G. Metropolitan Edison Co. 79/07/30. 1p.

7908130535 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
REID, R. W. Operating Reactors Branch 4. 79/08/02. 4pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908160239 Notification of 790809 meeting w/B&W Owners' Group in Bethesda, MD to discuss long-term generic requirements for B&W operating plants.
CAPRA, R. A. TMI-2 Unresolved Safety Issues. 79/08/06. 2pp.

7908130409 Responds to NRC 781029 ltr & supplements 790104 ltr. Will limit purging during normal operations to no greater than 90-hr/year, pending completion of NRC review. Will justify continued purging by 791215.
HERBEIN, J. G. Metropolitan Edison Co. 79/08/07. 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908220525 Notification of 790817 meeting w/Met Ed & General Public Utils Svc to discuss TMI lessons learned, emergency hardware & procedure mod review.
ENGLE, L. TMI-2 Bulletins & Orders. 79/08/13. 3pp.

7908230342 Notifies that draft radiological effluent Tech Specs will be submitted after completion of Unit 2 Tech Specs (to be issued 790820) per Boegli 790806 telcon.
HERBEIN, J. G. Metropolitan Edison Co. 79/06/14. 1p.

7908280549 Forwards supplemental response to NRC 790525 request for info re PWR feedwater lines. Oversized drawings encl.
HERBEIN, J. G. Metropolitan Edison Co. 79/08/17. 34pp.

7908280557 Confirms 790813 telcon between RA Lengel & D Dilanni re response to NRC 790502 ltr concerning adequacy of station electrical sys distribution voltage.
HERBEIN, J. G. Metropolitan Edison Co. 79/08/20. 1p.

7908310442 Responds to FOIA request for transcripts re TMI. Confirms telcon w/Reed & Wagman re placement of transcripts for first five days of Incident Response Ctr conversations in PDR by 790824.
FELTON, J. M. Division of Rules and Records. 79/08/21. 1p.

G. Inspection reports, IE Bulletins & correspondence

7908230476 Forwards IE Insp Repts 50-320/72-04 & 50-289/72-12 on 720711-14.
HOWARD, E. M. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 72/09/19. 2pp.

--7908230481 IE Insp Repts 50-320/72-04 & 50-289/72-12 on 720711-14. No noncompliance noted. Major areas inspected: enforcement action, licensee action on previously identified enforcement matters & unresolved items.
FOLSOM, S. A., BURZI, A. V. J. Region 1, Philadelphia, Office of the Director. HOWARD, E. M. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 72/09/13. 18pp.

7908230338 Forwards IE Insp Repts 50-320/72-06 & 50-289/72-16 on 720926 & 27.
HOWARD, E. M. Region 1, Philadelphia, Office of the Director. 72/11/03. 1p.

--7908230340 IE Insp Repts 50-320/72-06 & 50-289/72-16 on 720926 & 27. Noncompliance noted: fire associated w/heat treatment operations.
FOLSON, S. A., BARKER, F. F., HOWARD, E. M. Region 1, Philadelphia, Office of the Director. 72/11/07. 4pp.

7908230334 IE Insp Repts 50-320/72-08 & 50-289/72-19 on 721109. Mgt meeting held to discuss QA history of TMI projects & requirement for quality program for operations phase.
FOLSOM, S. A. Region 1, Philadelphia, Office of the Director. HOWARD, E. M., O'REILLY, J. P. Atomic Energy Commission-Deputy Director for Reactor Projects. 72/11/20. 3pp.

7908230581 Forwards IE Insp Repts 50-320/74-02 & 50-289/74-07 on 740220-22 & 25-27 & notice of violation.
O'REILLY, J. P. Region 1, Philadelphia, Office of the Director. 74/03/29. 2pp.

--7908230584 Notice of violation from insp on 740220-22 & 25-27.
* Region 1, Philadelphia, Office of the Director. 74/03/29. 2pp.

--7908230590 IE Insp Rpts 50-320/74-02 & 50-289/74-07 on 740220-22 & 25-27. Noncompliance noted: chlorine usage logs not maintained; airborne particulates not monitored on weekly basis & milk not sampled on monthly basis.
BORES, R. J. ; GALLINA, C. O. ; STOHR, J. P. (Region ... Philadelphia, Office of the Director. 74/03/29. 21pp.

79082306/ \ Forwards IE Insp Rpts 50-320/76-11 & 50-289/76-20 on 760824-26 & notice of violation.
O'REILLY, J. P. Region 1, Philadelphia, Office of the Director. 76/09/15. 2pp.

--7908230607 Notice of violation from insp on 760824-26.
* Region 1, Philadelphia, Office of the Director. 76/09/13. 1p.

--7908230611 IE Insp Rpts 50-320/76-11 & 50-289/76-20 on 760824-26. Noncompliance noted: quarterly inventories of emergency equipment not properly performed.
DONALDSON, D. E. ; STOHR, J. P. Region 1, Philadelphia, Office of the Director. 76/09/13. 16pp.

7908230625 Forwards IE Insp Rpts 50-320/76-10 & 50-289/76-18 on 760720-28 & 0803 & 04 & notice of violation.
NELSON, P. R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 76/09/16. 2pp.

--7908230629 Notice of violation from insp on 760720-28 & 0803 & 04.
* Region 1, Philadelphia, Office of the Director. 76/09/15. 1p.

--7908230634 IE Insp Rpts 50-320/76-10 & 50-289/76-18 on 760720-28 & 0803 & 04. Noncompliance noted: weekly air particulate samples were not composited & written procedures were not prepared to ensure compliance w/ETS.
BORES, R. J. ; BLAND, J. S. Region 1, Philadelphia, Office of the Director. 76/09/15. 17pp.

7908230621 IE Insp Rpts 50-320/76-13 & 50-289/76-22 on 760908 & 09. Noncompliance noted: four portable radiation detection instruments found out of calibr.
SHETNAM, R. L. ; KNAPP, P. L. Region 1, Philadelphia, Office of the Director. 76/09/20. 7pp.

7908230614 Forwards IE Insp Rpts 50-320/76-13 & 50-289/76-22 on 760908 & 09 & notice of violation.
NELSON, P. R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 76/09/21. 2pp.

--7908230617 Notice of violation from insp on 760908 & 09.
* Region 1, Philadelphia, Office of the Director. 76/09/20. 1p.

7908230594 Forwards IE Insp Rpts 50-320/76-16 & 50-289/76-24 on 761012-15 & 21 & notice of violation.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 76/11/05. 2pp.

--7908230597 Notice of violation from insp on 761012-15 & 21.
* Region 1, Philadelphia, Office of the Director. 76/11/05. 1p.

--7908230601 IE Insp Rpts 50-320/76-16 & 50-289/76-24 on 761012-15 & 21. Noncompliance noted: General Ofc Review Board Meeting 24 conducted w/alternates not duly appointed & required signs not posted when fuel movement activities commenced.
FASANO, A. N. ; FINKEL, W. A. Region 1, Philadelphia, Office of the Director. DAVIS, A. B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 76/11/05. 35pp.

7908230652 Forwards IE Insp Rpts 50-320/77-38 & 50-289/77-30 on 770921 & 22. No noncompliance noted.
* Region 1, Philadelphia, Office of the Director. 77/10/05. 1p.

--7908230659 IE Insp Rpts 50-320/77-38 & 50-289/77-30 on 770921 & 22. No noncompliance noted. Major areas inspected: licensee action on unresolved items re preoperational emergency planning.
DONALDSON, D. E. ; GALLINA, C. O. Region 1, Philadelphia, Office of the Director. STOHR, J. P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 77/10/04. 5pp.

7908230531 Forwards IE Insp Rpts 50-320/78-16 & 50-289/78-08 on 780417-21 & notice of violation.
NELSON, P. R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 78/05/31. 2pp.

--7908230534 Notice of violation from insp on 780417-21.
* Region 1, Philadelphia, Office of the Director. 78/05/25. 2pp.

--7908230544 IE Insp Rpts 50-320/78-16 & 50-289/78-08 on 780417-21. Noncompliance noted: failure to sample, analyze air particulates & iodine & failure to meet Sr-89 analytical sensitivity for drinking water & excessive radiation levels.
BORES, R. J. ; BERKSON, H. Region 1, Philadelphia, Office of the Director. STOHR, J. P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 78/05/25. 18pp.

7908230516 Notice of violation from insp on 781212-15.
* Region 1, Philadelphia, Office of the Director. 79/01/15. 2pp.

--7908230524 IE Insp Rpts 50-320/78-38 & 50-289/78-25 on 781212-15. Noncompliance noted: failure to control combustibles; failure to fully implement procedures & failure to implement SER commitment.
GAGE, L. W. Region 1, Philadelphia, Office of the Director. EBNETER, S. D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/01/15. 9pp.

7908230552 Forwards IE Insp Rpts 50-320/79-04 & 50-289/79-03 on 790213-15, 24, 25, 28 & 0301 & 02 & notice of violation.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/23. 2pp.

--7908230557 Notice of violation from insp on 790213-15, 24, 25, 28 & 0301 & 02.
* Region 1, Philadelphia, Office of the Director. 79/04/13. 2pp.

--7908230565 IE Insp Rpts 50-320/79-04 & 50-289/79-03 on 790213-15, 24, 25, 28 & 0301 &02. Noncompliance noted: failure to adhere to procedures & high radiation area entries w/o adequate continuously-indicating dose rate instruments.
PLUMLEE, K. E. ; CLEMONS, P. E. Region 1, Philadelphia, Office of the Director. CROCKER, H. W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/04/13. 9pp.

7908150754 Forwards IE Insp Rpts 50-320/79-08 & 50-289/79-09 on 790315. No noncompliance noted.
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/06/21. 2pp.

--7908150760 IE Insp Rpts 50-320/79-08 & 50-289/79-09 on 790315. No noncompliance noted. Major areas inspected: effluent sample split.
KOTTAN, J. J. ; STOHR, J. P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/06/20. 4pp.

7908150721 Responds to IE Bulletin 79-09 re failures of GE Type AK-2 circuit breakers. Circuit breakers described are used as reactor trip breakers in control rod drive sys. Discusses preventive maint program.
HERBEIN, J. G. Metropolitan Edison Co. 79/06/27. 1p.

7908150747 Forwards IE Bulletin 79-14, "Seismic analysis for As-Built Safety-Related Piping Sys."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/02. 1p.

7908150723 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Forwards description of computer program used in TMI-1 design. Program does not use algebraic summation in response spectrum analysis.
HERBEIN, J. G. Metropolitan Edison Co. 79/07/03. 2pp.

7908070680 Responds to IE Bulletin 79-10. Forwards data re operator & senior operator exam results.
HERBEIN, J. G. Metropolitan Edison Co. 79/07/05. 4pp.

7908150719 Responds to IE Bulletin 79-11 re faulty overcurrent trip devices. DB-50 circuit breakers are used; DB-75 circuit breakers are not used. DB-50 circuit breakers will be tested. Test procedure PM-E5 has been reviewed & revised.
HERBEIN, J. G. Metropolitan Edison Co. 79/07/06. 2pp.

7908150759 Forwards IE Info Notice 79-18, "Skylab Reentry."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/06. 1p.

7908150749 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/11. 1p.

7908010429 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908100233 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908100338 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/07/26 1p.

7908090302 Forwards IE Bulletin 79-16, "Vital Area Access Control." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/07/30 1p.

7908280115 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/08/07 1p.

7908230304 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/08/08 1p.

7908210378 Responds to IE Bulletin 79-17. Discusses status of intergranular stress corrosion cracking in weld joints using sensitive ultrasonic testing technique. Considers submittal adequate response.
HERBEIN, J.G. Metropolitan Edison Co. 79/08/15 2pp.

7908300139 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/08/15 1p.

R Periodic operating reports & related correspondence

7908010454 Forwards discharge monitoring rept for Jan 1979.
TROFFER, G.J. Metropolitan Edison Co. 79/02/23 12pp.

7908010900 Forwards discharge monitoring rept for Feb 1979.
TROFFER, G.J. Metropolitan Edison Co. 79/03/19 12pp.

7908010558 Forwards discharge monitoring rept for June 1979.
TROFFER, G.J. Metropolitan Edison Co. 79/07/25 12pp.

7908090372 Forwards "Ecological Study of Susquehanna River Near TMI," 1978 annual rept by Ichthyological Associates, Inc.
HILBISH, J. Metropolitan Edison Co. 79/08/03 1p.

--7908090378 "Ecological Study of Susquehanna River Near TMI," 1978 annual rept.
NARDACCI, G.A. Ichthyological Associates, Inc. 79/07/31 742pp.

7908270438 Forwards Jul 1979 operating rept.
HERBEIN, J.G. Metropolitan Edison Co. 79/08/15 1p.

--7908270444 Monthly operating rept for Jul 1979.
MITCHELL, D.G. Metropolitan Edison Co. 79/08/15 5pp.

S Reportable occurrences, LERs & related correspondence

7908070079 RO 79-13/P on 790620 during ultrasonic examinations of decay heat sys piping, leakage discovered on 10-inch suction piping from borated water storage tank. Caused by intergranular stress corrosion cracking.
SEELINGER, J.L. Metropolitan Edison Co. 79/06/21 1p.

7908130472 Submits RO 79-15/1T. B&W small break accidents analysis revealed that core may be uncovered if coolant pumps are tripped longer than 2 minutes after HPCI actuation. Caused by water loss from pumping.
SEELINGER, J.L. Metropolitan Edison Co. 79/07/24 1p.

7908100461 Forwards LER 79-014/04T-0.
HERBEIN, J.G. Metropolitan Edison Co. 79/07/26 2pp.

--7908100469 LER 79-014/04T-0 on 790626 informed by consultant that sediment showed Co-58 levels exceeding control station value. Caused by increased vol of liquid radioactive waste. No corrective action planned.
MITCHELL, D.G. Metropolitan Edison Co. 79/07/26 1p.

7908170426 Forwards LER 79-015/01T-0.
HERBEIN, J.G. Metropolitan Edison Co. 79/08/09 1p.

--7908170430 LER 79-015/01T-0 on 790723 possible unconservative assumption discovered in accident analysis for small break LOCA. Exposure of core may result if reactor coolant pumps are tripped after 2 minutes following small break LOCA.
MITCHELL, D.G. Metropolitan Edison Co. 79/08/09 2pp.

T Hearing transcripts on non-antitrust matters

7908080139 Transcript of 790725 briefing in Washington, DC on technical issues re restart of facility. Pp 1-39.
HENDRIE, J.M., KENNEDY, R.T., BRADFORD, P.A. Commission. 79/07/25.
40pp.

7908090579 Transcript of 790727 public meeting in Washington, DC re technical issues in restart of TMI-1. Pp 1-94.
HENDRIE, J.M., GILINSKY, V., KENNEDY, R.T. Commission. 79/07/27.
95pp.

7908210067 Transcript of 790731 meeting in Washington, DC. Pp 1-42.
HENDRIE, J.M., GILINSKY, V., KENNEDY, R.T. Commission. 79/07/31.
42pp.

--7908210082 Responds to NRC Commissioners questions re whether psychological effects on public are properly within scope of hearing which will be held prior to restart.
BICKWIT, L. Office of the General Counsel. 79/07/24. 8pp.

--7908210089 Continues 790727 discussion of startup proceeding. 30-day deadline of 790702 order & proposed order to extend deadline.
BICKWIT, L. Office of the General Counsel. 79/07/24. 27pp.

7908210060 Transcript of 790807 meeting in Washington, DC. Pp 1-62.
HENDRIE, J.M., GILINSKY, V., KENNEDY, R.T. Commission. 79/08/07.
62pp.

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7908270298 Ack receipt of 790403 ltr transmitting safeguards contingency plan for facility Class III fee required.
DIGGS, R.M. License Fee Management Branch. 79/07/03 2pp.

7908200204 Forwards preliminary security training & qualification plan. Plan withheld (ref 10CFR2.790).
ANDOGNINI, G.C. Boston Edison Co. 79/08/13. 1p.

G Adjudicatory correspondence

7908290424 Notifies that local newspapers frequently discuss operational problems & radiation releases at plant. Requests stricter supervision & control & suspension of CP. Forwards newspaper articles.
BARTLETT, R.M. Affiliation Unknown. 79/07/14. 4pp.

P Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22.
7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors. 79/06/04 52pp.

7908060544 Forwards request for addl info re degraded grid voltage for review of proposed Tech Spec changes to incorporate addl electric power sys surveillance requirements. Requests submittal within 90 days.
IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625).
79/06/19 3pp.

7908070422 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/06/22 3pp.

7908130315 Forwards "Rept on Breakwater Damage."
HULMAN, L.G. Hydrology Meteorology Branch. 79/06/25. 2pp.

--7908130324 "Rept on Breakwater Damage." Concentrated localized damage to breakwater is not consistent w/bases on which design was accepted. ASLB should be notified of possible degradation of breakwater.
* Hydrology Meteorology Branch. 79/06/25. 5pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program.Proposed agenda encl.
GRIMES,C.I. Plant Systems Branch. 79/06/27. 2p.

7908100128 Requests registration as user of Model PB-1.
ANDOGNINI,G.C. Boston Edison Co. 79/07/05. 1p.

7908060209 Summary of 790628 meeting w/BWR licensees,applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE,W.F. Standardization Branch. 79/07/11. 26pp.

7908210358 Forwards requests for addl sys & analysis info for generic rept on BWRs.Request includes info on sys capable of providing post-accident & transient core cooling & small break LOCA analysis.
IPPOLITO,T.A. Operating Reactors Branch 3. 79/07/13. 20pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves W/o encl.
GRIMES,B.K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908070224 Requests cooperation in data-gathering activities to provide NRC Commissioners,public & media w/up-to-date operating status of power reactors.Info requests will not be made while plant is in shutdown mode.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908100290 Forwards NUREG-0472,Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL,W.P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908300288 Requests cooperation in special environ sampling program to perform Fe-55 & P-32 analyses.Tests will determine presence of nuclides in marine pathway.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events.Requests addl five copies of response for each unit,if more than one is owned & operated.
HAASS,W.P. Quality Assurance Branch. 79/07/24. 1p.

7908300610 Requests addl info to design & const of breakwater & breakwater foundation.
IPPOLITO,T.A. Operating Reactors Branch 3. 79/07/31. 8pp.

7908080510 Responds to 790629 ltr requesting info re technical & mgt resources available to anticipate or respond to events of type experienced at TMI-2.Encl withheld (ref 10CFR2.790).
ANDOGNINI,G.C. Boston Edison Co. 79/08/03. 3pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations,guidance documents & repts re emergency planning.
EISENHUT,D.G. Division of Operating Reactors. 79/08/03. 53pp.

7908230155 Requests utils provid. description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL,W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908270454 Requests that GEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWR Reactors" transmitted on 790817 be included in docket.Later revision to be submittted by 791116 will include remainder of info requested.
ANDOGNINI,G.C. Boston Edison Co. 79/08/20. 1p.

7908280539 Provides info requested in NRC 7B1129 ltr re containment purging during normal plant operation.Forwards list of purge & vent valves capable of operation when subjected to dynamic forces of a design basis LOCA.
ANDOGNINI,G.C. Boston Edison Co. 79/08/21. 2pp.

0 Inspection reports, IE Bulletins & correspondence

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08.Requests attendance at 790628 meeting in Bethesda,MD re info needed by NRC to complete review.
IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625). 79/06/20. 44pp.

7908030236 Responds to IE Bulletins 78-12, 78-12A & 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses actions taken re pressure vessel weld matl record search & lack of archival matl for verification purposes.
ANDOGNINI,G.C. Boston Edison Co. 79/06/29. 3pp.

7908270117 Forwards IE Insp Rept 50-293/79-08 on 790501-04.No noncompliance noted.
BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/06/29. 2pp.

--7908270122 IE Insp Rept 50-293/79-08 & on 790501-04.No noncompliance noted.Major areas inspected previous inspector identified items including licensee followup actions re previous items of noncompliance.
NAPUDA,G., KISTER,H.B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/06/28. 5pp.

7908070702 Responds to IE Bulletin 79-11.No Westinghouse Type DB-50 or DB-75 circuit breakers are installed in safety-related sys.
ANDOGNINI,G.C. Boston Edison Co. 79/07/09. 2pp.

7908220648 Responds to IE Bulletin 79-02,Revision 1, "Pipe Support Base Plate Designs using Concrete Expansion Anchor Bolts." Found 12 loose nuts in 26 base plates examined.
ANDOGNINI,G.C. Boston Edison Co. 79/07/09. 4pp.

7908010420 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060207 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030222 Notifies that written responses to IE Bulletin 79-15, Sup.1 1,should be directed to IE Div of Reactor Const Insp.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908080303 Requests addl info to suppl previous response to IE Bulletin 79-08,to enable to complete safety evaluation.
IPPOLITO,T.A. Operating Reactors Branch 3. 79/07/20. 4pp.

7908010444 Submits proposed inservice weld insp program to be implemented at start of B00105 refueling outage.
ANDOGNINI,G.C. Boston Edison Co. 79/07/24. 54pp.

7908100212 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908090276 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908270409 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908230287 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/08/08. 1p.

7908270535 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/08/10. 1p.

7908280235 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310253 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300094 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelph... Office of the Director 79/08/15 1p

7908280592 Responds to 790720 request for addl info re IE Bulletin 79-08 Procedures revised by 790620 to assure isolation of RHR to fuel pool deminimizing line & torus makeup line in event of containment isolation signal.
ANDOGNINI, G. C. Boston Edison Co 79/08/21 11pp

R Periodic operating reports & related correspondence

7908200231 Forwards monthly operating rept for Jul 1979.
MCGUIRE, P. J. Boston Edison Co. 79/08/01 1p

--7908200233 Monthly operating rept for Jul 1979.
GAFFNEY, C. M. Boston Edison Co. 79/08/09 6pp

7908290413 Forwards revised monthly operating rept for Jul 1979.
MCGUIRE, P. J. Boston Edison Co. 79/08/01 1p

--7908290415 Revised monthly operating rept for Jul 1979.
GAFFNEY, C. M. Boston Edison Co. 79/08/09 1p

S Reportable occurrences, LERs & related correspondence

7908010309 RO 79-022/01X-0 on 790713 two pipe supports did not meet original SSE design specifications. Caused by design error. Plant design change requests prepared & mods in progress.
MATHIS, C. J. Boston Edison Co. 79/07/16 1p

7908020416 LER 79-027/01X-0 on 790727 during normal operation, loss of offsite power & reactor scram occurred. Caused by lightning striking station switchyard.
FULTON, J. M. Boston Edison Co. 79/07/27 1p

7908130363 RO 79-027/01X-0 on 790727 lightning struck station switchyard, causing loss of offsite power & reactor scram. HPCI was started for injecting water into vessel. Relief valve 203-3A will be replaced & tested prior to restart.
FULTON, J. M. Boston Edison Co. 79/07/27 1p

7908080397 Forwards LER 79-028/03L-0.
MCGUIRE, P. J. Boston Edison Co. 79/08/02 1p

--7908080398 LER 79-028/03L-0 on 790627 during placement of RHR loop A in supression pool cooling, flow was observed w/motor-operated valve 1001-36A indicating closed. Cause not determined.
MATHIS, C. J. Boston Edison Co. 79/08/02 1p

7908170418 Forwards LER 79-027/01T-0.
MCGUIRE, P. J. Boston Edison Co. 79/08/09 1p

--7908170423 LER 79-027/01T-0 on 790727 reactor scram occurred as result of loss of all offsite power. Caused by lightning striking offsite distribution lines. Resulting backflash caused high speed relay operation for line to ground fault.
FULTON, J. M. Boston Edison Co. 79/08/10 1p

7908280526 Forwards LER 79-030/03L-0.
MCGUIRE, P. J. Boston Edison Co. 79/08/22 1p

--7908280530 LER 79-030/03L-0 on 790725 motor control ctr breaker of globe valve MOV-1001-36B tripped on overload after valve given signal to open. Caused by shear in valve stem guide key. Stem clamps drilled in place & tapped for set screws.
FULTON, J. M. Boston Edison Co. 79/08/16 2pp

U Congressional/Executive Correspondence

7908010175 Responds to 790222 ltr re UCS statements re NRC reliance on WASH-1400 & safety of facility. Forwards various documents, including JM Hendrie & PA Bradford 790226 testimony before Congress.
HENDRIE, J. M. Commission 79/06/05 22pp

--7908010204 Requests comments & info re UCS statements about NRC reliance on Rasmussen rept, fire protection plans & safety of facility. Forwards UCS statements.
STUDDS, G. E. House of Rep. 79/02/22 8pp

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7908070061 Responds to 790614 ltr re agreement relating to offsite emergency event. NRC need not sign agreement, but needs to be notified of incident severity. DOE is to coordinate response to radiological accidents in area.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/29 1p

--7908070064 Forwards draft agreement to be signed by NRC & util, committing NRC to respond to facility request in event of offsite emergency involving release of radioactivity.
WANDKE, N. E. Commonwealth Edison Co. 79/06/14 2pp

7908130162 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requ... payment of Class III fee. Plans should be submitte... 790823.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp

7908160367 Forwards request for addl info re contingency plans. Encl withheld (ref 10CFR2.790).
ZIEMANN, D. L. Operating Reactors Branch 2 79/07/19 2pp

7908030167 Discusses current status of fire protection mods re gas suppression sys, fire doors & reactor coolant pump as follow-up to C Reed 790606 ltr & in response to NRC 790413 request.
REED, C. Commonwealth Edison Co. 79/07/27 3pp

7908030394 Notifies that fire protection program mod of electric equipment room to install test switches in each essential indication circuit in I & C racks has been delayed due to design phase & will be completed by 791012.
NAUGHTON, W. F. Commonwealth Edison Co. 79/07/27 1p

7908160249 Notifies that refund for Class I & II amend fees re fire protection Tech Spec changes is being processed.
MILLER, W. O. License Fee Management Branch 79/07/27 1p

7908200250 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/08/16 1p

G Adjudicatory correspondence

7908080136 Testimony of RE Webb on contentions re accident hazards of spent fuel storage. Storage is unsafe due to possibility of loss-of-water accidents. Reactors should be closed down.
WEBB, R. E. Lower Alloways Creek, NJ 79/02/27 40pp

--7908080144 "Analysis of Accident Hazards of Storing Highly Radioactive Spent Fuel Rods in Spent Fuel Storage Pools at Nuclear Power Plants & At Other Offsite Storage Facilities."
WEBB, R. E. Lower Alloways Creek, NJ 79/04/03 42pp

7908020365 Forwards errata to 790329 EIA & safety evaluation re proposed expansion of facility spent fuel pool capacity.
GODDARD, R. J. Branch 2 79/05/25 1p

--7908020371 Errata to 790329 EIA & safety evaluation re proposed expansion of facility spent fuel pool capacity.
GODDARD, R. J. Branch 2 79/05/25 1p

7908150056 Confirms agreement in principle re Contention 2(n) at spent fuel hearings in June 1979. If reracking is approved, util will limit occupational exposure, per JP Leider 790109 affidavit. Requests affirmation of understanding.
STEPTOE, P. P. Isham, Lincoln & Beale 79/07/03 2pp

7908080378 Forwards licensee witness R Kraatz 790709 affidavit correcting error made during cross-examination re replacement power costs for one unit. Corrects transcript page 832.
STEPTOE, P. P. Isham, Lincoln & Beale 79/07/09 3pp

7908080289 Forwards IL Safe Energy Alliance 790624 ltr re installation of four racks in plant spent fuel storage pool. NRC has not received formal proposal to install racks.
GADDARD, R. J. Branch 2 79/07/10 1p

--7908080294 Opposes installation of four racks at plant spent fuel storage pool prior to final NRC decision on compaction. Requests NRC deny premature rack installation by util.
QUIGG, C. Illinois Safe Energy Alliance 79/06/24 1p

7908170204 Ack 790607 ltr to J Carter forwarding statement adopted by Village Council urging NRC not to consider Con Ed request for addl nuclear waste storage until safe waste storage plan developed. Statement forwarded to ASLB for consideration.
EISENHUT, D. G. Division of Operating Reactors 79/07/26 4pp

H General correspondence

7908150324 Expresses concern re nuclear waste storage in IL. Suggests developing alternate sources of energy.
BARAKAT, S. F. Affiliation Unknown 79/07/16 1p

DOCKETED ITEMS

7908150195 Responds to D Ferris 790615 ltr re proposed facility spent fuel pool rack mods. Concerns re faulty fuel racks & potential cooling sys failures are addressed in encl 790329 safety evaluation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/20 1p

7908150094 Ack receipt of correspondence re status of spent fuel storage at six operating facilities near Lake Michigan. Responds to 790429 ltr.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/26 2pp

--7908150107 Discusses spent fuel storage capability at Big Rock Point. NUREG-0020 indicates authorized capacity of 120 spent fuel assemblies, while DOE indicates capacity of 365. Requests clarification.
SCHAEFER, J. Lake Michigan Federation 79/05/20 1p

--7908150125 Ack receipt of info re nuclear power plants near Lake MI. Forwards rept re status of spent fuel storage at plants. Requests comments re rept.
SCHAEFER, J. Lake Michigan Federation 79/06/21 1p

--7908150139 "Status of Spent Fuel Storage at Six Nuclear Plants Located on Shores of Lake MI."
SCHAEFER, J. Lake Michigan Federation 79/05/31 20pp

7908280457 Ack 790620 ltr to President Carter forwarding resolution re proposed expansion of spent fuel storage capacity at facility. Resolution has been incorporated in official hearing record of ASLB.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/08/06 5pp

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp

7908020546 Forwards errata to 790329 safety evaluation & EIA re proposed expansion of spent fuel pool capacity.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625) 79/05/29 3pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp

7908070652 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/22 3pp

7908270508 Responds to ltrs reporting results of seismic reanalysis of reactors coolant piping at facilities using updated WESTDYN code. Reanalysis & results acceptable & matter resolved. Forwards safety evaluation.
SCHWENCER, A. Operating Reactors Branch 1 79/07/05 2pp

--7908270515 Safety evaluation by Ofc of Nuclear Reactor Regulation re seismic reanalysis of reactor coolant piping.
* Office of Nuclear Reactor Regulation 79/07/05 1p

7908130310 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires NRC initial notification.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/09 1p

7908080719 Confirms that meeting at util corporate office has been rescheduled for 790719 at 3 PM. Location, purpose & attendees discussed in NRC 790612 ltr.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/10 1p

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908070332 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/19 1p

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908020460 Submits schedule for addl response to NRC issues re containment purging during normal plant operation.
REED, C. Commonwealth Edison Co. 79/07/30 2pp

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co. 79/07/30 2pp

7908130569 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 4pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

7908270083 Discusses status of N-1 loop operation reviews/technical assistance contract. Suggests mgt establish priority for task.
BURDOIN, J. Plant Systems Branch 79/08/03 2pp.

7908300791 Requests addl info re basis for not proposing second level undervoltage protection. Proposed design mod & changes in Tech Specs must be based on guidance contained in NRC positions submitted in 770603 ltr.
SCHWENCER, A. Operating Reactors Branch 1 79/08/06 2pp

7908210368 Submits addl info re steam generator water hammer evaluations. No setpoint change warranted.
REED, C. Commonwealth Edison Co. 79/08/08 5pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908200380 Forwards info requested in NRC 790629 & 0724 ltrs re capabilities & technical resources available to handle unusual events.
JANECEK, R. F. Commonwealth Edison Co. 79/08/13 1100pp

7908210469 Forwards revised pages to ETS, App B, re measuring & reporting chemical releases.
REED, C. Commonwealth Edison Co. 79/08/13 2pp

--7908210482 Revised pages to ETS, App B.
* Commonwealth Edison Co. 79/08/13 8pp.

7908280010 Requests withholding of Westinghouse proprietary info (ref 10CFR2.790) from 790629 licensee submittal to NRC re small break LOCA analyses.
REED, C. Commonwealth Edison Co. 79/08/22 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908010415 Ack receipt of 790517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/79-06 & 50-304/79-07.
HIND, J. A. Region 3, Chicago, Safeguards Branch 79/06/01 1p

--7908010631 Responds to NRC 790426 ltr re violations noted in IE Insp Repts 50-295/79-06 & 50-304/79-07. Details withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/05/17 1p

7908090242 Forwards IE Insp Rept 50-295/79-08 on 790529-31 & notice of violation.
HIND, J. A. Region 3, Chicago, Safeguards Branch 79/06/15 2pp

--7908090249 Notice of violation from insp on 790529-31.
* Region 3, Chicago, Office of the Director. 79/06/14. 1p.

--7906090257 IE Insp Rept 50-295/79-08 on 790529-31. Noncompliance noted: not reporting receipt & shipment by Form NRC-741 or Form NRC-742 & not following nuclear procedure.
FINLEY, A. G. ; PATTERSON, J. P. Region 3, Chicago, Office of the Director. HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/06/14. 1p.

7908070819 Forwards IE Insp Repts 50-295/79-11 & 50-304/79-11 on 790430-0518. No noncompliance noted.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/19. 2pp.

--7908070825 IE Insp Repts 50-295/79-11 & 50-304/79-11 on 790430-0518. No noncompliance noted. Major areas inspected: operator training, engineered safety features sys, mods to safety injection logic & response to IE Bulletins 79-06, 06A & 06A, Revision 1.
KOHLER, J. E. ; SPESSARD, R. L. Region 3, Chicago, Office of the Director. 79/06/14. 9pp.

7908080680 Forwards IE Insp Repts 50-295/79-09 & 50-304/79-10 on 790601. No noncompliance noted.
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/19. 2pp.

--7908080700 IE Insp Repts 50-295/79-09 & 50-304/79-10 on 790601. No noncompliance noted. Major areas inspected: emergency planning activities including annual emergency medical drill at plant & Victory Memorial Hosp.
OESTMANN, M. J. ; AXELSON, W. L. ; ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/06/14. 4pp.

7908030582 Forwards IE Insp Rept 50-295/79-12 on 790611 & 13. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/27. 2pp.

--7908030587 IE Insp Rept 50-295/79-12 on 790611 & 13. No noncompliance noted. Major areas inspected: radiographs for feedwater nozzles for four Unit 1 steam generators.
HARRISON, J. J. ; WARD, K. D. ; DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/21. 3pp.

7908070053 Corrects IE Insp Rept 50-295/79-08. Insp number is 50-295/79-10. Corrected first page of rept encl.
HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/06/27. 2pp.

7908080523 Responds to IE Bulletin 79-11. No Westinghouse DB-50 & DB-75 circuit breakers used in safety-related sys.
REED, C. Commonwealth Edison Co. 79/07/02. 1p.

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co. 79/07/05. 9pp.

--7908060120 "Evaluation of Analytis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc. 79/05/31. 24pp.

7908080143 Forwards addl info to 790424 response to IE Bulletin 79-07. Reanalysis of DBE for reactor coolant loop was performed by Westinghouse. Piping stresses & nozzle loads fall below allowable level.
REED, C. Commonwealth Edison Co. 79/07/10. 7pp.

7908150349 Supplements response to IE Bulletin 79-11. Westinghouse DB-50 & DB-75 circuit breakers are neither used in safety-related sys nor stored as spares at facilities.
REED, C. Commonwealth Edison Co. 79/07/12. 2pp.

7908150339 Responds to IE Bulletin 79-13 re cracking in feedwater sys piping. Requests relief from performing volumetric examinations of auxiliary feedwater pipe welds. Suggests surface examination be substituted.
REED, C. Commonwealth Edison Co. 79/07/13. 7pp.

7908130127 Ack receipt of 790706 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-295/79-10.
HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/07/17. 1p.

--7908130161 Responds to NRC 790615 ltr re violation noted in IE Insp Rept 50-295/79-10. Corrective actions: fuel moves noted on nuclear component transfer list will be noted on fuel location record.
REED, C. Commonwealth Edison Co. 79/07/06. 3pp.

7908290284 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300392 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED, C. Commonwealth Edison Co. 79/08/01. 2pp.

7908170019 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08. 1p.

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908140537 Forwards LER 79-043/03L-0.
WANDKE, N. E. Commonwealth Edison Co. 79/07/24. 1p.

--7908140542 LER 79-048/03L-0 on 790702 check source & indicator needle of auxiliary bldg rad monitor ORT-AR08 stuck in high alarm position. Caused by bent needle stuck to meter facing. Needle straightened.
OST, F. Commonwealth Edison Co. 79/07/24. 1p.

7908140551 Forwards LER 79-050/01T-0.
WANDKE, N. E. Commonwealth Edison Co. 79/07/26. 1p.

--7908140555 LER 79-050/01T-0 on 790713. Westinghouse reported potential problem involving inaccuracies in steam generator level indication following feedwater line break inside containment. Vendor suggests raising setpoint by 10%.
PARKER, T. M. Commonwealth Edison Co. 79/07/26. 2pp.

7908140780 Forwards LER 79-044/99X-0.
WANDKE, N. E. Commonwealth Edison Co. 79/07/30. 1p.

--7908140785 LER 79-044/99X-0 on 790608: operators manually initiated safety injection after false steam pressure differential signals caused control room safety injection annunciation. Caused by waterhammer shock in steam generator loop D.
UGOLINI, D. Commonwealth Edison Co. 79/07/30. 2pp.

7908140810 Forwards LER 79-052/03L-0.
WANDKE, N. E. Commonwealth Edison Co. 79/07/31. 1p.

--7908140814 LER 79-052/03L-0 on 790713: reactor coolant loop flow transmitter 1FT 44C had drifted high by 5.5%. Caused by instrument drift. Transmitter readjusted to zero & mechanics being trained to identify drift situation.
HANSON, P. Commonwealth Edison Co. 79/07/31. 1p.

7908140643 Forward LER 79-051/03L-0.
WANDKE, N. E. Commonwealth Edison Co. 79/08/06. 1p.

--7908140645 LER 79-051/03L-0 on 790718: fuel monitor 1RT-PR27 failed sporadically. Caused by corroded contact pins in control room module connector. Pins replaced w/no further repairs required.
MEYER, B. Commonwealth Edison Co. 79/08/06. 1p.

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

7908130208 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908220054 Confirms 790724 mgt meeting in Bethesda, MD to discuss security program.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 79/07/17 3pp.

7908060437 Forwards amended physical security plan Plan withheld (ref 10CFR2.790).
MILLS, L. M. Tennessee Valley Authority 79/07/30 1p.

7908210314 Forwards security personnel training & qualification plans. Plans withheld (ref 10CFR2.790).
MILLS, L. M. Tennessee Valley Authority 79/08/17 1p.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L. M. Tennessee Valley Authority 79/08/07 2pp.

7908270268 Summarizes 790724 mgt meeting in Bethesda, MD re activities authorized by OLs DPR-33, DPR-52 & DPR-68. Info withheld (ref 10CFR2.790).
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08 2pp.

K. Utility Final Safety Analysis Report (FSAR) & amends.

7908070357 Forwards Amend 69 to FSAR.
MILLS, L. M. Tennessee Valley Authority 79/08/02 2pp.

--7908070366 Amend 69 to FSAR.
* Tennessee Valley Authority 79/08/02 32pp.

P. Operating license stage documents & correspondence

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908030123 Requests addl justification re acceptable temp tolerances for connectors prior to approval of SANDIA qualification tests. Requests clarification of purpose of immersion heater in autoclave.
VOLLMER, R. Division of Operating Reactors 79/06/14 2pp.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch 79/07/11 26pp.

7908300054 Responds to 790223 & 0309 ltrs re stem-mounted limit switches installed on MSIV. Analysis must be provided re MSIV closure input & schematic drawings regarding circuits w/inputs from switches & interposing relay.
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/12 3pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering 79/07/16 4pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908070317 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19 1p.

7908130498 Notice of receipt of 790629 application for amend to Licenses DPR-33, DPR-52 & DPR-68. Application subj to $4,000 Class III fee & two $800 Class I amend fees.
MILLER, W. O. License Fee Management Branch 79/07/20 1p.

7908150132 Forwards request for addl info re 790323 submittal concerning contingency plan. Encl withheld (ref 10CFR2.790).
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/20 2pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908160033 Responds to 790308 ltr which requested refund of fees paid for Tech Spec changes. Fee for Change 110 refunded 780825. Since review of Change 111 began shortly after receipt, refund is not in order.
DIGGS, R. M. License Fee Management Branch 79/07/25 2pp.

7908300213 Responds to 790315 ltr re amend to Licenses DPR-33, DPR-52 & DPR-68. Forwards legal opinion that revisions are not necessary. Code provides adequate authority re shipment of unirradiated & spent fuels.
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/25 2pp.

--7908300226 Responds to 790405 memo re revision of std NRC license authorizing shipment of unirradiated & spent fuel. Revisions are not necessary.
MALSCH, M. G. Regulations Division 79/04/13 6pp.

7908060245 Discusses delay in LCPI power supply mods due to matl delivery problems. Outlines schedule for completion of power supply mods.
MILLS, L. M. Tennessee Valley Authority 79/07/31 1p.

7908060417 Responds to NRC 790712 ltr re environ qualification of stem-mounted limit switches installed on MSIVs. Will replace unqualified limit switches on inboard MSIVs during next refueling outage.
MILLS, L. M. Tennessee Valley Authority 79/07/31 1p.

7908270089 Approves util 790711 request to change Tech Specs re surveillance testing of solenoid operated air/nitrogen valves in containment atmosphere dilution sys. Forwards safety evaluation.
LAINAS, G. Plant Systems Branch 79/08/02 2pp.

--7908270095 Review of util 790711 request for changes to Tech Specs re surveillance requirements for containment atmosphere dilution sys solenoid operated air valves. Appr. es mods. Will continue review of generic purge valve bypass issue.
* Plant Systems Branch 79/08/02 1p.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908080519 Forwards amend to License DPR-68 changing Tech Specs to accommodate Reload 2 Cycle 3 operation & to eliminate LPCI loop selection logic per Amend 23 of License DPR-68. Fuel cycle reload rept justifying changes encl.
MILLS, L. M. Tennessee Valley Authority 79/08/06 44pp.

--7908080524 "Supplemental Reload Licensing Submittal for Unit 3 Reload 2."
ERVIN, A. M., BRUGGE, R. O. General Electric Co. NEDO-24199 79/06/30 20pp.

7908140552 Forwards proposed amend to Tech Specs for Licenses DPR-33, DPR-52 & DPR-68.
MILLS, L. M. Tennessee Valley Authority 79/08/06 2pp.

--7908140556 Proposed Tech Spec changes to allow partial tensioning of reactor pressure vessel head bolts at 70 F & allow nuclear heat to be utilized above 100 F, thus decreasing heatup time.
* Tennessee Valley Authority 79/08/06 15pp.

7908140565 Forwards addl info on proposed Tech Spec change re reduction of scram timing pressure restrictions.
MILLS, L. M. Tennessee Valley Authority 79/08/07 7pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908170334 Submits info in response to NRC 790629 ltr re corporate capability.
MILLS, L. M. Tennessee Valley Authority 79/08/15 29pp.

Q. Inspection reports, IE Bulletins & correspondence

7908010159 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority 79/05/29 3pp.

7908170138 Forwards IE Insp Repts 50-259/79-15, 50-260/79-15 & 50-296/79-15 on 790529-31. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/12. 2pp.

--7908170147 IE Insp Repts 50-259/79-15, 50-260/79-15 & 50-296/79-15 on 790529-31. No noncompliance noted. Major areas inspected: response to bulletins.
PRICE, D. S. Region 2, Atlanta, Office of the Director.
DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/11. 3pp.

7908270326 Forwards response to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion anchor bolts. Where necessary, plant operators instructed to replace self-drilling anchors w/wedge bolts.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/19. 97pp.

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD, re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 79/06/20. 44pp.

7908020536 Discusses several errors in NRC 790509 ltr re recent IE insp repts. First docket number should be 50-259 & rept number for all units should be 79-09.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/21. 1p.

7908060001 Forwards IE Insp Repts 50-259/79-12, 50-260/79-12 & 50-296/79-12 on 790402-27. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/21. 2pp.

--7908060002 IE Insp Repts 50-259/79-12, 50-260/79-12 & 296/79-12 on 790402-27. No noncompliance noted. Major areas inspected: plant operation, followup to reportable occurrences, offsite safety & plant protection.
SULLIVAN, R. F., DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20. 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 3pp.

7908010032 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908140334 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 circuit breakers used at facility.
MILLS, L. M. Tennessee Valley Authority. 79/07/06. 1p.

7908020023 Responds to 790413 ltr transmitting IE Bulletin 79-08. Forwards revision to page 13 of 790424 response.
MILLS, L. M. Tennessee Valley Authority. 79/07/11. 2pp.

7908230571 Forwards IE Insp Repts 50-259/79-13, 50-260/79-13 & 50-296/79-13 on 790430-0615. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/11. 2pp.

--7908230578 IE Insp Repts 50-259/79-13, 50-260/79-13 & 50-296/79-13 on 790430-0615. No noncompliance noted. Major areas inspected: plant operation, ROs, organization & maint & radiation area controls.
SULLIVAN, R. F. Region 2, Atlanta, Office of the Director.
DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/10. 6pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908130033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908080338 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/20. 4pp.

7908080721 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908080746 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908290636 Forwards suppl response to IE Bulletin 79-01A, identifying safety sys involved in ura of ASCO solenoid valves. Stainless steel seated valve should remain operable even if Buna N gasket becomes brittle.
MILLS, L. M. Tennessee Valley Authority. 79/07/26. 3pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14. Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L. M. Tennessee Valley Authority. 79/07/27. 1p.

7908160070 Forwards response to IE Bulletin 79-12. Discusses review of methods & procedures concerning rod withdrawal during startup, in attempt to eliminate fast reactor periods in future.
MILLS, L. M. Tennessee Valley Authority. 79/07/30. 4pp.

7908160304 Ack receipt of 790706 IE Insp Repts 50-259/79-16, 50-260/79-16 & 50-296/79-16. No proprietary info.
MILLS, L. M. Tennessee Valley Authority. 79/07/30. 3pp.

7908240228 Ack receipt of 790508 & 0611 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/07/30. 1p.

--7908240243 Responds to NRC 790416 ltr re violations noted in IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06. Revises 790508 response. Corrective actions contain physical security info. Attached response withheld (ref 10CFR2.790).
GILLELAND, J. E. Tennessee Valley Authority. 79/06/11. 1p.

--7908240254 Responds to NRC 790416 ltr re violations noted in IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06. Corrective actions contain physical security info. Attached response withheld (ref 10CFR2.790).
GILLELAND, J. E. Tennessee Valley Authority. 79/05/08. 1p.

--7908240277 Forwards IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06 on 790228-0302 & notice of violation. Notice of violation & insp repts withheld (ref 10CFR2.790). Summaries of insp repts not exempt.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/04/16. 2pp.

--7908240290 IE Insp Repts 50-259/79-06, 50-260/79-06 & 50-296/79-06 on 790228-3020. Noncompliance noted: security organization, detection aids & deficient locks & keys. Eight pages of insp repts withheld (ref 10CFR2.790).
*. Region 2, Atlanta, Safeguards Branch. 79/04/16. 1p.

7908100487 Responds to 790720 ltr & forwards addl response to IE Bulletin 79-08 re initiation of containment isolation.
MILLS, L. M. Tennessee Valley Authority. 79/08/06. 9pp.

7908160151 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

7908270177 Ack receipt of 790720 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14.
LEWIS, R. C. Region 2, Atlanta, Office of the Director. 79/08/07. 1p.

--7908270185 Responds to NRC 790625 ltr re violation noted in IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14. Corrective actions essential raw cooling water RHR pump seal heat exchanger valves will be locked.
MILLS, L. M. Tennessee Valley Authority. 79/08/20. 2pp.

--7908270193 Forwards IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14 on 790521-25 & notice of violation.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 2pp.

--7908270199 Notice of violation from insp on 790521-25.
* Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 1p.

--7908270209 IE Insp Repts 50-259/79-14, 50-260/79-14 & 50-296/79-14 on 790521-25 Noncompliance noted failure to follow plant procedures re locking of RHR pump seal heat exchanger valves.
MOON, S. T. Region 2, Atlanta, Office of the Director. RUHLMAN, W. A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 6pp.

7908170015 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08. 2pp.

7908290217 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/10. 2pp.

R Periodic operating reports & related correspondence

7908070671 Forwards fish impingement rept for second quarter 1979.
MILLS, L. M. Tennessee Valley Authority. 79/07/30. 5pp.

7908140532 Amends 790730 fish impingement rept. Matl encl supersedes previously-submitted data for second quarter 1979.
MILLS, L. M. Tennessee Valley Authority. 79/08/09. 14pp.

7908140445 Forwards monthly operating rept for Jul 1979.
ALENCOURT, H. Tennessee Valley Authority. 79/08/10. 1p.

--7908140451 Monthly operating rept for Jul 1979.
ALENCOURT, H. ; THOM, T. ; GREEN, D. Tennessee Valley Authority. 79/08/02. 30pp.

S Reportable occurrences, LERs & related correspondence

7908010390 Forwards LER 79-008/03L-0.
FOX, H. S. Tennessee Valley Authority. 79/07/26. 1p.

--7908010393 LER 79-008/03L-0 on 790627 no speed indication noted on reactor core isolation coolant. Caused by broken wires to magnetic pickup EQ-M box. Wires repaired.
* Tennessee Valley Authority. 79/07/26. 2pp.

7908210425 Forwards LER 79-009/03L-0.
CALHOUN, J. R. Tennessee Valley Authority. 79/08/13. 1p.

--7908210429 LER 79-009/03L-0 on 790717 hydrogen ignition damaged HEPA filters. Caused by improper offgas recombiner preheater operation. Sys HEPA filters & charcoal bed inspected. Three filters replaced. Procedures will be revised.
* Tennessee Valley Authority. 79/08/13. 2pp.

7908280691 Forwards LER 79-010/03L-0.
CALHOUN, J. R. Tennessee Valley Authority. 79/08/22. 1p.

--7908280695 LER 79-010/03L-0 on 790723 setpoint for pressure switch 68-96 switch 1 found set above Tech Specs limit. Caused by instrument drift. Switch readjusted to proper setpoint & functionally tested for repeatability.
* Tennessee Valley Authority. 79/08/22. 2pp.

DOCKET 50-297 NORTH CAROLINA STATE UNIV. PULSTAR REACTOR

H General correspondence

7908210223 Ack receipt of 790530 ltr. Outlines objectives of NRC review of plants. Util has satisfactorily complied w/short-term requirements, permitting resumption or continuation of operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/14. 1p.

R Periodic operating reports & related correspondence

7908170380 Forwards "PULSTAR Annual Rept." 780701-790630.
SAKE, R. F. North Carolina State Univ. 79/08/07. 1p.

--7908170382 "PULSTAR Annual Rept." 780701-790630.
* North Carolina State Univ. 79/06/30. 41pp.

DOCKET 50-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

7908230085 Notification of 790808 meeting w/util in Nemaha County, NE to discuss security program.
ROONEY, V. L. Operating Reactors Branch 3. 79/07/13. 3pp.

J Insurance & indemnity information

7908070509 Forwards Annual Financial Rept 1978 & uniform forecast form for util analysts for IA Power.
PILANT, J. M. Nebraska Public Power District. 79/08/01. 3pp.

--7908070513 Annual Financial Rept, 1978.
* Iowa Power. 79/02/16. 52 pp.

P Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR- :0, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908080396 Submits summary of procedures to be used for clad removal & insp during 1980 refueling outage.
PILANT, J. M. Nebraska Public Power District. 79/07/02. 3pp.

7908270260 Ack receipt of 790320 ltr transmitting safeguards contingency plan for facility. Class III fee required.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 1p.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908300042 Notifies of approval of insp program for BWR pressure vessel feedwater & control rod drive return line nozzles proposed in 781227 ltr. Requests summary description of procedures for clad removal & insp.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/11. 2pp.

7908160265 Notification of 790926 meeting w/util in Nemaha County, NE to discuss LASL confirmatory vital area analysis.
ROONEY, V. L. Operating Reactors Branch 3. 79/07/13. 1p.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908220576 Forwards Amend 58 to License DPR-46, safety evaluation & notice of issuance & availability.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/23. 2pp.

--7908220584 Amend 58 to License DPR-46 modifying Tech Specs to permit operation of facility at less than 40% power for period not to exceed 48 hours between 790622 & 25 w/containment deinerted.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/23. 4pp.

--7908220588 Safety evaluation supporting Amend 58 to License DPR-46.
* Operating Reactors Branch 3. 79/07/23. 2pp.

--7908220593 Notice of issuance & availability of Amend 58 to License DPR-46.
ROONEY, V. L. Operating Reactors Branch 3. 79/07/23. 2pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908140691 Submits info re corporate mgt & technical capabilities re events similar to TMI-2 incident, as requested by NRC 790629 ltr.
PILANT, J. M. Nebraska Public Power District. 79/07/30. 32pp.

7908070625 Responds to 790724 discussions w/NRC. Forwards addl info re QA policy document Amend 3P, Section 8.
PILANT, J. M. Nebraska Public Power District. 79/08/02. 5pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908210508 Forwards background & supplementary info re App B ETS not incorporated into proposed App A radiological effluent Tech Specs, per Pilant 790525 proposal & NRC 781115 request.
PILANT, J. M. Nebraska Public Power District. 79/08/16. 4pp.

7908210512 Forwards info re Target Rock safety relief valves, per 790716 request.
PILANT, J. M. Nebraska Public Power District. 79/08/16. 3pp.

Q. Inspection reports, IE Bulletins & correspondence

7908080451 Responds to IE Bulletin 79-10 re requalification training program. Forwards operator & senior operator examination data.
PILANT, J. M. Nebraska Public Power District. 79/05/17. 3pp.

7908020581 IE Insp Rept 50-298/79-10 on 790501-04 & 14-15. Noncompliance noted: failure to perform safety-related maint activity w/latest approved revision of procedure.
JOHNSON, E. H., CUPP, E. A., WESTERMAN, T. F. Region 3, Chicago, Office of the Director. 79/06/04. 8pp.

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790629 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 79/06/20. 44pp.

7908170153 Responds to IE Bulletins 79-12 & 12A re atypical weld matl in reactor vessel welds. C-E 790608 submittal meets all reporting requirements of bulletins. Neither C-E nor util have archive matl for verification.
PILANT, J. M. Nebraska Public Power District. 79/06/26. 2pp.

7908170161 Responds to IE Bulletin 79-11. All Westinghouse Type DB-50 breakers have tested satisfactorily. Spare end caps for trip coils have been inspected. Modified DB-50 breakers will be tested during each refueling outage.
PILANT, J. M. Nebraska Public Power District. 79/06/27. 2pp.

7908100196 Provides addl info in response to IE Bulletin 79-07. Forwards results of safety relief valve discharge piping reevaluation & detailed computer code validation program.
PILANT, J. M. Nebraska Public Power District. 79/06/29. 18pp.

7908160012 Responds to IE Bulletin 79-08 re events relevant to BWRs identified during TMI incident. No Tech Spec changes are necessary.
PILANT, J. M. Nebraska Public Power District. 79/07/05. 1p.

7908100200 Forwards response to IE Bulletin 79-02. Analytical efforts & anchor bolt testing have assured that each seismic Category I piping sys will remain fully operational.
PILANT, J. M. Nebraska Public Power District. 79/07/06. 19pp.

7908160006 Responds to IE Bulletin 79-12 re short period scrams at BWR facilities. Describes means of preventing addl scrams. Responds to Item I-5 re critical prediction of rod pattern estimates & emergency rod in switch.
PILANT, J. M. Nebraska Public Power District. 79/07/11. 3pp.

7908020398 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/07/18. 1p.

7908160034 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. Clarifies safety significance of safety relief valve discharge piping discussed in 790629 ltr.
PILANT, J. M. Nebraska Public Power District. 79/07/18. 2pp.

7908140055 Ack receipt of 790727 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-298/79-10.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/07/19. 1p.

--7908140057 Responds to NRC 790606 ltr re violation noted in IE Insp Rept 50-298/79-10. Corrective actions: personnel involved have been instructed to use latest revision of procedure.
PILANT, J. M. Nebraska Public Power District. 79/06/27. 2pp.

7908080324 Requests addl info to suppl previous response to IE Bulletin 79-08 to enable NRC to complete safety evaluation.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/20. 4pp.

7908220162 Ack receipt of 790626 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-298/79-09.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/07/24. 1p.

7908060041 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/07/26. 1p.

7908060127 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/07/26. 1p.

7908080465 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Major insp elements to be used are contained in seismic & gravity load piping isometrics for each sys & Ielco-Grinnell drawings.
PILANT, J. M. Nebraska Public Power District. 79/08/01. 48pp.

7908140549 Responds to request for addl info re IE Bulletin 79-08. Design of BWR containment is such that all lines penetrating containment have valves which may be isolated.
PILANT, J. M. Nebraska Public Power District. 79/08/07. 9pp.

7908290212 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/10. 1p.

R. Periodic operating reports & related correspondence

7908140761 Forwards monthly operating rept for Jul 1979.
LESSOR, L. C. Nebraska Public Power District. 79/08/03. 1p.

--7908140764 Monthly operating rept for Jul 1979.
BORER, P. J. Nebraska Public Power District. 79/08/03. 4pp.

S. Reportable occurrences, LERs & related correspondence

7908010555 Forwards LER 79-016/03L-0.
LESSOR, L. C. Nebraska Public Power District. 79/06/26. 2pp.

--7908010557 LER 79-016/03L-0 on 790531: RHR pump 1A tripped during start on overcurrent in Phase C. Caused by failure of GE model 121AC66RBA overcurrent relay operating disc to return to normal position. Relay cleaned, recalibr & retested.
BEDNAR, L. F. Nebraska Public Power District. 79/06/26. 2pp.

7908080596 Forwards LER 79-017/03L-0.
LESSOR, L. C. Nebraska Public Power District 79/07/19 2pp

--7908080602 LER 79-017/03L-0 on 790620 during review, observed that Surveillance Procedure 6.2.4.1 did not include daily check of undervoltage relays or monthly functional testing. Cause unstated. Procedures revised.
BEDNAR, L. F. Nebraska Public Power District 79/07/19 1p

7908010700 Forwards PNO-79-67AX.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/20 1p

7908310436 Forwards LER 79-015/03X-1.
LESSOR, L. C. Nebraska Public Power District 79/08/01 3pp

--7908310444 LER 79-015/03X-1 on 790525 breaker 1AS failed to close automatically after reactor scrammed. Caused by improper operations of switch 52 in breaker 1AN. Breaker 1FA failed to trip. Caused by misaligned trip coil & armature.
BEDNAR, L. F. Nebraska Public Power District 79/08/01 1p

7908310415 Forwards LER 79-005/03X-1.
LESSOR, L. C. Nebraska Public Power District 79/08/02 2pp

--7908310420 LER 79-005/03X-1 on 790216 reactor recirculation motor generator set A tripped during normal operation. Caused by failure of level switch NBI-LIS-58A due to corrosion. Corrosion cleaned from inside switch case & switch replaced.
NOYES, C. R. Nebraska Public Power District 79/08/02 1p

7908310357 Forwards LER 79-018/03L-0.
LESSOR, L. C. Nebraska Public Power District 79/08/03 2pp

--7908310364 LER 79-018/03L-0 on 790706 during routine testing, reactor vessel level indicating switch NBI-LIS-58A was found w/trip point less than allowed. Caused by sediments of dust & moisture in auxiliary switch.
PHILLIPS, D. Nebraska Public Power District 79/08/03 1p

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

7908130119 Forwards "Evaluation of Min Fire Brigade Shift Size." Min size should be five persons.
LAINAS, G. Plant Systems Branch 79/06/28 2pp

--7908130122 "Evaluation of Min Fire Brigade Shift Size."
* Plant Systems Branch 79/06/08 32pp

7908130222 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp

7908020437 Forwards amended additions to modified amended physical security plan & contingency plan. Plan withheld (ref 10CFR2.790).
BURSTEIN, S. Wisconsin Electric Power Co. 79/08/01 1p

7908290411 Forwards training & qualification plan. Plan withheld (ref 10CFR2.790).
BURSTEIN, S. Wisconsin Electric Power Co. 79/08/21 1p

H. General correspondence

7908150084 Ack receipt of correspondence re status of spent fuel storage at six operating facilities near Lake Michigan. Responds to 790429 ltr.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/26 2pp

--7908150107 Discusses spent fuel storage capability at Big Rock Point. NUREG-0020 indicates authorized capacity of 120 spent fuel assemblies, while DOE indicates capacity of 365. Requests clarification.
SCHAEFER, J. Lake Michigan Federation 79/05/20 1p

--7908150125 Ack receipt of info re nuclear power plants near Lake MI. Forwards rept re status of spent fuel storage at plants. Requests comments re rept.
SCHAEFER, J. Lake Michigan Federation 79/06/21 1p

--7908150139 "Status of Spent Fuel Storage at Six Nuclear Plants Located on Shores of Lake MI."
SCHAEFER, J. Lake Michigan Federation 79/05/31 20pp

7908020423 Requests extension of time beyond 790730 response date to supply info re capability of mgt & technical staffs to react to accident of TMI type. One copy will be submitted due to proprietary nature of data.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/30 1p

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp

7908030232 Summarizes status of five overpressure protection & three flooding reviews evaluated by LLL in response to Eisenhut 790604 memo.
SHEMANSKI, P. Plant Systems Branch 79/06/12 2pp

7908010270 Corrects 790511 ltr re ref to Amend 42 to License DPR-27. Ltr should have referred to Amend 43.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625) 79/06/18 2pp

7908160561 Responds to 770314 ltr re analysis of radiological consequences of postulated fuel handling accident inside containment. Potential consequences within exposure guidelines of 10CFR100. Safety evaluation encl.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625) 79/06/20 2pp

--7908160566 Safety evaluation re fuel handling accident inside containment. Radiological consequences to person located at exclusion area boundary are within dosage guideline values of 10CFR100.
* Office of Nuclear Reactor Regulation 79/06/20 4pp

7908060542 Forwards request for addl info re proposed changes to nonradiological ETS. Requests response within 60 days.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625) 79/06/22 5pp

7908070679 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/22 3pp

7908020285 Discusses util 770728 ltr re degraded grid voltage generic issues. Forwards request for addl info re trip setpoint time delay, voltage monitor verification of IEEE requirements & channel functional tests.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625) 79/07/03 3pp

7908030338 Summary of 790706 meeting w/util re repair of welds found on feedwater lines inside containment. Agenda, attendance list & photomicrographs encl.
TRAMMELL, C. M. Operating Reactors Branch 1 79/07/09 10pp

7908100534 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires initial notification of NRC.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/09 1p

7908150547 Requests registration as user of Model LL-50-100.
FAY, C. W. Wisconsin Electric Power Co. 79/07/16 1p

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908070347 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/19 1p

7908200138 Responds to 790409 request re evacuation plans in event of radiation problem. Forwards NUREG-0396 & Reg Guide 1.101. W/o encl.
KNIGHTON, G. W. Environmental Evaluation Branch 79/07/19 1p

7908010383 Requests that WCAP-9600, "Rept on Small Break Accidents for Westinghouse NSSS Sys" be included in dockets.
FAY, C. W. Wisconsin Electric Power Co. 79/07/23 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp.

7908130584 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model licence condition encl.
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 4pp.

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 52pp.

7908200326 Describes re-evaluation of potential steam generator water hammer. Forwards table of operating experience & feedwater piping configurations. Water hammer not likely to occur under any conditions.
DEARIEN, J. A. EG & G, Inc. 79/08/06 3pp.

7908290561 Requests clarification of fee classification for radiation protection manager qualification Tech Spec changes.
MILLER, W. O. License Fee Management Branch 79/08/07 2pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908270473 Responds to NRC 790622 request for additional info re changes to nonradiological environ surveillance program for facility.
BURSTEIN, S. Wisconsin Electric Power Co. 79/08/22 18pp.

G. Inspection reports, IE Bulletins & correspondence

7908060537 Forwards addl info in response to IE Bulletin 79-04 in light of Velan check valve reanalysis. Mods to piping sys or pipe supports not required. All pipe support loads less than max specified by design.
BURSTEIN, S. Wisconsin Electric Power Co. 79/05/25. 3pp.

7908150225 Forwards IE Insp Repts 50-266/79-08 & 50-301/79-10 on 790612-14. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/25. 2pp.

--7908150232 IE Insp Repts 50-266/79-08 & 50-301/79-10 on 790612-14. No noncompliance noted. Major areas inspected: followup on IE Bulletin 79-02, pipe support base plate designs using concrete expansion bolts & review of test program.
GALLAGHER, E. J., HAYES, D. W. Region 3, Chicago, Office of the Director 79/06/21 5pp.

7908080553 Responds to IE Bulletin 79-11 re Westinghouse Type DB-50 & DB-75 breakers in safety-related sys. Review of tests & calibr records indicates no recent failures. Problem & corrective action explained in I4R 79-004/01T-0.
FAY, C. W. Wisconsin Electric Power Co. 79/06/29 2pp.

7908140330 Provides 24-h notification of volumetric examinations of steam generator feedline piping welds performed per IE Bulletin 79-13. Testing of feedwater lines A & B revealed possible defects but no potential threats to safety.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/06 4pp.

7908150230 Discusses 781026 response to IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessel Welds," & modified requirements in IE Bulletins 78-12A & 12B. Certification, Westinghouse 790625 ltr & C-E 790605 ltr encl.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/06 6pp.

7908090416 Responds to IE Bulletin 79-13 re radiographic examinations of feedwater nozzle-to-piping welds & adjacent pipe & nozzle areas. Unit 2 feedline welds are being repaired. Unit 1 will be inspected during fall refueling outage.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/12 48pp.

7908020359 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908290309 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908290377 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300437 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908080475 Responds to IE Bulletin 79-14, "Seismic Analyses for As-Built Safety Related Piping Systems." All acceptable piping will be inspected as soon as practicable & Unit 1 containment will be inspected during Fall 1979 refueling.
BURSTEIN, S. Wisconsin Electric Power Co. 79/08/01 36pp.

7908210329 Forwards request for addl info, in response to IE Bulletins 79-06A & 79-06A, Revision 1. Needed info includes review completion date, containment isolation procedures & procedures controlling manipulation of safety valves.
SCHWENCER, A. Operating Reactors Branch 1 79/08/03. 4pp.

7908150398 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300789 Determines that reanalysis of safety-related piping lines affected by IE Bulletin 79-07 has been performed w/acceptable computer program which does not use algebraic summation & that results are acceptable.
SCHWENCER, A. Operating Reactors Branch 1 79/08/07 2pp.

7908170027 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08. 1p.

7908300307 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

7908300740 Responds to NRC 790803 ltr requesting addl info re IE Bulletins 79-06A & 79-06A Revision 1. Summary of owners group review of emergency procedures & intended procedural revisions will be submitted by 791231.
FAY, C. W. Wisconsin Electric Power Co. 79/08/23 11pp.

R. Periodic operating reports & related correspondence

7908140401 Forwards monthly operating rept for Jul 1979.
BURSTEIN, S. Wisconsin Electric Power Co. 79/08/09. 1p.

--7908140409 Monthly operating rept for Jul 1979.
* Wisconsin Electric Power Co. 79/08/03. 8pp.

7908160448 Forwards monthly operating rept for Jul 1979.
BURSTEIN, S. Wisconsin Electric Power Co. 79/08/09. 1p.

S. Reportable occurrences, LERs & related correspondence

7908010381 Forwards LER 79-006/01T-0.
FAY, C. W. Wisconsin Electric Power Co. 79/07/24. 1p.

--7908010385 LER 79-006/01T-0 on 790711 during insp & repair of main feedline, confirmed that branch connection of auxiliary feedline was not mfg per design requirements. Branch connections replaced by weldolets.
FAY, C. W. Wisconsin Electric Power Co. 79/07/24. 2pp.

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

7908270255 Ack receipt of 790322 ltr transmitting safeguards contingency plan for facility Class III fee required.
DIGGS, R M. License Fee Management Branch. 79/07/03. 1p.

7908200206 Forwards preliminary security training & qualification plan. Plan withheld (ref 10CFR2.790).
STEWART, W P. Florida Power Corp. 79/08/17. 2pp.

7908310378 Forwards schedule for completion of mods listed in Section 3.0 of 790727 safety evaluation, to improve file protection program. Mods expected to be implemented before 801031, barring matl delivery problems.
STEWART, W P. Florida Power Corp. 79/08/27. 3pp.

G. Adjudicatory correspondence

7908290127 Draft ltr forwarding FR notice & safety evaluation re unit restart. Requests schedule for long-term mods.
DENTON, H R. Office of Nuclear Reactor Regulation. 79/07/03. 2pp.

--7908290139 Safety evaluation related to unit restart. Concludes licensee has complied w/NRC 790518 order & may accordingly restart unit.
* Commission. 79/07/02. 27pp.

--7908290152 Draft notice of authorization to resume operation.
REID, R W. Operating Reactors Branch 4. 79/07/03. 2pp.

H. General correspondence

7908270113 Submits updated info re admittance of addl NRC personnel. Requests site orientation re issuance of badges, escort duties & emergency evaluation re given to personnel.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/30. 2pp.

7908020473 Forwards info mgt technical qualifications for handling event similar to TMI accident.
STEWART, W P. Florida Power Corp. 79/07/31. 200pp.

7908140511 Submits change of address.
BREEDLOVE, P D. Florida Power Corp. 79/08/08. 2pp.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908290499 Forwards 790419 draft of Offsite Dose Calculation Manual for use w/790419 draft Tech Specs based on NUREG-0472, Revision 2, Feb 1978.
BRIGHT, R M. Florida Power Corp. 79/05/30. 1p.

--7908290506 Draft Offsite Dose Calculation Manual.
* Florida Power Corp. 79/04/19. 34pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D G. Division of Operating Reactors. 79/06/04. 52pp.

7908280754 Discusses util application of portions of QA program to transport radioactive packages.
STEWART, W P. Florida Power Corp. 79/06/15. 2pp.

7908030311 Forwards branch safety evaluation of proposed overpressure mitigating sys. Sys acceptable, but branch recommends mods to be implemented during next refueling shutdown.
LAINAS, G. Plant Systems Branch. 79/06/20. 1p.

--7908030315 Safety evaluation of overpressure mitigating sys. Recommends mods in areas of electrical, instrumentation & controls.
* Plant Systems Branch. 79/06/20. 5pp.

--7908030318 Technical evaluation of electrical, instrumentation & control aspects of proposed low temp overpressure mitigating sys.
ROBERTS, E W. EG & G, Inc. 79/06/20. 11pp.

7908030089 Forwards Amend 21 to License DPR-72, safety evaluation & notice of issuance & availability.
REID, R W. Operating Reactors Branch 4. 79/07/03. 2pp.

--7908030095 Amend 21 to License DPR-72, changing Tech Specs to allow "racking out" power supply breakers for high pressure isolation valves during Mode 4 operation.
REID, R W. Operating Reactors Branch 4. 79/07/03. 4pp.

--7908030098 Safety evaluation supporting Amend 21 to License DPR-72.
REID, R W. Operating Reactors Branch 4. 79/07/03. 11pp.

--7908030101 Notice of issuance & availability of Amend 21 to License DPR-72.
REID, R W. Operating Reactors Branch 4. 79/07/03. 2pp.

7908030304 Forwards Amend 19 to License DPR-72 safety evaluation & notice of issuance & availability.
REID, R W. Operating Reactors Branch 4. 79/07/03. 3pp.

--7908030307 Amend 19 to License DPR-72, revises Tech Specs to permit power operation during Cycle 2 at currently authorized power level of 2452 MWt.
GAMMILL, W P. Assistant Director for Operating Reactor Projects. 79/07/03. 37pp.

--7908030308 Safety evaluation supporting Amend 19 to License DPR-72.
* Office of Nuclear Reactor Regulation. 79/07/03. 11pp.

--7908030310 Notice of exemption authorizing facility to operate at rated core thermal power until 790806.
EISENHUT, D G. Division of Operating Reactors. 79/07/03. 5pp.

--7908030314 Notice of issuance & availability of Amend 19 to License DPR-72.
REID, R W. Operating Reactors Branch 4. 79/07/03. 3pp.

7908070356 Forwards Amend 20 to License DPR-72, safety evaluation & notice of issuance & availability.
REID, R W. Operating Reactors Branch 4 (Pre 790625). 79/07/03. 2pp.

--7908070365 Amend 20 to License DPR-72, changing required sodium hydroxide concentration in reactor bldg spray chemical additive tank & increasing required shutdown margin.
REID, R W. Operating Reactors Branch 4 (Pre 790625). 79/07/03. 15pp.

--7908070394 Safety evaluation supporting Amend 20 to License DPR-72.
* Office of Nuclear Reactor Regulation. 79/07/03. 7pp.

--7908070403 Notice of issuance & availability of Amend 20 to License DPR-72.
REID, R W. Operating Reactors Branch 4 (Pre 790625). 79/07/03. 2pp.

7908080252 Notifies that Class III amend fee of $4,000 is being refunded.
MILLER, W O. License Fee Management Branch. 79/07/11. 1p.

7908080281 Requests that Division of Accounting refund amend fee to util; exemption from fee is in order.
MILLER, W O. License Fee Management Branch. 79/07/11. 1p.

7908150720 Requests evaluation of semiscale small break experiment w/small break computer program by 790901.
ROSS, D F. TMI-2 Unresolved Safety Issues. 79/07/16. 7pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D G. Division of Operating Reactors. 79/07/18. 58pp.

7908070309 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908170168 Forwards Amend 22 to License DPR-72, safety evaluation & notice of issuance & availability.
REID, R W. Operating Reactors Branch 4. 79/07/23. 2pp.

--7908170170 Amend 22 to License DPR-72, incorporating into Tech Specs changes to ECCS surveillance requirements.
REID, R W. Operating Reactors Branch 4. 79/07/23. 5pp.

--7908170172 Safety evaluation supporting Amend 22 to License DPR-72.
* Office of Nuclear Reactor Regulation. 79/07/23. 2pp.

--7908170177 Notice of issuance & availability of Amend 22 to License DPR-72.
REID, R. W. Operating Reactors Branch 4. 79/07/23. 2pp.

7908200055 Requests proposed amend to license to delete Tech Specs re secondary water chemistry monitoring program & to incorporate requirements of encl model license. Requests submittal condition within 60 days.
REID, R. W. Operating Reactors Branch 4. 79/07/23. 4pp.

7908010373 Responds to P Polk request & forwards oscillograph traces of grid voltage & current flows during 790711 Crystal River & Hatch trips.
BETSILL, J. A. Georgia Power Co. 79/07/24. 7pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908230056 Requests results of semiscale small break experiment be compared w/small break computer program being used by C-E in support of owners group. To date, evaluations of latter have been inconclusive.
ROSS, D. F. TMI-2 Bulletins & Orders. 79/07/25. 8pp.

7908170606 Updates info re NRC personnel to be admitted to facility & needing picture badges. Requests site orientation re badges, escort duties & emergency evacuation.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908230110 Forwards Amend 23 to License DPR-72, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4. 79/07/27. 3pp.

--7908230114 Amend 23 to License DPR-72, adding license conditions relating to completion of facility mods & implementation of administrative controls for fire protection.
REID, R. W. Operating Reactors Branch 4. 79/07/27. 2pp.

--7908230117 Safety evaluation supporting Amend 23 to License DPR-72.
* Operating Reactors Branch 4. 79/07/27. 60pp.

--7908230121 Notice of issuance & availability of Amend 23 to License 72.
REID, R. W. Operating Reactors Branch 4. 79/07/27. 2pp.

7908070330 Submits Revision 3 to App C to QA topical rept [illegible]1-76A, providing alternative to requirement for insp of rigging & hoisting equipment.
[illegible]WING, R. E. Florida Power & Light Co. 79/07/30. 2pp.

7908300549 Summary of 790719 meeting w/utils in Bethesda, MD to discuss outstanding items from NRC orders & IE Bulletins generic to all B&W facilities.
CAPRA, R. A. TMI-2 Bulletins & Orders. 79/07/31. 24pp.

7908070383 Forwards Tech Specs Change Request 17, requesting amend to App A of License DPR-72. Certificate of Svc encl.
STEWART, W. P. Florida Power Corp. 79/08/02. 3pp.

--7908070386 Tech Specs Change Request 17 to amend App A of License DPR-72 re low temp overpressure protection mitigating sys.
* Florida Power Corp. 79/08/02. 7pp.

7908210346 Updates info re admittance of addl NRC personnel to facility. Requests site orientation for R Sauer.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/03. 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908270530 Requests addl info re proposed spent fuel pool expansion.
REID, R. W. Operating Reactors Branch 4. 79/08/03. 3pp.

7908090387 Responds to NRC 790706 request. Forwards schedule for completion of long-term mod re emergency feedwater flow, per Section II of 790516 order.
STEWART, W. P. Florida Power Corp. 79/08/06. 4pp.

7908090457 Lists steps to ensure auxiliary feedwater flow during post-refueling startup, per 790803 telcon w/NRC. Actions result from malfunction of ultrasonic flow indicator transducers, due to main feedwater use at overly high temp.
STEWART, W. P. Florida Power Corp. 79/08/06. 3pp.

7908100301 Notifies that mods & procedures incorporated in ECCS small breaks analysis are complete.
STEWART, W. P. Florida Power Corp. 79/08/06. 2pp.

7908160239 Notification of 790809 meeting w/B&W Owners' Group in Bethesda, MD to discuss long-term generic requirements for B&W operating plants.
CAPRA, R. A. TMI-2 Unresolved Safety Issues. 79/08/06. 2pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908140447 Advises that util does not agree w/positions identified in NRC 790611 ltr re degraded grid voltage conditions.
STEWART, W. P. Florida Power Corp. 79/08/10. 3pp.

7908170397 Informs of multiphase program to evaluate effects of asymmetric LOCA loads. Program to be completed Jul 1980.
STEWART, W. P. Florida Power Corp. 79/08/13. 3pp.

7908210405 Forwards time history & shock response spectrum re reactor coolant pump power monitors prepared by Harris Corp Gilbert Commonwealth evaluation of rept data encl.
BRIGHT, R. M. Florida Power Corp. 79/08/14. 6pp.

7908230415 Forwards operator logs documenting start & stop times for both emergency feedwater pumps during endurance runs & Work Request 8999 used by util mechanics to document bearing temp during tests, in response to NRC 790810 request.
STEWART, W. P. Florida Power Corp. 79/08/17. 22pp.

Q. Inspection reports, IE Bulletins & correspondence

7907020065 Forwards IE site inspector daily repts for B&W reactors for 790419.
DAVIS, J. G. Office of Inspection & Enforcement, Office of the Director. 79/04/20. 1p.

7908010638 Forwards IE Insp Rept 50-302/79-04 on 790212-16 & notice of violation.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/05/24. 2pp.

--7908010643 Notice of violation from insp on 790212-16.
* Region 2, Atlanta, Office of the Director. 79/05/24. 7pp.

--7908010650 IE Insp Rept 50-302/79-04 on 790212-16. Noncompliance noted: failure to apply required program control on supplies, failure to distribute documents & failure to record bases for safety evaluations.
MCDONALD, J. A., KELLOGG, P. J., RUHLMAN, W. A. Region 2, Atlanta, Office of the Director. 79/05/18. 29pp.

7908280808 Forwards IE Insp Rept 50-302/79-17 on 790523-25. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/06. 2pp.

--7908280817 IE Insp Rept 50-3-2/79-17 on 790523-25. No noncompliance noted. Major areas inspected: licensee organization & administration, operations & maintenance & preparation for refueling activities.
BRADFORD, W. H., VERDERY, E. H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/04. 3pp.

7908030572 Responds to IE Bulletin 79-01 re environ qualification of Class IE equipment. Forwards review of safety-related electrical equipment installed inside containment & qualifications to function under accident conditions.
STEWART, W. P. Florida Power Corp. 79/06/18. 7pp.

7908290213 Forwards IE Insp Rept 50-302/79-18 on 790601. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/19. 2pp.

--7908290221 IE Insp Rept 50-302/79-18 on 790601. No noncompliance noted. Major areas inspected: nonradiological environ procedures & environ monitoring.
CUNNINGHAM, A. L. Region 2, Atlanta, Office of the Director.
HUFHAM, J. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/18. 3pp.

DOCKETED ITEMS

7908030040 Responds to IE Bulletin 79-01A re facility design. No ASCO solenoid valves are used in safety-related sys inside containment.
STEWART, W. P. Florida Power Corp. 79/06/22. 1p.

7908270312 Responds to IE Bulletin 79-10. Provides addl info re requalification training program statistics.
STEWART, W. P. Florida Power & Light Co. 79/06/26. 3pp.

7908300775 Responds to IE Bulletins 79-02 & 79-02, Revision 1. Ninety-two pipe supports have been identified as inadequate. Affected supports will be redesigned & installed.
BEATTY, G. P. Florida Power Corp. 79/07/03. 1p.

7908240128 Forwards IE Insp Rept 50-302/79-20 on 790613-15 & 20-22. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/05. 2pp.

--7908240132 IE Insp Rept 50-302/79-20 on 790613-15 & 20-22. No noncompliance noted. Major areas inspected: concrete expansion anchor installation.
MODENOS, L. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/03. 3pp.

7908240291 Forwards IE Insp Rept 50-302/79-19 on 790528-0601. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/05. 2pp.

--7908240297 IE Insp Rept 50-302/79-19 on 790528-0601. No noncompliance noted. Major areas inspected: refueling activities, maint & mod of fuel handling equipment & followup of open items from previous insps.
BURNETT, P. T., GRAHAM, M. J., MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/03. 5pp.

7908010028 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908240123 Forwards IE Insp Rept 50-302/79-25 on 790616-19. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 2pp.

--7908240127 IE Insp Rept 50-302/79-25 on 790616-19. No noncompliance noted. Major areas inspected: feedwater pipe welds via radiographic methods.
ECONOMOS, N. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/09. 4pp.

7908030130 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908170630 Supplements 790706 response to IE Bulletin 79-02, Revision 1. Describes plans to upgrade safety-related pipe hangers. Will submit schedule by 790720. Mods will be complete before reaching Mode 2 operation. Tables encl.
MOORE, G. C. Florida Power Corp. 79/07/13. 11pp.

7908290688 Forwards supplemental response to IE Bulletin 79-02, Revision 1. All pipe hangers will be upgraded to appropriate or greater safety factor prior to facility entering Mode 2 status.
MOORE, G. C. Florida Power Corp. 79/07/13. 12pp.

7908200264 Forwards response to IE Bulletin 79-13, Item 5. Emergency procedures EP-108 & EP-105 have been revised extensively, in light of TMI-2 accident. Describes methods of detecting feedwater leaks in containment.
STEWART, W. P. Florida Power & Light Co. 79/07/16. 2pp.

7908010410 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030008 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080039 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130108 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908170259 Forwards suppl to 790713 response to IE Bulletin 79-02, Revision 1 & response to six informal NRC questions. Suppl identifies hangers being upgraded to appropriate safety factor during present outage.
STEWART, W. P. Florida Power Corp. 79/07/20. 26pp.

7908150709 Responds to Item 6 of IE Bulletin 79-13. Describes requested feedwater weld examinations.
STEWART, W. P. Florida Power Corp. 79/07/25. 8pp.

7908060515 Forwards IE Bulletin 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 1p.

7908070749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908080712 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160229 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

/908060072 Forwards drawings re Control Rod 3 pump & valve inservice insp program, in response to NRC 790308 ltr.
STEWART, W. P. Florida Power Corp. 79/07/31. 2pp.

7908300074 Ack receipt of 790622 & 29 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-13.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/08/01. 1p.

--7908300080 Responds to NRC 790531 ltr re violations noted in IE Insp Rept 50-302/79-13. Corrective actions: revised SP-300 to require logging of sump & recorder level after each shift.
STEWART, W. P. Florida Power Corp. 79/07/24. 1p.

--7908300087 Responds to NRC 790531 ltr re violations noted in IE Insp Rept 50-302/79-13. Corrective actions: personnel have been cautioned that variance from approved procedures must be implemented by approved procedural controls.
STEWART, W. P. Florida Power Corp. 79/06/22. 2pp.

--7908300088 Forwards IE Insp Rept 50-302/79-13 on 790326-0504 & notice of violation.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/05/31. 2pp.

--7908300091 Notice of violation from insp on 790326-0504.
* Region 2, Atlanta, Office of the Director. 79/05/31. 1p.

--7908300100 IE Insp Rept 50-302/79-13 on 790326-0504. Noncompliance noted: failure to perform surveillance requirement on containment sump & failure to approve temporary procedure change.
MCHENRY, T. J., QUICK, D. R. Region 2, Atlanta, Office of the Director. DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/05/31. 16pp.

7908170001 Responds to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys. Forwards insp program & list of safety-related sys to be inspected.
STEWART, W. P. Florida Power Corp. 79/08/02. 10pp.

7908160140 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

7908170011 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08. 2pp.

7908290192 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/10 2pp

R. Periodic operating reports & related correspondence

7908170409 Forwards monthly operating rept for Jul 1979.
STEWART, W.P. Florida Power Corp. 79/08/10 1p

--7908170413 Monthly operating rept for Jul 1979.
BEATTY, G. Florida Power Corp. 79/07/31 6pp

7908310518 Forwards "Effluent & Waste Disposal Semiannual Rept" for Jan-June 1979.
STEWART, W.P. Florida Power Corp. 79/08/31 2pp

--7908310522 "Effluent & Waste Disposal Semiannual Rept" for Jan-June 1979.
* Florida Power Corp. 79/08/29 59pp

S. Reportable occurrences, LERs & related correspondence

7908030399 Forwards LER 79-063/03L-0.
STEWART, W.P. Florida Power Corp. 79/07/30 2pp

--7908030408 LER 79-063/03L-0 on 790709 pin hole leak discovered at piping elbow on discharge chain of Makeup Pump 1B Caused by cyclic vibration fatigue Repaired under Mod 79-7-70. ME179-7-7 initiated to reduce cyclic vibration.
COOPER, J. Florida Power Corp. 79/07/09 1p

7908060506 Forwards LER 79-057/03L-1.
STEWART, W.P. Florida Power Corp. 79/08/01 1p

--7908060514 LER 79-057/03L-1 on 790606 emergency diesel generator output breakers A & B tripped during separate tests Caused by procedural deficiencies Revisions have been implemented.
COOPER, J. Florida Power Corp. 79/07/30 3pp

7908100455 Forwards LER 79-064/04L-0.
STEWART, W.P. Florida Power Corp. 79/08/02 1p

--7908100459 Suppl info to LER 79-064/04L-0 on 790727 difference of more than two std deviations discovered between preoperational & operational study in metabolic functions of aquatic sys Caused by natural or seasonal variations.
* Florida Power Corp. 79/08/01 3pp

7908100343 Forwards LER 79-065/03L-0.
STEWART, W.P. Florida Power Corp. 79/08/03 1p

--7908100351 LER 79-065/03L-0 on 790711 while in Mode 3 Loop HPI flow transmitter B discovered out of calibr during surveillance procedure SP-414 Caused by instrument drift. Transmitter recalibr & returned to svc.
COOPER, J. Florida Power Corp. 79/08/02 2pp

7908210361 Forwards LER 79-066/03L-0.
STEWART, W.P. Florida Power Corp. 79/08/13 1p

--7908210363 LER 79-066/03L-0 on 790718 during Mode 5, reported that RCS chloride, fluoride, gross Beta & DEI-131 analyses not performed from 790714-18 due to personnel oversight RCS sampled on 790718 & parameters were within Tech Spec limit.
COOPER, J. Florida Power Corp. 79/08/09 2pp

7908230541 Forwards LER 79-067/03L-0.
STEWART, W.P. Florida Power Corp. 79/08/17 1p

--7908230548 LER 79-067/03L-0 on 790723 chloride concentration in pressurizer was 0.18 ppm Caused by steaming action in pressurizer during startup Spray flow increased diluting chlorides to within spec limits.
COOPER, J. Florida Power Corp. 79/08/14 2pp

7908280584 Confirms 790816 telcon to B Messitt re plant entering mode 3 as result of reactor trip Detailed rept to follow in 14 days.
BEATTY, G.P. Florida Power Corp. 79/08/17 1p

7908280594 Discusses event on 790817 re unplanned release of radioactive liquid when turbine bldg sump was pumped to settling pond Health & safety of general public was not affected Rept will be submitted within 14 days.
BEATTY, G.P. Florida Power Corp. 79/08/17 1p

7908270445 Forwards LER 79-068/03L-0.
STEWART, W.P. Florida Power Corp. 79/08/20 1p

--7908270450 LER 79-068/03L-0 on 790723 post-maint testing of core flood tank vent valves CFV-15 & 16 not completed prior to return to svc Caused by defective procedures Procedures revised.
COOPER, J. Florida Power Corp. 79/08/15 2pp

7908280693 Forwards LER 79-069/03L-0.
STEWART, W.P. Florida Power & Light Co. 79/08/21 1p

--7908280699 LER 79-069/03L-0 on 790724 emergency diesel generator B had excessive exhaust manifold temps & fire exiting from exhaust muffler Caused by fuel accumulation in manifold due to air leak on turbocharger discharge.
COOPER, J. Florida Power & Light Co. 79/08/16 3pp

7908290450 Forwards LER 79-069/03L-0.
STEWART, W.P. Florida Power Corp. 79/08/21 1p

--7908290457 LER 79-069/03L-0 on 790724 emergency diesel generator had excessive exhaust manifold temps & fire exiting exhaust muffler Caused by air leak on turbocharger discharge Air leak repaired & generator returned to svc.
COOPER, J. Florida Power Corp. 79/08/16 3pp

7908310303 Forwards LER 79-070/03L-0.
STEWART, W.P. Florida Power Corp. 79/08/27 1p

--7908310309 LER 79-070/03L-0 on 790731 reactor bldg atmospheric monitor RMA-6 was found isolated Caused by damaged wires to control switches for containment monitoring isolation valves WSV-5 & WSV-6 Wires were repaired.
COOPER, J. Florida Power Corp. 79/08/21 2pp

7908310466 Forwards LER 79-071/03L-0.
STEWART, W.P. Florida Power Corp. 79/08/27 1p

--7908310481 LER 79-071/03L-0 on 790801 in Mode 1, reactor bldg isolation Valves CAV-4 & CAV-5 would not close from control room after securing from continuous blowdown Caused by valves being stuck & underlubricated Valves freed & lubricated.
COOPER, J. Florida Power Corp. 79/08/27. 2pp.

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

7908070061 Responds to 790614 ltr re agreement relating to offsite emergency event NRC need not sign agreement, but needs to be notified of incident severity DOE is to coordinate response to radiological accidents in area.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/06/29. 1p.

--7908070064 Forwards draft agreement to be signed by NRC & util, committing NRC to respond to facility request in event of offsite emergency involving release of radioactivity.
WANDKE, N.E. Commonwealth Edison Co. 79/06/14. 2pp.

7908130162 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee Plans should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch 79/07/03 2pp

7908160367 Forwards request for addl info re contingency plans Encl withheld (ref 10CFR2.790).
ZIEMANN, D.L. Operating Reactors Branch 2 79/07/19 2pp

7908030167 Discusses current status of fire protection mods re gas suppression sys, fire doors & reactor coolant pump as follow-up to C Reed 790606 ltr & in response to NRC 790413 request.
REED, C. Commonwealth Edison Co. 79/07/27 3pp

7908030394 Notifies that fire protection program mod of electric equipment room to install test switches in each essential indication circuit in 1 & 2 racks has been delayed due to design phase & will be completed by 791012.
NAUGHTON, W.F. Commonwealth Edison Co. 79/07/27 1p

7908160249 Notifies that refund for Class I & II amend fees re fire protection Tech Spec changes is being processed.
MILLER, W.D. License Fee Management Branch 79/07/27 1p

7908200250 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/08/16. 1p.

G. Adjudicatory correspondence

7908080136 Testimony of RE Webb on contentions re accident hazards of spent fuel storage. Storage is unsafe due to possibility of loss-of-water accidents. Reactors should be closed down.
WEBB, R E. Lower Alloways Creek, NJ. 79/02/27. 40pp.

--7908080144 "Analysis of Accident Hazards of Storing Highly Radioactive Spent Fuel Rods in Spent Fuel Storage Pools at Nuclear Power Plants & At Other Offsite Storage Facilities."
WEBB, R.E. Lower Alloways Creek, NJ. 79/04/03. 42pp.

7908020365 Forwards errata to 790329 EIA & safety evaluation re proposed expansion of facility spent fuel pool capacity.
GODDARD, R J. Branch 2. 79/05/25. 1p.

--7908020371 Errata to 790329 EIA & safety evaluation re proposed expansion of facility spent fuel pool capacity.
GODDARD, R J. Branch 2. 79/05/25. 1p.

7908150056 Confirms agreement in principle re Contention 2(n) at spent fuel hearings in June 1979. If reracking is approved, util will limit occupational exposure per JP Leider 790109 affidavit. Requests affirmation of understanding.
STEPTOE, P. P. Isham, Lincoln & Beale. 79/07/03. 2pp.

7908080378 Forwards licensee witness R Kraatz 790709 affidavit correcting error made during cross-examination re replacement power costs for one unit. Corrects transcript page 832.
STEPTOE, P. P. Isham, Lincoln & Beale. 79/07/09. 3pp.

7908080289 Forwards IL Safe Energy Alliance 790624 ltr re installation of four racks in plant spent fuel storage pool. NRC has not received formal proposal to install racks.
GADDARD, R. J. Branch 2. 79/07/10. 1p.

--7908080294 Opposes installation of four racks at plant spent fuel storage pool prior to final NRC decision on compaction. Requests NRC deny premature rack installation by util.
GUIGG, C. Illinois Safe Energy Alliance. 79/06/24. 1p.

7908170204 Ack 790607 ltr to J Carter forwarding statement adopted by Village Council urging NRC not to consider Con Ed request for addl nuclear waste storage until safe waste storage plan developed. Statement forwarded to ASLB for consideration.
EISENHUT, D. G. Division of Operating Reactors. 79/07/24. 4pp.

H. General correspondence

7908150324 Expresses concern re nuclear waste storage in IL. Suggests developing alternate sources of energy.
BARAKAT, S. F. Affiliation Unknown. 79/07/16. 1p.

7908150195 Responds to D Ferri 790615 ltr re proposed facility spent fuel pool rack mods. Concerns re faulty fuel racks & potential cooling sys failures are addressed in encl 790329 safety evaluation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/20. 1p.

7908150084 Ack receipt of correspondence re status of spent fuel storage at six operating facilities near Lake Michigan. Responds to 790429 ltr.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/26. 2pp.

--7908150107 Discusses spent fuel storage capability at Big Rock Point. NUREG-0020 indicates authorized capacity of 120 spent fuel assemblies, while DOE indicates capacity of 365. Requests clarification.
SCHAEFER, J. Lake Michigan Federation. 79/05/20. 1p.

--7908150125 Ack receipt of info re nuclear power plants near Lake MI. Forwards rept re status of spent fuel storage at plants. Requests comments re rept.
SCHAEFER, J. Lake Michigan Federation. 79/06/21. 1p.

--7908150139 "Status of Spent Fuel Storage at Six Nuclear Plants Located on Shores of Lake MI."
SCHAEFER, J. Lake Michigan Federation. 79/05/31. 20pp.

7908170205 Ack receipt of 10CFR2.206 petition requesting full EIS re high burnup fuel project at facility. Appropriate action will be taken within reasonable time.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/08/06. 1p.

7908280457 Ack 790620 ltr to President Carter forwarding resolution re proposed expansion of spent fuel storage capacity at facility. Resolution has been incorporated in official hearing record of ASLB.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/08/06. 5pp.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908020546 Forwards errata to 790329 safety evaluation & EIA re proposed expansion of spent fuel pool capacity.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/05/29. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908070652 Notifies of intent to install second communications sys. linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used "to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/22. 3pp.

7908270508 Responds to ltrs reporting results of seismic reanalysis of reactors coolant piping at facilities using updated WESTDYN code. Reanalysis & results acceptable & matter resolved. Forwards safety evaluation.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/05. 2pp.

--7908270515 Safety evaluation by Ofc of Nuclear Reactor Regulation re seismic reanalysis of reactor coolant piping.
* Office of Nuclear Reactor Regulation. 79/07/05. 1p.

7908130310 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires NRC initial notification.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/09. 1p.

7908080719 Confirms that meeting at util corporate office has been rescheduled for 790719 at 3 PM. Location, purpose & attendees discussed in NRC 790612 ltr.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/10. 1p.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070332 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/19. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908020460 Submits schedule for addl response to NRC issues re containment purging during normal plant operation.
REED, C. Commonwealth Edison Co. 79/07/30. 2pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch. 79/07/30. 64pp.

7908160376 Forwards table showing manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co. 79/07/30. 2pp.

7908130569 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/01. 4pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations,guidance documents & repts re emergency planning.
EISENHUT,D G Division of Operating Reactors 79/08/03 53pp

7908270083 Discusses status of N-1 loop operation reviews/technical assistance contract.Suggests mgt establish priority for task.
BURDOIN,J Plant Systems Branch 79/08/03 2pp

7908300791 Requests addl info re basis for not proposing second level undervoltage protection.Proposed design mod & changes in Tech Specs must be based on guidance contained in NRC positions submitted in 770603 ltr.
SCHWENCER,A Operating Reactors Branch 1 79/08/06 2pp

7908210368 Submits addl info re steam generator water hammer evaluations.No setpoint change warranted.
REED,C Commonwealth Edison Co 79/08/08 5pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
HAMILL,W Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908200380 Forwards info requested in NRC 790629 & 0724 ltrs re capabilities & technical resources available to handle unusual events.
JANECEK,R F Commonwealth Edison Co 79/08/13 1100pp

7908210469 Forwards revised pages to ETS,App B,re measuring & reporting chemical releases.
REED,C Commonwealth Edison Co 79/08/13 2pp

--7908210482 Revised pages to ETS,App B.
* Commonwealth Edison Co 79/08/17 8pp

7908280010 Requests withholding of Westinghouse proprietary info (ref 10CFR2.790) from 790629 licensee submittal to NRC re small break LOCA analyses.
REED,C Commonwealth Edison Co 79/08/22 2pp

G. Inspection reports, IE Bulletins & correspondence

7908010415 Ack receipt of 790517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/79-06 & 50-304/79-07.
HIND,J A Region 3, Chicago, Safeguards Branch 79/06/01 1p

--7908010431 Responds to NRC 790426 ltr re violations noted in IE Insp Repts 50-295/79-06 & 50-304/79-07.Details withheld (ref 10CFR2.790).
REED,C Commonwealth Edison Co 79/05/17 1p

7908070819 Forwards IE Insp Repts 50-295/79-11 & 50-304/79-11 on 790430-0518.No noncompliance noted.
HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/19 2pp

--7908070825 IE Insp Repts 50-295/79-11 & 50-304/79-11 on 790430-0518.No noncompliance noted.Major areas inspected:operator training, engineered safety features sys,mods to safety injection logic & response to IE Bulletins 79-06,06A & 06A,Revision 1.
KOHLER,J E ; SPESSARD,R L Region 3, Chicago, Office of the Director 79/06/14 9pp

7908080680 Forwards IE Insp Repts 50-295/79-09 & 50-304/79-10 on 790601.No noncompliance noted.
DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/19 2pp

--7908080700 IE Insp Repts 50-295/79-09 & 50-304/79-10 on 790601.No noncompliance noted.Major areas inspected:emergency planning activities including annual emergency medical drill at plant & Victory Memorial Hosp.
OESTMANN,M J ; AXELSON,W L ; ESSIG,T H Region 3, Chicago, Office of the Director 79/06/14 4pp

7908070523 Responds to IE Bulletin 79-11.No Westinghouse DB-50 & DB-75 circuit breakers used in safety-related sys.
REED,C Commonwealth Edison Co 79/07/02 1p

7908060111 Responds to IE Bulletin 79-02.Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin.Bolt torque audit in progress.
REED,C Commonwealth Edison Co 79/07/05 9pp

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc 79/05/31 24pp

7908080143 Forwards addl info to 790424 response to IE Bulletin 79-07.Reanalysis of DBE for reactor coolant loop was performed by Westinghouse.Piping stresses & nozzle loads fall below allowable level.
REED,C Commonwealth Edison Co 79/07/10 7pp

7908140156 Forwards inservice insp performed on 790319-0413 in compliance w/ASME Boiler & Pressure Vessel Code,1974 Edition.W/o encl.
WANDKE,N E Commonwealth Edison Co 79/07/12 1p

7908150349 Supplements response to IE Bulletin 79-11.Westinghouse DB-50 & DB-75 circuit breakers are neither used in safety-related sys nor stored as spares at facilities.
REED,C Commonwealth Edison Co 79/07/12 2pp

7?J8030035 QA Program Insp Rept 99900034/71-04 on 710824/27.
OLLER,R E ; VETTER,W E Atomic Energy Commission (Pre 1975) 71/09/30 11pp

7908150339 Responds to IE Bulletin 79-13 re cracking in feedwater sys piping.Requests relief from performing volumetric examinations of auxiliary feedwater pipe welds.Suggests surface examination be substituted.
REED,C Commonwealth Edison Co 79/07/13 7pp

7908290284 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER,J G Region 3, Chicago, Office of the Director 79/07/26 1p

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER,J G Region 3, Chicago, Office of the Director 79/07/26 1p

7908300392 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER,J G Region 3, Chicago, Office of the Director 79/07/26 1p

7908200245 Responds to IE Bulletin 79-14,Item 1,re seismic analysis for as-built safety-related piping sys.Forwards lists of design documents which were sources of input info for seismic analysis of facilities.W/o encl.
REED,C Commonwealth Edison Co 79/08/01 2pp

7908170019 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER,J G Region 3, Chicago, Office of the Director 79/08/08 1p

7908300312 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER,J G Region 3, Chicago, Office of the Director 79/08/15 1p

S. Reportable occurrences, LERs & related correspondence

7908140771 Forwards LER 79-040/03L-0.
WANDKE,N E Commonwealth Edison Co 79/07/31 1p

--7908140778 LER 79-040/03L-0 on 790724 steam generator level 2L-538 indicated 20% higher than other channels for steam generator D.Caused by faulty power supply,Model 4111085-001 Power supply replaced w/calibr spare.
CAMPBELL,J Commonwealth Edison Co 79/07/31 1p

7908140748 Forwards LER 79-036/03T-0.
WANDKE,N E Commonwealth Edison Co 79/08/02 1p

--7908140754 LER 79-036/03T-0 on 790703 while boric acid tank was recirculating Unit 2 boron injection tank,boron concentration was found to be 11.2%-0.3% above Tech Spec max.Caused by leakage from RCS.
KRAWCZAK,A T Commonwealth Edison Co 79/08/02 1p

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

7908270264 Ack receipt of 790327 ltr transmitting safeguards contingency plan for facility.Class III fee required.
DIGGS,R M License Fee Management Branch 79/07/03 2pp

DOCKETED ITEMS

7908100486 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill; if drill scenario requires initial notification of NRC.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/09 1p.

7908220326 Forwards security guard training & qualification manual for review. Withheld (ref 10CFR2.790).
MATHEWS, E. R. Wisconsin Public Service Corp 79/08/16 1p.

H. General correspondence

7908150084 Ack receipt of correspondence re status of spent fuel storage at six operating facilities near Lake Michigan. Responds to 790429 ltr.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/26 2pp.

--7908150107 Discusses spent fuel storage capability at Big Rock Point. NUREG-0020 indicates authorized capacity of 120 spent fuel assemblies, while DOE indicates capacity of 365. Requests clarification.
SCHAEFER, J. Lake Michigan Federation 79/05/20 1p.

--7908150125 Ack receipt of info re nuclear power plants near Lake MI. Forwards rept re status of spent fuel storage at plants. Requests comments re rept.
SCHAEFER, J. Lake Michigan Federation 79/06/21 1p.

--7908150139 "Status of Spent Fuel Storage at Six Nuclear Plants Located on Shores of Lake MI."
SCHAEFER, J. Lake Michigan Federation 79/05/31 20pp.

7908010457 Forwards summary rept re corporate mgt & technical capabilities.
MATHEWS, E. R. Wisconsin Public Service Corp 79/07/30 31pp.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908070683 Notifies of intent to install second comunications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/22 3pp.

7908030484 Summary of 790703 meeting w/util in Bethesda, MD re cracking in feedwater piping sys.
OLSHAN, L. N. Operating Reactors Branch 1 79/07/05 26pp.

7908080614 Notifies that no further action is necessary re generic issue of potential boron dilution incidents.
SCHWENCER, A. Operating Reactors Branch 1 79/07/11 2pp.

7908090502 Forwards request for addl info re degraded grid voltage. Response should be forwarded within 60 days.
TRAMMELL, C. M. Operating Reactors Branch 1 79/07/17 3pp.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908070349 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/19 1p.

7908200138 Responds to 790409 request re evacuation plans in event of radiation problem. Forwards NUREG-0396 & Reg Guide 1.101. W/o encl.
KNIGHTON, G. W. Environmental Evaluation Branch 79/07/19 1p.

7908160286 Notifies that updated QA program for operations phase of plant, as described in FSAR through Revision 2, is consistent w/util commitment to comply w/Reg Guide 1.58, Aug 1973.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625) 79/07/23 2pp.

7908010372 Forwards fee for review of safeguards contingency plan.
MATHEWS, E. R. Wisconsin Public Service Corp 79/07/24 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908230143 Requests addl info re containment purge sys to suppl 790713 submittal.
LAINAS, G. Plant Systems Branch 79/07/27 3pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch 79/07/30 64pp.

7908130587 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1 79/08/01 4pp.

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees. For plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908200326 Documents reevalution of potential steam generator water hammer in subj facilities. Forwards table of operating experience & feedwater piping configurations. Water hammer not likely to occur under any conditions.
DEARIEN, J. A. EG & G, Inc 79/08/06 3pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

Q. Inspection reports, IE Bulletins & correspondence

7908070755 Forwards operator requalification training program statistics, in response to IE Bulletin 79-10.
MATHEWS, E. R. Wisconsin Public Service Corp 79/05/31 3pp.

7908020310 Responds to 790523 request for extension to respond to IE Bulletins 78-12, 78-12A & 78-12B, "Atypical Weld Matl in Reactor Pressure Vessels." Request denied.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/06 3pp.

7908090499 Responds to IE Bulletin 79-11. Westinghouse DB-50 & DB-75 circuit breakers are not used in safety-related sys.
MATHEWS, E. R. Washington Public Power Supply System 79/06/26 1p.

7908280188 Forwards IE Insp Rept 50-305/79-11 on 790522-25 & 0605-08. No noncompliance noted.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/07/02 2pp.

--7908280193 IE Insp Rept 50-305/79-11 on 790522-25 & 0605-08. No noncompliance noted. Major areas inspected: plant operations, nonroutine event followup, maint & refueling activities.
CHOULES, N. C.; WARNICK, R. F. Region 3, Chicago, Office of the Director 79/06/29 8pp.

7908100120 Forwards revised pages of IE Insp Rept 50-305/79-09 on 790606-08 & cover ltr.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/03 2pp.

--7908100127 Corrected first page of IE Insp Rept 50-305/79-09 on 790606-08. No noncompliance noted. Major areas inspected: QA/QC program, implementing procedures, work activities & nondestructive examination data.
WARD, K. D.; DANIELSON, D. H. Region 3, Chicago, Office of the Director 79/06/19 1p.

--7908100134 Forwards IE Insp Rept 50-305/79-09 on 790606-08 No noncompliance noted.
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/25 2pp

--7908100356 IE Insp Rept 50-305/79-09 on 790606-08 No noncompliance noted Major areas inspected QA/QC program implementing procedures,work activities & nondestructive examination data of inservice insp
WARD,K.D.; DANIELSON,D.H. Region 3, Chicago, Office of the Director 79/06/19 7p

7908020263 Ack receipt of 790608 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/79-04.
HIND,J.A. Region 3, Chicago, Safeguards Branch 79/07/05 1p

--7908020267 Responds to NRC 790518 ltr re violations noted in IE Insp Rept 50-305/79-04 Corrective actions withheld (ref 10CFR2.790)
MATHEWS,E.R. Wisconsin Public Service Corp 79/06/11 2pp

7908080695 Forwards responses to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion anchor bolts Testing program,engineering analysis program & lab experimentation initiated to address bulletin
MATTHEWS,E.R. Wisconsin Public Service Corp 79/07/09 7pp

7908290504 Forwards IE Insp Rept 50-305/79-02 on 790222-23 & 0305-09 & notice of violation
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/10 3pp

--7908290509 Notice of violation from insp on 790222-23,0305-09 & 0524
* Region 3, Chicago, Office of the Director 79/07/10 1p

--7908290516 IE Insp Rept 50-305/79-02 on 790222-23,0305-09 & 0524 Noncompliance noted both diesel generators were nonoperable.
CHOULES,N.C.; SMITH,J.D.; WARNICK,R.F. Region 3, Chicago, Office of the Director 79/07/02 6pp

7908130427 Submits clarifications to 790620 response to IE Bulletin 79-06A,Revision 1,re addl emergency procedure for pressurizer steam leaks
MATHEWS,E.R. Wisconsin Public Service Corp 79/07/13 2pp

7908020363 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/20 1p

7908150434 Discusses generic rept, "Atypical Weld Matl in Reactor Pressure Vessel Welds." C-E found no evidence of atypical weld matl use in reactor pressure vessels Rept does include availability of archive weld matl
MATHEWS,E.R. Wisconsin Public Service Corp 79/07/20 1p

7908210146 Responds to IE Bulletin 79-13 re cracking in feedwater sys piping Forwards 790713 summary rept
MATHEWS,E.R. Wisconsin Public Service Corp 79/07/26 3pp

7908290313 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908290400 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908300434 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908150401 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/08/07 1p

7908170028 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/08/08 1p

7908230290 Forwards response to Item 1 of IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys Insp program for verification initiated Response to Items 2 & 3 to be completed by first week of Sept 1979
MATHEWS,E.R. Wisconsin Public Service Corp 79/08/09 2epp

7908300310 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/08/15 1p

R Periodic operating reports & related correspondence

7908140382 Forwards monthly operating rept for Jul 1979.
MATHEWS,E.R. Wisconsin Public Service Corp 79/08/08 1p

--7908140387 Monthly operating rept for July 1979
WALLACE,J.J. Wisconsin Public Service Corp 79/08/02 4pp

7908310526 Forwards "Semiannual Effluent Rept for Jan-June 1979."
MATHEWS,E.R. Wisconsin Public Service Corp 79/08/24 1p

--7908310530 "Semiannual Effluent Rept for Jan-June 1979."
* Wisconsin Public Service Corp 79/06/30 29pp

S Reportable occurrences, LERs & related correspondence

7908010569 Forwards LER 79-020/04T-0
MATHEWS,E.R. Wisconsin Public Service Corp 79/07/24 1p

--7908010572 LER 79-020/04T-0 on 790709 daily sampling of turbine bldg sump & water pretreatment sys lagoon was not performed on 790707 & 08 Caused by failure of weekend shift to collect samples Personnel reinstructed
RUITER,G.H. Wisconsin Public Service Corp 79/07/24 1p

7908080401 Forwards LER 79-021/03L-0
MATHEWS,E.R. Wisconsin Public Service Corp 79/08/03 1p

--7908080403 LER 79-021/03L-0 on 790705 leak rate of five isolation valves in containment exceeded capability of test equipment All necessary replacements,cleaning & adjustments unertaken for valves involved
RUITER,G.H. Wisconsin Public Service Corp 79/08/03 1p

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7908080538 Submits schedule for response to IE Bulletins 78-12 12A & 12B Info will be available by 790731
WACHTER,L.J. Northern States Power Co. 79/06/29 1p

F Security, medical, emergency & fire protection plans

7908130200 Notifies that review of safeguards contingency plan involves consideration of safeguards issue,requiring payment of Class III fee Plans should be submitted by 790823
DIGGS,R.M. License Fee Management Branch 79/07/03 1p

7908010584 Forwards appropriate licensing fee for safeguards contingency plan,in response to 790703 request.
MAYER,L.O. Northern States Power Co. 79/07/20 4pp

7908230311 Forwards security force training & qualification plan Plan withheld (ref 10CFR2.790).
MAYER,L.O. Northern States Power Co. 79/08/17 1p

7908280555 Forwards appropriate licensing fee for NRC review & approval of util 790817 security force training & qualification plans.
MAYER,L.O. Northern States Power Co. 79/08/23 3pp

G Adjudicatory correspondence

7908170289 Urges NRC to reject 790618 request of MN Pollution Control Agency to reopen record of spent fuel pool mod proceeding Matter can be resolved by generic rulemaking rather than piecemeal adjudication
REYNOLDS,W.B. Shaw, Pittman, Potts, & Trowbridge 79/06/29 2pp

H General correspondence

7908210319 Forwards "Mgt & Technical Resources,Jul 1979," per NRC 790629 info request re util ability to handle emergency situations financially
MAYER,L.O. Northern States Power Co. 79/08/10 1p

DOCKETED ITEMS

--7908210321 "Mgt & Technical Resources, Jul 1979."
* Northern States Power Co. 79/08/31 225pp

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04 52pp.

7908150335 Intends to ship radioactive matl from facilities using Package PB-1.
MAYER, L. D. Northern States Power Co. 79/06/08 1p.

7908130402 Notifies of intent to ship radioactive matl using certified shipping package Model 7-100.
MAYER, L. D. Northern States Power Co. 79/06/19 1p.

7908070674 Notifies of intent to install second communication sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/22. 3pp.

7908230647 Forwards "Steam Generator Water Hammer Technical Evaluation." Recommends installation of top discharge feedrings in all steam generators & test program to qualify effect of auxiliary feedwater on water hammer.
DEARIEN, J. A. EG & G, Inc. 79/06/27 2pp.

--7908230650 "Steam Generator Water Hammer Technical Evaluation."
* EG & G, Inc. 79/06/30 17pp.

7908140309 Notifies of intent to ship radioactive matl in Model GE-600.
MAYER, L. D. Northern States Power Co. 79/07/05 1p.

7908130306 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill. If drill scenario requires initial notification of NRC.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/09. 1p.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiologi, , Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18 1p.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18 1p.

7908070343 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/19. 1p.

7908270303 Forwards request for addl info re degraded grid voltage to be sent to licensee in order to complete review of 780504 submittal. Response required within 45 days.
LAINAS, G. Plant Systems Branch. 79/07/23 3pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24 1p.

7908290640 Forwards request for addl info to util 790504 submittal re potential equipment failure due to degraded grid voltage.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/30 3pp.

7908080455 Confirms delay until 790813 to respond to 790629 request & WP Haass ltr re info on mgt & technical resources available to licensees for response to nuclear plant emergencies.
MAYER, L. D. Northern States Power Co. 79/08/02 1p.

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees, for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch. 79/08/02 7pp.

7908290260 Forwards Amends 37 & 31 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/02 2pp.

--7908290269 Amends 37 & 31 to Licenses DPR-42 & DPR-60 changing Tech Specs in Apps A & B.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/02 2pp.

--7908290294 Safety evaluation supporting Amends 37 & 31 to Licenses DPR-42 & DPR-60, respectively.
* Office of Nuclear Reactor Regulation. 79/08/02 6pp.

--7908290303 Notice of issuance & availability of Amends 37 & 31 to Licenses DPR-42 & DPR-60, respectively.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/02 2pp.

7908160118 Forwards Amends 38 & 32 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/03 2pp.

--7908160129 Amends 38 & 32 to Licenses DPR-42 & DPR-60, respectively, incorporating new definitions, limiting conditions for operation & adding surveillance requirement for reactor cooling sys overpressure protection sys.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/03 10pp.

--7908160138 Safety evaluation supporting Amends 38 & 32 to Licenses DPR-42 & DPR-60, respectively.
* Office of Nuclear Reactor Regulation. 79/08/03 14pp.

--7908160143 Notice of issuance & availability of Amends 38 & 32 to Licenses DPR-42 & DPR-60, respectively.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/03 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908200326 Documents reevalution of potential steam generator water hammer in subj facilities. Forwards table of operating experience & feedwater piping configurations. Water hammer not likely to occur under any conditions.
DEARIEN, J. A. EG & G, Inc. 79/08/06 3pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09 56pp.

Q. Inspection reports, IE Bulletins & correspondence

7908070048 Responds to IE Bulletin 79-11. Reactor trip breakers are used in safety-related sys. Breakers do not have overtrip feature.
WACHTER, L. J. Northern States Power Co. 79/06/04 1p.

7908160117 Forwards IE Insp Repts 50-282/79-13 & 50-306/79-10 on 790501-31 & notice of violation.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/27 2pp.

--7908160120 Notice of violation from insp on 790501-31.
* Region 3, Chicago, Office of the Director. 79/06/26 1p.

--7908160130 IE Insp Repts 50-282/79-13 & 50-306/79-10 on 790501-31. Noncompliance noted: failure to perform quarterly exercise test of two valves.
FEIERABEND, C. D., DANIELS, F. T., WARNICK, R. F. Region 3, Chicago, Office of the Director. 79/06/26. 13pp.

7908150080 Ack receipt of 790531 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-282/79-01 & 50-306/79-01.
HEISHMAN, R. F. Region 3, Chicag Reactor Operations Nuclear Support Branch. 79/06/29 1p.

--7908150090 Responds to NRC 790215 ltr re violations noted in IE Insp Repts 50-282/79-01 & 50-306/79-01. Corrective actions: general review of methods undertaken to assure prompt identification of deficiencies & subsequent corrections.
WACHTER, L. J. Northern States Power Co. 79/05/31. 4pp.

7908140319 Responds to IE Bulletin 79-02 Analytical & experimental generic program used for baseplate analysis. Reviewed all Seismic Category I pipe supports & found expansion anchor bolts are shell type.
WACHTER, L. J. Northern States Power Co. 79/07/06 3pp.

7908090595 Submits further response to IE Bulletin 79-06A Revision 1, Item 10 All safety-related maint procedures were reviewed. Procedures will be improved by independent verification.
WACHTER, L. J. Northern States Power Co. 79/07/13 1p.

7908130407 Responds to IE Bulletin 79-13 re feedwater cracks No cracks in Unit 1 Emergency procedures are adequate to recognize & respond to feedwater line breaks.
WACHTER, L. J. Northern States Power Co. 79/07/13 2pp.

7908020342 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20 1p.

7908290291 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26 1p.

7908290370 Forwards IE Bulletin 79-18, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26 1p.

7908300446 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26 1p.

7908160363 Responds to IE Bulletin 79-14, Item 1 Discusses insp elements & approach, design documents & insp program timetable.
WACHTER, L. J. Northern States Power Co. 79/08/01 4pp.

7908150371 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07 1p.

7908170024 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08 1p.

7908300290 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15 1p.

R. Periodic operating reports & related correspondence

7908060267 Submits Environ Event Rept 79-06 re cooling tower operations for July 1979 Average daily blowdown flow in excess of 150 cubic ft per second was required for only nine days because Unit 1 was removed from svc.
WARD, E. C. Northern States Power Co. 79/08/01 1p.

7908140759 Forwards "Effluent & Waste Disposal Semiannual Rept" for Jan-June 1979.
MAYER, L. O. Northern States Power Co. 79/08/10 1p.

--7908140765 "Effluent & Waste Disposal Semiannual Rept" for Jan-June 1979.
* Northern States Power Co. 79/06/30 9pp.

7908160437 Forwards monthly operating rept for Jul 1979.
MAYER, L. O. Northern States Power Co. 79/08/13 1p.

--7908160440 Monthly operating rept for Jul 1979.
HUNSTAD, A. A. Northern States Power Co. 79/08/01 8pp.

S. Reportable occurrences, LERs & related correspondence

7908280540 Forwards LER 79-023/03L-0.
MAYER, L. O. Northern States Power Co. 79/08/24 1p.

--7908280542 LER 79-023/03L-0 on 790726 design deficiency was found in motor driven auxiliary feedwater pump low lube oil pressure circuitry in each unit Redundant turbine driven pumps are unaffected Design change has been initiated.
HUNSTAD, A. A. Northern States Power Co. 79/08/24 1p.

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F. Security, medical, emergency & fire protection plans

7908160339 Responds to 790526 ltr re evacuation plans for area. ME Dept of State Police is responsible for preparation & implementation of emergency & evacuation plans in ME. Plans available in municipal offices of specific ME towns.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/11 1p.

--7908160343 Appeals to NRC w/respect to lack of evacuation plans. Requests that plant remain shutdown until evacuation plan is rewritten.
MAUTNER, P. P. Affiliation Unknown. 79/05/26 1p.

7908030076 Forwards NRC evaluation of licensee response to fire protection safety evaluation, Item 3.2.1, re adequacy of safe shutdown capability Evaluation is incomplete.
LAINAS, G. Plant Systems Branch. 79/06/22 2pp.

--7908030080 Safety evaluation of fire protection open item re adequacy of safe shutdown capability Identifies addl info needed before capability in fire emergency can be properly evaluated.
* Plant Systems Branch. 79/06/22 7pp.

7908130322 Forwards request for addl info re amend to 790323 modified security plan Encl withheld (ref 10CFR2.790).
REID, R. W. Operating Reactors Branch 4. 79/06/29 5pp.

7908060155 Requests prompt forwarding of Class III fee for 790322,23 & 0430 safeguards contingency plans.
DIGGS, R. M. License Fee Management Branch. 79/07/03 2pp.

7908150239 Forwards evaluation of fire protection safety evaluation rept Addl info required re adequacy of safe shutdown capability during fire emergency.
REID, R. W. Operating Reactors Branch 4. 79/07/19 10pp.

7908010326 Submits Class III payment to cover costs associated w/licensing review of security contingency plan, as requested in NRC 790703 ltr Believes revised fee schedule illegal. Submits fee under protest.
GROCE, R. H. Yankee Atomic Electric Co. 79/07/23 1p.

7908170364 Forwards proprietary version of response to NRC questions re security contingency plan Contingency plans developed for events which signal beginning or aggravation of security contingency Plans withheld (ref 10CFR2.790).
GROCE, R. H. Maine Yankee Atomic Power Co. 79/08/13 2pp.

7908230325 Forwards security force training & qualification plan. Plan withheld (ref 10CFR2.790).
GROCE, R. H. Maine Yankee Atomic Power Co. 79/08/17 2pp.

G. Adjudicatory correspondence

7908090409 Responds to 790502 petition requesting that shutdown be continued pending evaluation of asymmetric LOCA loads on reactor vessel & reactor support sys. Denies petition.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/26 1p.

--7908090417 Director decision under 10CFR2.06.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/26 5pp.

--7908090425 Forwards draft acknowledgement ltr to Murray, transmittal ltr to licensee & notice of receipt of request for publication in FR, to be used in response to petition under 10CFR2.206. Requests outgoing ltr & notice.
MURRAY, J. P. Office of the Executive Legal Director. 79/05/14. 4pp.

--7908090429 Forwards request for action & petition. Requests acknowledgement of receipt of petition.
MURRAY, P. L. Murray, Plumb & Murray. 79/05/02 1p.

--7908090434 Request for issuance of order to show cause.
MURRAY, P. L. Murray, Plumb & Murray. 79/05/07 5pp.

7908300612 Joint staff & licensee motion to terminate civil penalty proceeding Parties have proposed settlement. Forwards settlement for approval per 10CFR2.203.
LIEBERMAN, J. Rulemaking & Enforcement Division. BAKER, D. A., KEANE, S. E. Wisconsin Public Service Corp. 79/07/05 1p.

--7908300616 Agreement between NRC & licensee re civil penalty proceeding. NRC approves response to IE Circular 78-03. Licensee agrees to pay civil penalty & withdraw requested hearing. Certificate of Svc encl.
LIEBERMAN, J. Rulemaking & Enforcement Division. BAKER, D. A., KEANE, S. E. Wisconsin Public Service Corp. 79/07/05 4pp.

7908300103 Orders extension until 790724 for NRC review of denial of enforcement action per 10CFR2.772(g).
CHILK, S. J. Office of the Secretary of the Commission 79/07/09 1p.

7908300055 Orders extension until 790810 for NRC review of 790626 denial of enforcement action per 10CFR2.706.
CHILK, S. J. Office of the Secretary of the Commission 79/07/13 1p.

H. General correspondence

7908100055 Responds to 790313 ltr opposing shutdown of five plants due to questions re ability of piping sys to withstand earthquakes.Earthquake maps of eastern OH & western PA encl.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/09 3pp.

--7908100066 Opposes plant shutdown due to earthquake concerns.
CAMPBELL, W. R. Affiliation Unknown 79/03/17 2pp.

7908200012 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy.NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200046 Commends NRC shutdown of five nuclear plants.
BORTIN, B. Affiliation Unknown 79/03/17 1p.

--7908200063 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy.NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200065 Commends NRC move to shut down five plants.
MARSCHARK, E. D. Affiliation Unknown 79/03/16 2pp.

--7908200070 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy.NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200073 Applauds NRC shutdown of five plants due to seismic inadequacy.
FUSCO, G. Affiliation Unknown 79/03/27 1p.

--7908200078 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy.NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200080 Thanks NRC for closing down unsafe plants.
THOMSON, J. Affiliation Unknown 79/05/17 1p.

--7908200087 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy.NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 1p.

--7908200091 Applauds NRC shutdown of five nuclear power plants.
COLEMAN, E. Affiliation Unknown 79/03/29 1p.

7908010273 Responds to 790604 ltr.Every effort is being made to ensure continued protection of health & safety of public at all nuclear power plants.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/18 1p.

--7908010278 Requests shutdown of all nuclear plants.Atomic power is unsafe.
STANLEY, L. A. Affiliation Unknown 79/06/04 1p.

7908030589 Responds to 790611 ltr re seismic instruments in use during 790417 earthquake.Recorders were set to trigger for vertical acceleration of 0.01 g or more & did not trigger during earthquake.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/05 1p.

7908150452 Discusses 790524 termination of order to show cause, allowing plant to resume operation.Continued operation would not endager public health & safety.
GAMMILL, W. P. Assistant Director for Operating Reactor Projects 79/07/20 2pp.

7908020418 Notifies of delay until 790820 for submitting info re mgt & technical resource available to handle unusual events.
RANDAZZA, J. B. Maine Yankee Atomic Power Co. 79/07/27 1p.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation.W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908130359 Notifies all operating plants using C-E-designed reactors of generic review re TMI.Requests attendance at 790612 meeting in Bethesda, MD re info needed by NRC to complete review.
STOLZ, J. F. Light Water Reactors Branch 1 79/06/05 16pp.

7908080223 Notification of 790814 meeting w/util to discuss security program.
NELSON, C. C. Operating Reactors Branch 4 79/06/19 2pp.

7908020192 Discusses 781122 ltr re modified spent fuel pin storage concept to increase storage capability.Two phase implementation is not acceptable.NRC review required.
GRIMES, B. K. Assistant Director for Systems Engineering 79/06/22 3pp.

7908070453 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc.Second line will be used to relay radiologic & environ data during emergencies.Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp.

7908140472 Responds to 790502 ltr.NRC terminated 790313 order to show cause & allowed facility to resume power operation on 790524 after determining public health & safety did not mandate shutdown.
GAMMILL, W. P. Division of Operating Reactors 79/07/13 2pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups.Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/18 58pp.

7908030502 Requests addl info demonstrating that seal ring cannot become destructive missile during lon-term operation or statement that seal ring will be removed by next refueling outage.
REID, R. W. Operating Reactors Branch 4 79/07/18 2pp.

7908070242 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors.Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p.

7908220489 Requests addl info for degraded grid voltage.
LAINAS, G. Plant Systems Branch 79/07/20 3pp.

7908150405 Ack receipt of 790625 ltr re escape of sponge rubber balls from cooling sys.Licensee is examining design change to increase recovery of balls.Appearance of balls is not evidence of inability to control release of contaminants.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/23 1p.

--7908150409 Expresses concern re balls emitted from closed sys for 1.5 yrs.Forwards sample.
ROTH, N. Affiliation Unknown 79/06/23 1p.

7908200099 Requests proposed amend to license to delete Tech Specs re secondary water chemistry monitoring program & to incorporate requirements of encl model license condition.Requests submittal within 60 days.
REID, R. W. Operating Reactors Branch 4 79/07/23 4pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events.Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908290180 Forwards request for addl info on steam generator water hammer to be sent to Westinghouse & C-E licensees, for plants not equipped w/top discharge devices on steam generator feedwater sys & for which no mods are planned.
LAINAS, G. Plant Systems Branch 79/08/02 7pp.

7908100458 Forwards proprietary & non-proprietary versions of Amend 1 to CEN-114, "Review of Small Break Transients in C-E NSSS." LIEBLER,G.E. C-E Operating Plants Owners Group 79/08/03 6pp

--7908100465 Amend 1-NP to CEN-114-NP, "Review of Small Break Transient in C-E NSSS." CEN-144-P withheld (ref 10CFR2.790)
* Combustion Engineering, Inc. CEN-114-P 79/07/31 1110pp

7908220217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT,D.G. Division of Operating Reactors 79/08/03 53pp

7908130457 Requests proposed change 69 to App A of License DPR-36 re composition & organization of onsite fire brigade Revised Tech Specs encl
VANDENBURGH,D.E. Maine Yankee Atomic Power Co 79/08/07 2pp

--7908130460 Proposed Tech Spec Change 69 to App A of License DPR-36 re composition & organization of onsite fire brigade
* Maine Yankee Atomic Power Co 79/08/07 1p

7908300734 Notification of 790817 meeting w/util in Bethesda,MD to discuss App I Tech Specs.
NELSON,C.C. Light Water Reactors Branch 4 79/08/07 3pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL,W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908170428 Forwards CEN-114-NP Amend 1, "Review of Small Break Transients in C-E Nuclear Steam Supply Sys." Proprietary version CEN-114-P withheld (ref 10CFR2.790).
SCHERER,A.E. C-E Power Systems 79/08/10 1p

7908220437 Advises that Yankee Atomic Electric Co has entered into svc contract w/licensee for technical support as required for unusual events Forwards details of onsite & offsite mgt & technical resources & technical support.
THURLOW,E.W. Maine Yankee Atomic Power Co 79/08/10 53pp

7908210356 Forwards "Conduit Seal Fire Barrier Testing, BISCO Test 748-15," by Brand Industrial Svcs, Inc Discusses test results
MOODY,D.E. Maine Yankee Atomic Power Co 79/08/16 2pp

--7908210357 "Conduit Seal Fire Barrier Testing, BISCO Test 748-15."
ANDERSON,J.S. Bisco, Brand Industrial Svcs, Inc. 79/05/29 50pp

G. Inspection reports, IE Bulletins & correspondence

7908020508 Responds to IE Bulletins 79-01 & 79-01A re environ qualification of Class IE equipment Provides written evidence of qualification of electrical equipment required to function under accident conditions.
MOODY,D.E. Maine Yankee Atomic Power Co 79/06/15 2pp

7908020103 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/79-03.
BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/28 1p

--7908020106 Responds to NRC 790502 ltr re violations noted in IE Insp Rept 50-309/79-03 Corrective actions two plant procedures revised to ensure spray bldg ventilation sys is aligned through HEPA filters.
MOODY,D.E. Maine Yankee Atomic Power Co 79/05/23 2pp

--7908020110 Forwards IE Insp Rept 50-309/79-03 on 790315,20-23 & 27 & notice of violation.
BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/02 2pp

--7908020114 Notice of violation from insp on 790315,20-23 & 27
* Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/01 1p

--7908020121 IE Insp Rept 50-309/79-03 on 790315,20-23 & 27 Noncompliance noted exceeded 1-h gaseous release rate limit.
KEIMIG,R.R., LAZARUS,W.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/01 13pp

7908080313 Responds to IE Bulletin 79-11 Westinghouse Type DB circuit breakers not used in safety-related Class IE circuits.
GROCE,R.H. Maine Yankee Atomic Power Co 79/07/03 1p

7908080710 Responds to IE Bulletin 79-02 Program initiated to develop generic base plate flexibility computer analysis & insp of sample population of drilled-in anchor bolts.
GROCE,R.H. Maine Yankee Atomic Power Co 79/07/05 4pp

7908220637 Forwards revised page 3 of response to IE Bulletin 79-02, Revision 1.
GROCE,R.H. Maine Yankee Atomic Power Co 79/07/12 2pp

7908170362 Responds to IE Bulletin 79-13 Item 5 re adequacy of procedures re feedwater line breaks Insp will be conducted during 790901 planned shutdown Describes methods for detecting feedwater leaks in containment.
GROCE,R.H. Maine Yankee Atomic Power Co 79/07/13 1p

7908010430 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/17 1p

7908060381 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908030254 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/19 1p

7908270517 Responds to IE Bulletin 79-14 Util conducted review of seismically designed safety-related piping in response to NRC 790313 show cause order No further insp of piping sys installation will be conducted.
GROCE,R.H. Maine Yankee Atomic Power Co 79/07/24 1p

7908100237 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908100341 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908130034 Requests addl info to suppl previous response to IE Bulletin 79-06B before NRC can complete safety evaluation.
REID,R.W. Operating Reactors Branch 4 79/07/26 3pp

7908090306 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/30 1p

7908280122 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/07 1p

7908230339 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/08 1p

7908270551 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908280288 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/13 1p

7908310284 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

7908300142 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/15 1p

R. Periodic operating reports & related correspondence

7908140770 Forwards monthly operating rept for Jul 1979.
MOODY, D. E. Maine Yankee Atomic Power Co. 79/08/10 1p.

--7908140774 Monthly operating rept for Jul 1979.
SJOGREN, R. M. Maine Yankee Atomic Power Co. 79/08/10 5pp.

S. Reportable occurrences, LERs & related correspondence

7908010561 Forwards LER 79-015/03L-0.
WOOD, E. C. Maine Yankee Atomic Power Co. 79/07/24 1p.

--7908010567 LER 79-015/03L-0 on 790712 during operation, RPS channel A hi power matrix trip lights illuminated but pre-trip & trip lights did not. Caused by failed 15 volt dc power supply. Unit replaced in kind & returned for analysis.
ANDERSON, P. L. Maine Yankee Atomic Power Co. 79/07/24 1p.

7908030248 Forwards LER 79-016/03L-0.
WOOD, E. C. Maine Yankee Atomic Power Co. 79/07/27 1p.

--7908030266 LER 79-016/03L-0 on 790722 during routine steady state operations; spurious trip occurred on reactor protection sys Channel D TM/LP circuit. Cause not determined on site. Returned to mfg.
ANDERSON, P. L. Maine Yankee Atomic Power Co. 79/07/27 1p.

U. Congressional/Executive Correspondence

7908020232 Ack receipt of 790318 ltr to President Carter re NRC order to shut down five nuclear plants for seismic reasons. Review of piping sys is in progress. Forwards earthquake map for VA.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/06 3pp.

--7908020241 Forwards CJ Hemmer 790318 ltr for response. Ltr protests closing of five nuclear power plants for seismic reasons.
ZINN, P. K. President of US & Executive Offices 79/03/21 2pp.

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908030614 Notifies of completion of review of 790215 ECCS analysis. Plant is in conformance w/10CFR50.46 per NRC 780427 order. Forwards safety evalution.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625) 79/06/06 2pp.

--7908030622 Safety evaluation rept for Zr-water correction to ECCS analysis for OL DPR-70.
* Office of Nuclear Reactor Regulation 79/06/06 3pp.

7908010261 Issuance of OL delayed due to investigation of TMI incident. Will advise if new safety requirements are applicable to facility.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/13 2pp.

7908070467 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp.

7908020041 Summary of 790613 meeting w/util in Bethesda, MD re current NRC CP & OL application review policies & criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 7Opp.

7908030331 Summary of 790627 meeting w/util in Bethesda, MD re lessons learned from TMI-2 & impact on issuance of OL for facility. Attendance list encl.
DROMERICK, A. Light Water Reactors Branch 3 79/07/10 3pp.

7908[illegible]42 Responds to 790619 ltr to JM Hendrie supporting OL. Steps being taken to resolve TMI-related matters prior to issuance of OL.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/11 2pp.

--7908080149 Advises that facility is ready for operation & requests issuance of OL as soon as possible. Supporting documentation encl.
SMITH, R. I. Public Service Electric & Gas Co. of New Jersey 79/06/19 5pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/18 58pp.

7908220443 FOIA request for access to Public Svc Electric & Gas documents responding to NRC questions re population data & spent fuel pool.
COLEMAN, A. C. Affiliation Unknown 79/07/23 1p.

7908220458 FOIA request for access to documents of Public Svc Electric & Gas re estimated annual cost for operating facility.
COLEMAN, A. C. Affiliation Unknown 79/07/23 1p.

7908300062 Requests addl info re strap damage on fuel spacer grids, for review of FSAR by 790810.
PARR, O. D. Operating Reactors Branch 3 79/07/30 3pp.

7908230073 Summary of 790725 meeting w/util & Westinghouse in Bethesda, MD re lessons learned from TMI & issuance of OL.
DROMERICK, A. Light Water Reactors Branch 3 79/08/01 4pp.

7908130546 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
PARR, O. D. Light Water Reactors Branch 3 79/08/02 4pp.

7908220446 Responds to FOIA request re Public Svc Electric & Gas responses to NRC questions re population data & spent fuel pool. Info is available in LPDR in Amends 14, 18, 20, 23, 27, 36 & 38 to application.
FELTON, J. M. Division of Rules and Records 79/08/17 1p.

7908220464 Responds to FOIA request for access to Public Svc Electric & Gas documents re estimated annual cost for operating facility. Info is available in LPDR as 731112 Amend 25 to application.
FELTON, J. M. Division of Rules and Records 79/08/20 1p.

7908300512 Responds to request for addl info re environ qualification of electrical cables. All safety-related cables inside containment have been qualified to LOCA environ.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 79/08/28 4pp.

7908300520 Responds to request for addl info re fuel assembly grid strap damage.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 79/08/28 3pp.

7908300661 Responds to 790731 ltr requesting submittal of proposed secondary water chemistry program to be ref in condition to OL & to replace any proposed Tech Specs. Upcoming six-month investigation will provide basis for procedures.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 79/08/28 2pp.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

7908100442 Responds to request for addl info re Item 2 of Suppl 3 to SER. Forwards "Qualification Tests of Electrical Cables in Simulated LOCA Environ" by Franklin Research Ctr.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 79/08/07 1p.

--7908100447 "Qualification Tests of Electrical Cables in Simulated LOCA Environ," prepared by Franklin Research Ctr for American Insulated Wire Corp.
* Franklin Institute. F-C5115 79/04/30 40pp.

F. Security, medical, emergency & fire protection plans

7908200194 Forwards preliminary security training & qualification plan. Plan withheld (ref 10CFR2.790).
LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey 79/08/16 1p.

G. Adjudicatory correspondence

7908300050 Opposes OL for facility. Nuclear power is not safe. Region will not suffer power shortage w/o facility. Safety should be first concern to those entrusted w/health & safety of public.
ZITZER, P. Committee for Application of Nuremberg Principles to US Nuclear Power Production 79/06/25 3pp.

7908070406 Request that NRC issue order to show cause & request to stay licensing Requests intervenor status Submits list of contentions & partial list of resouce documents Certificate of Svc encl
COLEMAN, A. C. ; COLEMAN, E. G. Affiliation Unknown 79/08/02 11pp

7908280659 Gives applicant understanding of AC & EG Coleman petition to NRC re issuance of order to show cause Requests correction if necessary
WETTERHAHN, M. J. Conner, Moore & Corber 79/08/24 1p

H General correspondence

7908020384 Ack receipt of 790613 ltr to JM Hendrie urging prompt issuance of OL Delay is due to TMI investigation which may affect design & safety requirements of nuclear power plants currently under const
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/02 2pp

--7908020386 Urges expediency in issuance of OL on behalf of NJ Doe of Board of Public Utils Stresses impact on consumers & alternative power generation
BARBOUR, G. H. New Jersey, State of 79/06/13 2pp

7907200298 Forwards corporate capabilities re mgt & technical resource. Encl available in Central Files
LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey 79/08/09 1p

P Operating license stage documents & correspondence

7908070262 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors Info requests will not be made while plant is in shutdown mode
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p

Q Inspection reports, IE Bulletins & correspondence

7908010149 Responds to IE Bulletin 79-06A, Revision 1 Changes in Tech Spec Tables 3.3-3, 3.3-4, 3.3-5 & 4.3-2 Forwarded 790516 reflect delet. of coincident pressurizer low pressure signals & chan incorporated since TMI
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 79/06/01 2pp

7908020139 Forwards IE Insp Repts 50-272/79-12 & 50-311/79-24 on 790325-0421 No noncompliance noted
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/01 2pp

--7908020154 IE Insp Repts 50-272/79-12 & 50-311/79-24 on 790325-0421 No noncompliance noted Major areas inspected logs & records, preparations for refueling outage, followup on licensee events & licensed operator training
KEIMIG, R. R. ; NORHELM, L. J. ; NICHOLAS, H. H. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/30 15pp

7908280221 Forwards IE Insp Rept 50-311/79-23 on 790329-30, 0404-06 & 09-12 No noncompliance noted
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/19 2pp

--7908280225 IE Insp Rept 50-311/79-03 on 790329-30, 0404-06 & 09-12 No noncompliance noted Major areas inspected operating instructions, alarm procedures, surveillance & maint procedures
ZIMMERMAN, R. P. ; BLUMBERG, N. J. Region 1, Philadelphia, Office of the Director ; KISTER, J. B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/14 19pp

7908200122 Forwards safety evaluation re 790503 response to IE Bulletin 79-07 "Seismic Stress Analysis of Safety-Related Piping"
FARR, O. D. Light Water Reactors Branch 3 79/07/23 2pp

--7908280128 Safety evaluation of licensee 790503 response to IE Bulletin 79-07, "Seismic Stress Analysis of Safety Equipment." Requires reanalysis of all piping sys Imposes 90-day licensing condition
Light Water Reactors Branch 3 79/06/23 3pp

7908200259 Forwards IE Insp Rept 50-311/79-30 on 790501-04 No noncompliance noted
VRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/29 2pp

--7908200268 IE Insp Rept 50-311/79-30 on 790501-04 No noncompliance noted Major areas inspected applicant action on previous insp findings, annunciator response procedure format & content & outstanding procedure items
CONTE, R. J. ; ZIMMERMAN, R. P. ; KISTER, H. B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/28 11pp

7908080277 Responds to IE Bulletin 79-11 No Westinghouse DB-50 or DB-75 circuit breakers used in safety-related sys End caps inspected & found satisfactory
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 79/07/03 3pp

7908070785 Responds to IE Bulletins 79-12, 12A & 12B re atypical weld matl C-E generic rept, "Atypical Weld Matl in Reactor Pressure Vessels," which was forwarded to NRC on 790608, addresses Items 1-4
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 79/07/06 2pp

7908170471 Responds to IE Bulletin 79-02 No deficiencies in pipe support base plates Other supports show deficiences re embedment Corrective action in progress
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 79/07/06 5pp

7908220631 Submits supplemental response to IE Bulletin 79-06A, Revision 1 Briefing presented by NRC to licensed station personnel on 790420 constitutes adequate review of accident sequence Engineering safety features procedures tightened
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 79/07/13 19pp

7908010524 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/17 1p

7908060494 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908080236 Notification of 790725 meeting w/util in Bethesda, MD to discuss ACRS subcommittee 790727 meeting re TMI incident
DROMERICK, A. Light Water Reactors Branch 3 79/07/18 2pp

7908030277 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/19 1p

7908100273 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908090331 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/30 1p

7908160230 Notification of 790817 meeting w/util in Bethesda, MD to discuss matters re IE Bulletin 79-02
DROMERICK, A. Operating Reactors Branch 3 79/08/03 2pp

7908160442 Ack receipt of NRC 790723 ltr setting forth seismic stress analysis requirements for safety-related equipment as identified in IE Bulletin 79-07 Re-evaluation of all seismic Category I large & small bore piping will be forwarded
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 79/08/07 2pp

7908280178 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/07 1p

7908280329 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/13 1p

7908310315 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B H Region 1, Philadelphia, Office of the Director
79/08/14 1p

7908300182 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B H Region 1, Philadelphia, Office of the Director
79/08/15 1p

R Periodic operating reports & related correspondence

7908010495 Forwards June 1979 wastewater treatment rept for sewage treatment plant at facility.
MIDURA,H J Public Service Electric & Gas Co of New Jersey
79/07/06 2pp

7908010537 Forwards rept on diversion of water from well 5 & chloride analysis of Wells 1-3 & 6 for quarter ending June 1979.
MIDURA,H J Public Service Electric & Gas Co of New Jersey
79/07/09 3pp

7908010540 Forwards operating rept of industrial waste treatment plant for June 1979.
MIDURA,H J Public Service Electric & Gas Co of New Jersey
79/07/09 2pp

S Reportable occurrences, LERs & related correspondence

7908100029 Confirms 790608 telcon re potential safety hazard from deficiency identified in procedure to verify performance characteristics of Barton Lot 1 transmitters.List of affected plants encl.None in operation.
ANDERSON,T M Westinghouse Electric Corp 79/06/11 4pp

7908240597 Ack receipt of 790713 interim rept re component cooling pump impellers.
CARLSON,R T Region 1, Philadelphia, Office of the Director
79/07/30 1p

--7908240601 Discusses significant deficiency re component cooling pump impellers which exhibit numerous surface linear indications. New impellers have been ordered.Manufacturer rept re impellers will be supplied before 790727.
MARTIN,T J Public Service Electric & Gas Co of New Jersey
79/07/13 2pp

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

A Application/construction stage documents & correspondence

7908070809 Responds to 790628 memo re reliability evaluation of B&W auxiliary feedwater sys.
HLSS,D F TMI-2 Bulletins & Orders 79/07/02 2pp

7908140119 Advises that approval has been obtained for exempting Classes 1,11 & III amends re upgraded STS bases program from fees.
REID,R W Operating Reactors Branch 4 79/07/05 2pp

7908280239 Responds to encl 790606 ltr.Discusses decision by SMUD Board of Directors not to hold public hearing prior to restart;reasons for delay in plant restart & licensee actions resulting from TMI-2 incident.
DENTON,H R Office of Nuclear Reactor Regulation 79/07/16 3pp

--7908280246 Requests NRC comments re SMUD Board of Directors actions re refusal to hold public hearings;delay in plant restart & affect TMI-2 incident on operation of plant.
SMITH,J Downwind Alliance 79/06/06 1p

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda,MD to discuss status of TMI-2 activities by NRC task force groups.Meeting agenda & list of attendees encl.
EISENHUT,D G Division of Operating Reactors 79/07/18 58pp

7908080214 Requests addl info re degraded grid voltages.Requests response within 45 days.
REID,R W Operating Reactors Branch 4 79/07/23 4pp

7908060287 Extends invitation for visit to plant during week of 790820. Discusses containment isolation butterfly valves.
GOLDMAN,H L Allis-Chalmers Corp 79/07/26 1p

7908080189 Notifies that 790713 application for radiological effluent Tech Spec changes is not exempt from 10CFR170.22 fee requirements.Class III amend fee should be forwarded to NRC.
MILLER,W O License Fee Management Branch 79/07/30 1p

F Security, medical, emergency & fire protection plans

7908060163 Requests prompt forwarding of Class III fees for 780510 & 1003 Amends 2 & 3 to modified amended security plan.
DIGGS,R M License Fee Management Branch 79/07/03 2pp

7908220047 Forwards replacement pages to security plan evaluation rept which supports issuance of Amend 27 to License DPR-54.Pages withheld (ref 10CFR2.790).
REID,R W Operating Reactors Branch 4 79/07/25 3pp

7908200219 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
MATTIMOE,J J Sacramento Municipal Utility District 79/08/16 1p

G Adjudicatory correspondence

7908030612 Notifies of public inquiries re NRC shutdown order & circumstances for restart.Requests public hearing to reassure public of soundness of NRC decisions.
VARANINI,E E California, State of 79/06/07 2pp

7908080612 Discusses options for NRC action on Friends of Earth & SMUD requests for hearing per NRC 790507 shutdown order.Facility operation need not be stayed pending completion of hearing. Draft order encl.
BICKWIT,L Office of the General Counsel SECY-A-79-051 79/06/12. 18pp

--7908080620 Submits correction to SECY-A-79-51 on requests for hearing. ASLB has authority to order remedial action.
BICKWIT,L Office of the General Counsel SECY-A-79-051.
79/06/13 1p

--7908080627 Forwards revised draft order in response to Commissioners comments reflecting HR Denton 790619 memo to Commissioners re completion of NRC review of short-term actions.
BICKWIT,L Office of the General Counsel SECY-A-79-0518.
79/06/20 2pp

7908030551 Orders parties to amend petitions to intervene to state how interests are affected by NRC 790507 order.Each petitioner must set forth contentions.ASLB will hold 790801 prehearing conference to consider requests.
GLASER,M L Atomic Safety and Licensing Board Panel 79/07/03 3pp

7908150268 Confirms extension of deadline for amended petitions to 790723 per 790710 telcon w/ML Glaser.
VANDERVELDEN,M Friends of the Earth 79/07/10 1p

7908150276 Requests that ASLB 790703 order be extended to 790723.Order has not yet been served upon requesting petitioners.
HURSH,G ; CASTRO,R Sacramento Municipal Utility District
79/07/10 1p

7908170293 Announces position as general counsel for util;will be recipient for notices,documents & other papers.
KAPLAN,D S Sacramento Municipal Utility District 79/07/12 1p

7908300092 Responds to 790331 ltr re shutdown of plant & disposal of radwaste.Discusses changes in plant equipment operator procedures & operator training since TMI.No high level radwaste is imported for storage or mgt at present.
GAMMILL,W P Assistant Director for Operating Reactor Projects.
79/07/31 3pp

H General correspondence

7908300253 Responds to 790614 & 24 ltrs expressing concerns re shutdown of facility.Forwards NRC 790627 ltr to util permitting operation resumption & NRC 790621 order.
DENTON,H R Office of Nuclear Reactor Regulation 79/07/23 1p

--7908300263 Expresses concern re hardships caused by shutdown.Groups asking for nuclear plant shutdowns are not representative. Oil,natural gas & solar energy are not viable alternatives to nuclear power production.
WRINKLE,H H Affiliation Unknown 79/06/24 1p

--7908300273 Requests resumption of facility operation.Expresses concern re hardships resulting from shutdown.Util has complied w/all NRC requirements.Discusses util history.
WRINKLE,H H Affiliation Unknown 79/06/14 4pp

7908220545 Responds to 790624 ltr to NRC & 790614 ltr to HR Denton urging resumption of facility operation.Provides background info re shutdown.Forwards 790703 order & notice of prehearing conference & explains purpose of conference.
HELTEMES,C J Standardization Branch 79/07/27 1p

--7908220555 Order for filing amended & supplemental requests re effects of actions per NRC 790507 order Prehearing conference will be held 790801 in Sacramento,CA.
GLASER,M L. Atomic Safety and Licensing Board Panel. 79/07/03. 3pp.

--7908220559 Urges NRC to expedite resumption of operation due to unseasonably high temp & severe power shortage.Completion of required mods should justify startup.Suggests waste disposal methods.
WRINKLE,H H. Affiliation Unknown. 79/06/14. 3pp.

--7908220572 Urges swift action in ruling on any problems re 72 nuclear power plants in order to maintain full operation during critical period of energy shortage.Forwards related newspaper articles.
WRINKLE,H H. Affiliation Unknown. 79/06/24. 3pp.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design,fabrication history & insp & operating history of PWR feedwater lines.
STELLO,V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation.W/o encl.
EISENHUT,D G. Division of Operating Reactors. 79/06/04. 52pp.

7908130507 Forwards JL Crews 790531 memo re control grade reactor trips.Info should be used in reviewing util conformance to NRC 790507 order.
JORDAN,E L. Division of Reactor Operations Inspections. 79/06/05. 2pp.

--7908130513 Discusses design of hard-wired control-grade reactor trips which actuate on loss of main feedwater & turbine trip. Non-failsafe design is less reliable than intended by NRC 790507 order.
CREWS,J L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/05/31. 2pp.

7908090647 Notifies that util completed response to NRC 790507 order & proposed lifting suspension of plant operation. Submits proposed ltr to licensee.Forwards safety evaluation re resumed operation.
DENTON,H R. Office of Nuclear Reactor Regulation. 79/06/19. 4pp.

--7908090649 Safety evaluation re resumed operation.Licensee has fulfilled requirements of NRC 790507 order.Restart is authorized.
* Commission. 79/06/19. 29pp.

7908150720 Requests evaluation of semiscale small break experiment w/small break computer program by 790901.
ROSS,D F. TMI-2 Unresolved Safety Issues. 79/07/16. 7pp.

7908270267 Forwards request for addl info re degraded grid voltage, to be sent to licensee in order to complete review of 771010 submittal.Response required within 45 days.
LAINAS,G. Plant Systems Branch. 79/07/18. 3pp.

7908200107 Requests proposed amend to license to delete Tech Specs re secondary water chemistry monitoring program & to incorporate requirements of encl model license condition. Requests submittal within 60 days.
REID,R W. Operating Reactors Branch 4. 79/07/23. 4pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events.Requests addl five copies of response for each unit,if more than one is owned & operated.
HAASS,W P. Quality Assurance Branch. 79/07/24. 1p.

7908010350 Submits addl info re feedwater piping & inservice insp sys, in response to NRC 790525 ltr.
MATTIMOE,J J. Sacramento Municipal Utility District. 79/07/27. 9pp.

7908070521 Responds to 790629 ltr re info required to review corporate capabilities to handle incidents similar to TMI.Submits info re mgt technical resource capabilities.
WALBRIDGE,W C. Sacramento Municipal Utility District. 79/07/30. 44pp.

7908060252 Requests two-month delay in submitting details of proposed reactor vessel cavity seal plate storage design.Expects meaningful design parameters by 790930.
MATTIMOE,J J. Sacramento Municipal Utility District. 79/07/31. 1p.

7908300599 Summary of 790719 meeting w/utils in Bethesda,MD to discuss outstanding items from NRC orders & IE Bulletins generic to all B&W facilities.
CAPRA,R A. TMI-2 Bulletins & Orders. 79/07/31. 24pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations,guidance documents & repts re emergency planning.
EISENHUT,D G. Division of Operating Reactors. 79/08/03. 53pp.

7908160239 Notification of 790809 meeting w/B&W Owners' Group in Bethesda,MD to discuss long-term generic requirements for B&W operating plants.
CAPRA,R A. TMI-2 Unresolved Safety Issues. 79/08/06. 2pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL,W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908240388 Forwards fee for Amend 62 to License DPR-54. Fee paid under protest.
MATTIMOE,J J. Sacramento Municipal Utility District. 79/08/16. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7907020065 Forwards IE site inspector daily repts for B&W reactors for 790419.
DAVIS,J G. Office of Inspection & Enforcement, Office of the Director. 79/04/20. 1p.

7908020222 Forwards info concerning requalification training program statistics for operators & senior operators, in response to IE Bulletin 79-10.
MATTIMOE,J J. Sacramento Municipal Utility District. 79/05/23. 3pp.

7908070470 Responds to IE Bulletin 79-01.Response will be delayed until 790712,due to efforts required to respond to earlier bulletins re TMI.
MATTIMOE,J J. Sacramento Municipal Utility District. 79/05/31. 1p.

7908170117 Forwards IE Insp Rept 50-312/79-10 on 790507,08,14,17,22 29-31,0601,02,04,08 & 10-11.No noncompliance noted.
CREWS,J L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/06/19. 2pp.

--7908170123 IE Insp Rept 50-312/79-10 on 790507,08,14,17,22,29-31,0601, 02,04,08 & 10-11.No noncompliance noted.Major areas inspected:plant operations,response to IE bulletins & operator retraining pertaining to TMI incident.
JOHNSON,P , CARLSON,J. Region 5, San Francisco, Office of the Director. FAULKENBERRY,S. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/06/19. 6pp.

7908030055 QA Program Insp Rept 99900034/71-04 on 710824/27.
OLLER,R E , VETTER,W E. Atomic Energy Commission (Pre 1975). 71/09/30. 11pp.

7908010394 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN,R H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908020507 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN,R H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908020410 Forwards corrected copy of IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN,R H. Region 5, San Francisco, Office of the Director. 79/07/19. 1p.

7908170213 Details understanding of 790720 telcon notification of analyses & insp/testing results for Class 1 piping supports per IE Bulletin 79-02.
ENGELKEN,R H. Region 5, San Francisco, Office of the Director. 79/07/20. 2pp.

7908060028 Forwards IE Bulletins 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
ENGELKEN,R H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908060077 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908060160 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210518 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908170040 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10. 1p.

7908280395 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310157 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300252 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908140473 Forwards monthly operating rept for Jul 1979.
RODRIGUEZ, R. J. Sacramento Municipal Utility District. 79/08/07. 1p.

--7908140482 Monthly operating rept for Jul 1979.
COLOMBO, R. W. Sacramento Municipal Utility District. 79/07/31. 7pp.

S. Reportable occurrences, LERs & related correspondence

7908020534 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020032 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908100331 Forwards LER 79-006/02T-0.
MATTIMOE, J. J. Sacramento Municipal Utility District. 79/08/02. 2pp.

--7908100337 LER 79-006/02T-0 on 790720 addl small break LOCA analyses indicated 10CFR50 App K criteria may be exceeded for certain spectrum of small leaks in RCS coupled w/loss of reactor coolant pressure. Caused by operator failure.
COLOMBO, R. W. Sacramento Municipal Utility District. 79/08/02. 1p.

7908100478 Forwards LER 79-007/01T-0.
MATTIMOE, J. J. Sacramento Municipal Utility District. 79/08/02. 2pp.

--7908100482 LER 79-007/01T-0 on 790720 discovered six safety-related concrete expansion anchor bolts which did not meet criteria in IE Bulletin 79-02. Plant shut down to modify bolts to meet new design criteria.
COLOMBO, R. W. Sacramento Municipal Utility District. 79/08/02. 1p.

7908200370 Forwards LER 79-008/03L-0.
MATTIMOE, J. J. Sacramento Municipal Utility District. 79/08/09. 1p.

--7908200372 LER 79-008/03L-0 on 790719 while performing monthly pump surveillance on B decay heat removal pump, leakage observed at pump seal in excess of Tech Spec allowance. Caused unstated. Leaking seal replaced & sys tested.
COLOMBO, R. W. Sacramento Municipal Utility District. 79/08/20. 1p.

T. Hearing transcripts on non-antitrust matters

7908010620 Transcript of 790626 meeting in Washington, DC. Pp 1-55.
HENDRIE, J. M.; KENNEDY, R. T.; GILINSKY, V. Commission. 79/06/26. 61pp.

7908020196 Transcript of 790626 meeting in Washington, DC. Pp 1-55.
HENDRIE, J. M. Commission. 79/06/26. 56pp.

--7908020203 Proposes that suspension of operations be ended. Forwards draft safety evaluation & ltr to licensee.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/19. 34pp.

--7908020209 Order directing chairman of the ASLB to select Board to conduct necessary hearings. Board shall determine whether Friends of Earth meet requisite personal interest test. Hearings shall not affect restart.
CHILK, S. J. Office of the Secretary of the Commission. 79/06/21. 12pp.

7908090653 Transcript of 790801 meeting in Sacramento, CA. Pp 1-51.
GLASER, M.; SHON, F.; COLE, R. Atomic Safety and Licensing Board Panel. 79/08/01. 51pp.

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

A. Application/construction stage documents & correspondence

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 58pp.

F. Security, medical, emergency & fire protection plans

7908130155 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 1p.

7908230394 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
TRIMBLE, D. C. Arkansas Power & Light Co. 79/08/17. 1p.

H. General correspondence

7908090580 Responds to NRC 790629 ltr re mgt & technical resources. Organization charts & position descriptions encl.
CAVANAUGH, W. Arkansas Power & Light Co. 79/07/30. 44pp.

P. Operating license stage documents & correspondence

7908010038 Responds to IE Bulletin No 0E Type AK-2 circuit breakers used in Unit 2 & no plans for future use. Breakers installed in Unit 1 control rod drive sys are maintained per inservice insp procedure.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/05/10. 2pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908010303 Forwards questions for completion of technical review of proposed mod for protection of engineered safety feature equipment from degraded electric power conditions. Recommends that Tech Specs be submitted w/responses.
LAINAS, G. Plant Systems Branch. 79/06/15. 4pp.

7908030588 Notifies of review of 780823, 790313 & 0521 submissions re power distribution sys & degraded grid voltage. Forwards request for addl info.
REID, R. W. Operating Reactors Branch 4 (Pre 790625). 79/06/20. 4pp.

7908280757 Requests registration as user of Model B3-1.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/20. 1p.

7908170155 Comments on FAA draft environ statement for Russellville Municipal Airport, Russellville, AR. Recommends site located 8 to 9 miles from plant.
REGAN, W. H. Assistant Director for Environmental Technology 79/06/27 1p

7908080276 Requests addl info re plans to determine actual chemistry of closure head weld & rept on elevated temp data. Schedule for response should be provided as soon as possible.
REID, R. W. Operating Reactors Branch 4 79/06/29 1p

7908100123 Forwards request for addl info to complete evaluation of inservice testing program.
REID, R. W. Operating Reactors Branch 4 79/06/29 7pp

7908290508 Submits review of fee considerations re feedwater sys & responses to IE Bulletins 79-05B on valve setpoints. Suggests fee schedule for each unit be determined in consistent manner.
MILLER, W. O. License Fee Management Branch 79/07/05 2pp

7908100320 Requests registration as user of Model CNS 21-300 radioactive matl shipping cask.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/11 1p

7908140481 Requests addl info within 30 days re purge valves & actuators to continue review of amend to license.
REID, R. W. Operating Reactors Branch 4 79/07/16 4pp

7908150512 Requests registration as user of Models 927A1 & 927C1.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/16 1p

7908150720 Requests evaluation of semiscale small break experiment w/small break computer program by 790901.
ROSS, D. F. TMI-2 Unresolved Safety Issues 79/07/16 7pp

7908160157 Discusses encl 790606 ltr re desi[illegible] of drain line from reactor bldg sump to auxiliary bldg sump. NRC evaluation of design should be completed by late Jul 1979.
ROSS, D. F. TMI-2 Unresolved Safety Issues 79/07/16 2pp

7908170538 Requests registration as user of Model 6144.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/16 1p

7908150493 Requests registration as user of Model HN-100, Series 2.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/17 1p

7908150542 Requests registration as user of Model [illegible]-200.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/17 [illegible]

7908070355 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/07/18 1p

7908150256 Advises that 780202 response has been reviewed re potential for reactor cavity annulus seal ring to become destructive missile in LOCA. Requests analysis demonstrating safe conditions & statement re seal ring removal.
REID, R. W. Light Water Reactors Branch 4 79/07/19 2pp

7908200111 Requests proposed amend to license to delete Tech Specs re secondary water chemistry monitoring program & to incorporate requirements of encl model license condition. Requests submittal within 60 days.
REID, R. W. Operating Reactors Branch 4 79/07/23 4pp

7908013461 Responds to NRC 790331 request re seismic & environ qualifications of recently-installed cooling equipment. Seismic criteria were specified in IEEE 345-1975 & environ criteria in IEEE 323-1974.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/24 1p

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908230056 Requests results of semiscale small break experiment be compared w/small break computer program being used by C-E in support of owners group. To date, evaluations of latter have been inconclusive.
ROSS, D. F. TMI-2 Bulletins & Orders 79/07/25 8pp

7908020476 Submits info in response to 790525 request re PWR feedwater lines. Fabrication history, preservice/inservice insp & operating history are included.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/27 4pp

7908090580 Responds to NRC 790629 ltr re mgt & technical resources. Organization charts & position descriptions encl.
CAVANAUGH, W. Arkansas Power & Light Co. 79/07/30 44pp

7908300599 Summary of 790717 m[illegible]g w/utils in Bethesda, MD to discuss outstanding items from NRC orde[illegible] IE Bulletins generic to all B&W facilities.
CAPRA, R. A. TMI-2 Bulletins & Orders 79/07/31 24pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

7908160239 Notification of 790809 meeting w/B&W Owners' Group in Bethesda, MD to discuss long-term generic requirements for B&W operating plants.
CAPRA, R. A. TMI-2 Unresolved Safety Issues 79/08/06 2pp

7908220274 Notification of 790822 meeting w/Middle South Svcs, Inc to discuss topical rept on reactor physics methods for use at facilities.
FIENO, D. Core Performance Branch 79/08/09 2pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908290420 Forwards info on seismically qualified purge valves & actuators in response to 790716 request.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/08/22 3pp

7908300670 Responds to 790620-0816 & [illegible] ltrs re degraded grid voltage. Forwards "Undervoltage Relays" & "Test Plugs for Drawout Relays & Meters" by GE & Table 1, "ANO-1 Running Loads Upon Full House Transfer to ST 1."
TRIMBLE, D. C. Arkansas Power & Light Co. 79/08/24 22pp

G. Inspection reports, IE Bulletins & correspondence

7907020065 Forwards IE site inspector daily repts for B&W reactors for 790419.
DAVIS, J. G. Office of Inspection & Enforcement, Office of the Director 79/04/20 1p

7908080448 Ack receipt of 781121 & 790423 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-313/78-17.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/23 1p

--7908090456 Submits revision to 781121 ltr responding to violation noted in IE Insp Rept 50-313/78-17. Revised corrective actions: addl personnel will be trained to determine waste releases & analysis will be conducted prior to waste release.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/04/23 2pp

7908090688 Forwards IE Insp Rept 50-313/79-09 & 50-368/79-09 on 790414-0511. No noncompliance noted.
MADSON, G. L. Region 4, Dallas, Office of the Director 79/05/31 2pp.

--7908090691 IE Insp Rept 50-313/79-09 & 50-368/79-09 on 790414-0511. No noncompliance noted. Major areas inspected: previously noted items, refueling activities & licensee actions taken in response to IE Bulletin 79-05A.
JOHNSON, W. D., SPANGLER, R. G., WESTERMAN, T. F. Region 4, Dallas, Office of the Director 79/05/30 15pp

7908090261 Ack receipt of 790530 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-07 & 50-368/79-07.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/14 1p

--7908090275 Responds to NRC 790501 ltr re violations noted in IE Insp Repts 50-313/79-07 & 50-368/79-07. Corrective actions: procedures revised to require ignition work permit & control of combustible debris.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/05/30 3pp.

7908160021 Responds to IE Bulletin 79-03 re schedule for testing Youngstown piping used in Unit 1 Examination of piping is not necessary. Testing results to verify conclusion will be submitted by 790901.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/06/22 1p

7908160025 Supplements 790510 ltr re IE Bulletin 79-09. GE Type AK-2A-25-1 circuit breakers are installed in nine locations in reactor trip switchgear of Unit 2. Corrective actions are being developed to conform w/GE Advice Ltr 175.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/06/22 1p.

7908020367 Requests submittal of procedures to be used to facilitate IE program assessment team insp scheduled for 790730-0803 & 06-10. Submitted procedures will be returned following completion of insp.
MADSEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/03 1p

7908030111 Responds to IE Bulletin 79-02, Revision 1 re seismic analysis of concrete pipe support base plate design. Forwards rept "Statistical Sampling Program to Test Concrete Expansion Bolts," by Bechtel Corp.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/07/06 11pp

---7908030118 "Statistical Sampling Program to Test Concrete Expansion Bolts," prepared for AR Power & Light.
* Bechtel Power Corp. (subs. of Bechtel Corp.) 79/05/17 69pp

7908160028 Responds to IE Bulletin 79-13, item 5. Volumetric examination of Unit 2 feedwater nozzle-to-piping welds will be performed. Emergency procedures re feedwater line break accidents are adequate.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/07/12 2pp.

7908030055 QA Program Insp Rept 99900034/71-04 on 710824-27.
OLLER, R.E.; VETTER, W.E. Atomic Energy Commission (Pre 1975) 71/09/30 11pp.

7908170371 Responds to IE Bulletins 79-01 & 01A re environ qualification of safety-related electrical equipment inside reactor bldg. No stem-mounted limit switches or solenoid valves planned for use.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/07/13 46pp

7908020393 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/07/18 1p

7908060019 Forwards IE Bulletins 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/07/26 1p

7908060038 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/07/26 1p

7908060123 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/07/26 1p

7908160459 Forwards rept re steam generator tube inservice insp performed during third refueling outage.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/08/08 1p

7908160049 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/08/10 1p

R Periodic operating reports & related correspondence

7908020430 Submits results of impingement monitoring at intake during June 1979. Computer cards encl.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/07/26 8pp.

7908150514 Forwards second quarter 1979 NPDES rept for Permit AR0001392.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/08/06 9pp.

7908230370 Forwards monthly operating rept for Jul 1979.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/08/14 1p

---7908230371 Monthly operating rept for Jul 1979.
SHIVELY, C.N. Arkansas Power & Light Co. 79/08/14 5pp.

7908290512 Forwards impingement monitoring rept for Jul 1979. Input data cards encl.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/08/23 1p

---7908290517 Impingement monitoring rept for Jul 1979.
* Arkansas Power & Light Co. 79/08/16 10pp.

S Reportable occurrences, LERs & related correspondence

7908140267 Requests approval of proposed expansion of heavy water moderated & organic cooled reactor generic issue implementation re degraded grid voltage. Forwards draft ltr to licensees w/encl background of event & guidelines.
EISENHUT, D.G. Division of Operating Reactors 79/07/05 9pp.

7908080502 Submits RO 50-313/79-10: transient dynamic load not included in design of main steam pipe supports & restraints located in containment. Piping stress exceeds max allowable. Review in progress.
O'HANLON, J.P. Arkansas Power & Light Co. 79/07/16 1p.

7908010694 Forwards PNO-79-67AX.
MADSEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/20 1p.

7908020449 Forwards LER 79-009/03L-0 & 79-010/01T-0.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/07/27 1p.

---7908020459 LER 79-009/03L-0 on 790628 during power operation reactor bldg hydrogen purge fan VSF-30A tripped after 90 minutes of 10-h run. Caused by overcurrent. Fan restarted using less sealing water.
SHIVELY, C.N. Arkansas Power & Light Co. 79/07/27 1p.

---7908020475 LER 79-010/01T-0 on 790714 design of main steamline restraints did not consider steam hammer transient forces. Review performed. Overstressed area will be modified.
SHIVLEY, C.N. Arkansas Power & Light Co. 79/07/27 4pp.

7908080495 Forwards Special Rept 79-N/A99X-0.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/08/01 1p.

---7908080511 Special Rept 79-N/A/99X-0 on 790522 during routine insp, cable leads were found lifted but not tagged. Lifted leads prevented automatic opening of emergency feedwater valves. Cause unknown. Leads reconnected.
SHIVELY, C.N. Arkansas Power & Light Co. 79/08/01 1p.

7908310386 Forwards RO 79-N/A/99X-0.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/08/01 1p.

---7908310393 RO 79-N/A/99X-0 on 790522 during routine maint investigation, cable leads at C-46, 1-8-5 termination 2 & 6 were found lifted. Cause unknown. Leads reconnected & valves proven operable.
SHIVELY, C.N. Arkansas Power & Light Co. 79/05/22 1p.

7908310381 Confirms 790809 verbal rept of RO. Valve PS-V1002 was improperly tested on 780328. Test gage was not calibr. Following test, valve will be retested. Detailed rept to follow.
O'HANLON, J.P. Arkansas Power & Light Co. 79/08/10 1p.

7908300569 Forwards LER 79-011/01T-0.
TRIMBLE, D.C. Arkansas Power & Light Co. 79/08/23 1p.

---7908300571 LER 79-011/01T-0 on 790809 during NRC performance appraisal team interview, discovered that pressurizer safety relief valve PSV-1002 was not properly tested in Mar 1978. Valve retested 790812 w/no adjustments required.
SHIVELY, C.N. Arkansas Power & Light Co. 79/08/23 4pp.

DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

7908130192 Notifies that re iew of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch 79/07/03. 2pp.

7908280572 Forwards guard force training program & retraining & requalification program manua s. Plans withheld (ref 10CFR2.790).
HUNTER, R.S. Indiana & Michigan Power Co. 79/08/17. 1p.

H. General correspondence

7908150084 Ack receipt of correspondence re status of spent fuel storage at six operating facilities near Lake Michigan. Responds to 790429 ltr.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/07/26. 2pp.

--7908150107 Discusses spent fuel storage capability at Big Rock Point. NUREG-0020 indicates authorized capacity of 120 spent fuel assemblies, while DOE indicates capacity of 365. Requests clarification.
SCHAEFER, J. Lake Michigan Federation. 79/05/20. 1p.

--7908150125 Ack receipt of info re nuclear power plants near Lake MI. Forwards rept re status of spent fuel storage at plants. Requests comments re rept.
SCHAEFER, J. Lake Michigan Federation. 79/06/21. 1p.

--7908150139 "Status of Spent Fuel Storage #: Six Nuclear Plants Located on Shores of Lake MI."
SCHAEFER, J. Lake Michigan Federation. 79/05/31. 20pp.

7908060241 Documents telcon between JI Castresana & WP Hauss re extension until 790817 to supply info required to review corporate capabilities. Request approved by WP Hass.
DOLAN, J.E. Indiana & Michigan Power Co. 79/07/27. 2ps.

7908280610 Responds to NRC 790629 request for info re technical & mgt resources available for unusual events. Organization charts & resumes for offsite mgt resources & staff encl.
HUNTER, R.S. Indiana & Michigan Power Co. 79/08/17. 110pp.

P. Operating license stage documents & correspon

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D.G. Division of Operating Reactors. 79/06/04. 52pp.

7908010594 Discusses review of safety injection actuation sys Tech Spec change request. Proposed changes result from response to IE Bulletin 79-06A & are acceptable. Safety evaluation encl.
LAINAS, G. Plant Systems Branch. 79/06/20. 2pp.

--7908010603 Ofc of Nuclear Reactor Regulation safety evaluation of proposed mods to safety injection actuation sys logics. Mods are acceptable.
* Plant Systems Branch. 79/06/20. 2pp.

7908070644 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/06/22. 3pp.

7908030045 Forwards Amend 30 to License DPR-58, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/03. 2pp.

--7908030048 Amend 30 to License DPR-58, permitting operation w/slightly positive moderator temp coefficient below 70% of rated thermal power.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/03. 5pp.

--7908030052 Safety evaluation supporting Amend 30 to License DPR-58.
* Operating Reactors Branch 1. 79/07/03. 3pp.

--7908030056 Notice of issuance & availability of Amend 30 to License DPR-58.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/03. 2pp.

7908130294 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires initial notification of NRC.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/09. 1p.

7908310147 Requests registration as user of Model HN-200.
DOLAN, J.E. Indiana & Michigan Power Co. 79/07/09. 2pp.

7908130093 Discusses program to upgrade bases section of STS. Amends in fee Classes I, II, & III which result from program will be fee exempt.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/11. 2pp.

7908100360 Forwards request for addl info to util 770722 submittal re degraded grid voltage. Info sought within 45 days.
LAINAS, G. Plant Systems Branch. 79/07/13. 2pp.

7908150027 Outlines addl info needed re proposed mod to discharge structure scour bed. Requests description of condition of scour beds & procedures used to assess bed condition prior to implementation of corrective actions.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/13. 2pp.

7908270271 Requests addl $2,800 for Class III fee be forwarded per NRC 790531 ltr.
MILLER, W.O. License Fee Management Branch. 79/07/16. 1p.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W.P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070329 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/19. 1p.

7908010562 Ack receipt of NRC 790703 ltr re safeguards contingency plan. Forwards Class III processing fee.
DOLAN, J.E. Indiana & Michigan Power Co. 79/07/23. 2pp.

7908060007 Forwards request for addl spent fuel pool expansion info, in response to util 790416 & 0629 submittals. Requests response within 30 days.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/24. 3pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W.P. Quality Assurance Branch. 79/07/24. 1p.

7908060233 Amends info contained in 790504 & 08 submittals. Floor response damping factor used to determine max upset condition stresses was 4% instead of 2%. Stresses within allowable values.
DOLAN, J.E. Indiana & Michigan Power Co. 79/07/27. 3pp.

7908060345 Forwards addl info re spent fuel storage capacity expansion program.
DOLAN, J.E. Indiana & Michigan Power Co. 79/07/27. 7pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J.P. Standardization Branch. 79/07/30. 64pp.

7908290280 Forwards Amends 31 & 12 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/31. 3pp.

--7908290290 Amends 31 & 12 to Licenses DPR-58 & DPR-74, authorizing completion of mods per Table 1 in 790604 fire protection SER.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/31. 2pp.

--7908290306 Safety evaluation supporting Amends 31 & 12 to Licenses DPR-56 & DPR-74, respectively.
* Office of Nuclear Reactor Regulation. 79/07/31. 24pp.

--7908290315 Notice of issuance & availability of Amends 31 & 12 to Licenses DPR-58 & DPR-74, respectively.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/31. 2pp.

7908130577 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/01. 4pp.

7908300589 Requests schedule for submittal of outstanding air entrainment & jet impingement testing & for response to 781107 request for addl info.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/01. 3pp.

7908090508 Requests rept on small break accidents in Westinghouse NSSS (WCAP-9600) be included in dockets Section 6 & App A re revised generic emergency operations instructions will be integrated into procedures & training program upon approval.
DOLAN, J. E. Indiana & Michigan Power Co. 79/08/02. 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908140559 Requests Tech Spec changes re auxiliary feedwater sys per sys mod described in Amend 84 to FSAR. Changes would separate shared operation of motor driven auxiliary feedwater pumps.
DOLAN, J. E. Indiana & Michigan Power Co. 79/08/09. 3pp.

--7908140559 App A to Tech Specs: detailing separating of shared operation of motor driven auxiliary feedwater pumps by installation of addl pump in each unit.
* Indiana & Michigan Power Co. 79/08/09. 11pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908210037 Forwards request for addl info needed to complete activity re 770722 submittal on degraded voltage. Response required within 45 days.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/15. 3pp.

7908220357 Forwards Flow Diagrams 1-2-5143, Revision 16 & 1-2-5142, Revision 20 per telcon request. Diagrams apply to RHR & safety injection sys. W/o encl.
MALONEY, G. P. Indiana & Michigan Power Co. 79/08/16. 2pp.

7908280664 Forwards application for amend to OLs DPR-58 & DPR-74 & Annual Rept 1978.
DOLAN, J. E. Indiana & Michigan Power Co. 79/08/24. 2pp.

--7908280671 Application for amend to OLs DPR-58 & DPR-74 to reflect proposed merger of IN & MI Power Co w/IN & MI Electric Co. Latter would be surviving corp w/100% direct ownership interest.
DOLAN, J. E. Indiana & Michigan Power Co. 79/08/24. 5pp.

--7908280676 Annual Rept 1978.
* Affiliation Unknown. 78/12/31. 53pp.

G. Inspection reports, IE Bulletins & correspondence

7908030554 Responds to info forwarded in 790424, 0504 & 0620 ltrs re results of seismic piping stress reanalysis. Reanalysis techniques & results of reanalysis are acceptable. Forwards safety evaluation rept.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/06/22. 2pp.

--7908030559 Safety evaluation re review of piping reanalysis. Reanalysis techniques & results of reanalysis are acceptable per IE Bulletin 79-07.
* Engineering Branch. 79/06/22. 2pp.

7908150255 Forwards IE Insp Repts 50-315/79-16 & 50-316/79-09 on 790613. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/25. 2pp.

--7908150266 IE Insp Repts 50-315/79-16 & 50-316/79-09 on 790613. No noncompliance noted. Major areas inspected, licensee action on IE Circular 78-08.
JABLONSKI, F. J.; HAYES, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/21. 3pp.

7908150280 Forwards IE Insp Rept 50-315/79-14 & 50-316/79-11 on 790529-0601 & notice of violation.
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/25. 2pp.

--7908150290 Notice of violation from insp on 790529-0601.
* Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/25. 1p.

--7908150346 IE Insp Repts 50-315/79-14 & 50-316/79-11 on 790529-0601. Noncompliance noted: inadequate air sampling & inadequate followup on whole body counting results.
SCHMACHER, M. C.; FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/20. 8pp.

7908150357 Forwards IE Insp Repts 50-315/79-13 & 50-316/79-10 on 790505-31 & notice of violation.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/25. 2pp.

--7908150367 Notice of violation from insp on 790505-31.
* Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/25. 1p.

--7908150382 IE Insp Rept 50-315/79-13 & 50-316/79-10 on 790505-31. Noncompliance noted: failure to maintain or implement procedures & mod not revealed or approved by onsite review committee.
MASSE, R. E.; BAKER, K. R.; BOYD, D. C. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/21. 13pp.

7908160184 Ack receipt of 790601 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/79-05 & 50-316/79-05.
HEISHMAN, R. F. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/28. 1p.

--7908160193 Responds to NRC 790508 ltr re violations noted in IE Insp Repts 50-315/79-05 & 50-316/79-05. Corrective actions: issued temporary sheet on 790525 to eliminate requirement of logging fuses removed for short time period.
DOLAN, J. E. American Electric Power Co., Inc. 79/06/01. 3pp.

7908080376 Forwards C-E 790608 ltr in response to IE Bulletins 78-12, 12A & 12B, "Atypical Weld Matl in Reactor Pressure Vessels."
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/03. 2pp.

--7908080389 Forwards 790608 generic rept requested per IE Bulletin 78-12, re atypical weld matl in reactor pressure vessel welds. W/o rept Affidavit & Westinghouse 790625 ltr encl.
SCHERER, A. E. Combustion Engineering, Inc., C-E Minerals Div. 79/06/08. 4pp.

7908290520 Forwards IE Insp Repts 50-315/79-10 & 50-316/79-07 on 790521-24 & notice of violation.
FIORELLI, G. Region 3, Chicago, Office of the Director. 79/07/03. 2pp.

--7908290523 Notice of violation from insp on 790521-24.
* Region 3, Chicago, Office of the Director. 79/07/03. 1p.

--7908290529 IE Insp Repts 50-315/79-10 & 50-316/79-07 on 790521-24. Noncompliance noted: failure to develop repair procedures prior to beginning of work.
KEY, W. J.; DANIELSON, D. H. Region 3, Chicago, Office of the Director. 79/06/28. 4pp.

7908080366 Responds to 790522 ltr re IE Bulletin 79-11, Westinghouse DB-75 breakers are not used on safety-related Class IE circuits. Safety-related breakers shall be tested at each refueling outage.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/05. 2pp.

7908130403 Responds to IE Bulletin 79-02, Revision 1 re pipe support baseplate designs using concrete expansion anchor bolts. Teledyne Engineering Svcs 790629 generic program baseplate/expansion anchor studies encl.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/11. 10pp.

7908170464 Responds to IE Bulletin 79-13. Cracked feedwater elbows replaced, radiographed & found acceptable.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/20. 3pp.

7908240518 Submits suppl to 790501 ltr responding to IE Bulletin 79-06A, Revision 1, re instrumentation to recognize void formation in reactor coolant sys, containment isolation, operating procedure & training & valve lineup walkaround.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/25. 14pp.

7908290279 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300385 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908230132 Ack receipt of 790525 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-315/79-07 & 50-316/79-06.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/07/30. 1p.

--7908230138 Responds to NRC 790502 ltr re violation noted in IE Insp Repts 50-315/79-07 & 50-316/79-06. Special briefing sessions conducted & test drills undertaken re 20-ft isolation zone required when tanks are placed near security fence.
DOLAN, J. E. Indiana & Michigan Power Co. 79/05/25 2pp.

7908150283 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07 1p.

7908170017 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08 1p.

7908300262 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15 1p.

R. Periodic operating reports & related correspondence

7908310335 Forwards monthly operating rept for Jul 1979.
SHALLER, D. V. Indiana & Michigan Power Co. 79/08/13 1p.

--7908310338 Monthly operating rept for Jul 1979.
GILLETT, W. J. Indiana & Michigan Power Co. 79/08/07 10pp.

S. Reportable occurrences, LERs & related correspondence

7908150314 Forwards SI Actuation Rept 81-12 on 790323.
SHALLER, D. V. Indiana & Michigan Power Co. 79/06/22 1p.

--7908150320 SI Actuation Rept 81-12 on 790323 while in Mode 1 at 100% power; power supplies to vital instrument buses I & II failed. SI actuated by false instrument indications. Power failure caused by failed capacitor.
* Indiana & Michigan Power Co. 79/03/23 2pp.

7908060416 Forwards LERs 79-034/03L-0 & 79-035/03L-0.
SHALLER, D. V. Indiana & Michigan Power Co. 79/07/31 1p.

--7908060422 LER 79-036/03L-0 on 790705 during plant tour, two ice condenser intermediate deck doors were found frozen shut. Cause not determined. No further action planned. Formerly numbered incorrectly as LER 79-034/03L-0.
BROWN, M. S. Indiana & Michigan Power Co. 79/07/31 1p.

--7908060430 LER 79-035/03L-0 on 790705 while cleanup of demineralized water sys was in process, RCS passed from operational Mode 5 to Mode 4 & isolation valves closed. Caused by breakdown of communication between cleanup crew & reactor operator.
LEASE, R. S. Indiana & Michigan Power Co. 79/07/31 2pp.

7908140650 Forwards LER 79-037/03L-0 & revised LER 79-034/03L-0, changing rept number to 79-036/03L-0.
SHALLER, D. V. Indiana & Michigan Power Co. 79/08/08 1p.

--7908140656 LER 79-037/03L-0 on 790709 position of certain control bank C rods exceeded 12-step limit imposed by Tech Specs. Caused by drifting of rod signal conditioning module.
BEILMAN, T. P. Indiana & Michigan Power Co. 79/08/08 1p.

--7908140790 LER 79-036/03L-0 on 790709 two ice condenser intermediate deck doors found frozen shut. Cause not determined. Ice chipped off 5 doors returned to operable status.
BROWN, M. S. Indiana & Michigan Power Co. 79/07/31 1p.

7908210517 Forwards updated LERs 78-065/03X-1, 79-022/03X-1, 79-030/03X-1, 79-038/03L-0 & 79-039/03L-0.
SHALLER, D. V. Indiana & Michigan Power Co. 79/08/15 1p.

--7908210525 Updated LER 78-065/03X-1 on 781229 previous rept of inoperable pressurizer level channel is no longer considered RO due to recent Tech Spec change deleting all pressurizer low level operability requirements.
BEILMAN, T. P. Indiana & Michigan Power Co. 79/08/15 2pp.

--7908210534 Updated LER 79-022/03X-1 on 790323 to prevent recurrence of nearly simultaneous bus failures, battery equalizing charge has been reduced from 280 to 275 volts. Addl design change requested to provide overvoltage alarm to alert operators.
BEILMAN, T. P. Indiana & Michigan Power Co. 79/08/15 2pp.

--7908210541 Updated LER 79-030/03X-1 on 790417 design change coupled w/relay degradation caused relay to react slower during sequence. Design change RFC-DC-12-2384 installed as preventive measure.
BEILMAN, T. P. Indiana & Michigan Power Co. 79/08/15 2pp.

--7908210546 Updated LER 79-038/03L-0 on 790717 engineering review in progress to determine cause of recurring problem of indicated position of control rods N-13 & H-6 exceeding Tech Specs.
BEILMAN, T. P. Indiana & Michigan Power Co. 79/08/15 2pp.

--7908210551 Updated LER 79-039/03L-0 on 790720 control sys repaired to deliver larger quantity of acid to RCS. No further action planned.
CHADWELL, H. M. Indiana & Michigan Power Co. 79/08/15 2pp.

7908290423 Forwards LER 79-040/03L-0.
SHALLER, D. V. Indiana & Michigan Power Co. 79/08/22 1p.

--7908290439 LER 79-040/03L-0 on 790726 during moderator coefficient test, reactor power decreased from 79% to 58% in 40 minutes. Iodine isotopic analysis not performed in required time. Caused by poor communication between operator & supervisor.
RISCHLING, J. L. Indiana & Michigan Power Co. 79/07/26 2pp.

DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

7908130192 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03 2pp.

7908280572 Forwards guard force training program & retraining & requalification program manuals. Plans withheld (ref 10CFR2.790).
HUNTER, R. S. Indiana & Michigan Power Co. 79/08/17 1p.

H. General correspondence

7908150084 Ack receipt of correspondence re status of spent fuel storage at six operating facilities near Lake Michigan. Responds to 790429 ltr.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/26 2pp.

--7908150107 Discusses spent fuel storage capability at Big Rock Point. NUREG-0020 indicates authorized capacity of 120 spent fuel assemblies, while DOE indicates capacity of 365. Requests clarification.
SCHAEFER, J. Lake Michigan Federation. 79/05/20. 1p.

--7908150125 Ack receipt of info re nuclear power plants near Lake MI. Forwards rept re status of spent fuel storage at plants. Requests comments re rept.
SCHAEFER, J. Lake Michigan Federation. 79/06/21 1p.

--7908150139 "Status of Spent Fuel Storage at Six Nuclear Plants Located on Shores of Lake MI."
SCHAEFER, J. Lake Michigan Federation. 79/05/31 20pp.

7908060241 Documents telcon between JI Castresana & WP Haass re extension until 790817 to supply info required to review corporate capabilities. Request approved by WP Haass.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/27 2pp.

7908280610 Responds to NRC 790629 request for info re technical & mgt resources available for unusual events. Organization charts & resumes for offsite mgt resources & staff encl.
HUNTER, R. S. Indiana & Michigan Power Co. 79/08/17 110pp.

I. Financial information

7908060433 Forwards indemnity fee for period 780818 through 800817, per 790713 request.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/26 2pp.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25 3pp.

7908010594 Discusses review of safety injection actuation sys Tech Spec change request. Proposed changes result from response to IE Bulletin 79-06A & are acceptable. Safety evaluation encl.
LAINAS, G. Plant Systems Branch. 79/06/20 2pp.

DOCKETED ITEMS

--7908010603 Ofc of Nuclear Reactor Regulation safety evaluation of proposed mods to safety injection actuation sys logics Mods are acceptable.
* Plant Systems Branch 79/06/20 2pp

7908070644 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 3pp

7908130294 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires initial notification of NRC.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/09 1p

7908310147 Requests registration as user of Model HN-200.
DOLAN, J E Indiana & Michigan Power Co 79/07/09 2pp

7908130093 Discusses program to upgrade bases section of STS. Amends in fee Classes I, II, & III which result from program will be fee exempt.
SCHWENCER, A Operating Reactors Branch 1 79/07/11 2pp

7908100360 Forwards request for addl info to util 770722 submittal re degraded grid voltage. Info sought within 45 days.
LAINAS, G Plant Systems Branch 79/07/13 2pp

7908270271 Requests addl $2,800 for Class III fee be forwarded per NRC 790531 ltr.
MILLER, W O License Fee Management Branch 79/07/16 1p

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W P Assistant Director for Standard & Advanced Reactors 79/07/18 1p

7908070329 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/19 1p

7908010562 Ack receipt of NRC 790703 ltr re safeguards contingency plan. Forwards Class III processing fee.
DOLAN, J E Indiana & Michigan Power Co 79/07/23 2pp

7908060007 Forwards request for addl spent fuel pool expansion info, in response to util 790416 & 0629 submittals. Requests response within 30 days.
SCHWENCER, A Operating Reactors Branch 1 79/07/24 3pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W P Quality Assurance Branch 79/07/24 1p

7908060233 Amends info contained in 790504 & 08 submittals. Floor response damping factor used to determine max upset condition stresses was 4% instead of 2%. Stresses within allowable values.
DOLAN, J E Indiana & Michigan Power Co 79/07/27 3pp

7908060345 Forwards addl info re spent fuel storage capacity expansion program.
DOLAN, J E Indiana & Michigan Power Co 79/07/27 7pp

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J P Standardization Branch 79/07/30 64pp

7908290280 Forwards Amends 31 & 12 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability.
SCHWENCER, A Operating Reactors Branch 1 79/07/31 3pp

--7908290290 Amends 31 & 12 to Licenses DPR-58 & DPR-74, authorizing completion of mods per Table 1 in 790604 fire protection SER.
SCHWENCER, A Operating Reactors Branch 1 79/07/31 2pp

--7908290306 Safety evaluation supporting Amends 31 & 12 to Licenses DPR-58 & DPR-74, respectively.
* Office of Nuclear Reactor Regulation 79/07/31 24pp

--7908290315 Notice of issuance & availability of Amends 31 & 12 to Licenses DPR-58 & DPR-74, respectively.
SCHWENCER, A Operating Reactors Branch 1 79/07/31 2pp

7908130577 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A Operating Reactors Branch 1 79/08/01 4pp

7908300589 Requests schedule for submittal of outstanding air entrainment & jet impingement testing & for response to 781107 request for addl info.
SCHWENCER, A Operating Reactors Branch 1 79/08/01 3pp

7908090508 Requests rept on small break accidents in Westinghouse NSSS (WCAP-9600) be included in dockets. Section 6 & App A re revised generic emergency operations instructions will be integrated into procedures & training program upon approval.
DOLAN, J E Indiana & Michigan Power Co 79/08/02 2pp

7908140559 Requests Tech Spec changes re auxiliary feedwater sys per sys mod described in Amend 84 to FSAR. Changes would separate shared operation of motor driven auxiliary feedwater pumps.
DOLAN, J E Indiana & Michigan Power Co 79/08/09 3pp

--7908140559 App A to Tech Specs, detailing separating of shared operation of motor driven auxiliary feedwater pumps by installation of addl pump in each unit.
* Indiana & Michigan Power Co 79/08/09 11pp

7908210037 Forwards request for addl info needed to complete activity re 770722 submittal on degraded voltage. Response required within 45 days.
SCHWENCER, A Operating Reactors Branch 1 79/08/15 3pp

7908220357 Forwards Flow Diagrams 1-2-5143, Revision 16 & 1-2-5142, Revision 20 per telcon request. Diagrams apply to RHR & safety injection sys w/o encl.
MALONEY, G P Indiana & Michigan Power Co 79/08/16 2pp

7908280664 Forwards application for amend to OLs DPR-58 & DPR-74 & Annual Rept 1978.
DOLAN, J E Indiana & Michigan Power Co 79/08/24 2pp

--7908280671 Application for amend to OLs DPR-58 & DPR-74 to reflect proposed merger of IN & MI Power Co w/IN & MI Electric Co. Latter would be surviving corp w/100% direct ownership interest.
DOLAN, J E Indiana & Michigan Power Co 79/08/24 5pp

--7908280676 Annual Rept 1978.
* Affiliation Unknown 78/12/31 53pp

Q. Inspection reports. IE Bulletins & correspondence

7908090311 Responds to IE Bulletins 78-12, 12A & 12B. CB&I 790424 rept re weld matl provides necessary info. Westinghouse & American Electric Power conclude rept adequately represents weldment matl data.
DOLAN, J E Indiana & Michigan Power Co 79/06/01 3pp

--7908090576 Responds to IE Bulletins 78-12 & 12A. Forwards rept re all completed reactor vessels. W/o encl.
KELLEY, R E Chicago Bridge & Iron Co 79/04/24 1p

--7908090584 Responds to IE Bulletins 78-12 & 12A re atypical weld matl in reactor pressure vessel welds. Weld matl info & other required info are included in CB&I 790424 rept.
NOON, F Westinghouse Electric Corp 79/05/23 2pp

7908030554 Responds to info forwarded in 790424, 0504 & 0620 ltrs re results of seismic piping stress reanalysis. Reanalysis techniques & results of reanalysis are acceptable. Forwards safety evaluation rept.
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/22 2pp

--7908030559 Safety evaluation re review of piping reanalysis. Reanalysis techniques & results of reanalysis are acceptable per IE Bulletin 79-07.
* Engineering Branch 79/06/22 2pp

7908150255 Forwards IE Insp Repts 50-315/79-16 & 50-316/79-09 on 790613. No noncompliance noted.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/25 2pp

DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2

9. Inspection reports, IE Bulletins & correspondence

7908150266 IE Insp Repts 50-315/79-16 & 50-316/79-09 on 790613 No noncompliance noted. Major areas inspected: licensee action on IE Circular 78-08.
JABLONSKI, F. J., HAYES, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/21. 3pp.

7908150280 Forwards IE Insp Rept 50-315/79-14 & 50-316/79-11 on 790529-0601 & notice of violation.
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/25. 2pp.

--7908150290 Notice of violation from insp on 790529-0601.
* Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/25. 1p.

--7908150346 IE Insp Repts 50-315/79-14 & 50-316/79-11 on 790529-0601. Noncompliance noted: inadequate air sampling & inadequate followup on whole body counting results.
SCHMACHER, M. C., FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/20. 8pp.

7908150357 Forwards IE Insp Repts 50-315/79-13 & 50-316/79-10 on 790505-31 & notice of violation.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/25. 2pp.

--7908150367 Notice of violation from insp on 790505-31.
* Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/25. 1p.

--7908150382 IE Insp Rept 50-315/79-13 & 50-316/79-10 on 790505-31. Noncompliance noted: failure to maintain or implement procedures & mod not revealed or approved by onsite review committee.
MASSE, R. E., BAKER, K. R., BOYD, D. C. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/21. 13pp.

7908030327 Submits status rept of licensee actions on TMI bulletins. Reactor presently shutdown for repairs to feedwater line cracks. Scheduled to restart this week.
WIGGINTON, D. Operating Reactors Branch 1. 79/06/28. 2pp.

7908160184 Ack receipt of 790601 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/79-05 & 50-316/79-05.
HEISHMAN, R. F. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/28. 1p.

--7908160193 Responds to NRC 790508 ltr re violations noted in IE Insp Repts 50-315/79-05 & 50-316/79-05. Corrective actions: issued temporary sheet on 790525 to eliminate requirement of logging fuses removed for short time period.
DOLAN, J. E. American Electric Power Co., Inc. 79/06/01. 3pp.

7908290520 Forwards IE Insp Repts 50-315/79-10 & 50-316/79-07 on 790521-24 & notice of violation.
FIORELI, I. G. Region 3, Chicago, Office of the Director. 79/07/03. 2pp.

--7908290523 Notice of violation from insp on 790521-24.
* Region 3, Chicago, Office of the Director. 79/07/03. 1p.

--7908290529 IE Insp Repts 50-315/79-10 & 50-316/79-07 on 790521-24. Noncompliance noted: failure to develop repair procedures prior to beginning of work.
KEY, W. J., DANIELSON, D. H. Region 3, Chicago, Office of the Director. 79/06/28. 4pp.

7908080366 Responds to 790522 ltr re IE Bulletin 79-11. Westinghouse DB-75 breakers are not used on safety-related Class IE circuits. Safety-related breakers shall be tested at each refueling outage.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/05. 2pp.

7908130403 Responds to IE Bulletin 79-02, Revision 1 re pipe support baseplate designs using concrete expansion anchor bolts. Teledyne Engineering Svcs 790629 generic program baseplate/expansion anchor studies encl.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/11. 10pp.

7908170464 Responds to IE Bulletin 79-13. Cracked feedwater elbows replaced, radiographed & found acceptable.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/20. 3pp.

7908240518 Submits suppl to 790501 ltr responding to IE Bulletin 79-06A, Revision 1, re instrumentation to recognize void formation in reactor coolant sys, containment isolation, operating procedure & training & valve lineup walkaround.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/25. 14pp.

7908290279 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300385 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908230132 Ack receipt of 790525 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-315/79-07 & 50-316/79-06.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/07/30. 1p.

--7908230138 Responds to NRC 790502 ltr re violation noted in IE Insp Repts 50-315/79-07 & 50-316/79-06. Special briefing sessions conducted & test drills undertaken re 20-ft isolation zone required when tanks are placed near security fence.
DOLAN, J. E. Indiana & Michigan Power Co. 79/05/25. 2pp.

7908150283 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908170017 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08. 1p.

7908300262 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908170341 Forwards monthly operating rept for Jul 1979.
SHALLER, D. V. Indiana & Michigan Power Co. 79/08/13. 1p.

--7908170343 Monthly operating rept for Jul 1979.
GILLETT, W. T. Indiana & Michigan Power Co. 79/08/07. 7pp.

S. Reportable occurrences, LERs & related correspondence

7908100029 Confirms 790608 telcon re potential safety hazard from deficiency identified in procedure to verify performance characteristics of Barton Lot 1 transmitters. List of affected plants encl. None in operation.
ANDERSON, T. M. Westinghouse Electric Corp. 79/06/11. 4pp.

7908030224 Forwards LER 79-023/03L-0.
SHALLER, D. V. Indiana & Michigan Power Co. 79/07/27. 1p.

--7908030234 LER 79-023/03L-0 on 790629 in Mode 4, during startup from cold shutdown, east engineered safety features ventilation sys fire protection spray for charcoal filter operated at 2,230. Caused by grounded manual actuation station.
MURPHY, C. E. Indiana & Michigan Power Co. 79/07/27. 1p.

7908060312 Forwards LERs 79-024/03L-0 & 79-025/03L-0.
SHALLER, D. V. Indiana & Michigan Power Co. 79/07/31. 1p.

--7908060316 LER 79-024/03L-0 on 790702: south boric acid storage tank & boron injection tank were out of spec while unit was in hot standby. Caused by normal fluctuation. Boric acid was transferred to tank.
MURPHY, C. E. Indiana & Michigan Power Co. 79/07/31. 1p.

--7908060325 LER 79-025/03L-0 on 790702: safety valve was lifted on Steam Generator 3, which brought reactor to sub-critical condition. Operation of safety valve was within allowed setpoints. Gag removed & high power trips reset.
MURPHY, C. E. Indiana & Michigan Power Co. 79/07/31. 1p.

7908140632 Forwards LER 79-025/03L-0.
SHALLER, D. V. Indiana & Michigan Power Co. 79/08/08. 1p.

DOCKETED ITEMS

--7908140637 LER 79-025/03L-0 on 790709 while reviewing axial power distribution monitoring sys printouts discovered two occasions in which results of only one detector scan printed out Cause under investigation.
RISCHLING, J. L. Indiana & Michigan Power Co. 79/08/08. 1p.

7908210511 Forwards LER 79-026/03L-0 & corrected copy of LER 79-025/03L-0.
SHALLER, D. V. Indiana & Michigan Power Co. 79/08/15. 1p.

--7908210521 LER 79-026/03L-0 on 790723 while studying computer printout for axial power distribution discovered one detector scan printed out Problem under investigation Operations personnel closely monitoring printouts.
RISCHLING, J. L. Indiana & Michigan Power Co. 79/08/08. 1p.

--7908210527 LER 79-027/03L-0 on 790723 previously issued as LER 79-025/03L-0 while reviewing computer printout discovered K 0900 address not reset to 0 prior to scanning core Temporary change sheet issued.
MURPHY, C. E. Indiana & Michigan Power Co. 79/08/15. 1p.

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

E. NRC Safety Evaluation Report (SER), supple & correspondence

7908210280 Supplements 790806 ltr re Secction 3.3 of draft SER Submits addl info on fire protection program re instrument air & rerouting Hydrogen piping.
GORE, J. W. Baltimore Gas & Electric Co. 79/08/17. 3pp.

F. Security, medical, emergency & fire protection plans

7908130065 Notifies that SER re fire protection cannot be completed unless util completes response to 790419 ltr Util must answer remaining open issues & identify positions for appeal.
FERGUSON, R. Plant Systems Branch. 79/06/28. 1p.

7908060162 Requests prompt forwarding of Class III fee for 790319 safeguards contingency plan.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908030146 Notification of 790711 meeting w/util in Bethesda, MD to discuss draft fire protection safety evaluation.
CONNOR, E. J. Operating Reactors Branch 4. 79/07/06. 2pp.

7908100205 Advises that util 790319 request for safeguards contingency plan fee approval consists of Class III & Class I amends for Units 1 & 2, respectively.
OLSON, R. C. Baltimore Gas & Electric Co. 79/07/12. 1p.

7908100592 Notification of 790724 meeting w/util in Bethesda, MD to discuss draft fire protection safety evaluation.
CONNER, E. L. Operating Reactors Branch 4. 79/07/19. 2pp.

7908170230 Notification of 790731 meeting w/util in Bethesda, MD to discuss draft fire protection safety evaluation.
CONNER, E. L. Operating Reactors Branch 4. 79/07/26. 1p.

7908100410 Forwards responses to NRC positions identified in Section 3.3 of draft safety evaluation re fire protection review. Oversized drawings available in Central Files only.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/08/06. 57pp.

7908140688 Forwards response to NRC draft safety evaluation rept Section 3.3 re fire protection program.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/08/06. 58pp.

7908210059 Submits facts re NRC policy concerning implementation of General Design Criterion 3 for fire protection. Urges maint of mods schedules for Oct 1980 Submittal of info re open items & design details should be expedited.
EISENHUT, D. G. Division of Operating Reactors. 79/08/09. 2pp.

7908200200 Forwards preliminary security training & qualification plan. Plan withheld (ref 10CFR2.790).
EVANS, V. R. Baltimore Gas & Electric Co. 79/08/17. 1p.

7908310396 Responds to requests for addl info re fire protection program Discusses hydraulic calculations re sprinkler sys & prelaid hose.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/08/29. 7pp.

I. Financial information

7908010535 Forwards info in support of Aug 1 annual submittal date for guarantee Info includes Annual Financial Rept 1978 to stockholders & projected cash flow for yr ending 800731.
POINDEXTER, C. H. Baltimore Gas & Electric Co. 79/07/25. 1p.

--7908010541 Extends thanks for 781004 comments suggesting mods to NRC Reg Guide 9.4 Guide is suggested format for cash flow projections Will consider util comments when revising guide.
SALTZMAN, J. Antitrust & Indemnity Group. 78/10/26. 1p.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908130359 Notifies all operating plants using C-E-designed reactors of generic review re TMI Requests attendance at 790612 meeting in Bethesda, MD re info needed by NRC to complete review.
STOLZ, J. F. Light Water Reactors Branch 1. 79/06/05. 16pp.

7908070424 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc Second line will be used to relay radiologic & environ data during emergencies Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/06/22. 3pp.

7908130649 Notifies that STS upgrade program will be exempted from fee in Classes I, II & III.
REID, R. W. Operating Reactors Branch 4. 79/07/05. 2pp.

7908140093 Responds to 790615 info request re emergency medical planning & procedures in event of nuclear accident.
EISENHUT, D. G. Division of Operating Reactors. 79/07/17. 2pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 58pp.

7908070227 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908100379 Notification of 790726 meeting w/util in Bethesda, MD to discuss plan to install reactor coolant pressure speed sensing sys for new reactor protection sys trip.
CONNER, E. L. Operating Reactors Branch 4. 79/07/19. 2pp.

7908220059 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition Current STS for all PWRs are ineffective re steam generator tube degradation Model license condition encl.
REID, R. W. Operating Reactors Branch 4. 79/07/23. 4pp.

7908280578 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition Current STS for all PWRs are ineffective re steam generator tube degradation Model license condition encl.
REID, R. W. Operating Reactors Branch 4. 79/07/23. 4pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908220590 Forwards "Notice of Consideration of Mod to Facilities Spent Fuel Storage Pool," filed w/FR.
REID, R. W. Operating Reactors Branch 4. 79/07/30. 2pp.

--7908220602 "Notice of Consideration of Proposed Mod to Facilities Spent Fuel Storage Pool."
REID, R. W. Operating Reactors Branch 4. 79/07/30. 4pp.

7908080498 Forwards requested info re fabrication history, inservice insp & operation & chemistry control for feedwater piping.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/07/31. 15pp.

7908080534 Forwards requested info re offsite mgt resources & offsite technical resources available to anticipate or respond to unusual events.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/07/31. 26pp.

7908090635 Forwards Amends 40 & 22 to licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability.
REID, R.W. Operating Reactors Branch 4 79/07/31 2pp.

--7908090642 Amends 40 & 22 to Licenses DPR-53 & DPR-69, respectively, changing App A Tech Specs of both units, to implement degraded grid voltage condition requirements & allow battery capacity testing during operation.
REID, R.W. Operating Reactors Branch 4 79/07/31 32pp.

--7908090645 Safety evaluation supporting Amends 40 & 22 to Licenses DPR-53 & DPR-69, respectively.
* Office of Nuclear Reactor Regulation 79/07/31 8pp.

--7908090689 Notice of issuance & availability of Amends 40 & 22 to Licenses DPR-53 & DPR-69, respectively.
REID, R.W. Operating Reactors Branch 4 79/07/31 2pp.

7908100458 Forwards proprietary & non-proprietary versions of Amend 1 to CEN-114, "Review of Small Break Transients in C-E NSSS."
LIEBLER, G.E. C-E Operating Plants Owners Group 79/08/03 6pp.

--7908100465 Amend 1-NP to CEN-114-NP, "Review of Small Break Transients in C-E NSSS." CEN-144-P withheld (ref 10CFR2.790).
* Combustion Engineering, Inc. CEN-114-P 79/07/31 1110pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D.G. Division of Operating Reactors 79/08/03 53pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908170428 Forwards CEN-114-NP, Amend 1, "Review of Small Break Transients in C-E Nuclear Steam Supply Sys." Proprietary version (CEN-114-P, withheld (ref 10CFR2.790).
SCHERER, A.E. C-E Power Systems 79/08/10 1p.

9. Inspection reports, IE Bulletins & correspondence

7907200082 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/05/31 1p.

7908020585 Notifies that C-E rept, info requested by IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessels," applies to facility C-E certification encl.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 79/06/18 4pp.

7908020228 Forwards addl response to IE Bulletin 79-01 Lists ASCO solenoids installed in containment of both units. Unacceptable equipment will be replaced as soon as possible.
BRYANT, J.C. Baltimore Gas & Electric Co. 79/06/26 4pp.

7908070665 Responds to IE Bulletin 70-02, Revision 1, re concrete expansion anchor bolts. Discusses status of pipe hanger analysis program, base plate flexibility, design requirements & safety factors of anchor bolts.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 79/07/06 8pp.

7908070806 Responds to IE Bulletin 79-04. Increased weights of Velan valves have no significant impact on overall stress calculations for piping involved.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 79/07/13 2pp.

7908070844 Responds to IE Bulletin 79-13 re adequacy of feedwater sys piping. Discusses extended schedule for radiographic insp of nozzle welds & feedwater piping welds inside containment. Requests info re acceptability of insp schedule.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 79/07/16 2pp.

7908170313 Provides supplemental responses to IE Bulletins 79-01 & 01A re use of ASCO solenoid valves. Valves are necessary to containment isolation & failure would have minimal adverse effects.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 79/07/16 3pp.

7908010421 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/17 1p.

7908020307 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT, K.V. Region 1, Philadelphia, Office of the Director 79/07/18 1p.

7908030226 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/19 1p.

7908290711 Responds to IE Bulletin 79-15 Facilities do not utilize deep draft pumps in safety-related applications.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 79/07/19 1p.

7908100215 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/26 1p.

7908100328 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/26 1p.

7908090283 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/07/30 1p.

7908200108 Responds to IE Bulletin 79-14 re description of plans for seismic analyses of as-built piping sys.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 79/07/31 5ipp.

7908270419 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/07 1p.

7908230293 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/08 1p.

7908270538 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/10 1p.

7908280248 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/13 1p.

7908310256 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/14 1p.

7908300105 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/15 1p.

7908280554 Discusses actions taken re requirements of IE Bulletin 79-06B & 06C. Provides documentation of procedural changes made to enhance core cooling should voids be formed & results of design review re containment isolation.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 79/08/20 4pp.

R. Periodic operating reports & related correspondence

7908230344 Forwards monthly operating rept for Jul 1979.
MERSON, S.D. Baltimore Gas & Electric Co. 79/08/15 1p.

--7908230349 Monthly operating rept for Jul 1979.
MERSON, S.D. Baltimore Gas & Electric Co. 79/08/15 17pp.

S. Reportable occurrences, LERs & related correspondence

7908100486 Forwards LER 79-024/04T-0.
RUSSELL, L.B. Baltimore Gas & Electric Co. 79/07/26 1p.

--7908100491 LER 79-024/04T-0 on 790712: while regenerating condensate deep bed demineralizer, caustic solution discharge occurred. Caused by equipment malfunction. Affected valve will be repaired.
EHERTS, R.F. Baltimore Gas & Electric Co. 79/07/26 2pp.

7908100500 Forwards LER 79-026/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/07/26 1p.

--7908100503 LER 79-026/03L-0 on 790719 water leak from cracked weld on reactor coolant charging pump discharge drain valve observed. Caused by crack in heat-affected zone of socket weld. Pump removed & cracked pipe spool replaced.
HEIBEL, R. P., MIERNICKI, M. J. Baltimore Gas & Electric Co. 79/07/19 1p.

7908070678 LER 79-031/01X-0 on 790731 undervoltage circuitry A-4 logic would not initiate & 15-volt power supplies to A & B actuation drawers were found de-energized. Cause & corrective action under investigation.
DENTON, H. R. Baltimore Gas & Electric Co. 79/08/01 2pp.

7908080509 Forwards LER 79-021/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/06 1p.

--7908080512 LER 79-021/03L-0 on 790708 containment gaseous radiation monitor indicated erroneously. Caused by detector tube failure. Detector repaired & returned to svc.
DAVIS, S. M., RIZZO, P. G. Baltimore Gas & Electric Co. 79/08/06 2pp.

7908200328 Forwards LER 79-023/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/10 1p.

--7908200333 LER 79-023/03L-0 on 790712 while withdrawing Group 1 control element assembly, position indication for assembly 65 stopped indicating outward motion at 42 inches. Caused by electronic failure of printed circuit board. Board replaced.
LAGIEWSKI, J. S. Baltimore Gas & Electric Co. 79/08/10. 8pp.

7908220385 Forwards LER 79-022/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/10 1p.

--7908220389 LER 79-022/03L-0 on 790712 reactor protective sys channel B T-hot fa[illegible] high, causing reactor trip. Caused by hot leg temp de[illegible] Failing open. Detector scheduled for replacem.
LAGIEWSKI, J. S., RIZZO, P. G. Baltimore Gas & Electric Co. 79/08/10 1p.

7908230383 Forwards LER 79-031/01T-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/14 1p.

--7908230386 LER 79-031/01T-0 on 790731 test on undervoltage circuitry after troubleshooting revealed that logic A-4 would not operate due to de-energized power supply. Caused by actuation of overvoltage protection circuit. Actuation readjusted.
DENTON, H. R., RIZZO, P. G. Baltimore Gas & Electric Co. 79/08/14. 2pp.

7908230518 Forwards LER 79-029/04T-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/15 1p.

--7908230530 LER 79-029/04T-0 on 790710 Camp Canoy 790613 samples showed higher than normal Ag-110 levels. Caused by introduction of more sensitive sampling technique.
EHERTS, R. F. Baltimore Gas & Electric Co. 79/07/23. 2pp.

7908230361 Forwards LER 79-033/04T-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/16. 1p.

--7908230366 LER 79-033/04T-0 on 790803 while regenerating makeup water mixed bed demineralizer, caustic solution discharged. Caused by operator error. Affected personnel reinstructed & definitive procedures promulgated.
EHERTS, R. F. Baltimore Gas & Electric Co. 79/08/16. 2pp.

7908270478 Forwards LER 79-025/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/17. 1p.

--7908270484 LER 79-025/03L-0 on 790719 reactor protection sys channel A T-cold input fluctuated. Cause suspected to be intermittently open temp element or connection at element. Repairs implemented.
RIZZO, P. G., HEIBEL, R. P. Baltimore Gas & Electric Co. 79/08/17. 1p.

7908280620 Forwards LER 79-027/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/17. 1p.

--7908280626 LER 79-027/03L-0 on 790719 metrascope position of control element assemblies was lost. Caused by faulty metrascope power supply. Faulty components replaced, setpoints calibr & alarms cleared.
HEIBEL, R. P., RIZZO, P. G. Baltimore Gas & Electric Co. 79/08/17. 2pp.

7908300624 LER 79-031/01X-0 on 790731 during normal operation, logic circuit A would not initiate when power supplies to actuation cabinet drawers were deenergized. Cause under investigation.
BENINN, R. Baltimore Gas & Electric Co. 79/08/17. 2pp.

7908280628 Forwards LER 79-030/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/23. 1p.

--7908280639 LER 79-030/03L-0 on 790728 water leak discovered on discharge isolation valve of reactor coolant charging pump. Caused by cracked repair weld on discharge isolation valve. Weld repaired using gas tungsten arc process.
LAGIEWSKI, J. S., MIERNICKI, M. J. Baltimore Gas & Electric Co. 79/08/23 2pp.

7908280675 Forwards LER 79-028/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/23. 1p.

--7908280682 LER 79-028/03L-0 on 790724 while operating diesel generator 11 for troubleshooting, smoke was noted coming from exciter control cabinet 1C61C. Caused by grounded primary winding in exciter potential transformer T-54.
LAGIEWSKI, J. S. Baltimore Gas & Electric Co. 79/08/23. 1p.

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

E. NRC Safety Evaluation Report (SER), suppls & correspondence

7908210280 Supplements 790806 ltr re Secction 3.3 of draft SER. Submits addl info on fire protection program re instrument air & rerouting Hydrogen piping.
GORE, J. W. Baltimore Gas & Electric Co. 79/08/17. 3pp.

F. Security, medical, emergency & fire protection plans

7908130065 Notifies that SER re fire protection cannot be completed unless util completes response to 790419 ltr. Util must answer remaining open issues & identify positions for appeal.
FERGUSON, R. Plant Systems Branch. 79/06/28. 1p.

7908060162 Requests prompt forwarding of Class III fee for 790319 safeguards contingency plan.
DIGGS, R. M. License Fee Management Branch. 79/07/03 2pp.

7908030146 Notification of 790711 meeting w/util in Bethesda, MD to discuss draft fire protection safety evaluation.
CONNOR, E. J. Operating Reactors Branch 4. 79/07/06 2pp.

7908100205 Advises that util 790319 request for safeguards contingency plan fee approval consists of Class III & Class I amends for Units 1 & 2, respectively.
OLSON, R. C. Baltimore Gas & Electric Co. 79/07/12. 1p.

7908100592 Notification of 790724 meeting w/util in Bethesda, MD to discuss draft fire protection safety evaluation.
CONNER, E. L. Operating Reactors Branch 4. 79/07/19. 2pp.

7908170230 Notification of 790731 meeting w/util in Bethesda, MD to discuss draft fire protection safety evaluation.
CONNER, E. L. Operating Reactors Branch 4. 79/07/26. 1p.

7908100410 Forwards responses to NRC positions identified in Section 3.3 of draft safety evaluation re fire protection review. Oversized drawings available in Central Files only.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/08/06. 57pp.

7908140688 Forwards response to NRC draft safety evaluation rept Section 3.3 re fire protection program.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/08/06. 58pp.

7908210039 Submits facts re NRC policy concerning implementation of General Design Criterion 3 for fire protection. Urges maint of mods schedules for Oct 1980. Submittal of info re open items & design details should be expedited.
EISENHUT, D. G. Division of Operating Reactors. 79/08/09. 2pp.

7908310396 Responds to requests for addl info re fire protection program. Discusses hydraulic calculations re sprinkler sys & prelaid hose.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/08/29. 7pp.

I. Financial information

7908010535 Forwards info in support of Aug 1 annual submittal date for guarantee. Info includes Annual Financial Rept 1978 to stockholders & projected cash flow for yr ending 800731.
POINDEXTER, C. H. Baltimore Gas & Electric Co. 79/07/25. 1p.

--7908010541 Extends thanks for 781004 comments suggesting mods to NRC Reg Guide 9.4 Guide is suggested format for cash flow projections Will consider util comments when revising guide.
SALTZMAN, J. Antitrust & Indemnity Group 78/10/26 1p

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp

7908130359 Notifies all operating plants using C-E-designed reactors of generic review re TMI Requests attendance at 790612 meeting in Bethesda, MD re info needed by NRC to complete review.
STOLZ, J. F. Light Water Reactors Branch 1 79/06/05 16pp

7908070424 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp

7908130649 Notifies that STS upgrade program will be exempted from fee in Classes I, II & III.
REID, R. W. Operating Reactors Branch 4 79/07/05 2pp

7908140093 Responds to 790615 info request re emergency medical planning & procedures in event of nuclear accident.
EISENHUT, D. G. Division of Operating Reactors 79/07/17 2pp

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/18 58pp

7908070227 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908100379 Notification of 790726 meeting w/util in Bethesda, MD to discuss plan to install reactor coolant pressure speed sensing sys for new reactor protection sys trip.
CONNER, E. L. Operating Reactors Branch 4 79/07/19 2pp

7908220059 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
REID, R. W. Operating Reactors Branch 4 79/07/23 4pp

7908280578 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
REID, R. W. Operating Reactors Branch 4 79/07/23 4pp

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p

7908220590 Forwards "Notice of Consideration of Mod to Facilities Spent Fuel Storage Pool," filed w/FR.
REID, R. W. Operating Reactors Branch 4 79/07/30 2pp

--7908220602 "Notice of Consideration of Proposed Mod to Facilities Spent Fuel Storage Pool."
REID, R. W. Operating Reactors Branch 4 79/07/30 4pp

7908080498 Forwards requested info re fabrication history, inservice insp & operation & chemistry control for feedwater piping.
LUNDVALL, A. E. Baltimore Gas & Electric Co 79/07/31 15pp

7908080534 Forwards requested info re offsite mgt resources & offsite technical resources available to anticipate or respond to unusual events.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/07/31 26pp

7908090635 Forwards Amends 40 & 22 to licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4 79/07/31 2pp

--7908090642 Amends 40 & 22 to Licenses DPR-53 & DPR-69, respectively, changing App A Tech Specs of both units to implement degraded grid voltage condition requirements & allow battery capacity testing during operation.
REID, R. W. Operating Reactors Branch 4 79/07/31 32pp

--7908090645 Safety evaluation supporting Amends 40 & 22 to Licenses DPR-53 & DPR-69, respectively.
* Office of Nuclear Reactor Regulation 79/07/31 8pp

--7908090689 Notice of issuance & availability of Amends 40 & 22 to Licenses DPR-53 & DPR-69, respectively.
REID, R. W. Operating Reactors Branch 4 79/07/31 2pp

7908100458 Forwards proprietary & non-proprietary versions of Amend 1 to CEN-114, "Review of Small Break Transients in C-E NSSS."
LIEBLER, G. E. C-E Operating Plants Owners Group 79/08/03 6pp

--7908100465 Amend 1-NP to CEN-114-NP, "Review of Small Break Transients in C-E NSSS." CEN-144-P withheld (ref 10CFR2.790).
* Combustion Engineering, Inc. CEN-114-P 79/07/31 1110pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908170428 Forwards CEN-114-NP Amend 1, "Review of Small Break Transients in C-E Nuclear Steam Supply Sys." Proprietary version, CEN-114-P withheld (ref 10CFR2.790).
SCHERE, A. E. C-E Power Systems 79/08/10 1p

7908300474 Requests amend to License DPR-69 to modify Tech Specs to include measurement-calculational uncertainties of 6% & 7%.
LUNDWALL, A. E. Baltimore Gas & Electric Co. 79/08/27 3pp

G. Inspection reports, IE Bulletins & correspondence

7907200082 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/05/31 1p

7908020585 Notifies that C-E rept. info requested by IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessels," applies to facility. C-E certification encl.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/06/18 4pp

7908020228 Forwards addl response to IE Bulletin 79-01 Lists ASCO solenoids installed in containment of both units. Unacceptable equipment will be replaced as soon as possible.
BRYANT, J. C. Baltimore Gas & Electric Co. 79/06/26 4pp

7908070665 Responds to IE Bulletin 70-02, Revision 1, re concrete expansion anchor bolts. Discusses status of pipe hanger analysis program, base plate flexibility, design requirements & safety factors of anchor bolts.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/07/06 8pp

7908070806 Responds to IE Bulletin 79-04. Increased weights of Velan valves have no significant impact on overall stress calculations for piping involved.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/07/13 2pp

7908070844 Responds to IE Bulletin 79-13 re adequacy of feedwater sys piping. Discusses extended schedule for radiographic insp of nozzle welds & feedwater piping welds inside containment. Requests info re acceptability of insp schedule.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/07/16 2pp

7908170313 Provides supplemental responses to IE Bulletins 79-01 & 01A re use of ASCO solenoid valves. Valves are necessary to containment isolation & failure would have minimal adverse effects.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/07/16 3pp

7908010421 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908020307 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
BEYRIT, K. V. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030226 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908290711 Responds to IE Bulletin 79-15. Facilities do not utilize deep draft pumps in safety-related applications.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/07/19. 1p.

7908100215 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908100329 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908090283 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908200108 Responds to IE Bulletin 79-14 re description of plans for seismic analyses of as-built piping sys.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/07/31. 5lop.

7908270419 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908230293 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/08. 1p.

7908270538 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/10. 1p.

7908280248 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908[illegible] Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300105 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

7908280554 Discusses actions taken re requirements of IE Bulletin 79-06B & 06C. Provides documentation of procedural changes made to enhance core cooling should voids be formed & results of design review re containment isolation.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/08/20. 4pp.

R. Periodic operating reports & related correspondence

7908230344 Forwards monthly operating rept for Jul 1979.
MERSON, S. D. Baltimore Gas & Electric Co. 79/08/15. 1p.

--7908230349 Monthly operating rept for Jul 1979.
MERSON, S. D. Baltimore Gas & Electric Co. 79/08/15. 17pp.

S. Reportable occurrences, LERs & related correspondence

7908080450 Forwards LER 79-025/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/03. 1p.

--7908080457 LER 79-025/03L-0 on 790704 during routine surveillance test, control element assemblies 22 & 62 failed to initiate motion inhibit signal. Caused by motion inhibit setpoint voltage level drifting from set actuation level. New setpoints made.
DAVIS, S. M., RIZZO, P. G. Baltimore Gas & Electric Co. 79/08/03. 2pp.

7908230518 Forwards LER 79-029/04T-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/15. 1p.

--7908230530 LER 79-029/04T-0 on 790710: Camp Conoy 790613 samples showed higher than normal Ag-110 levels. Caused by introduction of more sensitive sampling technique.
EHERTS, R. F. Baltimore Gas & Electric Co. 79/07/23. 2pp.

7908230500 Forwards LER 79-026/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/17. 1p.

--7908230513 LER 79-026/03L-0 on 790717: periodic water inventory check revealed coolant leakage greater than 1 g/minute. Caused by leaking reactor coolant pump middle seal pressure transmitter. Transmitter isolated & replaced.
HEIBEL, R. P., RIZZO, P. G. Baltimore Gas & Electric Co. 79/08/17. 1p.

7908270476 Forwards LER 79-027/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 79/08/17. 1p.

--7908270485 LER 79-027/03L-0 on 790718 channel C trips were received from power level-thermal margin-low pressure & axial flux offset. Cause of intermittent problem is suspected to be loose connection or faulty switch circuit.
HEIBEL, R. P., RIZZO, P. G. Baltimore Gas & Electric Co. 79/08/17. 2pp.

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908210197 "Selection & Procurement of Pressure Relief Valves for Light Water Cooled Nuclear Reactor Sys," prepared w/MPR Associates, Inc.
* Oak Ridge National Laboratory W-7405-ENG26. 72/06/30. 96pp.

7908210186 Forwards "Monitoring Post-Accident Conditions in Power Reactors."
DENNING, R. S. Battelle Memorial Institute, Columbus Laboratories. 73/04/09. 1p.

--7908210193 "Monitoring Post-Accident Conditions in Power Reactors."
DENNING, R. S., MILLER, N. E., PLUMMER, A. M. Battelle Memorial Institute, Columbus Laboratories. 73/04/09. 76pp.

7908210201 Draft 2 of "NRC Incident Response."
GRIMES, B. K. Assistant Director for Systems Engineering, BRYAN, S. Division of Reactor Operations Inspections. 79/07/23. 128pp.

7908220068 Responds to 790625 request for documents re uncertainty in calculations of accident probabilities & consequences. Forwards list of documents subject to request. Discusses FOIA procedures.
FELTON, J. M. Division of Rules and Records. 79/08/20. 6pp.

--7908220071 Notes re TMI-2 aircraft risk. "Review of Methods of Uncertainty Estimation of Estimators, W/Application to SRP Estimators."
READ, J. Division of Site Safety & Environmental Analysis. 76/12/31. 19pp.

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7904270395 Notifies that copies of TMI FES (NUREG-0552) & suppl will be back from printer & ready for distribution on 790410.
BESAW, W. J. Division of Technical Information & Document Control. 79/04/10. 1p.

F. Security, medical, emergency & fire protection plans

7908210475 Responds to request made during 790515 meeting of NRC subcommittee task force. Submits info on operators manual emergency procedures re thermocouples.
MACMILLAN, J. H. Babcock & Wilcox Co. 79/05/21. 10pp.

7908130195 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908170354 Forwards proprietary version of "TMI Guard Force Training & Qualification Plan." Plan withheld (ref 10CFR2.790).
HERBEIN, J. G. Metropolitan Edison Co. 79/08/15. 1p.

G. Adjudicatory correspondence

7908220087 Forwards, for info, 790608 note to files re TMI.
CHANDLER, L. J. Branch 1. 79/06/08. 1p.

--7908220093 Note re A Rosenthal 790507 request for info concerning emergency planning. Requests info as to acceptability of of plan.
CHANDLER, L. J. Branch 1. 79/06/08. 1p.

7908150492 Ack receipt of 790510 ltr expressing concern re nuclear power. Every effort is being made to ensure protection of public health & safety.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/29. 2pp.

--7908150494 Demands immediate nuclear moratorium & shutdown of all nuclear plants. Suggests solar power as answer to world energy crises. Expresses concern re TMI-2 evacuation.
JADERNAK, M.; DAY, M.; GIORGI, J. Affiliation Unknown. 79/05/10. 1p.

7908150740 Ack request to be apprised of hearings & legal actions re TMI-1 restart. Forwards NRC 790702 order requiring that facility remain shut down until further order & that public hearings be held.
CUNNINGHAM, G. H. Branch 2. 79/07/05. 2pp.

7908150477 Forward petitions requesting public hearings re TMI-2 event. Petitions are being treated under 10CFR 206. Also forwards FR notice.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/06. 3pp.

--7908150483 Request for emergency action by NRC to hold public hearings prior to activation of any plans to modify operational status not in accordance w/Tech Specs.
KEPFORD, C. Affiliation Unknown. 79/04/27. 5pp.

--7908150485 Supplements 790427 request for public hearings.
KEPFORD, C. Affiliation Unknown. 79/05/26. 9pp.

--7908150488 FR notice of request for action under 10CFR2.206. C Kepford 790427 & 0516 petitions requesting public hearings re TMI-2 have been received.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/06. 1p.

7908150764 Notice of Environ Coalition on Nuclear Power request for action under 10CFR2.206 to institute hearings re TMI-2 event.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/06. 1p.

--7908150769 Requests immediate action to hold public hearings before any alteration of TMI-2 operational status not in accordance w/Tech Specs.
KEPFORD, C. Environmental Coalition on Nuclear Power. 79/05/16. 14pp.

7908150750 Forwards draft order specifying bases for NRC concerns & procedures to govern hearing to be held prior to TMI-1 restart.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/20. 1p.

--7908150753 Draft order specifying basis for NRC concerns & procedures to govern further proceedings.
* Office of Nuclear Reactor Regulation. 79/07/20. 8pp.

7908150752 Responds to 790629 request for show cause hearing to revoke TMI-1 OL. NRC has ordered plant shutdown until further order. License revocation would be premature.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/20. 2pp.

7908240154 Submits NRC responses to interrogatories submitted by Susquehanna Valley Alliance.
COLLINS, J. T. TMI-2 Operations/Support. 79/07/30. 37pp.

7908210406 Strongly opposes release of radwaste into atmosphere.
DRAZ, Z. The Tribune Chronicle, Warren, OH. 79/08/14. 1p.

7908210400 Reminds NRC of Anti-Nuclear Group Representing York (ANGRY) 790809 petition requesting EIS prior to restart of unit. Requests assurance that no radioactive releases will be permitted until issue is resolved.
BOWERS, J. Anti-Nuclear Group Representing York. 79/08/17. 1p.

--7908210404 Petition by Anti-Nuclear Group Representing York (ANGRY) requesting preparation of EIS prior to release of radioactive gases from plant.
BOWERS, J. Anti-Nuclear Group Representing York. BRADFORD, G. Affiliation Unknown. 79/08/09. 3pp.

H. General correspondence

7908240229 Summary of FBI contacts re TMI incident. Info partially withheld: names of individuals (ref FOIA Exemption 7.)
BAIR, P. Executive Officer for Operations Support. 79/04/07. 2pp.

7908210210 Requests info on cause & control of TMI accident, conduct of emergency actions & activities of agency in investigating & modifying accident potential of other plants.
DEMLOW, D. J. Michigan, State of. 79/04/09. 1p.

7908210091 Discusses 790510 field trip to Philadelphia, PA. Parents wish info re air quality safety as result of TMI accident.
JULIANO, D. P. New York, NY. 79/04/10. 1p.

7905080181 Forwards notice of 791205-07 meeting of IAEA in West Germany to discuss procedures & sys for assisting operator during normal & anomalous operation.
EISENHUT, D. G. Assistant Director for Systems Engineering. 79/04/19. 8pp.

7908230351 Lists documents to be forwarded per telcon request. Includes "Principle NRC Staff Involved in TMI Operations" & "TMI Recovery Operation - Support Organizations." Estimates on total population radiation doses encl.
CORNELL, E. K. Office of the Executive Director for Operations. 79/04/25. 4pp.

7905070024 Forwards description of procedures for handling documents related to TMI-2 incident.
VANBENBERG, L. Office of Management and Program Analysis. 79/04/26. 8pp.

7908210128 Forwards Sandia Labs correspondence to NRC re assistance given during TMI. Info includes type of assistance, names of personnel & results of work done.
CORDOVA, G. E. Energy, Dept. of. 79/05/22. 11pp.

7908210427 Discusses actions taken to ensure continued health & safety of public around nuclear power plants. Full-time inspectors have been assigned to plants using B&W reactors. Operating procedures have been revised.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/25. 1p.

7908210481 Discusses actions taken to ensure continued health & safety of public around nuclear power plants. Full-time inspectors have been assigned to plants using B&W reactors. Operating procedures have been revised.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/25. 1p.

7908230014 Forwards NUREG-0557, "Evaluation of Long-Term Post-Accident Core Cooling of TMI." W/o encl.
CHANDLER, L. J. Branch 1. 79/05/29. 1p.

7906280056 Requests 790606 submission of ideas re change of regulatory requirements to be incorporated in TMI-2 Lessons Learned Task Force charter.
MATTSON, R. J. Division of Systems Safety. 79/05/31. 3pp.

7908010272 Board notification: "Post-TMI Task Force." Distribution list for all licensing & appeal boards encl.
CHRISTENBURY, E. Office of the General Counsel. 79/06/06. 23pp.

7908010616 Forwards statement of policy on licensing, based on review of NRC 790530 meeting transcript.
BICKWIT, L. Office of the General Counsel. 79/06/06. 4pp.

7908210171 Responds to 790420 & 0509 ltrs re use of digital computers to monitor sys & components. More research is being done.
MATTSON, R. J. Division of Systems Safety. 79/06/06. 9pp.

--7908210174 Forwards RF Saxe 790420 ltr to JM Hendrie.
SAXE, R. F. North Carolina State Univ. 79/05/09. 1p.

--7908210181 Discusses use of digital computers to monitor sys & components. Availability of small cheap minicomputers makes it imperative to install sys in each plant.
SAXE, R. F. North Carolina State Univ. 79/04/20. 2pp.

7907160257 Submits written record of 790510-25 actions re TMI event: assigned to environ section, performed ground surveys, collected air, soil, vegetation & milk samples.
WOODRUFF, R. L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/15. 2pp.

7908230449 Responds to 790514 ltr to Chairman Hendrie expressing concern about release of water from TMI nuclear power plant to Susquehanna River. Assures of thorough safety review, environ assessment & consideration of public health.
DENTON, H. R. Office of Nuclear Reactor Regulation. 78/06/15. 2pp.

--7908230455 Urges prevention of dumping of water from TMI nuclear power plant into Susquehanna River. Expresses concern for public water supply.
WOHLSEN, A. B. Pennsylvania, State of. 79/05/14. 1p.

7907160262 Submits written record of 790421-30 actions re TMI event assigned to health physics group, performed surveys, collected air samples, observed solid waste handling & filter tests.
NORTH, H. S. Region 5, San Francisco, Office of the Director. 79/06/19. 2pp.

7908150748 Responds to 790409 ltr re NRC surveillance over nuclear plants in FL. Facilities are meeting requirements stated in IE Bulletins re TMI-2 event. Forwards summary of actions taken at plants as result of TMI-2.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/06/25. 4pp.

--7908150751 Expresses concern re release of radioactive gases into environ & safety of major population & tourist ctrs. Urges constant surveillance over plant operations & careful safety review.
GUNTER, B. Florida, State of. 79/04/09. 1p.

7908150771 Requests summary data re releases of radioactive matls & regulatory requirements.
LUNDIN, B. T. President's Commission on the Accident at Three Mile Island. 79/06/28. 1p.

7908220067 Forwards summary of results of investigation re possible matl substitution in tank at TMI.
THORNBURG, H. D. Division of Reactor Construction Inspection. 79/07/02. 4pp.

7908150745 Discusses supplemental info from Canada re use of TLDs as noble gas effluent monitors for power reactors.
BUCHANAN, J. D. Environ Protect Standards Branch. 79/07/07. 3pp.

7908150733 Forwards rept re util decision to place TMI-2 into operation to gain tax advantages despite history of malfunctions.
TOOR, H. M. Critical Mass Energy Project. 79/07/09. 2pp.

--7908150735 "Death & Taxes An Investigation of the Initial Operation of TMI-2."
BANCROFT, M. H., STULBERG, R. B., MCINTYRE, R. Public Citizen Litigation Group. 79/04/05. 30pp.

7908150724 Responds to 790705 request for generic repts developed during studies related to TMI-2. Forwards NUREG-0560, B&W generic study. Westinghouse, C-E & generic repts will be sent when complete.
HELTEMES, C. J. Standardization Branch. 79/07/12. 1p.

7908150767 Recommends creation of organizational unit to take responsibility re design features to improve operator response.
CHECK, P. S. Reactor Safety Branch. 79/07/16. 1p.

7908150726 Responds to 790525 questions re TMI-2 event. Discusses potential damage from hydrogen explosion & meltdown prevention after core exposure.
SCHROEDER, F. Division of Systems Safety. 79/07/17. 4pp.

7908150731 Responds to request for info. Discusses TMI production capacity & costs.
SELLS, D. E. Division of Site Safety & Environmental Analysis. 79/07/19. 1p.

7908150746 Responds to encl 790620 ltr forwarding Wayne County Board of Commissioners resolution urging stricter nuclear safety stds & licensing. Every effort is being made to ensure continued protection of health & safety.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/19. 5pp.

7908150763 Responds to request for summary data re releases of radioactive matls from nuclear plants. Forwards NUREG-0521, review of 1968-78 LERs & overview of history of regulatory effluent limitations.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/23. 21pp.

7908150449 Responds to 790518 ltr expressing concern re site flooding. Discusses NRC flood risk assessment methodology. Estimate of PMF is adequately conservative. NRC does not require alternate site consideration.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/26. 4p.

--7908150463 Expresses concern re TMI flood risk. Requests info re NRC flood risk assessment methodology. Suggests Hill Island as a safer alternative site. Forwards related journal articles.
WALLIS, J. R. American Geophysical Union. 79/05/18. 24pp.

--7908150466 "Quantile Estimation W/More or Less Flood-Like Distributions."
LANDWEHR, J. M., MATALAS, N. C. Interior, Dept. of, U.S. Geological Survey, WALLIS, J. R. IBM Corp. 79/04/27. 34pp.

7908080016 Responds to 790417 ltr re licensing procedures. Discusses phases of reactor licensing process & factors impinging on resumption of operation of plant, following TMI-type incident.
VARGA, S. A. Assistant Director for Light Water Reactors. 79/07/27. 1p.

--7908080017 Requests info re procedure for util to obtain license & procedure for reopening following TMI-type incident.
GODWIN, T. Affiliation Unknown. 79/04/17. 1p.

7908150729 Forwards requested background info re loop seals in pressurizer surge line. Effect of seals on pressurizer level indications studied as generic technical matter in 1977. Manometer effect could occur during some transients.
REHM, T. A. Office of the Executive Director for Operations. 79/07/27. 2pp.

7908220148 Forwards documents requested in 790724 telcon re NRC actions taken or planned as result of TMI incident.
MATTSON, R. J. TMI-2 Lessons Learned Task Force. 79/07/31. 3pp.

7908090381 Responds to 790727 request. Forwards revised organization charts describing onsite organization for operation & radioactive waste mgt & offsite organization of mgt & technical support.
HERBEIN, J. G. Metropolitan Edison Co. 79/08/06. 5pp.

7908220010 Submits response to NRC 790629 ltr requesting details of licensee mgt/technical resource organization. Response to NRC 790724 ltr will be submitted under separate cover. Descriptive documentation encl.
HERBEIN, J. G. Metropolitan Edison Co. 79/08/06. 170pp.

7908140515 Advises that RC Arnold has been named senior vice president of util & will retain present position of vice president of GPU Svc Corp.
CREITZ, W. M. Metropolitan Edison Co. 79/08/09. 2pp.

7908310451 Forwards BT Elkins 790508 FOIA request to DOE for all info re TMI accident. Requests review of documents discovered while initially responding to FOIA request to determine if releasable. Direct reply requested to Elkins.
RUDOLPH, J. E. Energy, Dept. of. 79/08/14. 2pp.

7908220257 Discusses NUREG-0564. Advocates caution & questions lack of attention to assignment of probabilities to severe accidents re TMI.
SPALLONE, K. Affiliation Unknown. 79/08/16. 5pp.

7908310469 Responds to 790508 FOIA request for documents re TMI. Approves request & forwards documents.
FELTON, J. M. Division of Rules and Records. 79/08/22. 1p.

J. Insurance & indemnity information

7907260154 Provides info re Price-Anderson Act, in response to J Estes 790509 request.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/06/15. 3pp.

7908010491 Forwards complaints filed in US District Court for Middle District of PA. Cases include Park vs Met Ed, CA 79-906, Mars vs Met Ed, CA 79-912 & Ward vs Met Ed, CA 79-769.
CARRIER, W. C. American Nuclear Insurers. 79/07/26. 40pp.

7908200247 Forwards Endorsement 39 to ANI Policy NF-220.
GERRETY, H. F. GPU Service Corp. 79/08/13. 2pp.

7908220289 Forwards complaint, "Jankovic vs Met Ed," CA 79-994. Notifies of suits dropped as result of class action complaint consolidation. Forwards rept re socioeconomic study conducted by State of PA.
CARRIER, W. C. American Nuclear Insurers. 79/08/17. 21pp.

O. Advisory Committee on Reactor Safeguards reports & correspondence

7906290039 Submits revised agenda for ACRS Subcommittee on TMI-2 Accident Implications 790531-0601 meeting.
HELTEMES, C. J. Standardization Branch. 79/05/25. 2pp.

--7906290049 Forwards revised schedule for ACRS Subcommittee on TMI-2 Accident 790531-0601 meeting.
MAJOR, R. K. ACRS - Advisory Committee on Reactor Safeguards.
79/05/25 4pp.

7908210327 Forwards matl from TMI Accident Implications Subcommittee meeting W/o encl.
MAJOR, R. K. ACRS - Advisory Committee on Reactor Safeguards.
79/05/30 2pp.

7908230318 Forwards info re significant ACRS recommendations in 14 areas which were made on non-B&W plants prior to 790328, in response to 790619 ltr W/o encl.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards.
79/07/25 2pp.

7908030393 Forwards response to 790524 request to provide NRC w/concise discussion & position on each specified ACRS recommendation re TMI-2 incident. Info will be used for NRC discussions in ACRS subcommittee & full committee meetings on TMI-2.
BUCHHOLZ, R. H. General Electric Co., Nuclear Energy Products Div.
79/07/27 17pp.

P Operating license stage documents & correspondence.

7908230469 "Human Engineering of Nuclear Power Plant Control Rooms & Its Effects on Operator Performance." Prepared for NRC.
FINLAYSON, F. C., HUSSMAN, T. A., SMITH, K. R. Aerospace Corp.
AT(49-24)-0216 77/02/28 189pp.

7906150423 Statement by GP Miller, station manager, re 790328 TMI incident.
MILLER, G. P. Metropolitan Edison Co. 79/03/28 32pp.

7906060035 Forwards 790401-03 transcripts of interviews w/TMI operators.
* Office of Inspection & Enforcement, Office of the Director.
79/04/03 130pp.

7904260285 Concurs w/draft commission info paper transmitted in 790410 memo. Accessioned documents & title lists promised cannot be provided before 790601.
BESAW, W. J. Division of Technical Information & Document Control.
79/04/11 1p.

7904270035 Forwards request for info re lessons learned from TMI-2 incident. Specific areas to be addressed include meteorological data, available models for dose calculations & availability of plant & regional base info.
DENISE, R. P. Assistant Director for Site Technology. 79/04/13.
2pp.

7906060001 Notifies that tape recorder malfunctioned during 790411-12 interview session & NRC unable to provide transcripts.
MARSH, R. J. Office of Inspection & Enforcement, Office of the Director. 79/04/19 1p.

7906060006 Notifies that tape recorder malfunctioned during 790411-12 interview session, & NRC unable to provide transcripts of session.
MARSH, R. J. Office of Inspection & Enforcement, Office of the Director. 79/04/19 1p.

7906060009 Requests information in connection with IE investigation.
MARSH, R. J. Office of Inspection & Enforcement, Office of the Director. 79/04/20 1p.

7908230008 Forwards requested summary of telcon.
SCHWARZ, H. A. Brookhaven National Laboratory. 79/04/24 4pp.

7908210220 Responds to 790418 ltr re U Mills Tailings Radiation Control Act of 1978. NRC will consider matter in near future.
ENGELHARDT, T. F. Deputy Executive Legal Director. 79/04/30 1p.

--7908210229 Comments on U Mills Tailings Radiation Control Act of 1978. most consistent interpretation provides that no NRC tailings license is required for 3 yrs & defers imposition of new requirements for 3 yrs.
LYNCH, D. A. US Steel Corp. 79/04/18 3pp.

7906210438 Discusses 790425 & 0502 meetings re duplication of Metropolitan Edison repts.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/05/02 14pp.

7906210445 Procedures for interviews by NRC investigation team.
MARTIN, B. Office of Inspection & Enforcement, Office of the Director. 79/05/06 3pp.

7906210425 Submits TMI accident events & related interviews.
MARTIN, B. Division of Systems Safety. 79/05/08 10pp.

7908240036 Forwards schedule & scope of TMI radiological investigation.
ALLEN, J. M. Region 1, Philadelphia, Office of the Director.
79/05/08 3pp.

7906210430 Submits master documents & info requested by NRC investigation team.
* Commission. 79/05/09 1p.

7908280003 Discusses inaccuracy in 790508 New York Times article reporting visit of Udall subcommittee to TMI.
DIECHAMP, H. General Public Utilities 79/05/09 2pp.

7906210429 Forwards transcripts of taped interviews W/o encl.
SHACKLETON, D. C. Region 1, Philadelphia, Office of the Director.
79/05/16 1p.

7906210442 Forwards interim sequence of operating events re TMI-2 incident, as of 790508.
DAVIS, J. G. Office of Inspection & Enforcement, Office of the Director. 79/05/16 49pp.

7906210444 Reviews interview transcripts.
GIBSON, A. F. Region 1, Philadelphia, Office of the Director.
79/05/16 5pp.

7906210440 Discusses notebook missing at TMI.
SHACKLETON, D. C. Region 1, Philadelphia, Office of the Director.
79/05/17 2pp.

7906210432 Lists transcripts provided to IE headquarters. Info partially withheld: name of individual (ref FOIA Exemption 7).
GIBSON, A. F. Region 1, Philadelphia, Office of the Director.
79/05/23 5pp.

7908210142 Provides addl info re analysis of samples of charcoal filters performed by Naval Research Lab. Forwards Q Oertel 790517 memo.
MYERS, S. Energy, Dept of. 79/05/23 3pp.

7908220097 Forwards Atomic Energy Control Board news releases 79-7 & 79-9 & responses by licensees re TMI incident.
JENNEKENS, J. H. Canada, Atomic Energy Control Board. 79/05/23.
166pp.

7908220165 Forwards CEA draft of Vol 3 of rept on TMI.
BERESOVSKI, T. State, Dept of. 79/05/23 1p.

--7908220171 Draft "Rept on Mission to States by B Roche & A Cayol From 790401-06 on Accident of TMI."
* State, Dept of. 79/05/23 42pp.

7906210434 Evaluates denial of interview.
MARSH, R., YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/05/24 5pp.

7908210149 Responds to request made by President's Commission on TMI re emergency response. Naval reactors program provided assistance to Commonwealth of PA, NRC & General Public Util.
RICKOVER, H. G. Energy, Dept of. 79/05/24 10pp.

7908210110 Responds to 790515 telegram re TMI support. All assistance in support of accident was in direct support of emergency action coordination team.
GATES, M. E. Energy, Dept of. 79/05/25 1p.

7908210157 Responds to 790515 teletype re assistance given during TMI. Describes activities in meteorology, analytical & health protection assistance.
STETSON, D. Energy, Dept of, Savannah River Operations. 79/05/25
4pp.

--7908210166 Forwards results of analyses on sample of primary coolant water from TMI. Tests analyzed presence of elements.
OVERMAN, R. F. E. I. du Pont de Nemours & Co., Inc. 79/05/07 5pp.

7908210383 Responds to 790515 telegram re assistance given to NRC, Commonwealth of PA or util. Provided air distribution manifolds & reactor physics calculations.
STANDERFER, F. R. Energy, Dept of. 79/05/25 3pp.

7908210501 Responds to 790515 telegram re involvement in TMI. Activities included advising on decontamination & other radioactive matl situations, analysis of signal noise & dissemination of info to media.
LENHARD, J. A. Oak Ridge National Laboratory. 79/05/25 116pp.

7908210113 Responds to May 1979 telegram.EG&G, Inc continues to provide assistance to NRC re TMI accident.Forwards chart of activities funded through NRC programs.
WILLIAMS, C.F. Energy, Dept of. 79/05/27. 4pp.

7908230006 Forwards repts re oxygen & hydrogen production & recombination for TMI-2, in response to Gilinsky questions. Concludes that deflagration is more probable than detonation but neither is likely under TMI conditions.W/o encl.
KELBER, C.N. Assistant Director for Advanced Reactor Safety Research. 79/05/29. 1p.

7908230011 Requests current calculation of hydrogen/oxygen generation rate during incident.
GILINSKY, V. Commission. 79/05/29. 1p.

7908150761 Summary of 790521 meeting re Exxon role in TMI-related re-evaluations of operating plants.
KANE, W. Standardization Branch. 79/05/31. 4pp.

7908150582 Ack receipt of 790418 ltr re possible matl substitution for tank at TMI. Cognizant field ofc will investigate & forward rept when complete.
THORNBURG, H.D. Division of Reactor Construction Inspection. 79/06/01. 2pp.

7908150762 Notifies of typographical errors in licensee joint motion for summary disposition of radon issues.Certificate of Svc encl.
SILBERG, J.E. Shaw, Pittman, Potts, & Trowbridge. 79/06/05. 9pp.

7908210121 Responds to request by President's Commission on TMI. Forwards internal memos describing involvement in TMI activities.
BAUER, R.H. Energy, Dept of. 79/06/06. 16pp.

7908160556 Discusses mutual objectives of Nuclear Safety Analysis Ctr study of TMI incident & TMI Lessons Learned Task Force.
MATTSON, R.J. Division of Systems Safety. 79/06/08. 1p.

7908230004 Submits interim rept re status of analysis by Ofc of Nuclear Reactor Regulation & contractors concerning generation & behavior of hydrogen & oxygen during TMI icident.
MURLEY, T.E. Division of Reactor Safety Research. 79/06/13. 5pp.

7907180165 Examines possibility that tube cracks existing in steam generator B may not have withstood transients occurring on 790328.Result would have been baseline leaks in generator.
BOSNAK, R.J. Mechanical Engineering Branch. 79/06/14. 4pp.

7908150635 Responds to 790531 memo re lesson learned from TMI-2 event. Suggests "flight recorder" concept, reconsideration of need to assume co-planar flow blockage in LOCA analysis & incorporation of NRC fuel experts into one branch.
MEYER, R.O. Core Performance Branch. 79/06/19. 2pp.

7907180126 Discusses inability to determine whether tripping of HPI pumps & subsequent failure to restart pumps was operator or mechanical error.
MATTSON, R.J. Division of Systems Safety. 79/06/20. 1p.

7908230331 Forwards "General Review of Health Physics Program at TMI Nuclear Station" per request.
ARNOLD, R.C. Metropolitan Edison Co. 79/06/20. 1p.

7908150625 Responds to 790531 memo re lesson learned from TMI-2 event. Suggests requirements for integrated ECCS designed in new plants.RHR sys which could support ECCS would be starting point for integrated ECCS design.
VILLALVA, I. Standardization Branch. 79/06/21. 2pp.

7908070450 Notifies of intent to install second communications sys linking facilities w/NRC regional ofc & main Bethesda, MD ofc.Second line will be used to relay radiologic & environ data during emergencies.Testing procedures encl.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/06/22. 3pp.

7908070481 Comments on trip rept to TMI.Rept failed to mention that need was expressed for definitive criteria for shallow land burial grounds.W/o criteria, decisions are based on engineering judgments.Requests development of criteria.
COLLINS, J.T. TMI-2 Operations/Support. 79/06/23. 8pp.

--7908070487 Forwards trip report re TMI trip made by NMSS representatives to review planning for processing wastes, specifically waste disposal & transportation.Recommends pursuing method of converting waste to solid matrix.
DIRCKS, W.J. Office of Nuclear Material Safety & Safeguards. 79/06/18. 1p.

--7908070488 Submits trip rept re 790605 TMI trip by NMSS to review waste disposal & transportation.Forwards GPU 790511 Svc memo from McGoey to Rusche.
BROWNING, R.E. Division of Waste Management. 79/06/13. 10pp.

7908210397 Forwards evaluation of cause of primary-to-secondary leak in steam generator B during TMI incident.
MATTSON, R.J. Division of Systems Safety. 79/06/26. 1p.

7908150642 Responds to 790531 memo re lessons learned from TMI-2 event. Suggests series of thermocouples along length of fuel element near reactor axis to assist in void detection & installation of hydrogen detection device near core axis.
KIRSLIS, S.S. Environmental Projects Branch 1. 79/06/27. 2pp.

7908150717 Summary of 790611 meeting re open items & proposed changes for TMI-1 restart.
DIIANNI, D.C. Operating Reactors Branch 4. 79/06/28. 35pp.

7908220402 Comments on circumstances surrounding TMI Incident regrettable & disturbing to those who helped engineer & develop nuclear energy.Suggests items for engineering review.
FLINCHBAUGH, D.E. PRC Sys Svcs Co. 79/06/28. 3pp.

7908130333 Notifies all power reactor licensees that NRC is conducting overall review & evaluation of mgt & technical resources available to handle TMI event.Forwards description of required info.Requests submission by 790730.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/06/29. 6pp.

7908150650 Responds to 790531 memo re lessons learned from TMI-2 event. Recommends maintaining min hydrogen concentration in coolant to prevent net water radiolysis & installation of emergency sampling & analysis sys at all plants.W/o encl.
HOATSON, D.A. Fuel Behavior Branch. 79/06/29. 2pp.

7908150714 Discusses lessons learned from TMI-2 event.Suggests data bank on failure rate of individual plant components having major safety implications.Recommends development of NRC emergency response team w/special training.
REYES, J.N. Information Security Branch. 79/06/29. 2pp.

7908230001 Responds to 790529 request for current calculation of hydrogen/oxygen generation rate during TMI-2 incident.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/06/29. 2pp.

7908150613 Forwards M Chiramal 790702 note re study of equipment in TMI-2 containment.
LAINAS, G. Plant Systems Branch. 79/07/02. 1p.

--7908150608 Discusses investigation of equipment in TMI-2 containment. Suggests establishment of exact location of equipment & water level, measurement of radiation, temp, humidity & visual & photographic insp of all equipment.
CHIRAMAL, M. Plant Systems Branch. 79/07/02. 2pp.

7908150768 Forwards summary of section involvement in TMI-2 event.
HULMAN, L.G. Hydrology Meteorology Branch. 79/07/03. 26pp.

7908220158 Advises of actions initiated & repts prepared by foreign countries subsequent to TMI-2.
SHEA, J.R. Office of International Programs. SECY-79-425. 79/07/03. 16pp.

7908150743 Discusses upgraded standard Tech Specs bases program.Amends in Classes I-III will be fee-exempt.
REID, R.W. Operating Reactors Branch 4. 79/07/05. 2pp.

7908210394 Responds to 790619 ltr re analysis of operational QA problems at TMI.Info will be published in Aug 1979.
HAASS, W.P. Quality Assurance Branch. 79/07/05. 1p.

7908150668 Forwards LG Hulman 790626 memo.Requests review of encl groundwater monitoring program criteria, assessment of implementation intention & implementation schedule.
COLLINS, J.T. TMI-2 Operations/Support. 79/07/06. 1p.

7908150742 Recommends resolution of containment purge issue prior to TMI-1 operation.Licensee response to generic ltr should be evaluated & resolved prior to operation.
LAINAS, G. Plant Systems Branch. 79/07/09. 1p.

7908150755 Responds to 790529 telegram re delays in safety & environ reviews.Resources have been diverted to TMI-2 investigation. Discusses 790613 & 18 meetings re review of current applications.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/07/10. 3pp.

--7908150758 Requests reconsideration of proposed reordering of licensing priorities.Facility has been in licensing process longer than any other.Timely completion of plant is vital.
HOWELL,S.H. Consumers Power Co. 79/05/29. 1p.

7908220415 Forwards response to 790507 ltr concerning TMI events & implications.Rept on TMI accident encl.
VINCK,W. European Communities, Commission of. 79/07/12. 1p.

--7908220419 "Rept on Accident at TMI."
* European Communities, Commission of. 79/07/12. 18pp.

7908030055 QA Program Insp Rept 99900034/71-04 on 710824/27.
OLLER,R.E.; VETTER,W.E. Atomic Energy Commission (Pre 1975). 71/09/30. 11pp.

7908150470 Responds to 790604 suggestion that greater release might have occurred at TMI-2 if purging had been in progress during incident.Discusses containment isolation.Purging & venting are being reviewed on generic basis.
DENTON,H.R. Office of Nuclear Reactor Regulation. 79/07/16. 3pp.

--7908150473 Discusses TMI-2 containment isolation.Suggests that open containment ventilation valves could have caused greater radioactive release.Requests review.
GILINSKY,V. Commission. 79/06/04. 1p.

7908150656 Forwards BF Peterson 790620 ltr suggesting mods for enhancing safety of TMI-2.
WILLIAMS,F.J. TMI-2 Operations/Support. 79/07/16. 1p.

--7908150661 Forwards suggested mods for enhancing safety of TMI-2.
PETERSON,B.F. Affiliation Unknown. 79/07/20. 4pp.

7908150684 Submits interim response to 790620 memo re HPI pump performance during TMI incident.Manual starting difficulty for pump 1A appears caused by contact bounce.Most pump trips caused by operator action.
MOSELEY,N.C. Division of Reactor Operations Inspections. 79/07/16. 1p.

--7908150707 Requests high priority investigation re cause of frequent HPI pump tripping during first 16-h of TMI-2 event, in order that significant generic reactor safety implications can be quickly identified.
MATTSON,R.J. Division of Systems Safety. 79/06/20. 1p.

7908150738 Forwards Tech Spec change re administrative controls on radwaste operations review committee being formed to process backlog of procedures on new radwaste equipment & mods to existing radwaste equipment.
VOLLMER,R.H. TMI-2 Operations/Support. 79/07/16. 2pp.

--7908150739 Tech Specs Section 6.5.3, "Radwaste Operations Review Committee.Administrative Controls."
* TMI-2 Operations/Support. 79/07/16. 4pp.

7908220161 "Rept on Reactor Accident at TMI," submitted by Danish delegation.
* Environmental Protection Agency. 79/07/16. 35pp.

7908220408 Submits studies & actions undertaken by CNEN following TMI.
ZAFFIRO,C. Italy. 79/07/16. 4pp.

7908150716 Summary of 790711-12 meeting at site re sys thermal hydraulic analysis.
MINNER,W. Division of Systems Safety. 79/07/17. 4pp.

7908150741 Discusses planned 790730-0810 site visit to discuss vital area analysis of facilities.
REID,R.W. Operating Reactors Branch 4. 79/07/17. 2pp.

7908230329 Withdraws request that rept, "General Review of Health Physics Program at TMI Station," be treated as proprietary under 10CFR2.790.NRC may retain rept for use during investigations of TMI-2 accident.
ARNOLD,R.C. Metropolitan Edison Co. 79/07/18. 1p.

7908310437 FOIA request for transcripts re TMI.Appeal re excessive delay in receipt of requested documents & tapes per FOIA.
WEISS,E.R. Sheldon, Harmon, Roisman & Weiss. 79/07/18. 2pp.

7908310586 Appeals initial FOIA decision re continued noncompliance w/Union of Concerned Scientists FOIA request for tapes & transcripts of conversations recorded at Incident Response Ctr during TMI incident.Requests release of transcripts.
WEISS,E.R. Sheldon, Harmon, Roisman & Weiss. 79/07/18. 2pp.

7908150756 Responds to 790516 & 0618 ltrs re characteristics of fuel assemblies in TMI & nuclear characteristics of certain matls.
SCHROEDER,F. Division of Systems Safety. 79/07/20. 2pp.

7908230238 Forwards review of TMI-2 const project documents re to decision to put TMI-2 into operation on '81230; final rept of TMI-2 re training & certification of TMI-2 licensed personnel, in response to 790712 request.
BLAKE,E.L. Shaw, Pittman, Potts, & Trowbridge. 79/07/20. 2pp.

--7908230245 "Review of TMI-Unit 2 Const Project," prepared for NJ Dept of Public Advocate.
* Touche Ross & Co. 78/10/25. 114pp.

--7908230251 Forwards repts & related correspondence as per discussions re TMI-2.
HEWARD,R.W. GPU Service Corp. 79/04/12. 1p.

--7908230257 General Public Utils Generation Operating Procedure Guidelines & Stds."
FINFROCK,I.R.; HERBEIN,J.G.; CONRAD,R.W. GPU Service Corp. 78/06/28. 8pp.

--7908230266 Forwards summary chronology of TMI-2 in-plant activities, TMI-2 test program chronology bar chart & list of delays to TMI-2 test program, in response to request for detailed analysis of TMI-2 startup test program.
CUTLER,R.C. GPU Service Corp. 79/01/23. 47pp.

--7908230272 "Final Rept of TMI-2 Accident Assessment Documentation - Training Programs & Procedure Review."
* GPU Service Corp. 79/05/16. 59pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events.Requests addl five copies of response for each unit, if more then one is owned & operated.
HAASS,W.P. Quality Assurance Branch. 79/07/24. 1p.

7908230322 Notifies of issuance of NUREG-0578, "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations," during week of Jul 23.Rept will be distributed to all NRC employees.
BESAW,W.J. Division of Technical Information & Document Control. 79/07/24. 1p.

7908230440 Forwards answers to questions asked during 790531 presentation of testimony to President's Commission on TMI-2 incident.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/24. 5pp.

7908010260 Notifies of new completion date of July 1980 for Phase II of multi-phase program to evaluate effect of asymmetric LOCA loads, due to analyses resulting from TMI-2 incident.
HERBEIN,J.G. Metropolitan Edison Co. 79/07/25. 2pp.

7908030425 Responds to FOIA request for documents on or after 790328 re OL delay.Forwards SECY-79-344, "Interim Nuclear Reactor Regulation Organization to Deal W/Impacts of TMI-2 & Other Nuclear Reactor Regulation Priority Tasks."
FELTON,J.M. Division of Rules and Records. 79/07/25. 1p.

--7908030436 Seeks NRC approval of Ofc of Nuclear Reactor Regulation plan to formalize interim organizational structure to deal w/impacts of TMI-2 on resources & priorities within that ofc.
DENTON,H.R. Office of Nuclear Reactor Regulation. SECY-79-344. 79/05/19. 29pp.

7908010559 Documents 790724 telcon concerning info from SNAP program re hydriding of Zircaloy cladding in TMI incident.Hydriding did not occur to any significant extent.
PEARLMAN,H. Rockwell International Corp. 79/07/30. 4pp.

7908080486 Forwards fee for amend per 790703 ltr.
HERBEIN,J.G. Metropolitan Edison Co. 79/07/30. 1p.

7908220153 Forwards previous ltrs to President's Commission on TMI describing sequence of events that led to concern that hydrogen bubble in TMI-2 RCS may become combustible.
MATTSON,R.J. TMI-2 Lessons Learned Task Force. 79/07/30. 2pp.

7908220177 Forwards population dose rept re calculated population dose commitments based on measured effluents from nuclear power plants during 1975.W/o encl.
BLAND,J.S. Assistant Director for Environmental Projects. 79/07/30. 1p.

7908230354 Forwards document previously referred to FBI re TMI-2 incident.
ELANDERS, D. G. Federal Bureau of Investigation 79/08/02 1p

--7908230359 Notifies of nuclear accident on 790328 at TMI Nuclear power plant caused by four separate failures. Three were caused by malfu.tioning equipment & one from apparent human error. Evacuation of four surrounding counties considered.
* Federal Bureau of Investigation 79/03/31 1p

--7908230365 Forwards FOIA request received by NRC from AZ Roisman of NRDC for documents re TMI-2 incident. Includes document originated by FBI for review to determine public release. Requests complete FBI response to Roisman.
FELTON, J. M. Division of Rules and Records 79/06/13 1p

7908220421 Forwards info fulfilling requirements described in 790725 deposition.
NOVAK, T. M. Reactor Systems Branch 79/08/06 1p

--7908220425 Forwards first draft of "RCS Overpressure Protection During Startup or Shutdown."
NOVAK, T. Reactor Systems Branch 75/12/02 1p

--7908220440 Draft "RCS Overpressure Protection During Startup or Shutdown."
* Reactor Systems Branch 75/12/02 4pp

--7908220444 SRP Section 5.3.2, "Pressure Temp Limits."
* Office of Nuclear Reactor Regulation 75/12/02 18pp
Available at NTIS.

--7908220447 Forwards branch request for addl info re first round questions.
MAZETIS, G. R. Reactor Systems Branch 77/09/28 2pp

--7908220450 Requests addl info for first round questions for branch acceptance review of FSAR.
* Reactor Systems Branch 77/09/28 5pp

--7908220454 Forwards branch request for addl info re first round questions.
MAZETIS, G. R. Reactor Systems Branch 78/03/09 1p

--7908220460 Requests addl info for first round questions for branch review of applicant FSAR through Amend 38.
* Reactor Systems Branch 78/03/08 17pp

--7908220462 Forwards branch request for addl info re first round questions.
MAZETIS, G. R. Reactor Systems Branch 78/03/09 1p

--7908220466 Requests addl info for first round questions review.
* Reactor Systems Branch 78/03/09 3pp

--7908220468 Forwards branch request for addl info re second round questions.
ROSS, D. F. Reactor Systems Branch 78/09/28 1p

--7908220472 Requests addl info for second round questions for FSAR review.
* Reactor Systems Branch 78/09/28 22pp

--7908220495 Forwards Reactor Sys Branch request for addl info for second round questions.
SCHROEDER, F. Assistant Director for Reactor Safety 78/10/26 1p

--7908220499 Requests addl info for Reactor Sys Branch review of Round 2 questions re main steam line break.
* Assistant Director for Reactor Safety 78/10/26 3pp

--7908220502 Forwards Reactor Sys Branch request for addl info re second round questions.
TEDESCO, R. L. Assistant Director for Reactor Safety 78/12/27 2pp

--7908220503 Requests addl info for Reactor Sys Branch review of second round questions.
* Assistant Director for Reactor Safety 78/12/27 6pp

--7908220509 Forwards ACRS questions for facility. Open items remain.
VARGA, S. A. Light Water Reactors Branch 4 77/11/15 1p

--7908220514 Requests addl info for ACRS review.
* Light Water Reactors Branch 4 77/11/07 13pp

7908170581 Responds to FOIA request for all documents & communications in NRC possession re TMI-2. Forwards updated, "Title List - Publicly Available Documents - TMI Unit 2 - Docket 50-320."
FELTON, J. M. Division of Rules and Records 79/08/13 1p

7908170586 Responds to FOIA request for documents relating to communications between TMI personnel & NRC. Forwards updated rept, "Title List - Publicly Available Documents - TMI-2 Docket 50-320."
FELTON, J. M. Division of Rules and Records 79/08/13 1p

7908170594 Responds to FOIA request for documents & other records produced by IE staff or agents re TMI-2 incident. Forwards updated "Title List - Publicly Available Documents - TMI Unit 2 - Docket 50-320."
FELTON, J. M. Division of Rules and Records 79/08/13 1p

7908230342 Notifies that draft radiological effluent Tech Specs will be submitted after completion of Unit 2 Tech Specs (to be issued 790820) per Boegli 790806 telcon.
HERBEIN, J. G. Metropolitan Edison Co. 79/08/14 1p

7908220212 Advises Commissioners that licensing activities on pending CP & OL applications will be resumed.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/08/20 4pp

--7908220218 Agrees w/recommendations & schedule established re dedicated penetrations for external recombiners described in NUREG-0578 re TMI. Concludes questions re hydrogen generation need to be re-examined.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards 79/08/13 3pp

--7908220221 Forwards revised page 3 to 790813 ltr re recommendations of TMI task force & alternatives to shift technical advisors.
FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards 79/08/15 27pp

7908230284 Forwards document in support of request to NRC for info on TMI-2 incident. No objections to release of documents in full.
LEEF, P. M. State Dept of 79/08/21 1p

--7908230289 Forwards FOIA request received by NRC from AZ Roisman of NRDC for documents re TMI-2 accident. Includes document for review to determine release to public. Response should be sent directly to Roisman.
FELTON, J. M. Division of Rules and Records 79/06/07 1p

--7908230298 Requests all documents in NRC possession re TMI-2.
ROISMAN, A. Z. Natural Resources Defense Council 79/04/04 1p

--7908230306 Forwards "Tentative Thoughts on Impact of TMI Accident on INFCE Effort: Nonproliferation & Future of Nuclear Power."
RATHJENS, G. State Dept of 79/04/10 4pp

7908310442 Responds to FOIA request for transcripts re TMI. Confirms telcon w/Reed & Wagman re placement of transcripts for first five days of Incident Response Ctr conversations in PDR by 790824.
FELTON, J. M. Division of Rules and Records 79/08/21 1p

7908310487 Responds to 790718 ltr appealing NRC failure to make available tapes or transcripts of conversations recorded at Incident Response Ctr during TMI incident. Transcripts placed in PDR on 790822. No further action to be taken.
FELTON, J. M. Division of Rules and Records 79/08/23 1p

7908310527 Responds to FOIA reque: for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2 & 5-7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records 79/08/27 21pp

7908310534 Responds to FOIA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2 & 5-7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records 79/08/27 21, p

7908310537 Responds to FOIA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2 & 5-7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records 79/08/27 21pp

7908310542 Responds to FOIA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2 & 5-7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records 79/08/27 21pp

7908310556 Responds to FOIA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2 & 5-7 & totally denied under Exemption 5.
FELTON, J.M. Division of Rules and Records 79/08/27 21pp.

G. Inspection reports, IE Bulletins & correspondence

7908230476 Forwards IE Insp Repts 50-320/72-04 & 50-289/72-12 on 720711-14.
HOWARD, E.M. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 72/09/19 2pp.

--7908230481 IE Insp Repts 50-320/72-04 & 50-289/72-12 on 720711-14. No noncompliance noted. Major areas inspected: enforcement action, licensee action on previously identified enforcement matters & unresolved items.
FOLSOM, S.A., BURZI, A.V.J. Region 1, Philadelphia, Office of the Director. HOWARD, E.M. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 72/09/13 18pp.

7908230338 Forwards IE Insp Repts 50-320/72-06 & 50-289/72-16 on 720926 & 27.
HOWARD, E.M. Region 1, Philadelphia, Office of the Director 72/11/03 1p.

--7908230340 IE Insp Repts 50-320/72-06 & 50-289/72-16 on 720926 & 27. Noncompliance noted: fire associated w/heat treatment operations.
FOLSOM, S.A., BARKER, F.F., HOWARD, E.M. Region 1, Philadelphia, Office of the Director 72/11/07 4pp.

7908230334 IE Insp Repts 50-320/72-08 & 50-289/72-19 on 721109. Mgt meeting held to discuss QA history of TMI projects & requirement for quality program for operations phase.
FOLSOM, S.A. Region 1, Philadelphia, Office of the Director. HOWARD, E.M., O'REILLY, J.P. Atomic Energy Commission-Deputy Director for Reactor Projects 72/11/20 3pp.

7908230570 Forwards IE Insp Rept 50-320/74-01 on 740109-11 & notice of violation.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 74/01/31 2pp.

--7908230573 Notice of violation from insp on 740109-11.
* Region 1, Philadelphia, Office of the Director 74/01/31 1p.

--7908230577 IE Insp Rept 50-320/74-01 on 740109-11. Noncompliance noted: chemical analysis, physical characteristics & NDT records were not traceable to individual liner plate penetrations.
* Region 1, Philadelphia, Office of the Director 74/01/31 7pp.

7908230581 Forwards IE Insp Repts 50-320/74-02 & 50-289/74-07 on 740220-22 & 25-27 & notice of violation.
O'REILLY, J.P. Region 1, Philadelphia, Office of the Director 74/03/29 2pp.

--7908230584 Notice of violation from insp on 740220-22 & 25-27.
* Region 1, Philadelphia, Office of the Director 74/03/29 2pp.

--7908230590 IE Insp Repts 50-320/74-02 & 50-289/74-07 on 740220-22 & 25-27. Noncompliance noted: chlorine usage logs not maintained, airborne particulates not monitored on weekly basis & milk not sampled on monthly basis.
BORES, R.J., GALLINA, C.O., STOHR, J.P. Region 1, Philadelphia, Office of the Director 74/03/29 21pp.

7908230643 Forwards IE Insp Rept 50-320/74-08 on 741205, 0915, 19 & 30.
CARLSON, R.T. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 75/01/15 2pp.

--7908230649 IE Insp Rept 50-320/74-08 on 741205, 09, 15, 19 & 30. No noncompliance noted. Major areas inspected: conducted static tests re anchor wedges & low relaxation strands.
VARELA, A.A., HAYNES, R.C. Region 1, Philadelphia, Office of the Director 75/01/14 9pp.

7908230486 Forwards IE Insp Rept 50-320/76-06 on 760510-13 & notice of violation.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 76/06/03 2pp.

--7908230494 IE Insp Rept 50-320/76-06 on 760223-24. Noncompliance noted: crimping of safety-related cable & wire in circuits to motors & control cabinets performed w/crimping tools which were not controlled & calibr.
NARROW, L., FINKEL, A., HEISHMAN, R.F. Region 1, Philadelphia, Office of the Director 76/06/02 18pp.

7908230604 Forwards IE Insp Repts 50-320/76-11 & 50-289/76-20 on 760824-26 & notice of violation.
O'REILLY, J.P. Region 1, Philadelphia, Office of the Director 76/09/15 2pp.

--7908230607 Notice of violation from insp on 760824-26.
* Region 1, Philadelphia, Office of the Director 76/09/13 1p.

--7908230611 IE Insp Repts 50-320/76-11 & 50-289/76-20 on 760824-26. Noncompliance noted: quarterly inventories of emergency equipment not properly performed.
DONALDSON, D.E., STOHR, J.P. Region 1, Philadelphia, Office of the Director 76/09/13 16pp.

7908230625 Forwards IE Insp Repts 50-320/76-10 & 50-289/76-18 on 760720-28 & 0803 & 04 & notice of violation.
NELSON, P.R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 76/09/16 2pp.

--7908230629 Notice of violation from insp on 760720-28 & 0803 & 04.
* Region 1, Philadelphia, Office of the Director 76/09/15 1p.

--7908230634 IE Insp Repts 50-320/76-10 & 50-289/76-18 on 760720-28 & 0803 & 04. Noncompliance noted: weekly air particulate samples were not composited & written procedures were not prepared to ensure compliance w/ETS.
BORES, R.J., BLAND, J.S. Region 1, Philadelphia, Office of the Director 76/09/15 17pp.

7908230614 Forwards IE Insp Repts 50-320/76-13 & 50-289/76-22 on 760908 & 09 & notice of violation.
NELSON, P.R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 76/09/21 2pp.

--7908230617 Notice of violation from insp on 760908 & 09.
* Region 1, Philadelphia, Office of the Director 76/09/20 1p.

--7908230621 IE Insp Repts 50-320/76-13 & 50-289/76-22 on 760908 & 09. Noncompliance noted: four portable radiation detection instruments found out of calibr.
SWETNAM, R.L., KNAPP, P.L. Region 1, Philadelphia, Office of the Director 76/09/20 7pp.

7908230594 Forwards IE Insp Repts 50-320/76-16 & 50-289/76-24 on 761012-15 & 21 & notice of violation.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 76/11/05 2pp.

--7908230597 Notice of violation from insp on 761012-15 & 21.
* Region 1, Philadelphia, Office of the Director 76/11/05 1p.

--7908230601 IE Insp Repts 50-320/76-16 & 50-289/76-24 on 761012-15 & 21. Noncompliance noted: General Ofc Review Board Meeting 24 conducted w/alternates not duly appointed & required signs not posted when fuel movement activities commenced.
FASANO, A.N., FINKEL, W.A. Region 1, Philadelphia, Office of the Director. DAVIS, A.B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 76/11/05 35pp.

7908230637 Forwards IE Insp Rept 50-320/77-03 on 770112-14.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 77/02/01 2pp.

--7908230640 IE Insp Rept 50-320/77-03 on 770112-14. No noncompliance noted. Major areas inspected: surveillance testing & calibr & test & measurement equipment.
SMITH, J.T., FASANO, A.N. Region 1, Philadelphia, Office of the Director. KEIMIG, R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 77/01/28 19pp.

7908230652 Forwards IE Insp Repts 50-320/77-36 & 50-289/77-30 on 770921 & 22. No noncompliance noted.
* Region 1, Philadelphia, Office of the Director 77/10/05 1p.

--7908230659 IE Insp Repts 50-320/77-36 & 50-289/77-30 on 770921 & 22. No noncompliance noted. Major areas inspected: licensee action on unresolved items re preoperational emergency planning.
DONALDSON, D.E., GALLINA, C.O. Region 1, Philadelphia, Office of the Director. STOHR, J.P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/10/04 5pp.

7908230531 Forwards IE Insp Repts 50-320/78-16 & 50-289/78-08 on 780417-21 & notice of violation.
NELSON, P.R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/05/31 2pp.

--7908230334 Notice of violation from insp on 780417-21.
* Region 1, Philadelphia, Office of the Director. 78/05/25. 2pp.

--7908230544 IE Insp Repts 50-320/78-16 & 50-289/78-08 on 780417-21. Noncompliance noted: failure to sample, analyze air particulates & iodine & failure to meet Sr-89 analytical sensitivity for drinking water & excessive radiation levels.
BORES, R. J.; BERKSON, H. Region 1, Philadelphia, Office of the Director. STOHR, J. P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 78/05/25. 18pp.

7908230516 Notice of violation from insp on 781212-15.
* Region 1, Philadelphia, Office of the Director. 79/01/15. 2pp.

--7908230524 IE Insp Repts 50-320/78-38 & 50-289/78-25 on 781212-15. Noncompliance noted: failure to control combustibles, failure to fully implement procedures & failure to implement SER commitment.
GAGE, L. W. Region 1, Philadelphia, Office of the Director. EBNETER, S. D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/01/15. 9pp.

7908230552 Forwards IE Insp Repts 50-320/79-04 & 50-289/79-03 on 790213-15, 24, 25, 28 & 0301 & 02 & notice of violation.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/23. 2pp.

--7908230557 Notice of violation from insp on 790213-15, 24, 25, 28 & 0301 & 02.
* Region 1, Philadelphia, Office of the Director. 79/04/13. 2pp.

--7908230565 IE Insp Repts 50-320/79-04 & 50-289/79-03 on 790213-15, 24, 25, 28 & 0301 &02 Noncompliance noted: failure to adhere to procedures & high radiation area entries w/o adequate continuously-indicating dose rate instruments.
PLUMLEE, K. E.; CLEMONS, P. E. Region 1, Philadelphia, Office of the Director. CROCKER, H. W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/04/13. 9pp.

7906290348 Forwards writeup of D Quick 790502-03 presentation re design deficiencies, operations & maint problems w/B&W design. Problems pointed up by TMI-2 incident.
WILLIAMS, F. J. Division of Project Management. 79/05/17. 11pp.

7908230489 Notice of violation from insp on 760510-13.
* Region 1, Philadelphia, Office of the Director. 76/06/02. 1p.

7908150754 Forwards IE Insp Repts 50-320/79-08 & 50-289/79-09 on 790315. No noncompliance noted.
SMITH, G. M. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/06/21. 2pp.

--7908150760 IE Insp Repts 50-320/79-08 & 50-289/79-09 on 790315. No noncompliance noted. Major areas inspected: effluent sample split.
KOTTAN, J. J.; STOHR, J. P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/06/20. 4pp.

7908150747 Forwards IE Bulletin 79-14 "Seismic analysis for As-Built Safety-Related Piping Sys."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/02. 1p.

7908150759 Forwards IE Info Notice 79-18, "Skylab Reentry."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/06. 1p.

7908150749 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/11. 1p.

7908010429 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908020171 IE Bulletins 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl."
* Office of Inspection & Enforcement, Office of the Director. 79/07/26. 7pp.

7908100233 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908100338 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908090302 Forwards IE Bulletin 79-16, "Vital Area Access Control." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908280115 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908230304 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/08. 1p.

7908300139 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

R Periodic operating reports & related correspondence

7908010454 Forwards discharge monitoring rept for Jan 1979.
TROFFER, G. J. Metropolitan Edison Co. 79/02/23. 12pp.

7908010500 Forwards discharge monitoring rept for Feb 1979.
TROFFER, G. J. Metropolitan Edison Co. 79/03/19. 12pp.

7908210373 Forwards monthly acquatic study rept for June 1979.
MALICK, R. Ichthyological Associates, Inc. 79/07/18. 1p.

--7908210374 Monthly acquatic study rept for June 1979.
NARDACCI, G. A. Ichthyological Associates, Inc. 79/07/18. 30pp.

7908010558 Forwards discharge monitoring rept for June 1979.
TROFFER, G. J. Metropolitan Edison Co. 79/07/25. 12pp.

7908090372 Forwards "Ecological Study of Susquehanna River Near TMI," 1978 annual rept by Ichthyological Associates, Inc.
HILBISH, J. Metropolitan Edison Co. 79/08/03. 1p.

--7908090378 "Ecological Study of Susquehanna River Near TMI," 1978 annual rept.
NARDACCI, G. A. Ichthyological Associates, Inc. 79/07/31. 742pp.

S Reportable occurrences, LERs & related correspondence

7908230499 Forwards LER 77-016/01T-0.
EVANS, J. Toledo Edison Co. 77/10/07. 1p.

--7908230507 LER 77-016/01T-0 on 771024 half trip of steam & feedwater rupture control sys resulted in opening of pressurizer power relief valve. Possibly caused by loose connections at terminal boards.
STALTER, L. C. Toledo Edison Co. 77/10/07. 4pp.

T Hearing transcripts on non-antitrust matters

7908300082 Transcript of 790505 TMI-2 investigation interview w/DR Neely.
MARTIN, T. T. Region 1, Philadelphia, Office of the Director. SHACKLETON, D. C. Region 5, San Francisco, Office of the Director. 79/06/14. 18pp.

7908290532 Transcript of 790423 TMI-2 investigation interview w/JH Flint.
CRESWELL, J. S. Region 3, Chicago, Office of the Director. KIRKPATRICK, D. C. Office of Inspection & Enforcement, Office of the Director. 79/06/19. 45pp.

7908290557 Transcript of 790424 TMI-2 investigation interview w/SW Porter.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director. ESSIG, T. H. Region 3, Chicago, Office of the Director. SHACKLETON, D. C. Region 5, San Francisco, Office of the Director. 79/06/20. 117pp.

7908290567 Transcript of 790424 TMI-2 investigation interview w/EW Houser.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director. SHACKLETON, D. C. Region 5, San Francisco, Office of the Director. 79/06/20. 127pp.

7908290714 Transcript of 790303 TMI-2 investigation interview
w/RD McCann.
RESNER, M. E. Office of Inspector & Auditor. DONALDSON, D. E. Region 1, Philadelphia, Office of the Director. COLLINS, D. M. Region 2, Atlanta, Office of the Director. 79/06/20. 36pp.

7908290579 Transcript of 790424 TMI-2 investigation interview
w/TL Mulleavy.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
ESSIG, T. H., MARSH, R. Region 3, Chicago, Office of the Director.
79/06/21. 81pp.

7908290603 Transcript of 790425 TMI-2 investigation interview
w/R Dubiel.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
MARSH, R., ESSIG, T. H. Region 3, Chicago, Office of the Director.
79/06/21. 35pp.

7908290618 Transcript of 790426 TMI-2 investigation interview
w/SW Porter.
ESSIG, T. H. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
79/06/21. 44pp.

7908290630 Transcript of 790501 TMI-2 investigation interview
w/JC Higgins.
MARSH, R., HUNTER, D. R. Region 3, Chicago, Office of the Director.
MARTIN, T. T. Region 1, Philadelphia, Office of the Director.
79/06/21. 51pp.

7908290645 Transcript of 790502 TMI-2 investigation interview
w/EC Fuhrer.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
COLLINS, D. M. Region 2, Atlanta, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
79/06/21. 65pp.

7908290721 Transcript of 790503 TMI-2 investigation interview
w/LE Espy.
SINCLAIR, J. R. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/06/21. 16pp.

7908300039 Transcript of 790503 TMI-2 investigation interview
w/J Hipple & G Rider.
SINCLAIR, J. R. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/06/21. 43pp.

7908300052 Transcript of 790504 TMI-2 investigation interview
w/HW Furst, KL Myers & MA Pelen.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
COLLINS, D. M. Region 2, Atlanta, Office of the Director.
ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/06/21. 47pp.

7908300075 Transcript of 790505 TMI-2 investigation interview
w/DE Zeiter.
SINCLAIR, J. R. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/06/21. 83pp.

7908290709 Transcript of 790502 TMI-2 investigation interview
w/MA Janouski.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
MARSH, R. Region 3, Chicago, Office of the Director. 79/06/22. 92pp.

7908290720 Transcript of 790503 TMI-2 investigation interview
w/WJ Raymond.
SINCLAIR, J. R. Office of Inspector & Auditor. MARTIN, T. T. Region 1, Philadelphia, Office of the Director. HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/06/22. 35pp.

7908290724 Transcript of 790503 TMI-2 investigation interview
w/TM Gerusky, MA Reilly & WP Dornsife.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
ESSIG, T. H. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
79/06/22. 38pp.

7908290729 Transcript of 790503 TMI-2 investigation interview
w/TJ Leach.
RESNER, M. E. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/06/22. 45pp.

7908300045 Transcript of 790503 TMI-2 investigation interview
w/RB Evans.
SINCLAIR, J. R. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/06/22. 48pp.

7908300071 Transcript of 790503 TMI-2 investigation interview
w/RE Hornbeck.
RESNER, M. E. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/06/23. 27pp.

7908300089 Transcript of 790505 TMI-2 investigation interview
w/T Potter & H Woodard.
ESSIG, T. H., MARSH, R. Region 3, Chicago, Office of the Director. 79/06/23. 71pp.

7908300174 Transcript of 790507 TMI-2 investigation interview
w/JE Cline.
ESSIG, T. H. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
79/06/23. 30pp.

7908290465 Transcript of 790421 TMI-2 investigation interview
w/DA Berry.
MARTIN, T. T. Region 1, Philadelphia, Office of the Director.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
79/06/25. 53pp.

7908300061 Transcript of 790504 TMI-2 investigation interview
w/DE Corl.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
79/06/25. 30pp.

7908300067 Transcript of 790504 TMI-2 investigation interview
w/L Rogers.
RESNER, M. E. Office of Inspector & Auditor. MARTIN, T. T. Region 1, Philadelphia, Office of the Director. CRESWELL, J. S. Region 3, Chicago, Office of the Director. 79/06/25. 77pp.

7908300111 Transcript of 790507 TMI-2 investigation interview
w/CO Gallina.
MARSH, B. Region 3, Chicago, Office of the Director. MARTIN, T. T. Region 1, Philadelphia, Office of the Director. 79/06/25. 79pp.

7908290574 Transcript of 790424 TMI-2 investigation interview
w/JH DeMan.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
COLLINS, D. M. Region 2, Atlanta, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
79/06/26. 136pp.

7908290615 Transcript of 790425 TMI-2 investigation interview
w/GA Kunder.
KIRKPATRICK, D. C. Office of Inspection & Enforcement, Office of the Director. HUNTER, D. R. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
79/06/26. 59pp.

7908290622 Transcript of 790501 TMI-2 investigation interview
w/JR Smith.
RESNER, M. E., SINCLAIR, J. R. Office of Inspector & Auditor.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
79/06/26. 44pp.

7908300202 Transcript of 790507 TMI-2 investigation interview
w/RW Bensel & P Warren.
SINCLAIR, J. R. Office of Inspector & Auditor. CRESWELL, J. S. Region 3, Chicago, Office of the Director. DONALDSON, D. E. Region 1, Philadelphia, Office of the Director. 79/06/26. 63pp.

7908300260 Transcript of 790507 TMI-2 investigation interview
w/BA Good.
ESSIG, T. H. Region 3, Chicago, Office of the Director. RESNER, M. E. Office of Inspector & Auditor. 79/06/26. 50pp.

7908300265 Transcript of 790508 TMI-2 investigation interview
w/DR Keesler & JM Dupes.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
SINCLAIR, J. R. Office of Inspector & Auditor. 79/06/26. 50pp.

7908290645 Transcript of 790508 TMI-2 investigation interview
w/JL Seelinger.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
SINCLAIR, D. C. Office of Inspector & Auditor. 79/06/27. 172pp.

7908290565 Transcript of 790424 TMI-2 investigation interview
w/RW Dubiel.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/06/27. 28pp.

7908290624 Transcript of TMI-2 investigation interview
w/M Buring.
MARSH, R., ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/06/27. 33pp.

7908290659 Transcript of 790330 TMI-2 investigation interview
w/F Scheimann & DJ Laudermilch.
*. Office of Inspection & Enforcement, Office of the Director. 79/06/27. 36pp.

DOCKETED ITEMS

7908290675 Transcript of 790425 TMI-2 investigation interview
w/J DeMan.
*, Office of Inspection & Enforcement, Office of the Director.
79/06/27. 15pp.

7908300120 Transcript of 790507 TMI-2 investigation interview
w/RR Keimig.
MARSH, B. Region 3, Chicago, Office of the Director. MARTIN, T. T.
Region 1, Philadelphia, Office of the Director. 79/06/27. 20pp.

7908300140 Transcript of 790506 TMI-2 investigation interview
w/LJ Landry.
SINCLAIR, J. R. Office of Inspector & Auditor. 79/06/27. 101pp.

7908300254 Transcript of 790507 TMI-2 investigation interview
w/JJ Kottan.
ESSIG, T. H. Region 3, Chicago, Office of the Director. RESNER, M. E.
Office of Inspector & Auditor. 79/06/27. 19pp.

7908280720 Transcript of 790509 TMI-2 investigation interview
w/EA Womack.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/06/28. 19pp.

7908290425 Transcript of 790411 TMI-2 investigation interview
w/GP Miller & J Logan.
CRESWELL, J. S., MARSH, [illegible], HUNTER, D. R. Region 3, Chicago, Office of
the Director. 79/06/28. 64pp.

7908290441 Transcript of TMI-2 investigation interview
w/M Janouski.
CRESWELL, J. S., MARSH, R. Region 3, Chicago, Office of the Director.
79/06/28. 19pp.

7908290524 Transcript of 790423 TMI-2 investigation interview
w/E Frederick.
HUNTER, D. R., MARSH, B. Region 3, Chicago, Office of the Director.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
79/06/28. 101pp.

7908290550 Transcript of 790423 TMI-2 investigation interview
w/PP Velez.
YUHAS, G. P., DONALDSON, D. E. Region 1, Philadelphia, Office of the
Director. SHACKLETON, D. C. Region 5, San Francisco, Office of the
Director. 79/06/28. 133pp.

7908290733 Transcript of 790503 TMI-2 investigation interview
w/ML Benson & HC Crawford.
MARTIN, T. T. Region 1, Philadelphia, Office of the Director.
ESSIG, T. H. Region 3, Chicago, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/06/29. 101pp.

7908300101 Transcript of 790330 TMI-2 investigation interview
w/C Faust & J Gingrich.
MARSH, B. Region 3, Chicago, Office of the Director. 79/06/28.
34pp.

7908300104 Transcript of 790507 TMI-2 investigation interview
w/WH Baunack.
MARSH, B. Region 3, Chicago, Office of the Director. MARTIN, T. T.
Region 1, Philadelphia, Office of the Director. 79/06/28. 45pp.

7908300160 Transcript of 790507 TMI-2 investigation interview
w/MK Gabner.
RESNER, M. E. Office of Inspector & Auditor. YUHAS, G. P. Region 1,
Philadelphia, Office of the Director. 79/06/28. 30pp.

7908300216 Transcript of 790507 TMI-2 investigation interview
w/GP Miller.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/06/28. 38pp.

7908280705 Transcript of 790508 TMI-2 investigation interview
w/RW Winks, represented by BD Nelson.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/06/29. 20pp.

7908280709 Transcript of 790508 TMI-2 investigation interview
w/RC Twilley.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/06/29. 20pp.

7908280715 Transcript of 790509 TMI-2 investigation interview
w/JJ Kelly.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/06/29. 31pp.

7908280727 Transcript of 790509 TMI-2 investigation interview
w/JC Deddens, represented by BD Nelson.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/06/29. 24pp.

7908280756 Transcript of 790515 TMI-2 investigation interview
w/ED Yochheim.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
SINCLAIR, J. R. Office of Inspector & Auditor. 79/06/29. 28pp.

7908290093 Transcript of 790521 TMI-2 investigation interview
w/KH Frederick.
RESNER, M. E. Office of Inspector & Auditor. YUHAS, G. P. Region 1,
Philadelphia, Office of the Director. JACKSON, L. L. Region 2,
Atlanta, Office of the Director. 79/06/29. 26pp.

7908290485 Transcript of 790422 TMI-2 investigation interview
w/T Daugherty.
MARSH, R., CRESWELL, J. S. Region 3, Chicago, Office of the Director.
79/06/29. 35pp.

7908300126 Transcript of 790507 TMI-2 investigation interview
w/W Madden.
MARSH, B. Region 3, Chicago, Office of the Director. 79/06/29.
21pp.

7908280688 Transcript of 790508 TMI-2 investigation interview
w/EC Egenrieder.
SINCLAIR, J. R. Office of Inspector & Auditor. YUHAS, G. P. Region
1, Philadelphia, Office of the Director. COLLINS, D. M. Region 2,
Atlanta, Office of the Director. 79/06/30. 103pp.

7908280696 Transcript of 790509 TMI-2 investigation interview
w/JB Logan.
SINCLAIR, J. R. Office of Inspector & Auditor. HUNTER, D. R. Region
3, Chicago, Office of the Director. FASANO, A. N. Region 1,
Philadelphia, Office of the Director. 79/06/30. 97pp.

7908290453 Transcript of 790420 & 22 TMI-2 investigation interview
w/FM Huwe.
DONALDSON, D. E., YUHAS, G. P. Region 1, Philadelphia, Office of the
Director. SHACKLETON, D. C. Region 5, San Francisco, Office of the
Director. 79/06/30. 146pp.

7908290593 Transcript of 790425 TMI-2 investigation interview
w/ex-radiation chemistry senior.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/06/30. 110pp.

7908290635 Transcript of 790502 TMI-2 investigation interview
w/ED Showalter.
SINCLAIR, J. R., RESNER, M. E. Office of Inspector & Auditor.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/06/30. 37pp.

7908290640 Transcript of 790502 TMI-2 investigation interview
w/JR Floyd.
RESNER, M. E. Office of Inspector & Auditor. HUNTER, D. R.,
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
79/06/30. 33pp.

7908290692 Transcript of 790502 TMI-2 investigation interview
w/DR Neely.
RESNER, M. E., SINCLAIR, J. R. Office of Inspector & Auditor.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
79/06/30. 46pp.

7908280680 Transcript of 790509 TMI-2 investigation interview
w/LO Wright.
SINCLAIR, J. R. Office of Inspector & Auditor. 79/07/01. 34pp.

7908280745 Transcript of 790510 TMI-2 investigation interview
w/J Herbein.
MARSH, R. Region 3, Chicago, Office of the Director. GIBSON, A. F.
Region 2, Atlanta, Office of the Director. 79/07/01. 35pp.

7908280763 Transcript of 790515 TMI-2 investigation interview
w/FL Bronson.
MARSH, R., ESSIG, T. H. Region 3, Chicago, Office of the Director.
79/07/01. 39pp.

7908290431 Transcript of 790412 TMI-2 investigation interview
w/WH Zewe.
CRESWELL, J. S., HUNTER, D. R., MARSH, R. Region 3, Chicago, Office of
the Director. 79/07/01. 74pp.

7908280657 Transcript of 790508 TMI-2 investigation interview
w/RL Benner & ML Kuhn.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
SINCLAIR, J. R. Office of Inspector & Auditor. 79/07/02. 50pp.

7908280666 Transcript of 790508 TMI-2 investigation interview w/RW Dubiel.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
RESNER, M. E. Office of Inspector & Auditor. ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/07/02. 63pp.

7908280674 Transcript of 790508 TMI-2 investigation interview w/R Zechman, N Brown, D Boltz & M Beers.
MARSH, R. Region 3, Chicago, Office of the Director.
KIRKPATRICK, D. C. Office of Inspection & Enforcement, Office of the Director. 79/07/02. 58pp.

7908280775 Transcript of 790516 TMI-2 investigation interview w/TE Davis.
RESNER, M. E. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/07/02. 63pp.

7908280802 Transcript of 790517 TMI-2 investigation interview w/BA Mehler.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/02. 45pp.

7908290476 Transcript of 790421 TMI-2 investigation interview w/C Faust.
MARSH, R., HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/02. 90pp.

7908290491 Transcript of 790422 TMI-2 investigation interview w/T Daugherty.
MARSH, R., CRESWELL, J. S. Region 3, Chicago, Office of the Director. 79/07/02. 31pp.

7908290503 Transcript of 790422 TMI-2 investigation interview w/AW Miller.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director. 79/07/02. 19pp.

7908290515 Transcript of 790422 TMI-2 investigation interview w/GR Hitz.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director. 79/07/02. 19pp.

7908290519 Transcript of 790423 TMI-2 investigation interview w/FJ Scheimann.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director. 79/07/02. 54pp.

7908290539 Transcript of 790423 TMI-2 investigation interview w/W Zewe.
CRESWELL, J. S., MARSH, R., HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/02. 76pp.

7908290610 Transcript of 790425 TMI-2 investigation interview w/MJ Ross.
KIRKPATRICK, D. C. Office of Inspection & Enforcement, Office of the Director. HUNTER, D. R. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director. 79/07/02. 59pp.

7908290633 Transcript of 790501 TMI-2 investigation interview w/SR Finicle.
MARSH, R. Region 3, Chicago, Office of the Director.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director. 79/07/02. 37pp.

7908290666 Transcript of 790330 TMI-2 investigation interview w/S Mull.
* Office of Inspection & Enforcement, Office of the Director. 79/07/02. 33pp.

7908300247 Transcript of 790507 TMI-2 investigation interview w/WJ Pusansky & JF Stacey.
DONALDSON, D. E., YUHAS, G. P. Region 1, Philadelphia, Office of the Director. RESNER, M. E. Office of Inspector & Auditor. 79/07/02. 52pp.

7908280733 Transcript of 790509 TMI-2 investigation interview w/DW Ethridge & KL Myers.
ESSIG, T. H. Region 3, Chicago, Office of the Director. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. RESNER, M. E. Office of Inspector & Auditor. 79/07/03. 81pp.

7908280739 Transcript of 790509 TMI-2 investigation interview w/R Arnold.
MARSH, R. Region 3, Chicago, Office of the Director. GIBSON, A. F. Region 2, Atlanta, Office of the Director. 79/07/03. 39pp.

7908280799 Transcript of 790517 TMI-2 investigation interview w/RK Fountain.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
BINION, T. Office of Inspector & Auditor. 79/07/03. 48pp.

7908280807 Transcript of 790517 TMI-2 investigation interview w/JP Donnachie.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
RESNER, M. E. Office of Inspector & Auditor. 79/07/03. 65pp.

7908280860 Transcript of 790519 TMI-2 investigation interview w/FD Telenko.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
FOSTER, W. H. Office of Inspector & Auditor. 79/07/03. 19pp.

7908290067 Transcript of 790521 TMI-2 investigation interview w/DM Shovlin.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
FOSTER, W. H. Office of Inspector & Auditor. 79/07/03. 94pp.

7908290083 Transcript of 790521 TMI-2 investigation interview w/ID Porter.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
FOSTER, W. H. Office of Inspector & Auditor. 79/07/03. 46pp.

7908290099 Transcript of 790521 TMI-2 investigation interview w/DR Miller.
RESNER, M. E. Office of Inspector & Auditor. FASANO, A. N. Region 1, Philadelphia, Office of the Director. 79/07/03. 35p.

7908290104 Transcript of 790521 TMI-2 investigation interview w/TL Mulleavy.
RESNER, M. E. Office of Inspector & Auditor. DONALDSON, D. E. Region 1, Philadelphia, Office of the Director. ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/07/03. 113pp.

7908290123 Transcript of 790522 TMI-2 investigation interview w/SL Mull.
FOSTER, W. H. Office of Inspector & Auditor. HUNTER, W. T. Region 3, Chicago, Office of the Director. FASANO, A. N. Region 1, Philadelphia, Office of the Director. 79/07/03. 19pp.

7908290133 Transcript of 790522 TMI-2 investigation interview w/WH Metzger.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
MARSH, R., CRESWELL, J. S. Region 3, Chicago, Office of the Director. 79/07/03. 44pp.

7908290170 Transcript of 790523 TMI-2 investigation interview w/V Cooper.
RESNER, M. E. Office of Inspector & Auditor. MARTIN, R. D. Region 2, Atlanta, Office of the Director. HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/03. 33pp.

7908290172 Transcrip. of 790522 TMI-2 investigation interview w/JG Reed.
JACKSON, L. L. Office of Inspector & Auditor. FOSTER, W. H. Region 2, Atlanta, Office of the Director. 79/07/03. 33pp.

7908290186 Transcript of 790522 TMI-2 investigation interview w/ex-control room operator.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
CRESWELL, J. S., MARSH, R. Region 3, Chicago, Office of the Director. 79/07/03. 75pp.

7908290653 Transcript of 790330 TMI-2 investigation interview w/DR Miller & E Frederick.
KIRKPATRICK, D. Office of Inspection & Enforcement, Office of the Director. 79/07/03. 40pp.

7908290695 Transcript of 790412 TMI-2 investigation interview w/R Dubiel, J Hilbish & G Miller.
* Office of Inspection & Enforcement, Office of the Director. 79/07/03. 51pp.

7908300150 Transcript of 790507 TMI-2 investigation interview w/EG Schaedel.
RESNER, M. E. Office of Inspector & Auditor. CRESWELL, J. S. Region 3, Chicago, Office of the Director. 79/07/03. 26pp.

7908300229 Transcript of 790507 TMI-2 investigation interview w/GP Miller.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director. 79/07/03. 77pp.

DOCKETED ITEMS

7908290140 Transcript of 790522 TMI-2 investigation interview w/HC Crawford.
ESSIG, T. H. Region 3, Chicago, Office of the Director. RESNER, M. E. Office of Inspector & Auditor. 79/07/04. 31pp.

7908290191 Transcript of 790523 TMI-2 investigation interview w/GA Kunder.
FOSTER, W. H. Office of Inspector & Auditor. HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/04. 60pp.

7908290195 Transcript of 790524 TMI-2 investigation interview w/JK Lionarons.
RESNER, M. E. Office of Inspector & Auditor. HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/04. 46pp.

7908290210 Transcript of 790523 TMI-2 investigation interview w/HL Wilson.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/07/04. 21pp.

7908290215 Transcript of 790523 TMI-2 investigation interview w/TF Illjes.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
RESNER, M. E. Office of Inspector & Auditor. 79/07/04. 21pp.

7908290232 Transcript of 790524 TMI-2 investigation interview w/EW Houser.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/07/04. 12pp.

7908290256 Transcript of 790524 TMI-2 investigation interview w/DE Weaver.
RESNER, M. E. Office of Inspector & Auditor. FASANO, A. N. Region 1, Philadelphia, Office of the Director. CRESWELL, J. S. Region 3, Chicago, Office of the Director. 79/07/04. 69pp.

7908290299 Transcript of 790429 TMI-2 investigation interview w/J Floyd.
* Office of Inspection & Enforcement, Office of the Director.
79/07/04. 6pp.

7908300274 Transcript of 790508 TMI-2 investigation interview w/A Tsaggaris.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
ESSIG, T. H. Region 3, Chicago, Office of the Director. RESNER, M. E. Office of Inspector & Auditor. 79/07/04. 38pp.

7908290149 Transcript of 790517 TMI-2 investigation interview w/GA Kunder.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
MARTIN, T. T. Region 1, Philadelphia, Office of the Director.
RESNER, M. E. Office of Inspector & Auditor. 79/07/05. 49pp.

7908290160 Transcript of 790522 TMI-2 investigation interview w/KL Harner.
FOSTER, W. H. Office of Inspector & Auditor. COLLINS, D. M. Region 2, Atlanta, Office of the Director. 79/07/05. 30pp.

7908290179 Transcript of 790522 TMI-2 investigation interview w/R Dubiel.
FOSTER, W. H. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/07/05. 117pp.

7908290264 Transcript of 790524 TMI-2 investigation interview w/SW Porter.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
ESSIG, T. H. Region 3, Chicago, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/07/05. 63pp.

7908290273 Transcript of 790529 TMI-2 investigation interview w/E Frederick, C Faust, F Scheimann, B Zewe & M Ross.
MARTIN, T. T. Region 1, Philadelphia, Office of the Director.
MARTIN, R. D. Region 2, Atlanta, Office of the Director.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
79/07/05. 44pp.

7908290283 Transcript of 790530 TMI-2 investigation interview w/KE Plumlee & RL Nimitz.
RESNER, M. E. Office of Inspector & Auditor. ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/07/05. 51pp.

7908290309 Transcript of 790420 TMI-2 investigation interview w/J Flint.
* Office of Inspection & Enforcement, Office of the Director.
79/07/05. 14pp.

7908290316 Transcript of 790601 TMI-2 investigation interview w/WE Diebler & TE Pyke.
RESNER, M. E. Office of Inspector & Auditor. DONALDSON, D. E., YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
79/07/05. 71pp.

7908290320 Transcript of 790601 TMI-2 investigation interview w/JJ Allen.
RESNER, M. E. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/07/05. 71pp.

7908290324 Transcript of 790602 TMI-2 investigation interview w/JR Floyd.
COLLINS, D. M. Region 2, Atlanta, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/07/05. 71pp.

7908290347 Transcript of 790531 TMI-2 investigation interview w/J Hilbish & R Lefin.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
MARSH, B., ESSIG, T. H. Region 3, Chicago, Office of the Director.
79/07/05. 10pp.

7908290357 Transcript of 790531 TMI-2 investigation interview w/RN Klingaman.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
ESSIG, T. H., MARSH, R. Region 3, Chicago, Office of the Director.
79/07/05. 35pp.

7908290379 Transcript of 790531 TMI-2 investigation interview w/BJ Beck.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
ESSIG, T. H., MARSH, B. Region 3, Chicago, Office of the Director.
79/07/05. 11pp.

7908290386 Transcript of TMI-2 investigation interview w/B Mehler.
* Office of Nuclear Reactor Regulation. 79/07/05. 22pp.

7908290404 Transcript of TMI-2 investigation interview w/C Faust.
* Office of Nuclear Reactor Regulation. 79/07/05. 24pp.

7908280632 Transcript of 790601 TMI-2 investigation interview of R Wilson, Met Ed, in Middletown, PA. Pp 1-31.
MARSH, R. Region 3, Chicago, Office of the Director. FASANO, A. N. Region 1, Philadelphia, Office of the Director. WILSON, R. Metropolitan Edison Co. 79/07/06. 32pp.

7908290292 Transcript of TMI-2 investigation interview w/B Zewe.
* Office of Inspection & Enforcement, Office of the Director.
79/07/06. 49pp.

7908290371 Transcript of 790531 TMI-2 investigation interview w/JE Mudge.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
ESSIG, T. H., MARSH, R. Region 3, Chicago, Office of the Director.
79/07/06. 34pp.

7908290384 Transcript of 790601 TMI-2 investigation interview w/JR Thorpe.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
MARSH, R. Region 3, Chicago, Office of the Director. 79/07/06. 15pp.

7908280783 Transcript of 790516 TMI-2 investigation interview w/TE Pyke.
BINION, T. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. MARSH, B. Region 3, Chicago, Office of the Director. 79/07/07. 43pp.

7908230462 Transcript of 790709 subcommittee meeting in Washington, DC on TMI-2 accident & bulletins.
* ACRS - Advisory Committee on Reactor Safeguards. 79/07/09. 230pp.

7908280772 Transcript of 790516 TMI-2 investigation interview w/K Bryan.
SINCLAIR, J. R., BINION, T. Office of Inspector & Auditor. HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/09. 54pp.

7908280779 Transcript of 790516 TMI-2 investigation interview w/WS Wilkerson.
BINION, T. Office of Inspector & Auditor. ESSIG, T. H., HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/09. 43pp.

7908280786 Transcript of 790517 TMI-2 investigation interview w/KE Burkholder.
COLLINS, D. M. Region 2, Atlanta, Office of the Director.
SHACKLETON, D. C. Region 5, San Francisco, Office of the Director.
79/07/09. 52pp.

7908280787 Transcript of 790517 TMI-2 investigation interview w/TV Witbeck.
MARSH, B., HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/09. 16pp.

7908280791 Transcript of 790517 TMI-2 investigation interview w/GH Smith.
GIBSON, A. F. Region 2, Atlanta, Office of the Director.
FOSTER, W. H. Office of Inspector & Auditor. 79/07/09. 23pp.

7908280795 Transcript of 790517 TMI-2 investigation interview w/WJ Marshall.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
FOSTER, W. H. Office of Inspector & Auditor. MARTIN, T. T. Region 1, Philadelphia, Office of the Director. 79/07/09. 36pp.

7908280797 Transcript of 790517 TMI-2 investigation interview w/Dauphin County, PA Civil Defense Ofc.
ESSIG, T. H. Region 3, Chicago, Office of the Director.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director. 79/07/09. 3pp.

7908280813 Transcript of 790518 TMI-2 investigation interview w/CL Guthrie.
MARTIN, T. T. Region 1, Philadelphia, Office of the Director.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
RESNER, M. E. Office of Inspector & Auditor. 79/07/09. 33pp.

7908280819 Transcript of 790518 TMI-2 investigation interview w/DC Carl.
KELLEY, C. B. Office of Inspector & Auditor. ESSIG, T. H. Region 3, Chicago, Office of the Director. SHACKLETON, O. C. Region 5, San Francisco, Office of the Director. 79/07/09. 28pp.

7908280823 Transcript of 790518 TMI-2 investigation interview w/DJ Laudermilch.
FOSTER, W. H. Office of Inspector & Auditor. MARTIN, T. T. Region 1, Philadelphia, Office of the Director. 79/07/09. 34pp.

7908280827 Transcript of 790518 TMI-2 investigation interview w/WE Potts.
KELLEY, C. B., RESNER, M. E. Office of Inspector & Auditor. ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/07/09. 48pp.

7908280837 Transcript of 790518 TMI-2 investigation interview w/HA McGovern.
MARTIN, T. T. Region 1, Philadelphia, Office of the Director.
MARTIN, R. D. Region 2, Atlanta, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director. 79/07/09. 54pp.

7908280844 Transcript of 790519 TMI-2 investigation interview w/MN Leakway.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
CRESWELL, J. S. Region 3, Chicago, Office of the Director. 79/07/09. 25pp.

7908280852 Transcript of 790519 TMI-2 investigation interview w/MJ Ross.
MARTIN, T. T. Region 1, Philadelphia, Office of the Director.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
FOSTER, W. H. Office of Inspector & Auditor. 79/07/09. 51pp.

7908280856 Transcript of 790519 TMI-2 investigation interview w/PH Shannon.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
FOSTER, W. H. Office of Inspector & Auditor. 79/07/09. 52pp.

7908290048 Transcript of 790519 TMI-2 investigation interview w/MS Coleman.
CRESWELL, J. S. Region 3, Chicago, Office of the Director.
FASANO, A. N. Region 1, Philadelphia, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director. 79/07/09. 45pp.

7908290052 Transcript of 790520 TMI-2 investigation interview w/DI Olson.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
FOSTER, W. H. Office of Inspector & Auditor. 79/07/09. 31pp.

7908290202 Transcript of 790523 TMI-2 investigation interview w/JP Stohr.
RESNER, M. E. Office of Inspector & Auditor. ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/07/09. 18pp.

7908290224 Transcript of 790523 TMI-2 investigation interview w/GR Hitz.
FOSTER, W. H. Office of Inspector & Auditor. HUNTER, D. R. Region 3, Chicago, Office of the Director. 79/07/09. 33pp.

7908290245 Transcript of 790524 TMI-2 investigation interview w/WE Deimler.
YUHAS, G. P. Region 1, Philadelphia, Office of the Director.
MARSH, R. Region 3, Chicago, Office of the Director. 79/07/09. 50pp.

7908290392 Transcript of TMI-2 investigation interview w/E Frederick.
* Office of Nuclear Reactor Regulation. 79/07/09. 3pp.

7908290399 Transcript of TMI-2 investigation interview w/K Bryan.
* Office of Nuclear Reactor Regulation. 79/07/09. 22pp.

7908290043 Transcript of 790519 TMI-2 investigation interview w/ED Hemmila.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
RESNER, M. E. Office of Inspector & Auditor. 79/07/10. 50pp.

7908290059 Transcript of 790521 TMI-2 investigation interview w/JJ Chwastyk.
HUNTER, D. R. Region 3, Chicago, Office of the Director.
MARTIN, R. D. Region 1, Philadelphia, Office of the Director.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director. 79/07/10. 55pp.

7908280623 Transcript of 790626 TMI-2 investigation interview of BR Kalenevitch, Met Ed, in Middletown, PA. Pp 1-27.
SHACKLETON, O. C. Region 5, San Francisco, Office of the Director.
KALENEVITCH, B. Metropolitan Edison Co. 79/07/17. 28pp.

7908030392 Transcript of President's Commission on Accident at TMI 790718 public hearing in Washington, DC. Pp 1-176.
KEMENY, J. G., BABBITT, B., HAGGERTY, P. E. TMI-2 Bulletins & Orders. 79/07/18. 206pp.

7908030604 Transcript of President's Commission on Accident at TMI 790719 public hearing in Washington, DC. Pp 177-358.
KEMENY, J. G., BABBITT, B., HAGGERTY, P. E. TMI-2 Bulletins & Orders. 79/07/19. 185pp.

7908030609 Transcript of President's Commission on Accident at TMI 790719 press conference in Washington, DC. Pp 1-14.
KEMENY, J. G. TMI-2 Bulletins & Orders. 79/07/19. 17pp.

7908030613 Transcript of President's Commission on Accident at TMI 790720 public hearing in Washington, DC. Pp 1-14.
KEMENY, J. G., BABBITT, B., HAGGERTY, P. E. TMI-2 Bulletins & Orders. 79/07/20. 125pp.

7908030616 Transcript of 790720 press conference in Washington, DC. Pp 1-16.
KEMENY, J. G. TMI-2 Bulletins & Orders. 79/07/20. 18pp.

7908280766 Transcript of 790516 TMI-2 investigation interview w/DF Limroth.
RESNER, M. E. Office of Inspector & Auditor. YUHAS, G. P. Region 1, Philadelphia, Office of the Director. 79/07/18. 32pp.

7908220115 Transcript of 790726 Ad Hoc Subcommittee meeting in Washington, DC re TMI accident implications. Pp 1-329.
OKRENT, D., ETHERINGTON, H., MARK, J. C. ACRS - Advisory Committee on Reactor Safeguards. 79/07/26. 330pp.

7908220126 Transcript of 790727 proceedings in Washington, DC re TMI accident implications.
SEISS, C. P., ETHERINGTON, H., MARK, J. C. ACRS - Advisory Committee on Reactor Safeguards. 79/07/27. 234pp.

7908290568 Transcript of 790424 TMI-2 investigation interview w/RW Dubiel.
DONALDSON, D. E. Region 1, Philadelphia, Office of the Director.
MARSH, R., ESSIG, T. H. Region 3, Chicago, Office of the Director. 79/07/31. 28pp.

7908130486 Transcript of 790802 public hearing by President's Commission on Accident at TMI, in Washington, DC. Pp 1-349. Proceedings transcript encl.
KEMENY, J. G., BABBITT, B., HAGGERTY, P. E. President's Commission on the Accident at Three Mile Island. 79/08/02. 369pp.

7908220076 Transcript of 790808 subcommittee meeting in Washington, DC re underlying causes contributing to TMI-2 accident. Pp 1-133.
CARBON, M. W., BENDER, M., ETHERINGTON, H. ACRS - Advisory Committee on Reactor Safeguards. 79/08/08. 134pp.

7908290107 Transcript of 790821 hearing in Washington, D. C. Pp. 1-77.
* TMI-2 Bulletins & Orders. 79/08/21. 100pp.

U. Congressional/Executive Correspondence

7908230016 Requests comments on encl 790401 ltr from TR Franz to Senator Metzenbaum re flight taken over TMI on 790823.
METZENBAUM, H. M. Senate. 79/04/09. 2pp.

7908210215 Requests govt publications re TMI. Constituents request explanation of dangers of nuclear accidents & consequences of meltdown.
WALKER, R. S. House of Rep. 79/04/10. 1p.

7908220102 Responds to verbal question from Senator Chauty of France re TMI accident. Low probability of accident in France.
GIRAUD, A. France. 79/04/24. 6pp.

7907020277 Replies to 790416 ltr forwarding KE Beckwith inquiry re right of util to pass accident costs on to rate-paying customers. Rate setting is function of state public svc commission or other state agency, not NRC.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/05/25. 1p.

7907260314 Ack receipt of 790516 ltr requesting NRC rept on Price-Anderson Act. Forwards "Selected Matls on Atomic Energy Indemnity & Insurance Legislation" & relevant chapter of NRC Annual Rept to Congress 1978.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/06/12. 3pp.

--7907260324 Requests NRC rept on Price-Anderson Act, on behalf of M Ergueta.
MICA, D. A. House of Rep. 79/05/16. 1p.

7907260295 Informs that A Grosse suggestion that plants mark release of radioactive gases w/colored smoke or odorous substance has too many limitations to be effective. Forwards "Evaluation of Smoke or Odorous Substance Release w/Radioactive Plumes."
GOSSICK, L. V. Office of the Executive Director for Operations. 79/06/13. 4pp.

--7907260305 Forwards AV Grosse 790426 ltr suggesting that releases of radioactivity be marked by coloring of plume. Requests review of suggestion.
COUGHLIN, L. House of Rep. 79/05/03. 2pp.

7908010105 Responds to request for info re adequacy & accuracy of population dose assessment. Summarizes info obtained. Forwards "Population Dose & Health Impact of Accident at TMI." W/o encl.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/19. 2pp.

DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

7908130189 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908270468 Forwards physical security plan for training & qualifying security personnel. Plan withheld (ref 10CFR2.790).
KELLY, R. J. Georgia Power Co. 79/08/17. 1p.

H. General correspondence

7908150679 Submits info re corporate capabilities, in response to NRC 790629 request.
KELLY, R. J. Georgia Power Co. 79/08/10. 200pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908020322 Confirms 790702 telcon in which NRC concurred w/planned schedule for returning reactor to svc. Concurrence based on investigation results & planned retesting program.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/05. 2pp.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908170577 Forwards Amend 67 to License DPR-57, safety evaluation & notice of issuance & availability.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/17. 2pp.

--7908170585 Amend 67 to License DPR-57, revising turbine control valve fast closure setpoint on low electrohydraulic control oil pressure.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/17. 4pp.

--7908170590 Safety evaluation supporting Amend 67 to License DPR-57.
* Office of Nuclear Reactor Regulation. 79/07/17. 3pp.

--7908170597 Notice of issuance & availability of Amend 67 to License DPR-57.
ROONEY, V. L. Operating Reactors Branch 3. 79/07/17. 2pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070316 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908270482 Forwards request for addl info to be sent to licensee in order to complete review of 770722 submittal re technical assistance contract 10026. Response required within 45 days.
LAINAS, G. Plant Systems Branch. 79/07/23. 3pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908030148 Forwards Amend 1 to spent fuel pool mod rept, revising pages dealing w/stress analysis results applicable to high density fuel storage modules.
KELLY, R. J. Georgia Power Co. 79/07/27. 6pp.

7908270101 Forwards Amend 68 to License DPR-57 & notice of issuance & availability.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/31. 3pp.

--7908270107 Amend 68 to License DPR-57, changing Tech Specs in App A re fire protection sys.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/31. 2pp.

--7908270112 Revised pages of App A Tech Specs for License DPR-57 re fire protection sys. Forwarded by Amend 68.
* Operating Reactors Branch 3. 79/07/31. 4pp.

--7908270116 Notice of issuance & availability of Amend 68 to License DPR-57.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/31. 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908300355 Notifies of 790822 meeting w/util in Atlanta, GA to discuss emergency planning & implementing procedures. Agenda encl.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/06. 3pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09 5pp.

7908240207 Forwards request for addl info re end-of-cycle recirculation pump trip.
LAINAS, G. Plant Systems Branch. 79/08/14 3pp.

Q. Inspection reports, IE Bulletins & correspondence

7908090160 FOIA request for copies of NRC insp repts for 770301-0415 & Jan-Apr 1978 NRC bulletins & other documents re anchor bolt problems & alleged tritium leakage at plants.
REAGER, D.W. Wisoff, Reager, Selkowitz & Adler. 79/06/08 1p.

7908020361 Responds to IE Bulletin 79-11. No Westinghouse Type DB-50 or DB-75 circuit breakers have been used.
STAFFA, R.W. Georgia Power Co. 79/06/19 1p.

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 79/06/20 44pp.

7908020251 Supplements 790416 response to IE Bulletin 79-03. Forwards summary of ultrasonic test results on 12-inch recirculation loop A jet pump risers. W/o encl.
STAFFA, R.W. Georgia Power Co. 79/06/22 1p.

7908070142 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/06/28 2pp.

7908080570 Forwards EDS Nuclear, Inc 790419 response to IE Bulletin 79-07. None of methods described in Item 1 of bulletin were used in computer programs for seismic analysis of safety-related pipe at plant.
STAFFA, R.W. Georgia Power Co. 79/06/26 39pp.

7908030495 Forwards examination summary records that were inadvertently omitted from util 790622 response to IE Bulletin 79-03.
STAFFA, R.W. Georgia Power Co. 79/06/27 11pp.

7908230426 Advises that C-E rept, "Info Requested by IE Bulletin 78-12, Atypical Weld Matl in Reactor Pressure Vessel Welds," submitted to NRC on 790608, contains generic coverage of weld matl & testing programs used by licensee.
STAFFA, R.W. Georgia Power Co. 79/06/29 1p.

7908300729 Notifies that opening paragraph of 790629 ltr should ref IE Bulletin 78-12.
STAFFA, R.W. Georgia Power Co. 79/07/03 1p.

7908010031 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/06 2pp.

7908310042 Forwards response to IE Bulletin 79-02 per 790308 ltr re pipe support base plate designs using concrete expansion anchor bolts. Outlines verification program for pipe support base plate rigidity.
STAFFA, R.W. Georgia Power Co. 79/07/06 11pp.

7908030134 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/13 2pp.

7908130390 Ack receipt of IE Insp Repts 50-321/79-16 & 50-366/79-20 on 790605-08. No proprietary info.
STAFFA, R.W. Georgia Power Co. 79/07/13 1p.

--7908130400 Forwards IE Insp Repts 50-321/79-16 & 50-366/79-20 on 790605-08. No noncompliance noted.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25 2pp.

--7908150407 IE Insp Repts 50-321/79-16 & 50-366/79-20 on 790605-08. No noncompliance noted. Major areas inspected: plant procedures.
MOON, B.T., LIM, J.C., RUHLMAN, W.A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/22 6pp.

7908010414 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/17 2pp.

7908030013 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908080046 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908130124 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908160469 Ack receipt of IE Insp Rept 50-321/79-15. No proprietary info.
STAFFA, R.W. Georgia Power Co. 79/07/18 1p.

--7908160475 Forwards IE Insp Rept 50-321/79-15. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/25 2pp.

--7908160478 IE Insp Rept 50-321/79-15 on 790606-08. No noncompliance noted. Major areas inspected: concrete expansion anchor.
VALLISH, E.J. Region 2, Atlanta, Office of the Director. 79/06/22 3pp.

7908160481 Ack receipt of 790711 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/79-12 & 50-366/79-16.
SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/19 1p.

--7908160488 Responds to NRC 790615 ltr re violations noted in IE Insp Repts 50-321/79-12 & 50-366/79-16. Corrective actions: high radiation doors inspected daily & wire mesh on heat exchanger room door repaired.
STAFFA, R.W. Georgia Power Co. 79/07/11 2pp.

--7908160490 Forwards IE Insp Repts 50-321/79-12 & 50-366/79-16 on 790507-11 & notice of violation.
SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/15 2pp.

--7908160489 Notice of violation from insp on 790507-11.
* Region 2, Atlanta, Office of the Director. 79/06/12 1p.

--7908160491 IE Insp Repts 50-321/79-12 & 50-366/79-16 on 790507-11. Noncompliance noted: failure to perform survey, failure to keep high radiation area locked & failure to submit radiological section of annual environ surveillance rept.
HOSEY, C.M. Region 2, Atlanta, Office of the Director.
JENKINS, G.R. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/12 8pp.

7908080319 Requests addl info to suppl previous response to IE Bulletin 79-08, to enable NRC to complete safety evaluation.
IPPOLITO, T.A. Operating Reactors Branch 3. 79/07/20 4pp.

7908090171 Responds to FOIA request for insp repts, bulletins & other documents related to tritium leakage at facilities. Forwards leakage accession list & LER output from 1969 to present.
FELTON, J.M. Division of Rules and Records. 79/07/20 1p.

7908170555 Ack receipt of 790717 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/79-18 & 50-366/79-22.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/20 1p.

--7908170562 Responds to NRC 790626 ltr re violations noted in IE Insp Repts 50-321/79-18 & 50-366/79-22. Corrective actions: re-evaluated all operating personnel & reviewed files of licensed operators. Expected completion date 790815.
STAFFA, R.W. Georgia Power Co. 79/07/17 1p.

--7908170565 Forwards IE Insp Repts 50-321/79-18 & 50-366/79-22 on 790604-05 & notice of violation.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/26 2pp.

--7908170568 Notice of violation from insp on 790604-05.
* Region 2, Atlanta, Office of the Director. 79/06/25. 1p.

--7908170573 IE Insp Repts 50-321/79-18 & 50-366/79-22 on 790604-05. Noncompliance noted: failure to follow procedures re training & retraining programs.
RUHLMEN, W. A., JENKINS, H. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 6pp.

7908210150 Summary of 790711 meeting w/GA Conservancy in Atlanta, GA re licensing process, insp program & TMI accident. Forwards 790510 rept "Population Dose & Health Impact of Accident at TMI" & NUREG-0396. W/o encl.
O'REILLY, J. P. Region 3, Chicago, Office of the Director. 79/07/20. 3pp.

7908080716 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908080741 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908230669 Responds to NRC 790531 ltr requesting info re IE Bulletin 79-12. Mods will be performed to rod withdrawal sequence to assure against reccurence of fast period scrams.
WIDNER, W. A. Georgia Power Co. 79/07/26. 3pp.

7908160236 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908160310 Ack receipt of IE Insp Repts 50-321/79-19 & 50-366/79-24 on 790618-22. No proprietary info.
WIDNER, W. A. Georgia Power Co. 79/07/27. 1p.

--7908160319 Forwards IE Insp Repts 50-321/79-19 & 50-366/79-24 on 790618-22. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/09. 2pp.

--7908160327 IE Insp Repts 50-321/79-19 & 50-366/79-24 on 790618-22. No noncompliance noted. Major areas inspected: radioactive waste mgt program, including radioactive effluent release monitoring & records & repts for radioactive effluents.
HOSEY, C. M., WRAY, J. R., JENKINS, G. R. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/09. 5pp.

7908220684 Responds to IE Bulletin 79-14 & NRC 790702 ltr requesting identification of certain items re verification of seismic analysis. Relevant info encl.
WIDNER, W. A. Georgia Power Co. 79/08/01. 41pp.

7908210304 Ack receipt of 790702 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/79-13 & 50-366/79-17.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/08/03. 1p.

--7908210310 Responds to NRC 790611 ltr re violations noted in IE Insp Repts 50-321/79-13 & 50-366/79-17. Corrective actions withheld (ref 10CFR2.790).
STAFFA, R. W. Georgia Power Co. 79/07/02. 1p.

--7908210316 Forwards IE Insp Repts 50-321/79-13 & 50-366/79-17 on 790514-18. Notice of violation withheld (ref 10CFR2.790).
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/06/11. 2pp.

--7908210320 IE Insp Repts 50-321/79-13 & 50-366/79-17 on 790514-18. Noncompliance noted: designated vehicle improperly secured in protected area. Details withheld (ref 10CFR2.790).
PERRY, C. D. Region 2, Atlanta, Office of the Director.
TOBIN, W. J. Region 2, Atlanta, Safeguards Branch. 79/06/08. 1p.

7908160148 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

7908170013 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08. 2pp.

7908160403 Responds to 790720 request & forwards addl info re IE Bulletin 79-08. Standing order issued 790515 as interim means of implementing reporting requirements of Item 9 of bulletin.
KELLY, R. J. Georgia Power Co. 79/08/10. 6pp.

7908290200 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/10. 1p.

7908280462 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

R. Periodic operating reports & related correspondence

7908150513 Forwards monthly operating rept for Jul 1979.
MANRY, M. Georgia Power Co. 79/08/08. 1p.

--7908150519 Monthly operating rept for Jul 1979.
ALLEN, P. B. Georgia Power Co. 79/08/08. 9pp.

S. Reportable occurrences, LERs & related correspondence

7908030389 Notifies of RO 50-321/79-47 on 790619 while reviewing supports on reactor core isolation cooling torus suction line to replace expanion anchors. Found guide bars required to provide lateral restraint already installed.
MANRY, M. Georgia Power Co. 79/06/19. 2pp.

7908100243 Outlines util actions to be taken re failure of HPCI & reactor core isolation cooling sys to perform as designed following reactor trip on 790627.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/28. 2pp.

7908020444 Notifies of RO 50-321/1979-43 on 790629: radwaste sump discharge piping not adequately installed per seismic Class I requirements. Caused by design error. Piping & design deficiency will be modified.
MANRY, M. Georgia Power Co. 79/06/29. 2pp.

7908020439 Notifies of RO 50-321/1979-48 on 790720: overcurrent trips for essential motor control centers R24-S011 & R24-S012 were 300 amp instead of 600 amp. Caused by oversight. Trip devices replaced.
MANRY, M. Georgia Power Co. 79/07/20. 2pp.

7908020427 Forwards LER 79-044/03L-0.
MANRY, M. Georgia Power Co. 79/07/26. 1p.

--7908020434 LER 79-044/03L-0 on 790704: while loading fuel assemblies into reactor vessel, determined that source range monitors functional test had not been performed prior to fuel loading. Test immediately performed. Caused by review delay.
COGGIN, C. L. Georgia Power Co. 79/07/26. 1p.

7908140678 RO 50-321/1979-50, Revision 0 on 790726: while in shutdown for maint & refueling pump 1C RHR found to have excessive leak at mechanical seal. Caused by ruptured seal. Ruptured seal replaced.
MANRY, M. Georgia Power Co. 79/07/26. 1p.

7908020421 Forwards LER 79-047/01T-0.
MANRY, M. Georgia Power Co. 79/07/27. 1p.

--7908020426 LER 79-047/01T-0 on 790718: during review of E51-RC1CH & E51-RC1H-17 supports on reactor core isolation cooling torus suction line, discovered guide bars for lateral restraint not installed. Supports to be installed.
COGGIN, C. L. Georgia Power Co. 79/07/27. 2pp.

7908030506 Forwards LER 79-021/03L-4.
MANRY, M. Georgia Power Co. 79/07/30. 1p.

--7908030511 LER 79-021/03L-4 on 790320: updates 790326 rept discussing possible further investigation of elevated tritium concentrations in groundwater samples collected in protected area near facility.
* Georgia Power Co. 79/07/30. 51pp.

7908060460 Forwards LER 79-050/01T-0.
MANRY, M. Georgia Power Co. 79/07/30. 1p.

--7908060463 LER 79-050/01T-0 on 790725 w/reactor in shutdown cooling mode, 1C RHR pump (E11-C002C) was found to have excessive leakage at mechanical seal Caused by rupture of mechanical seal Seal replaced & pump returned to svc.
* Georgia Power Co. 79/07/30. 1p.

7908060469 Forwards LER 79-048/01T-0.
MANRY, M. Georgia Power Co. 79/07/30. 1p.

--7908060474 LER 79-048/01T-0 on 790719 w/reactor shut down for refueling, overcurrent trip devices in supply breakers for reactor bldg motor control ctr were found to be 300 amp instead of 600 amp. Caused by personnel error.
COGGIN, C. L. Georgia Power Co. 79/07/30. 3pp.

7908 70695 Forwards LER 79-049/03L-0.
MANRY, M. Georgia Power Co. 79/08/01. 1p.

--7908070699 LER 79-049/03L-0 on 790718 during refueling shutdown, discovered that Tech Specs 3.2-11, Item 8, had been revised to include recorder requirement, but procedure HNP-1-3880M was not. Caused by personnel oversight. Procedure revised.
NIX, R. T. Georgia Power Co. 79/08/01. 1p.

7908130410 Forwards LER 79-026/03L-1.
MANRY, M. Georgia Power Co. 79/08/03. 1p.

--7908130415 LER 79-026/03L-1 on 790422 failure of MSIVs B21-F028A & B21-F028B valves to close in 3-5. B21-F028A valve low on hydraulic fluid, which was added. B21-F028B needle valve adjusted.
NIX, R. T. Georgia Power Co. 79/08/03. 1p.

7908130464 RO 50-321/79-56 on 790803 while performing hanger rework in response to IE Bulletin 79-02, discovered recirculation test test line B not seismically supported. Caused by design error.
MANRY, M. Georgia Power Co. 79/08/03. 2pp.

7908130476 RO-50-321/79-55 on 790803. Relay coil E11-K126 in panel H11-P618 was found to not energize while performing HNP-1-3153-E. Cause under investigation. Relay replaced; sys restored to original functional status.
MANRY, M. Georgia Power Co. 79/08/03. 2pp.

7908150651 RO 50-321/79-56 on 790803 while performing hanger rework, found piping section which was not seismically supported. Caused by design error. Piping will be made seismic before reactor startup.
MANRY, M. Georgia Power Co. 79/03/03. 1p.

7908140802 Forwards LER 79-037/01T-1.
MANRY, M. Georgia Power Co. 79/08/07. 1p.

--7908140806 LER 79-037/01T-1 on 790612 limit switches on main steam isolation valves B21-F022A, B, C & D did not have complete temp & radiation qualification test rept. Caused by procedural change. New switch ordered.
COGGIN, C. L. Georgia Power Co. 79/07/23. 2pp.

7908200262 Forwards LER 79-051/03L-0.
MANRY, M. Georgia Power Co. 79/08/10. 1p.

--7908200267 LER 79-051/03L-0 on 790726 during cold shutdown, while performing Design Change Request 78-201, control power cables to E11-F008 valve were disconnected & cut w/valve in open position. Caused by personnel error. Valve reconnected.
NIX, R. T. Georgia Power Co. 79/08/10. 2pp.

7908200281 Forwards LER 79-054/06T-0.
MANRY, M. Georgia Power Co. 79/08/10. 1p.

--7908200285 LER 79-054/06T-0 on 790802 during monthly inventory of onsite SNM, discovered three detectors had been mistakenly shipped off site for disposal w/o authorization. Caused by improper tagging. Procedure changes submitted.
COGGIN, C. I. Georgia Power Co. 79/08/10. 2pp.

7908240335 Forwards LER 79-055/01T-0.
MANRY, M. Georgia Power Co. 79/08/10. 1p.

--7908240393 LER 79-055/01T-0 on 790827 cross-channel logic automatic start relay for RHR pump D failed to energize. Caused by incorrect relay wiring. Relay replaced & retested.
COGGIN, C. L. Georgia Power Co. 79/08/10. 2pp.

7908200272 Forwards LER 79-056/01T-0.
MANRY, M. Georgia Power Co. 79/08/13. 1p.

--7908200273 LER 79-056/01T-0 on 790803 during performance of hanger rework project, discovered section of piping crossfied not supported per Seismic Class I requirements. Caused by design error. Piping upgraded.
COGGIN, C. L. Georgia Power Co. 79/08/13. 2pp.

7908240367 Forwards LER 79-052/03L-0.
MANRY, M. Georgia Power Co. 79/08/15. 1p.

--7908240377 LER 79-052/03L-0 on 790722 plant review board meeting 79-169 was held w/three alternates, contrary to Tech Spec administrative procedure HNP-6. Caused by misinformation re quorum requirements. Quorum requirements reviewed again.
COGGIN, C. L. Georgia Power Co. 79/08/14. 2pp.

7908270380 RO 50-321/1979-64 on 790814 RHR svc water pumps would not pass min flow requirements. Caused by installation error. Modified design was approved.
MANRY, M. Georgia Power Co. 79/08/15. 2pp.

7908240399 Forwards LER 79-057/03L-0.
MANRY, M. Georgia Power Co. 79/08/16. 1p.

--7908240411 LER 79-057/03L-0 on 790802 coil for relay A71-k25 in panel H11-p623 failed to energize while performing reactor water cleanup auto isolation. Caused by burned-out coil. Relay replaced & retested.
* Georgia Power Co. 79/08/17. 1p.

7908240324 Forwards LER 79-053/03L-0.
MANRY, M. Georgia Power Co. 79/08/17. 1p.

--7908240339 Ler 79-053/03L-0 on 790801 during surveillance procedure HNP-1-3001, high reactor pressure trip switch B21-N023B actuated at 1075 psig. Caused by setpoint drift. Switch recalibr & functional test successfully completed.
* Georgia Power Co. 79/08/17. 1p.

7908240348 Forwards LER 79-043/01T-1.
MANRY, M. Georgia Power Co. 79/08/17. 1p.

--7908240362 LER 79-043/01T-1 on 790628 radwaste sump discharge piping between drywell penetrations & second containment isolation valves was not supported per Seismic Class I requirements. Caused by design error. Supports redesigned & installed.
COGGIN, C. L. Georgia Power Co. 79/08/17. 3pp.

7908240417 Forwards LER 79-061/03L-0.
MANRY, M. Georgia Power Co. 79/08/17. 1p.

--7908240424 LER 79-061/03L-0 on 790803 during refueling shutdown, failure of relay Z41-K158 caused failure of automatic start of standby air handling unit. Caused unknown. Relay later tested successfully.
COGGIN, C. I. Georgia Power Co. 79/08/17. 2pp.

7908240472 Forwards LER 79-059/03L-0.
MANRY, M. Georgia Power Co. 79/08/17. 1p.

--7908240476 LER 79-059/03L-0 on 790804 while performing surveillance procedure during shutdown mode, switch failed to operate at proper setpoint. Caused by foreign particles on switch mechanism. Switch cleaned & calibr.
* Georgia Power Co. 79/08/17. 1p.

7908240479 Forwards LER 79-058/03L-0.
MANRY, M. Georgia Power Co. 79/08/17. 1p.

--7908240486 LER 79-058/03L-0 on 790803 while performing sys functional test, time delay relay found to be set at 11-s, exceeding Tech Specs limit. Caused by time delay setpoint drift. Relay recalibr & tested.
COGGIN, C. L. Georgia Power Co. 79/08/17. 1p.

7908240490 Forwards LER 79-060/03L-0.
MANRY, M. Georgia Power Co. 79/08/17. 1p.

--7908240495 LER 79-060/03L-0 on 790805 while performing normal surveillance, auxiliary relay failed to actuate. Caused by open relay coil. Relay replaced & functional test completed sucessfully.
* Georgia Power Co. 79/08/17. 1p.

7908290408 Forwards LER 79-064/01T-0.
MANRY, M. Georgia Power Co. 79/08/21. 1p.

--7908290409 LER 79-064/01T-0 on 790814 pump seismic restraints at 66-ft elevation at intake structure were installed w/self-drilling red head anchor bolts & in pattern not specified in prints. Cause not stated.
COGGIN, C. L. Georgia Power Co. 79/08/21 3pp.

7908310324 Forwards LER 79-062/03L-0.
MANRY, M. Georgia Power Co. 79/08/24 1p.

--7908310327 LER 79-062/03L-0 on 790811 outboard shutdown cooling isolation valve was slow in opening & closing. Caused by valve maint. Valve operator adjusted to proper operating time.
NIX, R. T. Georgia Power Co. 79/08/24 1p.

7908310401 Forwards LER 79-068/03L-0.
MANRY, M. Georgia Power Co. 79/08/24 1p.

--7908310406 LER 79-068/03L-0 on 790726 secondary containment violated when support group personnel opened bldg airlock door at same time other door in air lock was open. Caused by design deficiency. Design revision underway & expected 800101.
COGGIN, C. L. Georgia Power Co. 79/08/24 1p.

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A. Application/construction stage documents & correspondence

7908020382 Responds to 790507 questions re NRC meteorological review. No requirement to reanalyze concentrations at site. Evaluation of site using proposed model would not affect concentrations used in dose assessment.
HOEFLING, R. K. Office of the General Counsel 79/05/31 2pp

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908150010 Forwards addl responses to 790618 questions re shielded components & condensate demineralizer.
NOVARRO, J. P. Long Island Lighting Co. 79/06/27 6pp.

7908020041 Summary of 790613 meeting w/util in Bethesda, MD re current NRC CP & OL application review policies & criteria for establishing review priorities.
FOOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

7908030124 Notification of 790717-18 meeting w/representatives from Mark II owners group in Lebanon, NH to discuss Mark II pool dynamic programs.
ANDERSON, C. J. Containment Systems Branch 79/07/03 12pp.

7908080232 Responds to 790606 ltr requesting NRC require util to determine feasibility of converting facility to coal generation. Since util has stated intent to do so, NRC will take no further action on resolution.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/05 2pp.

--7908080239 Forwards Resolution 490, requesting NRC require util to conduct study of feasibility & cost of converting facility from nuclear to conventional fuel.
ROGERS, W. H. Suffolk County, NY 79/06/06 2pp.

7908090433 Forwards NY Daily News 790621 article re TMI. Article refers to AEC 690905 rept in which design of plant was reviewed.
HAND, R. C. Reilly, Like & Schneider 79/07/06 2pp.

7908280571 Advises that approval has been obtained for exemption from Classes I, II & III amend fees re upgraded STS bases program.
RUBENSTEIN, L. S. Operating Reactors Branch 4 79/07/12 2pp.

7908080190 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/19 2pp.

7908010334 Submits suppl to 790228 ltr, clarifying use of newer editions of ASME III' code, suppl addenda & code cases in lieu of base code.
NOVARRO, J. P. Long Island Lighting Co. 79/07/20 1p.

7908280576 Notifies that Code Case N-240 to ASME Section III, Div 1 for hydrostatic testing of open ended piping is being used.
NOVARRO, J. P. Long Island Lighting Co. 79/08/14 1p.

F. Security, medical, emergency & fire protection plans

7908100323 Forwards revised safeguards contingency plan. Plan withheld (ref 10CFR2.790).
NAVORRO, J. P. Long Island Lighting Co. 79/08/08 3pp.

7908200197 Forwards preliminary security training & qualification plan. Plan withheld (ref 10CFR2.790).
NOVARRO, J. P. Long Island Lighting Co. 79/08/13 2pp.

G. Adjudicatory correspondence

7905310454 Forwards NRC "Safety Evaluation of GE Topical Rept Fuel Rod Prepressurization Amend 1 NEDE-23786-1" & Board notifications of 790409 & 13, "Nuclear Licensing Incident at TMI." W/o encl.
HOEFLING, R. K. Branch 4 79/04/24 1p.

7908130035 Forwards SECY-79-278 dtd 790418 & SECY-79-278A dtd 790507 re physical protection of irradiated fuel shipments. NRC approved implementation of interim final rule imposing requirements for protection of fuel in transit 790507.
HOEFLING, R. K. Branch 4 79/05/30 1pp

7908300393 Notifies that intervenor North Shore Committee Against Nuclear & Thermal Pollution joins intervenor Suffolk County 790517 & 0620 requests.
SHAPIRA, R. Cammer & Shapiro 79/06/28 1p.

--7908300403 Responds to Hoefling 790611 ltr re evacuation plans. Requests copy of intervenor Suffolk County emergency plan.
SHAPIRO, B. Cammer & Shapiro 79/06/28 1p.

7908150009 Responds to 790608 ltr re util 780925 application for 10CFR70 license. No requirements for hearing prior to issuance of license.
HOEFLING, R. K. Branch 4 79/07/03 1p.

7908300046 Response to intervenor Suffolk County second set of interrogatories. Submits info re monitoring design & const changes, review of FSAR, rating contractors & hydrostatic testing. Affidavit of AD Toth & Certificate of Svc encl.
TOTH, A. D. Region 1, Philadelphia, Office of the Director 79/07/06 7pp.

H. General correspondence

7908220379 Forwards summary of special rept re results of employee relations survey conducted in Aug 1978 per 790618 request. W/o encl.
HOEFLING, R. K. Branch 4 79/07/10 1p.

G. Inspection reports, IE Bulletins & correspondence

7908100100 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping. Applied S&W computer program to Item 3, which linked all major versions of NUPIPE to Version 03/10. GE program on Item 3 verified SAP4G & PISYS.
NOVARRO, J. P. Long Island Lighting Co. 79/06/06 3pp.

7908030208 Responds to IE Bulletin 79-04 re incorrect check valve weights. Provides list of all Category I sys & appropriate line designation or mark numbers. Correct check valve weights for all types provided by Velan Engineering Corp.
NOVARRO, J. P. Long Island Lighting Co. 79/06/15 4pp.

7908070460 Responds to IE Bulletin 79-05 re possible degradation of safety-related functions due to moisture leakage in stranded wire conductors. Equipment is being reviewed. Requests related data from Sandia tests & NRC.
NOVARRO, J. P. Long Island Lighting Co. 79/06/28 1p.

7908030220 Requests comments on encl NUREG-0397 re revised insp program & assignment of resident NRC inspector at selected reactor & major fuel facility sites.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/29 2pp.

7908090633 Responds to IE Bulletins 78-12, 12A & 12B. C-E rept, "Atypical Weld Matl in Reactor Pressure Vessels," includes matls used in facility. Found no archive weld matl.
NOVARRO, J. P. Long Island Lighting Co. 79/07/02 5pp.

7908010428 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/17 1p.

7908060378 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030247 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908100232 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908230095 Responds to IE Bulletin 79-11 re Westinghouse Type DB-50 & DB-75 circuit breakers. Circuit breakers are not in use in safety-related sys.
NOVARRO, J.P. Long Island Lighting Co. 79/07/27. 1p.

7908090298 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908280096 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908280281 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310311 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300132 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

7908280651 Forwards revision to preservice insp program to comply w/Response 1 to NRC Request 121.1b.
NOVARRO, J.P. Long Island Lighting Co. 79/08/21. 52pp.

S. Reportable occurrences, LERs & related correspondence

7908210108 Ack receipt of 790629 ltr forwarding interim rept, per 10CFR50.55(e), re welding of integral attachments to Class 1 piping sys. Rept will be reviewed & evaluated.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/07/13. 1p.

U. Congressional/Executive Correspondence

7908080270 Forwards 790718 ltr from Congressman JA Ambro requesting copy of all plant engineering & design coordination repts.
RUBENSTEIN, L.S. Light Water Reactors Branch 4. 79/07/25. 2pp.

--7908080275 Requests delivery before 790731 of all plant engineering & design coordination repts.
AMBRO, J.A. House of Rep. 79/07/18. 1p.

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util in Bethesda, MD re current NRC CP & OL application review policies & criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908030128 Notification of 790718-19 meeting w/util in Bethesda, MD to discuss radiological effluent Tech Specs & electric issues.
BUCKLEY, B.C. Light Water Reactors Branch 1. 79/07/17. 4pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D.G. Division of Operating Reactors. 79/07/18. 58pp.

7908130540 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
STOLZ, J.F. Light Water Reactors Branch 1. 79/08/02. 4pp.

7908170353 Forwards request for addl info required for reviewing application.
STOLZ, J.F. Light Water Reactors Branch 1. 79/08/02. 4pp.

7908210342 Forwards request for addl info re single rod drop event Tech Specs, evaluation of higher fission gas release, fuel design criteria & avoiding fuel spacer grid damage.
STOLZ, J.F. Light Water Reactors Branch 1. 79/08/02. 4pp.

7908230687 Ack receipt of 781207 & 19 LOCA reanalyses w/corrected metal/water reaction model. Forwards request for addl info to ascertain worst break was analyzed. FSAR update necessary re organizational change.
STOLZ, J.F. Light Water Reactors Branch 1. 79/08/03. 4pp.

F. Security, medical, emergency & fire protection plans

7908220428 Forwards security training & qualification plan. Plan witheld (ref 10CFR2.790).
CRANE, P.A. Pacific Gas & Electric Co. 79/08/16. 1p.

G. Adjudicatory correspondence

7906070320 Forwards errata sheet w/suggested mod to proposed findings of fact & conclusions of law. Served on 790410.
KETCHEN, E.G. Branch 4. 79/04/19. 3pp.

7908020376 Ack receipt of 790425 ltr to JM Hendrie opposing facility licensing due to proximity of Hosgri fault. Discusses NRC/Westinghouse public hearings & plant mods to withstand seismic activities.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/06/14. 2pp.

--7908020381 Opposes facility licensing due to proximity of Hosgri fault.
WALACHA, E. Affiliation Unknown. 79/04/25. 1p.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R.L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
[illegible]INTO, J.F. Hearings Division. 79/03/05. 1p.

7908210133 Ack receipt of 790423 & 0621 ltrs requesting info re actions to be taken by ASLB. Ruling on reopening of hearings has been deferred until further action & evaluations are made re safety of nuclear reactors.
NGELHARDT, T.F. Deputy Executive Legal Director. 79/07/05. 2pp.

7908220030 Requests denial of intervenor San Luis Obispo Mothers for Peace motion to reopen record re security plans. Motion has no factual or legal basis. Certificate of Svc. encl.
NORTON, B. Portland General Electric Co. 79/07/06. 6pp.

7908310390 Opposes licensing of facility. Expresses concern re safety, waste disposal, U mining & control of power by large corporations.
PALTIN, S. Affiliation Unknown. 79/08/20. 1p.

H. General correspondence

7908150201 Ack receipt of 790622 ltr & Jul 1979 "Rept to NRC From PG&E Describing Response Programs Following Accident at TMI." NRC priority review will encompass requirements from TMI-2 task forces.
VASSALLO, D.B. Division of Project Management. 79/07/20. 1p.

7908150273 Responds to 790607 ltr to Chairman Hendrie. Full-time task force has been re-established to prepare emergency plans & Governor Brown has appointed emergency review panel to mitigate consequences of accident.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/07/23. 2pp.

--7908150279 Advises that Santa Barbara City Council has endorsed D Yager 790508 ltr sent to Chairman Hendrie.
SHIFFMAN, D. T. Santa Barbara County, CA. 79/06/07 1p

--7908150287 Requests that NRC require adequate emergency plan in conjunction w/facility.
YAGER, D. Santa Barbara County, CA. 79/05/08. 2pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908230612 Forwards Amends 79 & 80 to FSAR, including matl for Hosgri rept.
CRANE, P. A. Pacific Gas & Electric Co. 79/08/20. 2pp.

--7908230615 Amends 79 & 80 to FSAR.
* Pacific Gas & Electric Co. 79/08/20. 110pp.

P. Operating license stage documents & correspondence

7908010462 Responds to NRC 790629 request for info re corporate capabilities & technical & mgt resources. Info requested in Sections I & II B will be developed & submitted at later date. Preliminary plan encl.
CRANE, P. A. Pacific Gas & Electric Co. 79/07/31. 37pp.

Q. Inspection reports, IE Bulletins & correspondence

7908080675 Forwards unsolicited response to IE Bulletin 79-06A, requesting that holders of OLs for Westinghouse PWRs respond to 13 issues resulting from TMI incident.
GORMLY, H. J. Pacific Gas & Electric Co. 79/05/25. 14pp.

7908150222 Forwards IE Insp Repts 50-275/79-12 & 50-323/79-07 on 790430-0503 & notice of violation.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/01. 2pp.

--7908150226 Notice of violation from insp on 790430-0503.
* Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/01. 2pp.

--7908150233 IE Insp Repts 50-275/79-12 & 50-323/79-07 on 790430-0503. Noncompliance noted: tubing support installed on another support exceeded max specified weight limit & conduits not installed as required by procedures & drawings.
KIRSCH, D. F., HUTSON, T. W. Region 5, San Francisco, Office of the Director. DODDS, R. T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/01. 7pp.

--7908150246 Ack receipt of 790706 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/79-12 & 50-323/79-07.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/07/24. 1p.

--7908150241 Responds to NRC 790601 ltr re violations noted in IE Insp Repts 50-275/79-12 & 50-323/79-07. Corrective actions: minor variation repts issued; tubing supports reinspected & nonvital raceways resupported.
CRANE, P. A. Pacific Gas & Electric Co. 79/07/06. 3pp.

7908130421 Forwards response to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-related piping." None of methods specified in bulletin are used.
CRANE, P. A. Pacific Gas & Electric Co. 79/06/12. 2pp.

7908200229 Forwards IE Insp Repts 50-275/79-13 & 50-323/79-08 on 790604-07 & 20. No noncompliance noted.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/07/06. 2pp.

--7908200235 IE Insp Repts 50-275/79-13 & 50-323/79-08 on 790604-07 & 20. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, pipe supports & restraints & nonconformance reporting sys.
KIRSCH, D. F., HUTSON, T. W., DODDS, R. T. Region 5, San Francisco, Office of the Director. 79/07/05. 9pp.

7908010389 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908020495 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908160018 Responds to IE Bulletin 79-01A re solenoid valves. All acetal plastic parts in Class IE ASCO solenoid valves inside containment were replaced. Swals & O-rings made of Buna-N will be replaced.
CRANE, P. A. Pacific Gas & Electric Co. 79/07/18. 1p.

7908020406 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/19. 1p.

7908170596 Forwards to files unsolicited Pacific GAs & Electric Co responses to IE Bulletin 79-06A.
BUCKLEY, B. C. Light Water Reactors Branch 1. 79/07/24. pp.

7908060054 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908060145 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210493 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908170034 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10. 1p.

7908280379 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310148 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300240 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908090200 Ack receipt of 790522 ltr re discrepancy in raceway saddle bolting requirements.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/06/08. 1p.

--7908090227 Responds to 790502 notice of violation re lack of specific bolt mounting requirements in raceway detail drawings. Corrective action: accessible supports reinspected & discrepant drawing details corrected.
CRANE, P. A. Pacific Gas & Electric Co. 79/05/22. 2pp.

7908100029 Confirms 790608 telcon to Moseley re potential safety hazard due to deficiency identified in procedure to check performance characteristics of Barton Lot 1 transmitters. List of affected plants encl. None in operation.
ANDERSON, T. M. Westinghouse Electric Corp. 79/06/11. 4pp.

7908020527 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020026 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908150715 Forwards Yankee Atomic Electric Co 781128 deficiency rept, "Refueling Water Storage Tank Design Deficiency," & request for addl info.
STOLZ, J. F. Light Water Reactors Branch 1. 79/07/20. 4pp.

7908170144 Ack receipt of 790713 ltr re adequacy of design of lateral seismic bracing supporting electrical conduits & raceways.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/01. 1p.

--7908170526 Discusses deficiency re adequacy of design of lateral seismic bracing supporting electrical conduits & raceways. Audit is in progress. Deficient supports will be modified as identified. Personnel will be reinstructed in procedures.
CRANE, P. A. Pacific Gas & Electric Co. 79/07/13. 2pp.

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

7908130180 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908100163 Forwards approval fees for contingency plans. Since plan is site-specific document, requests refund of duplicate fee.
UTLEY, E. E. Carolina Power & Light Co. 79/07/30. 1p.

7908230399 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
UTLEY, E. E. Carolina Power & Light Co. 79/08/17. 2pp.

H. General correspondence

7908200383 Requests amend to License DPR-71 & DPR-62 to document corporate reorganization. Forwards revised pages to Tech Specs. Supersedes 780814 submittal.
UTLEY, E. E. Carolina Power & Light Co. 79/08/14. 29pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908240057 Notifies that util will continue shipment of irradiated reactor fuel for storage per encl schedule & OLs. Encls withheld (ref 10CFR2.790).
* Carolina Power & Light Co. 79/06/28. 2pp.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070305 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908230690 Ack 770914, 790214 & 0423 ltrs changing or clarifying QA programs. Revised provisions of programs acceptable.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/01. 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 5pp.

7908270446 Approves NRC 790820 request to provide NC Governor J. Hunt w/proprietary matl & technical capability matl filed in response to HR Denton 790629 request.
UTLEY, E. E. Carolina Power & Light Co. 79/08/20. 1p.

7908280561 Responds to 790713 request for addl info re BWR reactors. GE owners group will forward 790817 rept, NEDO-24708, as response to short-term generic info request. Revision w/addl info will be forwarded by 791116.
UTLEY, E. E. Carolina Power & Light Co. 79/08/22. 1p.

7908290566 Submits results of seismic reanalysis of safety-related piping, accounting for valve operator eccentricity. Info re modeling of piping elbows & large radius piping sections will be addressed in separate correspondence.
UTLEY, E. E. Carolina Power & Light Co. 79/08/24. 5pp.

Q. Inspection reports, IE Bulletins & correspondence

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 79/06/20. 44pp.

7908240174 Forwards IE Insp Repts 50-324/79-18 & 50-325/79-18 on 790518-19. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20. 2pp.

--7908240181 IE Insp Repts 50-324-79-18 & 50-325/79-18 on 790518-19. No noncompliance noted. Major areas inspected: verification of piping supports for four safety sys in comparison to as-built design drawings.
BLACKWOOD, E., FOSTER, L. E. Region 2, Atlanta, Office of the Director. KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20. 5pp.

7908070126 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908010025 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908060326 Follows up 780214 response to IE Bulletin 78-02. Blowout plugs located in top of electrical penetration boxes were covered w/stainless steel plates to reduce risk of electrical short circuits.
UTLEY, E. E. Carolina Power & Light Co. 79/07/09. 2pp.

7908240323 Forwards IE Insp Repts 50-324/79-21 & 50-325/79-21 on 790523-25. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/11. 2pp.

--7908240336 IE Insp Repts 50-324/79-21 & 50-325/79-21 on 790523-25. No noncompliance noted. Major areas inspected: licensee actions in response to IE Bulletin 79-08.
HINCKLEY, D. G., JENKINS, H. D., KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/11. 6pp.

7908080135 Responds to IE Bulletin 79-11 re faulty overcurrent trip devices in safety-related sys. No Westinghouse Type DB-50 or DB-75 breakers are used in safety-related Class IE sys or maintained as spares.
UTLEY, E. E. Carolina Power & Light Co. 79/07/12. 1p.

7908170121 Responds to IE Bulletins 79-02 & 02, Revision 1, re pipe supports using concrete expansion anchor bolts. Provides status of analytical review of concrete fastener capacities. Describes review efforts. Safety will be verified.
UTLEY, E. E. Carolina Power & Light Co. 79/07/12. 20pp.

7908030105 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/13 2pp.

7908010401 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/17 2pp.

7908020552 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18 2pp.

7908130045 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18 2pp.

7908130095 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18 2pp.

7908080314 Requests addl info to suppl previous response to IE Bulletin 79-08 to enable NRC to complete safety evaluation.
IPPOLITO, T.A. Operating Reactors Branch 3. 79/07/20 4pp.

7908060006 Responds to IE Bulletin 79-12 re short-period scrams. Short-period scrams are of operational concern due to lost availability, but have minimal safety significance.
UTLEY, E.E. Carolina Power & Light Co. 79/07/24 5pp.

7908070727 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/26 2pp.

7908080706 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/26 2pp.

7908160201 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/27 2pp.

7908300590 Responds to IE Bulletin 79-12 re program for review & evaluation of short period scrams. Operating procedures revised to provide for bank notch withdrawal. On-shift training for prevention of scrams [illegible]d.
UTLEY, E.E. Carolina Power [illegible] 79/08/01. 4pp.

7908300588 Responds to IE Bulletins 79-14 & 79-14, Revision 1, re use of as-built piping & support configurations in plant seismic analyses. Cites meetings & ltrs satisfying verification requirement.
FURR, B.J. Carolina Power & Light Co. 79/08/02 1p.

7908160134 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/07 2pp.

7908170008 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/08 2pp.

7908290187 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/10 2pp.

7908280420 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B.H. Region 2, Atlanta, Office of the Director. 79/08/13 2pp.

7908230608 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping, per 790816 & 17 telcons. Supporting tables & graphs encl.
UTLEY, E.E. Carolina Power & Light Co. 79/08/17 8pp.

R Periodic operating reports & related correspondence

7908200353 Forwards monthly operating rept for Jul 1979.
BANKS, H.R. Carolina Power & Light Co. 79/08/10 1p.

--7908200356 Monthly operating rept for Jul 1979.
WILLIS, E. Carolina Power & Light Co. 79/08/03 12pp.

7908230429 Forwards revised page to Jul monthly operations rept issued on 790810. Original page incorrectly listed unit shutdown & power reductions as Number 13 instead of Number 14.
BANKS, H.R. Carolina Power & Light Co. 79/08/20 2pp.

S Reportable occurrences, LERs & related correspondence

7908060133 Summary of 790613 telcon w/licensee re sequence of events leading to Unit 2 790612 reactor scram. Intensive monitoring program & replacement of suspect solenoid will be performed.
HANNON, J.N. Operating Reactors Branch 3. 79/06/25 4pp.

7908020441 Confirms RO 79-052/01P: during reanalyses of safety-related piping sys, two snubber support beams in RHR steam condensing lines lacked required capacity. Caused by missing pipe guide on level instrument leg.
TOLLISON, A.C. Carolina Power & Light Co. 79/07/03 1p.

7908030492 Forwards LER 79-047/03L-0.
BANKS, H.R. Carolina Power & Light Co. 79/07/16 1p.

--7908030498 LER 79-047/03L-0 on 790617: monitor tripped & failed to restart during normal surveillance. Caused by loose bracket inside photohelic pressure gauge. Bracket adjusted, tightened & returned to normal operation.
TOLLISON, A.C. Carolina Power & Light Co. 79/07/16 2pp.

7908030415 Forwards LER 79-054/03L-0.
BANKS, H.R. Carolina Power & Light Co. 79/07/31 1p.

--7908030423 LER 79-054/03L on 790702: during periodic testing, B21-LIS-N017 C switch 1 was out of tolerance low. Caused by instrument drift. Instrument recalibr & returned to svc.
TOLLISON, A.C. Carolina Power & Light Co. 79/07/31 1p.

7908060398 Forwards LER 79-021/03L-0.
BANKS, H.R. Carolina Power & Light Co. 79/08/01 1p.

--7908060415 LER 79-021/03L-0 on 790702: steam line snubber, pump suction snubber & main steam relief snubbers found inoperable. Caused by seal failure. Snubbers rebuilt, functionally tested & reinstalled.
TOLLISON, A.C. Carolina Power & Light Co. 79/08/01 1p.

7908140693 Forwards LER 79-025/03L-0.
BANKS, H.R. Carolina Power & Light Co. 79/08/08 1p.

--7908140700 LER 79-025/03L-0 on 790710: snubbers 2E11-128SS427, RHR heat exchanger outlet A, & 2E11-50SS597, RHR loop A, failed bleed rate portion of test on rebuilt snubbers. Caused by defective valve on second snubber.
TOLLISON, A.C. Carolina Power & Light Co. 79/08/08 2pp.

7908150671 Forwards LER 79-055/03L-0.
BANKS, H.R. Carolina Power & Light Co. 79/08/10 1p.

--7908150680 LER 79-055/03L-0 on 790714 reactor core isolation cooling turbine tripped in overspeed before reaching rated speed. Caused by failure in electrohydraulic actuator & transistor in control unit, due to moisture. Parts replaced.
TOLLISON, A.C. Carolina Power & Light Co. 79/08/10 2pp.

7908200303 Forwards LER 79-057/03L-0.
BANKS, H.R. Carolina Power & Light Co. 79/08/14 1p.

--7908200306 LER 79-057/03L-0 on 790717: safety relief valve lifted & reset at 970 lb for no apparent cause. Valve solenoid & operator replaced. Supplemental rept will be issued when results received.
TOLLISON, A.C. Carolina Power & Light Co. 79/08/14 1p.

7908230381 Forwards LER 79-058/03L-0.
BANKS, H.R. Carolina Power & Light Co. 79/08/15 1p.

--7908230382 LER 79-058/03L-0 on 790719 during reactor high pressure trip calibr & functional test, switch 1 of instrument 2B21-PS-N023C did not actuate per Tech Specs. Caused by instrument drift. Instrument recalibr.
TOLLISON, A.C. Carolina Power & Light Co. 79/08/15 1p.

7908230400 Forwards LER 79-059/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/15. 1p.

--7908230404 LER 79-059/03L-0 on 790718 discovered low fluid level on snubber 2E51-40GS87, RCIC pump suction. Caused by leaking seals. Snubber replaced.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/15. 1p.

7908210385 Forwards LER 79-060/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/17. 1p.

--7908210399 LER 79-060/03L-0 on 790721 torus level out of spec high & slowly increasing. Caused by min flow valve F012 not fully closed, due to erratic pressure switch E41-PSH-N027. Switch replaced.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/17. 2pp.

7908210432 Forwards LER 79-053/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/17. 1p.

--7908210434 LER 79-053/03L-0 on 790721 HPCI steam isolation valve F001 breaker tripped while closing. Caused by valve F001 motor pinion gear installed backwards on shaft binding limitorque operator. Parts replaced.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/17. 2pp.

7908230450 Forwards LER 79-064/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/20. 1p.

--7908230459 LER 79-064/03L-0 on 790731 GE notified util that error existed in Tech Specs for max critical power ratio. Caused by use of incorrect void coefficient data. Revision to Tech Specs currently underway.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/20. 1p.

7908230556 Forwards LER 79-076/03X-1.
BANKS, H. R. Carolina Power & Light Co. 79/08/20. 1p.

--7908230561 LER 79-076/03X-1 on 781202 recorder for chloride intrusion monitor CO-CIS-3075-1 (condensate pump discharge) was not indicating. Caused by detector malfunction. Detector replaced, calibr & returned to svc.
TOLLINSON, A. C. Carolina Power & Light Co. 79/08/20. 1p.

7908270432 Forwards LER 79-061/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/20. 1p.

--7908270441 LER 79-061/03L-0 on 790722 CO-CR 24 point 3, which monitors hotwell outlet, was printing erratically. Cause undetermined. Cell will be repacked to prevent leakage that could lead to erratic reading.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/20. 1p.

7908240457 Forwards LER 79-063/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/21. 1p.

--7908240462 LER 79-063/03L-0 on 790723 during normal plant operation, technician working on fire protection mod discovered line drain valve w/excessive leakage. Caused by check valve in drain line w/off-centered disk.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/21. 1p.

7908300689 Forwards LER 79-065/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/23. 1p.

--7908300700 LER 79-065/03L-0 on 790803 during normal surveillance of control panel 2-CO-CR24 points 1-4 printed erratically. Caused by air leakage around cell. Duct seal applied around cell penetrations. Cells to be replaced in Sept 1979.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/23. 1p.

7908290548 Forwards LER 79-062/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/24. 1p.

--7908290563 LER 79-062/03L-0 on 790726 while performing reactor low level calibr & functional test, instruments 2B21-LIS-N031 C & D were out of calibr. Caused by instrument drift. All switches recalibr.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/24. 2pp.

DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

7908130180 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908100163 Forwards approval fees for contingency plans. Since plan is site-specific document, requests refund of duplicate fee.
UTLEY, E. E. Carolina Power & Light Co. 79/07/30. 1p.

7908230399 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
UTLEY, E. E. Carolina Power & Light Co. 79/08/17. 2pp.

G. Adjudicatory correspondence

7908210416 Requests that OL proceedings be reviewed because of large active earthquake fault near site. Believes facility is huge mistake & should not be licensed.
BOBCZYNSKI, N. I. Affiliation Unknown. 79/08/13. 3pp.

H. General correspondence

7908200383 Requests amend to License DPR-71 & DPR-62 to document corporate reorganization. Forwards revised pages to Tech Specs. Supersedes 780814 submittal.
UTLEY, E. E. Carolina Power & Light Co. 79/08/14. 29pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908240057 Notifies that util will continue shipment of irradiated reactor fuel for storage per encl schedule & OLs. Encls withheld (ref 10CFR2.790).
* Carolina Power & Light Co. 79/06/28. 2pp.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908080359 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908070305 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908090553 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908230690 Ack 770914, 790214 & 0423 ltrs changing or clarifying QA programs. Revised provisions of programs acceptable.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/01. 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908270446 Approves NRC 790820 request to provide NC Governor J Hunt w/proprietary matl & technical capability matl filed in response to HR Denton 790629 request.
UTLEY, E. E. Carolina Power & Light Co. 79/08/20. 1p.

7908280561 Responds to 790713 request for addl info re BWR reactors. GE owners group will forward 790817 rept, NEDO-24708, as response to short-term generic info request. Revision w/addl info will be forwarded by 791116.
UTLEY, E. E. Carolina Power & Light Co. 79/08/22. 1p.

7908290566 Submits results of seismic reanalysis of safety-related piping, accounting for valve operator eccentricity. Info re modeling of piping elbows & large radius piping sections will be addressed in separate correspondence.
UTLEY, E. E. Carolina Power & Light Co. 79/08/24. 5pp.

Q. Inspection reports, IE Bulletins & correspondence.

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Ltr 790625). 79/06/20. 44pp.

7908240174 Forwards IE Insp Rpts 50-324/79-18 & 50-325/79-18 on 790518-19. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20. 2pp.

--7908240181 IE Insp Rpts 50-324-79-18 & 50-325/79-18 on 790518-19. No noncompliance noted. Major areas inspected: verification of piping supports for four safety sys in comparison to as-built design drawings.
BLACKWOOD, E. ; FOSTER, L. E. Region 2, Atlanta, Office of the Director. KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20. 5pp.

7908070126 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908010025 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908060326 Follows up 790214 response to IE Bulletin 78-02. Blowout plugs located in top of electrical penetration boxes were covered w/stainless steel plates to reduce risk of electrical short circuits.
UTLEY, E. E. Carolina Power & Light Co. 79/07/09. 2pp.

7908240323 Forwards IE Insp Rpts 50-324/79-21 & 50-325/79-21 on 790523-25. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/11. 2pp.

--7908240336 IE Insp Rpts 50-324/79-21 & 50-325/79-21 on 790523-25. No noncompliance noted. Major areas inspected: licensee actions in response to IE Bulletin 79-08.
HINCKLEY, D. G. ; JENKINS, H. D. ; KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/11. 6pp.

7908080135 Responds to IE Bulletin 79-11 re faulty overcurrent trip devices in safety-related sys. No Westinghouse Type DB-50 or DB-75 breakers are used in safety-related Class IE sys or maintained as spares.
UTLEY, E. E. Carolina Power & Light Co. 79/07/12. 1p.

7908170121 Responds to IE Bulletins 79-02 & 02, Revision 1, re pipe supports using concrete expansion anchor bolts. Provides status of analytical review of concrete fastener capacities. Describes review efforts. Safety will be verified.
UTLEY, E. E. Carolina Power & Light Co. 79/07/12. 20pp.

7908030105 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010401 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908020552 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130045 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130095 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080314 Requests addl info to suppl previous response to IE Bulletin 79-08 to enable NRC to complete safety evaluation.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/20. 4pp.

7908060006 Responds to IE Bulletin 79-12 re short-period scrams. Short-period scrams are of operational concern due to lost availability, but have minimal safety significance.
UTLEY, E. E. Carolina Power & Light Co. 79/07/24. 5pp.

7908070727 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908080706 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160201 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908300590 Responds to IE Bulletin 79-12 re program for review & evaluation of short period scrams. Operating procedures revised to provide for bank notch withdrawal. On-shift training for prevention of scrams completed.
UTLEY, E. E. Carolina Power & Light Co. 79/08/01. 4pp.

7908300588 Responds to IE Bulletins 79-14 & 79-14, Revision 1, re use of as-built piping & support configurations in plant seismic analyses. Cites meetings & ltrs satisfying verification requirement.
FURR, B. J. Carolina Power & Light Co. 79/08/02. 1p.

7908160134 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

7908170008 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08. 2pp.

7908290187 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/10. 2pp.

7908280420 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

7908230608 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping, per 790816 & 17 telcons. Supporting tables & graphs encl.
UTLEY, E. E. Carolina Power & Light Co. 79/08/17. 8pp.

R. Periodic operating reports & related correspondence.

7908200353 Forwards monthly operating rept for Jul 1979.
BANKS, H. R. Carolina Power & Light Co. 79/08/10. 1p.

--7908200356 Monthly operating rept for Jul 1979.
WILLIS, E. Carolina Power & Light Co. 79/08/03. 12pp.

7908230428 Forwards revised page to Jul monthly operations rept issued on 790810. Original page incorrectly listed unit shutdown & power reductions as Number 13 instead of Number 14.
BANKS, H. R. Carolina Power & Light Co. 79/08/20. 2pp.

S. Reportable occurrences, LERs & related correspondence

7908060133 Summary of 790613 telcon w/licensee re sequence of events leading to Unit 2 790612 reactor scram. Intensive monitoring program & replacement suspect solenoid will be performed.
HANNON, J. N. Ope g Reactors Branch 3. 79/06/25. 4pp.

7908030312 Forwards [illegible] 7-007/03L-2.
BANKS, H. R. Carol[illegible]uer & Light Co. 79/07/31. 1p.

--7908030313 LER 79-007/03L-2 on 790109: RHR pump D would not start during LPCI/RHR sys component test. Caused by charging motor switch being in off position. Switch turned on & test completed satisfactorily.
TOLLISON, A. C. Carolina Power & Light Co. 79/07/31. 2pp.

7908060522 Forwards LER 79-042/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/02. 1p.

--7908060545 LER 79-042/03L-0 on 790706: support beams for snubber B RHR heat exchanger steam condensing line were unable to carry loads under worst case seismic conditions. Cause unstated. Beams reinforced per redesign & plant mod.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/02. 1p.

7908060540 Forwards LER 79-048/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/02. 1p.

--7908060543 LER 79-048/03L-0 on 790713: during high streamline functional test, monitor B was found out of calibr. Caused by instrument drift. Instrument recalibr & returned to svc.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/02. 1p.

7908060466 Forwards LER 79-044/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/03. 1p.

--7908060501 LER 79-044/03L-0 ON 790706: while performing reactor low water level 1 channel calibr, switch 1 found out of tolerance low. Caused by instrument drift. Instrument recalibr & returned to svc.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/03. 1p.

7908200296 Forwards LER 79-046/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/14. 1p.

--7908200299 LER 79-046/03L-0 on 790716: surveillance time limit for Penetrant Test 1 11 core parameter check exceeded by 2-h. Caused by failure of transverse incore probe machine due to loosened tension holding probe to counter. Tension adjusted.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/14. 1p.

7908230379 Forwards LER 79-047/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/15. 1p.

--7908230380 LER 79-047/03L-0 on 790719: during normal reactor startup, "full-in" indication remained on after rod 30-23 was pulled. No indication of "full-in" on rod 42-11 given & "full-in" signal not sent to control circuitry by rod 22-11. Repaired.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/15. 1p.

7908230537 Forwards LER 78-078/03X-1.
BANKS, H. R. Carolina Power & Light Co. 79/08/20. 1p.

--7908230547 LER 78-078/03X-1 on 781005: false position superimposed on actual rod position when core position display selected. Caused by grounded switch on RPI sys probe. Switch wrapped in fiberglass tape to clear ground.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/20. 1p.

7908240401 Forwards LER 79-022/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/21. 1p.

--7908240406 LER 79-022/03L-0 on 790723: linear heat generation rate found to be 0.29 kW/ft above limit during daily core parameter check after reaching 99% power. Caused by faulty computer reading. After evaluation 1-3% power derate imposed.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/21. 2pp.

7908240408 Forwards LER 79-049/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/21. 1p.

--7908240412 LER 79-049/03L-0 on 790724: drywell 0-2 monitor air dryer showed -1259 reading during normal operation after routine preventive maint. Caused by ice buildup on chiller coils resulting in reduced sample flow.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/21. 2pp.

7908290505 Forwards LER 79-052/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/24. 1p.

--7908290514 LER 79-052/03L-0 on 790728: during startup, rods 26-15 & 18-23 had no position indication at notchs 38 & 30, respectively. Caused by faulty prototypic inlet piping probe in drywell. Problems will be corrected during next outage.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/24. 1p.

7908310449 Forwards LER 79-054/03L-0.
BANKS, H. R. Carolina Power & Light Co. 79/08/27. 1p.

--7908310459 LER 79-054/03L-0 on 790805: while pulling control rod on power increase following startup, rod block monitor channel A failed. Caused by defective filter capacitator in VDC power supply. Capacitator replaced & instrument returned to svc.
TOLLISON, A. C. Carolina Power & Light Co. 79/08/27. 1p.

DOCKET 50-326 UNIV. OF CALIFORNIA AT IRVINE RES. REACTOR

Q. Inspection reports, IE Bulletins & correspondence

7908150431 Forwards IE Insp Rept 50-326/79-03 on 790509-10. No noncompliance noted.
CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/06/29. 2pp.

--7908150443 IE Insp Rept 50-326/79-03 on 790509-10. No noncompliance noted. Major areas inspected: organization, logs & records, requalification program, review & audit, procedures, surveillance & followup on licensee events.
JOHNSTON, G. W., FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/06/29. 5pp.

7908280789 Discusses IE Insp Rept 50-326/79-02 on 790226. Notice of violation withheld (ref 10CFR2.790).
NORDERHAUG, L. R. Region 5, San Francisco, Safeguards Branch. 79/07/26. 2pp.

7908170048 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10. 1p.

7908310190 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

R. Periodic operating reports & related correspondence

7908130428 Forwards annual operating rept Jul 1978-June 1979.
MILLER, G. E. California, Univ. of, Irvine. 79/08/06. 1p.

--7908130429 Annual operating rept for Jul 1978-June 1979.
MILLER, G. E. California, Univ. of, Irvine. 79/08/06. 19pp.

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. R. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908010699 Summary of 790614 meeting w/util & USGS re opportunity for util to justify restricting application of 1897 Intensity VIII Giles County earthquake to east-west zone crossing northern part of southern Appalachian sector.
MCMULLEN, R. B. Geosciences Branch. STAHLE, C. R. Light Water Reactors Branch 4. 79/06/29. 4pp.

7908020041 Summary of 790613 meeting w/util in Bethesda, MD re current NRC CP & OL application review policies & criteria for establishing review priorities.
ROOD, H. Ligh[illegible] Water Reactors Branch 2. 79/07/02. 70pp.

7908140117 Notifies that ASME Code Class N-192 may be used in safety-related piping. Data provided on flexible hoses will conform to Reg Guide 1.84.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/07/10. 2pp.

7908160333 Discusses util progress in upgrading bases section of STS. Notifies of amend fee exemption approval.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/07/12. 2pp.

7908160040 Notification of 790801 meeting w/utils in Bethesda, MD to discuss status of TMI-related activities by Lessons Learned, Bulletins & Orders, Emergency Preparedness & Operator Training Task Groups.
VASSALLO, D. B. Division of Project Management. EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 59pp.

7908130563 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/08/01. 4pp.

7908170222 Requests addl info to permit completion of reviews Response required by 790831 to maintain review schedule.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/08/07. 3pp.

7908170442 Forwards "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp & "Justification of Seismic Design Criteria Used for Facilities, Phase II, Responses to NRC Questions 1 Through 6."
MILLS, L. M. Tennessee Valley Authority. 79/08/09. 2pp.

--7908170449 "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp.
* Tennessee Valley Authority. 79/02/28. 114pp.

--7908170454 "Justification of Seismic Design Criteria Used for Facilities, Phase II, Responses to NRC Questions 1 Through 6."
* Tennessee Valley Authority. 79/06/30. 100pp.

7908220258 Forwards 790629 ltrs from util to SW Harvey & JC White of EPA re aquatic monitoring programs including proposed amend to EPA license.
ZELLER, H. D. Environmental Protection Agency. 79/08/14. 8pp.

7908280556 Discusses anticipated problems & design deficiencies of Westinghouse waste encapsulation sys, in ref to 790328 meeting w/NRC Effluent Treatment Sys Branch. Bids for portable solidification sys are being evaluated.
MILLS, L. M. Tennessee Valley Authority. 79/08/23. 2pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L. M. Tennessee Valley Authority. 79/08/23. 2pp.

F. Security, medical, emergency & fire protection plans

7908130208 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908060427 Forwards amended physical security plan. Plan withheld (ref 10CFR2.790).
MILLS, L. M. Tennessee Valley Authority. 79/07/30. 1p.

7908210314 Forwards security personnel training & qualification plans. Plans withheld (ref 10CFR2.790).
MILLS, L. M. Tennessee Valley Authority. 79/08/17. 1p.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Dfc of Power.
MILLS, L. M. Tennessee Valley Authority. 79/08/07. 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908020185 Forwards IE Insp Repts 50-327/79-26 & 50-328/79-13 on 790425-27. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/16. 2pp.

--7908020190 IE Insp Repts 50-327/79-26 & 50-328/79-13 on 790425-27. No noncompliance noted. Major areas inspected: electrical fire stop installation & quality records.
GIBBONS, T. D., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/16. 4pp.

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority. 79/05/29. 3pp.

7908030594 Forwards IE Insp Repts 50-327/79-28 & 50-328/79-15 on 790508-11. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/31. 2pp.

--7908030608 IE Insp Repts 50-327/79-28 & 50-328/79-15 on 790508-11. No noncompliance noted. Major areas inspected: safety-related cable installation & QC records for backflow gate hoist motors & qualifications of QC electrical inspectors.
HARDWICK, R. J., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/31. 4pp.

7908280770 Forwards IE Insp Rept 50-327/79-30 on 790515-18 & 22-25. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Safeguards Branch. 79/06/06. 2pp.

--7908280778 IE Insp Rept 50-327/79-30 & 790515-18 & 22-25. No noncompliance noted. Major areas inspected: hot functional tests, plant surveillance procedures & preoperational test packages.
DONAT, T. J., MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/06. 8pp.

7908010692 Submits results of investigations for various plants, in response to 790417 IE Bulletin 79-09 re GE Type AK-2 circuit breakers.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/20. 4pp.

7908280145 Forwards IE Insp Rept 50-327/79-31 on 790531-0601. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20. 2pp.

--7908280155 IE Insp Rept 50-327/79-31 on 790531-0601. No noncompliance noted. Major areas inspected: preoperational tests & procedures.
DONAT, T. J. Region 2, Atlanta, Office of the Director.
MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20. 3pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 3pp.

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L. M. Tennessee Valley Authority. 79/07/05. 40pp.

7908240302 Forwards IE Insp Rept 50-327/79-25 on 790417-22, 30 & 0507-11. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/06. 2pp.

--7908240316 IE Insp Rept 50-327/79-25 on 790417-22, 30 & 0506-11. No noncompliance noted. Major areas inspected: preoperational test procedures & proposed Tech Spec changes.
DONAT, T. J., COTTLE, W., MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/06. 13p.

7908240210 Forwards IE Insp Repts 50-327/79-32 & 50-328/79-17 on 790619-22. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 2pp.

--7908240214 IE Insp Repts 50-327/79-32 & 50-328/79-17 on 790619-22. No noncompliance noted. Major areas inspected: installation & review of records for safety-related electrical cables & in-place storage & records for electrical motors.
RUFF, A. B. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 3pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/07/18 3pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L. M. Tennessee Valley Authority. 79/07/20 1p.

7908080721 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/07/26 2pp.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/07/26 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/07/27 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L. M. Tennessee Valley Authority. 79/07/27 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/08/07 3pp.

5. Reportable occurrences, LERs & related correspondence

7908100029 Confirms 790808 telcon to Moseley re potential safety hazard due to deficiency identified in procedure to check performance characteristics of Barton Lot 1 transmitters. List of affected plants encl. None in operation.
ANDERSON, T. M. Westinghouse Electric Corp. 79/06/11 4pp.

7908020482 Forwards final deficiency rept re essential raw cooling water valve positioning.
MILLS, L. M. Tennessee Valley Authority. 79/07/03 1p.

--7908020485 Final deficiency rept re essential raw cooling water valve positioning. Automatic opening signals to essential raw cooling water valve will be removed before initial criticality of Unit 1.
* Tennessee Valley Authority. 79/07/03 1p.

7908030058 Forwards first interim rept re reactor vessel insulation deficiency.
MILLS, L. M. Tennessee Valley Authority. 79/07/03 2pp.

--7908030062 First interim rept re reactor vessel insulation deficiency. Lower reactor vessel head metallic mirror insulation appears insufficiently rigid to prevent impinging incore instrumentation guide tubes during seismic event.
* Tennessee Valley Authority. 79/07/03 1p.

7908020453 Forwards final deficiency rept on seal water injection flow, reported 790607.
MILLS, L. M. Tennessee Valley Authority. 79/07/05 1p.

--7908020455 Final deficiency rept re incorrect orifice size of seal water injection flow elements initially reported 790607. Caused by misinterpreted drawings from Westinghouse. Correct orifices will be installed & seal injection flow rebalanced.
* Tennessee Valley Authority. 79/07/05 1p.

7908280698 Forwards first interim deficiency rept re Barton level transmitters. Next rept will be forwarded by 790921.
MILLS, L. M. Tennessee Valley Authority. 79/07/11 1p.

--7908280702 First interim deficiency rept re failure of Barton narrow range steam generator level transmitters to meet acceptance criteria for accuracy. Suspect transmitters being returned to Barton for checking & mods.
* Tennessee Valley Authority. 79/07/11 2pp.

7908030086 Forwards final rept re in-containment conduit junction box deficiency.
MILLS, L. M. Tennessee Valley Authority. 79/07/12 2pp.

--7908030092 Final rept re conduit junction box deficiency. Junction boxes insufficiently sealed. Terminations will be replaced w/splices using heat shrinking sleeving before fuel loading.
* Tennessee Valley Authority. 79/07/12 1p.

7908010398 Forwards second interim deficiency rept re DBA movements of steel containment.
MILLS, L. M. Tennessee Valley Authority. 79/07/18 1p.

--7908010402 Second interim deficiency rept re DBA movement of steel containment. Piping penetrating steel containment analyzed & designed w/o adequate consideration for DBA movements. Reanalysis will ensure inertial effects are addressed.
* Tennessee Valley Authority. 79/07/18 5pp.

7908010400 Forward first interim deficiency rept re diesel generator turbocharger lubrication.
MILLS, L. M. Tennessee Valley Authority. 79/07/20 1p.

--7908010408 First interim deficiency rept when diesel generator at operating temp & retarted between 15 minutes & 3-h after shutdown, damage to turbocharger thrust bearing may occur. Caused by oil sys not receiving lubrication.
* Tennessee Valley Authority. 79/07/20 1p.

7908010341 Forwards first interim deficiency rept re corrosion of cable terminations in junction boxes & Foxboro transmitters inside containment.
MILLS, L. M. Tennessee Valley Authority. 79/07/24 1p.

--7908010347 First interim deficiency rept re corrosion of cable terminations in junction boxes & Foxboro transmitters. Terminations will be replaced w/splices for Class IE circuits.
* Tennessee Valley Authority. 79/07/24 1p.

7908140803 Forwards first interim deficiency rept re steam generator water level ref column error. Next rept will be submitted by 790928.
MILLS, L. M. Tennessee Valley Authority. 79/07/26 1p.

--7908140808 First interim deficiency rept re steam generator water level ref column error. Caused by Westinghouse design oversight. Vendor to perform detailed analyses to determine necessary corrective action.
* Tennessee Valley Authority. 79/07/26 2pp.

7908150526 Forwards final deficiency rept re missing support for auxiliary feedwater pump trip & throttle valve.
MILLS, L. M. Tennessee Valley Authority. 79/08/01 1p.

--7908150535 Final deficiency rept re missing support for auxiliary feedwater pump trip & throttle valve. Proper supports for trip & throttle valve will be installed.
* Tennessee Valley Authority. 79/08/01 1p.

7908140706 Forwards first interim deficiency rept re hydrogen detection sys environ qualification.
MILLS, L. M. Tennessee Valley Authority. 79/08/02 1p.

--7908140715 First interim deficiency rept. Review of environ qualification data for hydrogen detection sys components revealed lack of documentation for 150 F & 50 million rads 30-day radiation dose. Supplier conducting tests.
* Tennessee Valley Authority. 79/08/02 1p.

7908150622 Corrects date for submittal of next interim deficiency rept re Penn Ventilator QA program to 790714.
MILLS, L. M. Tennessee Valley Authority. 79/08/08 1p.

7908300682 Forwards final deficiency rept re electrical handhole structural integrity.
MILLS, L. M. Tennessee Valley Authority. 79/08/16 1p.

--7908300707 Final deficiency rept re electrical handhole structural integrity. Evaluation indicates that six structures in question are adequate for all design basis events.
* Tennessee Valley Authority. 79/08/16 1p.

7908280581 Forwards final deficiency rept re insufficient flexibility of low head injection test lines.
MILLS, L. M. Tennessee Valley Authority. 79/08/22 1p.

--7908280585 Final deficiency rept re insufficient flexibility of low head injection test lines. Lines have been reanalyzed & rerouting will be completed.
* Tennessee Valley Authority. 79/08/22 1p.

DOCKETED ITEMS

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D.B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908010699 Summary of 790614 meeting w/util & USGS re opportunity for util to justify restricting application of 1897 Intensity VIII Giles County earthquake to east-west zone crossing northern part of southern Appalachian sector.
MCMULLEN,R.B. Geosciences Branch STAHLE,C.R. Light Water Reactors Branch 4. 79/06/29. 4pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD,H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908140117 Notifies that ASME Code Class N-192 may be used in safety-related piping.Data provided on flexible hoses will conform to Reg Guide 1.84.
RUBENSTEIN,L.S. Light Water Reactors Branch 4. 79/07/10. 2pp.

7908160333 Discusses util progress in upgrading bases section of STS. Notifies of amend fee exemption approval.
RUBENSTEIN,L.S. Light Water Reactors Branch 4. 79/07/12. 2pp.

7908160040 Notification of 790801 meeting w/utils in Bethesda,MD to discuss status of TMI-related activities by Lessons Learned, Bulletins & Orders,Emergency Preparedness & Operator Training Task Groups.
VASSALLO,D.B. Division of Project Management EISENHUT,D.G. Division of Operating Reactors. 79/07/18. 59pp.

7908130563 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STC for all PWRs are ineffective re steam generator tube degradation.Model license condition encl.
RUBENSTEIN,L.S. Light Water Reactors Branch 4. 79/08/01. 4pp.

7908170222 Requests addl info to permit completion of reviews.Response required by 790831 to maintain review schedule.
RUBENSTEIN,L.S. Light Water Reactors Branch 4. 79/08/07. 3pp.

7908170442 Forwards "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp & "Justification of Seismic Design Criteria Used for Facilities,Phase II: Responses to NRC Questions 1 Through 6."
MILLS,L.M. Tennessee Valley Authority. 79/08/09. 2pp.

--7908170449 "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp.
* Tennessee Valley Authority. 79/02/28. 114pp.

--7908170454 "Justification of Seismic Design Criteria Used for Facilities,Phase II,Responses to NRC Questions 1 Through 6."
* Tennessee Valley Authority. 79/06/30. 100pp.

7908220268 Forwards 790629 ltrs from util to SW Harvey & JC White of EPA re aquatic monitoring programs including proposed amend to EPA license.
ZELLER,H.D. Environmental Protection Agency. 79/08/14. 8pp.

7908280556 Discusses anticipated problems & design deficiencies of Westinghouse waste encapsulation sys.in ref to 790328 meeting w/NRC Effluent Treatment Sys Branch.Bids for portable solidification sys are being evaluated.
MILLS,L.M. Tennessee Valley Authority. 79/08/23. 2pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS,L.M. Tennessee Valley Authority. 79/08/23. 2pp.

F. Security, medical, emergency & fire protection plans

7908130208 Notifies that review of safeguards contingency plan invcives consideration of safeguards issue,requiring payment of Class III fee.Plans should be submitted by 790823.
DIGGS,R.M. License Fee Management Branch. 79/07/03. 2pp.

7908060427 Forwards amended physical security plan.Plan withheld (ref 10CFR2.790).
MILLS,L.M. Tennessee Valley Authority. 79/07/30. 1p.

7908210314 Forwards security personnel training & qualification plans. Plans withheld (ref 10CFR2.790).
MILLS,L.M. Tennessee Valley Authority. 79/08/17. 1p.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS,L.M. Tennessee Valley Authority. 79/08/07. 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908020185 Forwards IE Insp Repts 50-327/79-26 & 50-328/79-13 on 790425-27.No noncompliance noted.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/16. 2pp.

--7908020190 IE Insp Repts 50-327/79-26 & 50-328/79-13 on 790425-27.No noncompliance noted.Major areas inspected:electrical fire stop installation & quality records.
GIBBONS,T.D., BRYANT,J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/16. 4pp.

7908010158 Forwards response to IE Bulletins 78-12,12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts.Westinghouse generic rept due Oct 1979.
GILLELAND,J.E. Tennessee Valley Authority. 79/05/29. 3pp.

7908030594 Forwards IE Insp Repts 50-327/79-28 & 50-328/79-15 on 790508-11.No non-ompliance noted.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/31. 2pp.

--7908030608 IE Insp Repts 50-327/79-28 & 50-328/79-15 on 790508-11.No noncompliance noted.Major areas inspected:safety-related cable installation & QC records for backflow gate hoist motors & qualifications of QC electrical inspectors.
HARDWICK,R.J., BRYANT,J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/31. 4pp.

7908010692 Submits results of investigations for various plants,in response to 790417 IE Bulletin 79-09 re GE Type AK-2 circuit breakers.
GILLELAND,J.E. Tennessee Valley Authority. 79/06/20. 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/06/26. 3pp.

7908060142 Responds to IE Bulletins 79-02 & 02,Revision 1.Forwards results of pipe support base plate design investigations.
MILLS,L.M. Tennessee Valley Authority. 79/07/05. 40pp.

7908240210 Forwards IE Insp Repts 50-327/79-32 & 50-328/79-17 on 790619-22.No noncompliance noted.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 2pp.

--7908240214 IE Insp Repts 50-327/79-32 & 50-328/79-17 on 790619-22.No noncompliance noted.Major areas inspected:installation & review of records for safety-related electrical cables & in-place storage & records for electrical motors.
RUFF,A.B. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 3pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15 Suppl 1 should be directed to IE Div of Reactor Const Insp.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/18. 3pp.

790\170517 Responds to IE Bulletin 79-11 No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L M. Tennessee Valley Authority. 79/07/20. 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/26. 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L M. Tennessee Valley Authority. 79/07/27. 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/08/07. 3pp.

5. Reportable occurrences, LERs & related correspondence

7908020482 Forwards final deficiency rept re essential raw cooling water valve positioning.
MILLS, L M. Tennessee Valley Authority. 79/07/03. 1p.

--7908020485 Final deficiency rept re essential raw cooling water valve positioning. Automatic opening signals to essential raw cooling water valve will be removed before initial criticality of Unit 1.
* Tennessee Valley Authority. 79/07/03. 1p.

7908030038 Forwards first interim rept re reactor vessel insulation deficiency.
MILLS, L M. Tennessee Valley Authority. 79/07/03. 2pp.

--7908030062 First interim rept re reactor vessel insulation deficiency. Lower reactor vessel head metallic mirror insulation appears insufficiently rigid to prevent impacting incore instrumentation guide tubes during seismic event.
* Tennessee Valley Authority. 79/07/03. 1p.

7908020453 Forwards final deficiency rept on seal water injection flow reported 790607.
MILLS, L M. Tennessee Valley Authority. 79/07/05. 1p.

--7908020455 Final deficiency rept re incorrect orifice size of seal water injection flow elements initially reported 790607. Caused by misinterpreted drawings from Westinghouse. Correct orifices will be installed & seal injection flow rebalanced.
* Tennessee Valley Authority. 79/07/05. 1p.

7908280698 Forwards first interim deficiency rept re Barton level transmitters. Next rept will be forwarded by 790921.
MILLS, L M. Tennessee Valley Authority. 79/07/11. 1p.

--7908280702 First interim deficiency rept re failure of Barton narrow range steam generator level transmitters to meet acceptance criteria for accuracy. Suspect transmitters being returned to Barton for checking & mods.
* Tennessee Valley Authority. 79/07/11. 2pp.

7908030086 Forwards final rept re in-containment conduit junction box deficiency.
MILLS, L M. Tennessee Valley Authority. 79/07/12. 2pp.

--7908030092 Final rept re conduit junction box deficiency. Junction boxes insufficiently sealed. Terminations will be replaced w/splices using heat shrinking sleeving before fuel loading.
* Tennessee Valley Authority. 79/07/12. 1p.

7908010398 Forwards second interim deficiency rept re DBA movements of steel containment.
MILLS, L M. Tennessee Valley Authority. 79/07/18. 1p.

--7908010402 Second interim deficiency rept re DBA movement of steel containment. Piping penetrating steel containment analyzed & designed w/o adequate consideration for DBA movements. Reanalysis will ensure inertial effects are addressed.
* Tennessee Valley Authority. 79/07/18. 5pp.

7908010400 Forward first interim deficiency rept re diesel generator turbocharger lubrication.
MILLS, L M. Tennessee Valley Authority. 79/07/20. 1p.

--7908010408 First interim deficiency rept when diesel generator at operating temp & retarted between 15 minutes & 3-h after shutdown, damage to turbocharger thrust bearing may occur. Caused by oil sys not receiving lubrication.
* Tennessee Valley Authority. 79/07/20. 1p.

7908010341 Forwards first interim deficiency rept re corrosion of cable terminations in junction boxes & Foxboro transmitters inside containment.
MILLS, L M. Tennessee Valley Authority. 79/07/24. 1p.

--7908010347 First interim deficiency rept re corrosion of cable terminations in junction boxes & Foxboro transmitters. Terminations will be replaced w/splices for Class IE circuits.
* Tennessee Valley Authority. 79/07/24. 1p.

7908140803 Forwards first interim deficiency rept re steam generator water level ref column error. Next rept will be submitted by 790928.
MILLS, L M. Tennessee Valley Authority. 79/07/26. 1p.

--7908140808 First interim deficiency rept re steam generator water level ref column error. Caused by Westinghouse design oversight. Vendor to perform detailed analyses to determine necessary corrective action.
* Tennessee Valley Authority. 79/07/26. 2pp.

7908150526 Forwards final deficiency rept re missing support for auxiliary feedwater pump trip & throttle valve.
MILLS, L M. Tennessee Valley Authority. 79/08/01. 1p.

--7908150535 Final deficiency rept re missing support for auxiliary feedwater pump trip & throttle valve. Proper supports for trip & throttle valve will be installed.
* Tennessee Valley Authority. 79/08/01. 1p.

7908140706 Forwards first interim deficiency rept re hydrogen detection sys environ qualification.
MILLS, L M. Tennessee Valley Authority. 79/08/02. 1p.

--7908140715 First interim deficiency rept. Review of environ qualification data for hydrogen detection sys components revealed lack of documentation for 150 F & 50 million rads 30-day radiation dose. Supplier conducting tests.
* Tennessee Valley Authority. 79/08/02. 1p.

7908150622 Corrects date for submittal of next interim deficiency rept re Penn Ventilator QA program to 790714.
MILLS, L M. Tennessee Valley Authority. 79/08/08. 1p.

7908300682 Forwards final deficiency rept re electrical handhole structural integrity.
MILLS, L M. Tennessee Valley Authority. 79/08/16. 1p.

--7908300707 Final deficiency rept re electrical handhole structural integrity. Evaluation indicates that six structures in question are adequate for all design basis events.
* Tennessee Valley Authority. 79/08/16. 1p.

7908280581 Forwards final deficiency rept re insufficient flexibility of low head injection test lines.
MILLS, L M. Tennessee Valley Authority. 79/08/22. 1p.

--7908280585 Final deficiency rept re insufficient flexibility of low head injection test lines. Lines have been reanalyzed & rerouting will be completed.
* Tennessee Valley Authority. 79/08/22. 1p.

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D B. Assistant Director for Light Water Reactors.
79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908030155 Notification that 790710 meeting w/util in Bethesda, MD to discuss abnormal settlement of structures at site is rescheduled for 790718.
HOOD, D. Light Water Reactors Branch 4 79/07/03 3pp.

7908090503 Ack receipt of 790609 telegram re facilities. Comments on expressed concern for sinking nuclear plant, sabotage & possibility for another TMI-type incident. Assures thorough investigations to assess situation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/05 2pp.

--7908090509 Expresses concern at util attempt to ignore serious matters such as sinking & sabotage of nuclear plant & effects on Midland residents. Urges NRC to fulfill regulatory obligations to prevent future TMI-type incident.
MARSHALL, W. H. Midwest Environmental Protection Association 79/06/09 1p.

7908100380 Summary of 790618 meeting w/util in Bethesda, MD re status of plant safety & environ reviews.
HOOD, D. Light Water Reactors Branch 4 79/07/10 3pp.

7908150755 Responds to 790529 telegram re delays in safety & environ reviews. Resources have been diverted to TMI-2 investigation. Discusses 790613 & 18 meetings re review of current applications.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/10 3pp.

--7908150758 Requests reconsideration of proposed reordering of licensing priorities. Facility has been in licensing process longer than any other. Timely completion of plant is vital.
HOWELL, S. H. Consumers Power Co. 79/05/29 1p.

7908130302 Responds to DJ Demlow 790529 telegram to JM Hendrie re delay in licensing review. Review delayed by restructuring of casework & priorities due to diversion of managerial & technical resources to TMI investigation.
GOSSICK, L. V. Office of the Executive Director for Operations 79/07/11 2pp.

7908130309 Responds to 790529 telegram to Hendrie re delay in OL review process. Explains priorities for reviews. Licensee does not qualify except for work on structural & foundation problems. TMI has high priority.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/11 2pp.

--7908130311 Forwards DJ Demlow 790529 telegram to JM Hendrie.
DEMLOW, D. J. Michigan, State of 79/05/30 1p.

--7908130317 Opposes delay in operating licensing review process. Stresses that delay will cause cost overruns & increased consumer rates. Urges reconsideration of NRC position.
DEMLOW, D. J. Michigan, State of 79/05/29 1p.

7908230048 Notifies that exemptions are approved in amend fee Classes I-III as results of upgraded STS program. All amends under program expected to fall in fee classes I-III. Exemptions should provide addl incentive for program.
HOWELL, S. H. Consumers Power Co. 79/07/12 2pp.

7908070793 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/13 1p.

7908080623 Responds to 790330 telegram to JM Hendrie re scheduled completion date of plant. Review of plant will be interrupted until Jan 1980 due to diversion of staff to work on TMI accident investigation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/13 3pp.

--7908080631 Requests meeting at earliest possible date between util & NRC to discuss scheduled completion date of plant.
CALDWELL, B. G. Dow Chemical Co. 79/05/30 1p.

7908090217 Responds to FOIA request for 14 items related to facility. Forwards documents, including insp repts, in response to three of 14 items requested & list of addl documents available in LPDR.
FELTON, J. M. Division of Rules and Records 79/07/23 6pp.

7908060236 Discusses activities undertaken re TMI-2 incident & resolution of open items. Joint recommendations of Midland Nuclear Safety Task Force, B&W & Bechtel currently under review.
HOWELL, S. H. Consumers Power Co. 79/07/26 2pp.

7908210049 Notification of 790823 meeting w/util in Bethesda, MD to discuss design for sequencing emergency loads in event of loss of off-site power. Responses to NRC questions encl.
HOOD, D. Light Water Reactors Branch 4 79/07/31 5pp.

7908130557 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN, L. S. Light Water Reactors Branch 4 79/08/01 4pp.

7908230140 Notifies of 790802 meeting w/util & Bechtel in Vancouver, BC to observe model tests of containment sump design. Agenda encl.
HOOD, D. Light Water Reactors Branch 4 79/08/01 4pp.

7909220447 Forwards branch request for addl info re first round questions.
MAZETIS, G. R. Reactor Systems Branch 77/09/28 2pp.

--7908220450 Requests addl info for first round questions for branch acceptance review of FSAR.
* Reactor Systems Branch 77/09/28 5pp.

--7908220454 Forwards branch request for addl info re first round questions.
MAZETIS, G. R. Reactor Systems Branch 78/03/09 1p.

--7908220460 Requests addl info for first round questions for branch review of applicant FSAR through Amend 38.
* Reactor Systems Branch 78/03/08 17pp.

--7908220462 Forwards branch request for addl info re first round questions.
MAZETIS, G. R. Reactor Systems Branch 78/03/09 1p.

--7908220466 Requests addl info for first round questions review.
* Reactor Systems Branch 78/03/09 3pp.

--7908220468 Forwards branch request for addl info re second round questions.
ROSS, D. F. Reactor Systems Branch 78/09/28 1p.

--7908220472 Requests addl info for second round questions for FSAR review.
* Reactor Systems Branch 78/09/28 22pp.

--7908220495 Forwards Reactor Sys Branch request for addl info for second round questions.
SCHROEDER, F. Assistant Director for Reactor Safety 78/10/26 1p.

--7908220499 Requests addl info for Reactor Sys Branch review of Round 2 questions re main steam line break.
* Assistant Director for Reactor Safety 78/10/26 3pp.

--7908220502 Forwards Reactor Sys Branch request for addl info re second round questions.
TEDESCO, R. L. Assistant Director for Reactor Safety 78/12/27 2pp.

--7908220503 Requests addl info for Reactor Sys Branch review of second round questions.
* Assistant Director for Reactor Safety 78/12/27 6pp.

G. Adjudicatory correspondence

7908020290 Discusses SAND-77-1927, "Transport of Radionuclides in Urban Environs: Working Draft Assessment." Identifies general objectives & topics discussed. No regulatory action necessary per SECY-78-311 & SECY-78-311A.
SOHINKI, S. M. Branch 3 79/04/25 2pp.

--7908020302 Forwards info potentially relevant to ASLB & ASLAB in NRC proceedings re analyses of sabotage attacks on spent fuel transportation sys & description of damages caused by various types of high explosive attacks. W/o encl.
CARTER, T. F. Division of Safeguards 79/01/22 2pp.

7908020414 Forwards NRC 790511, 12 & 16 memos re estimated const completion date. Discusses currently projected const completion date of Nov 1981.
HOEFLING, R. K. Branch 4 79/05/31 1p.

--7908020417 Forwards corrected copy of page 2 of Hood 790515 memo to Vassallo re estimated const completion date.
HOOD, D. Light Water Reactors Branch 4 79/05/16 2pp.

7908100370 Discusses suspension proceeding transcripts of M Cherry allegations re plant costs, conflicting licensee data & Palisades derating & outage. Further Board inquiry may be necessary re Palisades derating & outage allegations.
PATON, W. D. Branch 4 79/06/01 5pp.

7906280112 Motion of Consumers Power Co to establish schedule.Hearings re environ & radiological health & safety issues should be held.
MILLER,M.I. , GIBBS,M.E. Isham, Lincoln & Beale 79/06/20 7pp.

7908150420 Forwards three interim repts re settlement of diesel generator foundations & bldg,main control panel & main feed pipe.
GIVVS,M.E. Isham, Lincoln & Beale 79/07/02 1p.

7908080048 Memo re assertion of attorney-client privilege by Dow Chemical per legal advice received in ref to contract w/util.Privilege waived per existing record. W/Certificate of Svc.
OLMSTEAD,W.J. Branch 4 79/07/03 9pp.

7908150259 Expresses concern re nuclear safety.Suggests facility conversion to coal.
MARSHALL,W.H. Midwest Environmental Protection Association 79/07/05 1p.

7908080053 Opposition to util 790620 motion to establish schedule for proceeding.Opposition limited to safety phase.Portion of motion directed to environ phase should be held in abeyance. Certificate of Svc encl.
HOEFLING,R.K. Branch 4 79/07/10 5pp.

7908170340 Ack receipt of 790615 ltr w/rept to NRC re possible improvements for handling disciplinary matters.Rept will be sent to licensing & appeal boards,Ofc of General Counsel & Executive Legal Director.
HENDRIE,J.M. Commission 79/07/12 1p.

--7908170346 Motion filed on behalf of MM Cherry for dismissal for lack of jurisdiction of all charges preferred against him.NRC & ASLB have no authority to suspend attys for conduct of that nature.
FREEMAN,M.V., BONDERMAN,D., COHEN,R.C. Arnold & Porter 78/02/02 30pp.

7908170549 Forwards util 790706 ltr & interim deficiency rept referencing Revision B of qualification test status rept.
GIBBS,M.E. Isham, Lincoln & Beale 79/07/16 1p.

--7908170558 Interim Deficiency Rept 4 re status of component qualification test document re-review.To date,only Foxboro transmitters were unable to meet qualification requirements in final analysis.
* Bechtel Power Corp. (subs of Bechtel Corp.) 79/07/05 2pp.

7908220298 Forwards 790709 Revision 2 to licensee response to NRC request re plant fill in diesel generator bldg settlement issue.
GIBBS,M.E. Isham, Lincoln & Beale 79/07/16 1p.

H. General correspondence

7908150593 Forwards chart showing QA program organizational change in production & transportation dept,effective 790711.
HOFFMAN,D.P. Consumers Power Co 79/08/10 3pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908080124 Forwards Amend 68 to application for CP & OL,containing Revision 23 to FSAR.Supplemental ref drawings (piping & instrument diagrams) encl.W/drawing list.
HOWELL,S.H. Consumers Power Co 79/07/31 10pp.

--7908080133 Revision 23 to FSAR,containing responses to NRC questions, fire protection evaluation rept & various updates & corrections.
* Consumers Power Co 79/07/31 375pp.

7908100454 Forwards Certificate of Svc to Amend 68,Revision 23 to FSAR.
BACON,J.L. Consumers Power Co 79/08/07 2pp.

P. Operating license stage documents & correspondence

7908010436 Forwards fee for steam generator tube surveillance Tech Spec change,inadvertently omitted from 790726 submittal.
CASHELL,S. Consumers Power Co 79/07/27 1p.

7908220421 Forwards info fulfilling requirements described in 790725 deposition.
NOVAK,T.M. Reactor Systems Branch 79/08/06 1p.

Q. Inspection reports, IE Bulletins & correspondence

7908150614 Forwards IE Insp Repts 50-329/79-13 & 50-330/79-13 on 790402-30 & notice of violation.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/30 2pp.

--7908150620 Notice of violation from insp on 790402-30.
* Region 3, Chicago, Office of the Director 79/05/29 1p.

--7908150627 IE Insp Repts 50-329/79-13 & 50-330/79-13 on 790402-30. Noncompliance noted:failure to adequately inspect tank vertical welds for zero leakage conditions.
COOK,R.J., KNOP,R.C. Region 3, Chicago, Office of the Director 79/05/29 10pp.

7908030623 Forwards IE Insp Repts 50-329/79-10 & 50-330/79-10 on 790514-17 & notice of violation.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/06 2pp.

--7908030629 Notice of violation from insp on 790514-17.
* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/01 2pp.

--7908030633 IE Insp Repts 50-329/79-10 & 50-330/79-10 on 790514-17. Noncompliance noted:failure to properly translate FSAR design requirements into specs & procedures.
GALLAGHER,E.J Region 3, Chicago, Reactor Construction & Engineering Support Branch LEE,E.W., HAYES,D.W. Region 3, Chicago, Office of the Director 79/06/01 11pp.

7908150450 Forwards IE Insp Repts 50-329/79-12 & 50-330/79-12 on 790508-11 & notice of violation.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/19 2pp.

--7908150457 Notice of violation from insp on 790508-11.
* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/15 3pp.

--7908150482 IE Insp Repts 50-329/79-12 & 50-330/79-12 on 790508-11. Noncompliance noted:inadequate drawing control;welding procedure qualification & matl receipt insp.
BARRETT,P.A., KNOP,R.C. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/15 28pp.

7908090297 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breakers in engineered safety sys. Westinghouse DB-50 & DB-75 circuit breakers not in use in safety-related sys.
HOWELL,S.H. Consumers Power Co 79/06/21 1p.

7908090632 Responds to IE Bulletin 79-02,Revision 1 Reinspections needed to accomplish Item 4 requirements will not be complete until Jul 1979.May have problem meeting required imbedment depths.Forwards rept re Bechtel bolts.
HOWELL,S.H. Consumers Power Co 79/07/03 8pp.

--7908090634 "Rept on Prying Action in Bolts for Bechtel SA-717."
MARK,R. Bechtel Power Corp. (subs of Bechtel Corp.) 79/05/14. 19pp.

--7908090637 Tech Specs for furnishing,installation & testing of expansion type concrete anchors.
* Conrumers Power Co 79/02/05. 36pp.

7908130658 Submits final response to IE Bulletin 79-03.Only 1 Ft of ASME SA-312,TP-304 or TP-316,in use in facility.Examination & repair of pipe not necessary.Pipe is unlikely to fail from pressure,due to location.
HOWELL,S.H. Consumers Power Co 79/07/16 2pp.

7908060199 Ack receipt of 790629 ltr informing NRC of steps taken to correct violations noted IE Insp Repts 50-329/79-13 & 50-330/79-13.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/18 1p.

--7908060212 Responds to NRC 790530 ltr re violations noted in IE Insp Repts 50-329/79-13 & 50-330/79-13.Corrective actions:incore instrument tank retested on 790516 using borescope.Rept will be available by 790715.
HOWELL,S.H. Consumers Power Co 79/06/29 2pp.

7908150412 Ack receipt of 790629 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-329/79-10 & 50-330/79-10.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/23 1p.

--7908150418 Responds to NRC 790606 ltr re violation noted in IE Insp Repts 50-329/79-10 & 50-330/79-10. Corrective actions: FSAR change notices are in process & will be incorporated no later than Aug 1979.
HOWELL, S. H. Consumers Power Co. 79/06/29. 3pp.

7908290330 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300402 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908150344 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300272 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908270345 Forwards Bechtel nonconformance monthly rept, Bechtel nonconformance rept log sheets, Bechtel quality action requests, Bechtel mgt corrective action rept, B&W repts of nonconformity & CPC nonconformance repts.
DOWELL, S. D. Consumers Power Co. 79/08/15. 800pp.

S. Reportable occurrences, LERs & related correspondence

7908030388 Ack receipt of 790525 interim rept on electrical penetration assembly, per 10CFR50.55. Review will be completed during future insp.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/19. 1p.

7908030414 Ack receipt of 790608 interim rept on pr[illegible]er sys, per 10CFR50.55. Final rept will be reviewed u[illegible]pt.
FIORELLI, G. Region 3, Chicago, Reactor Constru[illegible] & Engineering Support Branch. 79/06/19. 1p.

7908270269 Ack receipt of 790620 interim rept re status display panel modules.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/12. 1p.

7908270274 Ack receipt of 790625 interim rept re settlement of diesel generator foundation & bldg. Rept will be reviewed during 790718 meeting in Bethesda, MD.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/12. 1p.

7908270279 Ack receipt of 790620 interim rept re main feed piping impact testing.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/12. 1p.

7908290118 Expresses thanks for 790720 final rept per 10CFR50.55 re main control panel & status display panel modules. Review will be completed during future insp.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/30. 1p.

7908060405 Forwards interim deficiency rept on status of main feed pipe spools which have questionable impact test results & summary of sequence of events associated w/each of heats of piping spools.
HOWELL, S. H. Consumers Power Co. 79/08/01. 4pp.

--7908060410 Interim Deficiency Rept 2 re impact-testing of main feedwater pipe. Bechtel Corp is presently pursuing acceptability of matl associated w/Heats N-32762 & L-20479. Reportable condition remains uncertain.
* Bechtel Power Corp. (subs. of Bechtel Corp.). 79/07/26. 6pp.

7908140360 Forwards interim deficiency rept re svc water supply pressure for containment air coolers. Util 790711 QA program mgt corrective action rept encl.
HOWELL, S. H. Consumers Power Co. 79/08/07. 2pp.

--7908140366 Deficiency rept re svc water supply pressure for containment air coolers. Corrective action will be taken to ensure that boiling does not occur in containment air coolers & that design conforms to SAR.
MASSING, D. Bechtel Associates Professional Corp. 79/08/02. 2pp.

7908170390 Forwards interim rept re settlement of diesel generator foundations & bldg. Documents re presentation at 790718 meeting w/NRC encl.
HOWELL, S. H. Consumers Power Co. 79/08/10. 2pp.

--7908170393 Interim rept re settlement of diesel generator foundations & bldg, per presentation at 790718 meeting w/NRC. Oversized drawings encl.
* Consumers Power Co. 79/07/18. 14pp.

7908210421 Forwards interim deficiency rept on status of discrepant terminal block disconnect links. Final rept will be sent by 791026.
HOWELL, S. H. Consumers Power Co. 79/08/10. 1p.

--7908210431 Interim deficiency rept re discrepant terminal block disconnect links. Terminal block manufacturer & major equipment suppliers will be informed of deficiency. Schedule of corrective action will be in Interim Rept 2.
* Consumers Power Co. 79/07/20. 5pp.

7908210447 Submits interim deficiency rept re potential unsafe conditions if reactor coolant pumps are tripped after high sys void fractions develop in loop. Util considering automatic safety grade trip sys.
HOWELL, S. H. Consumers Power Co. 79/08/15. 1p.

7908210477 Submits interim rept re potentially unsafe situation if reactor coolant pumps are tripped after high sys void fractions develop in loop. Analyses show safe condition if pumps are tripped promptly in transient.
HOWELL, S. H. Consumers Power Co. 79/08/15. 1p.

7908290402 Final deficiency rept re station battery qualification test failure. Caused by design discrepancy. Production of new design will begin 790901. Bechtel 790815 ltr rept encl.
HOWELL, S. H. Consumers Power Co. 79/08/23. 4pp.

7908290560 Forwards QA program Mgt Corrective Action Rept 33 re discrepancies found in containment bldg tendons supplied by Inryco. Next rept will be sent by 790928.
HOWELL, S. H. Consumers Power Co. 79/08/23. 2pp.

--7908290567 QA program Mgt Corrective Action Rept 33: tendons in containment bldg found to have unknown wire lengths. Caused by manufacturer & QA program errors. Production equipment & QA procedures being corrected.
* Consumers Power Co. 79/07/27. 4pp.

T. Hearing transcripts on non-antitrust matters

7908060105 Transcript of 790724 hearing in Bethesda, MD. Pp 53,602-53,836.
MILLER, M. E., LEEDS, J. V., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 79/07/24. 235pp.

7908060065 Transcript of 790725 hearing in Bethesda, MD. Pp 53,837-54,000.
MILLER, M. E., LEEDS, J. V., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 79/07/25. 164pp.

7908080548 Transcript of 790730 meeting in Bethesda, MD. Pp 54,001-54,117.
MILLER, M. E., LEEDS, J. V., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 79/07/30. 117pp.

7908080543 Transcript of 790731 meeting in Bethesda, MD. Pp 54,118-54,343.
MILLER, M. E., LEEDS, J. V., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 79/07/31. 225pp.

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908030155 Notification that 790710 meeting w/util in Bethesda,MD to discuss abnormal settlement of structures at site is rescheduled for 790718.
HOOD,D. Light Water Reactors Branch 4 79/07/03 3pp.

7908090503 Ack receipt of 790609 telegram re facilities. Comments on expressed concern for sinking nuclear plant, sabotage & possibility for another TMI-type incident. Assures thorough investigations to assess situation.
DENTON,H.R. Office of Nuclear Reactor Regulation 79/07/05 2pp.

--7908090509 Expresses concern at util attempt to ignore serious matters such as sinking & sabotage of nuclear plant & effects on Midland residents. Urges NRC to fulfill regulatory obligations to prevent future TMI-type incident.
MARSHALL,W.H. Midwest Environmental Protection Association 79/06/09 1p.

7908100380 Summary of 790618 meeting w/util in Bethesda,MD re status of plant safety & environ reviews.
HOOD,D. Light Water Reactors Branch 4 79/07/10 3pp.

7908150755 Responds to 790529 telegram re delays in safety & environ reviews. Resources have been diverted to TMI-2 investigation. Discusses 790613 & 18 meetings re review of current applications.
DENTON,H.R. Office of Nuclear Reactor Regulation 79/07/10 3pp.

--7908150758 Requests reconsideration of proposed reordering of licensing priorities. Facility has been in licensing process longer than any other. Timely completion of plant is vital.
HOWELL,S.H. Consumers Power Co 79/05/29 1p.

7908130302 Responds to DJ Demlow 790529 telegram to JM Hendrie re delay in licensing review. Review delayed by restructuring of casework & priorities due to diversion of managerial & technical resources to TMI investigation.
GOSSICK,L.V. Office of the Executive Director for Operations 79/07/11 2pp.

7908130309 Responds to 790529 telegram to Hendrie re delay in OL review process. Explains priorities for reviews. Licensee does not qualify except for work on structural & foundation problems. TMI has high priority.
DENTON,H.R. Office of Nuclear Reactor Regulation 79/07/11 2pp.

--7908130311 Forwards DJ Demlow 790529 telegram to JM Hendrie.
DEMLOW,D.J. Michigan, State of 79/05/30 1p.

--7908130317 Opposes delay in operating licensing review process. Stresses that delay will cause cost overruns & increased consumer rates. Urges reconsideration of NRC position.
DEMLOW,D.J. Michigan, State of 79/05/29 1p.

7908230048 Notifies that exemptions are approved in amend fee Classes I-III as result of upgraded STS program. All amends under program expected to fall in fee classes I-III. Exemptions should provide addl incentive for program.
HOWELL,S.H. Consumers Power Co 79/07/12 2pp.

7908070703 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/13 1p.

7908080623 Responds to 790330 telegram to JM Hendrie re scheduled completion date of plant. Review of plant will be interrupted until Jan 1980 due to diversion of staff to work on TMI accident investigation.
DENTON,H.R. Office of Nuclear Reactor Regulation 79/07/13 3pp.

--7908080631 Requests meeting at earliest possible date between util & NRC to discuss scheduled completion date of plant.
CALDWELL,B.G. Dow Chemical Co 79/05/30 1p.

7908090217 Responds to FOIA request for 14 items related to facility. Forwards documents, including insp repts, in response to 3 of 14 items requested & list of addl documents available in LPDR.
FELTON,J.M. Division of Rules and Records 79/07/23 6pp.

--7908090263 Submits insp items for consideration for forwarding to ASLB. Six items pertain to core lifting, power oscillations, pressurizer level during transients, shutdown margin maint & severe thermal transient.
CRESWELL,J.S. Region 3, Chicago, Office of the Director 79/07/08 3pp.

7908060236 Discusses activities undertaken re TMI-2 incident & resolution of open items. Joint recommendations of Mid'and Nuclear Safety Task Force, B&W & Bechtel currently under review.
HOWELL,S.H. Consumers Power Co 79/07/26 2pp.

7908210049 Notification of 790823 meeting w/util in Bethesda,MD to discuss design for sequencing emergency loads in event of loss of offsite power. Responses to NRC questions encl.
HOOD,D. Light Water Reactors Branch 4 79/07/31 5pp.

7908130557 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN,L.S. Light Water Reactors Branch 4 79/08/01 4pp.

7908230140 Notifies of 790802 meeting w/util & Bechtel in Vancouver,BC to observe model tests of containment sump design. Agenda encl.
HOOD,D. Light Water Reactors Branch 4 79/08/01 4pp.

7908220447 Forwards branch request for addl info re first round questions.
MAZETIS,G.R. Reactor Systems Branch 77/09/28 2pp.

--7908220450 Requests addl info for first round questions for branch acceptance review of FSAR.
* Reactor Systems Branch 77/09/28 5pp.

--7908220454 Forwards branch request for addl info re first round questions.
MAZETIS,G.R. Reactor Systems Branch 78/03/09 1p.

--7908220460 Requests addl info for first round questions for branch review of applicant FSAR through Amend 3b.
* Reactor Systems Branch 78/03/08 17pp.

--7908220462 Forwards branch request for addl info re first round questions.
MAZETIS,G.R. Reactor Systems Branch 78/03/09 1p.

--7908220466 Requests addl info for first round questions review.
* Reactor Systems Branch 78/03/09 3p.

--7908220468 Forwards branch request for addl info re second round questions.
ROSS,D.F. Reactor Systems Branch 78/09/28 1p.

--7908220472 Requests addl info for second round questions for FSAR review.
* Reactor Systems Branch 78/09/28 2pp.

--7908220493 Forwards Reactor Sys Branch request for addl info for second round questions.
SCHROEDER,R. Assistant Director for Reactor Safety 78/10/26 1p.

--7908220499 Requests addl info for Reactor Sys Branch review of Round 2 questions re main steam line break.
* Assistant Director for Reactor Safety 78/10/26 3pp.

--7908220502 Forwards Reactor Sys Branch request for addl info re second round questions.
TEDESCO,R.L. Assistant Director for Reactor Safety 78/12/27 2pp.

--7908220503 Requests addl info for Reactor Sys Branch review of second round questions.
* Assistant Director for Reactor Safety 78/12/27 6pp.

G. Adjudicatory correspondence

7908020417 Forwards corrected copy of page 2 of Hood 790515 memo to Vassallo re estimated const completion date.
HOOD,D. Light Water Reactors Branch 4 79/05/16 2pp.

7908020414 Forwards NRC 790511,12 & 16 memos re estimated const completion date. Discusses currently projected const completion date of Nov 1981.
HOEFLING,R.K. Branch 4 79/05/31 1p.

7908100370 Discusses suspension proceeding transcripts of M Cherry allegations re plant costs, conflicting licensee data & Palisades derating & outage. Further Board inquiry may be necessary re Palisades derating & outage allegations.
PATON,W.D. Branch 4 79/06/01 5pp.

7906280112 Motion of Consumers Power Co to establish schedule Hearings re environ & radiological health & safety issues should be held.
MILLER,M I ; GIBBS,M E Isham, Lincoln & Beale 79/06/20 7pp

7908150420 Forwards three interim repts re settlement of diesel generator foundations & bldg,main control panel & main feed pipe.
GIVVS,M E Isham, Lincoln & Beale 79/07/02 1p

7908080048 Memo re assertion of attorney-client privilege by Dow Chemical per legal advice received in ref to contract w/util.Privilege waived per existing record. W/Certificate of Svc
OLMSTEAD,W J Branch 4 79/07/03 9pp

7908150259 Expresses concern re nuclear safety.Suggests facility conversion to coal.
MARSHALL,W H Midwest Environmental Protection Association 79/07/05 1p

7908080053 Opposition to util 790620 motion to establish schedule for proceeding.Opposition limited to safety phase.Portion of motion directed to environ phase should be held in abeyance. Certificate of Svc encl.
HOEFLING,R K Branch 4 79/07/10 5pp

7908170340 Ack receipt of 790615 ltr w/rept to NRC re possible improvements for handling disciplinary matters.Rept will be sent to licensing & appeal boards.Ofc of General Counsel & Executive Legal Director.
HENDRIE,J M Commission 79/07/12 1p

--7908170346 Motion filed on behalf of MM Cherry for dismissal for lack of jurisdiction of all charges preferred against him.NRC & ASLB have no authority to suspend attys for conduct of that nature.
FREEMAN,M V ; BONDERMAN,D ; COHEN,R C Arnold & Porter 78/02/02 30pp

7908170549 Forwards util 790706 ltr & interim deficiency rept referencing Revision 8 of qualification test status rept.
GIBBS,M E Isham, Lincoln & Beale 79/07/16 1p

--7908170558 Interim Deficiency Rept 4 re status of component qualification test document re-review.To date,only Foxboro transmitters were unable to meet qualification requirements in final analysis.
* Bechtel Power Corp (subs of Bechtel Corp.) 79/07/05 2pp

7908220298 Forwards 790709 Revision 2 to licensee response to NRC request re plant fill in diesel generator bldg settlement issue.
GIBBS,M E Isham, Lincoln & Beale 79/07/16 1p

H General correspondence

7908150593 Forwards chart showing QA program organizational change in production & transportation dept.Effective date of change is 790711.
HOFFMAN,D P Consumers Power Co 79/08/10 3pp

K Utility Final Safety Analysis Report (FSAR) & amends

7908080124 Forwards Amend 68 to application for CP & OL containing Revision 23 to FSAR.Supplemental ref drawings (piping & instrument diagrams) encl.W/drawing list.
HOWELL,S H Consumers Power Co 79/07/31 10pp

--7908080133 Revision 23 to FSAR,containing responses to NRC questions, fire protection evaluation rept & various updates & corrections.
* Consumers Power Co 79/07/31 375pp

7908100453 Forwards Certificate of Svc to Amend 68,Revision 23 to FSAR.
BACON,J L Consumers Power Co 79/08/07 2pp

P Operating license stage documents & correspondence

7908010436 Forwards fee for steam generator tube surveillance Tech Spec change; inadvertently omitted from 790726 submittal.
CASHELL,S Consumers Power Co 79/07/27 1p

7908220421 Forwards info fulfilling requirements described in 790725 deposition.
NOVAK,T M Reactor Systems Branch 79/08/06 1p

Q Inspection reports, IE Bulletins & correspondence

7908150614 Forwards IE Insp Repts 50-329/79-13 & 50-330/79-13 on 790402-30 & notice of violation.
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/30 2pp

--7908150620 Notice of violation from insp on 790402-30.
* Region 3, Chicago, Office of the Director 79/05/29 1p

--7908150627 IE Insp Repts 50-329/79-13 & 50-330/79-13 on 790402-30. Noncompliance noted:failure to adequately inspect tank vertical welds for zero leakage conditions.
COOK,R J ; KNOP,R C Region 3, Chicago, Office of the Director 79/05/29 10pp

7908030623 Forwards IE Insp Repts 50-329/79-10 & 50-330/79-10 on 790514-17 & notice of violation.
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/06 2pp

--7908030629 Notice of violation from insp on 790514-17.
* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/01 2pp

--7908030633 IE Insp Repts 50-329/79-10 & 50-330/79-10 on 790514-17. Noncompliance noted:failure to properly translate FSAR design requirements into specs & procedures.
GALLAGHER,E J Region 3, Chicago, Reactor Construction & Engineering Support Branch ; LEE,E W ; HAYES,D W Region 3, Chicago, Office of the Director 79/06/01 11pp

7908150450 Forwards IE Insp Repts 50-329/79-12 & 50-330/79-12 on 790508-11 & notice of violation.
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/19 2pp

--7908150457 Notice of violation from insp on 790508-11.
* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/15 3pp

--7908150482 IE Insp Repts 50-329/79-12 & 50-330/79-12 on 790508-11. Noncompliance noted:inadequate drawing control,welding procedure qualification & matl receipt insp.
BARRETT,P A ; KNOP,R C Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/15 28pp

7908090297 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breakers in engineered safety sys. Westinghouse DB-50 & DB-75 circuit breakers not in use in safety-related sys.
HOWELL,S H Consumers Power Co 79/06/21 1p

7908090632 Responds to IE Bulletin 79-02,Revision 1.Reinspections needed to accomplish Item 4 requirements will not be complete until Jul 1979.May have problem meeting required imbedment depths.Forwards rept re Bechtel bolts.
HOWELL,S H Consumers Power Co 79/07/03 8pp

--7908090634 "Rept on Prying Action in Bolts for Bechtel SA-717."
MARK,R Bechtel Power Corp (subs of Bechtel Corp.) 79/05/14 18pp

--7908090637 Tech Specs for furnishing,installation & testing of expansion type concrete anchors.
* Consumers Power Co 79/02/05 36pp

7908130658 Submits final response to IE Bulletin 79-03.Only 1 ft of ASME SA-312,TP-304 or TP-316 in use in facility.Examination & repair of pipe not necessary.Pipe is unlikely to fail from pressure due to location.
HOWELL,S H Consumers Power Co 79/07/16 2pp

7908060199 Ack receipt of 790629 ltr informing NRC of steps taken to correct violations noted IE Insp Repts 50-329/79-13 & 50-330/79-13.
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/18 1p

--7908060212 Responds to NRC 790530 ltr re violations noted in IE Insp Repts 50-329/79-13 & 50-330/79-13.Corrective actions:incore instrument tank retested on 790516 using borescope.Rept will be available by 790715.
HOWELL,S H Consumers Power Co 79/06/29 2pp

7908150412 Ack receipt of 790629 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-329/79-10 & 50-330/79-10.
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/23 1p

--7908150418 Responds to NRC 790606 ltr re violation noted in IE Insp Repts 50-329/79-10 & 50-330/79-10. Corrective actions FSAR change notices are in process & will be incorporated no later than Aug 1979.
HOWELL, S. H. Consumers Power Co. 79/06/29. 3pp.

7908290330 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300402 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908150344 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300272 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908270345 Forwards Bechtel nonconformance monthly rept, Bechtel nonconformance rept log sheets, Bechtel quality action requests, Bechtel mgt corrective action rept, BSW repts of nonconformity & CPC nonconformance repts.
DOWELL, S. D. Consumers Power Co. 79/08/25. 800pp.

S. Reportable occurrences, LERs & related correspondence

7908030388 Ack receipt of 790525 interim rept on electrical penetration assembly, per 10CFR50.55. Review will be completed during future insp.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/19. 1p.

7908030414 Ack receipt of 790608 interim rept on pressurizer heater sys, per 10CFR50.55. Final rept will be reviewed upon receipt.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/19. 1p.

7908270269 Ack receipt of 790620 interim rept re status display panel modules.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/12. 1p.

7908270274 Ack receipt of 790625 interim rept re settlement of diesel generator foundation & bldg. Rept will be reviewed during 790718 meeting in Bethesda, MD.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/12. 1p.

7908270279 Ack receipt of 790620 interim rept re main feed piping impact testing.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/12. 1p.

7908060405 Forwards interim deficiency rept on status of main feed pipe spools which have questionable impact test results & summary of sequence of events associated w/each of heats of piping spools.
HOWELL, S. H. Consumers Power Co. 79/08/01. 4pp.

--7908060410 Interim Deficiency Rept 2 re impact-testing of main feedwater pipe. Bechtel Corp is presently pursuing acceptability of matl associated w/Heats N-32762 & L-20479. Reportable condition remains uncertain.
* Bechtel Power Corp. (subs. of Bechtel Corp.). 79/07/26. 6pp.

7908140360 Forwards interim deficiency rept re svc water supply pressure for containment air coolers. Util 790711 QA program mgt corrective action rept encl.
HOWELL, S. H. Consumers Power Co. 79/08/07. 2pp.

--7908140366 Deficiency rept re svc water supply pressure for containment air coolers. Corrective action will be taken to ensure that boiling does not occur in containment air coolers & that design conforms to SAR.
MASSING, D. Bechtel Associates Professional Corp. 79/08/02. 2pp.

7908170390 Forwards interim rept re settlement of diesel generator foundations & bldg. Documents re presentation at 790718 meeting w/NRC encl.
HOWELL, S. H. Consumers Power Co. 79/08/10. 2pp.

--7908170393 Interim rept re settlement of diesel generator foundations & bldg, per presentation at 790718 meeting w/NRC. Oversized drawings encl.
* Consumers Power Co. 79/07/18. 14pp.

7908210421 Forwards interim deficiency rept on status of discrepant terminal block disconnect links. Final rept will be sent by 791026.
HOWELL, S. H. Consumers Power Co. 79/08/10. 1p.

--7908210431 Interim deficiency rept re discrepant terminal block disconnect links. Terminal block manufacturer, major equipment suppliers will be informed of [illegible]ency. Schedule of corrective action will be in Interim Rept 2.
* Consumers Power Co. 79/07/20. 5pp.

7908210447 Submits interim deficiency rept re potential unsafe conditions if reactor coolant pumps are tripped after high sys void fractions develop in loop. Util considering automatic safety grade trip sys.
HOWELL, S. H. Consumers Power Co. 79/08/15. 1p.

7908210477 Submits interim rept re potentially unsafe situation if reactor coolant pumps are tripped after high sys void fractions develop in loop. Analyses show safe condition if pumps are tripped promptly in transient.
HOWELL, S. H. Consumers Power Co. 79/08/15. 1p.

7908290402 Final deficiency rept re station battery qualification test failure. Caused by design discrepancy. Production of new design will begin 790901. Bechtel 790815 ltr rept encl.
HOWELL, S. H. Consumers Power Co. 79/08/23. 4pp.

7908290560 Forwards QA program Mgt Corrective Action Rept 33 re discrepancies found in containment bldg tendons supplied by Inryco. Next rept will be sent by 790928.
HOWELL, S. H. Consumers Power Co. 79/08/23. 2pp.

--7908290567 QA program Mgt Corrective Action Rept 33, tendons in containment bldg found to have unknown wire lengths. Caused by manufacturer & QA program errors. Production equipment & QA procedures being corrected.
* Consumers Power Co. 79/07/27. 4pp.

T. Hearing transcripts on non-antitrust matters

7908060105 Transcript of 790724 hearing in Bethesda, MD. Pp 53,602-53,836.
MILLER, M. E., LEEDS, J. V., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 79/07/24. 235pp.

7908060065 Transcript of 790725 hearing in Bethesda, MD. Pp 53,837-54,000.
MILLER, M. E., LEEDS, J. V., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 79/07/25. 164pp.

7908080548 Transcript of 790730 meeting in Bethesda, MD. Pp 54,001-54,117.
MILLER, M. E., LEEDS, J. V., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 79/07/30. 117pp.

7908080543 Transcript of 790731 meeting in Bethesda, MD. Pp 54,118-54,343.
MILLER, M. E., LEEDS, J. V., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 79/07/31. 225pp.

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F. Security, medical, emergency & fire protection plans

7908060154 Requests prompt forwarding of Class III fee for 790319 safeguards contingency plan.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908030505 Submits fee for review of plant safeguards contingency plan forwarded on 790319.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/24. 1p.

7908210509 Forwards modified security organization training & qualification plan. Plan withheld (ref 10CFR2.790).
ROOT, L. D. Iowa Electric Light & Power Co. 79/08/17. 1p.

V. Adjudicatory correspondence

7908090529 Forwards petition filed on behalf of Citizens United for Responsible Energy requesting issuance of order to suspend Amend 46 to License DPR-49. Notice of publication encl.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/26. 2pp.

--7908090533 Notice of 790409 petition by Citizens United for Responsible Energy 790409 petition requesting order to suspend Amend 46 to License DPR-49. Petition is treated as 10CFR2.206 request for action.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/26 1p

H. General correspondence

7908020436 Responds to 790629 ltr re corporate capabilities. Outlines responsibilities & personnel.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/30 113pp.

J. Insurance & indemnity information

7908210536 Forwards Endorsements 43 & 44 to NELIA Policy NF-214 & Endorsements 36 & 37 to MAELU Policy MF-72.
LOWENSTEIN, R. Lowenstein, Newman, Reis, Axelrad & Toll 79/08/13 5pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards 79/03/22 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908030066 Notifies of loss of environ sample location. Station 103 has replaced Station 75. Change in sample location affects surface water samples.
HAMMOND, E. L. Iowa Electric Light & Power Co. 79/06/15 1p.

7908070669 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/22 3pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch 79/06/27 2p.

7908150328 Discusses QA/QC reorganization. Appropriate documentation changes are being made.
TUTHILL, S. J. Iowa Electric Light & Power Co. 79/07/06 1p.

7908090598 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires initial notification of NRC.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/09 1p.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch 79/07/11 26pp.

7908030136 Summary of 790706 meeting w/util in Bethesda, MD re results obtained in testing of concrete expansion anchor bolts & evaluation of base plates as required in IE Bulletin 79-02, Revision 1.
JORDAN, E. L. Division of Reactor Operations Inspections 79/07/16 4pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering 79/07/16 4pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors 79/07/18 1p.

7908070342 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/19 1p.

7908170212 Responds to 790319 submittal of Chapter 8 of modified amended security plan. Document does not fulfill requirements. Forwards Reg Guide 5.54, "Std Format & Content for Nuclear Power Plant Safeguards Contingency Plans."
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/20 18pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch 79/07/24 1p.

7908070557 Notifies that contract negotiations which caused 7-wk work stoppage have been completed & were approved 790729 by electrical union. Work to begin 790730. NRC will be notified of const schedule update.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/30 1p.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp.

7908210473 Plans to submit response to 790713 request for addl info via group response of BWR Post-TMI Owners Group on 790817.
ROOT, L. D. Iowa Electric Light & Power Co. 79/08/10 1p.

7908270443 Responds to NRC 790813 request to suppl 781227 submittal re application of measured scram times.
ROOT, L. D. Iowa Electric Light & Power Co. 79/08/15 10pp.

7908270426 Amends 781227 application for amend of License DPR-49 to reflect mod needed to provide operating margin improvements.
ROOT, L. D. Iowa Electric Light & Power Co. 79/08/17 7pp.

Q. Inspection reports, IE Bulletins & correspondence

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790828 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625) 79/06/20 44pp.

7908090506 Responds to IE Bulletin 79-07. No response is required for Items 1, 2 & 4. Describes seismic analysis of GE-supplied main steam & recirculation sys piping performed by Nuclear Svc Corp.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/02 2pp.

7908100130 Responds to IE Bulletin 79-11 re defective overcurrent trip devices in circuit breakers for engineered safety sys. Initial review did not identify faulty devices. Final response to be forwarded by 790815.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/02 1p.

7908020218 Notification of 790706 meeting w/util in Bethesda, MD to discuss results of concrete expansion anchor bolt testing done in response to IE Bulletin 79-02.
JORDAN, E. L. Division of Reactor Operations Inspections 79/07/05 1p.

7908100164 Responds to IE Bulletin 79-02. Requests delay in answering action items until after 790706 meeting w/NRC.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/06 1p.

7908130205 Summarizes results of 790706 meeting re IE Bulletin 79-02, Revision 1. Licensee will evaluate operability of safety systems & anchor bolt installations in concrete block walls. Written rept will be submitted by 790710.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/06 1p.

7908140150 Responds to NRC 790706 immediate action ltr. Forwards Bechtel rept developed per 790706 meeting between NRC & util to discuss test results re IE Bulletin 79-02. Safety-related sys are operational as required per Tech Specs.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/10 9pp.

7908140160 Forwards documentation supporting responses conveyed to NRC during 790711 telcon re util 790710 ltr. Supplements response to 790706 immediate action ltr re evaluation of five failed supports.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/11 4pp.

7908150245 Supplements 790710 response to IE Bulletin 79-02 re support base plate designs using concrete expansion anchor bolts. All base plates using expansion bolts were inspected & modified, as required.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/11. 11pp.

7908020334 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908080320 Requests addl info to suppl previous response to IE Bulletin 79-08 to enable NRC to complete safety evaluation.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/20. 4pp.

7908290365 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300408 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908230627 Forwards response to IE Bulletin 79-12 Modified control rod sequence implemented.
ROOT, L. D. Iowa Electric Light & Power Co. 79/07/31. 2pp.

7908150356 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908170023 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08. 1p.

7908300279 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908210514 Forwards monthly operating rept for Jul 1979.
HAMMOND, E. L. Iowa Electric Light & Power Co. 79/08/14. 1p.

--7908210516 Monthly operating rept for Jul 1979.
VAN SICKEL, J. Iowa Electric Light & Power Co. 79/08/14. 8pp.

S. Reportable occurrences, LERs & related correspondence

7908090031 Responds to 790613 request re outage to repair reactor recirculation safe-ends. Forwards Keppler 790206 memo, 790206 key memo files, Williams 790206 memo files, 790122 parameter rept & Collins 790305 memo.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/19. 1p.

--7908090058 Notifies of position on safe-end welds. Welds do not satisfy intent of safety evaluation rept on Amend 47 for OL. Relief to operate w/welds would require consideration of stress analysis, leak detection & inservice insp.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/02/06. 3pp.

--7908090064 Submits interpretation of radiographic examination of recirculation nozzle safe-end repair welds.
KEY, W. J. Region 3, Chicago, Office of the Director. 79/02/06. 2pp.

--7908090071 Forwards interpretation of radiographic examination of recirculation nozzle safe-end repair welds.
WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 79/02/06. 6pp.

--7908090075 "Rept of Review of Radiographs of Repaired Recirculation Inlet Nozzle/Safe-End/Pipe Welds." Half of nozzles tested were unacceptable, per ASME code.
RISTAU, R. A. Parameter, Inc. 05-77-186. 79/01/22. 3pp.

--7908090079 Forwards interpretation & evaluation of radiograph of nozzle safe-end repair welds.
COLLINS, W. J. Office of Inspection & Enforcement, Office of the Director. 79/03/05. 7pp.

7908010443 Notifies of RD during normal operation, plant heat rate & efficiencies were better than normally expected. Caused by violation of licensed core thermal power limit during prior operation.
HAMMOND, E. L. Iowa Electric Light & Power Co. 79/07/26. 1p.

7908100418 Forwards LER 79-015/03L-0.
HAMMOND, E. L. Iowa Electric Light & Power Co. 79/08/03. 1p.

--7908100423 LER 79-015/03L-0 on 790705 surveillance test to measure relay dropout voltage not incorporated into test for LPCI & core spray trip sys bus power monitor relay. Caused by deletion of procedure following Change 15 to Tech Specs.
VANSICKEL, J. Iowa Electric Light & Power Co. 79/08/03. 1p.

7908130414 Forwards LER 77-006/01X-1.
HAMMOND, E. L. Iowa Electric Light & Power Co. 79/08/03. 1p.

--7908130420 LER 77-006/01X-1 on 770118 snubber HBB-6-SS-22 on HPCI turbine exhaust line had broken piston. Caused by cyclic pipe deflection. GBD-29-SS-12 on auxiliary boiler had broken loose from mounting point. Caused by vibration.
ZIMMERMAN, J. C. Iowa Electric Light & Power Co. 79/08/03. 1p.

7908150045 Forwards LER 79-016/01T-0.
HAMMOND, E. L. Iowa Electric Light & Power Co. 79/08/08. 1p.

--7908150050 LER 79-016/01T-0 on 790725 plant heat rate & efficiencies better than expected during normal plant operation. Caused by bypass low feedwater flow through valve manifold equalizing valves. Valves lapped & reassembled.
VANSICKEL, J. Iowa Electric Light & Power Co. 79/08/08. 2pp.

7908310370 Forwards LER 79-018/03L-0.
HAMMOND, E. L. Iowa Electric Light & Power Co. 79/08/24. 1p.

--7908310377 LER 79-018/03L-0 on 790726 during surveillance testing, pressure differential switches to reactor bldg vacuum breakers tripped out of spec values. Pressure differential 4305 was out of tolerance due to instrument drift.
SICKEL, J. V. Iowa Electric Light & Power Co. 79/08/24. 1p.

7908310487 Forwards LER 79-019/03L-0.
HAMMOND, E. L. Iowa Electric Light & Power Co. 79/08/27. 1p.

--7908310499 LER 79-019/03L-0 on 790728 following power increase by approved procedures, critical power ratio was found to be in violation of Tech Spec limit. Caused by xenon transient causing thermal power increase.
VAN SICKEL, J. Iowa Electric Light & Power Co. 79/08/27. 1p.

DOCKET 50-332 BARNWELL REPROCESSING PLANT

G. Inspection reports, IE Bulletins & correspondence

7908130393 Ack receipt of IE Insp Rept 50-332/79-01 on 790604-07. No proprietary info.
BAXTER, R. C. Allied General Nuclear Services. 79/06/25. 1p.

--7908130397 Forwards IE Insp Rept 50-332/79-01 on 790604-07. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/20. 2pp.

--7908130399 IE Insp Rept 50-332/79-01 on 790604-07. No noncompliance noted. Major areas inspected: organization, internal audit program, safety committees & witness of preoperational test in progress.
CORYELL, G. P., POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/20. 5pp.

DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

7908130202 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908020422 Lists items of fire protection program requiring addl time for response & proposed dates for response.
EARLY, P. J. Power Authority State of New York. 79/07/27. 4pp.

7908280013 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
BERRY, G. T. Power Authority State of New York. 79/08/20. 1p.

DOCKETED ITEMS

G. Adjudicatory correspondence

7907120284 Ack receipt of 790313 ltr commenting on shutdown of five nuclear power plants in eastern US. Objective is to review situation in expedited & disciplined manner so that plants can be returned to operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/22. 1p.

H. General correspondence

7908100055 Responds to 790313 ltr opposing shutdown of five plants due to questions re ability of piping sys to withstand earthquakes. Earthquake maps of eastern OH & western PA encl.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/09. 3pp.

--7908100066 Opposes plant shutdown due to earthquake concerns.
CAMPBELL, W. R. Affiliation Unknown. 79/03/17. 2pp.

7908200012 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200046 Commends NRC shutdown of five nuclear plants.
BORTIN, B. Affiliation Unknown. 79/03/17. 1p.

--7908200063 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200065 Commends NRC move to shut down five plants.
MARSCHARK, E. D. Affiliation Unknown. 79/03/16. 2pp.

--7908200070 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200073 Applauds NRC shutdown of five plants due to seismic inadequacy.
FUSCO, G. Affiliation Unknown. 79/03/27. 1p.

--7908200078 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200080 Thanks NRC for closing down unsafe plants.
THOMSON, J. Affiliation Unknown. 79/05/17. 1p.

--7908200087 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200091 Applauds NRC shutdown of five nuclear power plants.
COLEMAN, E. Affiliation Unknown. 79/03/28. 1p.

J. Insurance & indemnity information

7908220364 Forwards Endorsement 37 to MAELU Policy MF-77.
DEEG, F. H. Power Authority State of New York. 79/08/13. 2pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908070461 Notifies of intent to install second communications sys. linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/06/22. 3pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908020344 Summary of 790619 meeting w/util in Bethesda, MD re safety-related piping reanalysis necessitated by 790313 show cause order & NRC requirements for interim & unlimited plant operation.
POLK, P. J. Operating Reactors Branch 3. 79/06/29. 4pp.

7908130303 Requests that util propose changes to Tech Specs re responsibilities of senior reactor operator. All core operations should be directly supervised by senior reactor operator who has no other responsibilities during operation.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/06. 3pp.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908070255 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908300048 Forwards four revised pages to 790517 Amend 46 to License DPR-59, App B ETS.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/20. 7pp.

7908300040 Notifies that approval of 790626 application for amend of OL is contingent upon satisfactory response to IE Bulletin 79-15 re deep draft pump deficiencies.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/21. 2pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908020435 Requests Tech Spec change revising definition of "cold shutdown" & "cold condition" to allow placement of reactor mode selector switch in refuel mode & in startup/hot standby mode. Change must be completed prior to startup.
EARLY, P. J. Power Authority State of New York. 79/07/27. 2pp.

7908210075 Notification of 790802 meeting w/util & S&W in New York, NY to discuss NRC review of facility mods & 790312 show cause order.
POLK, P. J. Operating Reactors Branch 3. 79/07/31. 1p.

7908240041 Forwards Amend 47 to License DPR-59, safety evaluation & notice of issuance & availability.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/01. 3pp.

--7908240047 Amend 47 to License DPR-59 adding condition re completion of facility mod for fire protection.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/01. 2pp.

--7908240049 Safety evaluation supporting Amend 47 to License DPR-59.
Office of Nuclear Reactor Regulation. 79/08/01. 64pp.

--7908240054 Notice of issuance & availability of Amend 47 to License DPR-59.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/08/01. 2pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908230155 Requests utils provide description of methods t .erify that offsite power sys & onsite distribution sys are capable automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

7908150676 Provides addl info per 790802 commitments, in response to NRC 790807 request re plant startup Schedule for pipe support evaluations & discussion of seismic analysis of suppression chamber water level encl
EARLY, P. J. Power Authority State of New York 79/08/10 7pp

7908170324 Forwards response to NRC 790629 request for info on mgt & technical resources
EARLY, P. J. Power Authority State of New York 79/08/13 1p

--7908170328 "Mgt & Technical Resources."
* Power Authority State of New York 79/08/13 200pp

7908210544 Notifies that analysis of five supports associated w/HPCI sys is complete Identified supports will be modified prior to startup
EARLY, P. J. Power Authority State of New York 79/08/14 1p

7908200314 Forwards supplemental info to 790302 ltr re justification for continued containment purging during normal plant operation Summary review of all safety actuation signal circuits using manual override & oversized drawings encl
EARLY, P. J. Power Authority State of New York 79/08/15 11pp

7908270359 Requests 30-day extension for implementation of Amend 47 to DPR-59 in order to review commitments & suggested mods
BERRY, G. T. Power Authority State of New York 79/08/17 1p

7908280601 Withdraws 730419 commitment to install decoupling devices between recirculation pump & motor as means of preventing overspeeds following LOCA GE Rept NEDO-10677 states measures are unnecessary
EARLY, P. J. Power Authority State of New York 79/08/22 2pp

G Inspection reports, IE Bulletins & correspondence

7908170077 Forwards IE Insp Rept 50-333/79-06 on 790430-0504 No noncompliance noted
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/18 2pp

--7908170082 IE Insp Rept 50-333/79-06 on 790430-0504 No noncompliance noted Major areas inspected licensee pipe support verification program, expansion anchor testing, preliminary activities & findings per IE Bulletin 79-02
DURR, J. P. Region 1, Philadelphia, Office of the Director
TRIPP, L. E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/13 4pp

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08 Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review
IPPOLITO, T. A. Operating Reactors Branch 3 (Prm 790625) 79/06/20 44pp

7908070501 Responds to IE Bulletin 79-09 Preventative maint performed on all GE Type AK-2 breakers in safety-related applications at facility No conditions found which would prevent breakers from performing intended function
LEONARD, J. D. Power Authority State of New York 79/06/28 1p

7908070808 Responds to IE Bulletin 79-02, Revision 1, re pipe supports Review under way for concrete expansion anchor & pipe support base plates Explains extensive testing program re adequacy of expansion anchors
LEONARD, J. D. Power Authority State of New York 79/07/06 4pp

7908070650 Responds to IE Bulletin 79-14 Util is conducting seismic analyses, per NRC 790313 show cause order, which meet requirements of bulletin A/E revising documents to reflect as-built piping conditions in plant
LEONARD, J. D. Power Authority State of New York 79/07/09 1p

7908280828 Responds to IE Bulletins 78-12, 78-12A & 78-12B Reactor vessel contains no atypical welds
LEONARD, J. D. Power Authority State of New York 79/07/09 2pp

--7908280838 Responds to IE Bulletins 78-12, 78-12A & 78-12B Recommends C-E 790608 ltr re NRC request for verification of generic search
EGGER, E. R. General Electric Co 79/06/20 1p

--7908280849 Responds to IE Bulletin 78-12 Forwards "Info Requested by IE Bulletin 78-12, Atypical Weld Matl in Reactor Pressure Vessel Welds"
SCHERER, A. E. Combustion Engineering, Inc 79/06/08 2pp

7908010513 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/17 1p

7908060395 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908030261 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/19 1p

7908080329 Requests addl info to suppl previous response to IE Bulletin 79-08 to enable NRC to complete safety evaluation
IPPOLITO, T. A. Operating Reactors Branch 3 79/07/20 4pp

7908290673 Responds to IE Bulletin 79-12 re short period scrams at BWRs Operating procedure will be established to require banked withdrawal of Control Rod Groups 2-4 when Xenon concentration is at or near peak conditions
LEONARD, J. D. Power Authority State of New York 79/07/24 2pp

7908100250 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/26 1p

7908090320 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/30 1p

7908290158 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/07 1p

7908140626 Responds to request for addl info re IE Bulletin 79-08 concerning safety injection sys training instructions, critical values, inadvertent transfer of radioactive liquids & visual checks of sys status
LEONARD, J. D. Power Authority State of New York 79/08/08 4pp

7908230358 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/08 1p

7908270557 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908280314 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/13 1p

7908310290 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

7908300161 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/15 1p

R Periodic operating reports & related correspondence

7908070593 Forwards monthly operating rept for Jul 1979
LEONARD, J. D. Power Authority State of New York 79/08/03 1p

--7908070599 Monthly operating rept for Jul 1979
ZUFELT, E. Power Authority State of New York 79/08/03 13pp

DOCKETED ITEMS

7908300646 Forwards "Effluent & Waste Disposal Semiannual Rept." Jan-June 1979.
LEONARD, J. D. Power Authority State of New York. 79/08/15. 1p.

--7908300649 "Effluent & Waste Disposal Semiannual Rept." Jan-June 1979.
* Power Authority State of New York. 79/08/15. 84pp.

B. Reportable occurrences, LERs & related correspondence

7908060479 Forwards LER 79-042/03L-0.
LEONARD, J. D. Power Authority State of New York. 79/08/02. 1p.

--7908060500 LER 79-042/03L-0 on 790713 RHR svc water pump 10-P-1A & 10-P-1C could deliver only 7800 gallons per minute. Caused by installation of improper orifice in RHR svc water discharge line. Orifice removed & willbe modified.
CHILDS, W. V. Power Authority State of New York. 79/08/03. 2pp.

7908060521 Forwards LER 79-041/03L-0.
LEONARD, J. D. Power Authority State of New York. 79/08/02. 1p.

--7908060527 LER 79-041/03L-0 on 790711 procedure for drywell equipment drain pump functional test & calibr was in error. Caused by implementation of plant mod during 1978 refueling outage in which equipment pump level control logic was revised.
CHILDS, W. V. Power Authority State of New York. 79/08/02. 2pp.

7908060441 Forwards LER 79-044/03L-0.
LEONARD, J. D. Power Authority State of New York. 79/08/03. 1p.

--7908060448 LER 79-044/03L-0 on 790720 mainstream line tunnel radiation monitor D drifted so that indicator & trip point were approx 5.5% low. Caused by instrument drift. Instrument calibr & tested.
CHILDS, W. V. Power Authority State of New York. 79/08/03. 2pp.

7908060461 Forwards LER 79-043/03L-0.
LEONARD, J. D. Power Authority State of New York. 79/08/03. 1p.

--7908060471 LER 79-043/03L-0 on 790718 discharge check valve associated w/electric motor driven fire pump failed to properly reseat following pump shutdown. Caused by small pebble between valve clapper & valve body. Returned to svc.
CHILDS, W. V. Power Authority State of New York. 79/08/03. 2pp.

7908290456 Forwards LER 79-045/03L-0.
LEONARD, J. D. Power Authority State of New York. 79/08/24. 1p.

--7908290464 LER 79-045/03L-0 on 790725 during conduct of entitled containment hydrogen analyzer F-ISP-30, one analyzer was found out of calibr. Cause not stated. Analyzer recalibr.
CHILDS, W. V. Power Authority State of New York. 79/08/24. 2pp.

U. Congressional/Executive Correspondence

7908020237 Ack receipt of 790318 ltr to President Carter re NRC order to shut down five nuclear plants for seismic reasons. Review of piping sys is in progress. Forwards earthquake map for VA.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/06. 3pp.

--7908020241 Forwards CJ Hemmer 790318 ltr for response. Ltr protests closing of five nuclear power plants for seismic reasons.
ZINN, P. A. President of US & Executive Offices. 79/03/21. 2pp.

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7908270237 Ack receipt of 790322 ltr transmitting safeguards contingency plan for facility Class III fee required.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908220007 Forwards security organization training & qualification plan. Plan withheld (ref 10CFR2.790).
DUNN, C. N. Duquesne Light Co. 79/08/16. 1p.

G. Adjudicatory correspondence

7907120284 Ack receipt of 790313 ltr commenting on shutdown of five nuclear power plants in eastern US. Objective is to review situation in expedited & disciplined manner so that plants can be returned to operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/22. 1p.

7908230348 Forwards order for termination of proceeding initiated by 790313 show cause order.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/08/08. 3pp.

--7908230352 Order terminating proceeding initiated by 790313 show cause order re cold shutdown condition.
MATTSON, R. J. Office of Nuclear Reactor Regulation. 79/08/08. 10pp.

--7908230357 Safety evaluation supporting order terminating proceeding initiated by 790313 show cause order re cold shutdown condition. Facility may resume power operation.
* Office of Nuclear Reactor Regulation. 79/08/08. 16pp.

H. General correspondence

7908100055 Responds to 790313 ltr opposing shutdown of five plants due to questions re ability of piping sys to withstand earthquakes. Earthquake maps of eastern OH & western PA encl.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/09. 3pp.

--7908100066 Opposes plant shutdown due to earthquake concerns.
CAMPBELL, W. R. Affiliation Unknown. 79/03/17. 2pp.

7908200012 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200046 Commends NRC shutdown of five nuclear plants.
BORTIN, B. Affiliation Unknown. 79/03/17. 1p.

--7908200063 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200065 Commends NRC move to shut down five plants.
MARSCHARK, E. D. Affiliation Unknown. 79/03/16. 2pp.

--7908200070 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200073 Applauds NRC shutdown of five plants due to seismic inadequacy.
FUSCO, G. Affiliation Unknown. 79/03/27. 1p.

--7908200078 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200080 Thanks NRC for closing down unsafe plants.
THOMSON, J. Affiliation Unknown. 79/05/17. 1p.

--7908200087 Ack receipt of ltr commending NRC 790313 order to shut down plants for possible seismic inadequacy. NRC objective is to return plants to safe operation.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/17. 1p.

--7908200091 Applauds NRC shutdown of five nuclear power plants.
COLEMAN, E. Affiliation Unknown. 79/03/28. 1p.

P. Operating license stage documents & correspondence

7908150507 Responds to FOIA request for records re Task Action Plans A-40 & A-41, documents written by HR Denton & C Stepp, records re seismic issues & insp repts for facilities. Requested documents will be made available.
FELTON, J. M. Division of Rules and Records. 79/05/04. 2pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operatin history of PWR feedwater lines.
STELLO, V. Divis on of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908070434 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/06/22. 3pp.

7908010351 Responds to util 790307 request for technical assistance re degraded grid voltage. Addl info required by NRC to complete review. Request for addl info encl.
LAINAS, G. Plant Systems Branch. 79/07/02. 4pp.

7908130640 Requests addl info for review of degraded grid voltages on safety-related station electrical buses.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/05. 4pp.

7908100586 Discusses program to upgrade bases section of STS. Amends resulting from upgrading program will be fee-exempt.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/11. 2pp.

7908210066 Forwards Amend 19 to License DPR-66, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/17. 2pp.

7908210071 Amend 19 to License DPR-66, revising Tech Specs & requiring actuation of safety injection based on two out of three channels of low pressurizer pressure.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/17. 11pp.

--7908210074 Safety evaluation supporting Amend 19 to License DPR-66.
* Office of Nuclear Reactor Regulation. 79/07/17. 2pp.

--7908210076 Notice of issuance & availability of Amend 19 to License DPR-66.
TRAMMELL, C. M. Operating Reactors Branch 1. 79/07/17. 2pp.

7908070234 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908010574 Forwards Revision 3 to "Rept on Reanalysis of Safety-Related Piping Sys." Change reflects up-to-date reanalysis & mod program.
DUNN, C. N. Duquesne Light Co. 79/07/27. 2pp.

--7908010580 "Rept on Reanalysis of Safety-Related Piping Sys," Revision 3.
* Stone & Webster Engineering Corp. 79/07/03. 52pp.

7908080198 Notifies that 790626 Tech Spec Change Request 38 involved safety issue which required Class III amend fee. Requests addl amend fee be forwarded to NRC.
MILLER, W. O. License Fee Management Branch. 79/07/30. 1p.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch. 79/07/30. 64pp.

7908220064 Notifies that 790626 Tech Spec Change Request 39 application involves Class III amend fee. Requests addl $2,800 be forwarded to NRC.
MILLER, W. O. License Fee Management Branch. 79/07/31. 1p.

7908290642 Forwards request for addl info to util proposed steam break protection sys & N-1 loop operation.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/31. 6pp.

7908130574 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/01. 4pp.

7908080480 Forwards addl fee for Class III amend to License DPR-66, per 790730 ltr.
MOORE, G. W. Duquesne Light Co. 79/08/03. 1p.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908240175 Forwards for consideration draft order & draft safety evaluation re facility shutdown per lack of assurance that analysis of piping sys for seismic loads provided proof of safe shutdown during seismic event.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/08/03. 1p.

--7908240182 Draft order not requiring continued shutdown of facility or termination proceeding initiated by 790313 order. Analysis & mod to fuel pool cooling & purification sys required before further use.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/08/03. 10pp.

--7908240188 Draft safety evaluation supporting resumption of operation per required mods to seven supports, addition of three others & approval of two supports not yet found to be acceptable.
* Office of Nuclear Reactor Regulation. 79/08/03. 16pp.

7908090480 Forwards Revision 4 to "Rept on Reanalysis of Safety-Related Piping Sys."
DUNN, C. N. Duquesne Light Co. 79/08/07. 2pp.

--7908090483 Revision 4 to "Rept on Reanalysis of Safety-Related Piping Sys."
* Stone & Webster Engineering Corp. 79/08/03. 7pp.

7908140665 Forwards addl remittance of $2,800 for Class III amend, per 790626 request. Class II fee accompanied 790626 submittal re Tech Spec Change Request 39. Addl amount corrects fee to Class III.
MOORE, G. W. Duquesne Light Co. 79/08/08. 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908140839 Forwards Revision 1 to 1978 reactor containment integrated leak rate test rept.
DUNN, C. N. Duquesne Light Co. 79/08/10. 1p.

--7908140841 Revision 1 to 1978 reactor containment integrated leak rate test rept. Revision includes more detailed info concerning containment air lock leak testing & date correction re performance of Type B leak tests.
* Duquesne Light Co. 79/08/10. 11pp.

G. Inspection reports, IE Bulletins & correspondence

7908080305 Requests addl info in order to complete review of inservice insp program re safety injection sys & piping, high head safety injection pump, boron injection sys & containment spray sys.
SCHWENCER, A. Operating Reactors Branch 1. 79/06/27. 3pp.

7908130058 Forwards NUREG-0397, describing revised insp program that includes assignment of resident inspectors at selected reactor & major fuel facility sites. Further steps are being taken to deploy addl inspectors in near future. W/o encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/06/29. 2pp.

7908030251 Responds to IE Bulletins 78-12, 12A & 12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Generic rept info submitted to NRC by C-E, Inc on 780608 contained all pertinent weld vessel info.
DUNN, C. N. Duquesne Light Co. 79/07/05. 1p.

7908130595 Responds to IE Bulletin 79-11 re potential failure of circuit breaker overcurrent trip devices. Westinghouse Type DB-50 & DB-75 breakers not used in safety-related Class IE sys at plant.
DUNN, C. N. Duquesne Light Co. 79/07/05. 1p.

7908070812 Responds to IE Bulletin 79-02 re pipe supports using concrete expansion anchor bolts. Verifies satisfactory pipe support base plate flexibility, concrete expansion anchor bolts safety & related QC documentation.
WOOLEVER, E. J. Duquesne Light Co. 79/07/06. 3pp.

7908170143 Responds to 790502 proposed inserv. . insp program. Submittal requires Class III fee.
MILLER, W. O. License Fee Management Branch. 79/07/06. 1p.

7908070303 Forwards responses to IE Bulletin 79-02 re use of pipe support base plates in Seismic Category I sys. Insp program will not be complete until startup. Significant sampling conducted w/acceptable results.
DUNN, C. N. Duquesne Light Co. 79/07/09. 78pp.

7908150718 Forwards supplemental response to IE Bulletin 79-06A. Revised operating procedures that have been approved include actuation, loss of reactor coolant, loss of secondary coolant & steam generator tube rupture.
DUNN, C. N. Duquesne Light Co. 79/07/12 9pp.

7908170355 Responds to IE Bulletin 79-13, Item 5 re cracking in feedwater sys piping. Procedures dealing w/feedwater line break accident were determined to be adequate during insp completed 790708.
DUNN, C. N. Duquesne Light Co. 79/07/16 3pp.

7908010425 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/07/17 1p.

7908020313 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT, K. V. Region 1, Philadelphia, Office of the Director.
79/07/18 1p.

7908030238 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/07/19 1p.

7908100222 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/07/26 1p.

7908100334 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/07/26 1p.

7908090293 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/07/30 1p.

7908130273 Responds to IE Bulletin 79-14 re request for 30-day rept. Submits info re seismic analysis of pipelines.
DUNN, C. N. Duquesne Light Co. 79/07/30 3pp.

7908240587 Submits supplemental response to IE Bulletin 79-02 re interim startup. Submits justification for 790806 interim startup. Analyzes insp & engineering data & status of baseplates & anchor bolts tested.
DUNN, C. N. Duquesne Light Co. 79/07/30 4pp.

7908060354 Responds to IE Bulletin 79-01A re deficiencies in environ qualifications of ASCO solenoid valves. Approx 200 ASCO valves used in safety-related sys. Replacements being ordered & will be installed upon receipt.
DUNN, C. N. Duquesne Light Co. 79/07/31 2pp.

7908280079 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/08/07 1p.

7908210178 Notification of 790809 meeting w/util in Bethesda, MD to discuss IE Bulletin 79-01 & status of environ qualifications of certain electrical equipment.
WIGGINTON, D. L. Operating Reactors Branch 1. 79/08/08 2pp.

7908230300 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/08/08 1p.

7908140578 Responds to 790627 ltr & forwards addl info re inservice insp program. Boron injection & containment spray sys will not be subject to nondestructive examination.
DUNN, C. N. Duquesne Light Co. 79/08/10 1p.

7908270542 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste For Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/08/10 1p.

7908280262 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/08/13 1p.

7908310278 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/08/14 1p.

7908300123 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/08/15 1p.

R. Periodic operating reports & related correspondence

7908060213 Forwards NPDES monthly rept for June 1979.
MOORE, G. W. Duquesne Light Co. 79/07/31 15pp.

7908140518 Forwards monthly operating rept for Jul 1979.
DUNN, C. N. Duquesne Light Co. 79/08/10 1p.

--7908140525 Monthly operating rept for Jul 1979.
SPITZNOGLE, A. E. Duquesne Light Co. 79/08/07 5pp.

S. Reportable occurrences, LERs & related correspondence

7908030022 Submits LER 79-14/01P: cracks found in feedwater piping adjacent to steam generator nozzle to feedwater piping weld at another plant. Addl info & corrective actions will be forwarded.
WERLING, J. A. Duquesne Light Co. 79/06/19 2pp.

7908160147 Submits supplemental info to LER 79-014/01T-0 re identification of cracks in feedwater line elbows. Response fulfills requirements of IE Bulletin 79-13. Tables attached.
DUNN, C. N. Duquesne Light Co. 79/07/17 21pp.

7908010318 RO 79-20/01P on 790724 during baseplate insp procedure, pipe hanger baseplate H-208 discovered inoperable. Caused by lack of formal installation procedure during initial installation. Hanger will be repaired.
WERLING, J. A. Duquesne Light Co. 79/07/24 3 p.

7908010497 Forwards LER 79-019/01T-0.
WERLING, J. A. Duquesne Light Co. 79/07/24 2pp.

--7908010502 LER 79-019/01T-0 on 790723: two of four vendors of wire used in safety injection sys cannot document quality of wire for post-DBA containment environ. Wire will be replaced on four valves during refueling.
WERLING, J. A. Duquesne Light Co. 79/07/24 2pp.

7908010440 Notifies of LER 79-21/01P: during testing of emergency 4kv volt transformers, readings indicated degradation of insulation resistance as compared to original acceptance testing. Transformers will be required.
WERLING, J. A. Duquesne Light Co. 79/07/26 2pp.

7908060275 RO 79-24/01P on 790727: 44 ASCO solenoid valves in reactor containment found to be unqualified. Cause unstated. Investigation continues & rept to follow.
WERLING, J. A. Duquesne Light Co. 79/07/30 2pp.

7908130419 Forwards LERs 78-053/01T-1, 79-008/01T-1, 79-010/01T-1, 79-014/01T-1, 79-015/01T-1 & 79-024/01T-0.
WERLING, J. A. Duquesne Light Co. 79/08/01 2pp.

--7908130424 LER 78-053/01T-1 on 781026: during review of steam injection piping stress calculations, error in original piping stress analysis for one steam injection was discovered. Caused by use of unacceptable computer program. Mods to be installed.
WERLING, J. A. Duquesne Light Co. 79/08/01 2pp.

--7908130426 LER 79-008/01T-1 on 790329: notifies of potential inconsistency of single dropped control rod. Caused by incorrect measurement of core average power level by rod controller during rod drop events.
WERLING, J. A. Duquesne Light Co. 79/08/01 2pp.

--7908130434 LER 79-010/01T-1 on 790416: notifies of potential for failure of inside recirculation spray pump motors. Caused by reduction of internal clearance due to heat gradient as motor comes up to operating temp. Mods made to clearance.
WERLING, J. A. Duquesne Light Co. 79/08/01 2pp.

--7908130438 LER 79-014/01T-1 on 790618: during special radiographic insp of feedwater inlet piping welds, cracking was discovered in inlet elbows. Caused by fatigue failure along w/corrosion. Insp completed & welds repaired.
WERLING, J. A. Duquesne Light Co. 79/08/01 4pp.

--7908130442 LER 79-015/01T-1 on 790621 notifies that high energy line break inside containment could result in potential steam generator level bias. Caused by heatup of steam generator level measurement ref leg. Tech Spec change submitted.
WERLING, J. A. Duquesne Light Co. 79/08/01 2pp.

--7908130445 LER 79-024/01T-0 on 790727 as result of review of ASCO solenoid valves per IE Bulletin 79-01A. 44 valves found w/deficiencies in environ qualifications. Caused by inadequate design.
WERLING, J. A. Duquesne Light Co. 79/08/01 2pp.

7908130458 Forwards LER 79-016/03L-1.
WERLING, J. A. Duquesne Light Co. 79/08/02 2pp.

--7908130462 LER 79-016/03L-1 on 790608 discovered cables on pump header isolation valves incorrectly routed through cable trays. Caused by failure of const personnel to install & verify cable routings per procedure. Routing corrected.
WERLING, J. A. Duquesne Light Co. 79/08/02 1p.

7908100449 Forwards LER 79-018/03L-0.
WERLING, J. A. Duquesne Light Co. 79/08/03 2pp.

--7908100451 LER 79-018/03L-0 on 790703 while switching Vital Bus 3 to alternate source containment isolation, Phase B actuation occurred. Caused by Hi-Hi containment pressure. Revised procedure for transferring vital bus.
WERLING, J. A. Duquesne Light Co. 79/08/03 1p.

7908140749 Forwards LER 79-020/01T-0.
WERLING, J. A. Duquesne Light Co. 79/08/07 3pp.

--7908140768 LER 79-020/01T-0 on 790724 during insp, inoperable pipe hanger baseplate observed. Caused by improper installation of concrete expansion anchors in baseplate due to lack of formal procedures during initial installation.
WERLING, J. A. Duquesne Light Co. 79/08/07 1p.

7908140821 Forwards LER 79-021/01T-0.
WERLING, J. A. Duquesne Light Co. 79/08/09 2pp.

--7908140828 LER 79-021/01T on 790726 meggar readings indicated degradation of insulation resistance during testing of emergency bus GE transformers. Cause not stated. Transformers replaced w/qualified ITE transformers.
WERLING, J. A. Duquesne Light Co. 79/08/09 1p.

7908230430 Forwards LERs 79-019/01T-1 & 79-024/01T-1.
WERLING, J. A. Duquesne Light Co. 79/08/17 2pp.

--7908230435 LER 79-019/01T-1 on 790723 as result of review of safety injection sys cable used in containment, determined that four valves require wire replacement prior to startup. Cable will be replaced during refueling.
WERLING, J. A. Duquesne Light Co. 79/08/17 2pp.

--7908230438 LER 79-024/01T-1 on 790727 as result of review of solenoid valves, determined that 44 valves installed in reactor containment have deficiencies in environ qualifications. Caused by inadequate design. Valves will be replaced.
WERLING, J. A. Duquesne Light Co. 79/08/17 2pp.

7908230510 Forwards LER 79-022/03L-0.
WERLING, J. A. Duquesne Light Co. 79/08/17 2pp.

--7908230517 LER 79-022/03L-0 on 790722 three of four wires loose & pulled out of main power connector on containment hydrogen recombiner A while disassembling for insp. Caused by insufficient set screw torque on wires in pins of connector.
WERLING, J. A. Duquesne Light Co. 79/08/17 1p.

7908280422 Discusses LER 79-026/01P-0 on 790820 reactor was manually tripped following trip of main feed pump 1B due to low net positive suction head. Manual trip caused 1A & 1B 4kV buses to trip on all reactor coolant pumps on underfrequency.
WERLING, J. A. Duquesne Light Co. 79/08/21 2pp.

7908290461 Forwards LERs 79-023/03L-0 & 79-025/03L-0.
WERLING, J. A. Duquesne Light Co. 79/08/23 2pp.

--7908290472 LER 79-023/03L-0 on 790724 during surveillance test, diesel generator 1 output breaker failed to close when control switch was actuated. Caused by sticking pinion on air motor. Pinion assembly cleaned, exercised & satisfactorily tested.
WERLING, J. A. Duquesne Light Co. 79/08/23 1p.

--7908290492 LER 79-025/03L-0 on 790624 during records review, biasing circuit for channel 2 temp change signal summator produced output signal setpoint approx 25 degrees too low. Caused by failure of instrument loop signal summator.
WERLING, J. A. Duquesne Light Co. 79/08/23 1p.

U. Congressional/Executive Correspondence

7908020232 Ack receipt of 790318 ltr to President Carter re NRC order to shut down five nuclear plants for seismic reasons. Review of piping sys is in progress. Forwards earthquake map for VA.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/06 3pp.

--7908020241 Forwards CJ Hemmer 790318 ltr for response. Ltr protests closing of five nuclear power plants for seismic reasons.
ZINN, P. K. President of US & Executive Offices 79/03/21 2pp.

DOCKET 50-335 ST. LUCIE PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

7908130185 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp.

7908010571 Submits revised responses 790403 submittal on fire protection program re emergency diesel generator automatic sprinkler sys, fire loading & fire-rated separations & cable spreading & switchgear rooms.
UHRIG, R. E. Florida Power & Light Co. 79/07/27 2pp.

7908310454 Forwards requested info re fire door evaluations & ventilation sys designs. Concurs w/providing 3-h fire-rated protection between diesel generator rooms by upgrading existing door assembly.
UHRIG, R. E. Florida Power & Light Co. 79/08/24 3pp.

I. Financial information

7908070375 Forwards Annual Financial Rept 1978, consolidated financial statements, June 1979 (unaudited) & cash flow projections.
UHRIG, R. E. Florida Power & Light Co. 79/07/31 1p.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors 79/05/25 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 52pp.

7908130309 Notifies all operating plants using C-E-designed reactors of generic review re TMI. Requests attendance at 790612 meeting in Bethesda, MD re info needed by NRC to complete review.
STOLZ, J. F. Light Water Reactors Branch 1 79/06/05 16pp.

7908030262 Forwards safety evaluation re adequacy of Tech Specs & procedures for surveillance requirements for ECCS throttle valves. No addl Tech Specs needed.
REID, R. W. Operating Reactors Branch 4 (Pre 790625) 79/06/19 2pp.

--7908030264 Safety evaluation supporting util contention that specific Tech Spec changes re surveillance of high pressure safety injection throttle valves are unnecessary.
* Office of Nuclear Reactor Regulation 79/06/19 1p.

7908030627 Responds to IE Bulletin 79-06B. Initiation & verification of auxiliary feedwater flow to steam generator is primary duty of operator during transient & accident situations.
UHRIG, R. E. Florida Power & Light Co. 79/06/22 1p.

7908140114 Advises that approval has been obtained for exempting Classes I, II & III amends from fees re upgraded STS bases program.
REID, R. W. Operating Reactors Branch 4 79/07/05 2pp.

7908140477 Finds proposed cycling test for check valves of valve test program unacceptable. Forwards NRC position on cycling test program. Requests position be reviewed & accepted or that util demonstrate that full stroking valves impractical.
REID, R. W. Operating Reactors Branch 4 79/07/16 3pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda,MD to discuss status of TMI-2 activities by NRC task force groups.Meeting agenda & list of attendees encl.
EISENHUT,D G. Division of Operating Reactors. 79/07/18. 58pp.

7908270086 Forwards request for addl info to be sent to licensee in order to complete review of 770725 submittal re technical assistance contract 10052 Response required within 45 days.
LAINAS,G. Plant Systems Branch. 79/07/18. 4pp.

7908070319 Requests cooperation in data-gathering activities to provide NRC Commissioners,public & media w/up-to-date operating status of power reactors.Info requests will not be made while plant is in shutdown mode.
O'REILLY,J P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908200094 Requests proposed amend to license to delete Tech Specs secondary water chemistry monitoring program & to incorporate requirements of encl model license condition. Requests submittal within 60 days.
REID,R W. Operating Reactors Branch 4. 79/07/23. 4pp.

7908200136 Requests addl info re degraded grid voltage within 45 days of ltr receipt.Info necessary to complete review.
REID,R W. Operating Reactors Branch 4. 79/07/23. 4pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events.Requests addl five copies of response for each unit,if more than one is owned & operated.
HAASS,W P. Quality Assurance Branch. 79/07/24. 1p.

7908200132 Responds to concerns re safe plant operation.PWR licensees are required to modify facilities per specific NRC requirements.Util actions add assurance for protection of public safety W/o encl.
GAMMILL,W.P. Assistant Director for Operating Reactor Projects. 79/07/25. 2pp.

7908030330 Submits Revision 3 to App C of QA topical rept 1-76A, providing alternative to requirement for insp of rigging & handling equipment.
UHRIG,R.E. Florida Power & Light Co. 79/07/30. 2pp.

7908070395 Forwards info re fabrication,insp & operating history of feedwater lines in further response to 790525 request.
UHRIG,R.E. Florida Power & Light Co. 79/07/31. 5pp.

7908100458 Forwards proprietary & non-proprietary versions of Amend 1 to CEN-114,"Review of Small Break Transients in C-E NSSS."
LIEBLER,G.E. C-E Operating Plants Owners Group. 79/08/03. 6pp.

--7908100465 Amend 1-NP to CEN-114-NP, "Review of Small Break Transient in C-E NSSS." CEN-144-P withheld (ref 10CFR2.790).
* Combustion Engineering, Inc. CEN-114-P. 79/07/31. 1110pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations,guidance documents & repts re emergency planning.
EISENHUT,D.G. Division of Operating Reactors. 79/08/03. 53pp.

7908100466 Forwards "Reactor Containment Bldg Integrated Leak Rate Test."
UHRIG,R.E. Florida Power & Light Co. 79/08/07. 1p.

--7908100470 "Reactor Containment Bldg Integrated Leak Rate Test," summary technical rept.
* Ebasco Services, Inc. (subs. of Enserch Corp.). 79/07/10. 79pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL,W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908170428 Forwards CEN-114-NP Amend 1,"Review of Small Break Transients in C-E Nuclear Steam Supply Sys." Proprietary version,CEN-114 P withheld (ref 10CFR2.790).
SCHERER,A.E. C-E Power Systems. 79/08/10. 1p.

7908210265 Responds to 790625 ltr re QA reg guides & ANSI stds. Topical QA rept FPLTQAR 1-76A,proposed Revision 3,satisfies requirements of 10CFR50 App B.Util will comply w/reg guides.
UHRIG,R.E. Florida Power & Light Co. 79/08/13. 2pp.

7908280562 Submits containment purge status rept.Notifies that info re purge issue has been requested from Henry Pratt Co,C-E & Ebasco.Henry Pratt Co proposal received & under review.
UHRIG,R.E. Florida Power & Light Co. 79/08/20. 1p.

7908280662 Forwards revised pages & deletion instructions for ETS of App B to DPR-67,per 790315 proposed amend.
UHRIG,R.E. Florida Power & Light Co. 79/08/23. 16pp.

7908300645 Notifies that GE Liebler 790803 ltr accompanying CEN-114-P, Amend 1-P,constituted response to RW Reid 790605 request for addl info re small break LOCA analysis.
UHRIG,R.E. Florida Power & Light Co. 79/08/24. 1p.

7908310408 Forwards "Cycle 3 Startup Physics Testing Summary."
UHRIG,R.E. Florida Power & Light Co. 79/08/24. 1p.

--7908310412 "Cycle 3 Startup Physics Testing Summary."
DRYDEN,M.S., TOMANTO,J.R., RYALL,R.K. Florida Power & Light Co. 79/08/17. 27pp.

G. Inspection reports, IE Bulletins & correspondence

7908270302 Provides update to 790329 response to IE Bulletin 78-04. NAMCO D2400x switches are used in facility,but are not installed on safety-related equipment inside containment for any purpose other than valve position indication.
UHRIG,R.E. Florida Power & Light Co. 79/06/28. 1p.

7908140710 Advises that C-E rept "Info Requested by IE Bulletin 78-12, Atypical Weld Matl in Reactor Pressure Vessel Welds," submitted to NRC under separate ltr,has generic coverage of weld matl & testing programs used by C-E.
UHRIG,R.E. Florida Power & Light Co. 79/06/29. 1p.

7908170541 Forwards IE Insp Rept 50-335/79-13 on 790518-25.No noncompliance noted.
LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/29. 2pp.

--7908170545 IE Insp Rept 50-335/79-13 on 790518-25.No noncompliance noted.Major areas inspected:verification,containment, integrated leakage rate testing,snubbers & previous inspector-identified findings.
WEBSTER,E.H., DYER,J.A. Region 2, Atlanta, Office of the Director. VERDERY,E.H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/27. 12pp.

7908090141 Responds to IE Bulletin 79-01 re environ qualification of Class IE equipment.Forwards detailed test documentation package.Solenoid valves & limit switches will be replaced.
UHRIG,R.E. Florida Power & Light Co. 79/07/02. 59pp.

7908270289 Notifies that evaluation of 790403 response to 790308 Insp Rept 50-335/79-01A notice of violation has been completed. Actions taken to complete item of noncompliance are incomplete.Requests response within 10 days.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/07/02. 1p.

7908300743 Responds to IE Bulletin 79-02 re concrete expansion anchor bolts.Submits info re calculation of anchor bolt loads,min safety factor & ability to withstand cyclic loads.
UHRIG,R.E. Florida Power & Light Co. 79/07/05. 4pp.

7908010029 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908090537 Responds to IE Bulletin 79-11.Circuit breakers are not in use at plant.
UHRIG,R.E. Florida Power & Light Co. 79/07/09. 1p.

7908030132 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010412 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908210386 Forwards response to Item 5 of IE Bulletin 79-13.Nozzle area insp program will be completed during shutdown scheduled for 791001.Discusses adequacy of operating & emergency procedures & feedwater leak detection.
UHRIG,R.E. Florida Power & Light Co. 79/07/17. 3pp.

7908030009 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908080043 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/19 2pp.

7908130112 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908200011 Ack receipt of 790711 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-335/79-14.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/25 1p.

--7908200013 Responds to NRC 790620 ltr re violation noted in IE Insp Rept 50-335/79-14. Corrective actions required valves are locked & prestart check list will be revised by 790801.
UHRIG, R.E. Florida Power & Light Co. 79/07/11 2pp.

--7908200015 Forwards IE Insp Rept 50-335/79-14 on 790605-08 & notice of violation.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20 2pp.

--7908200018 Notice of violation from insp on 790605-08.
* Region 2, Atlanta, Office of the Director. 79/06/19 1p.

--7908200020 IE Insp Rept 50-335/79-14 on 790605-08. Noncompliance noted: failure to follow operating procedures.
DYER, J.A. Region 2, Atlanta, Office of the Director.
VERDERY, E.H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/19 3pp.

7908060518 Forwards IE Bulletin 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/26 1p.

7908070754 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/26 2pp.

7908080715 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/26 2pp.

7908130033 Requests addl info to suppl previous response to IE Bulletin 79-06B. Info necessary for NRC to complete safety evaluation.
REID, R.W. Operating Reactors Branch 4. 79/07/26 3pp.

7908160232 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/27 2pp.

7908240100 Ack receipt of 790719 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/79-15.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/31 1p.

--7908240104 Responds to NRC 790625 ltr re violations noted in IE Insp Rept 50-335/79-15. Corrective actions amended renewal applications for OLs were submitted detailing deficiencies in individual requalification program attendance.
UHRIG, R.E. Florida Power & Light Co. 79/07/19 3pp.

--7908240109 Forwards IE Insp Rept 50-335/79-15 on 790529-30, notice of violation & notice of deviation.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25 2pp.

--7908240112 Notice of violation from insp on 790529-30.
* Region 2, Atlanta, Office of the Director. 79/06/22 1p.

--7908240120 Notice of deviation from insp on 790529 & 30.
* Region 2, Atlanta, Office of the Director. 79/06/22 1p.

--7908240124 IE Insp Rept 50-335/79-15 on 790529 & 30. Noncompliance noted: failure to follow procedures & failure to comply w/NRC documentation requirements.
JENKINS, H.D. Region 2, Atlanta, Office of the Director.
RUHLMAN, W.A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/22 6pp.

7908170049 Forwards response to IE Bulletin 79-14 re seismic analysis of as-built safety-related piping sys. Requests NRC concurrence for performance of Item 8 insps during next extended outage of each unit.
UHRIG, R.E. Florida Power & Light Co. 79/08/02 23pp.

7908240146 Forwards seismic analysis assessment for sys, including safety injection, auxiliary feedwater, feedwater, main stream, containment spray & component cooling water, per IE Bulletin 79-14. Addl matl to be forwarded by 790831.
UHRIG, R.E. Florida Power & Light Co. 79/08/06. 65pp.

7908160146 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/08/07 2pp.

7908170012 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/08/08 2pp.

7908290196 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/08/10 2pp.

R Periodic operating reports & related correspondence

7908230393 Forwards "Semiannual Radioactive Effluent Release Rept." for Jan-June 1979.
UHRIG, R.E. Florida Power & Light Co. 79/08/20 1p.

--7908230396 "Semiannual Radioactive Effluent Release Rept." for Jan-June 1979.
* Florida Power & Light Co. 79/07/30 30pp.

S Reportable occurrences, LERs & related correspondence

7908070499 Forwards LER 79-022/03L-0.
SCHMIDT, A.D. Florida Power & Light Co. 79/07/27 2pp.

--7908070505 LER 79-022/03L-0 on 790627 during periodic surveillance testing auxiliary feedwater pump failed to start. Cause could not be determined. Condensation in steam line may have delayed starting enough to mislead operator.
SCHOPPMAN, M.A. Florida Power & Light Co. 79/07/27 1p.

7908140713 Forwards LER 79-023/03L-0.
SCHMIDT, A.D. Florida Power & Light Co. 79/08/01 1p.

--7908140726 LER 79-023/03L-0 on 790702 control element assembly 33 would not withdraw due to presence of fullout position indication. Caused by faulty upper electric limit reed switch.
SCHOPPMAN, M.A. Florida Power & Light Co. 79/08/01 1p.

7908200344 Forwards LER 79-024/03L-0.
SCHMIDT, A.D. Florida Power & Light Co. 79/08/06 1p.

--7908200347 LER 79-024/03L-0 on 790705 while reducing power, control element assembly 62 slipped from 134 inches to 120 inches. Caused by faulty timer module. Timer module replaced & assembly 62 performed normally.
SCHOPPMAN, M.A. Florida Power & Light Co. 79/08/06 1p.

7908300708 Forwards LER 79-025/03L-0.
SCHMIDT, A.D. Florida Power & Light Co. 79/08/17 1p.

--7908300711 LER 79-025/03L-0 on 790720 variable high power trip setpoint in core protection calculator failed to track reactor power. Caused by power supply in core protection calculator failing due to filter capacitor failure.
SCHOPPMAN, M.A. Florida Power & Light Co. 79/08/17 1p.

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

7908130196 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch. 79/07/03 2pp.

7908080476 Forwards requested fire protection info re alternate means of safe shutdown independent of control room & switchgear room sys, which could be damaged by fire.
COUNSIL, W. G. Northeast Utilities. 79/07/31. 33pp.

7908240592 Submits chronological data re NRC policy concerning implementation of General Design Criterion 3 for fire protection. Urges maint of mod schedules set for Oct 1980.
EISENHUT, D. G. Division of Operating Reactors. 79/08/09. 2pp.

7908210401 Forwards amend approval fee in connection w/790323 submittal of safeguards contingency plans.
COUNSIL, W. G. ; FEE, W. F. Northeast Utilities. 79/08/15. 1p.

P Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908130359 Notifies all operating plants using C-E-designed reactors of generic review re TMI. Requests attendance at 790612 meeting in Bethesda, MD re info needed by NRC to complete review.
STOLZ, J. F. Light Water Reactors Branch 1. 79/06/05. 16pp.

7908030232 Summarizes status of five overpressure protection & three flooding reviews evaluated by LLL in response to Eisenhut 790604 memo.
SHEMANSKI, P. Plant Systems Branch. 79/06/12. 2pp.

7908020306 Comments on ACRS meeting re proposed increase in licensed power level. would not object to NRC plan to increase power level to 2,700 MW.
FRALEY, R. F. Office of the Executive Director for Operations. 79/06/18. 1p.

7908070456 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/06/22. 3pp.

7908140091 Advises that approval has been obtained for exempting Classes I, II & III amends from fees re upgraded STS bases program.
REID, R. W. Operating Reactors Branch 4. 79/07/05. 2pp.

7908100041 Notification of 790718 meeting w/util in Bethesda, MD to discuss App I of proposed Tech Specs.
REID, R. W. Operating Reactors Branch 4. 79/07/10. 3pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 58pp.

7908070245 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908170076 Forwards Amends 63 & 54 to Licenses DPR-21 & DPR-65, respectively, & notice of issuance & availability.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 3pp.

--7908170081 Amends 63 & 54 to Licenses DPR-21 & DPR-65, respectively, incorporating Tech Spec changes re organizational structure, retraining & replacement training program & plant operations review committee.
SIEMANN, D. L. Operating Reactors Branch 2. REID, R. W. Operating Reactors Branch 4. 79/07/19. 14pp.

--7908170086 Notice of issuance & availability of Amends 63 & 54 to Licenses DPR-21 & DPR-65, respectively.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/19. 2pp.

7908200102 Requests proposed amend to license to delete Tech Specs re secondary water chemistry monitoring program & to incorporate requirements of encl model license condition. Requests submittal within 60 days.
REID, R. W. Operating Reactors Branch 4. 79/07/23. 4pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908100458 Forwards proprietary & non-proprietary versions of Amend 1 to CEN-114, "Review of Small Break Transients in C-E NSSS." LIEBLER, G. E. C-E Operating Plants Owners Group. 79/08/03. 6pp.

--7908100465 Amend 1-NP to CEN-114-NP, "Review of Small Break Transient in C-E NSSS." CEN-144-P withheld (ref 10CFR 790).
* Combustion Engineering, Inc. CEN-114-P. 79/07/31. 1110pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908160428 Notification that, due to unscheduled cold shutdown required to repair cracked weld in nonisolable steam line, change in scheduled replacement of safety-related transformers is required.
COUNSIL, W. G. Northeast Utilities. 79/08/09. 2pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908140720 Proposes amend to DPR-65 to change Tech Specs, adding leak rate surveillance requirements to ECCS & containment sys to assure radiological consequences of engineered safety feature component leakage outside containment.
COUNSIL, W. G. Northeast Utilities. 79/08/10. 3pp.

--7908140724 Proposed revisions to Tech Specs to add leak rate surveillance requirements to ECCS & containment sys.
* Northeast Utilities. 79/08/31. 5pp.

7908170428 Forwards CEN-114-NP Amend 1, "Review of Small Break Transients in C-E Nuclear Steam Supply Sys." Proprietary version, CEN-114-P withheld (ref 10CFR2.790).
SCHERER, A. E. C-E Power Systems. 79/08/10. 1p.

7908200369 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, 790425-0501."
COUNSIL, W. G. Northeast Utilities. 79/08/10. 1p.

--7908200373 "Reactor Containment Bldg Integrated Leak Rate Test, 790425-0501."
* Northeast Utilities. 79/08/10. 42pp.

7908300349 Notifies of receipt of Classes I & II fee payment for 790702 application for review of proposed amends to Sections 3 & 4 of ETS. Payment should have been for Classes I & III fees. Balance of payment requested.
DIGGS, R. M. License Fee Management Branch. 79/08/13. 1p.

7908210579 Submits data in response to NRC 790718 request re economic basis for not replacing aerated radwaste evaporator.
COUNSIL, W. G. ; FEE, W. F. Northeast Utilities. 79/08/14. 2pp.

7908290597 Notifies of replacement of safety-related load center transformer w/fully qualified transformer.
COUNSIL, W. G. Northeast Utilities. 79/08/20. 1p.

7908300642 Responds to BH Grier 790625 request for info re postulated increased likelihood of feedwater line break. Forwards tables re feedwater sys piping & thermal fatigue analysis.
COUNSIL, W. G. ; SWITZER, D. C. Northeast Utilities. 79/08/22. 46pp.

7908310400 Submits addl info re feedwater piping sys regarding Emergency Procedure 2509, steam line rupture & onsite & offsite acceptance criteria.
COUNSIL, W. G. Northeast Utilities. 79/08/24. 2pp.

7908310502 Provides info to fulfill commitment in util 790822 ltr re feedwater piping sys. Discusses instrumentation package for monitoring equipment to be installed on steam generator 2.
COUNSIL, W. G. Northeast Utilities. 79/08/24. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908010293 Notifies of completion of review of util 790424 response to IE Bulletin 79-06B & addl info provided in 790524 & 31 ltrs. Forwards evaluation of response. Appropriate actions taken to meet requirements of bulletin.
REID,R.W. Operating Reactors Branch 4 (Pre 790625) 79/06/07 17pp.

7908140049 Forwards IE Insp Rept 50-336/79-12 on 790425-30. No noncompliance noted.
BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/22 2pp.

--7908140051 IE Insp Rept 50-336/79-12 on 790425-30. No noncompliance noted. Major areas inspected: containment integrated leak rate test & licensee action on previous insp findings.
SMITH,T.H., CAPHTON,D.L. Region 1, Philadelphia, Office of the Director 79/06/15 6pp.

7908200062 Forwards IE Insp Repts 50-245/79-12 & 50-336/79-15 on 790507-11. No noncompliance noted.
CARLSON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/25 2pp.

--7908200066 IE Insp Repts 50-245/79-12 & 50-336/79-15 on 790507-11. No noncompliance noted. Major areas inspected: activities related to inservice insp & IE Bulletins 79-02 & 03.
SANDERS,W.F. Region 1, Philadelphia, Office of the Director. TRIPP,L.E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/15 5pp.

7908200058 Forwards IE Insp Rept 50-336/79-10 on 790402-05 & 09-12. No noncompliance noted.
CARLSON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/26 2pp.

--7908200060 IE Insp Rept 50-336/79-10 on 790402-05 & 09-12. No noncompliance noted. Major areas inspected: inservice insp activities & nondestructive examinations of steam generator tubes & sleeved guide tubes in control element assemblies.
JERNIGAN,E.P., WALTON,G.A. Region 1, Philadelphia, Office of the Director. TRIPP,L.E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/14 7pp.

7908020076 Ack receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/79-02 & 50-336/79-01.
BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/07/06 1p.

--7908020083 Responds to NRC 790321 ltr re violations noted in IE Insp Repts 50-245/79-02 & 50-336/79-01. Corrective actions withheld (ref 10CFR2.790).
COUNSIL,W.G. Northeast Nuclear Energy Co. (Northeast Utilities) 79/04/11 2pp.

--7908020088 Forwards IE Insp Repts 50-245/79-02 & 50-336/79-01 on 790106-0209 & notice of violation.
BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/21 2pp.

--7908020094 Notice of violation from insp on 790106-0209. Details withheld (ref 10CFR2.790).
* Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/16 1p.

--7908020099 IE Insp Repts 50-245/79-02 & 50-336/79-01 on 790106-0209. Noncompliance noted: facility access control inadequacy. Portions withheld (ref 10CFR2.790).
MCCABE,E.C., SHEDLOSKY,J.T. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/16 22pp.

7908080677 Responds to IE Bulletin 79-11, Item 1. Westinghouse DB-50 & DB-75 circuit breakers not used in safety-related Class IE sys.
COUNSIL,W.G. Northeast Utilities 79/07/06 1p.

7908220613 Responds to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Generic program description & plant-specific program repts encl.
COUNSIL,W.G. Northeast Utilities 79/07/06 2pp.

--7908220618 "Generic Program Description," discussing finite element model, shear-tension interaction tests & cyclic load tests.
* Northeast Utilities 79/07/06 2pp.

--7908220622 "Plant-Specific Programs."
* Northeast Utilities 79/07/06 6pp.

7908200253 Advises that C-E generic rept responding to IE Bulletin 78-12 adequately represents reactor pressure vessel data for facility.
COUNSIL,W.G. Northeast Utilities 79/07/12 1p.

7908170365 Responds to IE Bulletin 79-13, Item 5a re adequacy of procedures to respond to feedwater line breaks. Review indicates procedures adequate to respond to accidents. Insp planned during Sept 1979 shutdown.
COUNSIL,W.G. Northeast Utilities 79/07/13 2pp.

7908010504 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/17 1p.

7908060383 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/18 1p.

7908030255 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/17 1p.

7908100241 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/26 1p.

7908100345 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/26 1p.

7908090310 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/07/30 1p.

7908280135 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/07 1p.

7908230346 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/08 1p.

7908270552 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/10 1p.

7908280297 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/13 1p.

7908310286 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/14 1p.

7908300146 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director 79/08/15 1p.

R. Periodic operating reports & related correspondence

7908160441 Forwards monthly operating rept for Jul 1979.
OPEKA,J.F. Northeast Utilities 79/08/10 1p.

--7908160444 Monthly operating rept for Jul 1979.
HOWLETT,G.H. Northeast Utilities 79/08/02 4pp.

S. Reportable occurrences, LERs & related correspondence

7908070711 Notification of tube leakage in degasifier, resulting in minor contamination of auxiliary steam condensate recovery tank & auxiliary steam surge tank. Leaking tubes plugged. Degasifier returned to svc on 790504.
OPEKA,J.F. Northeast Utilities 79/06/27 1p.

7908030299 Forwards LER 79-019/03L-0.
OPEKA, J. F. Northeast Utilities. 79/07/27. 1p.

--7908030300 LER 79-019/03L-0 on 790627 at completion of surveillance test, output breaker for 12U emergency diesel generator could not be opened remotely from control room. Caused by loose wire connection in trip coil.
* Northeast Utilities. 79/07/27. 1p.

7908060528 Forwards LER 79-020/03L-0.
OPEKA, J. F. Northeast Utilities. 79/08/01. 1p.

--7908060533 LER 79-020/03L-0 on 790712 during operation, computer malfunction resulted in inoperability of incore detection monitoring sys. Caused by defective circuit card in computer memory. Card replaced.
SCOPELITIS, C. P. Northeast Utilities. 79/08/01. 1p.

7908160455 Forwards LER 79-021/03L-0.
OPEKA, J. F. Northeast Nuclear Energy Co. (Northeast Utilities). 79/08/10. 1p.

--7908160461 LER 79-021/03L-0 on 790713 reactor protection sys Channel A reactor coolant flow low trip was declared inoperable due to high signal on instrument loop. Cause not known. Signals will be observed for abnormalities regularly.
BATES, R. W. Northeast Nuclear Energy Co. (Northeast Utilities). 79/08/10. 1p.

7908170410 Forwards LER 79-021/03L-0.
OPEKA, J. F. Northeast Utilities. 79/08/10. 1p.

--7908170415 LER 79-021/03L-0 on 790713 reactor protection sys channel A reactor coolant flow low trip declared inoperable due to high signal on instrument loop PD121A. Cause unknown. Signals being observed.
BATES, R. W. Northeast Utilities. 79/08/10. 1p.

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7908030194 Approves 790406 proposed amend to security plan re separation of Units 1 & 2 from const area of Unit 3.
PARR, O. D. Light Water Reactors Branch 3. 79/06/29. 3pp.

7908130218 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908170477 Discusses items mentioned in 790611 ltr re fire protection safety evaluation. Issues concern installation of sprinkler sys over component cooling pumps & addition of 3-h damper between control room & turbine bldg.
PARR, O. D. Light Water Reactors Branch 3. 79/07/09. 4pp.

7908210003 Forwards security personnel training & qualification program Plan withheld (ref 10CFR2.790).
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/17. 1p.

Q. Adjudicatory correspondence

7908140045 Responds to 790419 interrogatories re turbine missile issue. Copies of documents identified per request will be directed to E Weiss.
SWANSON, D. T. Branch 1. 79/05/22. 4pp.

7908010634 Supports adoption of hearing schedule proposed in Potomac Alliance 790515 motion to reschedule hearing.
GOLDBERG, S. C. Branch 2. 79/05/29. 1p.

7908010684 Requests to make limited appearance statement.
WILLIAMSON, M. Affiliation Unknown. 79/06/08. 1p.

7908300754 Opposition to util 790618 motion for interim relief. ASLB lacks authority to grant relief. NRC regulations demand denial. Exemption to regulations should not be granted. Certificate of Svc encl.
DOUGHERTY, J. B. Potomac Alliance. 79/06/09. 16pp.

7908020506 Requests to make limited appearance statement at licensing prehearing.
JEFFRIES, S. Affiliation Unknown. 79/06/11. 1p.

7908160065 Waives provisions of 10CFR2.720(h)(2)(ii) governing discovery re written interrogatories served by Citizens Energy Forum & Potomac Alliance on NRC, regarding proposed amend to License NPF-4 to permit storage pool mod.
GOLDBERG, S. C. Branch 2. 79/06/18. 1p.

7908020562 Responds to Potomac Alliance 790601 interrogatories & document requests. Names & areas of expertise of proposed witnesses can be found in util 790620 response to Citizens Energy Forum interrogatories & document requests.
MCKAY, H. S., NEIL, R. M., FISHBACK, D. R. Virginia Electric & Power Co. 79/06/20. 69pp.

--7908020567 Responds to Citizens Energy Forum 790601 interrogatories & document requests. Drawings of new spent fuel pool racks are proprietary. Submits info re thermal effects, radioactive emissions & corrosion.
MCKAY, H. S., NEIL, R. M., EAST, J. Virginia Electric & Power Co. 79/06/20. 38pp.

--7908020570 VEPCO objections to 790601 interrogatories from Potomac Alliance & Citizens Energy Forum. Potomac Alliance format & Questions 21 & 44-47 are too broad. Citizens Energy Forum Question 5-1 requests proprietary drawings.
RINACA, J. M. Hunton & Williams. 79/06/20. 6pp.

7908010637 Forwards V Stello 790625 ltr to J Allen & 790625 director decision per 10CFR2.206 request for enforcement action. No need to offer decision as exhibit in pumphouse settlement phase of proceeding.
SWANSON, D. T. Branch 1. 79/06/27. 1p.

7908160068 Forwards affidavits for JS Wermiel testimony which accompanied NRC supplemental response to util motion for summary disposition re proposed amend to License NPF-4.
GOLDBERG, S. C. Branch 2. 79/06/28. 5pp.

7908090309 Orders extension until 790723 for Potomac Alliance to respond to util motion for summary disposition. Prehearing conference & hearing will begin 790814. Addl time granted to respond to util motion for interim relief.
DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/06/29. 2pp.

7908300122 Response to intervenor Citizens Energy Forum 790531 & Potomac Alliance 790601 interrogatories re accident portions of Contention 2, Contention 3 & contention on svc water cooling sys. Certificate of Svc.
GOLDBERG, S. C. Branch 2. 79/06/29. 21pp.

7908080040 Notifies that proposed protective order re proprietary Westinghouse data used in Shaffer fault tree analysis will be filed as soon as possible.
CHRISTMAN, J. N. Hunton & Williams. 79/07/03. 2pp.

7908150252 Confirms 790628 telcon re new info about util motion for summary disposition & prefiled written testimony re tornado missiles. Large missiles could not strike fuel elements.
CHRISTMAN, J. N. Hunton & Williams. 79/07/03. 4pp.

7908080104 Response submitted by util to intervenors Potomac Alliance & Citizens Energy Forum, Inc 790615 motion to amend petition to intervene. Requests denial of seismicity contention & mod of issues re spent fuel pool.
CHRISTMAN, J. N. Virginia Electric & Power Co. 79/07/05. 9pp.

--7908080122 Summarizes DC Circuit Court 790523 opinion in State of MN vs NRC. Recommends prompt issuance of final S-3 rule. New Board should conduct generic proceeding re waste disposal. Certificate of Svc encl.
EILPERIN, S. F. Office of the General Counsel. 79/06/11. 15pp.

7908300068 Opposes joint intervenors Potomac Alliance & Citizens Energy Forum 790615 motion to amend petition to intervene re seismicity contentions & extension of time. Discusses 10CFR2.714. Certificate of Svc encl.
GOLDBERG, S. C. Branch 2. 79/07/05. 6pp.

7908300058 Supports util 790618 motion for interim relief re installation of spent fuel storage racks. Interim use of racks is safe & does not affect contentions at issue. Certificate of Svc encl.
GOLDBERG, S. C. Branch 2. 79/07/06. 4pp.

7908300110 Notice of special appearance of Westinghouse to submit proprietary info to ASLAB & appearance of JR Kendrick & TM Daugherty on behalf of corp. Forwards draft protective order, affidavit of DH Shaffer & Certificate of Svc.
KENDRICK, J. R. Eckert, Seamans, Cherin & Mellott. DAUGHERTY, T. M. Westinghouse Electric Corp. 79/07/06. 11pp.

7908080131 Memo & order ALAB-555 re damage to safety-related structures from turbines. Grants Westinghouse request for protective order & declines claim of privilege.
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 79/07/13. 12pp.

7908170563 Forwards 790717 ltr from VEPCO counsel to ASLAB. Requests ltr be filed w/documents.
CHRISTMAN, J. N. Hunton & Williams. 79/07/17. 1p.

--7908170569 Forwards DH Shaffer 790713 statement on flaw coalescence, requested at 790620 public hearing.
CHRISTMAN, J. N. Hunton & Williams. 79/07/17. 3pp.

H. General correspondence

7908010515 Informs NRC that info required for review of corporate capabilities will be submitted by 790817.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/30. 1p.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908090546 Forwards Amend 67 to FSAR, Affidavit of svc encl.
PROFFITT, W. L. Virginia Electric & Power Co. 79/07/31. 4pp.

--7908090550 Amend 67 to FSAR W/25 oversized drawings.
* Virginia Electric & Power Co. 79/07/31. 23pp.

P. Operating license stage documents & correspondence

7908090569 Requests amend 4 to License NPF-4, consisting of proposed Tech Spec Change 19, involving grammatical & typographical corrections & changes resulting from inconsistencies created between Tech Specs of two units.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/06. 64pp.

7908030306 Lists corrective actions proposed by util re potential electrical problems noted in EL Jordan 790604 memo.
LAINAS, G. Plant Systems Branch. 79/06/21. 2pp.

7908080609 Informs of inadvertent reactor scram & safety injection which occurred due to operator error at other PWR facility. Requests reviews of events as related to facility mgt policies & procedures & safety sys surveillance procedures.
EISENHUT, D. G. Division of Operating Reactors. 79/06/26. 4pp.

7908160501 Forwards Amend 12 to License NPF-4, safety evaluation & notice of issuance & availability & testimony.
PARR, O. D. Light Water Reactors Branch 3. 79/06/28. 4pp.

--7908160529 Forwards revised safety evaluation correcting Tech Specs in support of Amend 12 to License NPF-4.
SWANSON, D. T. Branch 1. 79/01/09. 1p.

--7908160531 NRC testimony by L Heller, R Kiessel, J Lenahan, J Wermiel & A Dromerick re pumphouse settlement at facility.
* Atomic Safety and Licensing Appeal Panel. 79/04/27. 68pp.

7908090507 Advises that util has obtained approval for exempting Classes I-III amends from fees re upgraded STS bases program.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 3pp.

7908150182 Notifies that environ review responsibility is transferred to Operating Reactors Branch 1.
MULLER, D. R. Division of Site Safety & Environmental Analysis. 79/07/13. 1p.

7908070322 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908010354 Forwards Class III fees for NRC review of safeguards contingency plans.
BAUM, E. A. Virginia Electric & Power Co. 79/07/24. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908300057 Forwards NUREG-0472, "Revision 2 of Draft Radiological Effluent Tech Specs," W/o encl.
VARGA, S. A. Assistant Director for Light Water Reactors. 79/07/27. 3pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch. 79/07/30. 64pp.

7908030348 Requests that "Rept on Small Break Accident for Westinghouse NSSS Sys," submitted in response to NRC 790604 request, be included in dockets.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/31. 1p.

7908060369 Requests approval of brief deferral of Tech Specs surveillance requirements to allow addl testing of one train & I/N channels.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/31. 1p.

7908300277 Discusses 781109 proposed Tech Spec changes re secondary water chemistry control. Requests revised submittal that will include secondary water chemistry program. Forwards model license condition.
PARR, O. D. Light Water Reactors Branch 3. 79/07/31. 5pp.

7908270119 Advises of forthcoming visit to util headquarters on 790821 to review flux maps as re flux tilt LERs.
DROMERICK, A. Light Water Reactors Branch 3. 79/08/01. 3pp.

7908080683 Responds to FOIA request for documents re North Anna nuclear power plants.
FELTON, J. M. Division of Rules and Records. 79/08/03. 2pp.

--7908080692 Responds to 770401 request for info re investigations of allegations of withholding steam generator info. Technical staff responses encl.
SHAPAR, H. K. Office of the Executive Legal Director. 77/05/05. 12pp.

--7908080705 Responds to Ellis request for addl info re stress in svc water line resulting from pumphouse settlement. Redesign of pipe sys may be necessary.
BERATON, L. L. Site Safety Standards Branch. 75/07/29. 3pp.

--7908080713 Forwards rept re insp. Stresses exceeding code allowables introduced into piping sys. Recommendation that civil penalty be imposed upon licensee for failure to report const defect, is being revised.
UPRIGHT, C. M. Office of Inspection & Enforcement, Office of the Director. 75/10/09. 8pp.

--7908080718 Forwards draft rept for action re insp performed. Recommends that civil penalty be levied against licensee due to failure to rept const deficiency in seismic structure & sys. No engineering evaluation conducted prior to insp.
MOSELEY, N. C. Region 2, Atlanta, Office of the Director. 75/03/12. 9pp.

--7908080711 Discusses Investigation Repts 50-338/77-03 & 50-339/77-02. Noncompliance noted: failure to rept DC-81 matl. Final determination of requirement for reportability depends on legal significance of deficiency.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 77/03/21. 2pp.

--7908080720 Discusses evaluation of Investigation Repts 50-338/77-3 & 50-339/77-2. Recommends that enforcement action per 10CFR50.55(e) be instituted against util for failure to rept info contained in DC-81 in timely manner.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 77/03/21. 2pp.

--7908080726 Commonwealth of VA radiological emergency response plan.
* Virginia, State of. 76/04/30. 85pp.

--7908080733 Louisa County, VA radiological emergency response plan.
FRANCIS, S. L. Louisa County, VA. 76/05/31. 78pp.

7908290329 Forwards Amend 13 to License NPF-4, safety evaluation & notice of issuance & availability.
PARR, O. D. Light Water Reactors Branch 3. 79/08/03. 3pp.

--7908290343 Amend 13 to License NPF-4, consisting of one-time extension to surveillance frequency for response time testing, safety injection & containment depressurization actuation testing.
PARR, O. D. Light Water Reactors Branch 3. 79/08/03. 2pp.

DOCKETED ITEMS

--7908290358 Safety evaluation supporting Amend 13 to License NPF-4.
* Office of Nuclear Reactor Regulation. 79/08/03. 3pp.

--7908290373 Notice of issuance & availability of Amend 13 to License NPF-4.
PARR, O. D. Light Water Reactors Branch 3. 79/08/03. 2pp.

7908090571 Proposed Tech Spec Change Request 19 to amend License NPF-4, consisting of grammatical & typographical corrections & changes resulting from inconsistencies created between Tech Specs of both units.
* Virginia Electric & Power Co. 79/08/06. 61pp.

7908150509 Responds to FOIA request for documents relating to alleged withholding of info re nuclear plants operated by VEPCO. Documents requested encl.
FELTON, J. M. Division of Rules and Records. 79/08/06. 1p.

7908160445 Ack receipt of 790731 ltr re secondary water chemistry control. Agrees that control of chemistry requires initiation of license condition to implement & monitor control program. Description of program to be sent by 790901.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/14. 1p.

7908160467 Forwards "GE Vertical Induction Motors Inside Containment Recirculation Spray Pumps." Mods made will not affect previously demonstrated qualification of motors.
BROWN, S. C. Virginia Electric & Power Co. 79/08/14. 1p.

--7908160472 "GE Vertical Induction Motors Inside Containment Recirculation Spray Pumps."
SHEETS, M. W. General Electric Co., Nuclear Energy Products Div. 491HA689. 79/07/23. 41pp.

7908210309 Submits results of safety evaluation supporting plan to continue operation of Cycle 1 in power coastdown mode for approx 26 effective full power days. No change to Tech Specs anticipated.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/16. 2pp.

7908210410 Submits results of analyses verifying capability & capacity of electric power sys, as modified, to start & operate required safety loads within rated voltages. Oversized drawings encl.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/16. 23pp.

7908240506 Ack receipt of 790626 ltr re multiple equipment failures & unnecessary challenges to reactor trip & safeguards sys. Review of Unit 1 records indicates no such events occurred. Will revise procedure to assure sys safety.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/21. 1p.

7908270462 Responds to TMI-2 Lessons Learned Task Force short-term recommendations as applicable to facility.
PROFFITT, W. L. Virginia Electric & Power Co. 79/08/24. 45pp.

3. Inspection reports, IE Bulletins & ... espondence

7908020210 Forwards IE Insp Repts 50-338/79-22, 50-339/79-30, 50-404/79-03 & 50-405/79-03 on 790423-25. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/16. 2pp.

--7908020217 IE Insp Repts 50-33[illegible] 79-22, 50-339/79-30, 50-404/79-03 & 50-405/79-03 on 790423-25. No noncompliance noted. Major areas inspected: structural concrete QA/QC controls, svc water pumphouse settlement data, work performance & records.
LENAHAN, J. J., BRYANT, J. C. Region 2, Atlanta, Reactor Con... ...ion & Engineering Support Branch. 79/05/11. 7pp.

7908280094 Forwards IE Insp Rept 50-338/79-26 on 790521-25. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/14. 2pp.

--7908290123 IE Insp Rept 50-338/79-26 on 790521-25. No noncompliance noted. Major areas inspected: controlling procedures for effluent releases; gaseous radioactive effluent releases & liquid radioactive effluent control.
ZAVADOSKI, R. W. Region 2, Atlanta, Office of the Director. JENKINS, G. R. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/08. 4pp.

7908240343 Forwards IE Insp Rept 50-338/79-27 on 790607-08. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 2pp.

--7908240353 IE Insp Rept 50-338/79-27 on 790607-08. No noncompliance noted. Major areas inspected: training & retraining programs, operator requalification training & response to IE Bulletin 79-06A.
TAYLOR, P. A., FORD, E. J. Region 2, Atlanta, Office of the Director. RUHLMAN, W. A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 5pp.

7908070178 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908060172 Follows up 790426 ltr in response to IE Bulletin 79-06A. Primary operator action required to prevent formation of voids; continues to assure proper initiation of engineered safety equipment.
STALLINGS, C. M. Virginia Electric & Power Co. 79/06/29. 21pp.

7908080109 Responds to IE Bulletin 79-01. Forwards table re environ qualification of Class 1E electrical equipment. Two potential qualification problems identified in chiller equipment room & in safeguards bldg.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/02. 36pp.

7908080678 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/02. 2pp.

7908010035 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908090427 Responds to IE Bulletin 79-02. Procedures implemented at plant ensure that anchor bolts have been designed & installed in manner which satisfies requirements. No addl insp or analytical work is required.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/06. 3pp.

7908030144 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908070743 Responds to IE Bulletin 79-11 re use of Westinghouse DB-50 & DB-75 circuit breakers. Notifies that specified circuit breakers are in use, but w/o overcurrent trip feature.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/13. 2pp.

7908080151 Responds to IE Bulletin 79-13, Item 5, re cracking in feedwater sys piping. Discusses schedule for insp of feedwater piping welds & procedures to identify & respond to feedwater line break accident.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/13. 4pp.

7908010418 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908060362 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908020036 Forwards G Lainas 790709 memo to D Eisenhut re effect of high environ temp steam generator water level instrumentation. IE action planned to assure Westinghouse licensees take appropriate action.
LAINAS, G. Plant Systems Branch. 79/07/18. 1p.

--7908020038 Advises that Westinghouse informed all customers re possible inaccuracies in steam generator water level indication & subsequent corrections that should be applied. Recommends that item be subj of Board notification.
LAINAS, G. Plant Systems Branch. 79/07/09. 2pp.

--7908020044 PNO-79-185: nonconservative analysis results of high energy line break inside containment discovered per Westinghouse 790621 notification. Info being evaluated. Supplemental orders will be generated to customers.
KLINGLER, G. R., NOLAN, F., BRYAN, S. Office of Inspection & Enforcement, Office of the Director. 79/06/22. 1p.

7908030042 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080063 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/18. 2pp.

7908130281 Notifies that IE Bulletin 79-14 is revised to limit scope of required work. Forwards replacement page.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/18. 2pp.

7908060524 Forwards IE Bulletin 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/26. 1p.

7908070761 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/26. 2pp.

7908080728 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/26. 2pp.

7908220403 Ack receipt of 790703 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-25 & 50-339/79-34.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/26. 1p.

--7908220406 Responds to NRC 790608 ltr re violations noted in IE Insp Repts 50-338/79-25 & 50-339/79-34. Corrective actions: test engineers instructed to insure proper use of procedure deviations & documentation of problems.
STALLINGS, C M. Virginia Electric & Power Co. 79/07/03. 3pp.

--7908220410 Forwards IE Insp Repts 50-338/79-25 & 50-339/79-34 on 790507-11 & notice of violation.
LEWIS, R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/08. 2pp.

--7908220412 Notice of violation from insp on 790507-11.
* Region 2, Atlanta, Office of the Director. 79/06/08. 1p.

--7908220418 IE Insp Repts 50-338/79-25 & 50-339/79-34 on 790507-11. Noncompliance noted: failure to meet acceptance criteria & failure to document review or approve change to procedure.
WEBSTER, E H ; WAGNER, R M. Region 2, Atlanta, Office of the Director. KELLOGG, P J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/08. 8pp.

7908160276 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/07/27. 2pp.

7908220655 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/08/07. 2pp.

7908170016 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/08/06. 2pp.

7908290225 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/08/10. 2pp.

R Periodic operating reports & related correspondence

7908130352 Forwards monthly operating rept for Jul 1979.
STALLINGS, C M. Virginia Electric & Power Co. 79/08/08. 1p.

--7908130355 Monthly operating rept for Jul 1979.
MADISON, W R. Virginia Electric & Power Co. 79/08/01. 5pp.

S Reportable occurrences, LERs & related correspondence

7908030595 Notifies of potential significant deficiency. During insp of steam valve house piping sys, improper input criteria found for bldg displacement. Correct criteria used & mod of affected supports initiated.
STALLINGS, C M. Virginia Electric & Power Co. 79/04/27. 2pp.

7908030345 RO 79-089/01T discovered possibility of failure of process cards, causing adverse effects on associated loop actions. Process card failure analysis performed.
* Virginia Electric & Power Co. 79/07/23. 1p.

7908030367 RO 79-091/01T-0 on 790725 followup rept on discovery that component W-104 dual peripheral driver in 7,300 series signal comparator cartds could fail, causing associated bistable to fail in unsafe mode.
* Virginia Electric & Power Co. 79/07/26. 1p.

7908070494 Forwards LER 79-088/03L-0.
STALLINGS, C M. Virginia Electric & Power Co. 79/08/03. 1p.

--7908070497 LER 79-088/03L-0 on 790702, during performance of 1-PT-82A, emergency diesel generator 1H tripped. Generator was restarted w/no problems. Cause not determined.
CARTWRIGHT, W R. Virginia Electric & Power Co. 79/08/01. 2pp.

7908070577 Forwards LER 79-089/01T-0.
STALLINGS, C M. Virginia Electric & Power Co. 79/08/0[illegible]. 1p.

--7908070583 LER 79-089/01T-0 on 790720, discovered possibility that process cards, types NMB, NVP & NCB, could fail, causing adverse effects on associated loop actions. Caused by faulty component layout on cards. Analysis performed.
CARTWRIGHT, W R. Virginia Electric & Power Co. 79/08/02. 2pp.

7908280559 Submits info re deficiency reported 790731. Component W-104 on 7300 series signal comparator cards sometimes fails, preventing bistable from performing function. Components will be replaced.
STALLINGS, C M. Virginia Electric & Power Co. 79/08/06. 2pp.

7908100305 Forwards LER 79-087/03L-0.
STALLINGS, C M. Virginia Electric & Power Co. 79/08/07. 1p.

--7908100312 LER 79-087/03L-0 on 790715, contrary to Tech Specs, axial flux difference deviated greater than 5% for more than 3-m. Caused by power transient due to maint & testing. Dilution & power escalation undertaken by operator.
CARTWRIGHT, W R. Virginia Electric & Power Co. 79/08/07. 2pp.

7908130454 Forwards LER 79-091/01T-0.
STALLINGS, C M. Virginia Electric & Power Co. 79/08/08. 1p.

--7908130459 LER 79-091/01T-0 on 790724 discovered possibility of failure of 7,300 series signal comparator cards, causing possible bistable failure. Caused by component W-104 on NAL card ending to fail in shorted condition.
CARTWRIGHT, W R. Virginia Electric & Power Co. 79/08/06. 2pp.

7908160429 Forwards LER 79-090/99X-0 & Rept 44T-1844, "Tornado Missile Risk Analysis of Spent Fuel Pool," dtd Jul 1979.
STALLINGS, C M. Virginia Electric & Power Co. 79/08/13. 1p.

--7908160433 LER 79-090/99X-0 on 790629, recent data indicates nonconservatism in rept "Tornado Considerations for Nuclear Power Plants" ref in FSAR. Paper did not consider that damage caused by Lubbock, TX tornado was possible.
CARTWRIGHT, W R. Virginia Electric & Power Co. 79/08/10. 1p.

--7908160435 "Tornado Missile Risk Analysis of Spent Fuel Pool."
TWISDALE, L A ; DUNN, W L ; BILBRO, G L. Research Triangle Institute. 44T-1844. 79/07/31. 37pp.

7908240422 Forwards LER 79-085/03L-0.
STALLINGS, C M. Virginia Electric & Power Co. 79/08/21. 1p.

--7908240427 LER 79-085/03L-0 on 790715, following power reduction caused by secondary plant problems, quadrant power tilt alarm was observed. Possibly caused by dropped rodlets. Tilts under review.
CARTWRIGHT, W R. Virginia Electric & Power Co. 79/08/20. 3pp.

7908240485 Forwards LERs 79-093/03L-0 & 79-095/03L-0.
STALLINGS, C M. Virginia Electric & Power Co. 79/08/21. 1p.

--7908240493 LER 79-093/03L-0 on 790726, during Mode 1 operations, fire door B54-11 between Unit 2 emergency switchgear room & turbine bldg found nonfunctional. Caused by temporary cooling water hoses preventing closure. Hoses removed.
CARTWRIGHT, W R. Virginia Electric & Power Co. 79/08/17. 2pp.

--7908240498 LER 79-095/03L-0 on 790727, during rapid power reduction & subsequent increase in power, oxide flux difference deviated more than 5% from target for 104 minutes. Caused by power reduction. Power & control rods manipulated by operator.
CARTWRIGHT, W R. Virginia Electric & Power Co. 79/08/17. 2pp.

7908280649 Forwards LER 79-097/03L-0.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/23. 2pp.

--7908280653 LER 79-097/03L-0 on 790803 greater than 12 step disagreement was noted between individual & group indication for rod D-10. Caused by instrument drift. Immediate calibr & functional checks were performed.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/08/21. 1p.

7908280750 Forwards LER 79-094/03L-0.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/24. 1p.

--7908280759 LER 79-094/03L-0 on 790726 ventilation stack particulate radiation monitor RM-VG112 failed & was inoperable for 10-h. Caused by faulty power supply. New power supply ordered. Temporary power supply now in use.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/08/24. 2pp.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908030600 Responds to 790522 ltr re OL moratorium & shutdown due to pipe stress calculations. Primary consideration is given to public health & safety. Addl actual stress data is necessary to support restart of plant.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/13. 2pp.

--7908030607 Comments that recent moratorium will necessitate plant shutdown for summer months. Health & safety of public will not be jeopardized by operation of plant. Moratorium on OL places undue burden on util & ratepayers.
RAGONE, S. Virginia Electric & Power Co. 79/05/22. 2pp.

7908030306 Lists corrective actions proposed by util re potential electrical problems noted in EL Jordan 790604 memo.
LAINAS, G. Plant Systems Branch. 79/06/21. 2pp.

7908080609 Informs of inadvertent reactor scram & safety injection which occurred due to operator error at other PWR facility. Requests reviews of events as related to facility mgt policies & procedures & safety sys surveillance procedures.
EISENHUT, D. G. Division of Operating Reactors. 79/06/26. 4pp.

7908160501 Forwards Amend 12 to License NPF-4, safety evaluation & notice of issuance & availability & testimony.
PARR, O. D. Light Water Reactors Branch 3. 79/06/28. 4pp.

--7908160529 Forwards revised safety evaluation correcting Tech Specs in support of Amend 12 to License NPF-4.
SWANSON, D. T. Branch 1. 79/01/09. 1p.

--7908160531 NRC testimony by L. Heller, R. Kiessel, J. Lenahan, J. Pormiel & A. Dromerick re pumphouse settlement at facility.
* Atomic Safety and Licensing Appeal Panel. 79/04/27. 68pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 58pp.

7908010354 Forwards Class III fees for review of safeguards contingency plans. W/o encl.
BAUM, E. A. Virginia Electric & Power Co. 79/07/24. 1p.

7908300057 Forwards NUREG-0472, "Revision 2 of Draft Radiological Effluent Tech Specs." W/o encl.
VARGA, S. A. Assistant Director for Light Water Reactors. 79/07/27. 3pp.

7908170127 Forwards requests for addl info for review of OL application. Response required by 790810 to maintain review schedule.
PARR, O. D. Light Water Reactors Branch 3. 79/07/30. 4pp.

7908030348 Requests that "Rept on Small Break Accident for Westinghouse NSSS Sys," submitted in response to NRC 790604 request, be included in dockets.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/31. 1p.

7908220061 Requests util subcit proposed secondary water chemistry program to be incorporated in new license condition. Current STS of all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
PARR, O. D. Light Water Reactors Branch 3. 79/07/31. 5pp.

7908080683 Responds to FOIA request for documents re North Anna nuclear power plants.
FELTON, J. M. Division of Rules and Records. 79/08/03. 2pp.

--7908080692 Responds to 770401 request for info re investigations of allegations of withholding steam generator info. Technical staff responses encl.
SHAPAR, H. K. Office of the Executive Legal Director. 77/05/05. 12pp.

--7908080705 Responds to Ellis request for addl info re stress in svc water line resulting from pumphouse settlement. Redesign of pipe sys may be necessary.
BERATON, L. L. Site Safety Standards Branch. 75/07/29. 3pp.

--7908080713 Forwards rept re insp. Stresses exceeding code allowables introduced into piping sys. Recommendation that civil penalty be imposed upon licensee, for failure to report const defect, is being revised.
UPRIGHT, C. M. Office of Inspection & Enforcement, Office of the Director. 75/10/09. 8pp.

--7908080718 Forwards draft rept for action re insp performed. Recommends that civil penalty be levied against licensee due to failure to rept const deficiency in seismic structure & sys. No engineering evaluation conducted prior to insp.
MOSELEY, N. C. Region 2, Atlanta, Office of the Director. 75/03/12. 9pp.

--7908080711 Discusses Investigation Repts 50-338/77-03 & 50-339/77-02. Noncompliance noted: failure to rept DC-81 matl. Final determination of requirement for reportability depends on legal significance of deficiency.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 77/03/21. 2pp.

--7908080720 Discusses evaluation of Investigation Repts 50-338/77-3 & 50-339/77-2. Recommends that enforcement action per 10CFR50.55(e) be instituted against util for failure to rept info contained in DC-81 in timely manner.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 77/03/21. 2pp.

--7908080726 Commonwealth of VA radiological emergency response plan.
* Virginia, State of. 76/04/30. 85pp.

--7908080733 Louisa County, VA radiological emergency response plan.
FRANCIS, S. L. Louisa County, VA. 76/05/31. 78pp.

7908200025 Submits staff position on electrical protection of containment penetrations. Design did not meet requirements of single failure criterion of IEEE Std 279-1971. Requires mods schedule within seven days.
PARR, O. D. Light Water Reactors Branch 3. 79/08/03. 4pp.

7908150309 Responds to FOIA request for documents relating to alleged withholding of info re nuclear plants operated by VEPCO. Documents requested encl.
FELTON, J. M. Division of Rules and Records. 79/08/06. 1p.

7908140450 Forwards responses to requested info re reactor fuel.
THOMAS, W. N. Virginia Electric & Power Co. 79/08/10. 4pp.

7908150578 Ack receipt of 790803 ltr re electrical protection of containment penetrations. Review under way; w/final info to be submitted 790904.
BROWN, S. C. Virginia Electric & Power Co. 79/08/13. 1p.

7908160445 Ack receipt of 790731 ltr re secondary water chemistry control. Agrees that control of chemistry requires initiation of license condition to implement & monitor control program. Description of program to be sent by 790901.
STALLINGS, C. M. Virginia Electric & Power Co. 79/08/14. 1p.

7908160467 Forwards "GE Vertical Induction Motors Inside Containment Recirculation Spray Pumps." Mods made will not affect previously demonstrated qualification of motors.
BROWN, S. C. Virginia Electric & Power Co. 79/08/14. 1p.

--7908160472 "GE Vertical Induction Motors Inside Containment Recirculation Spray Pumps."
SHEETS, M.W. General Electric Co., Nuclear Energy Products Div. 49IHA689. 79/07/23. 41pp.

7908210309 Submits results of safety evaluation supporting plan to continue operation of Cycle 1 in power coastdown mode for approx 26 effective full power days. No change to Tech Specs anticipated.
STALLINGS, C.M. Virginia Electric & Power Co. 79/08/16. 2pp.

7908240506 Ack receipt of 790626 ltr re multiple equipment failures & unnecessary challenges to reactor trip & safeguards sys. Review of Unit 1 records indicates no such events occurred. Will revise procedure to assure sys safety.
STALLINGS, C.M. Virginia Electric & Power Co. 79/08/21. 1p.

7908270462 Responds to TMI-2 Lessons Learned Task Force short-term recommendations as applicable to facility.
PROFFITT, W.L. Virginia Electric & Power Co. 79/08/24. 45pp.

F. Security, medical, emergency & fire protection plans

7908030194 Approves 790406 proposed amend to security plan re separation of Units 1 & 2 from const area of Unit 3.
PARR, O.D. Light Water Reactors Branch 3. 79/06/29. 3pp.

7908130218 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R.M. License Fee Management Branch. 79/07/03. 2pp.

7908170477 Discusses items mentioned in 790611 ltr re fire protection safety evaluation. Issues concern installation of sprinkler sys over component cooling pumps & addition of 3-h damper between control room & turbine bldg.
PARR, O.D. Light Water Reactors Branch 3. 79/07/09. 4pp.

7908210003 Forwards security personnel training & qualification program Plan withheld (ref 10CFR2.790).
STALLINGS, C.M. Virginia Electric & Power Co. 79/08/17. 1p.

G. Adjudicatory correspondence

7908140045 Responds to 790419 interrogatories re turbine missile issue. Copies of documents identified per request will be directed to E. Weiss.
SWANSON, D.T. Branch 1. 79/05/22. 4pp.

7908010634 Supports adoption of hearing schedule proposed in Potomac Alliance 790515 motion to reschedule hearing.
GOLDBERG, S.C. Branch 2. 79/05/29. 1p.

7908010684 Requests to make limited appearance statement.
WILLIAMSON, M. Affiliation Unknown. 79/06/08. 1p.

7908300754 Opposition to util 790618 motion for interim relief. ASLB lacks authority to grant relief. NRC regulations demand denial. Exemption to regulations should not be granted. Certificate of Svc encl.
DOUGHERTY, J.B. Potomac Alliance. 79/06/09. 16pp.

7908020506 Requests to make limited appearance statement at licensing prehearing.
JEFFRIES, S. Affiliation Unknown. 79/06/11. 1p.

7908160065 Waives provisions of 10CFR2.720(h)(2)(iii) governing discovery re written interrogatories served by Citizens Energy Forum & Potomac Alliance on NRC regarding proposed amend to License NPF-4 to permit storage pool mod.
GOLDBERG, S.C. Branch 2. 79/06/18. 1p.

7908020562 Responds to Potomac Alliance 790601 interrogatories & document requests. Names & areas of expertise of proposed witnesses can be found in util 790620 response to Citizens Energy Forum interrogatories & document requests.
MCKAY, H.S., NEIL, R.M., FISHBACK, D.R. Virginia Electric & Power Co. 79/06/20. 69pp.

--7908020567 Responds to Citizens Energy Forum 790601 interrogatories & document requests. Drawings of new spent fuel pool racks are proprietary. Submits info re thermal effects, radioactive emissions & corrosion.
MCKAY, H.S., NEIL, R.M., EAST, J. Virginia Electric & Power Co. 79/06/20. 38pp.

--7908020570 VEPCO objections to 790601 interrogatories from Potomac Alliance & Citizens Energy Forum. Potomac Alliance format & Questions 21 & 44-47 are too broad. Citizens Energy Forum Question 5-1 requests proprietary drawings.
RINACA, J.M. Hunton & Williams. 79/06/20. 6pp.

7908010637 Forwards V Stello 790625 ltr to J Allen & 790625 director decision per 10CFR2.206 request for enforcement action. No need to offer decision as exhibit in pumphouse settlement phase of proceeding.
SWANSON, D.T. Branch 1. 79/06/27. 1p.

7908160068 Forwards affidavits for JS Wermiel testimony which accompanied NRC supplemental response to util motion for summary disposition re proposed amend to License NPF-
GOLDBERG, S.C. Branch 2. 79/06/28. 5pp.

7908090309 Orders extension until 790723 for Potomac Alliance to respond to util motion for summary disposition. Prehearing conference & hearing will begin 790814. Addl time granted to respond to util motion for interim relief.
DEALE, V.B. Atomic Safety and Licensing Board Panel. 79/06/29. 2pp.

7908300122 Response to intervenor Citizens Energy Forum 790531 & Potomac Alliance 790601 interrogatories re accident portions of Contention 2, Contention 3 & contention on svc water cooling sys. Certificate of Svc.
GOLDBERG, S.C. Branch 2. 79/06/29. 21pp.

7908080040 Notifies that proposed protective order re proprietary Westinghouse data used in Shaffer fault tree analysis will be filed as soon as possible.
CHRISTMAN, J.N. Hunton & Williams. 79/07/03. 2pp.

7908150252 Confirms 790628 telcon re new info about util motion for summary disposition & prefiled written testimony re tornado missiles. Large missiles could not strike fuel elements.
CHRISTMAN, J.N. Hunton & Williams. 79/07/03. 4pp.

7908080104 Response submitted by util to intervenors Potomac Alliance & Citizens Energy Forum, Inc 790615 motion to amend petition to intervene. Requests denial of seismicity contention & mod of issues re spent fuel pool.
CHRISTMAN, J.N. Virginia Electric & Power Co. 79/07/05. 9pp.

--7908080122 Summarizes DC Circuit Court 790523 opinion in State of MN vs NRC. Recommends prompt issuance of final S-3 rule. New Board should conduct generic proceeding re waste disposal. Certificate of Svc encl.
EILPERIN, S.F. Office of the General Counsel. 79/06/11. 15pp.

7908300068 Opposes joint intervenors Potomac Alliance & Citizens Energy Forum 790615 motion to amend petition to intervene re seismicity contentions & extension of time. Discusses 10CFR2.714. Certificate of Svc encl.
GOLDBERG, S.C. Branch 2. 79/07/05. 6pp.

7908300058 Supports util [illegible] motion for interim relief re installation of spent [illegible] storage racks. Interim use of racks is safe & does [illegible] t contentions at issue. Certificate of Svc er.
GOLDBERG, S.C. Branch 2. 79/07/06. 4pp.

7908300110 Notice of special appearance of Westinghouse to submit proprietary info to ASLAB & appearance of JR Kendrick & TM Daugherty on behalf of corp. Forwards draft protective order, affidavit of DH Shaffer & Certificate of Svc.
KENDRICK, J.R. Eckert, Seamans, Cherin & Mellott. DAUGHERTY, T.M. Westinghouse Electric Corp. 79/07/06. 11pp.

7908080131 Memo & order ALAB-555 re damage to safety-related structures from turbines. Grants Westinghouse request for protective order & declines claim of privilege.
BISHOP, C.J. Atomic Safety and Licensing Appeal Panel. 79/07/13. 12pp.

7908170563 Forwards 790717 ltr from VEPCO counsel to ASLAB. Requests ltr be filed w/documents.
CHRISTMAN, J.N. Hunton & Williams. 79/07/17. 1p.

--7908170569 Forwards DH Shaffer 790713 statement on flaw coalescence, requested at 790620 public hearing.
CHRISTMAN, J.N. Hunton & Williams. 79/07/17. 3pp.

H. General correspondence

7908170489 Responds to 790613 ltr expressing concern re adequacy of supply of electric power in light of unavailability of plants. Reanalysis & investigation of both stations necessary to assure health & safety of public.
GOSSICK, L.V. Office of the Executive Director for Operations. 79/07/24. 2pp.

--7908170496 Requests that NRC lift 3-month moratorium on issuance of permits & allow VEPCO plants to be licensed. Otherwise State of VA will suffer from blackouts & excessive rate increases. North Anna Unit 2 design entirely different than TMI.
EDMUNDS, J.T. Virginia, State of. 79/06/13. 1p.

7908010515 Informs NRC that info required to review corporate capabilities will be submitted by 790817.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/30. 1p.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908090546 Forwards Amend 67 to FSAR Affidavit of svc encl.
PROFFITT, W. L. Virginia Electric & Power Co. 79/07/31. 4pp.

--7908090550 Amend 67 to FSAR W/25 oversized drawings.
* Virginia Electric & Power Co. 79/07/31. 23pp.

Q. Inspection reports, IE Bulletins & correspondence

7908020210 Forwards IE Insp Repts 50-338/79-22, 50-339/79-30, 50-404/79-03 & 50-405/79-03 on 790423-25. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/16. 2pp.

--7908020217 IE Insp Repts 50-338/79-22, 50-339/79-30, 50-404/79-03 & 50-405/79-03 on 790423-25. No noncompliance noted. Major areas inspected: structural concrete QA/QC controls, svc water pumphouse settlement data, work performance & records.
LENAHAN, J. J., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/11. 7pp.

7908240114 Forwards IE Insp Repts 50-339/79-33, 50-404/79-05 & 50-405/79-05 on 790529-31. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/22. 2pp.

--7908240118 IE Insp Repts 50-339/79-33, 50-404/79-05 & 50-405/79-05 on 790529-31. No noncompliance noted. Major areas inspected: 10CFR50.55(e) items, response to IE Bulletins & site QA & QC organization & responsibilities.
MCFARLAND, C. R., BRYANT, J. C. Region 2, Atlanta, Office of the Director. 79/06/20. 6pp.

7908070178 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908060172 Follows up 790426 ltr in response to IE Bulletin 79-06A. Primary operator action required to prevent formation of voids, continues to assure proper initiation of engineered safety equipment.
STALLINGS, C. M. Virginia Electric & Power Co. 79/06/29. 21pp.

7908080678 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/02. 2pp.

7908010035 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06. 2pp.

7908150365 Submits final review of compliance w/IE Bulletin 79-03 re weld defects in steel pipe spools mfg by Youngstown Welding & Engineering Co. All items & matl radiographically inspected or reviewed & found acceptable.
BROWN, S. C. Virginia Electric & Power Co. 79/07/11. 3pp.

7909030144 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908070743 Responds to IE Bulletin 79-11 re use of Westinghouse DB-50 & DB-75 circuit breakers. Notifies that specified circuit breakers are in use, but w/o overcurrent trip feature.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/13. 2pp.

7908080151 Responds to IE Bulletin 79-13, Item 5 re cracking in feedwater sys piping. Discusses schedule for insp of feedwater piping welds & procedures to identify & respond to feedwater line break accident.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/13. 4pp.

7908010418 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908060362 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908020036 Forwards G Lainas 790709 memo to D Eisenhut re effect of high environ temp steam generator water level instrumentation. IE action planned to assure Westinghouse licensees take appropriate action.
LAINAS, G. Plant Systems Branch. 79/07/18. 1p.

--7908020038 Advises that Westinghouse informed all customers re possible inaccuracies in steam generator water level indication & subsequent corrections that should be applied. Recommends that item be subj of Board notification.
LAINAS, G. Plant Systems Branch. 79/07/09. 2pp.

--7908020044 PNO-79-185, nonconservative analysis results of high energy line break inside containment discovered per Westinghouse 790621 notification. Info being evaluated. Supplemental orders will be generated to customers.
KLINGLER, G. R., NOLAN, F., BRYAN, S. Office of Inspection & Enforcement, Office of the Director. 79/06/22. 1p.

7908030042 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080063 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130281 Notifies that IE Bulletin 79-14 is revised to limit scope of required work. Forwards replacement page.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908070771 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908080728 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908220403 Ack receipt of 790703 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-25 & 50-339/79-34.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 1p.

--7908220406 Responds to NRC 790508 ltr re violations noted in IE Insp Repts 50-338/79-25 & 50-339/79-34. Corrective actions: test engineers instructed to insure proper use of procedure deviations & documentation of problems.
STALLINGS, C. M. Virginia Electric & Power Co. 79/07/03. 3pp.

--7908220410 Forwards IE Insp Rpts 50-338/79-25 & 50-339/79-34 on 790507-11 & notice of violation.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/08. 2pp.

--7908220412 Notice of violation from insp on 790507-11.
* Region 2, Atlanta, Office of the Director. 79/06/08. 1,

--7908220418 IE Insp Repts 50-338/79-25 & 50-339/79-34 on 790507-11. Noncompliance noted: failure to meet acceptance criteria & failure to document, review or approve change to procedure.
WEBSTER, E. H., WAGNER, A. H. Region 2, Atlanta, Office of the Director. KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/08. 8pp.

7908160276 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908220657 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

7908170016 F ...rds IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/08/08 2pp

S. Reportable occurrences, LERs & related correspondence

7908200118 Deficiency rept on 790618 re missing lower jam nuts & bearing lock washers from four support tube assemblies of pressurizer. Replacement jam nuts & bearing lock washers will be installed prior to criticality.
BROWN, S. C. Virginia Electric & Power Co. 79/06/22 3pp.

7908150192 Submits info concerning 790627 rept re errors in steam generator levels during accident conditions per 10CFR21.
BROWN, S. C. Virginia Electric & Power Co. 79/07/02 4pp.

7908010396 Submits interim rept re status of steam generator level errors during accident conditions. Errors being studied by Westinghouse & further evaluation required. Results will be forwarded to NRC.
BROWN, S. C. Virginia Electric & Power Co. 79/07/27 1p.

7908060278 Submits deficiency rept re grounding of components in Westinghouse 7300 Series Process Control Sys. When process cards are inserted into card slots, heat sinks on transistors could become grounded from contact w/frame guide slot.
BROWN, S. C. Virginia Electric & Power Co. 79/08/03 3pp.

--7908060301 Deficiency rept re component failures in 7300 Series Westinghouse Process Control Sys. Site personnel believe failures in chip that controls output of bistables causes bistables to be inoperative in non-trip condition.
BROWN, S. C. Virginia Electric & Power Co. 79/08/03 3pp.

7908140553 Submits deficiency on 790802 when process cards, Types NMD, NLL, NVP & NCB are inserted into card slots, heat sinks on transistors could become grounded. Caused by faulty component layout.
BROWN, S. C. Virginia Electric & Power Co. 79/08/03 3pp.

7908100407 Submits final rept re potential overloads of electrical sys which supply offsite power. Worst case conditions examined indicate sys will have acceptable voltage levels for emergency motor starting & continuous operation.
BROWN, S. C. Virginia Electric & Power Co. 79/08/07 16pp.

7908230448 Submits final rept re potential overstressing of svc water sys piping & piping supports during post-LOCA conditions due to increased temp range. Summarizes results of piping analysis.
BROWN, S. C. Virginia Electric & Power Co. 79/08/20 3pp.

7908300727 Submits final rept re potential overstressing of svc water sys piping. Outlines specific analyses performed on svc water & component cooling water sys & results of analyses.
BROWN, S. C. Virginia Electric & Power Co. 79/08/20 3pp.

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments w/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors
79/04/18 3pp.

7908020370 Discusses 790511 site evaluation re results of initial review of physical security plan. Changes to plan withheld (ref 10CFR2.790).
KUNIHIRO, D. M. Reactor Safeguards Licensing Branch 79/06/20
3pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch 79/06/27 2p.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
P...D, H. Light Water Reactors Branch 2 79/07/02 70pp.

7908070796 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/13
1p.

7908150211 Forwards NRC comments on preoperational entrainment & impingement study for aquatic areas surrounding facility. Rept does not include preoperational testing. Lack of far field water sampling renders rept technically inadequate.
BALLARD, R. L. Environmental Projects Branch 1 79/07/19 19pp.

7908080158 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/24
2pp.

7906300665 Approves, w/mods, "Intrainment & Impingement study - Phases I & II."
COURCHAINE, R. J. Michigan, State of 79/08/02 3pp.

7908140560 Forwards Certificate of Svc for Amend 25 to license application.
MATERS, B. R. Detroit Edison Co. 79/08/06 3pp.

7908140624 Notifies that utils have formed intermediate BWR plant owners group to coordinate evaluation of knowledge & experience gained & lessons learned from TMI. Requests meeting on 790816 to discuss proposed actions.
JENS, W. H. Detroit Edison Co. 79/08/09 2pp.

G. Adjudicatory correspondence

7908020256 Forwards written interrogatories to Citizens for Employment & Energy (CEE). NRC tried not to duplicate applicant 790327 interrogatories to CEE.
BLACK, R. L. Branch 1 79/03/24 1p.

--7908020264 Interrogatories to Citizens for Employment & Energy re Contentions 6 & 14. Certificate of Svc encl.
BLACK, R. L. Branch 1 79/05/24 5pp.

7908080210 Responds to util interrogatories. Certificate of Svc encl.
PETZEL, D. Citizens for Energy & Employment 79/07/06 4pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908010564 Forwards Amend 25 to FSAR.
LANDGRAF, L. C. LeBoeuf, Lamb, Leiby & MacRae 79/07/31 2pp.

--7908010566 Amend 25 to FSAR.
* Detroit Edison Co. 79/07/31 55pp.

P. Operating license stage documents & correspondence

7908030256 Requests status of LLL electrical staff overpressure & flooding reviews.
EISENHUT, D. G. Division of Operating Reactors 79/06/04 1p.

Q. Inspection reports, IE Bulletins & correspondence

7908020265 Responds to IE Bulletin 79-04 re incorrect weights for swing check valves mfg by Velan Engineering Corp. Forwards 790524 memo indicating that no Velan swing check valves are used in plant safety-related sys.
HINES, E. Detroit Edison Co. 79/05/25 2pp.

7908030602 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. Forwards interim rept from consultants/vendors. No piping computer programs employing algebraic summation utilized by consultants/vendors.
HINES, E. Detroit Edison Co. 79/05/30 18pp.

7908100208 Forwards IE Insp Rept 50-341/79-13 on 790508-11 & notice of violation.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/11 2pp.

--7908100216 Notice of violation from insp on 790508-11.
* Region 3, Chicago, Office of the Director 79/06/04 3pp.

--7908100234 IE Insp Rept 50-341/79-13 on 790508-11. Noncompliance noted: failure to follow procedures, failure to assure performance of nondestructive examination by qualified personnel & failure to control measuring & test equipment.
PHILLIPS, H. S.; HARRISON, J. J.; KNOP, R. C. Region 3, Chicago, Office of the Director 79/06/04 11pp.

7908280437 Forwards response to IE Bulletin 78-12B re atypical weld matl in reactor pressure welds. No evidence of weld matl in welds. C-E ltr describing results of investigation encl.
HINES, E. Detroit Edison Co. 79/06/27 5pp.

--7908280444 Forwards certification that atypical weld matl described in IE Bulletins 78-12 & 12A not in use in reactor vessel.
SCHERER, A. E. Combustion Engineering, Inc. 79/06/08. 2pp.

7908100177 Responds to IE Bulletin 79-02, Revision 1, re potential design & operating problems w/concrete expansion anchors. Licensee has joined w/other utils to have Teledyne Engineering Svcs perform generic analysis. Completion by 790731.
HINES, E. Detroit Edison Co. 79/07/06. 5pp.

7908020333 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908290359 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300407 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908150353 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300276 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908080515 Submits interim deficiency rept followup re handling damage to core spray pump motor EZ-01-C001-D. Motor damage being evaluated. Final rept will be issued if damage is significant enough to be classified.
FAHRNER, W. J. Detroit Edison Co. 79/07/25. 1p.

7908140573 Notifies that Conax-supplied Kulka terminal blocks have passed environ test requirements as defined for drywell electrical penetrations. Rept of possible deficiency may be disregarded.
FAHRNER, W. J. Detroit Edison Co. 79/08/02. 2pp.

DOCKET 50-0344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC

F. Security, medical, emergency & fire protection plans

7908060389 Submits info justifying heat removal adequacy of air recirculation units in Safety Train B Switchgear Room, in response to NRC 790418 request. Info to be in next fire hazard analysis.
GOODWIN, C. Portland General Electric Co. 79/07/30. 6pp.

7908070371 Forwards modified physical security plan, PGE-1017. Plan withheld (ref 10CFR2.790).
GOODWIN, C. Portland General Electric Co. 79/08/02. 1p.

7908210480 Requests extension to 790825 for submittal of PGE-1024, "Trojan Nuclear Plant Security Force Training & Qualification Plan."
BROEHL, D. J. Portland General Electric Co. 79/08/17. 1p.

7908280022 Forwards security force training & qualification plan. Plan withheld (ref 10CFR2.790).
GOODWIN, C. Portland General Electric Co. 79/08/24. 1p.

G. Adjudicatory correspondence

7905150714 Forwards 790215 transcript of 790215 oral argument before ASLAB. W/o encl.
GRAY, J. R. Branch 1. 79/04/20. 1p.

7906110206 Second set of interrogatories on Phase II, submitted to intervenors E Rosolie & Coalition for Safe Power, re Contentions 16, 20 & 22. Certificate of Svc encl.
GRAY, J. R. Branch 1. 79/05/15. 6pp.

--7906110210 Second set of interrogatories on Phase II, submitted to consolidated intervenors, re Contentions 1, 4 & 11.
GRAY, J. R. Branch 1. 79/05/15. 3pp.

7908090391 Forwards 790523 decision of Court of Appeals in State of MN vs NRC & New England Coalition on Nuclear Pollution vs NRC. Requests NRC clarify finding in denial of petition for rulemaking by NRDC.
GRAY, J. R. Office of the General Counsel. 79/06/01. 19pp.

7908100591 Responds to util 790611 motion for order compelling E Rosalie & Coalition for Safe Power to respond fully to licensee second set of interrogatories. No position taken; no intention to further respond to motion.
GRAY, J. R. Branch 2. 79/06/20. 1p.

7908080067 Forwards responses prepared by Bechtel Power Corp to addl 14 of 50 questions, re 790518 ltr. Submits info re connection interfaces of addl walls to existing structures. Certificate of Svc encl.
JOHNSON, R. W. Portland General Electric Co. 79/06/29. 60pp.

7908300758 Supplemental response to licensee second set of interrogatories submitted by E Rosolie & Coalition for Safe Power. Responds to Interrogatories 13(c)(i), 14(a)(i), 15 (a)-(c) & 16-18.
ROSALIE, E. Coalition for Safe Power. 79/06/29. 2pp.

--7908300761 First set of interrogatories for licensee submitted by E Rosolie & Coalition for Safe Power. Seeks info re LER amend to Tech Specs, proposed mod work during refueling & Const QC Manual. Certificate of Svc encl.
ROSOLIE, E. Coalition for Safe Power. 79/06/30. 4pp.

7908230456 Responds to 790330 request re current status of reg guide ref in PGE-1020, Paragraph 3.2.2.2. Forwards CM Trammell 790628 memo to J Gray.
GRAY, J. R. Branch 1. 79/07/09. 1p.

--7908230465 Responds to E Rosolie 790330 request re current status of reg guide ref in PGE-1020, Paragraph 3.2.2.2. Forwards status of guides that are current & not revised & guides for which different versions are in effect.
TRAMMELL, C. M. Operating Reactors Branch 1. 79/06/28. 5pp.

--7908230471 Draft "Value/Impact Assessment of QA Requirements for Operation of Nuclear Power Plants."
* Assistant Director for Quality Assurance & Operations. 79/03/15. 10pp.

--7908230484 Draft "Value/Impact Assessment on Qualification of Nuclear Power Plant Insp, Examination & Testing Personnel."
* Office of Nuclear Reactor Regulation. 79/04/05. 10pp.

--7908230490 Draft "Preliminary Value/Impact Statement on QA Requirements for Installation, Insp & Testing of Structural Concrete, Structural Steel, Soils & Foundation During Const Phase at Nuclear Power Plants."
* Assistant Director for Quality Assurance & Operations. 79/07/09. 5pp.

--7908230491 "Preliminary Value/Impact Assessment on QA Program Requirements for Nuclear Power Plants."
* Assistant Director for Quality Assurance & Operations. 79/07/09. 6pp.

--7908230496 "Value/Impact Assessment for Reg Guide 1.28, Revision 1, QA Program Requirements, Design & Const."
* Assistant Director for Quality Assurance & Operations. 79/07/09. 2pp.

--7908230504 "Value/Impact Assessment for Reg Guide 1.26, Revision 2, QA Program Requirements, Design & Const."
* Assistant Director for Quality Assurance & Operations. 79/07/09. 3pp.

--7908230511 Discusses difficulty in distinguishing between requirements & guidelines or recommendations in reg guides re industry std.
GILBERT, W. O. General Electric Co. 75/02/20. 3pp.

--7908230519 Responds to 750220 ltr re interpretation of reg guides re industry std containing requirements & guidelines or recommendations. In instances cited, requirements & guidelines or recommendations were endorsed.
MINOGUE, R. B. Office of Standards Development. 75/05/06. 4pp.

--7908230525 "Value/Impact of Proposed Revision 1 to Reg Guide 1.38, QA Program Requirements for Packaging, Shipping, Receiving, Storage & Handling of Items for Water-Cooled Nuclear Power Plants."
* Assistant Director for Quality Assurance & Operations. 79/07/09. 7pp.

--7908230532 "Value/Impact of Proposed Revision 2 to Reg Guide 1.38, QA Requirements for Packaging, Shipping, Receiving, Storage & Handling of Items for Water-Cooled Nuclear Power Plants."
* Assistant Director for Quality Assurance & Operations. 79/07/09. 1p.

--7908230539 "Preliminary Value/Impact Statement on Reg Guide 1.38, Revision 3, QA Requirements for Packaging, Shipping, Receiving, Storage & Handling of Items for Nuclear Power Plants."
* Assistant Director for Quality Assurance & Operations. 79/07/09. 5pp.

--7908230543 "Impact of Proposed Revision 1 to Reg Guide 1.39, Housekeeping Requirements for Nuclear Power Plants."
* Office of Nuclear Reactor Regulation. 79/07/09. 5pp.

--7908230549 "Background & Value/Impact Assessment of Proposed Revision 2 to Reg Guide 1.39, Housekeeping Requirements for Water-Cooled Nuclear Power Plants."
* Office of Nuclear Reactor Regulation. 79/07/09. 2pp.

--7908230554 "Value/Impact of Proposed Revision 1 to Reg Guide 1.123, QA Requirements for Control of Procurement of Items & Svc for Nuclear Power Plants."
* Assistant Director for Quality Assurance & Operations. 79/07/09. 1p.

7908080020 Forwards answers prepared by Bechtel Power Corp to remaining two questions re 790518 ltr. Submits info re wall shear strengths & stiffness & displacement of turbine & control bldg. Certificate of Svc encl.
BROEHL, D. J. Portland General Electric Co. 79/07/10. 57pp.

7908220013 Requests that ASLB order intervenors E Rosolie & Coalition for Safe Power to answer Question C16-4 of NRC 790515 interrogatories re protection of safety-related equipment during mod. Certificate of Svc encl.
GRAY, J. R. Branch 1. 79/07/10. 9pp.

7908300302 Suppl to 790611 request that ASLB compel E Rosolie & Coalition for Safe Power to respond fully to Interrogatories 14(b) & (c), 15(c), 16, 17 & 18(a) & (b) of util 790508 second set of interrogatories w/Certificate of Svc.
JOHNSON, R. W. Portland General Electric Co. AXELRAD, M., CARR, A. V. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/10. 12pp.

H. General correspondence

7908010531 Responds to 790729 request for info on mgt & tech resources. Info is being compiled & will be submitted by 790813. Requests info be withheld from public disclosure (ref 10CFR2.790).
BROEHL, D. J. Portland General Electric Co. 79/07/26. 1p.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908020168 Discusses review of 790425 ltr re containment tendon surveillance. Forwards comments. Requests responses be included in upcoming revision to License Change Application 15.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/06/15. 4pp.

7908210069 Forwards safety evaluation of licensee 790606 request for amend to License NPF-1 re mod to safety injection actuation sys logic.
LAINAS, G. Plant Systems Branch. 79/06/22. 2pp.

--7908210096 Safety evaluation of mod to safety injection actuation sys logic. Mod satisfies IEEE 279-1971 requirements. Tech Specs are correct. Amend should be granted.
* Plant Systems Branch. 79/06/22. 1p.

7908080640 Notifies that approval has been obtained for exempting amends in Fee Classes I, II & III from fee requirements when amend is direct result of upgraded STS bases program.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/09. 2pp.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908160082 Forwards request for addl info required to conduct review of PGE-1020, "Rept on Design Mods for Trojan Control Bldg."
SCHWENCER, A. Operating Reactors Branch 1. 79/07/20. 8pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit if more than one is owned & operated.
HAASS, W. J. Quality Assurance Branch. 79/07/24. 1p.

7908010492 Forwards addl info re containment tendon surveillance program in response to 790615 ltr. Response to Item 3 will follow.
BROEHL, D. J. Portland General Electric Co. 79/07/26. 4pp.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch. 79/07/30. 64pp.

7908130581 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
SCHWENCER, A. Operating Reactors Branch 1. 79/08/01. 4pp.

7908080467 Advises that milk samples are no longer being taken from sampling location in area. Although no suitable alternative site available, will reinitiate program when possible.
GOODWIN, C. Portland General Electric Co. 79/08/03. 1p.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908270070 Responds to request for technical assistance in preparing response to petition from Coalition for Safe Power. Will prepare responses re fire protection. Environ qualification should be handled by Div of Sys Safety.
GRIMES, B. Assistant Director for Systems Engineering. 79/08/08. 1p.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908150618 Forwards License Change Application 55 requesting amend to License NPF-1 amend to reflect change in operating staff & corporate organization.
BROEHL, D. J. Portland General Electric Co. 79/08/13. 1p.

--7908150623 License Change Application 55, amending License NPF-1 to reflect changes in operating staff & corporate organization.
BROEHL, D. J. Portland General Electric Co. 79/08/09. 19pp.

7908170359 Forwards results of mgt & tech resources survey of util & facility per NRC 790629 & 0724 ltrs. Rept withheld (ref 10CFR2.790).
BROEHL, D. J. Portland General Electric Co. 79/08/13. 4pp.

7908170424 Forwards answers to questions in NRC 790720 ltr. Includes info re critical load handling during control bldg mod, movement of const equipment & description of safety-related equipment & cables located in mod work zone areas.
BROEHL, D. J. Portland General Electric Co. 79/08/13. 137pp.

7908200316 Forwards PGE-1022, "Inservice Testing Program for Pumps & Valves," in support of License Change Application 26, Revision 1.
LINDBLAD, W. J. Portland General Electric Co. 79/08/14. 1p.

--7908200319 "Inservice Testing Program for Pumps & Valves."
GERLT, D. H. Portland General Electric Co. PGE-1022. 79/06/30. 100pp.

7908270401 Forwards Offsite Dose Calculation Manual.
BROEHL, D. J. Portland General Electric Co. 79/08/14. 1p.

--7908270411 "Offsite Dose Calculation Manual w/Chem-Nuclear Sys Inc process control program for solidification of wet radioactive waste.Revision 19.dtd 790719."
* Portland General Electric Co. PGE-1021. 79/06/30. 70pp.

7908270363 Forwards suppl repts re upgraded cable penetration fire seal configurations,test repts verifying acceptability of configurations & table correlating drawing & acceptable test ANI 780808 & 790115 ltrs encl.
GOODWIN,C. Portland General Electric Co. 79/08/22. 8pp.

--7908270369 "Fire Test Configurations for Silicone Foam Fire Barriers." Const Technology Lab 790625 ltr to Brand Industrial Svc,Inc discussing rept review encl.
ANDERSON,J.S. Brand Industrial Services, Inc. 79/06/20. 39pp.

--7908270374 "Metal Clad Fire Wall Penetration Barrier Fire Testing." Portland Cement Association 790625 ltr discussing rept review encl.
ANDERSON,J.S. Brand Industrial Services, Inc. 79/05/21. 53pp.

--7908270378 "Evaluation of Dow Corning DC 3-6548 & BISCO SF-20 Silicone Foams During Three-Hour Controlled Fire Test w/Penetrating Items." Portland Cement Association 771003 ltr discussing rept review encl.
ABRAMS,M.S. Brand Industrial Services, Inc. 77/08/16. 43pp.

--7908270388 "Qualification,Fire & Hose Stream Tests."
ABRAMS,M.S. Construction Technology Laboratories (div. of Portland Cement Assoc.). 78/02/28. 18pp.

--7908270398 "Fire Endurance Test on Penetration Seal Sys in Concrete Floor Utilizing Silicone Elastomers."
ABRAMS,M.S. Construction Technology Laboratories (div. of Portland Cement Assoc.). 76/10/31. 59pp.

7908280683 Forwards corrected page to Attachment A of License Change Application 55 re organizational structure of facility staff.
GOODWIN,C. Portland General Electric Co. 79/08/22. 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908100077 Forwards IE Bulletin 79-07 re seismic stress analysis of safety-related piping & util 790423 response.Matter considered resolved for facility.
GRAY,J.R. Branch 1. 79/05/18. 4pp.

7908090601 Responds to IE Bulletin 79-01.Forwards info re environ qualifications of Class IE equipment at plant,examination of electrical equipment & equipment strength under postulated accident conditions.
GOODWIN,C. Portland General Electric Co. 79/06/12. 67pp.

7908090690 Ack receipt of 790514 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/79-07.
CREWS,J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/06/13. 1p.

--7908090692 Forwards IE Insp Rept 50-344/79-07 on 790301-30 & notice of violation.Details withheld (ref 10CFR2.790).
CREWS,J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/04/23. 2pp.

--7908090695 IE Insp Rept 50-344/79-07 on 790301-30.Noncompliance noted: failure to provide proper escort within protected area & to maintain access to designated vital area.
MALMROS,M.H. Region 5, San Francisco, Office of the Director.
STERNBERG,D.M. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/04/23. 6pp.

7908070552 Forwards suppl to 790612 response to IE Bulletin 79-01.Suppl provides addl info documenting discussions re capabilities of presently installed in-containment instrumentation to perform short-term & long-term monitoring functions.
MILLER,D.R. Portland General Electric Co. 79/06/15. 13pp.

7908010391 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908020498 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety Related Piping Sys."
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908020407 Forwards corrected copy of IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/07/19. 1p.

7908060024 Forwards IE Bulletins 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908060058 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908060130 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210497 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908170036 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/08/10. 1p.

7908280384 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER,B.H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310151 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300241 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908080469 Forwards monthly operating rept for Jul 1979.
WITHERS,S.D. Portland General Electric Co. 79/08/02. 1p.

--7908080473 Monthly operating rept for July 1979.
BAIR,C.G. Portland General Electric Co. 79/08/02. 5pp.

S. Reportable occurrences, LERs & related correspondence

7908140790 Forwards LER 79-010/03L-0.
WITHERS,B.D. Portland General Electric Co. 79/06/22. 3pp.

--7908140795 LER 79-010/03L-0 on 790525,two valves found leaking during local leak rate testing.Caused by uneven seating of two gate valves between disc & seat.Valves repaired & retested.
PERRY,J.C. Portland General Electric Co. 79/06/22. 3pp.

7908020529 Forwards PNO-79-67AW.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020028 Forwards PNO-79-67AX.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908130387 Forwards LER 79-012/03L-0.
WITHERS,B.D. Portland General Electric Co. 79/08/02. 1p.

--7908130389 LER 79-012/03L-0 on 790705,pressurizer pressure transmitter PT-457 setpoints exceeded Tech Specs.Caused by instrument drift.Transmitter recalibr & replaced.
PERRY,J.C. Portland General Electric Co. 79/08/02. 2pp.

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

7908150720 Requests evaluation of semiscale small break experiment w/small break computer program by 790901.
ROSS,D.F. TMI-2 Unresolved Safety Issues. 79/07/16. 7pp.

F. Security, medical, emergency & fire protection plans

7908270295 Ack receipt of 790323 ltr transmitting safeguards contingency plan for facility Class III fee required.
DIGGS,R.M. License Fee Management Branch. 79/07/03. 2pp.

7908140092 Forwards resolution of fire prevention program issues per 790605 discussion. Details included in IE Insp Rept 50-346/79-15.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/17. 3pp.

7908210526 Requests that deadline for mods to svc water pump & valve room fire protection sys be extended to 791231 due to late selection & mobilization of contractor.
ROE, L. E. Toledo Edison Co. 79/08/14. 3pp.

7908170412 Forwards preliminary industrial security plan. Plan withheld (ref 10CFR2.790).
ROE, L. E. Toledo Edison Co. 79/08/15. 1p.

G. Adjudicatory correspondence

7908020522 Ack receipt of 790503 ltr requesting facility shutdown until after public hearings re plant safety. Hearings will not be scheduled unless requested by licensee or public before 790605.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/01. 5pp.

--7908020528 Expresses concern re facility safety. Suggests shutdown until after public hearings.
MCCORMACK, T. Ohio, State of. 79/05/03. 2pp.

H. General correspondence

7908270528 Ack receipt of ltr re plant shutdown & piping leaks. Requests addl info to permit full response.
HELTEMES, C. J. Standardization Branch. 79/08/01. 1p.

7908100195 Responds to 790629 request for review of corporate capabilities in support of Facility Rept encl.
ROE, L. E. Toledo Edison Co. 79/08/08. 1p.

--7908100198 "Corporate Capabilities."
* Toledo Edison Co. 79/08/08. 140pp.

M. Antitrust correspondence

7908160240 Discusses antitrust actions against util per City of Cleveland 780104 request re conditions which require licensees to provide wheeling in combined Central Area Power Coordination territories. Forwards order.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 2pp.

--7908160257 Order modifying antitrust license Condition 3 re wheeling for & at request of other entities in combined Central Area Power Coordination Group territories.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 8pp.

--7908160264 Notice of violation of Antitrust license Condition 3 of Licenses NPF-3, CPPR-148 & CPPR-149 & specified const permits re wheeling for other entities in combined Central Area Power Coordination Group.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 4pp.

--7908160272 Specifies recommended changes to svc tariff re transmission of electric power between delivery points of util transmission sys.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 8pp.

--7908160281 Unexecuted transmission svc tariff re transmission of electrical power between delivery points of util to, from or between rural electrical cooperatives or municipalities. Agreements encl.
* Office of Nuclear Reactor Regulation. 79/06/25. 11pp.

--7908160297 Unexecuted amended transmission svc tariff re transmission of electrical power between delivery points of util & any electrical entity. Form of svc agreement & Exhibits A & B encl.
* Office of Nuclear Reactor Regulation. 79/06/25. 11pp.

7908030219 Forwards 790625 order modifying antitrust License Condition 3 of licenses issued in connection w/proceedings.
VOGLER, B. H. Anti-Trust Division. 79/06/28. 1p.

7908070008 Forwards Ofc of Nuclear Reactor Regulation 790625 order modifying Antitrust License Condition 3. W/o encl.
VOGLER, B. H. Anti-Trust Division. 79/06/28. 1p.

7908170261 Forwards 790716 order revising 790625 order re licenses & permits for facilities.
SALTZMAN, J. Antitrust & Indemnity Group. 79/07/16. 1p.

--7908170266 Revises 790625 order, extending deadline by 15 days for request re hearing & filing of transmission tariff.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/16. 2pp.

7908210073 Forwards FR notice to be transmitted to Ofc of FR for filing & publication.
SALTZMAN, J. Antitrust & Indemnity Group. 79/07/16. 1p.

--7908210078 Notice of issuance of order by Ofc of Nuclear Reactor Regulation granting 15-day extension for util to request hearing & file transmission tariff re 790625 order amending Antitrust License Condition 3.
SALTZMAN, J. Antitrust & Indemnity Group. 79/07/16. 1p.

7908060452 Responds to 790625 order re mod of Antitrust License Condition 3, directing amends to transmission svc tariff be filed w/Federal Energy Regulatory Commission effective immediately. Requests 25-day extension.
REYNOLDS, W. B. Shaw, Pittman, Potts, & Trowbridge. 79/08/02. 2pp.

7908070648 Requests opportunity to be heard on two issues set out in 790625 order calling for mod of Antitrust License Condition 3. Issues concern whether util has been in noncompliance since 780127, when first transmission tariff was filed.
REYNOLDS, W. B. Shaw, Pittman, Potts, & Trowbridge. 79/08/06. 2pp.

7908300195 Forwards RJ Mattson 790806 order modifying 790625 order re licenses & permits.
TOALSTON, A. L. Antitrust & Indemnity Group. 79/08/06. 1p.

--7908300206 Orders suspension of immediate effectiveness of 790625 order requiring util to file specific transmission tariff. City of Cleveland, OH & DOJ may respond to mod of 790625 order.
MATTSON, R. J. Office of Nuclear Reactor Regulation. 79/08/06. 3pp.

7908230308 Ack receipt of 790806 order granting City of Cleveland 30 days to respond to util request for stay of 790625 order. Opposes stay & will protest temporary stay.
GOLDBERG, R. Goldberg, Fieldman & Lethan, P. C. 79/08/20. 2pp.

P. Operating license stage documents & correspondence

7908100400 Forwards chronologies of 770924 Davis-Besse & 750613 Oconee events. In both cases steam formed in RCS analogously to TMI event.
WRIGHT, R. L. ACRS - Advisory Committee on Reactor Safeguards. 79/05/03. 3pp.

7908090083 FOIA request for records re 27 licensed operators.
HAUSER, B. Lorain Journal, Ohio. 79/05/09. 1p.

7908090208 FOIA request for documentation re plant shutdowns due to deficiencies, transcripts of various proceedings & NRC ltrs re safety features & design problems.
HOPKINS, J. P. Ohio, State of. 79/05/18. 3pp.

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908090678 Forwards Amend 16 to License NPF-3, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4. 79/06/04. 3pp.

--7908090680 Amend 16 to License NPF-3, revising Tech Specs re reactor core safety limit curve, reactor protection sys instrumentation trip setpoints & reactor coolant hot leg temp.
REID, R. W. Operating Reactors Branch 4. 79/06/07. 17pp.

--7908090684 Safety evaluation supporting Amend 16 to License NPF-3.
* Office of Nuclear Reactor Regulation. 79/06/07. 2pp.

--7908090686 Notice of issuance & availability of Amend 16 to License NPF-3.
REID, W. R. Operating Reactors Branch 4. 79/06/07. 2pp.

7908300223 Responds to 790525 request re TAC 11408. Forwards Plant Sys Branch safety evaluation re proposed change in completion date of noiss & isolation testing of safety features actuation sys.
LAINAS, G. Plant Systems Branch. 79/06/12. 1p.

--7908300231 Safety evaluation re change in date of completion of noise & isolation testing of safety features actuation sys
* Plant Systems Branch 79/06/12 2pp

--7908300239 "Evaluation of Time Extension for Safety Features Actuation Sys Studies," technical evaluation rept.
REEVES, W. E. Lawrence Livermore Laboratory 79/05/30 4pp

7908160113 Forwards drawings & drawing change notices re makeup & purification sys Drawings available in Central Files only.
ROE, L. E. Toledo Edison Co. 79/06/19 1p

7908070676 Notifies of intent to install second communications sys linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/22 3pp

7908080197 Requests addl info re fish impingement study.
REID, R. W. Operating Reactors Branch 4 79/06/27 3pp

7908150142 Discusses review of util actions re NRC 790516 order. Shutdown no longer required. Safety evaluation & draft ltr to licensee encl.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/27 1p

--7908150146 Draft ltr forwarding safety evaluation & FR notice re authorization to resume operation.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/27 4pp

--7908150153 Draft FR notice re authorization to resume operation.
REID, R. W. Operating Reactors Branch 4 79/06/27 3pp

--7908150162 Draft safety evaluation re licensee compliance w/NRC 790516 order. Licensee may restart facility.
* Office of Nuclear Reactor Regulation 79/06/27 36pp

7908160225 Forwards T.J. Lodge 790612 ltr submitting petition for rulemaking on evacuation & emergency planning issues & all correspondence to date between NRC & petitioner on issue.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/27 1p

--7908160235 Ack receipt of 790612 ltr requesting part of petition be treated as petition for rulemaking. Action taken for docketing. Remaining request for proceeding to modify license will be acted upon shortly.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/27 2pp

--7908160241 Order to shut down facility until specified steps re emergency & evacuation actions & public hearings are satisfactorily completed.
CHILK, S. J. Office of the Secretary of the Commission 79/06/21 3pp

--7908160248 Requests info submitted in 790424 & 0523 ltrs re inadequate emergency & evacuation plans be treated as petition for mod of OL. Portions of 790424 ltr should be consolidated w/PRM-50-23 filed by Critical Mass Energy Project.
LODGE, T. J. Toledo Coalition for Safe Energy 79/06/12 3pp

--7908160255 Requests definition of "reasonable time" per notice published in FR re util complaint. Forwards 790523 ltr responding to motion for dismissal filed by licensee. W/o encl.
LODGE, T. J. Toledo Coalition for Safe Energy 79/06/12 1p

--7908160260 Urges denial of Toledo Coalition for Safe Energy 790424 request for order to prohibit restart of facility until emergency & evacuation actions are taken by util & public hearings are held. Request lacks specificity.
CHURCHILL, B. W. Shaw, Pittman, Potts, & Trowbridge 79/06/08 2pp

--7908160267 Ack receipt of petition requesting issuance of order prohibiting restart of facility until emergency & evacuation actions are taken by util & public hearings are held. Forwards FR notice. W/o encl.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/01 1p

--7908160284 Forwards Toledo Coalition for Safe Energy 790424 petition requesting order to prohibit restart of facility until emergency & evacuation actions are taken by util & public hearings are held. FR notice encl.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/01 2pp

--7908160291 Notice of issuance & availability of Toledo Coalition for Safe Energy 790424 petition requesting order to prohibit restart of facility until emergency & evacuation actions are taken by util & public hearings are held.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/01 1p

--7908160299 Confirms 790521 telcon re treatment of 790424 ltr as request for formal hearing. Forwards 790420 Toledo Blade article & 790418 press release by OH PIRG re inadequate evacuation plans. Article not encl.
LODGE, T. J. Toledo Coalition for Safe Energy 79/05/23 7pp

--7908160306 Responds to 790424 ltr re inadequate emergency evacuation plans. Ltr treated as request for formal hearing. Forwards order issued to util requiring design mods & changes in operating procedure. W/o encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/17 1p

7908020339 Expresses concern over util failure to inform NRC of 790521 RO 79-062 involving inoperable auxiliary feedwater suction pressure switches & out-of-tolerance pressure setpoints. Submits questions re mgt awareness & lack of communication.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/06/29 3pp

7908080213 Requests addl info re determination of core parameters from rod drop test.
REID, R. W. Operating Reactors Branch 4 79/07/02 3pp

7908090660 Forwards revised safety evaluation for facility re 790516 shutdown order.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/02 2pp

--7908090664 Safety evaluation re licensee's compliance w/NRC 790516 order.
* Office of Nuclear Reactor Regulation 79/07/02 37pp

7908030159 Notification of 790801 meeting w/util in Bethesda, MD to discuss App I Tech Specs & environ monitoring program.
VISSING, G. S. Operating Reactors Branch 4 79/07/05 2pp

7908220228 Confirms that actions prescribed by NRC 790516 order to enhance response capability re transient events have been completed. Plant may resume operation. Requests schedule for long-term mods.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/06 4pp

--7908220231 Evaluation of licensee compliance w/NRC 790516 order. Unit 1 may resume operation.
* Office of Nuclear Reactor Regulation 79/07/06 38pp

--7908220237 Notice of authorization to resume operations. Actions taken in response to NRC 790516 order have been successfully completed.
REID, R. W. Operating Reactors Branch 4 79/07/06 3pp

7908130330 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires initial NRC notification.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/09 1p

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors 79/07/18 56pp

7908070346 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago Office of the Director 79/07/19 1p

7908090217 Responds to FOIA request for 14 items related to facility. Forwards documents, including insp repts, in response to three of 14 items requested & list of addl documents available in LPDR.
FELTON, J. M. Division of Rules and Records 79/07/23 6pp

--7908090255 Forwards memo re info for consideration by Licensing Boards. Preliminary evaluation indicated info did not meet intended criteria for Board notification. Originator believes info is pertinent & requests items be sent to appropriate Boards.
MOSELEY, N. C. Division of Reactor Operations Inspections 79/02/28 1p

--7908090263 Submits insp items for consideration for forwarding to ASLB. Six items pertain to core lifting, power oscillations, pressurizer level during transients, shutdown margin maint & severe thermal transient.
CRESWELL, J. S. Region 3, Chicago, Office of the Director 79/01/08 3pp

--7908090278 Forwards evaluation of six items re B&W-designed nuclear plants. Recommends that info be forwarded to Licensing Boards.
MOSELEY, N. C. Division of Reactor Operations Inspections. 79/03/28 10pp.

7908200056 Requests proposed amend to license to delete Tech Specs re secondary water chemistry monitoring program to incorporate requirements of encl model license condition. Requests submittal within 60 days.
REID, R. W. Operating Reactors Branch 4. 79/07/23. 5pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908230056 Requests results of semiscale small break experiment be compared w/small break computer program being used by C-E in support of owners group. To date, evaluations of latter have been inconclusive.
ROSS, D. F. TMI-2 Bulletins & Orders. 79/07/25. 8pp.

7908020442 Forwards 790410 "B&W 177 Fuel Assembly Owners' Group Asymmetric LOCA Loads Evaluation Program, Phase 2." Summarizes program started in response to NRC 780120 request. Conclusions will be available Jul 1980.
ROE, L. E. Toledo Edison Co. 79/07/26. 2pp.

--7908020443 "B&W 177 Fuel Assembly Owners' Group Asymmetric LOCA Loads Evaluation Program, Phase 2."
* Babcock & Wilcox Operating Plants Owners Group. 79/04/10. 9pp.

7908220353 Forwards Amend 18 to License NPF-3, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4. 79/07/26. 4pp.

--7908220360 Amend 18 to License NPF-3, adding license condition re completion of facility mod for fire protection & modifying Tech Specs to require five individuals w/fire protection training on site.
REID, R. W. Operating Reactors Branch 4. 79/07/26. 5pp.

--7908220363 Fire protection safety evaluation supporting Amend 18 to License NPF-3.
* Office of Nuclear Reactor Regulation. 79/07/26. 23pp.

--7908220367 Notice of issuance & availability of Amend 18 to License NPF-3.
REID, R. W. Operating Reactors Branch 4. 79/07/26. 2pp.

7908010361 Forwards application for amend to License NPF-3 re extension of time to perform first inservice insp of steam generator tubes & revised steam generator tube sampling selection.
ROE, L. E. Toledo Edison Co. 79/07/27. 9pp.

7908080132 Responds to 790723 document requests. Forwards NUREG-0558, "Population Dose & Health Impact of Accident at TMI Nuclear Station," & summary pages of four effluent & waste disposal semiannual repts for period 770422-781231. W/o encl.
CAPRA, R. A. TMI-2 Bulletins & Orders. 79/07/27. 1p.

7908300599 Summary of 790719 meeting w/utils in Bethesda, MD to discuss outstanding items from NRC orders & IE Bulletins generic to all B&W facilities.
CAPRA, R. A. TMI-2 Bulletins & Orders. 79/07/31. 24pp.

7908290665 Forwards Amend 19 to License NPF-3, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4. 79/08/01. 3pp.

--7908290674 Amend 19 to License NPF-3, allowing increase in spent fuel storage capability from 260 to max of 735 fuel assemblies in spent fuel pool through use at high capacity spent fuel racks.
GAMMILL, W. P. Division of Operating Reactors. 79/08/01. 7pp.

--7908290680 Safety evaluation supporting Amend 19 to License NPF-30.
* Office of Nuclear Reactor Regulation. 79/08/01. 4pp.

--7908290685 EIA supporting Amend 19 to License NPF-3.
* Office of Nuclear Reactor Regulation. 79/08/01. 22pp.

--7908290691 Notice of issuance & availability of Amend 19 to License NPF-3.
REID, R. W. Operating Reactors Branch 4. 79/08/01. 2pp.

7908070595 Forwards addl info requested in NRC 790702 ltr re determination of core parameter during rod drop test. Linear heat rates & DNB calculations for online computer calculations are conservative.
ROE, L. E. Toledo Edison Co. 79/08/02. 14pp.

7908090090 Responds to FOIA request for records re reactor operators. Forwards list of licensees & individual test results, w/o identifying individuals.
FELTON, J. M. Division of Rules and Records. 79/08/03. 7pp.

7908100453 Responds to NRC 790627 request. Forwards addl info re fish egg & larvae entrainment data contained in Section 3.1.2.a.5 of Annual Environ Operating Rept 1978.
ROE, L. E. Toledo Edison Co. 79/08/03. 3pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908160230 Notification of 790809 meeting w/B&W Owners' Group in Bethesda, MD to discuss long-term generic requirements for B&W operating plants.
CAPRA, R. A. TMI-2 Unresolved Safety Issues. 79/08/06. 2pp.

7908140478 Submits update on status of long-term items per NRC 790516 order. Discusses auxiliary feedwater sys, control sys, failure modes & effects analysis, transient analysis & procedure for mgt of small breaks.
ROE, L. E. Toledo Edison Co. 79/08/07. 2pp.

7908140527 Forwards addl info re feedwater line design, fabrication & history & preservice/inservice insp & operating history, requested in V Stello 790525 ltr.
ROE, L. E. Toledo Edison Co. 79/08/08. 5pp.

7908140602 Forwards revised pages to Chapter 1 of Initial Startup Rept, as revised by Suppl 5 for period 790406-0705.
GRANT, J. S. Toledo Edison Co. 79/08/08. 1p.

--7908140611 Revised pages to Chapter 1 of Initial Startup Rept, as revised by Suppl 5 for period 79046-0705.
* Toledo Edison Co. 79/08/08. 14pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining, all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908220432 Forwards revised Tech Spec proposal re changes in surveillance requirements for steam generator tube insp.
ROE, L. E. Toledo Edison Co. 79/08/17. 1p.

--7908220434 Tech Specs for RCS re changes in surveillance requirements for steam generator tube insp.
* Toledo Edison Co. 79/08/17. 5pp.

G. Inspection reports, IE Bulletins & correspondence

7907020065 Forwards IE site inspector daily repts for B&W reactors for 790419.
DAVIS, J. G. Office of Inspection & Enforcement, Office of the Director. 79/04/20. 1p.

7908030610 Responds to IE Bulletins 78-12, 12A & 12B re welds in matl surveillance specimens. Forwards B&W 790524 ltr re ferretic welds & B&W 790313 ltr re off-chemistry welds.
GRANT, J. S. Toledo Edison Co. 79/05/31. 4pp.

--7908030619 Responds to IE Bulletins 78-12 & 12A. Forwards rept "Records Investigation Rept Related to Off-Chemistry Welds in Matl Surveillance Specimens & Responses to IE Bulletins 78-12 & 78-12A Suppl." W/o encl.
TAYLOR, J. H. Babcock & Wilcox Co. 79/03/13. 2pp.

7908010313 Responds to IE Bulletin 79-01. Requests 30-day extension for response due to personnel shortages.
GRANT, J. S. Toledo Edison Co. 79/06/13. 1p.

7908160313 Forwards IE Insp Rept 50-346/79-13 on 790313-15, 0402-30, 0501-04, 17-18 & 21-25 & notice of violation.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/29. 2pp.

--7908160315 Notice of violation from insp on 790313-15,0402-30,0501-04, 17-18 & 21-25.
* Region 2, Atlanta, Office of the Director 79/06/29 1p

--7908160322 IE Insp Rept 50-346/79-13 on 790313-15,0402-30,0501-04, 17-18 & 21-25 Noncompliance noted: failure to follow procedure. TAMBLING, T N ; BAKER, K R ; WARNICK, R F Region 2, Atlanta, Office of the Director 79/06/28 17pp

7908100583 Forwards response to IE Bulletin 79-11 Westinghouse Type DB-50 & DB-75 circuit breakers not in use in safety-related sys.
GRANT, J S Toledo Edison Co 79/07/03 2pp

7908080093 Responds to IE Bulletin 79-02. Pipe support base plates not rigid. Analysis being performed on plates to determine if net loads are acceptable, considering effects of plate flexibility, bolt stiffness & shear tension interaction.
GRANT, J S Toledo Edison Co 79/07/06 29pp

7908130416 Forwards response to IE Bulletins 79-01 & 01A re review of environ qualification of Class IE equipment. No stem-mounted limit switches in use on safety-related valves.
GRANT, J S Toledo Edison Co 79/07/12 8pp

7908140109 Forwards reponses to IE Bulletin 79-13 Emergency procedures for responding to feedwater line break accident have been reviewed in light of TMI incident. Methods for feedwater leak inside containment detection encl
GRANT, J S Toledo Edison Co 79/07/13 5pp

7908020355 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

7908290293 Forwards IE Bulletins 79-05C & 06C, "Nuclear Incident at TMI - Suppl." Action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/26 1p

7908290374 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/26 1p

7908300441 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/26 1p

7908200113 Responds to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys.
GRANT, J S Toledo Edison Co 79/08/01 14pp

7908150384 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/08/07 1p

7908170026 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/08/08 1p

7908300300 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/08/15 1p

R Periodic operating reports & related correspondence

7908140460 Forwards monthly operating rept for Jul 1979.
MURRAY, T D Toledo Edison Co 79/08/07 1p

--7908140465 Monthly operating rept for Jul 1979
CABA, E Toledo Edison Co 79/08/07 11pp

S Reportable occurrences, LERs & related correspondence

7908230499 Forwards LER 77-016/01T-0.
EVANS, J Toledo Edisun Co 77/10/07 1p

--7908230507 LER 77-016/01T-0 on 770924 half trip of steam & feedwater rupture control sys resulted in opening of pressurizer power relief valve. Possibly caused by loose connections at terminal boards.
STALTER, L C Toledo Edison Co 77/10/07 4pp

7908070491 Forwards LER 79-070/03L-0.
MURRAY, T D Toledo Edison Co 79/08/01 1p

--7908070496 LER 79-070/03L-0 on 790705 1/2 trip occurred on Channels 1 & 3 of steam & feedwater rupture control sys. Caused by failure of +24 volt dc power supply PS02 in steam generator level instrumentation cabinet Channel 1.
HITCHENS, D C Toledo Edison Co 79/08/01 2pp

7908070688 Forwards LER 79-071/03L-0.
MURRAY, T D Toledo Edison Co 79/08/01 2pp

--7908070692 LER 79-071/03L-0 on 790704 while performing valve lineup for auxiliary feedwater sys test ST 5071.04, valve AF 3870 was discovered to lack position indication at control room switch. Caused by short in motor winding or single phasing.
NAYLOR, R W Toledo Edison Co 79/08/01 1p

7908060435 Forwards LER 79-075/03L-0.
MURRAY, T D Toledo Edison Co 79/08/02 2pp

--7908060439 LER 79-075/03L-0 on 790708 no visible oil level in outboard bearing oil reservoir sight glass on Containment Spray Pump 1-2. Caused by component failure. Oil added to reservoir & fittings tightened.
HARTIGAN, J P Toledo Edison Co 79/08/02 2pp

7908060447 Forwards LER 79-072/03L-0.
MURRAY, T D Toledo Edison Co 79/08/02 1p

--7908060450 LER 79-072/03L-0 on 790708 position indication on rod two of group eight was inoperable. Caused by component failure of reed switch within position indicator tube. Part was replaced & returned to svc.
NAYLOR, R W Toledo Edison Co 79/08/02 2pp

7908060453 Forwards LER 79-073/03L-0.
MURRAY, T D Toledo Edison Co 79/08/02 1p

--7908060455 LER 79-073/03L-0 on 790708 during checkout of valve relay, main steam inlet to auxiliary feed pipe turbine 1-1 isolation valve torqued while opening. Caused by normal valve wear. Valve was readjusted & returned to svc.
O'NEILL, J J Toledo Edison Co 79/08/02 2pp

7908100496 Forwards LER 79-074/03L-0.
MURRAY, T D Toledo Edison Co 79/08/02 1p

--7908100501 LER 79-074/03L-0 on 790707 auxiliary feedwater pump 1-2 suction-before-strainer pressure switch PSL-4929B actuated at pressure input outside allowable tolerance. Caused by component failure due to misapplication. Switch replaced.
HITCHENS, D C Toledo Edison Co 79/08/02 1p

7908100403 Forwards LER 79-077/03L-0.
MURRAY, T D Toledo Edison Co 79/08/03 1p

--7908100406 LER 79-077/03L-0 on 790705 auxiliary feedwater pump turbine 1-1 steam inlet valve MS-106 would not close on simulated low turbine inlet pressure signal. Caused by component failure components replaced.
JOHNSON, J J Toledo Edison Co 79/08/03 3pp

7908100462 Forwards LER 79-076/03L-0.
MURRAY, T D Toledo Edison Co 79/08/03 1p

--7908100467 LER 79-076/03L-0 on 790708 reading of core flood tank level indicator LI-CF3B2 did not appear to read same as indicator LI-CF3B1. Caused by faulty amplifier in level transmitter LT-CF3B2. Amplifier replaced & transmitter recalibr
BORYSIAK, M Toledo Edison Co 79/08/03 2pp

7908090568 Forwards LER 79-078/03L-0.
MURRAY, T D Toledo Edison Co 79/08/06 1p

--7908090573 LER 79-078/03L-0 on 790710 indication of source range neutron detector NI-1 failed low twice. Cause due to undetermined component failure in both cases. Unit tested to verify operability.
DEAKYNE, K Toledo Edison Co 79/08/06 2pp

7908230495 RO re possible failure of containment air cooler svc water outlet valves to meet response time requirements of Tech Specs. Discovered during review of Facility Change Request 79-259. Setpoints modified.
MURRAY, T D Toledo Edison Co 79/08/05 1p

7908140793 Forwards LER 79-079/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/08/09. 1p.

--7908140797 LER 79-079/03L-0 on 790712 while repositioning Group B, absolute position indication for Rod 4 shifted from 25% to 0% position. Caused by oxide film buildup on reed switch contacts. Corrective maint performed.
NAYLOR, R. W. Toledo Edison Co. 79/08/09. 2pp.

7908150502 Forwards LER 79-080/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/08/10. 1p.

--7908150504 LER 79-080/03L-0 on 790716 safety features actuation sys containment radiation detector RE 2005 spiked & tripped Channel 2 containment radiation bistable. Caused by component failure. Detector will be relocated outside containment.
ELDRED, D. T. Toledo Edison Co. 79/08/10. 2pp.

7908210459 Forwards LER 79-081/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/08/13. 1p.

--7908210460 LER 79-081/03L-0 on 790717 post-accident containment radiation monitor RE 5029 out of svc due to pump failure. Caused by loss of lubrication to pump bearings. Improved pump bearings will be installed.
ADAMS, J. Toledo Edison Co. 79/08/13. 2pp.

7908210433 Forwards LER 79-082/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/08/16. 1p.

--7908210439 LER 79-082/03L-0 on 790720 discovered that containment post-accident radiation monitor RE 5030 had tripped. Caused by sufficient pump wear resulting in low flow setpoint being reached. Pump bypass valve adjusted.
ADAMS, J. D. Toledo Edison Co. 79/08/16. 2pp.

7908210444 Forwards LER 79-083/03L-0.
MURRAY, J. D. Toledo Edison Co. 79/08/16. 1p.

--7908210448 LER 79-083/03L-0 on 790720 while verifying relative position indication for Group 5, Rod 4, discovered that Rod 6 of Group 5 showed 50% withdrawn on absolute position indication. Caused by oxide buildup on tube reed switches.
NAYLOR, R. W. Toledo Edison Co. 79/08/16. 3pp.

7908230387 Forwards LER 79-084/01T-0.
MURRAY, T. D. Toledo Edison Co. 79/08/17. 1p.

--7908230390 LER 79-084/01T-0 on 790806 containment air coolers svc outlet valves, automatically regulated by inlet air temp, failed to meet response time. Caused by design error in actuator air opening size. Valves will be redesigned.
RUDOLPH, J. P. Toledo Edison Co. 79/08/17. 2pp.

7908230523 Forwards LER 79-085/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/08/17. 1p.

--7908230529 LER 79-085/03L-0 on 790722 containment post-accident radiation monitor declared inoperable. Caused by component failure. Pump replaced w/rebuilt pump, surveillance tested & declared operable.
JENSEN, C. E. Toledo Edison Co. 79/08/17. 3pp.

7908280716 Forwards LER 79-086/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/08/21. 1p.

--7908280721 LER 79-086/03L-0 on 790725 while performing routine preventative maint, condensing unit train 2 of control room emergency ventilation sys would not start. Caused by failure of thermistor in compressor motor winding.
RUDOLPH, J. P. Toledo Edison Co. 79/08/21. 2pp.

7908310423 Forwards LER 79-002/03L-1.
MURRAY, T. D. Toledo Edison Co. 79/08/22. 1p.

--7908310425 LER 79-002/03L-1 on 790102 main steam valves 106 & 106A failed to open, resulting in auxiliary feed pump AFP 1-1 being taken out of operation. Caused by dirt buildup on valve stems as result of new const.
O'NEILL, J. J. Toledo Edison Co. 79/01/29. 1p.

DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

7908200327 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
CLAYTON, F. L. Alabama Power Co. 79/08/16. 1p.

H. General correspondence

7908020466 Notifies that util has been granted 2-wk extension for evaluation of mgt & technical resources.
CLAYTON, F. L. Alabama Power Co. 79/07/25. 1p.

7908160424 Responds to NRC request for addl info re mgt & technical resources available to respond to unusual events.
CLAYTON, F. L. Alabama Power Co. 79/08/10. 100pp.

P. Operating license stage documents & correspondence

7908030156 Forwards request for addl info re design, fabrication history & insp & operating history of PWR feedwater lines.
STELLO, V. Division of Operating Reactors. 79/05/25. 3pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908280785 Notifies of application of QA program to radwaste transportation activities per 10CFR71.51. Util has delegated development of QA program re radwaste shipment activities performed by contractor Chem Nuclear Inc.
CLAYTON, F. L. Alabama Power Co. 79/06/22. 1p.

7908020155 Forwards complete copy of Amend 11 to License NPF-2. Page 3 was omitted in NRC 790413 submittal due to collating error.
SCHWENCER, A. Operating Reactors Branch 1. 79/06/25. 2pp.

--7908020161 Amend 11 to License NPF-2.
SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 79/04/13. 3pp.

7908100589 Discusses program to upgrade bases section of STS. Amends resulting from upgrading program will be fee-exempt.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/09. 2pp.

7908280780 Submits info in response to 790705 ltr. Util QA program is located in Section 17.2 of FSAR & applied to radioactive waste transportation activities in accordance w/10CFR71.51.
CLAYTON, F. L. Alabama Power Co. 79/07/16. 1p.

7908080070 Forwards NUREG-0472, Revision 2, "Draft Radiological Effluent Tech Specs for PWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908070300 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19. 2pp.

7908170232 Notification of 790731 meeting w/util in Bethesda, MD to discuss purge & vent valve designs, operating requirements & associated electrical override circuitry designs.
REEVES, E. Operating Reactors Branch 1. 79/07/20. 2pp.

7908010380 Forwards response to 790525 request for info re PWR feedwater lines.
CLAYTON, F. L. Alabama Power Co. 79/07/24. 4pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908020429 Submits Class III fee required by NRC for inservice testing program review.
CLAYTON, F. L. Alabama Power Co. 79/07/27. 1p.

7908130232 Summary of 790530 meeting w/owners of Westinghouse-designed operating PWRs in Bethesda, MD re util responses to TMI-related IE bulletins which apply to Westinghouse-designed plants.
O'REILLY, J. P. Standardization Branch. 79/07/30. 64pp.

7908220540 Safety evaluation supporting Amend 13 to License NPF-2.
* Operating Reactors Branch 1. 79/07/31. 7pp.

7908220531 Forwards Amend 13 to License NPF-2, safety evaluation & notice of issuance & availability.
SCHWENCER, A. Operating Reactors Branch 1. 79/07/31. 2pp.

--7908220536 Amend 13 to License NPF-2, limiting conditions for operation & surveillance requirements of containment sys, ECCS & reactivity control sys.
SCHWENCER, A. Operating Reactors Branch 1 79/07/31 83pp

--7908220542 Notice of issuance & availability of Amend 13 to License NPF-2.
SCHWENCER, A. Operating Reactors Branch 1 79/07/31 2pp

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors 79/08/03 53pp

7908140569 Commits to maintain 48-inch containment purge valves in closed position in Modes 1-4 until demonstration that valves will meet functional requirements during accident conditions.
CLAYTON, F. L. Alabama Power Co. 79/08/07 1p

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects 79/08/09 56pp

Q. Inspection reports, IE Bulletins & correspondence

7908230309 Forwards response to IE Bulletin 79-02, "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts." Testing, verification, design review & repair program initiated to ensure adequacy of installation.
CLAYTON, F. L. Alabama Power Co. 79/06/06 29pp

7908090371 Forwards summary of 790522 meeting w/util in Atlanta, GA to discuss response to IE Bulletin 79-02 re anchor bolts. Significant number of anchor bolts will have to be replaced to meet Seismic Category I requirements to operate reactor.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/19 2pp

7908170226 Forwards IE Insp Rept 50-348/79-19 on 790508-10. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Office of the Director 79/06/19 2pp

--7908170234 IE Insp Rept 50-348/79-19 on 790508-10. No noncompliance noted. Major areas inspected: pipe support & restraint sys.
BROOKS, E. H. Region 2, Atlanta, Office of the Director. BURNETT, P. T. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/15 4pp

7908020389 Forwards responses to Items 2, 3, 6, 7, 8 & 12 from NRC 7?0607 "Evaluation of Licensees' Responses to IE Bulletins 79-06A & 79-06A, Revision 1."
CLAYTON, F. L. Alabama Power Co. 79/06/22 3pp

7908170195 Forwards IE Insp Rept 50-348/79-23 on 790604-08. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/22 2pp

--7908170202 IE Insp Rept 50-348/79-23 on 790604-08. No noncompliance noted. Major areas inspected: licensee actions taken in response to IE Bulletins 79-06, 06A & 06A, Revision 1 & plant operations.
HARDIN, A. R., BELISLE, G. A. Region 2, Atlanta, Office of the Director. VERDERY, E. H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/21 9pp

7908230677 Forwards IE Insp Rept 50-348/79-22 on 790604-05. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25 2pp

--7908230683 IE Insp Rept 50-348/79-22 on 790604-05. No noncompliance noted. Major areas inspected: licensed operators requalification training program, nonlicensed personnel training & licensee response to IE Bulletin 79-06A.
TAYLOR, P. A., FORD, E. J., RUHLMAN, W. A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25 4pp

7908240361 Forwards IE Insp Rept 50-348/79-24 & 50-364/79-09 on 790611-13. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/02 2pp

--7908240366 IE Insp Rept 50-348/79-24 & 50-364/79-09 on 790611-13. No noncompliance noted. Major areas inspected: steam generator feedwater nozzle & pipe welds & preservice insp procedures & activities.
CROWLEY, B. R. Region 2, Atlanta, Office of the Director. HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/29 7pp

7908010024 Forwards IE Info Notice 79-18, "Skylab Reentry." No actior required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/06 2pp

7908230682 Forwards IE Insp Rept 50-348/79-25 on 790620-22. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/06 2pp

--7908230684 IE Insp Rept 50-348/79-25 on 790620-22. No noncompliance noted. Major areas inspected: concrete expansion anchor testing procedures, work activities & records.
ANG, W. P. Region 2, Atlanta, Office of the Director. HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/05 3pp

7908080240 Responds to IE Bulletins 78-12, 12A & 12B. Principal vessel manufacturer was C-E. Info re Type, form, identifying heat & lot numbers & manufacturer of welding matls can be found in Section 5 of C-E generic response to NRC.
CLAYTON, F. L. Alabama Power Co. 79/07/09 4pp

7908030104 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/13 2pp

7908070817 Responds to IE Bulletin 79-13, Question 5, re detection of feedwater leaks inside containment. Discusses review of operating & emergency procedures for detection of feedwater line breaks. Final rept will be completed by 790720.
CLAYTON, F. L. Alabama Power Co. 79/07/16 2pp

7908010399 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17 2pp

7908030507 Responds to IE Bulletin 79-15, "Deep Draft Pump Deficiencies." No deep draft pumps in use at facility.
CLAYTON, F. L. Alabama Power Co. 79/07/18 1p

7908130062 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp

7908130091 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19 2pp

7908160470 Ack receipt of 790706 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-348/79-21.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/19 2pp

--7908160476 Responds to NRC 790615 ltr re violations noted in IE Insp Rept 50-348/79-21. Corrective actions, shop work orders will be reviewed re design changes & radiation signs will be posted.
CLAYTON, F. L. Alabama Power Co. 79/07/06 3pp

--7908160480 Forwards IE Insp Rept 50-348/79-21 on 790521-25 & notice of violation.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/15 2pp

--7908160483 Notice of violation from insp on 790521-25.
* Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/15 1p

--7908160487 IE Insp Rept 50-348/79-21. Noncompliance noted: inadequate posting of radiation area & failure to comply w/health physics procedures.
JENKINS, G. R. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. MILLSAP, W. J., TROUP, G. L. Region 2, Atlanta, Office of the Director. 79/06/15 8pp

7908080642 Forwards IE Bulletins 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/26. 2pp.

7908080702 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/26. 2pp.

7908080735 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/26. 2pp.

7908230664 Responds to IE Bulletin 79-13, Item 6 re radiographic & visual examination of feedwater sys. Tests on nozzle-to-pipe welds, feedwater pipe welds & 46 welds inside containment completed 790712. Welds acceptable.
CLAYTON, F.L. Alabama Power Co. 79/07/26. 3pp.

7908160197 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/27. 2pp.

7908220619 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action requested.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/07. 3pp.

7908170007 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/08. 2pp.

7908290178 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/10. 2pp.

7908280409 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." Action required.
GRIER, B.H. Region 2, Atlanta, Office of the Director. 79/08/13. 1p.

R Periodic operating reports & related correspondence

7908140543 Forwards monthly operating rept for Jul 1979.
CLAYTON, F.L. Alabama Power Co. 79/08/09. 1p.

--7908140546 Monthly operating rept for Jul 1979.
HAIRSTON, W.G. Alabama Power Co. 79/08/01. 4pp.

S Reportable occurrences, LERs & related correspondence

7908100029 Confirms 790608 telcon to Moseley re potential safety hazard due to deficiency identified in procedure to check performance characteristics of Barton Lot 1 transmitters. List of affected plants encl. None in operation.
ANDERSON, T.M. Westinghouse Electric Corp. 79/06/11. 4pp.

7908010543 Forwards LERs 79-026/03L-0 & 79-028/03L-0.
CLAYTON, F.L. Alabama Power Co. 79/07/26. 1p.

--7908010517 LER 79-026/03L-0 on 790716 total of 135 hydraulic snubbers did not meet surveillance test requirements. Caused by loss of oil due to seal leakage & failure to meet lockup & bleed acceptance criteria. Snubbers repaired & tested.
HAIRSTON, W.G. Alabama Power Co. 79/07/26. 3pp.

--7908010550 LER 79-028/03L-0 on 790627, radiation monitor R-5 declared inoperable due to loss of power. Feedbreaker found open. Cause unknown. Breaker closed & R-5 declared operable.
HARISTON, W.G. Alabama Power Co. 79/07/26. 1p.

7908070485 Forwards LER 79-031/03L-0.
CLAYTON, F.L. Alabama Power Co. 79/08/03. 1p.

--7908070492 LER 79-031/03L-0 on 790717 two control power fuses blew in N31 source range drawer & were causing loss of power in both source range channels. Caused by personnel error.
HAIRSTUN, W.G. Alabama Power Co. 79/08/03. 1p.

7908140733 Forwards updated LER 78-024/03L-1.
CLAYTON, F.L. Alabama Power Co. 79/08/08. 1p.

--7908140745 LER 78-024/03L-1 on 780408 while changing turbine governor valve control, load rejection of approx 170 MW resulted in momentary temp average increase. Control rods automatically initiated & average reduced.
HAIRSTON, W.G. Alabama Power Co. 79/08/08. 3pp.

7908140662 Forwards LER 79-029/03L-0.
CLAYTON, F.L. Alabama Power Co. 79/08/09. 1p.

--7908140673 LER 79-029/03L-0 on 790713 penetration room filtration sys trains A & B inoperable Caused by train B exhaust fan not starting & train A suction damper not opening. Overload reset & fuse replaced.
HAIRSTON, W.G. Alabama Power Co. 79/08/09. 3pp.

7908200311 Forwards LER 79-030/03L-0.
CLAYTON, F.L. Alabama Power Co. 79/08/14. 1p.

--7908200315 LER 79-030/03L-0 on 790717 during surveillance test, 600 volt ctr 1C supply breaker EE07 failed to load shed. Caused by open links in local control panel. Links closed & breaker verified.
HAIRSTON, W.G. Alabama Power Co. 79/08/14. 3pp.

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

7908030124 Notification of 790717-18 meeting w/representatives from Mark II owners group in Lebanon, NH to discuss Mark II pool dynamic programs.
ANDERSON, C.J. Containment Systems Branch. 79/07/03. 12pp.

7908100292 Notification of 790806-07 meeting w/util in Limerick, PA to asses status of const. Proposed agenda encl.
TIBBITTS, D.L. Light Water Reactors Branch 2. 79/07/03. 4pp.

7908130054 Notification of 790730-31 meeting w/util at site to discuss const status.
TIBBITTS, D.L. Light Water Reactors Branch 2. 79/07/03. 4pp.

F Security, medical, emergency & fire protection plans

7908290612 Responds to request re participation of NRC during radiation emergency. NRC conducts investigations, verifies implementation of emergency plans, assists DOE & provides advisory assistance to state & local agencies.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/23. 1p.

G Inspection reports, IE Bulletins & correspondence

7908130492 Forwards IE Insp Repts 50-352/79-03 & 50-353/79-03 on 790326-30. No noncompliance noted.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/06/21. 2pp.

--7908130495 IE Insp Repts 50-352/79-03 & 50-353/79-03 on 790326-30. No noncompliance noted. Major areas inspected: activities & records for safety-related equipment structures & supports & util action on previous insp findings.
MATTIA, J.C., CERNE, A., MCGAUGHY, R.W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/06/20. 15pp.

7908160576 Submits response to IE Bulletins 79-02 & 02, Revision 1. All nonconforming bolts will be replaced. Verification of bolts to be completed prior to 790731.
BOYER, V.S. Philadelphia Electric Co. 79/07/06. 6pp.

7908010521 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060489 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030268 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908200005 Responds to IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." No Westinghouse Type DB-50 & DB-75 circuit breakers in use or planned for use.
BAYER, V. S. Philadelphia Electric Co. 79/07/19 1p.

7908200297 Ack receipt of 790531 ltr forwarding fuel pool girder post-tensioning repts in response to NRC 790509 ltr. Addl info may be requested after review.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/07/20 1p.

--7908200301 Forwards two repts re fuel pool girder post-tensioning in response to NRC 790509 ltr forwarding IE Insp Rept 50-352/79-01.
BOYER, V. S. Philadelphia Electric Co. 79/05/31 120pp.

--7908200364 Requests two repts re fuel pool girder post-tesioning for review of unresolved item in IE Insp Rept 50-352/79-01.
CARLSON, R. C. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/07/09 2pp.

7908100259 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26 1p.

7908280167 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/07 1p.

7908280318 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/13 1p.

7908310294 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/14 1p.

7908300168 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/15 1p.

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908030124 Notification of 790717-18 meeting w/representatives from Mark II owners group in Lebanon, NH to discuss Mark II pool dynamic programs.
ANDERSON, C. J. Containment Systems Branch. 79/07/03 12pp.

F. Security, medical, emergency & fire protection plans

7908290612 Responds to request re participation of NRC during radiation emergency. NRC conducts investigations, verifies implementation of emergency plans, assists DOE & provides advisory assistance to state & local agencies.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/23 1p.

G. Inspection reports, IE Bulletins & correspondence

7908130492 Forwards IE Insp Repts 50-352/79-03 & 50-353/79-03 on 790326-30. No noncompliance noted.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/06/21 2pp.

--7908130495 IE Insp Repts 50-352/79-03 & 50-353/79-03 on 790326-30. No noncompliance noted. Major areas inspected, activities & records for safety-related equipment structures & supports & util action on previous insp findings.
MATTIA, J. C., CERNE, A., MCGAUGHY, R. W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/06/20. 15pp.

7908160576 Submits response to IE Bulletins 79-02 & 02, Revision 1. All nonconforming bolts will be replaced. Verification of bolts to be completed prior to 790731.
BOYER, V. S. Philadelphia Electric Co. 79/07/06 6pp.

7908010521 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17 1p.

7908060489 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18 1p.

7908030268 Notifies that written responses to IE Bulletin 79-15, Suppl 1 should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/19 1p.

7908200005 Responds to IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." No Westinghouse Type DB-50 & DB-75 circuit breakers in use or planned for use.
BAYER, V. S. Philadelphia Electric Co. 79/07/19 1p.

7908100259 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26 1p.

7908280167 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Direct 79/08/07 1p.

7908280318 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/13 1p.

7908310294 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/14 1p.

7908300168 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/15 1p.

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7906070316 Forwards SAND77-1927, "Transport of Radionuclides in Urban Environs Working Draft Assessment." SECY-78-311 & SECY-78-311A w/o encl.
BLACK, R. L. Branch 1 79/04/20 1p.

7908150762 Notifies of typographical errors in licensee joint motion for summary disposition of radon issues. Certificate of Svc encl.
SILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge. 79/06/05 9pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27 2p.

G. Adjudicatory correspondence

7905230354 Forwards documents requested in 790404 ltr re reanalyses of effects to equipment resulting from combination of seismic & LOCA loads for Mark II & III plants. W/o encl.
BLACK, R. L. Branch 1 79/04/20 1p.

H. General correspondence

7908200298 Forwards corporate capabilities re mgt & technical resource. Encl available in Central Files.
LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey. 79/08/09 1p.

G. Inspection reports, IE Bulletins & correspondence

7908030187 Responds to IE Bulletin 79-09 re GE Type AK-2 circuit breakers. No circuit breakers of type specified used for safety-related sys.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey. 79/06/19 1p.

7908170186 Responds to IE Bulletin 79-02, Revision 1, re pipe supports using concrete expansion anchor bolts. Only 24 anchor bolt designated for use in seismic piping sys. Reanalysis of base plate flexibility being performed.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey. 79/07/03 2pp.

7908090002 Responds to IE Bulletins 78-12, 12A & 12B re atypical weld matl in reactor pressure vessels. Forwards vendor verification that generic rept previously submitted pertains to plant vessels.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
79/07/06 5pp

--7908090004 Forwards weld wire data rept in response to IE Bulletins 78-12 & 12A & 790430 certification. W/o encl.
DEHLKERS, W. G. CBI Nuclear Co. 79/05/01 1p.

--7908090007 Forwards records investigation in response to IE Bulletins 78-12, 12A & 12B & supplS. No deviations detected as certified in Section 3 of rept. W/o encl.
CONN, W. C. General Electric Co. 79/04/27 4pp.

7908010524 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/17 1p.

7908060494 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/18 1p.

7908030277 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/19 1p.

7908290705 Forwards complete response to concerns raised in IE Bulletin 79-02. Pipe anchor & support base plates using expansion anchor bolts will be analyzed re plate flexibility, bolt stiffness & proper bolt spacing.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
79/07/20 5pp.

7908230112 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breakers for engineered safety sys. No Westinghouse Type DB-50 or DB-75 circuit breakers are used in safety-related sys.
MARETIN, J. J. Public Service Electric & Gas Co. of New Jersey
79/07/25 1p.

7908100273 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/26 1p.

7908280178 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/07 1p.

7908280329 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/13 1p.

7908310315 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/14 1p.

7908300182 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/15 1p.

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7906070316 Forwards SAND77-1927, "Transport of Radionuclides in Urban Environs Working Draft Assessment," SECY-78-311 & SECY-78-311A. W/o encl.
BLACK, R. L. Branch 1 79/04/20 1p.

7908150762 Notifies of typographical errors in licensee joint motion for summary disposition of radon issues. Certificate of Svc encl.
SILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge 79/06/05 9pp.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. E. Plant Systems Branch 79/06/27 2p.

F. Security, medical, emergency & fire protection plans

7908220005 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
UHRIG, R. E. Florida Power & Light Co. 79/08/17 1p.

G. Adjudicatory correspondence

7905230354 Forwards documents requested in 790404 ltr re reanalyses of effects to equipment resulting from combination of seismic & LOCA loads for Mark II & III plants. W/o encl.
BLACK, R. L. Branch 1 79/04/20 1p.

H. General correspondence

7908220390 Forwards Revision 2 to facility steam generator repair rept. W/o encl.
BARTH, C. A. Branch 3 79/07/03 1p.

7908200298 Forwards corporate capabilities re mat & technical resource. Encl available in central files.
LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey
79/08/09 1p.

G. Inspection reports, IE Bulletins & correspondence

7908030187 Responds to IE Bulletin 79-09 re GE Type AK-2 circuit breakers. No circuit breakers of type specified used for safety-related sys.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
79/06/19 1p.

7908170186 Responds to IE Bulletin 79-02, Revision 1, re pipe supports using concrete expansion anchor bolts. Only 24 anchor bolt designated for use in seismic piping sys. Reanalysis of base plate flexibility being performed.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
79/07/03 2pp.

7908090002 Responds to IE Bulletins 78-12, 12A & 12B re atypical weld matl in reactor pressure vessels. Forwards vendor verification that generic rept previously submitted pertains to plant vessels.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
79/07/06 5pp.

7908010524 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/17 1p.

7908060494 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/18 1p.

7908030277 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/19 1p.

7908290705 Forwards complete response to concerns raised in IE Bulletin 79-02. Pipe anchor & support base plates using expansion anchor bolts will be analyzed re plate flexibility, bolt stiffness & proper bolt spacing.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
79/07/20 5pp.

7908230112 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breakers for engineered safety sys. No Westinghouse Type DB-50 or DB-75 circuit breakers are used in safety-related sys.
MARETIN, J. J. Public Service Electric & Gas Co. of New Jersey
79/07/25 1p.

7908100273 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/07/26 1p.

7908280178 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/07 1p.

7908280329 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/08/13 1p.

7908310315 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300182 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

DOCKET 50-356 UNIV. OF ILLINOIS LANCRA RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

7908010353 Forwards IE Insp Repts 50-151/79-01 & 50-346/79-01 on 790604-05. Details & notice of violation withheld (ref 10CFR2.790).
HIND, J.A. Region 3, Chicago, Safeguards Branch. 79/06/20. 2pp.

--7908010356 IE Insp Repts 50-151/79-01 & 50-356/79-01 on 790604-05. Noncompliance noted: surveillance. Details withheld (ref 10CFR2.790).
HOWELL, J.C., SCHEFFER, J.C. Region 3, Chicago, Office of the Director. HIND, J.A. Region 3, Chicago, Safeguards Branch. 79/06/14. 1p.

7908170099 Ack receipt of 790713 ltr informing NRC of steps taken to correct violation noted in IE insp rept & 790620 ltr.
HIND, J.A. Region 3, Chicago, Safeguards Branch. 79/07/25. 1p.

S. Reportable occurrences, LERs & related correspondence

7908030444 Confirms notification of special rept. During operation on 790718 circulating water sys was chlorinated by using water from protection sys. Water level in fire tanks decreased below required level. Levels returned to specs.
MANRY, M. Georgia Power Co. 79/07/19. 2pp.

DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908270287 Notification of 790724-25 meeting in Bethesda, MD w/Mark II owners group to discuss condensation oscillation testing, world test monitoring & functional capacity. Agenda encl.
ANDERSON, C.J. Containment Systems Branch. 79/07/03. 4pp.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W.F. Standardization Branch. 79/07/11. 26pp.

7908080146 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
STOLZ, J.F. Light Water Reactors Branch 1. 79/07/11. 2pp.

7908170786 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/13. 1p.

7908160520 Confirms 790626 meeting in Cincinnati, OH to discuss status of plant const & preoperational testing programs.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/16. 1p.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D.G. Division of Operating Reactors. 79/07/18. 58pp.

7908170102 Forwards request for addl info for generic rept on BWRs as discussed during 790628 meeting.
STOLZ, J.F. Light Water Reactors Branch 1. 79/07/23. 19pp.

7908080148 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J.R. Assistant Director for Site & Safeguards. 79/07/24. 2pp.

7908030303 Responds to 790605 ltr transmitting draft nonradiological ETS. Draft of environ program procedures document will be submitted for review by 790914.
FLYNN, J.D. Cincinnati Gas & Electric Co. 79/07/27. 1p.

7908160206 Notification of 790920 meeting w/util in Bethesda, MD to discuss NRC comments & util response re radiation effluent Tech Specs & process control program.
PELTIER, I.A. Light Water Reactors Branch 1. 79/08/06. 2pp.

7908160215 Notification of 790829 meeting w/util in Bethesda, MD to discuss plan for qualifying NMSS equipment to NRC requirements.
PELTIER, I.A. Light Water Reactors Branch 1. 79/08/06. 2pp.

7908210571 Submits info requested at 790524 meeting re NSSS equipment to be used at LaSalle County which is not common to equipment used at Zimmer, in order to minimize repeated effort in examining environ qualification records.
DELGEORGE, L.O. Commonwealth Edison Co. 79/08/14. 2pp.

7908230330 Forwards responses to second round questions contained in NRC 790326 ltr & Revision 60 to FSAR Diagrams encl.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/08/20. 60pp.

F. Security, medical, emergency & fire protection plans

7908090578 Advises that changes to 780728 modified amended security plan are necessary for acceptance of plan. Changes due within 30 days of receipt of ltr. Forwards list of comments. List withheld (ref 10CFR2.790).
STOLZ, J.F. Light Water Reactors Branch 1. 79/07/13. 2pp.

Q. Adjudicatory correspondence

7908020021 Cincinati Gas & Electric opposition to intervenor Miami Valley Power Project 790420 request to inspect facility on 790512 re control rod, control rod seals, cable trays & related matters. Certificate of Svc.
CONNER, T.B. Conner, Moore & Corber. 79/05/03. 10pp.

7908090342 Notifies of possibility that certain IE staff members may not subscribe to NRC position in proceeding. ASLB & parties should be informed & staff members made available for testimony at evidentiary hearing.
BECHHOEFER, C., BRIGHT, G.O. Atomic Safety and Licensing Board Panel. HOOPER, F.F. Michigan, Univ. of. 79/06/04. 1p.

7908150601 Direct testimony of T Vandel re pressure testing on doors. Affidavit of R Anderson encl.
VANDEL, T.E. Region 3, Chicago, Office of the Director. 79/06/04. 4pp.

--7908150606 Direct joint testimony in opposition to Contention 14 raised by Miami Valley Power Project alleging that cable trays were not properly welded.
VANDEL, T.E., WESCOTT, H.M. Region 3, Chicago, Office of the Director. 79/06/04. 12pp.

--7908150615 Forwards IE Insp Rept 50-358/78-21 on 780918-22 & 28-29 & notice of violation.
HEISHMAN, R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/12/20. 2pp.

--7908150619 Notice of violation from insp on 780918-22 & 28-29.
* Region 3, Chicago, Office of the Director. 79/12/21. 1p.

--7908150628 IE Insp Rept 50-358/78-21 on 780918-22 & 28-29. Noncompliance noted: control of special processes (welding).
FOSTER, J.E., VANDEL, T.E., WESCOTT, B.M. Region 3, Chicago, Office of the Director. 78/12/21. 40pp.

--7908150637 Direct testimony in opposition to Miami Valley Power Project Contentions 15 & 16 re control rod thickness & seals alleged to be inadequately mfg. Certificate of Svc & supporting documentation encl.
MAURA, F. A. Region 3, Chicago, Office of the Director 79/06/04 22pp.

7908230125 Forwards documents used to determine acceptance for 10CFR70 license to possess nuclear fuel. License & two amend encl.
BARTH, C. A. Branch 3 79/07/03 1p.

--7908230129 Notifies of Amend 2 to License SNM-1823 re authorized use of enriched U per 10CFR70.9.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727) 79/05/03 1p.

--7908230134 Recommends approval of util 790412 application for amend of License SNM-1823. License should be revised re types & capacities of fuel handling cranes for receipt & storage of fuel assemblies.
DELANEY, J. C. Fuel Process. & Fab. Branch (Pre 790727) 79/05/03 1p.

--7908230139 Notifies of Amend 1 to License SNM-1823 per 10CFR70.4 & 70.9. Revises conditions re expiration date, authorized use & leak testing.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727) 79/03/06 2pp.

--7908230144 Recommends approval of util 790202 application for amend to License SNM-1823. License should be revised to allow use of nominal 5 Ci Pu-beryllium neutron source & expiration date should be contingent upon conversion to CP.
DELANEY, J. C. Fuel Process. & Fab. Branch (Pre 790727) 79/03/06 2pp.

--7908230147 Forwards License SNM-1823 & Indemnity Agreement B-85. Indemnity Agreement not encl.
ROUSE, L. C. Fuel Process. & Fab. Branch (Pre 790727) 78/06/26 2pp.

--7908230152 License SNM-1823 authorizing receipt, possession, insp, storage & packaging of U-235 by util.
ROUSE, L. C. Fuel Process. & Fab. Branch (Pre 790727) 78/06/26 2pp.

--7908230157 Safety evaluation rept re util 780308 application & 780331 suppl re storage of fuel & accessories. Proposed activities will not endanger health & safety of public. Recommends approval.
DELANEY, J. C. Fuel Process. & Fab. Branch (Pre 790727) 78/06/26 3pp.

--7908230164 Forwards four revised pages to 780314 license application re storage of unirradiated reactor fuel & radioactive matl. Revisions concern fuel handling cranes.
FLYNN, J. D. Cincinnati Gas & Electric Co. 79/04/12 5pp.

--7908230186 Requests amend to License SNM-1823. Requests use of 5 Ci Pu-beryllium neutron source & expiration date be made contingent upon conversion to CP.
FLYNN, J. D. Cincinnati Gas & Electric Co. 79/02/02 2pp.

--7908230192 Forwards revised page to 780314 license application re storage of unirradiated reactor fuel & radioactive matl. Revision corrects typographical error.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 78/03/31 2pp.

--7908230197 Submits license application for storage of unirradiated reactor fuel & radioactive matl per 10CFR70.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 78/03/14 1p.

--7908230202 Application for receipt, possession & storage of unirradiated fuel assemblies & incore monitoring sys detectors from 780601 until issuance of OL.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 78/03/08 18pp.

--7908230205 NELIA Policy NF-249 providing liability insurance for facility.
* Nuclear Energy Liability Insurance Association. 77/12/02 1p.

7908080217 Notification of resumption of evidentiary hearing on 790807. Hearing will continue on 790808-10.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel 79/07/13 1p.

7908080226 Applicant supplemental response to City of Cincinnati motion to amend petition for intervention. Original applicant response was filed on 790604. Urges Contentions 18 & 19 be denied. Certificate of Svc encl.
WETTERHAHN, M. J. Conner, Moore & Corber. 79/07/16 6pp.

H. General correspondence

7908200052 Supports prompt licensing & operation of facility. Recommends adoption of wastee disposal methods & fuel reprocessing begun in Europe.
LITTMANN, M. F. Affiliation Unknown 79/06/29 1p.

O. Inspection reports, IE Bulletins & correspondence

7908130047 Responds to IE Bulletin 79-04. Referenced Velan valves are not used in Category I piping.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/05/29 1p.

7908070203 Forwards IE Insp Rept 50-358/79-12 on 790425-27 & notice of violation.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/11 2pp.

--7908070207 Notice of violation from insp on 790425-27.
* Region 3, Chicago, Office of the Director 79/05/30 1p.

--7908070210 IE Insp Rept 50-358/79-12 on 790425-27. Noncompliance noted: failure to properly document welding insp.
VANDEL, T. E., HUGHES, J., KNOP, R. C. Region 3, Chicago, Office of the Director 79/05/30 17pp.

7908150358 Forwards IE Insp Rept 50-358/79-15 on 790508-11 & 17-18 & notice of violation.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/11 2pp.

--7908150362 Notice of violation from insp on 790508-11 & 17-18.
* Region 3, Chicago, Office of the Director 79/06/11 5pp.

--7908[illegible]70 IE Insp Rept 50-358/79-15 on 790508-11 & 17-18. Noncompliance noted: control of special processes matl qualifications, procedural requirements & documentation.
WILLIAMS, C. C. Region 3, Chicago, Office of the Director 79/06/06 13pp.

7908080212 Forwards IE Insp Rept 50-358/79-13 on 790411-13, 18 & 26-27 & notice of violation.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/12 2pp.

--7908080220 Notice of violation from insp on 790411-13, 18 & 26-27.
* Region 3, Chicago, Office of the Director 79/06/12 2pp.

--7908080229 IE Insp Rept 50-358/79-13 on 790411-13, 18 & 26-27. Noncompliance noted: failure to translate requirements & specs, failure to have approved brazing procedure & failure to conduct audit.
FOSTER, J. E., NORELIUS, C. E., HAYES, D. W. Region 3, Chicago, Office of the Director 79/06/08 24pp.

7908230042 Forwards IE Insp Rept 50-358/79-14 on 790522-24 & notice of violation.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/25 2pp.

--7908230047 Notice of violation from insp on 790522-24.
* Region 3, Chicago, Office of the Director 79/06/20 3pp.

--7908230052 IE Insp Rept 50-358/79-14 on 790522-24. Noncompliance noted: failure to provide adequate corrective action & failure to perform audits as scheduled.
VANDEL, T. F., PHILLIPS, H. S., KNOP, R. C. Region 3, Chicago, Office of the Director 79/06/20 23pp.

7908270556 Responds to IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers For Engineered Safety Sys." Neither Westinghouse Type DB-50 or DB-75 circuit breakers are used in safety-related sys.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/07/03 1p.

7908290368 Responds to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Forwards "Evaluation of Analysis Procedures for Design of Expansion Anchored Plates in Concrete" by Sargent & Lundy Engineers.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/07/06 6pp.

7908030555 Ack receipt of 790621 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/79-06.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/25 1p.

--7908030567 Responds to NRC 790516 ltr re violations noted in IE Insp Rept 50-358/79-06. Corrective actions faulty HPCS & LPCS equipment being modified & insp procedures being revised. Compliance will be achieved by 790629.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/06/21 6pp.

7908290339 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/26 1p.

7908230120 Ack receipt of 790710 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-358/79-12.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/08/03 1p.

--7908230128 Responds to NRC 790611 ltr re violation noted in IE Insp Rept 50-358/79-12. Corrective actions delinquent records re insp documentation on pipe whip restraint welding have been stamped to reflect QC requirements.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/07/13 2pp.

7908150336 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/07 1p.

7908300267 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/15 1p.

S. Reportable occurrences, LERs & related correspondence

7908160526 Ack receipt of 790620 interim rept re svc water intake structure silting.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/13 1p.

T. Hearing transcripts on non-antitrust matters

7908140141 Transcript of 790807 hearing in Cincinnati, OH. Pp. 2,222-2,427.
BECHHOEFER, C., HOOPER, F. F., BRIGHT, G. O. Atomic Safety and Licensing Board Panel 79/08/07 205pp.

7908150026 Transcript of 790808 hearing in Cincinnati, OH. Pp. 2,428-2,712.
BECHHOEFER, C., HOOPER, F. F., BRIGHT, G. O. Atomic Safety and Licensing Board Panel 79/08/08 288pp.

7908150727 Transcript of 790809 hearing in Cincinnati, OH. Pp. 2,713-3,042.
BECHHOEFER, C., HOOPER, F. F., BRIGHT, G. O. Atomic Safety and Licensing Board Panel 79/08/09 339pp.

7908150725 Transcript of 790810 hearing in Cincinnati, OH. Pp. 3,043-3,149.
BECHHOEFER, C., HOOPER, F. F., BRIGHT, G. O. Atomic Safety and Licensing Board Panel 79/08/10 106pp.

U. Congressional/Executive Correspondence

7908010089 Responds to 790521 ltr re constituent concerns about plant. Forwards "Summary of Investigations" re acceptability of components purchased by util & welding on cable trays.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/11 4pp.

7908210056 Forwards TP Martin 790428 affidavit & DL Wojtanowski 790604 forwarding ltr re potentially defective control rods at facility. Requests prompt NRC review & response.
GLENN, J. Senate Governmental Affairs 79/06/28 6pp.

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908170384 Forwards slides presented at NRC 790426 meeting re fuel structural design, in response to 790522 request. Info partially withheld (ref 10CFR2.790).
* Southern California Edison Co. 79/06/28 19pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

7908030117 Notification of 790709 meeting w/util in Bethesda, MD to discuss inclusion of Cities of Anaheim, CA & Riverside, CA as applicants for plants.
ROOD, H. Light Water Reactors Branch 2 79/07/02 4pp.

7908070663 Forwards addendum rept to "Cultural Resources & High Voltage Transmission Line from San Onofre to Santiago Substation & Black Star Canyon." W/o encl.
THIERER, I. Affiliation Unknown 79/07/06 1p.

7908100046 Notification of 790712-13 meeting w/util in Bethesda, MD to complete seismic/structural auvit of reactors.
BAER, R. L. Light Water Reactors Branch 2 79/07/06 3pp.

7908070742 Notification of 790724-26 meeting w/util in San Clemente, CA to discuss fire protection issues & tour facility.
ROOD, H. Light Water Reactors Branch 2 79/07/17 4pp.

7908160198 Notification of 790810 meeting w/util in Bethesda, Md to discuss dewatering well demobilization.
ROOD, H. Light Water Reactors Branch 2 79/07/31 3pp.

7908300304 Approves 790529 request for withholding submitted info re effects of fuel design mods on critical heat flux (ref 10CFR2.790).
BAER, R. L. Light Water Reactors Branch 2 79/08/07 2pp.

7908170434 Forwards "Summary Rept of Investigation/Demobilization of Const Dewatering Wells," prepared by Woodward-Clyde Consultants to facilitate NRC review.
BASKIN, V. P. Southern California Edison Co. 79/08/15 1p.

--7908170438 "Summary Rept of Investigation/Demobilization of Const Dewatering Wells," prepared for Southern CA Edison.
* Woodward-Clyde Consultants 79/07/31 400pp.

F. Security, medical, emergency & fire protection plans

7908130206 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp.

7908290474 Remits license amend fee for safeguards contingency plan submitted on 790323.
BASKIN, K. P. Southern California Edison Co. 79/08/22 3pp.

G. Adjudicatory correspondence

7908150017 Petitions NRC to deny OL for facility. Original licensing relied on WASH-1400. Repudiation of rept places facility safety in doubt. Expresses concern re proximity of active faults & waste disposal problem.
LEWIS, N., SANDS, F., CHANDLER, L. J. Affiliation Unknown 79/06/24 1p.

7908150004 Notifies that NRC will not respond to applicant 790619 response & objections to document requests from intervenors Friends of the Earth. Matter relates solely to discovery between intervenors & applicants.
CHANDLER, L. J. Branch 1 79/06/29 1p.

7908220374 Petition requesting NRC deny OLs due to unworkable evacuation plans & plant proximity to active earthquake fault.
SCHACK, S., MILLER, B. L., ADAMS, J. T. Affiliation Unknown 79/07/02 3pp.

H. General correspondence

7908300604 Responds to 790513 request for info re emergency planning at facilities. Will forward 1979 SER for facilities. Remaining questions will be answered during hearings.
CHANDLER, L. J. Branch 1 79/07/02 1p.

7908130405 Notifies of retirement effective 790831. A Arenal will assume all responsibilities during Aug.
MOORE, J. B. Southern California Edison Co. 79/08/06. 1p.

M. Antitrust correspondence

7908200021 Forwards "Info Requested by Atty General for Antitrust Review," submitted by Southern CA Edison Co on behalf of Cities of Anaheim & Riverside, CA. Discusses proposed transfer of ownership.
SHAPAR, H. K. Office of the Executive Legal Director. 79/08/03. 1p.

7908270543 Forwards documents re application to transfer Southern CA Edison Co ownership interest to Cities of Anaheim & Riverside, CA. Requests comments for antitrust review. W/o encl.
SHAPAR, H. K. Office of the Executive Legal Director. 79/08/03. 1p.

7908160358 Responds to NRC 790511 request for antitrust review info. Forwards util opening brief of E-7777 proceeding for San Onofre 2 & 3.
BARRY, D. N. Southern California Edison Co. 79/08/10. 10pp.

O. Inspection reports, IE Bulletins & correspondence

7908070739 Responds to IE Bulletin 79-09. GE Type AK-2 breakers used in reactor trip switchgear. Design change will be implemented to replace switchgear so breakers will not be used.
BASKIN, K. P. Southern California Edison Co. 79/06/13. 2pp.

7908280433 Describes status of efforts to provide vessel weld matl info requested by IE Bulletins 78-12, 12A & 12B. Generic rept from C-E certifies matl not in use at plants.
BASKIN, K. P. Southern California Edison Co. 79/06/18. 1p.

7908090697 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-361/79-08.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/26. 1p.

--7908090699 Responds to NRC 790502 ltr re violations noted in IE Insp Rept 50-361/79-08. Corrective actions: hanger inspectors all retrained in reading drawings & weld acceptance criteria. QA surveillance of pipe support process increased.
MOORE, J. B. Southern California Edison Co. 79/05/23. 4pp.

--7908090700 Forwards IE Insp Rept 50-361/79-08 on 790306-09 & notice of violation.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/05/02. 2pp.

--7908090702 Notice of violation from insp on 790306-09.
*** Region 5, San Francisco, Office of the Director. 79/05/02. 1p.

--7908090703 IE Insp Rept 50-361/79-08 on 790306-08. Noncompliance noted: failure to install pipe support in accordance with drawings.
ECKHARDT, J. H. ; HERNANDEZ, G. Region 5, San Francisco, Office of the Director. HAYNES, R. C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/05/02. 4pp.

7908150235 Forwards IE Insp Repts 50-361/79-15 & 50-362/79-15 on 790529-0601. No noncompliance noted.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/26. 2pp.

--7908150251 IE Insp Rept 50-361/79-15 & 50-362/79-15 on 790529-0601. No noncompliance noted. Major areas inspected: const activities involving license actions on previous insp findings, preservice insp, instrumentation & safety-related pipe welds.
ECKHARDT, J. H. ; HAIST, D. P. Region 5, San Francisco, Office of the Director. DODDS, R. T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/25. 6pp.

7908150178 Forwards IE Insp Repts 50-361/79-14 & 50-362/79-14 on 790529-31. No noncompliance noted.
CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/06/29. 2pp.

--7908150196 IE Insp Repts 50-361/79-14 & 50-362/79-14 on 790529-31. No noncompliance noted. Major areas inspected: preoperational test program, administrative controls on maint, operational staffing, plant procedures & independent insp effort.
CANTER, H. L. ; FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/06/27. 4pp.

7908170107 Forwards IE Insp Repts 50-361/79-17 & 50-362/79-17 on 790501-0601. No noncompliance noted.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/07/06. 2pp.

--7908170114 IE Insp Repts 50-361/79-17 & 50-362/79-17 on 790501-0601. No noncompliance noted. Major areas inspected: piping storage welding, reactor pressure vessel & internals installation & protection & general work in progress.
PATE, R. J. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. DODDS, R. T. Region 5, San Francisco, Office of the Director. 79/07/03. 5pp.

7908150304 Ack receipt of 790702 ltr informing NRC of steps taken to correct violations noted in IE insp rept.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/07/12. 1p.

--7908150311 Responds to NRC 790427 ltr re violations noted in IE insp rept. Corrective actions: periodic QA surveillance of post-weld heat treatment temp recorder will be performed.
MOORE, J. B. Southern California Edison Co. 79/07/02. 2pp.

7908010392 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908020500 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908020408 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/19. 1p.

7908210150 Summary of 790711 meeting w/GA Conservancy in Atlanta, GA re licensing process, insp program & TMI accident. Forwards 790510 rept "Population Dose & Health Impact of Accident at TMI" & NUREG-0396. W/o encl.
O'REILLY, J. P. Region 3, Chicago, Office of the Director. 79/07/20. 3pp.

7908060071 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908060157 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210485 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908170038 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10. 1p.

7908280388 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310155 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300245 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908020532 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020030 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908010577 Forwards suppl to final deficiency rept re undersized safety-related heating, ventilation & air conditioning damper actuators.
MOORE, J. B. Southern California Edison Co. 79/07/27. 1p.

--7908010585 Suppl to final deficiency rept re undersized safety-related heating, ventilation & air conditioning damper actuators. Caused by inadequate communication of engineering & design info/criteria between contractor & subcontractors.
* Southern California Edison Co. 79/07/27. 3pp.

7908130467 Amends 790409 final deficiency rept re staking of limitorque valve operators. Correct number of valves is 248, not 96 as initially reported. Insp required on proper staking of lock nuts.
MOORE, J. B. Southern California Edison Co. 79/08/06. 2pp.

7908300749 Ack receipt of 790727 ltr & supplemental rept on undersized safety-related heating, ventilation & air conditioning damper actuators.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/06. 1p.

7908160427 Forwards interim deficiency rept re small break LOCA analysis conducted by C-E. Final rept to be forwarded by 791112.
ARENAL, A. Southern California Edison Co. 79/08/10. 1p.

--7908160432 Interim deficiency rept re small break LOCA analysis. Evaluation indicates peak fuel cladding temp exceeds acceptance criteria of 10CFR50.46. Investigation continuing. Will submit final rept by 791112.
* Southern California Edison Co. 79/08/.? 3pp.

DOCKET 50-3[illegible] SAN ONOFRE NUCLEA[illegible] STATION, UNIT 3

A. Application/construction stage documents & correspondence

7908170384 Forwards slides presented at NRC 790426 meeting re fuel structural design, in response to 790522 request. Info partially withheld (ref 10CFR2.790).
* Southern California Edison Co. 79/06/29. 19pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908030117 Notification of 790709 meeting w/util in Bethesda MD to discuss inclusion of Cities of Anaheim, CA & Riverside, CA as applicants for plants.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 4pp.

7908070663 Forwards addendum to rept to "Cultural Resources & High Voltage Transmission Line from San Onofre to Santiago Substation & Black Star Canyon." W/o encl.
THIERER, T. Affiliation Unknown. 79/07/06. 1p.

7908100046 Notification of 790712-13 meeting w/util in Bethesda, MD to complete seismic/structural audit of reactors.
BAER, R. L. Light Water Reactors Branch 2. 79/07/06. 3pp.

7908070742 Notification of 790724-26 meeting w/util in San Clemente, CA to discuss fire protection issues & tour facility.
ROOD, H. Light Water Reactors Branch 2. 79/07/17. 4pp.

7908160198 Notification of 790810 meeting w/util in Bethesda, Md to discuss dewatering cell demobilization.
ROOD, H. Light Water Reactors Branch 2. 79/07/31. 3pp.

7908300304 Approves 790529 request for withholding submitted info re effects of fuel design mods on critical heat flux (ref 10CFR2.790).
BAER, R. L. Light Water Reactors Branch 2. 79/08/07. 2pp.

7908170434 Forwards "Summary Rept of Investigation/Demobilization of Const Dewatering Wells," prepared by Woodward-Clyde Consultants to facilitate NRC review.
BASKIN, V. P. Southern California Edison Co. 79/08/15. 1p.

--7908170438 "Summary Rept of Investigation/Demobilization of Const Dewatering Wells," prepared for Southern CA Edison.
* Woodward-Cly[illegible] Consultants. 79/07/31. 400pp.

F. Security, medical, emergency & fire protection plans

7908130206 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908290474 Remits license amend fee for safeguards contingency plan submitted on 790323.
BASKIN, K. P. Southern California Edison Co. 79/08/22. 3pp.

G. Adjudicatory correspondence

7908150017 Petitions NRC to deny OL for facility. Original licensing relied on WASH-1400. Repudiation of rept places facility safety in doubt. Expresses concern re proximity of active faults & waste disposal problem.
LEWIS, N. SANDS, F., CHANDLER, L. J. Affiliation Unknown. 79/06/24. 1p.

7908150004 Notifies that NRC will not respond to applicant 790619 response & objections to document requests from intervenors Friends of the Earth. Matter relates solely to discovery between intervenors & applicants.
CHANDLER, L. J. Branch 1. 79/06/29. 1p.

7908220374 Petition requesting NRC deny OLs due to unworkable evacuation plans & plant proximity to active earthquake fault.
SCHACK, S., MILLER, B. L., ADAMS, J. T. Affiliation Unknown. 79/07/02. 3pp.

H. General correspondence

7908300604 Responds to 790513 request for info re emergency planning at facilities. Will forward 1979 SER for facilities. Remaining questions will be answered during hearings.
CHANDLER, L. J. Branch 1. 79/07/02. 1p.

7908130405 Notifies of retirement effective 790831. A Arenal will assume all responsibilities during Aug.
MOORE, J. B. Southern California Edison Co. 79/08/06. 1p.

M. Antitrust correspondence

7908200021 Forwards "Info Requested by Atty General for Antitrust Review," submitted by Southern CA Edison Co on behalf of Cities of Anaheim & Riverside, CA. Discusses proposed transfer of ownership.
SHAPAR, H. K. Office of the Executive Legal Director. 79/08/03. 1p.

7908270543 Forwards documents re application to transfer Southern CA Edison Co ownership interest to Cities of Anaheim & Riverside, CA. Requests comments for antitrust review. W/o encl.
SHAPAR, H. K. Office of the Executive Legal Director. 79/08/03. 1p.

7908160358 Responds to NRC 790511 request for antitrust review info. Forwards util opening brief of E-7777 proceeding for San Onofre 2 & 3.
BARRY, D. N. Southern California Edison Co. 79/08/10. 10pp.

O. Inspection reports, IE Bulletins & correspondence

7908070739 Responds to IE Bulletin 79-09. GE Type AK-2 breakers used in reactor trip switchgear. Design change will be implemented to replace switchgear so breakers will not be used.
BASKIN, K. P. Southern California Edison Co. 79/06/13. 2pp.

7908280433 Describes status of efforts to provide vessel weld matl info requested by IE Bulletins 78-12, 12A & 12B. Generic rept from C-E certifies matl not in use at plants.
BASKIN, K. P. Southern California Edison Co. 79/06/18. 1p.

7908090697 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-361/79-08.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/26. 1p.

--7908090699 Responds to NRC 790502 ltr re violations noted in IE Insp Rept 50-361/79-08. Corrective actions: hanger inspectors all retrained in reading drawings & weld acceptance criteria. QA surveillance of pipe support process increased.
MOORE, J. B. Southern California Edison Co. 79/05/23. 4pp.

--7908090700 Forwards IE Insp Rept 50-361/79-08 on 790306-09 & notice of violation.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/05/02. 2pp.

--7908090702 Notice of violation from insp on 790306-09.
* Region 5, San Francisco, Office of the Director. 79/05/02. 1p.

--7908090703 IE Insp Rept 50-361/79-08 on 790306-08 Noncompliance noted: failure to install pipe support in accordance with drawings. ECKHARDT, J. H.; HERNANDEZ, G. Region 5, San Francisco, Office of the Director. HAYNES, R. C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/05/02. 4pp.

7908150235 Forwards IE Insp Repts 50-361/79-15 & 50-362/79-15 on 790529-0601. No noncompliance noted. SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/26. 2pp.

--7908150251 IE Insp Rept 50-361/79-15 & 50-362/79-15 on 790529-0601. No noncompliance noted. Major areas inspected: const activities involving license actions on previous insp findings, preservice insp, instrumentation & safety-related pipe welds. ECKHARDT, J. H.; HAIST, D. P. Region 5, San Francisco, Office of the Director. DODDS, R. T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/25. 6pp.

7908150178 Forwards IE Insp Repts 50-361/79-14 & 50-362/79-14 on 790529-31. No noncompliance noted. CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/06/29. 2pp.

--7908150196 IE Insp Repts 50-361/79-14 & 50-362/79-14 on 790529-31. No noncompliance noted. Major areas inspected: preoperational test program, administrative controls on maint, operational staffing, plant procedures & independent insp effort. CANTER, H. L.; FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/06/27. 4pp.

7908170107 Forwards IE Insp Repts 50-361/79-17 & 50-362/79-17 on 790501-0601. No noncompliance noted. SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/07/06. 2pp.

--7908170114 IE Insp Repts 50-361/79-17 & 50-362/79-17 on 790501-0601. No noncompliance noted. Major areas inspected: piping storage welding, reactor pressure vessel & internals installation & protection & general work in progress. PATE, R. J. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. DODDS, R. T. Region 5, San Francisco, Office of the Director. 79/07/03. 5pp.

7908150304 Ack receipt of 790702 ltr informing NRC of steps taken to correct violations noted in IE insp rept. SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/07/12. 1p.

--7908150311 Responds to NRC 790427 ltr re violations noted in IE insp rept. Corrective actions: periodic QA surveillance of post-weld heat treatment temp recorder will be performed. MOORE, J. B. Southern California Edison Co. 79/07/02. 2pp.

7908010392 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908020500 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908020408 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/19. 1p.

7908060071 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908060157 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210485 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908170038 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10. 1p.

7908280388 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required. GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310155 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300245 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908020532 Forwards PNO-79-67AW. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020030 Forwards PNO-79-67AX. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908010577 Forwards suppl to final deficiency rept re undersized safety-related heating, ventilation & air conditioning damper actuators. MOORE, J. B. Southern California Edison Co. 79/07/27. 1p.

--7908010585 Suppl to final deficiency rept re undersized safety-related heating, ventilation & air conditioning damper actuators. Caused by inadequate communication of engineering & design info/criteria between contractor & subcontractors. * Southern California Edison Co. 79/07/27. 3pp.

7908130467 Amends 790409 final deficiency rept re staking of limitorque valve operators. Correct number of valves is 248, not 96 as initially reported. Insp required on proper staking of lock nuts. MOORE, J. B. Southern California Edison Co. 79/08/06. 2pp.

7908300749 Ack receipt of 790727 ltr & supplemental rept on undersized safety-related heating, ventilation & air conditioning damper actuators. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/06. 1p.

7908160427 Forwards interim deficiency rept re small break LOCA analysis conducted by C-E. Final rept to be forwarded by 791112. ARENAL, A. Southern California Edison Co. 79/08/10. 1p.

--7908160432 Interim deficiency rept re small break LOCA analysis. Evaluation indicates peak fuel cladding temp exceeds acceptance criteria of 10CFR50.46. Investigation continuing. Will submit final rept by 791112. * Southern California Edison Co. 79/08/10. 3pp.

DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908220236 Summary of 790620 meeting w/applicant in Bethesda, MD re extension of facility CP to 850201. BENEDICT, R. A. Light Water Reactors Branch 2. 79/07/24. 4pp.

7908030503 Requests deferment of NRC action on 780831 request for extension of facility completion date. Financial effects stemming from TMI-2 incident will preclude recommencement of const. FINFROCK, I. R. Jersey Central Power & Light Co. 79/07/30. 2pp.

Q. Adjudicatory correspondence

7908220675 Ack receipt of resolution re accident prevention & safety procedures for nuclear plants. Resolution will be forwarded to IE for consideration & action & to CR Stevens for docketing. Resolution encl. SNYDER, G. L. Region 1, Philadelphia, Office of the Director. 79/06/26. 3pp.

P. Operating license stage documents & correspondence

7908300439 Notification of NRC intent to discontinue mailing info re facility. BAER, R. L. Light Water Reactors Branch 2. 79/07/02. 1p.

DOCKETED ITEMS

G. Inspection reports, IE Bulletins & correspondence

7908080489 Responds to IE Bulletin 79-03 re weld defects in 304 or 312 stainless steel pipe spools. Spools used in containment penetrations M-43 & M-44. Corrective actions: welds radiographed & defects repaired.
FINFROCK, I. R. Jersey Central Power & Light Co. 79/05/29 1p.

7908070830 Responds to IE Bulletin 79-11 re use of Westinghouse DB-50 & DB-75 circuit breakers in safety-related sys. No circuit breakers of this type have been purchased.
FINFROCK, I. R. Jersey Central Power & Light Co. 79/06/25 1p.

7908070675 Forwards C-E 790608 ltr responding to IE Bulletins 78-12, 12A & 12B re atypical weld matl in reactor pressure vessel welds.
FINFROCK, I. R. Jersey Central Power & Light Co. 79/06/29 1p.

--7908070687 Forwards C-E rept, "Info Requested by IE Bulletin 78-12, Atypical Weld Matl in Reactor Pressure Vessel Welds," & certification that all matls used in reactor vessel fabrication are discussed in rept.
SCHERER, A. E. Combustion Engineering, Inc. 79/06/08. 2pp.

7908270074 Forwards IE Insp Rept 50-363/79-05 on 790518. No noncompliance noted.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/07/02 2pp.

--7908270081 IE Insp Rept 50-363/79-05 on 790518. No noncompliance noted. Major areas inspected: organization, procedures & preparation for storage & maint of equipment, matls & structures during plant const delay.
NARROW, L. Region 1, Philadelphia, Office of the Director.
MCGAUGHY, R. W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/06/28. 3pp.

7908010427 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17 1p.

7908030372 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030242 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/19 1p.

7908100229 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26 1p.

7908130253 Responds to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys. No safety-related piping sys at plant.
FINFROCK, I. R. Jersey Central Power & Light Co. 79/07/30 1p.

7908230154 Responds to IE Bulletins 79-02 & 79-02 Revision 1, re pipe support base plate designs using concrete expansion anchor bolts. Pipe support base plate designs are not in use at plant.
FINFROCK, I. R. Jersey Central Power & Light Co. 79/07/30 1p.

7908280083 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/07 1p.

7908280276 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/13 1p.

7908310283 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/14 1p.

7908300127 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/15 1p.

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908080155 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
STOLZ, J. F. Light Water Reactors Branch 1. 79/07/11. 2pp.

7908010380 Forwards response to 790525 request for info re PWR feedwater lines.
CLAYTON, F. L. Alabama Power Co. 79/07/24. 4pp.

7908210323 Requests submission of proposed secondary water chemistry program limiting corrosion of steam generator tubes. Model license condition encl.
STOLZ, J. F. Light Water Reactors Branch 1. 79/08/02. 4pp.

F. Security, medical, emergency & fire protection plans

7908200327 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
CLAYTON, F. L. Alabama Power Co. 79/08/16. 1p.

H. General correspondence

7908020466 Notifies that util has been granted 2-wk extension for evaluation of mgt & technical resources.
CLAYTON, F. L. Alabama Power Co. 79/07/25. 1p.

G. Inspection reports, IE Bulletins & correspondence

7908230309 Forwards response to IE Bulletin 79-02, "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts." Testing, verification, design review & repair program initiated to ensure adequacy of installation.
CLAYTON, F. L. Alabama Power Co. 79/06/06. 29pp.

7908070276 Ack receipt of 790619 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-364/79-04.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/28. 2pp.

--7908070284 Responds to NRC 790410 ltr re violations noted in IE Insp Rept 50-364/79-04. Corrective actions: first jumper correctly installed, second jumper removed & training session held for startup test engineers.
CLAYTON, F. L. Alabama Power Co. 79/06/19. 2pp.

--7908070293 Forwards IE Insp Rept 50-364/79-04 on 790319-22 & notice of violation.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/10. 2pp.

--7908070297 Notice of violation from insp on 790319-22.
* Region 2, Atlanta, Office of the Director. 79/04/09. 1p.

--7908070302 IE Insp Rept 50-364/79-04. Noncompliance noted: failure to follow procedures for preoperational test witnessing.
WAGNER, A. G., MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/09. 3pp.

7908240361 Forwards IE Insp Rept 50-348/79-24 & 50-364/79-09 on 790611-13. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/02. 2pp.

--7908240366 IE Insp Rept 50-348/79-24 & 50-364/79-09 on 790611-13. No noncompliance noted. Major areas inspected: steam generator feedwater nozzle & pipe welds & preservice insp procedures & activities.
CROWLEY, B. R. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/29. 7pp.

7908080240 Responds to IE Bulletins 78-12, 12A & 12B. Principal vessel manufacturer was C-E. Info re Type, form, identifying heat & lot numbers & manufacturer of welding matls can be found in Section 5 of C-E generic response to NRC.
CLAYTON, F. L. Alabama Power Co. 79/07/09. 4pp.

7908030104 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010399 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030507 Responds to IE Bulletin 79-15, "Deep Draft Pump Deficiencies." No deep draft pumps in use at facility.
CLAYTON, F. L. Alabama Power Co. 79/07/18. 1p.

7908130062 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130091 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908070700 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actinn required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160197 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908220617 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

7908280405 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

S. Reportable occurrences, LERs & related correspondence

7908100029 Confirms 790608 telcon to Moseley re potential safety hazard due to deficiency identified in procedure to check performance characteristics of Barton Lot 1 transmitters. List of affected plants encl. None in operation.
ANDERSON, T. M. Westinghouse Electric Corp. 79/06/11. 4pp.

DOCKET 50-366 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

7908130189 Notifies that review of safeguards contingency p'an involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908270468 Forwards physical security plan for training & qualifying security personnel. Plan withheld (ref 10CFR2.790).
KELLY, R. J. Georgia Power Co. 79/08/17. 1p.

H. General correspondence

7908150679 Submits info re corporate capabilities, in response to NRC 790629 request.
KELLY, R. J. Georgia Power Co. 79/08/10. 200pp.

P. Operating license stage documents & correspondence

7908060004 Notification of 790611-12 meeting w/members of nuclear power industry in Albuquerque, NM to discuss implementation of physical security requirements for power reactors. Meeting agenda & blank registration forms encl.
MILLER, J. Assistant Director for Site & Safeguards. 79/03/22. 7pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 52pp.

7908030256 Requests status of ALL electrical staff overpressure & flooding reviews.
EISENHUT, D. G. Division of Operating Reactors. 79/06/04. 1p.

7908080047 Notification of 790629 meeting w/Mark I owners' group to discuss resolution of outstanding issues re structural acceptance criteria for Mark I containment long-term program. Proposed agenda encl.
GRIMES, C. I. Plant Systems Branch. 79/06/27. 2p.

7908020322 Confirms 790702 telcon in which NRC concurred w/planned schedule for returning reactor to svc. Concurrence based on investigation results & planned retesting program.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/05. 2pp.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908080350 Forwards NUREG-0460, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves. W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908070316 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/19. 1p.

7908300036 Request supplemental info to review 781201 submittal re proposed Tech Spec changes for settlement measurement & penetration differential settlements of Class I structures.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/20. 5pp.

7908010373 Responds to P Polk request & forwards oscillograph traces of grid voltage & current flows during 790711 Crystal River & Hatch trips.
BETSILL, J. A. Georgia Power Co. 79/07/24. 7pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908170552 Forwards Amend 10 to License NPF-5, safety evaluation & notice of issuance & availability.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/26. 2pp.

--7908170561 Amend 10 to License NPF-5, temporarily increasing limiting condition for operation on drywell average air temp from 135 F to 145 F.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/26. 5pp.

--7908170566 Safety evaluation supporting Amend 10 to License NPF-5.
* Office of Nuclear Reactor Regulation. 79/07/26. 3pp.

--7908170570 Notice of issuance & availability of Amend 10 to License NPF-5.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/07/26. 2pp.

7908030148 Forwards Amend 1 to spent fuel pool mod rept, revising pages dealing w/stress analysis results applicable to high density fuel storage modules.
KELLY, R. J. Georgia Power Co. 79/0./27. 6pp.

7908030316 Forwards proposed Tech Spec amend (DL App A) changing "hot shutdown" to "cold shutdown" for increased personnel safety during maint on inoperable torus to drywell vacuum breakers. Amend does not change mode of operation or equipment design.
KELLEY, R. J. Georgia Power Co. 79/07/27. 4pp.

7908150498 Forwards special rept re low water level in fire tanks.
MANRY, M. Georgia Power Co. 79/07/31. 1p.

--7908150500 Special rept re occurrence on 790718 water level in two fire tanks decreased to below 270,000 gallons required per Tech Specs. Caused by overpressurized & tripped well pumps. Pump pressure switch recalibr.
* Georgia Power Co. 79/07/31. 1p.

DOCKETED ITEMS

7908300355 Notifies of 790822 meeting w/util in Atlanta,GA to discuss emergency planning & implementing procedures.Agenda encl.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/06. 3pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects.
79/08/09. 56pp.

7908210430 Responds to NRC 790330 ltr.Forwards addl info re differential bldg settlement.
KELLY, R.J. Georgia Power Co. 79/08/14. 17pp.

G. Inspection reports, IE Bulletins & correspondence.

7908210562 Forwards IE Insp Rept 50-366/79-18 on 790508-10.No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/04. 2pp.

--7908210565 IE Insp Rept 50-366/79-18 on 790508-10.No noncompliance noted.Major areas inspected:concrete expansion anchor installation.
MODENOS, L., BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/31. 3pp.

7908090160 FOIA request for copies of NRC insp repts for 770301-0415 & Jan-Apr 1978 NRC bulletins & other documents re anchor bolt problems & alleged tritium leakage at plants.
REAGER, D.W. Widoff, Reager, Selkowitz & Adler. 79/06/08. 1p.

7908020361 Responds to IE Bulletin 79-11.No Westinghouse Type DB-50 or DB-75 circuit breakers have been used.
STAFFA, R.W. Georgia Power Co. 79/06/19. 1p.

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08.Requests attendance at 790628 meeting in Bethesda,MD re info needed by NRC to complete review.
IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625).
79/06/20. 44pp.

7908020251 Supplements 790416 response to IE Bulletin 79-03.Forwards summary of ultrasonic test results on 12-inch recirculation loop A jet pump risers W/o encl.
STAFFA, R.W. Georgia Power Co. 79/06/22. 1p.

7908070142 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/06/26. 2pp.

7908080570 Forwards EDS Nuclear,Inc 790419 response to IE Bulletin 79-07.None of methods described in Item 1 of bulletin were used in computer programs for seismic analysis of safety-related pipe at plant.
STAFFA, R.W. Georgia Power Co. 79/06/26. 39pp.

7908030495 Forwards examination summary records that were inadvertently omitted from util 790622 response to IE Bulletin 79-03.
STAFFA, R.W. Georgia Power Co. 79/06/27. 11pp.

7908230426 Advises that C-E rept, "Info Requested by IE Bulletin 78-12, Atypical Weld Matl in Reactor Pressure Vessel Welds," submitted to NRC on 790608,contains generic coverage of weld matl & testing programs used by licensee.
STAFFA, R.W. Georgia Power Co. 79/06/29. 1p.

7908300729 Notifies that opening paragraph of 790629 ltr should ref IE Bulletin 78-12.
STAFFA, R.W. Georgia Power Co. 79/07/03. 1p.

7908010031 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/06. 2pp.

7908310042 Forwards response to IE Bulletin 79-02 per 790308 ltr re pipe support base plate designs using concrete expansion anchor bolts.Outlines verification program for pipe support base plate rigidity.
STAFFA, R.W. Georgia Power Co. 79/07/06. 11pp.

7908030134 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/13. 2pp.

7908150390 Ack receipt of IE Insp Repts 50-321/79-16 & 50-366/79-20 on 790605-08.No proprietary info.
STAFFA, R.W. Georgia Power Co. 79/07/13. 1p.

--7908150400 Forwards IE Insp Repts 50-321/79-16 & 50-366/79-20 on 790605-08.No noncompliance noted.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/25. 2pp.

--7908150407 IE Insp Repts 50-321/79-16 & 50-366/79-20 on 790605-08.No noncompliance noted.Major areas inspected:plant procedures.
MOON, B.T., LIM, J.C., RUHLMAN, W.A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/22. 6pp.

7908010414 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/17. 2pp.

7908030013 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18. 2pp.

7908080046 Notifies that written responses to IE Bulletin 79-15,Suppl 1,should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18. 2pp.

7908130124 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18. 2pp.

7908160481 Ack receipt of 790711 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/79-12 & 50-366/79-16.
SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/19. 1p.

--7908160488 Responds to NRC 790615 ltr re violations noted in IE Insp Repts 50-321/79-12 & 50-366/79-16.Corrective actions:high radiation doors inspected daily & wire mesh on heat exchanger room door repaired.
STAFFA, R.W. Georgia Power Co. 79/07/11. 2pp.

--7908160490 Forwards IE Insp Repts 50-321/79-12 & 50-366/79-16 on 790507-11 & notice of violation.
SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/15. 2pp.

--7908160489 Notice of violation from insp on 790507-11.
* Region 2, Atlanta, Office of the Director. 79/06/12. 1p.

--7908160491 IE Insp Repts 50-321/79-12 & 50-366/79-16 on 790507-11 Noncompliance noted:failure to perform survey,failure to keep high radiation area locked & failure to submit radiological section of annual environ surveillance rept.
HOSEY, C.M. Region 2, Atlanta, Office of the Director.
JENKINS, G.R. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/06/12. 8pp.

7908080319 Requests addl info to suppl previous response to IE Bulletin 79-08,to enable NRC to complete safety evaluation.
IPPOLITO, T.A. Operating Reactors Branch 3. 79/07/20. 4pp.

7908090171 Responds to FOIA request for insp repts,bulletins & other documents related to tritium leakage at facilities.Forwards leakage accession list & LER output from 1969 to present.
FELTON, J.M. Division of Rules and Records. 79/07/20. 1p.

7908170555 Ack receipt of 790717 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/79-18 & 50-366/79-22.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/07/20. 1p.

--7908170562 Responds to NRC 790626 ltr re violations noted in IE Insp Repts 50-321/79-18 & 50-366/79-22.Corrective actions: re-evaluated all operating personnel & reviewed files of licensed operators.Expected completion date 790815.
STAFFA, R.W. Georgia Power Co. 79/07/17. 1p.

--7908170565 Forwards IE Insp Repts 50-321/79-18 & 50-366/79-22 on 790604-05 & notice of violation.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/26. 2pp.

--7908170568 Notice of violation from insp on 790604-05.
* Region 2, Atlanta, Office of the Director 79/06/25 1p

--7908170573 IE Insp Repts 50-321/79-18 & 50-366/79-22 on 790604-05. Noncompliance noted: failure to follow procedures re training & retraining programs.
RUHLMEN, W. A., JENKINS, H. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/25 6pp.

7908080716 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/26 2pp.

7908080741 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/26 2pp.

7908230669 Responds to NRC 790531 ltr requesting info re IE Bulletin 79-14. Mods will be performed to rod withdrawal sequence to assure against reccurence of fast period scrams.
WIDNER, W. A. Georgia Power Co. 79/07/26 3pp.

7908160031 Notifies that no proprietary info was contained in IE Insp Rept 50-366/79-23 transmitted by NRC 790703 ltr.
WIDNER, W. A. Georgia Power Co. 79/07/27 1p.

7908160236 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/27 2pp.

7908160310 Ack receipt of IE Insp Repts 50-321/79-19 & 50-366/79-24 on 790618-22. No proprietary info.
WIDNER, W. A. Georgia Power Co. 79/07/27 1p.

--7908160319 Forwards IE Insp Repts 50-321/79-19 & 50-366/79-24 on 790618-22. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/09 2pp.

--7908160327 IE Insp Repts 50-321/79-19 & 50-366/79-24 on 790618-22. No noncompliance noted. Major areas inspected: radioactive waste mgt program, including radioactive effluent release monitoring & records & repts for radioactive effluents.
HOSEY, C. M., WRAY, J. R., JENKINS, G. R. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/09 5pp.

7908220684 Responds to IE Bulletin 79-14 & NRC 790702 ltr requesting identification of certain items re verification of seismic analysis. Relevant info encl.
WIDNER, W. A. Georgia Power Co. 79/08/01 41pp.

7908210304 Ack receipt of 790702 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/79-13 & 50-366/79-17.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 79/08/03 1p.

--7908210310 Responds to NRC 790611 ltr re violations noted in IE Insp Repts 50-321/79-13 & 50-366/79-17. Corrective actions withheld (ref 10CFR2.790).
STAFFA, R. W. Georgia Power Co. 79/07/02 1p.

--7908210316 Forwards IE Insp Repts 50-321/79-13 & 50-366/79-17 on 790514-18. Notice of violation withheld (ref 10CFR2.790).
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 79/06/11. 2pp.

--7908210320 IE Insp Repts 50-321/79-13 & 50-366/79-17 on 790514-18. Noncompliance noted: designated vehicle improperly secured in protected area. Details withheld (ref 10CFR2.790).
PERNY, C. D. Region 2, Atlanta, Office of the Director.
TOBIN, W. J. Region 2, Atlanta, Safeguards Branch 79/06/08. 1p.

7908160148 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07 2pp.

7908170013 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08 2pp.

7908160403 Responds to 790720 request & forwards addl info re IE Bulletin 79-08. Standing order issued 790515 as interim means of implementing reporting requirements of Item 9 of bulletin.
KELLY, R. J. Georgia Power Co. 79/08/10 6pp.

7908290200 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/10 1p.

7908280462 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13 2pp.

R. Periodic operating reports & related correspondence

7908150531 Forwards monthly operating rept for Jul 1979.
MANRY, M. Georgia Power Co. 79/08/08 1p.

--7908150538 Monthly operating rept for Jul 1979.
ALLEN, P. B. Georgia Power Co. 79/08/08 7pp.

S. Reportable occurrences, LERs & related correspondence

7908100243 Outlines util actions to be taken re failure of HPCI & reactor core isolation cooling sys to perform as designed following reactor trip on 790627.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/28 2pp.

7908020452 Forwards LER 79-060/03L-0.
MANRY, M. Georgia Power Co. 79/07/26 1p.

--7908020456 LER 79-060/03L-0 on 790626 during approach to test condition 6 at 82% power & core max fraction of limiting power density of 0.82 rods were pulled & flow increased. Changes made to reduce high peaking factors.
COGGIN, C. L. Georgia Power Co. 79/07/26 2pp.

7908060392 Forwards LER 79-069/03L-0.
MANRY, M. Georgia Power Co. 79/07/30 1p.

--7908060411 LER 79-069/03L-0 on 790712: inboard steam isolation valve (2E51-F001) did not close when isolation signal given. Caused by valve stem being galled against packing follower. Stem was replaced.
* Georgia Power Co. 79/07/30 1p.

7908060443 Forwards LER 79-067/03L-0.
MANRY, M. Georgia Power Co. 79/07/30 1p.

--7908060451 LER 79-067/03L-0 on 790707: while performing sequence of HPCI quick start test, breaker for 2E41-F001 valve tripped. Caused by motor failure on valve. Motor was reworked, bench-tested, reinstalled & operated satisfactorily.
* Georgia Power Co. 79/07/30 1p.

7908070483 Forwards LER 79-070/03L-0.
MANRY, M. Georgia Power Co. 79/08/01 1p.

--7908070493 LER 79-070/03L-0 on 790712: high drywell pressure switch 2E11-N010 found to be set too high during normal surveillance procedure. Caused by setpoint drift. Switch recalibr & tested by HPN-2-5279.
NIX, R. T. Georgia Power Co. 79/08/01 1p.

7908070495 Forwards LER 79-072/03L-0.
MANRY, M. Georgia Power Co. 79/08/01 1p.

--7908070498 LER 79-072/03L-0 on 790717: controller 2E11-R600A did not automatically operate valve 2E11-F068A used to pump water to circulating water flume. Caused by open link from pressure transmitter to controller input.
NIX, R. T. Georgia Power Co. 79/08/01 1p.

7908130448 Forwards LER 79-071/03L-0.
MANRY, M. Georgia Power Co. 79/08/01 1p.

--7908130453 LER 79-071/03L-0 on 790717 while performing leak rate procedure HNP-1-3952E, drywell personnel airlock innerspace discovered leaking in excess of Tech Specs. Caused by worn operator hand wheel upper shaft seal.
NIX, R. T. Georgia Power Co. 79/08/01 1p.

7908100413 Forwards LER 79-078/03L-0.
MANRY,M. Georgia Power Co. 79/08/02 1p

--7908100416 LER 79-078/03L-0 on 790622 hydrogen gas concentration, measured downstream of recombiners, increased to 13% Caused by improper operation of preheater, resulting in insufficient amount of gases & moisture entering recombiner.
ROGERS,W.H. Georgia Power Co. 79/08/02 2pp

7908130338 Forwards LER 79-081/08L-0.
MANRY,M. Georgia Power Co. 79/08/02 1p

--7908130345 LER 79-081/08L-0 on 790725 while placing reactor bldg chillers in parallel for test of 72% steady state power, volumetric average drywell temp exceeded 135 F Cause not stated Temp reduced within 2-h Tech Specs changed.
COGGIN,C.L. Georgia Power Co. 79/08/03 2pp

7908130436 Forwards LER 79-080/03L-0.
MANRY,M. Georgia Power Co. 79/08/02 1p

--7908130437 LER 79-080/03L-0 on 790725 volumetric average drywell temp exceeded limit of 135 F set by Tech Spec Caused by maint personnel tripping operating chiller Reactor load lowered to reduce drywell temp to limit.
COGGIN,C.L. Georgia Power Co. 79/08/02 2pp

7908130423 Forwards LER 79-077/03L-0.
MANRY,M. Georgia Power Co. 79/08/03 1p

--7908130435 LER 79-077/03L-0 on 790712 oxygen cell found to be defective Caused by broken wire on oxygen cell New cell ordered Installation planned for 790810.
NIX,R.T. Georgia Power Co. 79/08/03 1p

7908130491 Forwards LER 79-073/03L-0.
MANRY,M. Georgia Power Co. 79/08/03 1p

--7908130494 LER 79-073/03L-0 on 790711 during normal surveillance, RHR flow indication to remote shutdown panel found inoperative. Caused by blown fuse in transmitter power supply Fuse replaced.
NIX,R.T. Georgia Power Co. 79/08/03 1p

7908130497 Forwards LER 79-074/03L-0.
MANRY,M. Georgia Power Co. 79/08/03 1p

--7908130502 LER 79-076/03L-0 on 790712 QA inspector observed both air lock doors in reactor bldg open at same time, breaking containment Caused by malfunction in limit switches on doors causing momentary alarms Repairs under consideration.
NIX,R.T. Georgia Power Co. 79/08/03 2pp

7908140812 Forwards LER 79-046/01T-1.
MANRY,M. Georgia Power Co. 79/08/03 1p

--7908140823 LER 79-046/01T-1 on 790603 reactor core isolation cooling sys initiated & operated for 1 minute before ruptured turbine exhaust diaphram caused trip Caused by dislocated valve disc which blocked 90% of valve outlet.
COGGIN,C.L. Georgia Power Co. 79/08/03 3pp

7908130469 Forwards LER 79-085/03L-0.
MANRY,M. Georgia Power Co. 79/08/06 1p

--7908130473 LER 79-085/03L-0 on 790718 higher flow on return line to reactor vessel than inlet flow to sys indicated by reactor water cleanup leak detection sys Cause unknown Sys run to obtain flow curves & equipment recalibr.
NIX,R.T. Georgia Power Co. 79/08/06 1p

7908140635 Forwards LER 79-083/03L-0.
MANRY,M. Georgia Power Co. 79/08/07 1p

--7908140646 LER 79-083/03L on 790729 HPCI steam line instrument setpoint exceeded acceptance criteria Caused by instrument drift. Instrument recalibrated & tested satisfactorily.
NIX,R.T. Georgia Power Co. 79/08/07 1p

7908140791 Forwards LER 79-082/03L-0.
MANRY,M. Georgia Power Co. 79/08/07 1p

--7908140796 LER 79-082/03L-0 on 790725 switch in low-low water level recirculation pump logic inoperable Caused by trash on switch contacts Contacts cleaned & tested Maint request issued to inspect & clean other switches.
NIX,R.T. Georgia Power Co. 79/08/07 1p

7908140696 Forwards LER 79-086/03L-0.
MANRY,M. Georgia Power Co. 79/08/08 1p

--7908140702 LER 79-086/03L-0 on 790730 HPCI sys declared inoperable when 2E41-F041 valve failed to close when initiated from control switch Valve failure caused by burned motor New motor & pinion key installed & tested satisfactorily.
NIX,R.T. Georgia Power Co. 79/08/08 2pp

7908140833 Forwards LER 79-075/03L-0.
MANRY,M. Georgia Power Co. 79/08/08 1p

--7908140837 LER 79-075/03L-0 on 790716 computer calculation indicated critical mass peaking factor of 3.046 w/limit of 2.38 Caused by calibr error Control rod withdrawal sequence altered to avoid future peaking problems.
COGGIN,C.L. Georgia Power Co. 79/08/08 2pp

7908200302 Forwards LER 79-090/03L-0.
MANRY,M. Georgia Power Co. 79/08/10 1p

--7908200352 LER 79-090/03L-0 on 790802 while performing calibr procedure 2E41-N012C, setpoint exceeded Tech Specs Caused by instrument drift Instrument recalibr & surveillance procedure performed successfully.
NIX,R.T. Georgia Power Co. 79/08/10 1p

7908200320 Forwards LER 79-078/03L-1.
MANRY,M. Georgia Power Co. 79/08/10 1p

--7908200323 LER 79-078/03L-1 on 790622 hydrogen gas concentration downstream of recombiners exceeded Tech Specs Caused by improper operation of preheater which resulted in insufficient gas & droplet temp Investigation underway.
ROGERS,W.H. Georgia Power Co. 79/08/10 2pp

7908200337 Forwards LER 79-091/03L-0.
MANRY,M. Georgia Power Co. 79/08/10 1p

--7908200340 LER 79-091/03L-0 on 790727 on 17 occasions from 790103-0723, procedures were released w/o obtaining plant manager approval within 14 days Caused by inadequate tracking method Methods will be revised.
COGGIN,C.L. Georgia Power Co. 79/08/10 1p

7908200351 Forwards LER 79-079/03L-0.
MANRY,M. Georgia Power Co. 79/08/10 1p

--7908200355 LER 79-079/03L-0 on 790718 reactor feedwater flow transmitters were incorrectly calibrated, resulting in errors in reactor power calculations Caused by use of unrevised procedures Procedures & data sheets reviewed & corrected.
COGGIN,C.L. Georgia Power Co. 79/08/06 2pp

7908200371 Forwards LER 79-089/03L-0.
MANRY,M. Georgia Power Co. 79/08/10 1p

--7908200374 LER 79-089/03L-0 on 790718 battery pilot cell surveillance not performed on 790712 per Tech Specs Caused by personnel oversight Satisfactory cell surveillance performed on 790718 & personnel informed of surveillance schedule.
NIX,R.T. Georgia Power Co. 79/08/10 1p

7908200377 Forwards LER 79-084/03L-0.
MANRY,M. Georgia Power Co. 79/08/10 1p

--7908200379 LER 79-084/03L-0 on 790729 during maint, HPCI pump suction low pressure switch 2E41-N010 found inoperative Caused by ruptured instrument diaphragm Instrument replaced & switch tested satisfactorily.
NIX,R.T. Georgia Power Co. 79/08/10 1p

7908240436 Forwards LER 79-026/01X-1.
MANRY,M. Georgia Power Co. 79/08/10 1p

--7908240440 LER 79-026/01X-1 on 790228 pipe supports failed, resulting in falling of condensate piping Caused by generic problem in concrete fasteners due to improper installation.
* Georgia Power Co. 79/08/10 3pp.

7908240525 Forwards LER 79-068/03L-0.
MANRY,M. Georgia Power Co. 79/08/16 1p

--7908240528 LER 79-068/03L-0 on 790809 lock on radwaste shield plug hoist was broken off Locking device was fabricated to prevent hoist operation w/o key.
BAXLEY,S.X. Georgia Power Co. 79/08/16 1p

7908240469 Forwards LER 79-088/03L-0.
MANRY, M. Georgia Power Co. 79/08/17. 1p.

--7908240480 LER 79-088/03L-0 on 790721 reactor, turbine & radwaste bldg charcoal filter deluge sprinkler sys were inoperable in automatic mode. Design review in progress.
COGGIN, C. L. Georgia Power Co. 79/08/17. 2pp.

7908280685 Forwards LER 79-066/03L-0.
MANRY, M. Georgia Power Co. 79/08/20. 1p.

--7908280690 LER 79-066/03L-0 on 790804 hydrogen gas concentration, measured downstream in combiners, exceeded Tech Spec limit of 4% Caused by moisture that entered recombiner A. Design change request initiated.
ROGERS, W. H. Georgia Power Co. 79/08/20. 2pp.

7908310313 Forwards LER 79-087/03L-0.
MANRY, M. Georgia Power Co. 79/08/23. 1p.

--7908310316 LER 79-087/03L-0 on 790810 while increasing reactor power, average linear planar heat generation rate exceeded limit. Caused by low xenon condition reducing equilibrium condition in control rod pattern. Rate will be better monitored.
COGGIN, C. L. Georgia Power Co. 79/08/23. 2pp.

7908310318 Forwards LER 79-074/03L-0.
MANRY, M. Georgia Power Co. 79/08/24. 1p.

7908310322 LER 79-074/03L-0 on 790808 reactor recirculation sys motor generator set 2B tripped while unit at steady state power. Cause unknown.
NIX, R. T. Georgia Power Co. 79/08/24. 2pp.

DOCKET 50-367 BAILLY GENERATING STATION

A. Application/construction stage documents & correspondence

7908030284 Discusses util proposal re shorter foundation piles for plant safety-related structures. Requests addl info & clarification re foundation "soft spots," piles chosen for load testing & sheeting & bracing plan.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/28. 3pp.

7908070801 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/13. 1p.

7908170207 Submits review of pile foundation design. Believes shorter piles present no safety hazard if certain procedures are followed.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/07/16. 3pp.

7908080202 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/24. 2pp.

7908160036 Notification of 790731 meeting w/util in Bethesda, MD to discuss dewatering & water level monitoring program data & procedures.
GECKLER, R. P. Environmental Projects Branch 1. 79/07/24. 1p.

7908160426 Forwards addl info re piling proposal in response to NRC 790628 request. Areas addressed: proposal for correcting preconst areas, selection of representative production piles for load testing & bracing plan.
SHORB, E. M. Northern Indiana Public Service Co. 79/08/14. 34pp.

7908300494 Forwards repts, "Supplementary Info, Hydrogeologic Evaluation of Const Dewatering" & "Summary Rept & Testing Investigation & Testing For Groundwater Pressure Relief During Const."
BOHN, R. J. Northern Indiana Public Service Co. 79/08/27. 2pp.

--7908300503 "Supplementary Info, Hydrogeologic Evaluation of Const Dewatering."
* Sargent & Lundy, Inc. 79/08/27. 32pp.

--7908300514 "Summary Rept Investigation & Testing for Groundwater Pressure Relief During Const."
* Groun/Water Technology, Inc. 79/08/27. 77pp.

G. Adjudicatory correspondence

7908030561 Joint suppl submitted by State of IL & joint intervenors to 7902[illegible] & 0305 hearing requests re util 790207 request for amend to CP. Submits health, safety & environ matters for consideration. Certificate of Svc encl.
SCOTT, W. J. Illinois, State of. VOLLEN, R. J. Vollen, R. J.
OSANN, E. W. Osann, E. W. 79/06/29. 14pp.

7908300268 Suppl to 780110 response to NRC 781211 questions re applicant short pilings proposal. Submits DB Vassallo 790628 ltr concluding that util 780308 proposal has merit but more info is needed to complete review.
CUNNINGHAM, G. H. Branch 2. 79/07/10. 2pp.

--7908300257 Notice of review of 780308 proposal re shorter piles for safety-related structures. Proposal has merit, but more info is needed to complete review. Certificate of Svc encl.
VASSALLO, D. B. Division of Project Management. 79/06/28. 5pp.

O. Advisory Committee on Reactor Safeguards reports & correspondence

7908150059 Forwards ACRS 790716 ltr to Chairman Hendrie re review of pile foundations for facility.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/07/20. 3pp.

--7908150063 Advises that pile foundations design has been reviewed during ACRS 790712-14 meeting. Use of shorter piling is not significant design change & would not require significant alteration of other aspects of facility design.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/07/16. 3pp.

Q. Inspection reports, IE Bulletins & correspondence

7908070757 Responds to IE Bulletin 79-12 C-E rept, "Info Requested by IE Bulletin 78-12, Atypical Weld Matl in Reactor Pressure Vessel Welds," adequately represents data for Bailly reactor vessel.
SHORB, J. G. Northern Indiana Public Service Co. 79/06/29. 2pp.

--7908070768 Forwards C-E rept, "Info Requested by IE Bulletin 78-12, Atypical Weld Matl in Reactor Pressure Vessel Welds," in response to bulletin. GE 790618 ltr & C-E 790608 ltr encl, certifying rept addressed matls used in facility. W/o rept.
* Northern Indiana Public Service Co. 79/06/08. 3pp.

7908090305 Responds to IE Bulletin 79-11 Westinghouse DB-50 & DB-75 circuit breakers not in use at plant.
SHORB, E. M. Northern Indiana Public Service Co. 79/06/29. 1p.

7908140323 Response to IE Bulletin 79-02, Revision 1. Pipe support baseplate flexibility will be accommodated; wedge-type anchor bolts will be designed using min-required factor of safety & expansion anchors will be installed per QA/QC procedures.
SHORB, E. M. Northern Indiana Public Service Co. 79/07/06. 3pp.

7908020340 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908300415 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908150363 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300285 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

R. Periodic operating reports & related correspondence

7908030147 Forwards well charts for 790711-18, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 790718.
BOHN, R. J. Northern Indiana Public Service Co. 79/07/27. 32pp.

7908140491 Forwards well charts for 790718-25 & charts for Bailly wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 790725.
BOHN, R. J. Northern Indiana Public Service Co. 79/08/03. 32pp.

7908220333 Forwards well charts for 790725-0801. Bailly wells w/o recorders for 790801, pond levels for 790801, pneumatic pressure transducers for 790802, water meter readings for 790801 & USGS wells for 790802.
BOHN, R. J. Northern Indiana Public Service Co. 79/08/10. 31pp.

7908230333 Forwards "Spring 1979 Quarterly Rept." for Apr-June 1978. Prepared by TX Instruments, Inc.
PURCELL, J. F. Northern Indiana Public Service Co. 79/08/15. 1p.

--7908230341 "Spring 1979 Quarterly Rept." for Apr-June 1978.
* Northern Indiana Public Service Co. 79/06/30. 200pp.

7908220275 Forwards well charts for 790801-08, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 790808.
BOHN, R. J. Northern Indiana Public Service Co. 79/08/17. 50pp.

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F. Security, medical, emergency & fire protection plans

7908130155 Notifies that review of safeguards contingency plan involves consideration of safeguards issue requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 1p.

7908230394 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
TRIMBLE, D. C. Arkansas Power & Light Co. 79/08/17. 1p.

H. General correspondence

7908090580 Responds to NRC 790629 ltr re mgt & technical resources. Organization charts & position descriptions encl.
CAVANAUGH, W. Arkansas Power & Light Co. 79/07/30. 44pp.

P. Operating license stage documents & correspondence

7908010038 Responds to IE Bulletin No 9E Type AK-2 circuit breakers used in Unit 2 & no plans for future use. Breakers installed in Unit 1 control rod drive sys are maintained per inservice insp procedure.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/05/10. 2pp.

7908130359 Notifies all operating plants using C-E-designed reactors of generic review re TMI. Requests attendance at 790612 meeting in Bethesda, MD re info needed by NRC to complete review.
STOLZ, J. F. Light Water Reactors Branch 1. 79/06/05. 16pp.

7908280757 Requests registration as user of Model B3-1.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/20. 1p.

7908210147 Ack imminent transfer of responsibility for unit to NRC Operating Reactors Branch 4.
MULLER, D. R. Division of Site Safety & Environmental Analysis. 79/06/25. 1p.

7908100320 Requests registration as user of Model CNS 21-300 radioactive matl shipping cask.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/11. 1p.

7908150512 Requests registration as user of Models 927A1 & 927C1.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/16. 1p.

7908170538 Requests registration as user of Model 6144.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/16. 1p.

7908150493 Requests registration as user of Model HN-100, Series 2.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/17. 1p.

7908150542 Requests registration as user of Model HN-200.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/17. 1p.

7908070355 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/07/18. 1p.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908020476 Submits info in response to 790525 request re PWR feedwater lines. Fabrication history, preservice/inservice insp & operating history are included.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/27. 4pp.

7908100254 Discusses submittal of CEN-114-P, "Review of Small Break Transients in C-E NSSS." Submittal is partial response to NRC 790605 ltr.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/08/02. 1p.

7908130536 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
STOLZ, J. F. Light Water Reactors Branch 1. 79/08/02. 4pp.

7908100458 Forwards proprietary & non-proprietary versions of Amend 1 to CEN-114, "Review of Small Break Transients in C-E NSSS." LIEBLER, G. E. C-E Operating Plants Owners Group. 79/08/03. 6pp.

--7908100465 Amend 1-NP to CEN-114-NP, "Review of Small Break Transient in C-E NSSS." CEN-144-P withheld (ref 10CFR2.790).
* Combustion Engineering, Inc. CEN-114-P. 79/07/31. 111Opp.

7908220274 Notification of 790822 meeting w/Middle South Svcs, Inc to discuss topical rept on reactor physics methods for use at facilities.
FIENO, D. Core Performance Branch. 79/08/09. 2pp.

7908170428 Forwards CEN-114-NP, Amend 1, "Review of Small Break Transients in C-E Nuclear Steam Supply Sys." Proprietary version, CEN-114-P, withheld (ref 10CFR2.790).
SCHERER, A. E. C-E Power Systems. 79/08/10. 1p.

7908280656 Submits ltr to document 790813 telcon. Discusses proportional pressurizer heaters & in house investigation.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/08/21. 1p.

7908290419 Requests withdrawal of proposed Tech Spec changes transmitted in 790417 & 0518 ltrs. Proposed changes would have allowed operation w/o fire watches in several safety-related areas.
CAVANAUGH, W. Arkansas Power & Light Co. 79/08/21. 1p.

Q. Inspection reports, IE Bulletins & correspondence

7908090688 Forwards IE Insp Rept 50-313/79-09 & 50-368/79-09 on 790414-0511. No noncompliance noted.
MADSON, G. L. Region 4, Dallas, Office of the Director. 79/05/31. 2pp.

--7908090691 IE Insp Rept 50-313/79-09 & 50-368/79-09 on 790414-0511. No noncompliance noted. Major areas inspected, previously noted items, refueling activities & licensee actions taken in response to IE Bulletin 79-05A.
JOHNSON, W. D., SPANGLER, R. G., WESTERMAN, T. F. Region 4, Dallas, Office of the Director. 79/05/30. 15pp.

7908090261 Ack receipt of 790530 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-07 & 50-368/79-07.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/06/14. 1p.

--7908090275 Responds to NRC 790501 ltr re violations noted in IE Insp Repts 50-313/79-07 & 50-368/79-07. Corrective actions: procedures revised to require ignition work permit & control of combustible debris.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/05/30. 3pp.

7908160021 Responds to IE Bulletin 79-03 re schedule for testing Youngstown piping used in Unit 1. Examination of piping is not necessary. Testing results to verify conclusion will be submitted by 790901.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/22. 1p.

7908160009 Responds to IE Bulletin 78-12. Submits "Atypical Weld Matl in Reactor Pressure Vessel Welds" prepared by C-E Inc. Certifies that rept addresses all applicable matl used in fabrication of reactor vessel.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/27. 1p.

7908080157 Forwards revised response to IE Bulletin 79-06B, incorporating NRC comments. Supersedes 790424 response.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/29. 20pp.

7908020367 Requests submittal of procedures to be used to facilitate IE program assessment team insp scheduled for 790730-0803 & 06-10. Submitted procedures will be returned following completion of insp.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/07/03. 1p.

7908030111 Responds to IE Bulletin 79-02,Revision 1 re seismic analysis of concrete pipe support base plate design.Forwards rept "Statistical Sampling Program to Test Concrete Expansion Bolts," by Bechtel Corp.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/07/06 11pp.

--7908030118 "Statistical Sampling Program to Test Concrete Expansion Bolts," prepared for AR Power & Light
* Bechtel Power Corp. (subs. of Bechtel Corp.). 79/05/17 69pp.

7908140177 Ack 790612 response to 790404 & 0522 ltrs re IE Insp Rept 50-368/79-06.Discusses use of non-Class IE test equipment. Concedes utilization in some instances is acceptable,but restrictions are subject to further NRC clarification.
MADSEN,G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/12 1p.

--7908140186 Forwards addl response to Item 1 of IE Insp Rept 50-368/79-06 re failure to establish written procedures to control degrading of safty-related Class IE components by installation of non-Class IE test equipment.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/06/12 2pp.

7908160028 Responds to IE Bulletin 79-13,Item 5.Volumetric examination of Unit 2 feedwater nozzle-to-piping welds will be performed.Emergency procedures re feedwater line break accidents are adequate.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/07/12 2pp.

7908170371 Responds to IE Bulletins 79-01 & 01A re environ qualification of safety-related electrical equipment inside reactor bldg.No stem-mounted limit switches or solenoid valves planned for use.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/07/13 46pp.

7908020393 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/18 1p.

7908160324 Discusses util response to IE Bulletin 79-06B.Addl info requested.
STOLZ,J.F. Light Water Reactors Branch 1 79/07/25 4pp.

7908060019 Forwards IE Bulletins 79-05C & 79-06C, "Nuclear Incident at TMI - Suppl." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/26 1p.

7908060038 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/26 1p.

7908060123 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/26 1p.

7908070491 Responds to IE Bulliten 79-14.Forwards justifying documentation,pipe support & restraint review log & typical ASME Section 3 & ANSI B31.1 sheets verifying that seismic analysis applies to safty related sys.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/08/01 62 pp.

7908140580 Comfirms 790731 telcon.Expects Task Force to arrive 790903. Apologizes for being unable to support planned 790802 insp.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/08/02 1p.

7908160049 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/10 1p.

R Periodic operating reports & related correspondence

7908230372 Forwards monthly operating rept for Jul 1979.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/08/14 1p.

--7908230373 Monthly operating rept for Jul 1979.
SHIVELY,C.N. Arkansas Power & Light Co. 79/08/14 5pp.

S. Reportable occurrences, LERs & related correspondence

7908010694 Forwards PNO-79-67AX.
MADSEN,G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/20 1p.

7908020424 RO 50-368/79-34 has been voided.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/07/25 2pp.

7908080495 RO 50-368/79-34 has been voided.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/07/25 2pp.

7908020484 Forwards LER 79-047/04L-0.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/07/27 1p.

--7908020492 LER 79-047/04L-0 on 790627:condenser vacuum pump radiation monitors inoperable more than seven days during Mode 1 operation.Caused by moisture buildup.Engineering evaluation is being conducted.
SHIVELY,C.N. Arkansas Power & Light Co. 79/07/27 1p.

7908060468 Forwards LERs 79-048/03L-0,79-049/03L-0,79-050/03L-0, 79-051/03L-0 & 79-052/03L-0.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/07/31 1p.

--7908060472 LER 79-048/03L-0 on 790703:startup channel excore nuclear log count ratemeter on remote shutdown indicated incorrectly during Mode 1 operation.Cause not stated. Feedback wiper arm cleaned.
SHIVELY,C.N. Arkansas Power & Light Co. 79/07/31 1p.

--7908060475 LER 79-049/03L-0 on 790703:hydraulic snubber visual insp surveillance not performed on schedule.Caused by erroneous assumption by plant personnel that surveillance performed during reactor coolant pump motor maint.
SHIVELY,C.N. Arkansas Power & Light Co. 79/07/31 1p.

--7908060480 LER 79-050/03L-0 on 790703:control room emergency air conditioner 2VE1-A failed to start from control room panel 2C33 during Mode 1.Caused by high pressure switch tripping due to low water in condenser.
SHIVELY,C.N. Arkansas Power & Light Co. 79/07/31 1p.

--7908060482 LER 79-051/03L-0 on 790706:emergency feedwater flow control valves from electric driven pump to steam generator A failed to close from control room demand signal.Cause not stated.Valve tested & motor replace.
SHIVELY,C.N. Arkansas Power & Light Co. 79/07/31 1p.

--7908060487 LER 79-052/03L-0 on 790708:core protection calculator B failed causing low DNBR & high linear power density trips in plant protection sys B.Caused by lost bit in high core memory due to failed air conditioner in computer room.
SHIVELY,C.N. Arkansas Power & Light Co. 79/07/31 1p.

7908070537 Forwards LERs 79-053/03L-0,79-054/03L-0,79-055/03L-0, 79-056/03L-0 & 79-057/04L-0.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/08/02 2pp.

--7908070551 LER 79-053/03L-0 on 790713:control room air conditioner compressor failed to start from control room panel.Caused by casting plug lodged in compressor valve.Plug removed,unit recharged & declared operable.
SHIVELY,C.N. Arkansas Power & Light Co. 79/08/02 1p.

--7908070576 LER 79-054/03L-0 on 790716:main feedwater valve A failed shut.Caused by frozen inboard bearing on valve operator motor.Bearing replaced,motor reinstalled & valve stroke-tested satisfactorily.Valve declared operable.
SHIVELY,C.N. Arkansas Power & Light Co. 79/08/02 1P

--7908070592 LER 79-055/03L-0 on 790719:main feedwater controller B malfunctioned.Caused by water in steam supply line.Water blown from steam line & tested successfully.
SHIVELY,C.N. Arkansas Power & Light Co. 79/08/02 1p.

--7908070605 LER 79-056/03L-0 on 790713:station batteries surveillance insp not performed on schedule.Caused by personnel oversight.Importance of program discussed w/supervisor.
SHIVELY,C.N. Arkansas Power & Light Co. 79/08/02 1p

--7908070623 LER 79-057/04L-0 on 790718:radwaste area exhaust radiation monitor found inoperable.Caused by broken coupling on radiation monitor sample pump.Pump coupling replaced & monitor returned to svc.
SHIVELY,C.N. Arkansas Power & Light Co. 79/08/02 1p.

7908200305 Forwards LER 79-058/03L-0.
TRIMBLE,D.C. Arkansas Power & Light Co. 79/08/14 1p.

--7908200308 LER 79-058/03L-0 on 790721:as result of investigation per IE Bulletin 79-02,seven restraints identified as having safety factor greater than two.Method of obtaining bolt loads revised.
SHIVELY,C.N. Arkansas Power & Light Co. 79/08/14 4pp.

DOCKET 50-369 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D.B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908080094 Forwards C-E 790608 ltr & certification re generic rept, "Atypical Weld Melt in Reactor Pressure Vessel Welds," evaluated by Westinghouse.Notes error in identification of reactor vessel mfg under C-E Contract 8871.
PARKER,W.O. Duke Power Co. 79/06/29 1p.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOL,H. Light Water Reactors Branch 2 79/07/02 70pp.

7908030413 FOIA request for documents prepared by NRC re alternatives to Duke Power Co proposal to ship spent fuel from Oconee plant to McGuire plant.
ROISMAN,A.Z. Natural Resources Defense Council 79/07/02 1p.

7908030435 Responds to FOIA request for documents prepared by NRC &/or NRC consultants re alternatives to Duke Power Co proposal to ship spent fuel from Oconee to McGuire.
FELTON,J.M. Division of Rules and Records 79/07/19 2pp.

--7908030462 Forwards questions for approval re proposed licensing of shipment of Oconee spent fuel to McGuire nuclear station.
GLENN,R.D. Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/22 14pp.

--7908030461 EIA re storage of Oconee spent fuel at McGuire spent fuel pool w/marked-up copy.
* Office of Nuclear Material Safety & Safeguards 78/12/31 212pp.

--7908030474 EIA re storage of Oconee spent fuel at McGuire spent fuel pool.
* Office of Nuclear Material Safety & Safeguards 78/11/30 76pp.

--7908030488 Drafts of EIA for McGuire nuclear station.
* Battelle Memorial Institute, Pacific Northwest Laboratory 79/08/02 584pp.

7908010485 Forwards second draft of radiological effluent Tech Specs, superseding 781218 & 790323 submittals.
PARKER,W.O. Duke Power Co. 79/07/25 74pp.

7908060220 Responds to 790706 request re info on potential impact on NRC resource needs & priorities associated w/decision to delay commercial operation of Cherokee 1 & 2 & postpone financial commitments for Cherokee 3 & Perkins 1,2 & 3.
DAIL,L.C. Duke Power Co. 79/07/27 8pp.

7908100472 Forwards "Cask Drop Analysis" using Natl Lead Industries 1/2 cask.
RAER,R.L. Duke Power Co. 79/08/02 1p.

--7908100473 "Cask Drop Analysis."
* Duke Power Co. 79/08/02 6pp.

7908100498 Forwards schedule of dates for submittal re licensing review of info on safety injection sys bypass,leakage detection instrumentation & load follow strategy analysis.Will submit info by ltr or in next FSAR revision.
PARKER,W.O. Duke Power Co. 79/08/06 2pp.

F. Security, medical, emergency & fire protection plans

7908210006 Forwards security training & qualification plan.Plan withheld (ref 10CFR2.790).
PARKER,W.O. Duke Power Co. 79/08/17 1p.

G. Adjudicatory correspondence

7908140048 Board notification.Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment,in response to 790606 request.
BLACK,R.L. Branch 1 79/06/29 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO,J.F. Hearings Division 79/03/05 1p.

G. Inspection reports, IE Bulletins & correspondence

7908020513 Ack receipt of IE Insp Rept 50-369/79-23.No proprietary info.
PARKER,W.O. Duke Power Co. 79/06/21 1p.

7908030601 Responds to IE Bulletin 79-11 re safety-related Class IE sys.No Westinghouse Type DB-75 or DB-50 circuit breakers in use.
PARKER,W.O. Duke Power Co. 79/06/25 1p.

7908270307 Responds to IE Bulletin 79-03.Forwards addl info re application of pipe mfg by Youngstown Welding & Engineering Co.
PARKER,W.O. Duke Power Co. 79/07/02 2pp.

7908240201 Forwards IE Insp Rept 50-369/79-27 on 790626.No noncompliance noted.
LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/06 2pp.

--7908240205 IE Insp Rept 50-369/79-27 on 790626.No noncompliance noted. Major areas inspected followup on unresolved items,open items & IE circulars.
COTTLE,W. Region 2, Atlanta, Office of the Director DANCE,H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/05 4pp.

7908170171 Responds to IE Bulletin 79-09 re use of GE circuit breakers. No GE Type AK-2 circuit breakers are in use or planned for use in plant safety-related sys.
PARKER,W.O. Duke Power Co. 79/07/09 1p.

7908150285 Ack receipt of IE Insp Repts 50-369/79-24 & 50-370/79-12 on 790522-25.No proprietary info.
PARKER,W.O. Duke Power Co. 79/07/12 1p.

--7908150294 Forwards IE Insp Repts 50-369/79-24 & 50-370/79-12 on 790522-25.No noncompliance noted.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/19 2pp.

--7908150302 IE Insp Repts 50-369/79-24 & 50-370/79-12 on 790522-25.No noncompliance noted.Major areas inspected:fire protection, electrical work,instrumentation work & quality records.
GIBBONS,T.D., CONLON,T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/18 4pp.

7908030114 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/13 2pp.

7908170057 Ack receipt of IE Insp Repts 50-369/79-25 & 50-370/79-13 on 790605-07.No proprietary info.
PARKER,W.O. Duke Power Co. 79/07/13 1p.

--7908170059 Forwards IE Insp Repts 50-369/79-25 & 50-370/79-13 on 790605-07.No noncompliance noted.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/21 2pp.

--7908170061 IE Insp Rept 50-369/79-25 & 50-370/79-13 on 790605-07.No noncompliance noted.Major areas inspected:audits,licensee identified items,equipment storage,housekeeping & electrical cable installation.
HUNT,M.D., BRYANT,J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/21 3pp.

7908010405 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/17 2pp.

7908030002 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/18 2pp.

7908080038 Notifies that written responses to IE Bulletin 79-15,Suppl 1,should be directed to IE Div of Reactor Const Insp.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/18 2pp.

7908130106 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908070741 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/26 2pp

7908080708 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/26 2pp

7908160207 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/27 2pp

7908160287 Ack receipt of IE Insp Rept 50-369/79-27.No proprietary info
PARKER, W.O. Duke Power Co 79/08/01 1p

7908220199 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/08/07 3pp

7908270293 Ack receipt of IE Insp Repts 50-369/79-26 & 50-370/79-14 on 790625-28.No proprietary info
PARKER, W.O. Duke Power Co 79/08/09 1p

--7908270297 Forwards IE Insp Repts 50-369/79-26 & 50-370/79-14 on 790625-28.No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/13 2pp

--7908270300 IE Insp Repts 50-369/79-269 & 50-370/79-14 on 790625-28. No noncompliance noted.Major areas inspected:electrical installation work,work activities & quality records.
GIBBONS, T.D. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/12 3pp

7908280436 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required
GRIER, B.H. Region 2, Atlanta, Office of the Director 79/08/13 2pp

S Reportable occurrences, LERs & related correspondence

7909280608 Suppl 1 to Significant Deficiency 369-370/79-01 on 790413: pressurizer power relief valve plug experienced binding in bonnet recess area.Caused by bonnet deformation.Valve operator design is being modified.
PARKER, W.O. Duke Power Co 79/08/15 1p

DOCKET 50-370 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D.B. Assistant Director for Light Water Reactors
79/06/06 47pp

7908080094 Forwards C-E 790608 ltr & certification re generic rept, "Atypical Weld Melt in Reactor Pressure Vessel Welds," evaluated by Westinghouse.Notes error in identification of reactor vessel mfg under C-E Contract 8871
PARKER, W.O. Duke Power Co 79/06/29 1p

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908030413 FOIA request for documents prepared by NRC re alternatives to Duke Power Co proposal to ship spent fuel from Oconee plant to McGuire plant.
ROISMAN, A.Z. Natural Resources Defense Council 79/07/02 1p

7908030435 Responds to FOIA request for documents prepared by NRC &/or NRC consultants re alternatives to Duke Power Co proposal to ship spent fuel from Oconee to McGuire.
FELTON, J.M. Division of Rules and Records 79/07/19 2pp

7908010485 Forwards second draft of radiological effluent Tech Specs, superseding 781218 & 790323 submittals.
PARKER, W.O. Duke Power Co 79/07/25 74pp

7908060220 Responds to 790706 request re info on potential impact on NRC resource needs & priorities associated w/decision to delay commercial operation of Cherokee 1 & 2 & postpone financial commitments for Cherokee 3 & Perkins 1,2 & 3.
DAIL, L.C. Duke Power Co 79/07/27 8pp

7908100472 Forwards "Cask Drop Analysis" using Natl Lead Industries 1/2 cask.
RAER, R.L. Duke Power Co 79/08/02 1p

--7908100473 "Cask Drop Analysis."
* Duke Power Co 79/08/02 6pp

7908100498 Forwards schedule of dates for submittal re licensing review of info on safety injection sys bypass,leakage detection instrumentation & load follow strategy analysis.Will submit info by ltr or in next FSAR revision.
PARKER, W.O. Duke Power Co 79/08/06 2pp

F Security, medical, emergency & fire protection plans

7908210006 Forwards security training & qualification plan.Plan withheld (ref 10CFR2.790).
PARKER, W.O. Duke Power Co 79/08/17 1p

G Adjudicatory correspondence

7908020290 Discusses SAND-77-1927, "Transport of Radionuclides in Urban Environs:Working Draft Assessment." Identifies general objectives & topics discussed.No regulatory action necessary per SECY-78-311 & SECY-78-311A.
SOHINKI, S.M. Branch 3 79/04/25 2pp

--7908020302 Forwards info potentially relevant to ASLB & ASLAB in NRC proceedings re analyses of sabotage attacks on spent fuel transportation sys & description of damages caused by various types of high explosive attacks.W/o encl.
CARTER, T.F. Division of Safeguards 79/01/22 2pp

7907110499 State of IL opposition to NRC 790504 motion & Comm Ed 790507 motion for reconsideration &/or clarification & referral of ASLB 790419 memo & order admitting Contentions 6 & 11.
SEKULER, S.N. Illinois, State of 79/05/17 6pp

7908140048 Board notification.Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment,in response to 790606 request.
BLACK, R.L. Branch 1 79/06/29 1p

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J.F. Hearings Division 79/03/05 1p

G Inspection reports, IE Bulletins & correspondence

7908030601 Responds to IE Bulletin 79-11 re safety-related Class IE sys.No Westinghouse Type DB-75 or DB-50 circuit breakers in use.
PARKER, W.O. Duke Power Co 79/06/25 1p

7908270307 Respunds to IE Bulletin 79-03.Forwards addl info re application of pipe mfg by Youngstown Welding & Engineering Co.
PARKER, W.O. Duke Power Co 79/07/02 2pp

7908170171 Responds to IE Bulletin 79-09 re use of GE circuit breakers. No GE Type AK-2 circuit breakers are in use or planned for use in plant safety-related sys.
PARKER, W.O. Duke Power Co 79/07/09 1p

7908150285 Ack receipt of IE Insp Repts 50-369/79-24 & 50-370/79-12 on 790522-25.No proprietary info.
PARKER, W.O. Duke Power Co 79/07/12 1p

--7908150294 Forwards IE Insp Repts 50-369/79-24 & 50-370/79-12 on 790522-25.No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/19 2pp

--7908150302 IE Insp Repts 50-369/79-24 & 50-370/79-12 on 790522-25.No noncompliance noted.Major areas inspected:fire protection, electrical work,instrumentation work & quality records.
GIBBONS, T.D., CONLON, T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/18 4pp

7908030114 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908170057 Ack receipt of IE Insp Repts 50-369/79-25 & 50-370/79-13 on 790605-07. No proprietary info.
PARKER, W. O. Duke Power Co. 79/07/13. 1p.

--7908170059 Forwards IE Insp Repts 50-369/79-25 & 50-370/79-13 on 790605-07. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/21. 2pp.

--7908170061 IE Insp Rept 50-369/79-25 & 50-370/79-13 on 790605-07. No noncompliance noted. Major areas inspected: audits; licensee identified items; equipment storage; housekeeping & electrical cable installation.
HUNT, M. D., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/21. 3pp.

7908010405 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030002 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080038 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130106 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908070741 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160207 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908220199 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

7908270293 Ack receipt of IE Insp Repts 50-369/79-26 & 50-370/79-14 on 790625-28. No proprietary info.
PARKER, W. O. Duke Power Co. 79/08/09. 1p.

--7908270297 Forwards IE Insp Repts 50-369/79-26 & 50-370/79-14 on 790625-28. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/13. 2pp.

--7908270300 IE Insp Repts 50-369/79-26 & 50-370/79-14 on 790625-28. No noncompliance noted. Major areas inspected: electrical installation work; work activities & quality records.
GIBBONS, T. D. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/12. 3pp.

7908280436 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

5 Reportable occurrences, LERs & related correspondence

7908280608 Suppl 1 to Significant Deficiency 369-370/79-01 on 790413. pressurizer power relief valve plug experienced binding in bonnet recess area. Caused by bonnet deformation. Valve operator design is being modified.
PARKER, W. O. Duke Power Co. 79/08/15. 1p.

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

A Application/construction stage documents & correspondence

7908080639 Approves 790521 request to apply approved ASME Code Case N-240, exempting piping subject to ASME code from hydrostatic testing. Code case may be ref in FSAR.
PARR, O. D. Light Water Reactors Branch 3. 79/06/05. 1p.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, F. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908080619 Confirms 790604 telcon w/HD Scholl of SEC re possible inaccuracies or omissions in util registration statement. No inaccuracies identified. Encl available in Central Files.
BOURNIA, A. Light Water Reactors Branch 3. 79/06/07. 1p.

7908080528 FOIA request for records re reasons for delay in startup of operation.
MCCULLOUGH, E. R. McCullough, E. R. 79/06/15. 1p.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908170068 FOIA request for all documents pertinent to facility const delays.
GOGOL, E. Citizens Against Nuclear Power. 79/07/06. 2pp.

7908080162 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 2pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 58pp.

7908150177 Forwards list of addl info about power sys to continue FSAR review & evaluation.
PARR, O. D. Light Water Reactors Branch 3. 79/07/19. 4pp.

7908160309 Forwards request for addl info re sys capable of providing post-accident & transient core cooling & containment isolation.
PARR, O. D. Light Water Reactors Branch 3. 79/07/23. 19pp.

7908080540 Responds to FOIA request for records re reasons for delay in startup of operation. Forwards 781215 Bournia memo & 790122 Parr ltr to DelGeorge.
FELTON, J. M. Division of Rules and Records. 79/07/30. 12pp.

--7908080549 Forwards list of outstanding issues in SER.
PARR, O. D. Light Water Reactors Branch 3. 79/02/05. 26pp.

7908090344 Forwards responses to questions re initial test program requirements.
DELGEORGE, L. O. Commonwealth Edison Co. 79/08/03. 34pp.

7908300295 Forwards request for addl info re core performance, to continue FSAR evaluation.
PARR, O. D. Light Water Reactors Branch 3. 79/08/08. 3pp.

7908170065 Responds to 790706 FOIA request for documents re facility const delays. Forwards list of requested documents which have been placed in PDR.
FELTON, J. M. Division of Rules and Records. 79/08/10. 2pp.

7908210571 Submits info requested at 790524 meeting re NSSS equipment to be used at LaSalle County which is not common to equipment used at Zimmer, in order to minimize repeated effort in examining environ qualification records.
DELGEORGE, L. O. Commonwealth Edison Co. 79/08/14. 2pp.

7908230420 Informs that BWR operating plant owners group GE rept, NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs" was submitted to NRC by 790817 ltr from TD Keenan to D Ross. Remainder of info follows in 791116 rept.
JANECEK, R. F. Commonwealth Edison Co. 79/08/20. 1p.

F Security, medical, emergency & fire protection plans

7908200338 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/08/06. 1p.

Q Adjudicatory correspondence

7908280552 Forwards petition by Citizens Against Nuclear Power, IL Valley Citizens Against Nuclear Power, Citizens United for Responsible Energy & Appleseed for NRC to institute proceeding to suspend &/or revoke license.
KODNER, J. L. Affiliation Unknown. 79/08/21. 1p.

--7908280553 Petition by Citizens Against Nuclear Power, IL Valley Citizens Against Nuclear Power, Citizens United for Responsible Energy & Appleseed to institute proceeding to suspend &/or revoke license.
* Affiliation Unknown. 79/08/21. 6pp.

I. Financial information

7908090558 Responds to 790129 request for financial info, completing commitment in LO Delgeorge 790409 ltr. Info includes regulation of retail business & recent rate increase testimony. Exhibits encl.
DELGEORGE, L. O. Commonwealth Edison Co. 79/05/02. 58pp.

P. Operating license stage documents & correspondence

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co. 79/07/30. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908010237 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Item 3 Disusses SAP/PISYS computer programs & verification procedure.
REED, C. Commonwealth Edison Co. 79/06/01. 3pp.

7908010085 Forwards IE Insp Repts 50-373/79-22, 50-374/79-16, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07. No noncompliance noted.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/12. 2pp.

--7908010193 IE Insp Repts 50-373/79-22, 50-374/79-09, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07 on 790521. No noncompliance noted. Major areas inspected: fuel loading schedule, electrical area & QA personnel.
HAYES, D. W., BARRETT, P. A., FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/07. 4pp.

7908080180 Forwards IE Insp Rept 50-373/79-23 on 790525, 29-30 & 0601. No noncompliance noted.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/06/19. 2pp.

--7908080194 IE Insp Rept 50-373/79-23 on 790525, 29-30 & 0601. No noncompliance noted. Major areas inspected: station operating procedures.
WALKER, R. D., SPESSARD, R. L. Region 3, Chicago, Office of the Director. 79/06/18. 4pp.

7908010304 Discusses 790417 response to notice of violation in IE Insp Rept 50-373/79-06. Procedures used to assure reflushing after maint or mod of sys still remain item of noncompliance.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/21. 4pp.

--7908010308 Forwards response to IE Insp Rept 50-373/79-06 & notice of violation. Disagrees w/noncompliance item re dc distribution preoperational test PT-AP-102. Considers test to be complete & in conformance w/manufacturer instructions.
REED, C. Commonwealth Edison Co. 79/04/17. Encl.

7908030037 Responds to IE Bulletin 78-12. Plant evaluations were submitted by GE & Westinghouse. Evaluation of LaSalle Unit 2 will be submitted by 790817. Forwards summary of documentation for each plant.
REED, C. Commonwealth Edison Co. 79/06/21. 3pp.

7908170173 Forwards IE Insp Repts 50-373/79-21 & 50-374/79-15 on 790529-31. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/27. 2pp.

--7908170179 IE Insp Repts 50-373/79-21 & 50-374/79-15 on 790529-31. No noncompliance noted. Major areas inspected: activities relative to safety-related heating, ventilation & air conditioning sys & electrical work activities.
BARRETT, P. A., NEISLER, J. H., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 79/06/22. 14pp.

7908280153 Submits supplemental response to IE Bulletin 79-09. GE Type AK-2 & AK-2A breakers in use in distribution equipment & 480 volt alternating current substations. Preventive maint program initiated.
REED, C. Commonwealth Edison Co. 79/06/28. 3pp.

7908280503 Forwards IE Insp Rept 50-373/79-25 on 790618. No noncompliance noted.
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/29. 2pp.

--7908280508 IE Insp Rept 50-373/79-25 on 790618. No noncompliance noted. Major areas inspected: radiation protection & radwaste mgt programs.
MILLER, D. E. Region 3, Chicago, Office of the Director. FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/27. 2pp.

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co. 79/07/05. 9pp.

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc. 79/05/31. 24pp.

7908090646 Advises that first page of ltr accompanying Insp Repts 50-373/79-17 & 50-374/79-11, identifying dockets as 50-454 & 50-455, should be corrected. Dockets should be identified as 50-373 & 50-374. Corrected page encl.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/18. 1p.

7908150439 Forwards responses to IE Bulletins 79-12, 12A & 12B re atypical weld matl in reactor pressure vessel welds.
REED, C. Commonwealth Edison Co. 79/07/18. 3pp.

7908130455 Responds to IE Bulletin 79-11. Westinghouse DB-50 & DB-75 circuit breakers not used at plants.
REED, C. Commonwealth Edison Co. 79/07/19. 1p.

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED, C. Commonwealth Edison Co. 79/08/01. 2pp.

7908150292 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908080639 Approves 790521 request to apply approved ASME Code Case N-240, exempting piping subject to ASME code from hydrostatic testing. Code case may be ref in FSAR.
PARR, O. D. Light Water Reactors Branch 3. 79/06/05. 1p.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908080619 Confirms 790604 telcon w/HD Scholl of SEC re possible inaccuracies or omissions in util registration statement. No inaccuracies identified. Encl available in Central Files.
BOURNIA, A. Light Water Reactors Branch 3. 79/06/07. 1p.

7908080528 FOIA request for records re reasons for delay in startup of operation.
MCCULLOUGH, E. R. McCullough, E. R. 79/06/15. 1p.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
RODD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908170068 FOIA request for all documents pertinent to facility const delays.
GOGOL, E. Citizens Against Nuclear Power. 79/07/06. 2pp.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W. F. Standardization Branch. 79/07/11. 26pp.

7908080162 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 2pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 58pp.

7908150177 Forwards list of addl info about power sys to continue FSAR review & evaluation.
PARR, O. D. Light Water Reactors Branch 3. 79/07/19. 4pp.

7908160309 Forwards request for addl info re sys capable of providing post-accident & transient core coolinn & containment isolation.
PARR, O. D. Light Water Reactors Branch 3. 79/07/23. 19pp.

7908080540 Responds to FOIA request for records re reasons for delay in startup of operation. Forwards 781215 Bournia memo & 790122 Parr ltr to DeIGeorge.
FELTON, J. M. Division of Rules and Records. 79/07/30. 12pp.

--7908080549 Forwards list of outstanding issues in SER.
PARR, O. D. Light Water Reactors Branch 3. 79/02/05. 26pp.

7908090344 Forwards responses to questions re initial test program requirements.
DELGEORGE, L. O. Commonwealth Edison Co. 79/08/03. 34pp.

7908300295 Forwards request for addl info re core performance, to continue FSAR evaluation.
PARR, O. D. Light Water Reactors Branch 3. 79/08/08. 3pp.

7908170065 Responds to 790706 FOIA request for documents re facility const delays. Forwards list of requested documents which have been placed in PDR.
FELTON, J. M. Division of Rules and Records. 79/08/10. 2pp.

7908210571 Submits info requested at 790524 meeting re NSSS equipment to be used at LaSalle County which is not common to equipment used at Zimmer, in order to minimize repeated effort in examining environ qualification records.
DELGEORGE, L. O. Commonwealth Edison Co. 79/08/14. 2pp.

7908230420 Informs that BWR operating plant owners group GE rept, NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs" was submitted to NRC by 790817 ltr from TD Keenan to D Ross. Remainder of info follows in 791116 rept.
JANECEK, R. F. Commonwealth Edison Co. 79/08/20. 1p.

F. Security, medical, emergency & fire protection plans

7908200338 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/08/06. 1p.

G. Adjudicatory correspondence

7908280552 Forwards petition by Citizens Against Nuclear Power, IL Valley Citizens Against Nuclear Power, Citizens United for Responsible Energy & Appleseed for NRC to institute proceeding to suspend &/or revoke license.
KODNER, J. L. Affiliation Unknown. 79/08/21. 1p.

--7908280553 Petition by Citizens Against Nuclear Power, IL Valley Citizens Against Nuclear Power, Citizens United for Responsible Energy & Appleseed to institute proceeding to suspend &/or revoke license.
* Affiliation Unknown. 79/08/21. 6pp.

I. Financial information

7908090558 Responds to 790129 request for financial info, completing commitment in LO Delgeorge 790409 ltr. Info includes regulation of retail business & recent rate increase testimony. Exhibits encl.
DELGEORGE, L. O. Commonwealth Edison Co. 79/05/02. 58pp.

P. Operating license stage documents & correspondence

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co. 79/07/30. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908020237 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Item 3 Disusses SAP/PISYS computer programs & verification procedure.
REED, C. Commonwealth Edison Co. 79/06/01. 3p.

7908010085 Forwards IE Insp Repts 50-373/79-22, 50-374/79-16, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07. No noncompliance noted.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/12. 2pp.

--7908010193 IE Insp Repts 50-373/79-22, 50-374/79-09, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07 on 790521. No noncompliance noted. Major areas inspected: fuel loading schedule, electrical area & QA personnel.
HAYES, D. W., BARRETT, P. A., FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/07. 4pp.

7908030037 Responds to IE Bulletin 78-12. Plant evaluations were submitted by GE & Westinghouse. Evaluation of LaSalle Unit 2 will be submitted by 790817. Forwards summary of documentation for each plant.
REED, C. Commonwealth Edison Co. 79/06/21. 3pp.

7908170173 Forwards IE Insp Repts 50-373/79-21 & 50-374/79-15 on 790529-31. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/27. 2pp.

--7908170179 IE Insp Repts 50-373/79-21 & 50-374/79-15 on 790529-31. No noncompliance noted. Major areas inspected: activities relative to safety-related heating, ventilation & air conditioning sys & electrical work activities.
BARRETT, P. A., NEISLER, J. H., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 79/06/22. 14pp.

7908280453 Submits supplemental response to IE Bulletin 79-09. GE Type AK-2 & AK-2A breakers in use in distribution equipment & 480 volt alternating current substations. Preventive maint program initiated.
REED, C. Commonwealth Edison Co. 79/06/28. 3pp.

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co. 79/07/05. 9pp.

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc. 79/05/31. 24pp.

7908090646 Advises that first page of ltr accompanying Insp Repts 50-373/79-17 & 50-374/79-11, identifying dockets as 50-454 & 50-455, should be corrected. Dockets should be identified as 50-373 & 50-374. Corrected page encl.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/18. 1p.

7908130455 Responds to IE Bulletin 79-11. Westinghouse DB-50 & DB-75 circuit breakers not used at plants.
REED, C. Commonwealth Edison Co. 79/07/19. 1p.

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.


IMAGE EVALUATION
TEST TARGET (MT-3)
1.0
1.1
1.25
1.4
1.6
1.8
2.0
2.2
2.5
2.8
3.2
3.6
4.0
4.5
5.0
6"
MICROCOPY RESOLUTION TEST CHART





IMAGE EVALUATION
TEST TARGET (MT-3)



MICROCOPY RESOLUTION TEST CHART



7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED, C. Commonwealth Edison Co. 79/08/01. 2pp.

7908150290 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

S Reportable occurrences, LERs & related correspondence

7908030374 Ack receipt of 790606 interim rept on vent stack per 10CFR50.55. Final rept will be reviewed upon receipt.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/19. 1p.

DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

Q Inspection reports, IE Bulletins & correspondence

7908140083 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10. 1p.

7908310168 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020248 Summary of 790522 meeting w/Ebasco, Law Engineering & LA Power & Light Co in LA re geology & soil conditions on & around site.
BENEDICT, R. A. Light Water Reactors Branch 2. 79/06/08. 2pp.

7908030250 Forwards request for addl info, including Questions 231.4-231.20, re reactor fuel. Forwards Question 371.10 re hydrology, which was discussed during 790523 site visit.
BAER, R. L. Light Water Reactors Branch 2. 79/06/11. 12pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRR CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908170078 Discusses status of program to upgrade bases section of STS & fee exemption approval.
BAER, R. L. Light Water Reactors Branch 2. 79/07/18. 2pp.

7908080185 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/19. 2pp.

7908160064 Summary of 790716 meeting w/util re timing of environ review & NRC info requirements for alternative site revisions.
COTA, P. C. Environmental Projects Branch 1. 79/07/27. 2pp.

7908220532 Submits request for addl info re power sys & conduct of operations.
BAER, R. L. Light Water Reactors Branch 2. 79/08/02. 18pp.

7908130398 Responds to NRC 781121 request that util re-examine 780728 petition for partial exemption to 10CFR21. Partial exemption is no longer required for GE Type CR terminal blocks in nine safety-related panels.
ASWELL, D. L. Louisiana Power & Light Co. 79/08/07. 1p.

7908220274 Notification of 790822 meeting w/Middle South Svcs, Inc to discuss topical rept on reactor physics methods for use at facilities.
FIENO, D. Core Performance Branch. 79/08/09. 2pp.

C Utility Environmental Report (ER), amends & correspondence

7908230243 Forwards updated list to be used in distributing amend to environ rept.
BALLARD, R. L. Environmental Projects Branch 1. 79/08/03. 5pp.

G Adjudicatory correspondence

7906070005 Forwards "Summary of Operating Experience w/Recirculating Steam Generators, dtd Jan 1979" & director denial of 10CFR2.206 request" in Vogtle proceeding. W/o encl.
MCGURREN, H. J. Branch 1. 79/04/18. 1p.

7908210042 Responds to ASLB 790426 request for info re New Orleans States Item 790403 article on defects in concrete work. Forwards IE 790404 memo. Concerns are baseless.
MCGURREN, H. J. Branch 1. 79/05/30. 1p.

--7908210046 Notifies of discussion w/J Amoss, author of New Orleans States Item 790403 article on defects in concrete work. Concerns are baseless.
HALL, R. E. Office of Inspection & Enforcement, Office of the Director. 79/04/04. 2pp.

7907110398 Requests rejection of Save Our Wetlands, Inc & Oystershell Alliance, Inc unstipulated Contentions 8-14 & 22. Contentions lack requisite basis & specificity required by 10CFR2.714(b). Certificate of Svc encl.
MCGURREN, H. J. Branch 1. 79/06/01. 12pp.

7908030418 FOIA request for all correspondence on or after 790328, wherein possibility of delay of OL proceedings was communicated to parties other than NRC.
IRVING, S. M. Public Law Utilities Group. 79/06/07. 2pp.

7908070736 Order ([illegible]onse to Oystershell Alliance, Inc & Save Our Wetlands, Inc 790[illegible] Motion. Motion is granted re correspondence. All other documents must be filed in triplicate & copies given to each ASLB member.
WOLFE, S. J. Atomic Safety and Licensing Board Panel. 79/06/27. 1p.

7908150435 Forwards order extending const completion date, evaluation of request for extension of CPPR-103 & EIS, in response to 770623 & 780905 request.
VASSALLO, D. B. Division of Project Management. 79/07/19. 2pp.

--7908150441 Order extending const completion date to 820601.
VASSALLO, D. B. Division of Project Management. 79/07/19. 2pp.

--7908150447 Safety evaluation of request to extend CPPR-103 to 820601. Recommends issuing order to extend date.
BENEDICT, R. A., BAER, R. L. Light Water Reactors Branch 2. 79/07/19. 3pp.

--7908150454 EIA supporting extension of CPPR-103 expiration date to 820601.
* Division of Site Safety & Environmental Analysis. 79/07/19. 4pp.

7908030425 Responds to FOIA request for documents on or after 790328 re OL delay. Forwards SECY-79-344, "Interim Nuclear Reactor Regulation Organization to Deal W/Impacts of TMI-2 & Other Nuclear Reactor Regulation Priority Tasks."
FELTON, J. M. Division of Rules and Records. 79/07/25. 1p.

F Utility Final Safety Analysis Report (FSAR) & amends

7908[illegible]465 Forwards Amend 6 to FSAR, in response to NRC request for info. Amend 7 scheduled for submittal 790924.
ASWELL, D. L. Louisiana Power & Light Co. 79/08/21. 4pp.

--7908270472 Amend 6 to FSAR.
* Louisiana Power & Light Co. 79/08/21. 600pp.

Q Inspection reports, IE Bulletins & correspondence

7908020276 Responds to IE Bulletin 79-07. Algebraic summation methods are not used by Ebasco & C-E in ref to seismic stress analysis. PIPESTRESS 2010 used for Ebasco piping analyses.
ASWELL, D. L. Louisiana Power & Light Co. 79/06/01. 2pp.

7908150111 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breakers are used in safety-related equipment Preventive maint program is being developed.
ASWELL, D. L. Louisiana Power & Light Co. 79/06/15 2pp.

7908100210 Forwards IE Insp Rept 50-382/79-06 on 790529-31 & 0601 No noncompliance noted.
SEIDLE, W. C. Region 4, Dallas, Office of the Director 79/06/20 2pp.

--7908100217 IE Insp Rept 50-382/79-06 on 790529-31 & 0601 No noncompliance noted Major areas inspected safety-related const activities, licensee followup re previously-noted item of noncompliance & status review of const deficiency.
MARTIN, L. E., CROSSMAN, W. A., HALL, R. E. Region 4, Dallas, Office of the Director 79/06/20 6pp.

7908150145 Submits final response to IE Bulletins 78-12, 12A & 12B C-E 790608 generic rept addresses all applicable matl in reactor vessel Vendor certification encl.
ASWELL, D. L. Louisiana Power & Light Co. 79/06/29 3pp.

7908150130 Responds to IE Bulletin 79-02 Base plates using concrete expansion anchor bolts to support Seismic Category I piping have been reviewed Majority of base plates may require design mod. Installation of work acceptable.
ASWELL, D. L. Louisiana Power & Light Co. 79/07/09 2pp.

7908310475 Responds to IE Bulletin 79-11 No Westinghouse DB-50 or DB-75 circuit breakers are installed or planned for installation at facility.
ASWELL, D. L. Louisiana Power & Light Co. 79/07/12 1p.

7908010325 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/07/17 1p.

7908020397 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/07/18 1p.

7908160128 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/08/06 1p.

7908290157 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/08/14 1p.

7908290701 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/08/15 1p.

S. Reportable occurrences, LERs & related correspondence

7908170487 Discusses Zurn Industries 790503 ltr to NRC re mechanical draft cooling towers in component cooling water sys. Test of actual installation best way to verify model test results & confirm all contract requirements are met by Zurn.
ASWELL, D. L. Louisiana Power & Light Co. 79/06/07 57pp.

7908010717 Forwards PNO-79-67AX.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/20 1p.

DOCKET 50-383 WATERFORD GENERATING STATION, UNIT 4

A. Application/construction stage documents & correspondence

7908160064 Summary of 790716 meeting w/util re timing of environ review & NRC info requirements for alternative site revisions.
COTA, P. C. Environmental Projects Branch 1 79/07/27 2pp.

DOCKET 50-386 NYC HALL OF SCIENCE RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

7908160025 Supplements 790510 ltr re IE Bulletin 79-09 GE Type AK-2A-25-1 circuit breakers are installed in nine locations in reactor trip switchgear of Unit 2 Corrective actions are being developed to conform w/GE Advice Ltr 175.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/22 1p.

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments. W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908030340 Notifies NCR that concrete work on cooling tower veils will resume on or about 790613.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/06/07 1p.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

7908270287 Notification of 790724-25 meeting in Bethesda, MD w/Mark II owners group to discuss condensation oscillation testing, world test monitoring & functional capacity. Agenda encl.
ANDERSON, C. J. Containment Systems Branch 79/07/03 4pp.

7908300457 Forwards request for addl info re LOCA & safety relief valve pool dynamic loads in area of containment systems.
PARR, O. D. Light Water Reactors Branch 3 79/07/04 6pp.

7908080209 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/20 2pp.

7908200079 Forwards second round questions re hydraulic engineering, for review of OL application.
PARR, O. D. Light Water Reactors Branch 3 79/07/23 2pp.

--7908200084 Second round questions re performance criteria regarding flood protection, identification of doors providing flood protection & Tech Specs insuring that doors will be closed during flood.
* Light Water Reactors Branch 3 79/07/23 1p.

7908060256 Discusses status of plans to perform full scale test to confirm oscillation load specs. Requests witnessing of test runs during week of 791112. Test matrix & plan will be forwarded in Sept.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/07/31 1p.

7908150655 Advises that GRI Intl has begun work on planned safety relief valve bubble load test to be run in suppression pool of Unit 1. Data from test to serve as basis for reduction of both pool boundary & submerged structure load specs.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/08/07 1p.

7908140630 Notifies that utils have formed Intermediate BWR Plant Owners Group to coordinate evaluation of knowledge & experience gained & lessons learned from TMI. Requests meeting on 790816 to discuss proposed actions.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/08/08 2pp.

7908270410 Comments on draft EIS. Sediment & erosion control should be discussed re certain PA state regulations & impact on farm & agricultural land should be displayed.
MUNKITTRICK, G. T. Agriculture, Dept. of 79/08/20 1p.

7908280670 Invites NRC representatives to participate in meetings of Emergency Plan Advisory Committee formed to review emergency plans.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/08/22 1p.

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7908060139 Forwards DES for review. Comments due 45 days after publication of FR notice. W/o encl.
REGAN, W. H. Environmental Projects Branch 2 79/06/28 7pp.

7908080560 Forwards DES & notice of availability.
SELLS, D. E. Environmental Projects Branch 2 79/06/29 2pp.

--7908080562 Notice of availability of DES for facility.
SELLS, D. E. Environmental Projects Branch 2. 79/06/27. 2pp.

--7908080565 DES re operation of facility.
* Office of Nuclear Reactor Regulation. NUREG-0564. 79/06/30. 300pp.

7908070591 Advises that evaluation of DES has been completed. Offers no substantive comments.
TREADWELL, J. R. Housing & Urban Development, Dept of. 79/07/31. 1p.

7908170394 Submits comments re draft Rept. Rept did not discuss impact on existing highways re traffic traveling to & from plant.
COOPER, G. H. Transportation, Dept of. 79/08/09. 1p.

7908140725 Requests extension to 791021 to comment on DES.
ROBINSON, D. E. Affiliation Unknown. 79/08/10. 2pp.

7908210412 Submits recommendations re DES (NUREG-0564). Emergency evacuation plan must be completed by county civil defense agency & addl source of water available other than Susquehanna River & Pond Hill Reservoir before startup.
HEISELBERG, E. Affiliation Unknown. 79/08/10. 2pp.

7908210522 Requests that deadline for public comments on DES be extended to 791201 to allow interested persons to have benefit of TMI rept before making comments.
PRATT, R. Sierra Club. 79/08/13. 1p.

7908210409 Discusses DES re use of 2,4,5-T weed control agent in rights-of-way. Study of coal & U fuel cycles should include indirect effect of mining on landscape.
VANDENBURG, D. O. Agriculture, Dept of. 79/08/14. 1p.

7908210365 Discusses flaws in DES, including failure to mention effects of radiation & radioactive waste disposal, archeological survey of site & transmission lines & cost-benefit comparison of coal & nuclear energy.
DRAIDOWSKI, T. A. Sierra Club. 79/08/15. 1p.

7908210311 Submits summary of areas of concern re DES. Requests extension in order to continue review & file more detailed comments.
MANN, D. Susquehanna Alliance. 79/08/17. 4pp.

7908210557 Forwards comments on DES. Document & proposal have been classified as Environ Rept 2. DES contains insufficient info to fully assess environ impact.
POMPONIO, J. R. Environmental Protection Agency. 79/08/17. 11pp.

7908230488 Opposes piecemeal preparation of DES. Disjointed approach prevents assessment of overall impact on human environ. Legal action may be taken to prevent continued use of approach.
HALLIGAN, T. J. Citizens Against Nuclear Dangers. 79/08/18. 2pp.

7908240535 Comments on DES. Environ impact of meltdown should be considered in evaluating economic factors. Facility is economically uncompetitive w/alternate energy sources.
SHELLY, F. L. Affiliation Unknown. 79/08/18. 5pp.

7908280614 Submits comments on DES, NUREG-0564. Evaluation of Ra-222 emission is incorrect. Only proper evaluation is w/no temporal cutoff. Such evaluation indicates underestimation of health consequences.
LOCHSTET, W. A. Affiliation Unknown. 79/08/19. 12pp.

F. Security, medical, emergency & fire protection plans.

7908290606 Responds to 790305 request re NRC participation during radiation emergency. NRC conducts investigations, verifies implementation of emergency plans, assists DOE & provides assistance to state & local agencies.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/23. 1p.

7908280032 Forwards Amend 15 to QL containing Revision C to physical security plan. Plan withheld (ref 10CFR2.790).
CURTIS, N. W. Pennsylvania Power & Light Co. 79/08/23. 1p.

G. Adjudicatory correspondence

7908020574 First round of interrogatories & document requests for intervenor Citizens Against Nuclear Dangers. Requests info re health effects, peak electrical load & radiation exposure. Certificate of Svc encl.
CUTCHIN, J. M. Branch 2. 79/05/21. 11pp.

--7908020578 Response submitted by intervenor Citizens Against Nuclear Dangers to NRC 790521 & util 790525 discovery requests. Each & every question is not applicable to intervenors. Certificate of Svc encl.
LEMANOWICZ, I. Citizens Against Nuclear Dangers. 79/06/16. 7pp.

7906260390 Motion for ASLB ruling on revision of preliminary timetable in case to coincide w/TMI developments & forthcoming NRC task force recommendations. Certificate of Svc encl.
LEMANOWICZ, I. Citizens Against Nuclear Dangers. 79/06/22. 3pp.

7906270329 Responds to request for documents per discovery requests re interrogatories directed to NRC. Forwards list of locations.
CUTCHIN, J. M. Branch 3. 79/06/27. 5pp.

7908080011 Response submitted by util to intervenor Citizens Against Nuclear Dangers 790522 interrogatories & document requests. Forwards list of documents available. Submits info re annual rept & litigation.
SILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge. BARBERICK, W. Pennsylvania Power & Light Co. 79/06/29. 16pp.

7908080015 Response submitted by Commonwealth of PA to intervenor Citizens Against Nuclear Danger first round discovery requests. Forwards list of documents re plant in files of PA De, t of Environ Resources. W/o encl.
CARTER, K. W. Pennsylvania, State of. 79/06/29. 5pp.

--7908080018 Response submitted by Commonwealth of PA to intervenor Environ Coalition on Nuclear Power first round discovery requests. Submits info re documents on TMI, emergency plans & radiation monitoring. Certificate of Svc encl.
CARTER, K. A. Pennsylvania, State of. 79/06/29. 7pp.

7908080029 Objection by licensees to Citizens Against Nuclear Dangers 790522 interrogatories & document requests. Objects to Interrogatories 2, 5, 6, 8, 10-12, 14, 15 & 18 & to portions of Interrogatories 3, 9 & 17.
SILBERG, J. E., YUSPEH, A. R. Shaw, Pittman, Potts, & Trowbridge. 79/06/29. 8pp.

7908080060 Response by util to intervenor Environ Coalition on Nuclear Power 790525 first round interrogatories & document requests. Submits info re evacuation plans, radiation monitoring & herbicides. Affidavit of W Barberick encl.
SILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge. BARBERICK, W. Pennsylvania Power & Light Co. 79/06/29. 11pp.

7908300021 Certificate of Svc averring listed parties have been sent applicant answers to Citizens Against Nuclear Dangers interrogatories & document requests & applicant objections.
SILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge. 79/06/29. 2pp.

7908300038 Forwards Exhibits E-1, E-3, E-5, answers to Environ Coalition on Nuclear Power 790629 first round discovery requests & Certificate of Svc. Only Certificate of Svc encl.
SNAPP, B. A. Pennsylvania Power & Light Co. 79/06/29. 2pp.

7908300341 Request by intervenor Environ Coalition on Nuclear Power that MK Creasy 790711 deposition be delayed. C Kepford & JH Johnson will not be able to attend session. Certificate of Svc encl.
JOHNSON, J. H. Environmental Coalition on Nuclear Power. 79/06/29. 2pp.

7908300353 Requests that ASLB issue protective order re applicant first round interrogatories. Questions are repetitive of NRC questions & very detailed. No objection to answering limited number of pertinent questions.
JOHNSON, J. H. Environmental Coalition on Nuclear Power. 79/06/29. 2pp.

--7908300369 Responds to NRC interrogatories. Answers general questions & specific questions re Contentions 1-3, 5-9 & 18. Certificates of Svc encl.
JOHNSON, J. H. Environmental Coalition on Nuclear Power. 79/06/29. 9pp.

7908080044 Motion pro se & on behalf of eleven intervenors that NRC revise preliminary timetable & extend for six to 12 months time to pose & answer first round discovery requests. Certificate of Svc encl.
MARSH, / Affiliation Unknown. 79/07/02. 3pp.

7908300128 Comments re rule for protection of spent fuel in transit, per ASLB 790618 order. Rule has no effect on rejected contentions. Contentions were properly rejected. Certificate of Svc encl.
CUTCHIN, J. M. Branch 3. 79/07/02. 5pp.

7908300756 Requests by intervenors Citizens Against Nuclear Dangers that ASLB reconsider Contention 12 re transportation of nuclear fuel. Roadbeds & rail trackage are deteriorating. Certificate of Svc encl.
HALLIGAN, T. J. Citizens Against Nuclear Dangers. 79/07/07. 2pp.

7908220026 Request submitted by licensee that ASLB compel intervenor Susquehanna Environ Advocates to answer 790525 first set of interrogatories & document its requests per 10CFR2.740(f). Certificate of Svc encl.
GILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge. 79/07/10. 4pp.

7908070635 Criticizes div for granting util provisional OL w/o conclusive study of TMI impact.
OBERST, D. Affiliation Unknown. 79/07/28. 2pp.

7908140572 Protests DES recommending issuance of OL. Advocates use of coal & alternate energy resources.
JEPPSEN, H. C. Affiliation Unknown. 79/08/08. 1p.

7908160406 Opposes issuance of facility licenses until problems of waste disposal have been solved & assurance can be given that low level radiation will not be harmful to population or environ.
HERSHEY, M. L. Affiliation Unknown. 79/08/11. 1p.

7908200363 Opposes nuclear reactors & waste of electricity.
MOSES, L. Affiliation Unknown. 79/08/14. 1p.

7908280583 Opposes proposed operation of nuclear reactors at Berwick, PA. Considers DES unfair to alternate sources of energy & criticizes cost/benefit analysis.
HUNTINGTON, M. Affiliation Unknown. 79/08/19. 8pp.

7908270390 Comments on DES. Urges denial of OL. Facility is not needed & is unsafe.
THOMPSON. Affiliation Unknown. 79/08/20. 2pp.

7908310361 Disagrees w/need for addl nuclear reactors. Would like to see env rpt statement prepared by someone other than util.
LAUGHL, ND. S. Affiliation Unknown. 79/08/31. 1p.

H. General correspondence.

7908270495 Comments on DES. Expresses concern re facility safety & damage to character of area.
SHORTZ, S. Affiliation Unknown. 79/08/20. 2pp.

K. Utility Final Safety Analysis Report (FSAR) & amends.

7908070668 Forwards Amend 14 to OL application, containing Revision 11 to FSAR.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/07/31. 1p.

--7908070682 Amend 14 to OL application, containing Revision 11 to FSAR.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/07/19. 448pp.

Q. Inspection reports, IE Bulletins & correspondence.

7908130662 Forwards IE Insp Rept 50-387/79-17 on 790508-10. No noncompliance noted.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/06/22. 2pp.

--7908130663 IE Insp Rept 50-387/79-17 & on 790508-10. No noncompliance noted. Major areas inspected: preoperational test program, document control, design changes & mods, plant & preventive maint, equipment protection & cleanliness.
NICHOLAS, H. H., MCNATT, T. G. Region 1, Philadelphia, Office of the Director. CAPHTON, D. L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/06/15. 5pp.

7908140340 Requests that one Unit 1 nozzle safe-end to safe-end extension weld be retained for NRC examination along w/N2G nozzle & copies of ultrasonic test data.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/07/02. 1p.

7908070288 Forwards response to IE Bulletin 79-02 re review of design & installation procedures for concrete expansion anchor bolts used in pipe support base plates for Seismic Category I sys. Calculation sheets & tables encl.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/07/06. 77pp.

7908070462 Responds to IE Bulletins 78-12, 12A & 12B. CB&I generic rept submitted to NRC adequately represents data for Unit 1 & 2 vessels. No archival matl found.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/07/13. 1p.

7908010522 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060492 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030274 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908290660 Responds to IE Bulletin 79-11 Westinghouse Type DB-50 & DB-75 circuit breakers not included in safety-related design applications.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/07/19. 1p.

7908200274 Ack receipt of 790716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-15 & 50-388/79-09.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/07/24. 1p.

--7908200277 Responds to NRC 790612 ltr re violations noted in IE Insp Repts 50-387/79-15 & 50-388/79-09. Corrective actions: tack welds on weld joint DCA-141-1-FW2 removed & failure of purge gas application clarified.
SABOL, A. R. Pennsylvania Power & Light Co. 79/07/16. 3pp.

--7908200280 Forwards IE Insp Repts 50-387/79-15 & 50-388/79-09 on 790402-27 & notice of violation.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/06/12. 2pp.

--7908200283 Notice of violation from insp on 790402-27.
*. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/06/08. 2pp.

--7908200288 IE Insp Repts 50-387/79-15 & 50-388/79-09 on 790402-27. Noncompliance noted: failure to inspect purging for tack welds & failure to provide documented instruction to control storage & maint insps of reactor pressure vessel.
GALLA, R. M., CERNE, A. C., MCGAUGHY, R. W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/06/08. 15pp.

7908100266 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908090327 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/30. 1p.

7908280172 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908280327 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310299 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300177 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence.

7908080684 Notifies of deficiency discovered 780913 re s/KSV power engine supplied by Cooper Energy Svc. Some sub-assemblies showed abnormal wear on surface of roller pin. Roller pin will be redesigned.
BENDER, B. B. Cooper Industries, Cooper-Bessemer Co. Div. 78/11/03. 2pp.

7908140746 Ack 790507 & 29 ltrs forwarding final deficiency rept re standby diesel generator.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/06 1p

--7908140753 Responds to 781103 deficiency rept by Cooper-Bessemer re study indicating abnormal wear on surface of roller pin in crosshead assembly of SSES standby diesel generator. Rept acceptable as interim rept.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/05/07 2pp

7908170087 Ack receipt of 790522 & 0628 ltrs forwarding interim rept re deficiency in solenoid valves. Expects to receive final rept on 790815.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/07/13 1p

7908140430 Amends 790323, 0522 & 0628 ltrs on deficiency rept re circle seal solenoid valves w/defective diodes. Determines condition not reportable.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/08/08 2pp

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908030340 Notifies NCR that concrete work on cooling tower walls will resume on or about 790613.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/06/07 1p

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908300457 Forwards request for addl info re LOCA & safety relief valve pool dynamic loads in area of containment systems.
PARR, O. D. Light Water Reactors Branch 3 79/07/04 6pp

7908080209 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/20 2pp

7908200079 Forwards second round questions re hydraulic engineering, for review of OL application.
PARR, O. D. Light Water Reactors Branch 3 79/07/23 2pp

--7908200084 Second round questions re performance criteria regarding flood protection, identification of doors providing flood protection & Tech Specs insuring that doors will be closed during flood.
* Light Water Reactors Branch 3 79/07/23 1p

7908060256 Discusses status of plans to perform full scale test to confirm oscillation load specs. Requests witnessing of test runs during week of 791112. Test matrix & plan will be forwarded in Sept.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/07/31 1p

7908150655 Advises that SRI Intl has begun work on planned safety relief valve bubble load test to be run in suppression pool of Unit 1. Data from test to serve as basis for reduction of both pool boundary & submerged structure load specs.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/08/07 1p

7908140630 Notifies that utils have formed Intermediate BWR Plant Owners Group to coordinate evaluation of knowledge & experience gained & lessons learned from TMI. Requests meeting on 790816 to discuss proposed actions.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/08/08 2pp

7908270410 Comments on draft E,S Sediment & erosion control should be discussed re certain PA state regulations & impact on farm & agricultural land should be displayed.
MUNKITTRICK, G. T. Agriculture, Dept of 79/08/20 1p

7908280670 Invites NRC representativrs to participate in meetings of Emergency Plan Advisory Committee formed to review emergency plans.
CURTIS, N. W. Pennsylvania Power & Light Co. 79/08/22 1p

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7908060139 Forwards DES for review. Comments due 45 days after publication of FR notice. W/o encl.
REGAN, W. H. Environmental Projects Branch 2 79/06/28 7pp

7908080560 Forwards DES & notice of availability.
SELLS, D. E. Environmental Projects Branch 2 79/06/28 2pp

--7908080562 Notice of availability of DES for facility.
SELLS, D. E. Environmental Projects Branch 2 79/06/27 2pp

--7908080565 DES re operation of facility.
* Office of Nuclear Reactor Regulation NUREG-0564 79/06/30 300pp

7908070591 Advises that evaluation of DES has been completed. Offers no substantive comments.
TREADWELL, J. R. Housing & Urban Development, Dept of 79/07/31 1p

7908170394 Submits comments re draft Rept. Rept did not discuss impact on existing highways' re traffic traveling to & from plant.
COOPER, S. H. Transportation, Dept of 79/08/09 1p

7908140725 Requests extension to 791021 to comment on DES.
ROBINSON, D. E. Affiliation Unknown 79/08/10 2pp

7908210412 Submits recommendations re DES (NUREG-0564). Emergency evacuation plan must be completed by county civil defense agency & addl source of water available other than Susquehanna River & Pond Hill Reservoir before startup.
HEISELBERG, E. Affiliation Unknown 79/08/10 2pp

7908210522 Requests that deadline for public comments on DES be extended to 791201 to allow interested persons to have benefit of TMI rept before making comments.
PRATT, R. Sierra Club 79/08/13 1p

7908210409 Discusses DES re use of 2,4,5-T weed control agent in rights-of-way. Study of coal & U fuel cycles should include indirect effect of mining on landscape.
VANDENBURG, D. O. Agriculture, Dept of 79/08/14 1p

7908210365 Discusses flaws in DES, including failure to mention TMI, radiation & radioactive waste disposal, archeological survey of site & transmission lines & cost-benefit comparison of coal & nuclear energy.
DRAZDOWSKI, T. A. Sierra Club 79/08/15 1p

7908210311 Submits summary of areas of concern re DES. Requests extension in order to continue review & file more detailed comments.
MANN, D. Susquehanna Alliance 79/08/17 4pp

7908210557 Forwards comments on DES. Document & proposal have been classified as Environ Rept 2. DES contains insufficient info to fully assess environ impact.
POMPONIO, J. R. Environmental Protection Agency 79/08/17 11pp

7908230488 Opposes piecemeal preparation of DES. Disjointed approach prevents assessment of overall impact on human environ. Legal action may be taken to prevent continued use of approach.
HALLIGAN, T. J. Citizens Against Nuclear Dangers 79/08/18 2pp

7908240535 Comments on DES. Environ impact of meltdown should be considered in evaluating economic factors. Facility is economically uncompetitive w/alternate energy sources.
SHELLY, F. L. Affiliation Unknown 79/08/18 5pp

7908280614 Submits comments on DES, NUREG-0564. Evaluation of Ra-222 emission is incorrect. Only proper evaluation is w/no temporal cutoff. Such evaluation indicates underestimation of health consequences.
LOCHSTET, W. A. Affiliation Unknown 79/08/19 12pp

F. Security, medical, emergency & fire protection plans

7908290606 Responds to 790305 request re NRC participation during radiation emergency. NRC conducts investigations, verifies implementation of emergency plans, assists DOE & provides assistance to state & local agencies.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/23 1p

DOCKETED ITEMS

7908280032 Forwards Amend 15 to OL containing Revision C to physical security plan Plan withheld (ref 10CFR2.790)
CURTIS, N.W. Pennsylvania Power & Light Co. 79/08/23 1p.

G. Adjudicatory correspondence

7908020574 First round of interrogatories & document requests for intervenor Citizens Against Nuclear Dangers Requests info re health effects, peak electrical load & radiation exposure Certificate of Svc encl.
CUTCHIN, J.M. Branch 2. 79/05/21 11pp.

--7908020578 Response submitted by intervenor Citizens Against Nuclear Dange"; to NRC 790521 & util 790525 discovery requests. Each & every question is not applicable to intervenors. Certificate of Svc encl.
LEMANOWICZ, I. Citizens Against Nuclear Dangers 79/06/16 7pp.

7906260390 Motion for ASLB ruling on revision of preliminary timetable in case, to coincide w/TMI developments & forthcoming NRC task force recommendations Certificate of Svc encl.
LEMANOWICZ, I. Citizens Against Nuclear Dangers 79/06/22 3pp.

7908270329 Responds to request for documents per discovery requests re interrogatories directed to NRC Forwards list of locations.
CUTCHIN, J.M. Branch 3. 79/06/27 5pp.

7908080011 Response submitted by util to intervenor Citizens Against Nuclear Dangers 790522 interrogatories & document requests Forwards list of documents available Submits info re annual rept & litigation.
SILBERG, J.E. Shaw, Pittman, Potts, & Trowbridge BARBERICK, W. Pennsylvania Power & Light Co. 79/06/29 16pp.

7908080015 Response submitted by Commonwealth of PA to intervenor Citizens Against Nuclear Danger First round discovery requests Forwards list of documents re plant in files of PA Dept of Environ Resources w/o encl.
CARTER, K.A.W. Pennsylvania, State of 79/06/29 5pp.

--7908080018 Response submitted by Commonwealth of PA to intervenor Environ Coalition on Nuclear Power first round discovery requests Submits info re documents on TMI emergency plans & radiation monitoring Certificate of Svc encl.
CARTER, K.A. Pennsylvania, State of 79/06/29 7pp.

7908080029 Objections by licensees to Citizens Against Nuclear Dangers 790522 interrogatories & document requests Objects to Interrogatories 2, 5, 6, 8, 10-12, 14, 15 & 18 & to portions of Interrogatories 3, 9 & 17.
SILBERG, J.E., YUSPEH, A.R. Shaw, Pittman, Potts, & Trowbridge 79/06/29 8pp.

7908080060 Response by util to intervenor Environ Coalition on Nuclear Power 790525 first round interrogatories & document requests Submits info re evacuation plans, radiation monitoring & herbicides Affidavit of W Barberick encl.
SILBERG, J.E. Shaw, Pittman, Potts, & Trowbridge BARBERICK, W. Pennsylvania Power & Light Co. 79/06/29 11pp.

7908300021 Certificate of Svc averring listed parties have been sent applicant answers to Citizens Against Nuclear Dangers interrogatories & document requests & applicant objections.
SILBERG, J.E. Shaw, Pittman, Potts, & Trowbridge 79/06/29 2pp.

7908300038 Forwards Exhibits E-1, E-3, E-5, answers to Environ Coalition on Nuclear Power 790629 first round discovery requests & Certificate of Svc Only Certificate of Svc encl.
SNAPP, B.A. Pennsylvania Power & Light Co. 79/06/29 2pp.

7908300341 Request by intervenor Environ Coalition on Nuclear Power that MK Creasy 790711 deposition be delayed C Kepford & JH Johnson will not be able to attend session. Certificate of Svc encl.
JOHNSON, J.H. Environmental Coalition on Nuclear Power 79/06/29 2pp.

7908300353 Requests that ASLB issue protective order re applicant's first round interrogatories Questions are repetitive of NRC questions & very detailed No objection to answering limited number of pertinent questions.
JOHNSON, J.H. Environmental Coalition on Nuclear Power 79/06/29 2pp.

--7908300369 Responds to NRC interrogatories Answers general questions & specific questions re Contentions 1-3, 5-9 & 18. Certificates of Svc encl.
JOHNSON, J.H. Environmental Coalition on Nuclear Power 79/06/29 9pp.

7908080044 Motion pro se & on behalf of eleven intervenors that NRC revise preliminary timetable & extend for six to 12 months time to pose & answer first round discovery requests. Certificate of Svc encl.
MARSH, C. Affiliation Unknown 79/07/02 3pp.

7908300128 Comments re rule for protection of spent fuel in transit, per ASLB 790618 order Rule has no effect on rejected contentions Contentions were properly rejected Certificate of Svc encl.
CUTCHIN, J.M. Branch 3. 79/07/02 5pp.

7908300756 Requests by intervenors Citizens Against Nuclear Dangers that ASLB reconsider Contention 12 re transportation of nuclear fuel Roadbeds & rail trackage are deteriorating Certificate of Svc encl.
HALLIGAN, T.J. Citizens Against Nuclear Dangers 79/07/07 2pp.

7908220026 Request submitted by licensee that ASLB compel intervenor Susquehanna Environ Advocates to answer 790525 first set of interrogatories & document its requests per 10CFR2.740(f). Certificate of Svc encl.
SILBERG, J.E. Shaw, Pittman, Potts, & Trowbridge 79/07/10 4pp.

7908070635 Criticizes div for granting util provisional OL w/o conclusive study of TMI impact.
OBERST, D. Affiliation Unknown 79/07/28 2pp.

7908140572 Protests DES recommending issuance of OL Advocates use of coal & alternate energy resources.
JEPPSEN, H.C. Affiliation Unknown 79/08/08 1p.

7908160406 Opposes issuance of facility licenses until problems of waste disposal have been solved & assurance can be given that low level radiation will not be harmful to population or environ.
HERSHEY, M.L. Affiliation Unknown 79/08/11 1p.

7908200363 Opposes nuclear reactors & waste of electricity.
MOSES, L. Affiliation Unknown. 79/08/14 1p.

7908280583 Opposes proposed operation of nuclear reactors at Berwick, PA Considers DES unfair to alternate sources of energy & criticizes cost/benefit analysis.
HUNTINGTON, M. Affiliation Unknown. 79/08/19 8pp.

7908270390 Comments on DES Urges denial of OL Facility is not needed & is unsafe.
THOMPSON, F. Affiliation Unknown. 79/08/20 2pp.

7908310367 Disagrees w/need for addl nuclear reactors Would like to see environ statement prepared by someone other than util.
LAUGHLAND, S. Affiliation Unknown. 79/08/31 1p.

H. General correspondence

7908270495 Comments on DES Expresses concern re facility safety & damage to character of area.
SHORTZ, S. Affiliation Unknown. 79/08/20 2pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908070668 Forwards Amend 14 to OL application, containing Revision 11 to FSAR.
CURTIS, N.W. Pennsylvania Power & Light Co. 79/07/31 1p.

--7908070682 Amend 14 to OL application, containing Revision 11 to FSAR.
CURTIS, N.W. Pennsylvania Power & Light Co. 79/07/19 448pp.

O. Inspection reports, IE Bulletins & correspondence

7908140340 Requests that one Unit 1 nozzle safe-end to safe-end extension weld be retained for NRC examination along w/N2G nozzle & copies of ultrasonic test data.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/07/02 1p.

7908070288 Forwards response to IE Bulletin 79-02 re review of design & installation procedures for concrete expansion anchor bolts used in pipe support base plates for Seismic Category I sys Calculation sheets & tables encl.
CURTIS, N.W. Pennsylvania Power & Light Co. 79/07/06 77pp.

7908070462 Responds to IE Bulletins 78-12, 12A & 12B, CB&I generic rept submitted to NRC adequately represents data for Unit 1 & 2 vessels No archival matl found.
CURTIS, N.W. Pennsylvania Power & Light Co. 79/07/13 1p.

7908010522 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/07/17 1p

7908060492 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/07/18 1p

7908030274 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/07/19 1p

7908290660 Responds to IE Bulletin 79-11 Westinghouse Type DB-50 & DB-75 circuit breakers not included in safety-related design applications.
CURTIS, N.W. Pennsylvania Power & Light Co. 79/07/19 1p

7908200274 Ack receipt of 790716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-15 & 50-388/79-09.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/07/24 1p

--7908200277 Responds to NRC 790612 ltr re violations noted in IE Insp Repts 50-387/79-15 & 50-388/79-09. Corrective actions: tack welds on weld joint DCA-141-1-FW2 removed & failure of purge gas application clarified.
SABOL, A.R. Pennsylvania Power & Light Co. 79/07/16 3pp

--7908200280 Forwards IE Insp Repts 50-387/79-15 & 50-388/79-09 on 790402-27 & notice of violation.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/12 2pp

--7908200283 Notice of violation from insp on 790402-27.
*** Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/08 2pp

--7908200288 IE Insp Repts 50-387/79-15 & 50-388/79-09 on 790402-27. Noncompliance noted: failure to inspect purging for tack welds & failure to provide documented instruction to control storage & maint insps of reactor pressure vessel.
GALLA, R.M., CERNE, A.C., MCGAUGHY, R.W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/08 15pp

7908100266 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/07/26 1p

7908090327 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/07/30 1p

7908280172 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/07 1p

7908280327 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/13 1p

7908310299 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/14 1p

7908300177 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/15 1p

S Reportable occurrences, LERs & related correspondence

7908140746 Ack 790507 & 29 ltrs forwarding final deficiency rept re standby diesel generator.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/06 1p

--7908140753 Responds to 781103 deficiency rept by Cooper-Bessemer re study indicating abnormal wear on surface of roller pin in crosshead assembly of SSES standby diesel generator. Rept acceptable as interim rept.
CURTIS, N.W. Pennsylvania Power & Light Co. 79/05/07 2pp

7908170087 Ack receipt of 790522 & 0628 ltrs forwarding interim rept re deficiency in solenoid valves. Expects to receive final rept on 790815.
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/07/13 1p

7908140430 Amends 790323, 0522 & 0628 ltrs on deficiency rept re circle seal solenoid valves w/defective diodes. Determines condition not reportable.
CURTIS, N.W. Pennsylvania Power & Light Co. 79/08/08 2pp

DOCKET 50-389 ST. LUCIE PLANT, UNIT 2

A Application/construction stage documents & correspondence

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908030330 Submits Revision 3 to App C of QA topical rept 1-76A, providing alternative to requirement for insp of rigging & handling equipment.
UHRIG, R.E. Florida Power & Light Co. 79/07/30 2pp

G Adjudicatory correspondence

7905240759 Forwards draft Reg Guide 1.XXX, "Lightning Protection for Nuclear Power Plants."
PATON, W.D. Branch 4 79/04/23 1p

7905150711 Notification of receipt of intervenor 790416 motion for discovery. Intervenors do not intend to respond to motions unless directed to do so.
TOURTELLOTTE, J. Branch 4 79/04/24 1p

7908290073 St Lucie Intervenors opposition to NRC 790622 motion for extension until 790921 to respond to ASLAB questions re electrical grid stability. Hearing is suggested in order to consider reasonableness of delay. Certificate of Svc encl.
HODDER, M.H. Hodder, M.H. HODDER, M.H. Florida Power & Light Co.
79/06/29 7pp

7908080056 Memo & order ALAB-553, NRC 790511 & 0621 motions requesting extension until 790921 to prepare & file written testimony are granted.
BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 79/07/11
5pp

P Operating license stage documents & correspondence

7908210265 Responds to 790625 ltr re QA reg guides & ANSI stds. Topical QA rept FPLTQAR 1-76A, proposed Revision 3 satisfies requirements of 10 CFR50, App B. Util will comply w/reg guides.
UHRIG, R.E. Florida Power & Light Co. 79/08/13 2pp

Q Inspection reports, IE Bulletins & correspondence

7908140710 Advises that C-E rept "Info Requested by IE Bulletin 78-12, Atypical Weld Matl in Reactor Pressure Vessel Welds," submitted to NRC under separate ltr, has generic coverage of weld matl & testing programs used by C-E.
UHRIG, R.E. Florida Power & Light Co. 79/06/29 1p

7908300745 Responds to IE Bulletin 79-02 re concrete expansion anchor bolts. Submits info re base plate flexibility, safety & cyclic loading & installation procedures.
UHRIG, R.E. Florida Power & Light Co. 79/07/02 2pp

7908030132 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/13 2pp

7908010412 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/17 2pp

7908030009 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant-Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908080043 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/07/18. 2pp.

7908130112 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/07/18. 2pp.

7908080738 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/07/26. 2pp.

7908160232 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/07/27. 2pp.

7908220548 Responds to IE Bulletin 79-11. Westinghouse DB-50 & DB-75 circuit breakers will not be used in safety related Class IE equipment.
UHRIG, R. E. Florida Power & Light Co. 79/07/31. 1p.

7908220636 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/08/07. 3pp.

7908280443 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors.
79/06/06. 47pp.

7908240177 Forwards application for SNM license per 10CFR70. Includes Sections 9.1 & 4.3.2.7 of FSAR re spent fuel pit storage racks & nuclear safety analysis. Fuel delivery to site will begin 790901.
GILLELAND, J. F. Tennessee Valley Authority. 79/06/08. 1p.

--7908240183 Application for SNM license. Incl: ...ns Sections 9.1 & 4.3.2.7 of FSAR re spent fuel pit storage racks & ...clear safety analysis.
* Tennessee Valley Authority. 79/06/08. ...pp.

7906010699 Summary of 790614 meeting w/util & USGS re opportunity for util to justify restricting application of 1897 Intensity VIII Giles County earthquake to east-west zone crossing northern part of southern Appalachian sector.
MCMULLEN, R. B. Geosciences Branch. STAHLE, C. R. Light Water Reactors Branch 4. 79/06/29. 4pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908140117 Notifies that ASME Code Class N-192 may be used in safety-related piping. Data provided on flexible hoses will conform to Reg Guide 1.84.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/07/10. 2pp.

7908240468 Advises that 790608 application for SNM license has been filed under new docket. License cannot be issued until review completed.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727). 79/07/17. 1p.

7908170476 Ack receipt of 790625 ltr responding to notice of violations from IE Insp Repts 50-390/79-20 & 50-391/79-16. Understands supplemental response will be provided by 790813.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/24. 2pp.

7908080541 Forwards "Rept on Environ Qualification for Balance of Plant Equipment Class IE."
MILLS, L. M. Tennessee Valley Authority. 79/08/01. 1p.

7908080572 Forwards response to NRC Instrumentation & Control Sys Branch Question 031.127 & seismic qualification repts for transmitters mounted on local instrument panels. Test rept TI-1058 to be submitted 790901.
MILLS, L. M. Tennessee Valley Authority. 79/08/01. 2pp.

--7908080579 "Rept of Seismic Testing of Millivolt Transmitters, Type 550 for Bailey Meter Co Under Purchase Order 198-W6-898-705."
SCHREINER, W. Acton Environ. Testing Corp. 10348-5. 73/09/26. 8pp.

--7908080597 "Seismic Vibration Tests on GE-MAC Type 555 D/P Transmitters & Type 556 Pressure Transmitters."
SADOFSKI, J. J. Tennessee Valley Authority. 507. 73/04/03. 92pp.

--7908080617 "Seismic Simulation Test Program on Electronic Differential Pressure Transmitter, Electronic Pressure Transmitter, Square Root Extractor, Isolation Amplifier & Compact Recorder."
THORNBERRY, R., JORDAN, H., FRAZIER, H. E. Wyle Laboratories. 43522-1. 77/03/15. 97pp.

7908130563 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/08/01. 4pp.

7908170442 Forwards "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp & "Justification of Seismic Design Criteria Used for Facilities, Phase II, Responses to NRC Questions 1 Through 6."
MILLS, L. M. Tennessee Valley Authority. 79/08/09. 2pp.

--7908170449 "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp.
* Tennessee Valley Authority. 79/02/28. 114pp.

--7908170454 "Justification of Seismic Design Criteria Used for Facilities, Phase II, Responses to NRC Questions 1 Through 6."
* Tennessee Valley Authority. 79/06/30. 100pp.

7908210040 Forwards requests for info on mechanical engineering & test program in order to continue review. Responses requested by 790928.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/08/09. 13pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L. M. Tennessee Valley Authority. 79/08/23. 2pp.

F. Security, medical, emergency & fire protection plans

7908130208 Notifies that review of safeguards contingency plan involves consideration of safeguards issues requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908210314 Forwards security personnel training & qualification plans. Plans withheld (ref 10CFR2.790).
MILLS, L. M. Tennessee Valley Authority. 79/08/17. 1p.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L. M. Tennessee Valley Authority. 79/08/07. 2pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908140411 Forwards Amend 40 to FSAR.
MILLS, L. M. Tennessee Valley Authority. 79/08/09. 1p.

--7908140414 Amend 40 to FSAR.
* Tennessee Valley Authority. 79/08/09. 263pp.

7908210550 Forwards affidavit of svc for Amend 40 to FSAR.
MILLS, L. M. Tennessee Valley Authority. 79/08/15. 2pp.

M. Antitrust correspondence

7908270280 Discusses OL antitrust review. No TVA actions since CP review indicate anticompetitive intent. No significant antitrust changes have occurred which would warrant OL antitrust review.
TOALSTON, A. Power Supply & Analysis Branch 79/07/03 9pp.

Q. Inspection reports, IE Bulletins & correspondence

7908020193 Forwards IE Insp Repts 50-390/79-18 & 50-391/79-14 on 790409-12. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/14 2pp.

--7908020197 IE Insp Repts 50-390/79-18 & 50-391/79-14 on 790409-12. No noncompliance noted. Major areas inspected: stud welding to metal containment vessel, safety-related piping, preservice insp & review of work activities.
GIRARD, E. H., CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/14 6pp.

7908010158 Forwards response to IE Bulletins 79-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority. 79/05/29 3pp.

7908070144 Ack receipt of 790523 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-390/79-09 & 50-391/79-07.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/08 1p.

--7908070149 Responds to NRC 790320 ltr re violation noted in IE Insp Repts 50-390/79-09 & 50-391/79-07. Corrective actions: welds of chemical & vol control holdup tanks will be inspected w/vendor.
GILLELAND, J. E. Tennessee Valley Authority. 79/05/23 2pp.

7908280128 Forwards IE Insp Repts 50-390/79-24 & 50-391/79-20 on 790529-0601. No noncompliance noted.
MURPHY, C. E. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/19 2pp.

--7908280138 IE Insp Repts 50-390/79-24 & 50-391/79-20 on 790529-0601. No noncompliance noted. Major areas inspected: installation & review of records, instrumentation components & sys safety-related electrical cables & electrical valve operators.
RUFF, A. B. Region 2, Atlanta, Office of the Director.
CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/15 3pp.

7908010692 Submits results of investigations for various plants, in response to 790417 IE Bulletin 79-09 re GE Type AK-2 circuit breakers.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/20 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26 3pp.

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L. M. Tennessee Valley Authority. 79/07/05 40pp.

7908240136 Forwards IE Insp Repts 50-390/79-27 & 50-391/79-23 on 790627-29. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/11 2pp.

--7908240144 IE Insp Repts 50-390/79-27 & 50-391/79-23 on 790627-29. No noncompliance noted. Major areas inspected: safety-related electrical power & control cable installation & safety-related electrical cable installation & storage.
HARDWICK, R. J. Region 2, Atlanta, Office of the Director.
CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/11 4pp.

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellafonte to be submitted before 790914. Pipe stools not used.
MILLS, L. M. Tennessee Valley Authority. 79/07/13 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 3pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L. M. Tennessee Valley Authority. 79/07/27 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27 3pp.

7908230475 Responds to IE Bulletin 79-14. Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L. M. Tennessee Valley Authority. 79/07/27 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07 3pp.

7908270272 Submits updated response to IE Bulletin 79-03 requested by FS Cantrell on 790807. Investigations have revealed that no ASME SA-312 stainless steel piping mfg by Youngstown Welding & Engineering Co has been used.
MILLS, L. M. Tennessee Valley Authority. 79/08/08 1p.

S. Reportable occurrences, LERs & related correspondence

7908100029 Confirms 790608 telcon to Moseley re potential safety hazard due to deficiency identified in procedure to check performance characteristics of Barton Lot 1 transmitters. List of affected plants encl. None in operation.
ANDERSON, T. M. Westinghouse Electric Corp. 79/06/11 4pp.

7908020432 Notifies of RO on 790703 discovered incorrect info on motor driven auxiliary feedwater pump drawings re connection of cooling water supply to lube oil. Util is evaluating. Written rept will be submitted 790801.
* Tennessee Valley Authority. 79/07/03 1p.

7908020488 Forwards final deficiency rept re essential raw cooling waste valve positioning.
MILLS, L. M. Tennessee Valley Authority. 79/07/03 1p.

--7908020490 Final deficiency rept re essential raw cooling water valve positioning. Automatic opening signals to essential raw cooling water valve will be removed before initial criticality of Unit 1.
* Tennessee Valley Authority. 79/07/03 1p.

7908030074 Forwards first interim rept re reactor vessel insulation deficiency.
MILLS, L. M. Tennessee Valley Authority. 79/07/03 2pp.

--7908030081 First interim deficiency rept re reactor vessel insulation. Support structure for metallic mirror insulation not rigid enough to prevent insulation from impacting incore instrumentation guide tubes during seismic event.
* Tennessee Valley Authority. 79/07/03 1p.

7908030404 Forwards first interim deficiency rept re Barton level transmitters. Next rept will be submitted by 790921.
MILLS, L. M. Tennessee Valley Authority. 79/07/12 1p.

--7908030419 First interim deficiency re Barton level transmitters failing to meet acceptance criteria of accuracy. Vendor discovered that output of Lot 1 transmitters shifted w/temp. Narrow range steam generator level transmitters returned.
* Tennessee Valley Authority. 79/07/12 2pp.

7908030337 Forwards first interim deficiency rept re Penn Ventilator Co QA program.
MILLS,L.M. Tennessee Valley Authority 79/07/16 2pp

--7908030344 First interim deficiency rept During audit,discovered Penn Ventilator Co had not implemented QA program.Invetigation continuing.
* Tennessee Valley Authority 79/06/18 1p

7908010388 Forwards first interim deficiency rept re diesel generation turbocharger lubrication.
MILLS,L.M. Tennessee Valley Authority 79/07/20 1p

--7908010395 First interim deficiency rept when diesel generator at operating temp,shutdown & restarted between 15 minutes & 3-4 later,damage to turocharger thrust bearing may occur. Caused by oil sys not receiving lubrication.
* Tennessee Valley Authority 79/07/20 1p

7908030410 Forwards first interim deficiency rept re steam generator water level ref column error.
MILLS,L.M. Tennessee Valley Authority 79/07/30 1p

--7908030417 First interim deficiency rept re steam generator water level ref column error.Caused by design error.Next rept by 790928.
* Tennessee Valley Authority 79/07/30 1p

7908060344 Second interim deficiency rept re incorrect analysis of essential raw cooling water piping over total temp range. Response has been delayed.Addl info will be submitted by 800121.
MILLS,L.M. Tennessee Valley Authority 79/07/30 1p

7908060510 Forwards final deficiency rept re auxiliary feedwater motor drive pump lube oil cooling.
MILLS,L.M. Tennessee Valley Authority 79/07/30 1p

--7908060519 Final deficiency rept during review of auxiliary feedwater pump installation,discharge connection for pump motor cooling was found not provided per design drawings.Caused by failure of manufacturer to provide connection.
* Tennessee Valley Authority 79/08/06 2pp

7908150545 Forwards third interim deficiency rept re tensile anchor capacities lower than assumed in design allowables.
MILLS,L.M. Tennessee Valley Authority 79/07/31 1p

--7908150550 Third interim deficiency rept re tensile anchor capacities lower than assumed in design allowables.Util has completed testing program for welded stud anchors w/flexible plate connections.Corrective action will be taken as necessary.
* Tennessee Valley Authority 79/07/31 1p

7908150503 Forwards final deficiency rept re missing support for auxiliary feedwater pump trip & throttle valve.
MILLS,L.M. Tennessee Valley Authority 79/08/01 1p

--7908150508 Final deficiency rept re missing support for auxiliary feedwater pump trip & throttle valve.Design drawings will be revised to assure required spring support.Supports will be installed during const.
* Tennessee Valley Authority 79/08/01 1p

7908140540 Forwards first interim rept re hydrogen detection sys environ qualification deficiency.Will submit next rept by 790918.
MILLS,L.M. Tennessee Valley Authority 79/08/07 1p

--7908140548 First interim deficiency rept re hydrogen detection sys environ qualifications.Review of environ qualification data reveals no verification that sys components meet 30-day dose requirements.Tests being conducted.
* Tennessee Valley Authority 79/08/07 1p

7908230566 Forwards final deficiency rept re power-operated relief valves that do not meet requirements.
MILLS,L.M. Tennessee Valley Authority 79/08/13 1p

--7908230575 Final rept re power-operated relief valves that do not meet requirements.Westinghouse will replace valve bonnets w/stiffer & heavier bonnets by Nov 1979.
* Tennessee Valley Authority 79/08/13 1p

7908280599 Notifies that 790716 interim deficiency rept re Penn ventilator QA program gave incorrect date for submittal of next deficiency rept.Next interim rept will be submitted by 790910.
MILLS,L.M. Tennessee Valley Authority 79/08/14 1p

7908290426 Forwards second interim deficiency rept re orifice flanges not meeting specs.
MILLS,L.M. Tennessee Valley Authority 79/08/20 1p

--7908290438 Second interim deficiency rept re two leaking orifice flanges.Caused by inserts being used to repair flange ports & by inadequate flange wall thickness.All flanges will be examined to assure min wall thickness.
* Tennessee Valley Authority 79/08/20 1p

7908280581 Forwards final deficiency rept re insufficient flexibility of low head injection test lines.
MILLS,L.M. Tennessee Valley Authority 79/08/22 1p

--7908280585 Final deficiency rept re insufficient flexibility of low head injection test lines.Lines have been reanalyzed & rerouting will be completed.
* Tennessee Valley Authority 79/08/22 1p

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D.B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908010699 Summary of 790614 meeting w/util & US Geological Survey re opportunity for util to justify restriction of 1897 Intensity VIII Giles County earthquake to east-west zone crossing northern part of sourthern Appalachian sector.
MCMULLEN,R.B. Geosciences Branch 79/06/29 4pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD,H. Light Water Reactors Branch 2 79/07/02 70pp

7908140117 Notifies that ASME Code Case N-192 may be used in safety-related piping.Data provided on flexible hoses will conform to Reg Guide 1.84.
RUBENSTEIN,L.S. Light Water Reactors Branch 4 79/07/10 2pp

7908170476 Ack receipt of 790625 ltr responding to notice of violations from IE Insp Repts 50-390/79-20 & 50-391/79-16.Understands supplemental response will be provided by 790815.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/24 2pp

7908080541 Forwards "Rept on Environ Qualification for Balance of Plant Equipment Class 1E."
MILLS,L.M. Tennessee Valley Authority 79/08/01 1p

7908080572 Forwards response to NRC Instrumentation & Control Sys Branch Question 031.127 & seismic qualification rpts for transmitters mounted on local instrument panels.Test rept TI-1058 to be submitted 790901.
MILLS,L.M. Tennessee Valley Authority 79/08/01 2pp

--7908080579 "Rept of Seismic Testing of Millivolt Transmitters,Type 550 for Bailey Meter Co Under Purchase Order 198-W6-898-705."
SCHREINER,W. Acton Environ. Testing Corp 10348-5 73/09/26 8pp

--7908080597 "Seismic Vibration Tests on GE-MAC Type 555 D/P Transmitters & Type 556 Pressure Transmitters."
SADOFSKI,J.J. Tennessee Valley Authority 507 73/04/03 92pp

7908130563 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation.Model license condition encl.
RUBENSTEIN,L.S. Light Water Reactors Branch 4 79/08/01 4pp

7908170442 Forwards "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp & "Justification of Seismic Design Criteria Used for Facilities,Phase II, Responses to NRC Questions 1 Through 6."
MILLS,L.M. Tennessee Valley Authority 79/08/09 2pp

--7908170449 "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp.
* Tennessee Valley Authority 79/02/28 114pp

--7908170454 "Justification of Seismic Design Criteria Used for Facilities,Phase II,Responses to NRC Questions 1 Through 6."
* Tennessee Valley Authority 79/06/30 100pp

7908210040 Forwards requests for info on mechanical engineering & test program in order to continue review.Responses requested by 790928.
RUBENSTEIN,L.S. Light Water Reactors Branch 4 79/08/09 13pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS,L.M. Tennessee Valley Authority 79/08/23 2pp.

F. Security, medical, emergency & fire protection plans

7908130208 Notifies that review of safeguards contingency plan involves consideration of safeguards issue,req iring payment of Class III fee.Plans should be submitted by 790823.
DIGGS,R.M. License Fee Management Branch 79/07/03 2pp.

7908210314 Forwards security personnel training & qu rication plans. Plans withheld (ref 10CFR2.790).
MILLS,L.M. Tennessee Valley Authority 79/08/17 1p.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Dfc of Power.
MILLS,L.M. Tennessee Valley Authority 79/08/07 2pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908140411 Forwards Amend 40 to FSAR.
MILLS,L.M. Tennessee Valley Authority 79/08/09 1p.

--7908140414 Amend 40 to FSAR.
* Tennessee Valley Authority 79/08/09 263pp.

7908210530 Forwards affidavit of svc for Amend 40 to FSAR.
MILLS,L.M. Tennessee Valley Authority 79/08/15 2pp.

M. Antitrust correspondence

7908270280 Discusses OL antitrust review.No TVA actions since CP review indicate anticompetitive intent.No significant antitrust changes have occurred which would warrant OL antitrust review.
TOALSTON,A. Power Supply & Analysis Branch 79/07/03 9pp.

O. Inspection reports, IE Bulletins & correspondence

7908020193 Forwards IE Insp Repts 50-390/79-18 & 50-391/79-14 on 790409-12.No noncompliance noted.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp.

--7908020197 IE Insp Repts 50-390/79-18 & 50-391/79-14 on 790409-12.No noncompliance noted.Major areas inspected:stud welding to metal containment vessel,safety-related piping,preservice insp & review of work activities.
GIRARD,E.H.; CONLON,T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 6pp.

7908010158 Forwards response to IE Bulletins 78-12,12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts.Westinghouse genetic rept due Oct 1979.
GILLELAND,J.E. Tennessee Valley Authority 79/05/29 3pp.

7908070144 Ack receipt of 790523 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-390/79-09 & 50-391/79-07.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/08 1p.

--7908070149 Responds to NRC 790320 ltr re violation noted in IE Insp Repts 50-390/79-09 & 50-391/79-07.Corrective actions: welds of chemical & vol control holdup tanks will be inspected w/vendor.
GILLELAND,J.E. Tennessee Valley Authority 79/05/23 2pp.

7908280128 Forwards IE Insp Repts 50-390/79-24 & 50-391/79-20 on 790529-0601.No noncompliance noted.
MURPHY,C.E. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/19 2pp.

--7908280138 IE Insp Repts 50-390/79-24 & 50-391/79-20 on 790529-0601.No noncompliance noted.Major areas inspected:installation & review of records,instrumentation components & sys,safety-related electrical cables & electrical valve operators.
RUFF,A.B. Region 2, Atlanta, Office of the Director
CONLON,T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/11 3pp.

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09 re GE Type AK-2 circuit breakers.
GILLELAND,J.E. Tennessee Valley Authority 79/06/20 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/06/26 3pp.

7908060142 Responds to IE Bulletins 79-02 & 02,Revision 1. Forwards results of pipe support base plate design investigations.
MILLS,L.M. Tennessee Valley Authority 79/07/05 40pp.

7908240136 Forwards IE Insp Repts 50-390/79-27 & 50-391/79-23 on 790627-29.No noncompliance noted.
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/11 2pp.

--7908240144 IE Insp Repts 50-390/79-27 & 50-391/79-23 on 790627-29.No noncompliance noted.Major areas inspected:safety-related electrical power & control cable installation & safety-related electrical cable installation & storage.
HARDWICK,R.J. Region 2, Atlanta, Office of the Director
CONLON,T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/11 4pp.

7908170208 Responds to NRC 790312 ltr.Forwards final response for Hartsville,Phipps Bend & Yellow Creek plants to IE Bulletin 79-03.Final response for Watts Bar & Bellafonte to be submitted before 790914.Pipe stools not used.
MILLS,L.M. Tennessee Valley Authority 79/07/13 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/17 3pp.

7908020316 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/18 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/18 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15,Suppl 1,should be directed to IE Div of Reactor Const Insp.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/18 3pp.

7908170517 Responds to IE Bulletin 79-11.No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS,L.M. Tennessee Valley Authority 79/07/20 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/26 2pp.

7908160252 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/27 3pp.

7908230475 Responds to IE Bulletin 79-14.Investigations for Item 1 not complete.Unable to meet response date of 790801.Will submit response before 790815.
MILLS,L.M. Tennessee Valley Authority 79/07/27 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/08/07 3pp.

7908270272 Submits updated response to IE Bulletin 79-03 requested by FS Cantrell on 790807. Investigations have revealed that no ASME SA-312 stainless steel piping mfg by Youngstown Welding & Engineering Co has been used.
MILLS,L.M. Tennessee Valley Authority 79/08/08 1p

S. Reportable occurrences: LERs & related correspondence

7908020432 Notifies of RO on 790703 discovered incorrect info on motor driven auxiliary feedwater pump drawings re connection of cooling water supply to lube oil Util is evaluating. Written rept will be submitted 790801.
* Tennessee Valley Authority 79/07/03 1p

7908020488 Forwards final deficiency re essential raw cooling water valve positioning.
MILLS,L.M. Tennessee Valley Authority 79/07/03 1p

--7908020490 Final deficiency rept re essential raw cooling water valve positioning. Automatic opening signals to essential raw cooling water valve will be removed before initial criticality of Unit 1.
* Tennessee Valley Authority 79/07/03 1p

7908030074 Forwards first interim rept re reactor vessel insulation deficiency.
MILLS,L.M. Tennessee Valley Authority 79/07/03 2pp

--7908030081 First interim deficiency rept re reactor vessel insulation. Support structure for metallic mirror insulation not rigid enough to prevent insulation from impacting incore instrumentation guide tubes during seismic event.
* Tennessee Valley Authority 79/07/03 1p

7908030404 Forwards first interim deficiency rept re Barton level transmitters. Next rept will be submitted by 790921.
MILLS,L.M. Tennessee Valley Authority 79/07/12 1p

--7908030419 First interim deficiency re Barton level transmitters failing to meet acceptance criteria of accuracy. Vendor discovered that output of Lot 1 transmitters shifted w/temp. Narrow range steam generator level transmitters returned.
* Tennessee Valley Authority 79/07/12 2pp

7908030337 Forwards first interim deficiency rept re Penn Ventilator Co QA program.
MILLS,L.M. Tennessee Valley Authority 79/07/16 2pp

--7908030344 First interim deficiency rept. During audit, discovered Penn Ventilator Co had not implemented QA program. Invetigation continuing.
* Tennessee Valley Authority 79/06/18 1p

7908010388 Forwards first interim deficiency rept re diesel generation turbocharger lubrication.
MILLS,L.M. Tennessee Valley Authority 79/07/20 1p

--7908010395 First interim deficiency rept when diesel generator at operating temp, shutdown & restarted between 15 minutes & 3-4h later, damage to turocharger thrust bearing may occur. Caused by oil sys not receiving lubrication.
* Tennessee Valley Authority 79/07/20 1p

7908030410 Forwards first interim deficiency rept re steam generator water level ref column error.
MILLS,L.M. Tennessee Valley Authority 79/07/30 1p

--7908030417 First interim deficiency rept re steam generator water level ref column error. Caused by design error. Next rept by 790928.
* Tennessee Valley Authority 79/07/30 1p

7908060344 Second interim deficiency rept re incorrect analysis of essential raw cooling water piping over total temp range. Response has been delayed. Addl info will be submitted by 800121.
MILLS,L.M. Tennessee Valley Authority 79/07/30 1p

7908060510 Forwards final deficiency rept re auxiliary feedwater motor drive pump lube oil cooling.
MILLS,L.M. Tennessee Valley Authority 79/07/30 1p

--7908060519 Final deficiency rept during review of auxiliary feedwater pump installation, discharge connection for pump motor cooling was found not provided per design drawings. Caused by failure of manufacturer to provide connection.
* Tennessee Valley Authority 79/08/06 2pp

7908150545 Forwards third interim deficiency rept re tensile anchor capacities lower than assumed in design allowables.
MILLS,L.M. Tennessee Valley Authority 79/07/31 1p

--7908150550 Third interim deficiency rept re tensile anchor capacities lower than assumed in design allowables. Util has completed testing program for welded stud anchors w/flexible plate connections. Corrective action will be taken as necessary.
* Tennessee Valley Authority 79/07/31 1p

7908150503 Forwards final deficiency rept re missing support for auxiliary feedwater pump trip & throttle valve.
MILLS,L.M. Tennessee Valley Authority 79/08/01 1p

--7908150508 Final deficiency rept re missing support for auxiliary feedwater pump trip & throttle valve. Design drawings will be revised to assure required spring support. Supports will be installed during const.
* Tennessee Valley Authority 79/08/01 1p

7908140540 Forwards first interim rept re hydrogen detection sys environ qualification deficiency. Will submit next rept by 790918.
MILLS,L.M. Tennessee Valley Authority 79/08/07 1p

--7908140548 First interim deficiency rept re hydrogen detection sys environ qualifications. Review of environ qualification data reveals no verfication that sys components meet 30-day dose requirements. Tests being conducted.
* Tennessee Valley Authority 79/08/07 1p

7908230566 Forwards final deficiency rept re power-operated relief valves that do not meet requirements.
MILLS,L.M. Tennessee Valley Authority 79/08/1? 1p

--7908230575 Final rept re power-operated relief valves that do not meet requirements. Westinghouse will replace valve bonnets w/stiffer & heavier bonnets by Nov 1979.
* Tennessee Valley Authority 79/08/13 1p

7908280599 Notifies that 790716 interim deficiency rept re Penn ventilator QA program gave incorrect date for submittal of next deficiency rept. Next interim rept will be submitted by 790910.
MILLS,L.M. Tennessee Valley Authority 79/08/14 1p

7908290426 Forwards second interim deficiency rept re orifice flanges not meeting specs.
MILLS,L.M. Tennessee Valley Authority 79/08/20 1p

--7908290438 Second interim deficiency rept re two leaking orifice flanges caused by inserts being used to repair flange ports & by inadequate flange wall thickness. All flanges will be examined to assure min wall thickness.
* Tennessee Valley Authority 79/08/20 1p

7908280581 Forwards final deficiency rept re insufficient flexibility of low head injection test lines.
MILLS,L.M. Tennessee Valley Authority 79/08/2? 1p

--7908280585 Final deficiency rept re insufficient flexibility of low head injection test lines. Lines have been reanalyzed & rerouting will be completed.
* Tennessee Valley Authority 79/08/22 1p

DOCKET 50-394 CALIFORNIA STATE POLYTECH COLLEGE RES. REACTOR

G. Inspection reports, IE Bulletins & correspondence

7908140072 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director
79/08/10 1p

7908310177 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director
79/08/14 1p

DOCKET 50-395 VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D.B. Assistant Director for Light Water Reactors
79/06/06 47pp

7908020541 Notifies of completion of review of Westinghouse rept "Qualification & Testing of Barton Pressure & Differential Pressure Transmitters." Requests description of alternate qualified instruments & bases for accepted measured error.
BAER, R. L. Light Water Reactors Branch 2 79/06/13 4pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

7908080227 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/19 2pp.

7908220241 Summary of 790622 meeting w/applicant in Bethesda, MD re reservoir-induced seismicity at site.
TIBBITS, D. L. Light Water Reactors Branch 2 79/07/26 7pp.

7908010355 Forwards Technical Rept 79-2 "Seismic Activity Near VC Summer Nuclear Station," for Apr-June 1979.
CREWS, E. H. South Carolina Electric & Gas Co. 79/07/27 1p.

-- 010357 Technical Rept 79-2, "Seismic Activity Near VC Summer ..lear Station," Apr-June 1979.
TALWANI, P. South Carolina, Univ. of. 79-2 79/06/30 25pp.

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7908020353 Forwards 790629 FR notice re availability of DES (NUREG-0534).
BALLARD, R. L. Environmental Projects Branch 1 79/06/29 2pp.

--7908020360 FR notice re availability of DES (NUREG-0534).
BALLARD, R. L. Environmental Projects Branch 1 79/06/29 2pp.

7908070037 Forwards DES (NUREG-0534). W/o encl.
BALLARD, R. L. Environmental Projects Branch 1 79/06/29 6pp.

7908070265 Forwards DES re proposed facility operation.
BALLARD, R. L. Environmental Projects Branch 1 79/06/29 4pp.

--7908070272 DES re proposed facility operation.
* Office of Nuclear Reactor Regulation NUREG-0534 79/06/30 348pp.

7908090341 Forwards DES & notice of availability.
BALLARD, R. L. Environmental Projects Branch 1 79/06/29 2pp.

7908010370 Responds to 790629 ltr. Offers no comments on DES.
BROWN, W. W. Army, Dept of, Corps of Engineers 79/07/23 1p.

7908210359 Forwards comments on DES re ichthyoplankton & fish sampling, impingement & thermal monitoring. Recommends requirement for plant species survey be eliminated from final rept.
CREWS, E. H. South Carolina Electric & Gas Co. 79/08/17 6pp.

7908280546 Comments on NUREG-0534, DES for plant. Health consequences of Ra-222 emissions from U fuel cycle are improperly evaluated. Entire toxic life of wastes must be considered.
LOCHSTET, W. A. Pennsylvania State Univ. 79/08/19 12pp.

7908300641 Comments on draft EIS re operation of nuclear station. Wetlands data should be included in FES. States should develop or update emergency response preparations.
HAGAN, J. E. Environmental Protection Agency 79/08/24 2pp.

7908300654 Responds to DES re operation of facility. Agrees in general w/conclusions, but offers several comments.
JENKINS, J. E. South Carolina, State of. 79/08/24 3pp.

F. Security, medical, emergency & fire protection plans

7908300607 Notifies of 790815 meeting w/util in Columbia, SC to discuss emergency planning & implementing procedures. Agenda encl.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/08/06 3pp.

7908230391 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
CREWS, E. H. South Carolina Electric & Gas Co. 79/08/17 1p.

I. Financial information

7908220051 Forwards request for addl financial info to be submitted by 790915.
BAER, R. L. Light Water Reactors Branch 2 79/07/30 3pp.

P. Operating license stage documents & correspondence

7908280638 Forwards "Fuel Handling Bldg Exfiltration Analysis for Postulated Fuel Handling Accident" per request.
CREWS, E. H. South Carolina Electric & Gas Co. 79/08/21 1p.

--7908280642 "Fuel Handling Bldg Exfiltration Analysis for Postulated Fuel Handling Accident."
* South Carolina Electric & Gas Co. 79/08/21 7pp.

Q. Inspection reports, IE Bulletins & correspondence

7908080099 Responds to IE Bulletin 79-11. Lower reactor vessel head insulation & associated sys is supported from frame carried on vessel itself.
CREWS, E. H. South Carolina Electric & Gas Co. 79/06/29 1p.

7908080674 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/02 2pp.

7908160280 Ack receipt of IE Insp Rept 50-395/79-20. No proprietary info.
JOHNSON, M. C. South Carolina Electric & Gas Co. 79/07/02 1p.

7908230586 Forwards IE Insp Rept 50-395/79-21 on 790618-20. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/02 2pp.

--7908230588 IE Insp Rept 50-395/79-21 on 790618-20. No noncompliance noted. Major areas inspected: overall preoperational test program & current plant operations & status.
SHOLDS, J. L. Region 2, Atlanta, Office of the Director
KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/29 3pp.

7908310111 Forwards response to IE Bulletins 79-02 & 02, Revision 1. Results of investigation for effects of flexibility on pipe support base plate anchors indicate that prying forces did not exist. Original design acceptable.
CREWS, E. H. South Carolina Electric & Gas Co. 79/07/05 14pp.

7908230595 Forwards IE Insp Rept 50-395/79-20 on 790625-27. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 2pp.

--7908230599 IE Insp Rept 50-395/79-20 on 790625-27. No noncompliance noted. Major areas inspected: const activities, reactor vessel internals installation activities & licensee action on previous insp findings.
BURDETTE, T. E., MCFARLAND, C. R. Region 2, Atlanta, Office of the Director BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 5pp.

7908230234 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breakers. No Westinghouse Type DB-50 or DB-75 breakers used in safety-related sys.
CREWS, E. H. South Carolina Electric & Gas Co. 79/07/12 1p.

7908030139 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13 2pp.

7908010417 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17 1p.

7908060356 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17 2pp.

7908030019 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908080051 Notifies that written responses to IE Bulletin 79-15,Suppl 1,should be directed to IE Div of Reactor Const Insp.
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/18 2pp

7908080052 Notifies that written responses to IE Bulletin 79-15,Suppl 1,should be directed to IE Div of Reactor Const Insp.
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/18 2pp

7908130069 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/18 1p

7908130128 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/18 1p

7908130132 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/18 1p

7908160325 Ack receipt of IE Insp Rept 50-395/79-16 on 790521-24. No proprietary info.
JOHNSON,M C South Carolina Electric & Gas Co 79/07/20 1p

--7908160331 Forwards IE Insp Rept 50-395/79-16 on 790521-24. No noncompliance noted.
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/20 2pp

--7908160341 IE Insp Rept 50-395/79-16 on 790521-24. No noncompliance noted. Major areas inspected safety-related pipe welding & followup on licensee-identified item.
VAN DOORN,P K ; CROWLEY,B R Region 2, Atlanta, Office of the Director ; HERDT,A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/19 7pp

7908080743 Forwards IE Bulletin 79-17, "Pipe Cracks in Staghant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/26 2pp

7908160245 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/27 2pp

7908160247 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J P Region 2, Atlanta, Office of the Director. 79/07/27 2pp

7908240083 Ack receipt of 790713 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-395/79-18.
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/30 1p

--7908240087 Responds to NRC 790619 ltr re violation noted in IE Insp Rept 50-395/79-18. Corrective actions: completed insp forms to be reviewed by independent party before forwarding to GA electrical supervisor for approval.
JOHNSON,M C South Carolina Electric & Gas Co 79/07/13 2pp

--7908240090 Forwards IE Insp Rept 50-395/79-18 on 790522-25 & notice of violation.
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/14 2pp

--7908240091 Notice of violation from insp on 790522-25.
* Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/19 1p

--7908240096 IE Insp Rept 50-395/79-18 on 790522-25 Noncompliance noted: licensee-identified items, inspector followup items, safety-related instrumentation & electrical cable installation QC records.
HARDWICK,R J ; CONLON,T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/18 4pp

7908280452 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER,B H Region 2, Atlanta, Office of the Director 79/08/13 2pp

7908280456 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER,B H Region 2, Atlanta, Office of the Director 79/08/13 2pp

S Reportable occurrences, LERs & related correspondence

7908230558 Supplements info in 790719 ltr identifying torn bottom plate in condensate storage tank. No definite cause has been established. Temporary welding repairs will be performed until investigation can be performed in late Sept.
JOHNSON,M C South Carolina Electric & Gas Co 79/08/17 3pp

DOCKET 50-396 UNIV. OF VIRGINIA CAVALIER REACTOR

F Security, medical, emergency & fire protection plans

7908310547 Responds to 790730 ltr. Upgrade of rule security requirements are not necessary. Requirements of 10CFR73.47 will apply in lieu of rule. Major changes to facility are to be undertaken if compliance w/rule is deemed necessary.
SHRIVER,B L Virginia, Univ of 79/08/15 6pp

G Inspection reports, IE Bulletins & correspondence

7908010078 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/06 2pp

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO,D B Assistant Director for Light Water Reactors 79/04/18 3pp

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D B Assistant Director for Light Water Reactors 79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD,H Light Water Reactors Branch 2 79/07/02 70pp

7908080192 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
PARR,O D Light Water Reactors Branch 3 79/07/11 2pp

7908080237 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER,J R Assistant Director for Site & Safeguards 79/07/20 2pp

7908080492 Requests extension to 7901215 for submittal of training & qualification plan.
RENBERGER,D L Washington Public Power Supply System 79/07/31 1p

7908140657 Notifies that utils w/BWRs currently in active FSAR review have agreed to take actions to support licensing activity. Requests meeting on 790816 to discuss course of action.
RENBERGER,D L Washington Public Power Supply System 79/08/08 2pp

7908200362 Forwards responses to sixth set of first round questions from Plant Sys & Power Sys branches. Responses to open items from previous question sets encl.
RENBERGER,D L Washington Public Power Supply System 79/08/14 110pp

K Utility Final Safety Analysis Report (FSAR) & amends

7908060364 Forwards Certificate of Svc for Amend 4 to FSAR.
RENBERGER,D L Washington Public Power Supply System 79/07/30 2pp

G Inspection reports, IE Bulletins & correspondence

7908280387 Responds to IE Bulletin 79-03. No welded pipe mfg by Youngstown Welding & Engineering Co in use or planned for use in safety-related sys.
RENBERGER,D L Washington Public Power Supply System 79/06/06 1p

7908070719* Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers used or planned for use in safety-related sys at facility.
RENBERGER, D. L. Washington Public Power Supply System. 79/06/12. 1p.

7908150202 Forwards IE Insp Rept 50-397/79-09 & on 790514-17. No noncompliance noted.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/29. 2pp.

--7908150212 IE Insp Rept 50-397/79-09 on 790514-17. No noncompliance noted. Major areas inspected reactor recirculation nozzle mods, structural steel installation & electrical cable installation.
BISHOP, T. W., VORDERBRUEGGEN Region 5, San Francisco, Office of the Director DODDS, R. T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/29. 12pp.

7908010397 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908020411 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908020509 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908060079 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908060166 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210472 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908280399 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310162 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300256 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908020537 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020033 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908010365 Forwards reportable deficiency re cable tray hangers from Quality Class II structural steel.
RENBERGER, D. L. Washington Public Power Supply System. 79/07/20. 1p.

--7908010369 Deficiency rept re support of Quality Class I cable tray hangers from Quality Class II structural steel. Some cable supports overloaded. Structural steel framing design modified to increase capacity of overloaded members.
* Washington Public Power Supply System. 79/07/20. 1p.

7908150560 Forwards deficiency rept re diesel engine turbo charger thrust bearing.
RENBERGER, D. L. Washington Public Power Supply System. 79/08/02. 1p.

--7908150568 Deficiency rept re diesel engine turbo charger thrust bearing. Failure of turbo charger would result in failure of diesel generator & reduce ECCS below min requirements. Vendor working on improved lube oil sys.
* Washington Public Power Supply System. 79/08/02. 1p.

7908200361 Forwards deficiency rept re turbocharger thrust bearing of diesel engines in onsite emergency power & HPCS sys.
RENBERGER, D. L. Washington Public Power Supply System. 79/08/02. 1p.

--7908200365 Deficiency rept re lubricating oil sys tests indicating high possibility of turbocharger thrust bearing damage resulting from repeat start operating modes. Improved lube sys will be installed prior to sys startup testing.
* Washington Public Power Supply System. 79/08/02. 1p.

7908150682 Forwards deficiency rept re improper installation of anchor bolts by contractor.
RENBERGER, D. L. Washington Public Power Supply System. 79/08/07. 1p.

--7908150688 Reportable deficiency: improper installation of anchor bolts by Waldinger Corp, contrary to approved drawings. Engineering change order requiring that anchor bolts be removed & corrected has been issued to contractor.
* Washington Public Power Supply System. 79/07/16. 1p.

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908100182 Forwards request for addl info to be included in next seismic monitoring program rept, since 790430 rept indicated absence of seismic activity in site area.
PARR, O. D. Light Water Reactors Branch 3. 79/07/13. 3pp.

7908200119 Responds to 790620 ltr re relation of facility to NC water quality stds & possible violation of licensing & const procedures. State certification received for compliance w/water stds. State clarification has been requested.
SELLS, D. E. Environmental Projects Branch 2. 79/07/19. 2pp.

--7908200124 Requests verification re compliance w/water classification requirements & possible violation of licensing & const procedures.
MARTIN, D. H. Conservation Council of North Carolina. 79/06/20. 1p.

7908070530 Submits evaluation of emergency svc water intake channel backfill previously placed along channel lining. Drawings of field permeability locations & in-place density tests encl.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/08/02. 11pp.

7908160431 Ack receipt of 790816 ltr re Water Quality Certification 214. Certification originally issued 731220, subsequently revised & reissued 770914 & is still valid.
MCRORIE, A. F. North Carolina, State of. 79/08/06. 1p.

7908200008 Forwards rept of 790417-18 site visit re earthwork const, per 790413 telcon. Reviewed field control of soil moisture content & need to review condition of soils supporting pipelines.
THOMPSON, O. O. Geosciences Branch. 79/08/06. 7pp.

G. Adjudicatory correspondence

7906230024 Proposed findings of fact & conclusions of law in form of supplemental initial decision. Applicant qualified to design & construct facility. Certificate of Svc encl.
REIS, E. Branch 3. 79/05/10. 81pp.

7908140641 Forwards 790425 & 0517 memos re const & piping.
BARTH, C. A. Branch 3. 79/06/04. 1p.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

P. Operating license stage documents & correspondence

7908270446 Approves NRC 790820 request to provide NC Governor J. Hunt w/proprietary matl & technical capability matl filed in response to HR Denton 790629 request.
UTLEY, E. E. Carolina Power & Light Co. 79/08/20. 1p.

Q. Inspection reports, IE Bulletins & correspondence

7908170206 Forwards IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/14. 2pp.

--7908170217 IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24. No noncompliance noted. Major areas inspected: storage & licensee action on previous findings.
HARRIS, J. R. Region 2, Atlanta, Office of the Director.
CANLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/12. 4pp.

7908100149 Ack receipt of 790612 ltr responding to 790521 notice of violation. Supplemental response due by 790711.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/25. 1p.

7908070126 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908070821 Responds to IE Bulletin 79-02, Revision 1, Concrete expansion anchor bolts not planned for use w/pipe support base plates. Lists criteria which will be met if use of anchor bolts becomes necessary.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/06. 2pp.

7908140302 Supplements 790529 response to IE Bulletin 78-12B. CB&I generic rept adequately addressed matls used in Units 1 & 2 reactor pressure vessels & C-E rept covered matls in Units 3 & 4 vessels.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/09. 2pp.

7908030105 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010401 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908020552 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130095 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908160351 Ack receipt of IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No proprietary info.
HOWE, P. W. Carolina Power & Light Co. 79/07/18. 1p.

--7908160411 Forwards IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 2pp.

--7908160415 IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No noncompliance noted. Major areas inspected: const status, licensee-identified items, steam generator mod, concrete placement & response to IE bulletins.
BRADLEY, R. D. Region 2, Atlanta, Office of the Director.
BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 5pp.

7908200209 Ack receipt of IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No proprietary info.
HOWE, P. W. Carolina Power & Light Co. 79/07/18. 1p.

--7908200215 Forwards IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 2pp.

--7908200221 IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No noncompliance noted. Major areas inspected: steel structures & supports, welding procedure specs & QA procedures.
ECONOMOS, N. Region 2, Atlanta, Office of the Director.
HERDT, A. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/09. 5pp.

7908070716 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160201 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908290631 Responds to NRC 790522 ltr re IE Bulletin 79-11. Util is not using Westinghouse Type DB-75 or DB-50 breakers in any safety-related sys.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/27. 1p.

7908300575 Ack receipt of IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-12 on 790709. No proprietary info.
HOWE, P. W. Carolina Power & Light Co. 79/07/31. 1p.

--7908300578 Forwards IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-12 on 790709-11. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/23. 2pp.

--7908300583 IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-11 on 790709-11. No noncompliance noted. Major areas inspected: structural concrete, site preparation, dams & licensee action on previous insp findings.
HARRIS, J. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/23. 5pp.

7908090575 Responds to IE Bulletin 79-14 requesting verification that seismic analysis applies to actual configuration of safety-related piping sys. Bulletin cannot be addressed because no complete safety-related piping sys has been installed.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/08/01. 1p.

7908170055 Responds to IE Bulletin 79-14 re seismic analyses of as-built safety-related piping sys. No complete sys built.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/08/01. 1p.

7908220621 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

7908280420 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

R. Periodic operating reports & related correspondence

7908060263 Forwards seismic monitoring program rept for Apr-June 197[illegible]. Responses to NRC 790713 questions re program encl.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/30. 18pp.

S. Reportable occurrences, LERs & related correspondence

7908100389 Forwards final deficiency rept re failure to post-weld heat treat containment mechanical penetration assemblies.
CHIANGI, N. J. Carolina Power & Light Co. 79/08/03. 1p.

--7908100391 Final deficiency rept re failure to post-weld heat treat containment mechanical penetration assemblies. Eleven penetrations stress-relieved on 790608-09. All required documentation performed.
* Carolina Power & Light Co. 79/08/03. 4pp.

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908100182 Forwards request for add'l info to be included in next seismic monitoring program rept, since 790430 rept indicated absence of seismic activity in site area.
PARR, O. D. Light Water Reactors Branch 3. 79/07/13. 3pp.

7908200119 Responds to 790620 ltr re relation of facility to NC water quality stds & possible violation of licensing & const procedures. State certification received for compliance w/water stds. State clarification has been requested.
SELLS, D. E. Environmental Projects Branch 2 79/07/19 2pp.

--7908200124 Requests verification re compliance w/water classification requirements & possible violation of licensing & const procedures.
MARTIN, D. H. Conservation Council of North Carolina 79/06/20 1p.

7908070530 Submits evaluation of emergency svc water intake channel backfill previously placed along channel lining. Drawings of field permeability locations & in-place density tests encl.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/08/02 11pp.

7908160431 Ack receipt of 790816 ltr re Water Quality Certification 214. Certification originally issued 731220, subsequently revised & reissued 770914 & is still valid.
MCRORIE, A. F. North Carolina, State of 79/08/06 1p.

G Adjudicatory correspondence

7906230024 Proposed findings of fact & conclusions of law in form of supplemental initial decision. Applicant qualified to design & construct facility. Certificate of Svc encl.
REIS, E. Branch 3 79/05/10 81pp.

7908140641 Forwards 790425 & 0517 memos re const & piping.
BARTH, C. A. Branch 3 79/06/04 1p.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1 79/06/29 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division 79/03/05 1p.

P Operating license stage documents & correspondence

7908270446 Approves NRC 790820 request to provide NC Governor J. Hunt w/proprietary matl & technical capability matl filed in response to HR Denton 790629 request.
UTLEY, E. E. Carolina Power & Light Co. 79/08/20 1p.

G Inspection reports, IE Bulletins & correspondence

7908170206 Forwards IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/14 2pp.

--7908170217 IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24. No noncompliance noted. Major areas inspected: storage & licensee action on previous findings.
HARRIS, J. R. Region 2, Atlanta, Office of the Director.
CANLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/12 4pp.

7908100149 Ack receipt of 790612 ltr responding to 790521 notice of violation. Supplemental response due by 790711.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/25 1p.

7908070126 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26 2pp.

7908070821 Responds to IE Bulletin 79-02, Revision 1 Concrete expansion anchor bolts not planned for use w/pipe support base plates. Lists criteria which will be met if use of anchor bolts becomes necessary.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/06 2pp.

7908140302 Supplies 790529 response to IE Bulletin 78-12B CB&I generic rept adequately addressed matls used in Units 1 & 2 reactor pressure vessels & C-E rept covered matls in Units 3 & 4 vessels.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/09 2pp.

7908030105 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13 2pp.

7908010401 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17 2pp.

7908020552 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908130045 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908130095 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18 2pp.

7908160351 Ack receipt of IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No proprietary info.
HOWE, P. W. Carolina Power & Light Co. 79/07/18 1p.

--7908160411 Forwards IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 2pp.

--7908160411 IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No noncompliance noted. Major areas inspected: const status, licensee-identified items, steam generator mod, concrete placement & response to IE bulletins.
BRADLEY, K. D. Region 2, Atlanta, Office of the Director.
BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 5pp.

7908200209 Ack receipt of IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No proprietary info.
HOWE, P. W. Carolina Power & Light Co. 79/07/18 1p.

--7908200215 Forwards IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 2pp.

--7908200221 IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No noncompliance noted. Major areas inspected: steel structures & supports, welding procedure specs & QA procedures.
ECONOMOS, N. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/09 5pp.

7908070716 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26 2pp.

7908160201 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27 2pp.

7908290631 Responds to NRC 790522 ltr re IE Bulletin 79-11. Util is not using Westinghouse Type DB-75 or DB-50 breakers in any safety-related sys.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/27 1p.

7908300575 Ack receipt of IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-12 on 790709. No proprietary info.
HOWE, P. W. Carolina Power & Light Co. 79/07/31 1p.

--7908300578 Forwards IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-12 on 790709-11. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/23 2pp.

--7908300583 IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-11 on 790709-11. No noncompliance noted. Major areas inspected: structural concrete, site preparation, dams & licensee action on previous insp findings.
HARRIS, J. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/23. 5pp.

7908090575 Responds to IE Bulletin 79-14 requesting verification that seismic analysis applies to actual configuration of safety-related piping sys. Bulletin cannot be addressed because no complete safety-related piping sys has been installed.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/08/01. 1p.

7908170055 Responds to IE Bulletin 79-14 re seismic analyses of as-built safety-related piping sys. No complete sys built.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/08/01. 1p.

7908220621 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

7908280420 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

B. Periodic operating reports & related correspondence

7908060263 Forwards seismic monitoring program rept for Apr-June 1979. Responses to NRC 790713 questions re program encl.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/30. 18pp.

DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

A. Application/construction stage documents & correspondence

7908100182 Forwards request for addl info to be included in next seismic monitoring program rept, since 790430 rept indicated absence of seismic activity in site area.
PARR, O. D. Light Water Reactors Branch 3. 79/07/13. 3pp.

7908200119 Responds to 790620 ltr re relation of facility to NC water quality stds & possible violation of licensing & const procedures. State certification received for compliance w/water stds. State clarification has been requested.
SELLS, D. E. Environmental Projects Branch 2. 79/07/19. 2pp.

--7908200124 Requests verification re compliance w/water classification requirements & possible violation of licensing & const procedures.
MARTIN, D. H. Conservation Council of North Carolina. 79/06/20. 1p.

7908070530 Submits evaluation of emergency svc water intake channel backfill previously placed along channel lining. Drawings of field permeability locations & in-place density tests encl.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/02. 11pp.

7908160431 Ack receipt of 790816 ltr re Water Quality Certification 214. Certification originally issued 731220, subsequently revised & reissued 770914 & is still valid.
MCRORIE, A. F. North Carolina, State of. 79/08/06. 1p.

G. Adjudicatory correspondence

7906230024 Proposed findings of fact & conclusions of law in form of supplemental initial decision. Applicant qualified to design & construct facility. Certificate of Svc encl.
REIS, E. Branch 3. 79/05/10. 81pp.

7908140641 Forwards 790425 & 0517 memos re const & piping.
BARTH, C. A. Branch 3. 79/06/04. 1p.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

P. Operating license stage documents & correspondence

7908210446 Approves NRC 790820 request to provide NC Governor J. Hunt w/proprietary matl & technical capability matl filed in response to HR Denton 790629 request.
UTLEY, E. E. Carolina Power & Light Co. 79/08/20. 1p.

G. Inspection reports, IE Bulletins & correspondence

7908170206 Forwards IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/14. 2pp.

--7908170217 IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24. No noncompliance noted. Major areas inspected: storage & licensee action on previous findings.
HARRIS, J. R. Region 2, Atlanta, Office of the Director.
CANLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/12. 4pp.

7908100149 Ack receipt of 790612 ltr responding to 790521 notice of violation. Supplemental response due by 790711.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/25. 1p.

7908070126 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908070821 Responds to IE Bulletin 79-02, Revision 1. Conc. site expansion anchor bolts not planned for use w/pipe support base plates. Lists criteria which will be met if use of anchor bolts becomes necessary.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/06. 2pp.

7908140302 Supplements 790529 response to IE Bulletin 78-12B. CB&I generic rept adequately addressed matls used in Units 1 & 2 reactor pressure vessels & C-E rept covered matls in Units 3 & 4 vessels.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/09. 2pp.

7908030105 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010401 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908020552 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130045 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130095 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908160351 Ack receipt of IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No proprietary info.
HOWE, P. W. Carolina Power & Light Co. 79/07/18. 1p.

--7908160411 Forwards IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 2pp.

--7908160415 IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No noncompliance noted. Major areas inspected: const status, licensee-identified items, steam generator mod, concrete placement & response to IE bulletins.
BRADLEY, R. D. Region 2, Atlanta, Office of the Director.
BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 5pp.

7908200209 Ack receipt of IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No proprietary info.
HOWE, P. W. Carolina Power & Light Co. 79/07/18. 1p.

--7908200215 Forwards IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 2pp.

--7908200221 IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No noncompliance noted. Major areas inspected: steel structures & supports, welding procedure specs & QA procedures.
ECONOMOS, N. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/09. 5pp.

7908070716 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160201 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908290631 Responds to NRC 790522 ltr re IE Bulletin 79-11. Util is not using Westinghouse Type DB-75 or DB-50 breakers in any safety-related sys.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/27. 1p.

7908300575 Ack receipt of IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-12 on 790709. No proprietary info.
HOWE, P. W. Carolina Power & Light Co. 79/07/31. 1p.

--7908300578 Forwards IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-12 on 790709-11. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/23. 2pp.

--7908300583 IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-11 on 790709-11. No noncompliance noted. Major areas inspected: structural concrete, site preparation, dams & licensee action on previous insp findings.
HARRIS, J. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/23. 5pp.

7908090575 Responds to IE Bulletin 79-14 requesting verification that seismic analysis applies to actual configuration of safety-related piping sys. Bulletin cannot be addressed because no complete safety-related piping sys has been installed.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/08/01. 1p.

7908170055 Responds to IE Bulletin 79-14 re seismic analyses of as-built safety-related piping sys. No complete sys built.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/08/01. 1p.

7908220621 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

7908280420 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

R Periodic operating reports & related correspondence

7908060263 Forwards seismic monitoring program rept for Apr-June 1979. Responses to NRC 790713 questions re program encl.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/30. 18pp.

DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

A Application/construction stage documents & correspondence

7908100182 Forwards request for addl info to be included in next seismic monitoring program rept in light of first 790430 rept in which no seismic activity was detected in plant site area.
PARR, O. D. Light Water Reactors Branch 3. 79/07/13. 3pp.

7908200119 Responds to 790620 ltr re relation of facility to NC water quality stds & possible violation of licensing & const procedures. State certification received for compliance w/water stds. State clarification has been requested.
BELLS, D. E. Environmental Projects Branch 2. 79/07/19. 2pp.

--7908200124 Requests verification re compliance w/water classification requirements & possible violation of licensing & const procedure.
MARTIN, D. H. Conservation Council of North Carolina. 79/06/20. 1p.

7908070530 Submits evaluation of emergency svc water intake channel backfill previously placed along channel lining. Drawings re field permeability locations & in-place density tests encl.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/08/02. 11pp.

7908160431 Ack receipt of 790816 ltr re Water Quality Certification 214. Certification originally issued 731220, subsequently revised & reissued 770914 & is still valid.
MCRORIE, A. F. North Carolina, State of. 79/08/06. 1p.

7908200008 Forwards rept of 790417-18 site visit re earthwork const, per 790413 telcon. Reviewed field control of soil moisture content & need to review condition of soils supporting pipelines.
THOMPSON, O. O. Geosciences Branch. 79/08/06. 7pp.

G Adjudicatory correspondence

7908140641 Forwards 790425 & 0517 memos re const & piping.
BARTH, C. A. Branch 3. 79/06/04. 1p.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, H. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

P Operating license stage documents & correspondence

7908270446 Approves NRC 790820 request to provide NC Governor J Hunt w/proprietary matl & technical capability matl filed in response to HR Denton 790629 request.
UTLEY, E. E. Carolina Power & Light Co. 79/08/20. 1p.

G Inspection reports, IE Bulletins & correspondence

7908170206 Forwards IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/14. 2pp.

--7908170217 IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24. No noncompliance noted. Major areas inspected: storage & licensee action on previous findings.
HARRIS, J. R. Region 2, Atlanta, Office of the Director. 79/06/12. 4pp.

7908100149 Ack receipt of 790612 ltr responding to 790521 notice of violation. Supplemental response due by 790711.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/25. 1p.

7908070126 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/[illegible]. 2pp.

7908070821 Responds to IE Bulletin 79-02, Revision 1 Concrete expansion anchor bolts not planned for use w/pipe support base plates. Lists criteria which will be met if use of anchor bolts becomes necessary.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/06. 2pp.

7908140302 Supplements 790529 response to IE Bulletin 78-12B. CB&I generic rept adequately addressed matls used in Units 1 & 2 reactor pressure vessels & C-E rept covered matls in Units 3 & 4 vessels.
MCDUFFIE, M. A. Carolina Power & Light Co. 79/07/09. 2pp.

7908030105 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010401 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908020552 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/18 2pp

7908130045 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/18 2pp

7908130095 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/18 2pp

7908160351 Ack receipt of IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No proprietary info.
HOWE, P W Carolina Power & Light Co. 79/07/18 1p

--7908160411 Forwards IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10 2pp

--7908160415 IE Insp Repts 50-400/79-10, 50-401/79-10, 50-402/79-09 & 50-403/79-09 on 790612-15. No noncompliance noted. Major areas inspected: const status, licensee-identified items, steam generator mod, concrete placement & response to IE bulletins.
BRADLEY, R D Region 2, Atlanta, Office of the Director. 79/07/10 5pp

7908200209 Ack receipt of IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No proprietary info.
HOWE, P W Carolina Power & Light Co. 79/07/18 1p

--7908200215 Forwards IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10 2pp

--7908200221 IE Insp Repts 50-400/79-12, 50-401/79-12, 50-402/79-11 & 50-403/79-11 on 790612-14. No noncompliance noted. Major areas inspected: steel structures & supports, welding procedure specs & QA procedures.
ECONOMOS, N Region 2, Atlanta, Office of the Director. 79/07/09 5pp

7908070716 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/26 2pp

7908160201 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/27 2pp

7908290631 Responds to NRC 790522 ltr re IE Bulletin 79-11. Util is not using Westinghouse Type DB-75 or DB-50 breakers in any safety-related sys.
MCDUFFIE, M A Carolina Power & Light Co. 79/07/27 1p

7908300575 Ack receipt of IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-12 on 790709. No proprietary info.
HOWE, P W Carolina Power & Light Co. 79/07/31 1p

--7908300578 Forwards IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-12 on 790709-11. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/23 2pp

--7908300583 IE Insp Repts 50-400/79-13, 50-401/79-13, 50-402/79-12 & 50-403/79-11 on 790709-11. No noncompliance noted. Major areas inspected: structural concrete, site preparation, dams & licensee action on previous insp findings.
HARRIS, J R Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/23 5pp

7908090575 Responds to IE Bulletin 79-14 requesting verification that seismic analysis applies to actual configuration of safety-related piping sys. Bulletin cannot be addressed because no complete safety-related piping sys has been installed.
MCDUFFIE, M A Carolina Power & Light Co. 79/08/01 1p

7908170055 Responds to IE Bulletin 79-14 re seismic analyses of as-built safety-related piping sys. No complete sys built.
MCDUFFIE, M A Carolina Power & Light Co. 79/08/01 1p

7908220621 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/08/07 3pp

7908280420 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B H Region 2, Atlanta, Office of the Director. 79/08/13 2pp

R Periodic operating reports & related correspondence

7908060263 Forwards second seismic monitring program rept for Apr-June 1979. Responses to NRC 790713 questions re program encl.
MCDUFFIE, M A Carolina Power & Light Co. 79/07/30 18pp

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

7908080683 Responds to FOIA request for documents re North Anna nuclear power plants.
FELTON, J M Division of Rules and Records. 79/08/03 2pp

--7908080692 Responds to 770401 request for info re investigations of allegations of withholding steam generator info. Technical staff responses encl.
SHAPAR, H K Office of the Executive Legal Director. 77/05/05 12pp

7908150509 Responds to FOIA request for documents relating to alleged withholding of info re nuclear plants operated by VEPCO. Documents requested encl.
FELTON, J M Division of Rules and Records. 79/08/06 1p

7908150673 Describes status per util 790206 ltr expressing intention to provide NRC w/util positions which are not in compliance w/reg guides. Units are in compliance w/Reg Guide 1.136, w/some exceptions.
BROWN, S C Virginia Electric & Power Co. 79/08/13 3pp

7908240452 Provides revised design groundwater level predictions per 760315 ltr. Subsurface drainage has not been incorporated in figures although appropriate mods have been made to assure adequacy of safety-related structures & facilities.
BROWN, S C Virginia Electric & Power Co. 79/08/21 3pp

7908280558 Advises of position re Reg Guide 1.140, Revision 0, "Design, Testing & Maint Criteria for Normal Ventilation Exhaust Air Filtration & Absorption Units of Light Water Cooled Nuclear Power Plants."
BROWN, S C Virginia Electric & Power Co. 79/08/24 4pp

7908280560 Advises of position re Reg Guide 1.52, Revision 2, "Design, Testing & Maint Criteria for Post-Accident Engineered Safety Feature Atmosphere Cleanup Sys Air Filtration & Absorption Units of Light Water Cooled Nuclear Power Plants."
BROWN, S C Virginia Electric & Power Co. 79/08/24 3pp

G Inspection reports, IE Bulletins & correspondence

7908020210 Forwards IE Insp Repts 50-338/79-22, 50-339/79-30, 50-404/79-03 & 50-405/79-03 on 790423-25. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/16 2pp

--7908020217 IE Insp Repts 50-338/79-22, 50-339/79-30, 50-404/79-03 & 50-405/79-03 on 790423-25. No noncompliance noted. Major areas inspected: structural concrete QA/QC controls, svc water pumphouse settlement data, work performance & records.
LENAHAN, J J , BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/11 7pp

7908010683 Responds to IE Bulletin 79-09 re use of GE Type AK-2-25 circuit breakers. Breakers will be used in preventive maint program by qualified personnel.
BROWN, S C Virginia Electric & Power Co. 79/06/19 2pp

7908240114 Forwards IE Insp Repts 50-339/79-33, 50-404/79-05 & 50-405/79-05 on 790529-31. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/22 2pp

--7908240118 IE Insp Repts 50-339/79-33, 50-404/79-05 & 50-405/79-05 on 790529-31. No noncompliance noted. Major areas inspected: 10CFR50.55(e) items, response to IE Bulletins & site QA & QC organization & responsibilities.
MCFARLAND, C. R. ; BRYANT, J. C. Region 2, Atlanta, Office of the Director. 79/06/20. 6pp.

7908070178 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908020269 Responds to IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." No Category I pipe support baseplates have been installed.
BROWN, S. C. Virginia Electric & Power Co. 79/06/27. 1p.

7908080678 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/02. 2pp.

7908150365 Submits final review of compliance w/IE Bulletin 79-03 re weld defects in steel pipe spools mfg by Youngstown Welding & Engineering Co. All items & matl radiographically inspected or reviewed & found acceptable.
BROWN, S. C. Virginia Electric & Power Co. 79/07/11. 3pp.

7908030144 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010418 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908060342 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030042 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080063 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130281 Notifies that IE Bulletin 79-14 is revised to limit scope of required work. Forwards replacement page.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908070771 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160276 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908170058 Responds to IE Bulletin 79-14 re seismic analyses for as-built safety-related piping sys. No safety-related piping installed. Lists relevant input documents & describes insp program.
BROWN, S. C. Virginia Electric & Power Co. 79/08/01. 3pp.

7908220657 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 2pp.

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

A. Application/construction stage documents & correspondence

7908080683 Responds to FOIA request for documents re North Anna nuclear power plants.
FELTON, J. M. Division of Rules and Records. 79/08/03. 2pp.

--7908080692 Responds to 770401 request for info re investigations of allegations of withholding steam generator info. Technical staff responses encl.
SHAPAR, H. K. Office of the Executive Legal Director. 77/05/05. 12pp.

7908150509 Responds to FOIA request for documents relating to alleged withholding of info re nuclear plants operated by VEPCO. Documents requested encl.
FELTON, J. M. Division of Rules and Records. 79/08/06. 1p.

7908150673 Describes status per util 790206 ltr, expressing intention to provide NRC w/util positions which are not in compliance w/reg guides. Units are in compliance w/Reg Guide 1.138, w/some exceptions.
BROWN, S. C. Virginia Electric & Power Co. 79/08/13. 3pp.

7908240452 Provides revised design groundwater level predictions per 760315 ltr. Subsurface drainage has not been incorporated in figures although appropriate mods have been made to assure adequacy of safety-related structures & facilities.
BROWN, S. C. Virginia Electric & Power Co. 79/08/21. 3pp.

7908280558 Advises of position re Reg Guide 1.140, Revision 0, "Design, Testing & Maint Criteria for Normal Ventilation Exhaust Air Filtration & Absorption Units of Light Water Cooled Nuclear Power Plants."
BROWN, S. C. Virginia Electric & Power Co. 79/08/24. 4pp.

7908280560 Advises of position re Reg Guide 1.52, Revision 2, "Design, Testing & Maint Criteria for Post-Accident Engineered Safety Feature Atmosphere Cleanup Sys Air Filtration & Absorption Units of Light Water Cooled Nuclear Power Plants."
BROWN, S. C. Virginia Electric & Power Co. 79/08/24. 3pp.

B. Inspection reports, IE Bulletins & correspondence

7908020210 Forwards IE Insp Repts 50-338/79-22, 50-339/79-30, 50-404/79-03 & 50-405/79-03 on 790423-25. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/16. 2pp.

--7908020217 IE Insp Repts 50-338/79-22, 50-339/79-30, 50-404/79-03 & 50-405/79-03 on 790423-25. No noncompliance noted. Major areas inspected: structural concrete QA/QC controls, svc water pumphouse settlement data, work performance & records.
LENAHAN, J. J. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/11. 7pp.

7908010683 Responds to IE Bulletin 79-09 re use of GE Type AK-2-25 circuit breakers. Breakers will be used in preventive maint program by qualified personnel.
BROWN, S. C. Virginia Electric & Power Co. 79/06/19. 2pp.

7908240114 Forwards IE Insp Repts 50-339/79-33, 50-404/79-05 & 50-405/79-05 on 790529-31. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/22. 2pp.

--7908240118 IE Insp Repts 50-339/79-33, 50-404/79-05 & 50-405/79-05 on 790529-31. No noncompliance noted. Major areas inspected: 10CFR50.55(e) items, response to IE Bulletins & site QA & QC organization & responsibilities.
MCFARLAND, C. R. ; BRYANT, J. C. Region 2, Atlanta, Office of the Director. 79/06/20. 6pp.

7908070178 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908020269 Responds to IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." No Category I pipe support baseplates have been installed.
BROWN, S. C. Virginia Electric & Power Co. 79/06/27. 1p.

7908080678 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/02. 2pp.

7908150365 Submits final review of compliance w/IE Bulletin 79-03 re weld defects in steel pipe spools mfg by Youngstown Welding & Engineering Co. All items & matl radiographically inspected or reviewed & found acceptable.
BROWN, S. C. Virginia Electric & Power Co. 79/07/11. 3pp.

7908030144 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010418 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/17 2pp.

7908060362 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/17 2pp.

7908030042 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/18 2pp.

7908080063 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/19 2pp.

7908130281 Notifies that IE Bulletin 79-14 is revised to limit scope of required work. Forwards replacement page.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/18 2pp.

7908070771 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/26 2pp.

7908160276 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/27 2pp.

7908170058 Responds to IE Bulletin 79-14 re seismic analyses for as-built safety-related piping sys. No safety-related piping installed. Lists relevant input documents & describes insp program.
BROWN, S C Virginia Electric & Power Co. 79/08/01 3pp.

7908220657 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/08/07 2pp.

DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7908010021 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/06
1p.

7908160098 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/08/10
1p.

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

7908270215 Ack receipt of 790323 ltr transmitting safeguards contingency plan for facility Class III fee required.
DIGGS, R M License Fee Management Branch 79/07/03 2pp.

7908270453 Forwards security force training & qualification plan. Plan withheld (ref 10CFR2.790).
LINDER, F Dairyland Power Cooperative 79/08/17 2pp.

G Adjudicatory correspondence

7908030108 Forwards 790521 petition filed by AK Morse requesting issuance of order to suspend License DPR-45. FR notice encl.
DENTON, H R Office of Nuclear Reactor Regulation 79/06/19 2pp.

--7908030113 Motion to suspend provisional License DPR-45 until spent fuel pool expansion is approved by NRC. Certificate of Svc encl.
MORSE, A K Affiliation Unknown 79/05/21 8pp.

7908080664 Notifies that safety evaluation & EIA for proposed license amend are nearing completion. Issuance is expected within two to three weeks.
WOODHEAD, C P Branch 3 79/06/28 1p.

7908170284 Forwards responses to two motions to suspend License DPR-45. Requests meeting w/licensee to discuss justification for not complying w/generic ltr to cease purging or limit purging to absolute min of 90-h.
GRIMES, B Assistant Director for Systems Engineering 79/07/13
6pp.

H General correspondence

7908080613 Forwards fee for application to amend License DPR-45, per 790718 request.
LINDER, F Dairyland Power Cooperative 79/08/02 1p.

7908230319 Forwards summary of mgt & technical resources available for handling unusual events.
LINDER, F Dairyland Power Cooperative 79/08/10 1p.

J Insurance & indemnity information

7908280603 Forwards Endorsement 33 to ANI Policy NF-217.
DEVINE, H F Dairyland Power Cooperative 79/08/22 2pp.

P Operating license stage documents & correspondence

7908270190 Requests addl info re util 761221 submittal on containment leak testing. Forwards copy of Div of Operating Reactors position on implementation of containment leakage testing requirement.
LAINAS, G Plant Systems Branch 79/07/20 12pp.

7908100322 Forwards NRC 790308 memo summarizing 790209 meeting w/SEP owners group re technical details of project.
SMITH, H Operating Reactors Branch 2 (Pre 790625) 79/04/19
5pp.

--7908100359 Summary of 790209 meeting w/SEP owners group in Livermore, CA re technical details of site-specific spectra project.
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625)
79/03/08 10pp.

7908030301 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Recommendations to improve diesel generator reliability will be weighed against any adverse impacts from implementation. W/o encl.
EISENHUT, D G Division of Operating Reactors 79/06/04 52pp.

7908070666 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22
3pp.

7908010696 Requests registration as user of Model LL-50-100.
LINDER, F Dairyland Power Cooperative 79/06/27 2pp.

7908100528 Notifies that licensees are encouraged to use initial notification/reactor operations sys during drill, if drill scenario requires notification of NRC.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/09
1p.

7908060209 Summary of 790628 meeting w/BWR licensees, applicants & GE re NRC short-term evaluation program for BWRs in light of accident at TMI.
KANE, W F Standardization Branch 79/07/11 26pp.

7908130661 Forwards Special Rept 17-5627 re sixth mechanized ultrasonic investigation of laminar indication inplate of BWR pressure vessel. W/o encl.
LINDER, F Dairyland Power Cooperative 79/07/11 2pp.

7908160096 Forwards safety evaluation & EIA supporting facility mods to increase capacity of spent fuel storage pool & amend to License DPR-45 per 780420 application. Proposed Tech Specs encl.
ZIEMANN, D L Operating Reactors Branch 2 79/07/13 2pp.

--7908160101 Safety evaluation supporting facility mods to increase capacity of spent fuel storage pool.
* Office of Nuclear Reactor Regulation 79/07/13 20pp.

--7908160103 EIA supporting amend to DPR-45 re increase in storage capacity of fuel element storage well from 134 to 440 storage cells.
* Office of Nuclear Reactor Regulation. 79/07/13. 20pp.

--7908160108 Proposed Tech Specs re spent fuel storage & handling.
* Office of Nuclear Reactor Regulation. 79/07/13. 3pp.

7908080350 Forwards NUREG-0462, "Technical Rept on Operating Experience w/BWR Pressure Relief Sys." Requests info re Target Rock safety relief valves W/o encl.
GRIMES, B. K. Assistant Director for Systems Engineering. 79/07/16. 4pp.

7908160303 Forwards request for addl info re sys area & small break LOCA analysis.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/17. 19pp.

7908030292 Notification of 790801 meeting w/operating reactor licensees & applicants in Bethesda, MD to discuss status of TMI-2 activities by NRC task force groups. Meeting agenda & list of attendees encl.
EISENHUT, D. G. Division of Operating Reactors. 79/07/18. 58pp.

7908100290 Forwards NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for BWRs."
GAMMILL, W. P. Assistant Director for Standard & Advanced Reactors. 79/07/18. 1p.

7908140483 Requests submission of Class III fee for review of rod drop safety issue as discussed in rept, "LACBWR Rod Drop Probability Study."
MILLER, W. O. License Fee Management Branch. 79/07/18. 1p.

7908070338 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/19. 1p.

7908170468 Forwards summary of 790628 meeting re NRC evaluation program for operating BWR plants & near-term OLs.
* Office of Nuclear Reactor Regulation. 79/07/19. 3pp.

7908230171 Requests addl info re degraded grid voltage.
LAINAS, G. Plant Systems Branch. 79/07/20. 3pp.

7908090552 Requests 40 copies of response to 790629 request for info re corporate mgt & technical capabilities to cope w/TMI-2 type events. Requests addl five copies of response for each unit, if more than one is owned & operated.
HAASS, W. P. Quality Assurance Branch. 79/07/24. 1p.

7908210543 Summary of 790709-10 site visit to Univ of IL lab as part of SEP review. Current soils testing rogram was inspected.
GREEVES, J. T. Geosciences Branch. 79/07/26. 4pp.

7908030170 Forwards fee covering request for approval/amend to safeguards contingency plan, in response to NRC 790703 request.
LINDER, F. Dairyland Power Cooperative. 79/07/27. 1p.

7908100157 Forwards Amend 17 to License DPR-45, safety evaluation & notice of issuance & availability.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/27. 3pp.

--7908100165 Amend 17 to License DPR-45, adding license condition re completion of facility mods to improve fire protection program.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/27. 2pp.

--7908100168 Safety evaluation supporting Amend 17 to License DPR-45.
* Operating Reactors Branch 2. 79/07/27. 62pp.

--7908100173 Notice of issuance & availability of Amend 17 to License DPR-45.
SILVER, R. D. Operating Reactors Branch 2. 79/07/27. 2pp.

--7908100185 Discusses SER re fire protection in operating nuclear power stations. Areas & of concern included valve supervision, ventilation & hose testing.
HALL, R. E. Brookhaven National Laboratory. 79/04/06. 4pp.

7908240206 Clarifies changes in review responsibility for Generic Item B-24. SEP branch will review purge isolation matter.
REEVES, E. A. Operating Reactors Branch 1. 79/07/27. 1p.

7908300776 Continues review of 770722 submittal re degraded grid voltage for BWR. Use of existing undervoltage relaying to protect against sustained degraded grid condition is unacceptable.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/30. 2pp.

7908230246 Requests addl info re contingency plan in order to continue review. Requests response within 45 days. Plan withheld (ref 10CFR2.790).
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/31. 2pp.

7908290114 Sets forth mods to NRC needs re NRC 790717 ltr requesting addl info required for rept on BWR Changes made after meeting w/GE BWR owners group.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/31. 5pp.

7908230217 Notification of regional meetings w/all power reactor licensees & applicants to discuss recent impacts on emergency planning & current regulations, guidance documents & repts re emergency planning.
EISENHUT, D. G. Division of Operating Reactors. 79/08/03. 53pp.

7908200334 Forwards info requested in NRC 750124 ltr re util request to expand spent fuel storage capacity. Proposed amend to OL DPR-45 re possession & use limits, proposed Tech Spec for leak testing & revised safeguards rept for operations encl.
LINDER, F. Dairyland Power Cooperative. 79/08/06. 8pp.

7908210249 Notifies NRC that facility does not use Target rock safety relief valves & will not act upon 790716 request for info.
LINDER, F. Dairyland Power Cooperative. 79/08/07. 1p.

7908160449 Forwards "LACBWR Fuel Cycle 6 Startup Test Program Results."
LINDER, F. Dairyland Power Cooperative. 79/08/08. 1p.

--7908160453 "LACBWR Fuel Cycle 6 Startup Test Program Results."
RAFFETY, S. J. Dairyland Power Cooperative. LAC-TR-070. 79/08/06. 14pp.

7908230678 Notification of 790822 meeting w/util in Bethesda, MD to discuss containment ventilation damper isolation reliability.
SHEA, J. J. Operating Reactors Branch 2. 79/08/08. 2pp.

7908230155 Requests utils provide description of methods to verify that offsite power sys & onsite distribution sys are capable of automatically restarting & maintaining all required safety loads in event of LOCA or loss of onsite or offsite power.
GAMMILL, W. Assistant Director for Operating Reactor Projects. 79/08/09. 56pp.

7908270413 Submits application to amend DPR-45 by proposing changes to Tech Specs re monitoring & limiting of effluent discharges & supplemental monitoring of plant environ.
LINDER, F. Dairyland Power Cooperative. 79/08/14. 3pp.

G Inspection reports, IE Bulletins & correspondence

7907190015 Forwards Revision 1 to Figure 1 encl in 790523 ltr, providing addl info in response to IE Bulletin 79-08.
LINDER, F. Dairyland Power Cooperative. 79/05/29. 2pp.

7908070175 Submits addl info in response to IE Bulletin 78-12B. No generic rept for facility. BWR vessel will be submitted by Allis-Chalmers. Requested info was submitted 790130 & 781227.
LINDER, F. Dairyland Power Cooperative. 79/05/30. 2pp.

7908080395 Responds to 790308 & 0621 ltrs re IE Bulletins 79-02 & 02, Revision 1. No pipe support anchors w/concrete expansion bolts used in Seismic Category 1 piping sys.
LINDER, F. Dairyland Power Cooperative. 79/06/06. 1p.

7908130339 Notifies all BWR licensees of status of NRC review of licensee response to IE Bulletin 79-08. Requests attendance at 790628 meeting in Bethesda, MD re info needed by NRC to complete review.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 79/06/20. 44pp.

7908210122 Forwards IE Insp Rept 50-409/79-13 on 790604-07 & notice of violation.
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/29. 2pp.

--7908210127 Notice of violation from insp on 790604-07.
* Region 3, Chicago, Office of the Director. 79/06/29. 1p.

DOCKETED ITEMS

--7908210131 IE Insp Rept 50-409/79-13 on 790604-07. Noncompliance noted: failure to keep sufficient records for Type B shipment.
GREGER, L. R. Region 3, Chicago, Office of the Director.
FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/27. 9pp.

7908240161 Forwards IE Insp Rept 50-409/79-12 on 790522-24 & 0709. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/16. 2pp.

--7908240314 IE Insp Rept 50-409/79-12 on 790522-24 & 790709. No noncompliance noted. Major areas inspected: soil test borings & recovery of undisturbed soil samples & review procedures & specs for test borings.
HAUES, D. W.; GALLAGHER, E. J. Region 3, Chicago, Office of the Director. 79/07/12. 42pp.

7908020330 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908080299 Requests addl info to suppl previous response to IE Bulletin 79-08 to enable NRC to complete safety evaluation.
ZIEMANN, D. L. Operating Reactors Branch 2. 79/07/20. 4pp.

7908010002 Forwards IE Insp Rept 50-409/79-14 on 790621-22. Notice of violation withheld (ref 10CFR2.790).
HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/07/23. 2pp.

--7908010009 IE Insp Rept 50-409/79-14 on 790621-22. Noncompliance noted: failure to perform interim security measures, failure to maintain footcandle illumination level & failure to control all points of access. Details withheld (ref 10CFR2.790).
MADEDA, T. J.; SCHEFFER, J. C.; HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/07/18. 1p.

7908290354 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300404 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908150683 Forwards inservice insp testing programs in accordance w/commitment made in application to amend provisional License DPR-45, submitted in 790511 ltr. W/23 oversized drawings.
LINDER, F. Dairyland Power Cooperative. 79/07/27. 139pp.

7908150347 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908170022 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/08. 1p.

7908300275 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

7908220366 Forwards addl info per NRC 790720 request re IE Bulletin 79-08 events relevant to BWRs identified during TMI incident.
LINDER, F. Dairyland Power Cooperative. 79/08/16. 7pp.

R Periodic operating reports & related correspondence

7908150419 Forwards monthly operating rept for Jul 1979.
LINDER, F. Dairyland Power Cooperative. 79/08/08. 1p.

--7908150428 Monthly operating rept for Jul 1979.
PAPWORTH, L. G. Dairyland Power Cooperative. 79/08/06. 10pp.

7908210391 Forwards reactor containment bldg integrated leak rate test for May 1979.
LINDER, F. Dairyland Power Cooperative. 79/08/14. 1p.

--7908210393 Reactor containment bldg integrated leak rate test for May 1979.
PAPWORTH, L. G. Dairyland Power Cooperative. LAC-TR-071. 79/05/31. 58pp.

S Reportable occurrences, LERs & related correspondence

7908140642 Forwards LER 79-013/03L-0.
LINDER, F. Dairyland Power Cooperative. 79/07/25. 4pp.

--7908140647 LER 79-013/03L-0 on 790704 during reactor power escalation, piston rod seal failure on turbine main steam bypass valve operating cylinder resulted in loss of hydraulic oil. Caused by normal wear of seal. Seals & oil replaced.
PAPWORTH, L. G. Dairyland Power Cooperative. 79/07/25. 1p.

7908030468 Forwards LER 79-012/03L-0.
LINDER, F. Dairyland Power Cooperative. 79/07/27. 2pp.

--7908030481 LER 79-012/03L-0 on 790702 during operation, test revealed pump A1 failed to start upon manual actuation of control room switch. Caused by electrical short causing diodes to burn out & fuel valve to remain closed. Diodes replaced.
WILEY, P. J. Dairyland Power Cooperative. 79/07/27. 1p.

7908150193 Forwards LER 79-014/03L-0.
LINDER, F. Dairyland Power Cooperative. 79/08/06. 2pp.

--7908150214 LER 79-014/03L-0 on 790708 during power escalation, control rod 10 was withdrawn rather than control rod 12, placing rods in out-sequence condition. Caused by operating personnel error. Compliance w/program to be emphasized.
PAPWORTH, L. G. Dairyland Power Cooperative. 79/07/27. 1p.

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7908010360 Informs that feedwater nozzle design rept will be submitted in Jan 1980. Delay is due to review of GE topical rept NEDE-21821, "BWR Feedwater Nozzle/Sparger Final Rept," & NEDE-21821-01 (Suppl 1).
RHODE, G. K. Niagara Mohawk Power Corp. 79/07/27. 1p.

7908010366 Informs that rept re use of austenitic stainless steel will be submitted by Jan 1980.
RHODE, G. K. Niagara Mohawk Power Corp. 79/07/27. 1p.

7908030500 Discusses reasons for plant safety review & audit board changing annual audit on ETS from third quarter to fourth quarter of year.
DISE, D. P. Niagara Mohawk Power Corp. 79/07/31. 1p.

7908160450 Requests review & approval of use of threaded splice method for reinforcing bar splicing in Category 1 structures. Forwards 761212 ASME Code case approving method of splicing.
RHODE, G. K. Niagara Mohawk Power Corp. 79/08/09. 1p.

--7908160452 "Cases of ASME Boiler & Pressure Vessel Code."
* American Society of Mechanical Engineers. 76/12/12. 3pp.

7908220381 Notifies that info requested in NRC 790713 ltr re safety sys is in NEDE-24708, "Addl Info Required for NRC Staff Generic Rept on BWRs," transmitted to D Ross on 790817. Rept suppl will be submitted by 791116.
DISE, D. P. Niagara Mohawk Power Corp. 79/08/17. 1p.

7908310387 Requests reopening of antitrust investigation re CP application. Util refusal to supply power to Massena, NY is coercive attempt to restrain free trade.
WEBER, S. Ecology Action of Oswego. 79/08/25. 1p.

Q Inspection reports, IE Bulletins & correspondence

7908080497 Responds to IE Bulletin 79-04. No 1500-psi 3/4 or 6-inch velan swing check valves installed or planned in Category 1 pip.ng sys.
RHODE, G. K. Niagara Mohawk Power Corp. 79/05/31. 1p.

7908070040 Responds to IE Bulletin 79-12B re atypical weld matl in reactor pressure vessel welds. Info requested was provided in CB&I 790501 generic rept CB&I certification & GE verification encl.
RHODE, G. K. Niagara Mohawk Power Corp. 79/06/15. 3pp.

7908030024 Responds to IE Bulletin 79-09. GE Type AK-2 circuit breakers will not be used in safety-related sys.
RHODE, G K Niagara Mohawk Power Corp 79/06/18 1p

7908200051 Forwards IE Insp Rept 50-410/79-04 on 790424-26. No noncompliance noted.
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/26 2pp

--7908200054 IE Insp Rept 50-410/79-04 on 790424-26. No noncompliance noted. Major areas inspected: reinforcing steel installation & cadwelding in primary containment exterior wall & record review of concrete placement in primary wall.
VARELA, A A Region 1, Philadelphia, Office of the Director
EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/21 6pp

7908070795 Responds to IE Bulletin 79-03 re stainless steel pipe spools mfg by Youngs* Welding & Mfg Co. Identifies safety-related sys where certain stainless steel pipe spools are in use. Reviews plan for insp & corrective actions.
BARTLETT, J Niagara Mohawk Power Corp 79/07/05 3pp

7908170458 Responds to IE Bulletin 79-02. Description of analytical model re base plate designs will be submitted by 790815. No sleeve- or shell-type anchor bolts to be used. Discusses bolt manufacturer QC test program & marking sys.
RHODE, G K Niagara Mohawk Power Corp 79/07/10 3pp

7908010506 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/07/17 1p

7908060388 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-related Piping Sys." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/07/18 1p

7908030258 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/07/19 1p

7908240220 Ack receipt of 790628 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-410/79-02.
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/07/20 1p

--7908240225 Responds to NRC 790618 ltr re violations noted in IE Insp Rept 50-410/79-02. Submits addl info re fluid head forging & penetration sleeves for facility. Radiography will be attempted on welds.
RHODE, G K Niagara Mohawk Power Corp 79/06/28 3pp

7908230088 Responds to IE Bulletin 79-11 Westinghouse Type DB-50 & DB-75 circuit breakers will not be used in safety-related sys.
RHODE, G K Niagara Mohawk Power Corp 79/07/25 1p

7908100244 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/07/26 1p

7908280142 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/08/07 1p

7908280302 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/08/13 1p

7908300151 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/08/15 1p

B. Reportable occurrences, LERs & related correspondence

7908090181 Ack receipt of 790522 ltr & interim deficiency rept nondestructive examination on containment liner welds.
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/05 1p

--7908090192 Submits interim deficiency rept re inadequate nondestructive examination of various weld configurations on containment liner. Final rept to be submitted by 790618.
RHODE, G K Niagara Mohawk Power Corp 79/05/22 1p

7908140652 Ack receipt of 790619 ltr re inadequate nondestructive examination of containment liner welds.
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/07/02 1p

--7908140660 Submits interim rept of deficiency re inadequate nondestructive examination of circumferential k-type butt seam welds in containment liner lower assembly. Detailed radiographic examination will be performed.
RHODE, G K Niagara Mohawk Power Corp 79/06/19 3pp

7908210106 Ack receipt of 790702 ltr forwarding interim rept on biological shield wall linear indications. Rept will be reviewed & evaluated.
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/07/17 1p

--7908210112 Submits interim rept on potential deficiency re biological shield wall. Linear indications found in two locations at weld. Two linear indications removed by grinding.
RHODE, G K Niagara Mohawk Power Corp 79/07/02 1p

7908170072 Ack receipt of 790322 ltr forwarding final rept re safety relief valve actuation. Considers rept to be closed.
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/07/26 1p

--7908170080 Advises NRC of current work w/GE consultants & Mark II Containment Group to resolve safety relief valve actuation & loads on primary containment issues. Will address issues in FSAR.
RHODE, G K Niagara Mohawk Power Corp 79/03/22 1p

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908150507 Responds to FOIA request for records re Task Action Plans A-40 & A-41, documents written by HR Denton & C Stepp, records re seismic issues & insp repts for facilities. Requested documents will be made available.
FELTON, J M Division of Rules and Records 79/07/04 2pp

7908150669 Forwards Amend 3 to "Rept on Soil Densification Program."
WOOLEVER, E J Duquesne Light Co 79/07/23 2pp

--7908150677 "Rept on Soil Densification Program," Amend 3.
* Duquesne Light Co 79/07/06 2500pp

G. Inspection reports, IE Bulletins & correspondence

7908080494 Responds to IE Bulletin 79-04. No 3, 4 or 6-inch velan swing check valves used in facility.
SCHAFFER, S G Duquesne Light Co 79/05/30 1p

7908030178 Responds to IE Bulletin 79-09 re GE Type AK-2 circuit breakers. No circuit breakers of type specified used in any safety-related sys.
WOOLEVER, E J Duquesne Light Co 79/06/21 1p

7908070753 Responds to IE Bulletin 78-12. Forwards C-E 790608 ltr certifying rept "Atypical Weld Matl in Reactor Pressure Vessel Welds," addresses matl used in facility.
WOOLEVER, E J Duquesne Light Co 79/06/29 2pp

7908010424 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/07/17 1p

7908060368 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/07/18 1p

7908030239 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B H Region 1, Philadelphia, Office of the Director
79/07/19 1p

7908200009 Responds to IE Bulletin 79-11 re use of Westinghouse Type DB-50 & DB-75 circuit breakers. Not planned for use at facility.
WOOLEVER, E J Duquesne Light Co 79/07/20 1p

7908100226 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director
79/07/26 1p

7908280074 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/07 1p

7908280268 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/13 1p

7908310281 Forwards IE Info Notice 79-20, "NF rcement Policy - NRC Licensed Individuals." No action required.
GRIER,B.H. Region 1, Philadelphia, Offi he Director.
79/08/14 1p

7908300117 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER,B.H. Region 1, Philadelphia, Office of the Director.
79/08/15 1p

6. Reportable occurrences, LERs & related correspondence

7908010299 Ack receipt of 790601 ltr re second interim deficiency rept on stop work directive for Bingham-Willamette Co.
CARLSON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/12 1p

7908240604 Concurs in 790713 request for extension to 790810 for submittal of final rept re stop work directive for Bingham-Willamette Co.
CARLSON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/07/25 1p

7908160438 Forwards final rept re stop work order issued to Bingham-Willamette Co on 790329.
WIDLEVER,E.J. Duquesne Light Co. 79/08/10 1p

--7908160443 Final rept on stop work order issued to Bingham-Willamette Co on 790329.Vendor failed to demonstrate compliance w/spec requirements for post-weld repair heat treating. Vendor will correct operational defects.
* Duquesne Light Co. 79/08/10 2pp

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D.B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD,H. Light Water Reactors Branch 2 79/07/02 70pp

7908090037 Forwards acceptance review of FSAR Recommends that application be accepted when encl questions are answered in acceptable manner.
SATTERFIELD,R.M. Electric, Instrumentation & Control Systems Branch 79/07/09 8pp

7908060220 Responds to 790706 request re info on potential impact on NRC resource needs & priorities associated w/decision to delay commercial operation of Cherokee 1 & 2 & postpone financial commitments for Cherokee 3 & Perkins 1,2 & 3.
DAIL,L.C. Duke Power Co. 79/07/27 8pp

7908130559 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation.Model license condition encl.
RUBENSTEIN,L.S. Light Water Reactors Branch 4 79/08/01 4pp

7908130446 Notifies that projected dates for fuel loading & commercial operation are delayed.Will forward request & justification for extension of CP to accommodate relay.
DAIL,L.C. Duke Power Co. 79/08/06 1p

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908150462 Requests use of ASME Code Case N-242 for steam generator power operated relief valves.B&W certificate of conformance encl.
DAIL,L.C. Duke Power Co. 79/08/08 2pp

G. Inspection reports, IE Bulletins & correspondence

7908070131 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/06/26 2pp

7908080203 Responds to IE Bulletin 79-02,Revision 1.Base plate flexibility will be accounted for in calculation of expansion anchor bolt loads for all seismic Category I pipe support base plates.
DAIL,L.C. Duke Power Co. 79/07/05 4pp

7908100381 Ack receipt of 790627 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-11 & 50-414/79-11.
SUTHERLAND,J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/06 1p

--7908100382 Notifies that NRC 790605 ltr & encl rept documenting insp on 790515-17 contained error in rept number.Rept number for both units is 79-11,not 79-4.
SUTHERLAND,J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/06 1p

--7908100383 Responds to NRC 790605 ltr re violations noted in IE Insp Repts 50-413/79-04 & 50-414/79-04.Corrective actions:bank opposite low pressure svc water intake structure was riprapped on 790525 to control erosion.
DAIL,L.C. Duke Power Co. 79/06/22 1p

--7908100384 Forwards IE Insp Repts 50-413/79-04 & 50-414/79-04 on 790515-17 & notice of violation.
SUTHERLAND,J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/05 2pp

--7908100385 Notice of violation from insp on 790515-17.
* Region 2, Atlanta, Office of the Director 79/06/05 1p

--7908100386 IE Insp Rept 50-413/79-11 & 50-414/79-11 on 790515-17. Noncompliance noted:failure to control erosion along section of intake cove opposite low pressure svc water intake structure.
CUNNINGHAM,A.L., HUFHAM,J.W. Region 2, Atlanta, Office of the Director 79/06/05 4pp

7908030121 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/13 2pp

7906230230 Responds to IE Bulletin 79-09.No GE Type AK-2 circuit breakers used or planned for use in safety-related sys.
DAIL,L.C. Duke Power Co. 79/07/16 1p

7908010407 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/17 2pp

7908030005 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/18 2pp

7908130101 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/18 2pp

7908060005 Responds to IE Bulletin 79-11.No Westinghouse DB-50 or DB-75 circuit breakers are used or planned for use in safety-related sys.
DAIL,L.C. Duke Power Co. 79/07/19 1p

7908070730 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/26 2pp

7908160214 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/27 2pp

7908270306 Ack receipt of IE Insp Repts 50-413/79-13 & 50-414/79-13 on 790627-29 No proprietary info
DAIL, L C Duke Power Co 79/08/01 1p

--7908270309 Forwards IE Insp Repts 50-413/79-13 & 50-414/79-13 on 790627-29 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/20 2pp

--7908270310 IE Insp Repts 50-413/79-13 & 50-414/79-13 on 790627-29 No noncompliance noted Major areas inspected safety-related piping & installation activities including welding & review of welding quality records
VANDOORN, P K Region 2, Atlanta, Office of the Director
79/07/19 5pp

7908220625 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/08/07 3pp

5 Reportable occurrences, LERs & related correspondence

7908140671 Forwards significant deficiency 413-414/79-1
DAIL, L C Duke Power Co 79/07/20 1p

--7908140679 Significant deficiency 79-1 during installation of equipment on section of main control board, deficient skip weld of wire duct detected Investigation revealed 60 improper welds All welds will be repaired by 790629
* Duke Power Co 79/06/21 2pp

7908280621 Forwards final deficiency rept re safety-related valve/operator natural frequency analysis
DAIL, L C Duke Power Co 79/08/14 2pp

--7908280627 Final deficiency rept IE-77/03-SPS-413/414 re potential malfunction of safety-related butterfly valve operators used in containment isolation valves Valves have been tested & operator support brackets redesigned
* Duke Power Co 79/08/10 2pp

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications
VASSALLO, D B Assistant Director for Light Water Reactors
79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities
ROOD, H Light Water Reactors Branch 2 79/07/02 70pp

7908090037 Forwards acceptance review of FSAR Recommends that application be accepted when encl questions are answered in acceptable manner
SATTERFIELD, R M Electric, Instrumentation & Control Systems Branch 79/07/09 8pp

7908060220 Responds to 790706 request re info on potential impacts on NRC resource needs & priorities associated w/decision to delay commercial operation of Cherokee 1 & 2 & postpone financial commitments for Cherokee 3 & Perkins 1, 2 & 3
DAIL, L C Duke Power Co 79/07/27 8pp

7908130559 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition Current STS for all PWRs are ineffective re steam generator tube degradation Model license condition encl
RUBENSTEIN, L S Light Water Reactors Branch 4 79/08/01 4pp

7908130446 Notifies that projected dates for fuel loading & commercial operation are delayed Will forward request & justification for extension of CP to accommodate relay
DAIL, L C Duke Power Co 79/08/06 1p

7908150462 Requests use of ASME Code Case N-242 for steam generator power operated relief valves B&W certificate of conformance encl
DAIL, L C Duke Power Co 79/08/08 2pp

6 Inspection reports, IE Bulletins & correspondence

7908070111 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/06/26 2pp

7908080203 Responds to IE Bulletin 79-02, Revision 1 Base plate flexibility will be accounted for in calculation of expansion anchor bolt loads for all seismic Category 1 pipe support base plates
DAIL, L C Duke Power Co 79/07/05 4pp

7908100381 Ack receipt of 790627 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-11 & 50-414/79-11
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/06 1p

--7908100382 Notifies that NRC 790605 ltr & encl rept documenting insp on 790515-17 contained error in rept number Rept number for both units is 79-11, not 79-4
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/06 1p

--7908100383 Responds to NRC 790605 ltr re violations noted in IE Insp Repts 50-413/79-04 & 50-414/79-04 Corrective actions: bank opposite low pressure svc water intake structure was riprapped on 790525 to control erosion
DAIL, L C Duke Power Co 79/06/22 1p

--7908100384 Forwards IE Insp Repts 50-413/79-04 & 50-414/79-04 on 790515-17 & notice of violation
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/05 2pp

--7908100385 Notice of violation from insp on 790515-17
* Region 2, Atlanta, Office of the Director 79/06/05 1p

--7908100386 IE Insp Rept 50-413/79-11 & 50-414/79-11 on 790515-17 Noncompliance noted failure to control erosion along section of intake cove opposite low pressure svc water intake structure
CUNNINGHAM, A L, HUFHAM, J W Region 2, Atlanta, Office of the Director 79/06/05 4pp

7908030121 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/13 2pp

7908230230 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers used or planned for use in safety-related sys
DAIL, L C Duke Power Co 79/07/16 1p

7908010407 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/17 2pp

7908030005 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908130101 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908060005 Responds to IE Bulletin 79-11 No Westinghouse DB-50 or DB-75 circuit breakers are used or planned for use in safety-related sys
DAIL, L C Duke Power Co 79/07/19 1p

7908070730 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/26 2pp

7908160214 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/27 2pp

7908270306 Ack receipt of IE Insp Repts 50-413/79-13 & 50-414/79-13 on 790627-29. No proprietary info.
DAIL, L. C. Duke Power Co. 79/08/01 1p.

--7908270309 Forwards IE Insp Repts 50-413/79-13 & 50-414/79-13 on 790627-29. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/20 2pp.

--7908270310 IE Insp Repts 50-413/79-13 & 50-414/79-13 on 790627-29. No noncompliance noted. Major areas inspected: safety-related piping & installation activities including welding & review of welding quality records.
VANDOORN, P. H. Region 2, Atlanta, Office of the Director. 79/07/19 5pp.

7908220625 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07 3pp.

S. Reportable occurrences, LERs & related correspondence

7908140671 Forwards significant deficiency 413-414/79-1.
DAIL, L. C. Duke Power Co. 79/07/20 1p.

--7908140679 Significant deficiency 79-1 during installation of equipment on section of main control board, deficient skip weld of wire duct detected. Investigation revealed 60 improper welds. All welds will be repaired by 790629.
* Duke Power Co. 79/06/21 2pp.

7908280621 Forwards final deficiency rept re safety-related valve/operator natural frequency analysis.
DAIL, L. C. Duke Power Co. 79/08/14 2pp.

--7908280627 Final deficiency rept IE-77/03-SPS-413/414 re potential malfunction of safety-related butterfly valve operators used in containment isolation valves. Valves have been tested & operator support brackets redesigned.
* Duke Power Co. 79/08/10 2pp.

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments. W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/07/18 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06 47pp.

7908010302 Forwards requests for addl info re proposed FSAR amend.
STOLZ, J. F. Light Water Reactors Branch 1. 79/06/19 4pp.

7908010651 Requests justification of organizational change re reporting level for QA manager.
HAASS, W. F. Quality Assurance Branch. 79/06/19 1p.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02 70pp.

7908080196 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/24 2pp.

7908140424 Lists areas of concern re safety-related structures, sys & components. May not completely satisfy NRC requirements in FSAR Amends 30 & 31. Requests meeting to clarify differences re license review cycle.
DALE, L. F. Mississippi Power & Light Co. 79/07/30 2pp.

7908080391 Ack receipt of memos documenting NRC 790613 meeting re potential delays due to TMI in issuance of CPs & OLs. Requests NRC treat plant safety review priority on basis of pre-1981 fuel load date.
DALE, L. F. Mississippi Power & Light Co. 79/07/31 2pp.

7908210334 Offers util opportunity to modify 780428 request for extension of CP completion dates. Addl info & Class I & II amend fees required.
STOLZ, J. F. Light Water Reactors Branch 1. 79/08/02 3pp.

7908240666 Notification of 790821-22 meeting w/util in Port Gibson, MS to discuss overall project status & detailed project schedule. Will observe const activities in progress to evaluate facility fuel load date. Discussion topics encl.
THOMAS, C. O. Light Water Reactors Branch 1. 79/08/06 3pp.

7908210170 Notification of 790815 meeting w/util in Bethesda, MD to discuss positions & applicant responses re in-phase & out-of-phase bubble oscillation loads & GE "Interim Containement Loads Rept." Revision 11.
THOMAS, C. O. Light Water Reactors Branch 1. 79/08/07 2pp.

7908280687 Forwards affidavit of svc re distribution of Amend 32.
DALE, L. F. Mississippi Power & Light Co. 79/08/22 2pp.

F. Security, medical, emergency & fire protection plans

7908210007 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
STAMPLEY, N. L. Mississippi Power & Light Co. 79/08/17 1p.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908160473 Forwards Amend 32 to FSAR.
STAMPLEY, N. L. Mississippi Power & Light Co. 79/08/15 1p.

--7908160486 Amend 32 to FSAR.
STAMPLEY, N. L. Mississippi Power & Light Co. 79/08/10 96pp.

P. Operating license stage documents & correspondence

7908140004 Notifies that utils will form Intermediate BWR Plant Owners Group to evaluate lessons learned from TMI. Requests meeting on 790816 to discuss proposed actions.
DALE, L. F. Mississippi Power & Light Co. 79/08/10 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908020517 Ack receipt of IE Insp Repts 50-416/79-08 & 50-417/79-08. No proprietary info.
DALE, L. F. Mississippi Power & Light Co. 79/06/18 1p.

--7908020520 Forwards IE Insp Repts 50-416/79-08 & 50-417/79-08 on 790501-04. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/22 2pp.

--7908020526 IE Insp Rpts 50-416/79-08 & 50-417/79-08 on 790501-04. No noncompliance noted. Major areas inspected: Unit 1 steel structures & supports work & Unit 2 progress on installation of safety-related major mechanical components.
VALLISH, E. , BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/22 3pp.

7908020533 Ack receipt of IE Insp Repts 50-416/79-09 & 50-417/79-09 on 790502-04. No proprietary info.
DALE, L. F. Mississippi Power & Light Co. 79/06/18 1p.

--7908020539 Forwards IE Insp Repts 50-416/79-09 & 50-417/79-09 on 790502-04. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/18 2pp.

--7908020544 IE Insp Repts 50-416/79-09 & 50-417/79-09 on 790502-04. No noncompliance noted. Major areas inspected: QA program implementation, electrical cable clamps, control of weld filler matl, weld procedure revision & insp of const.
RAUSCH, J. K. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/18 5pp.

7908030071 Responds to IE Bulletin 79-09 re failure of GE Type AK-2 circuit breakers in safety-related sys. Plant uses circuit breakers in 125-volt dc sys. Breakers do not have undervoltage tripping devices.
DALE, L. F. Mississippi Power & Light Co. 79/06/18 1p.

7908160557 Responds to IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." All pipe anchors w/base plates using expansion anchors reanalyzed to account for plate flexibility.
DALE, L. F. Mississippi Power & Light Co. 79/07/06 73pp.

7908030137 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/13 2pp.

7908010416 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/17 2pp.

7908030017 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 2pp.

7908080050 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 2pp.

7908130126 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 2pp.

7908030591 Ack receipt of 790703 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/79-10 & 50-417/79-10.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/19 1p.

--7908030596 Responds to NRC 790605 ltr re violations noted in IE Insp Repts 50-416/79-10 & 50-417/79-10. Corrective actions: eccentric tapered reducer in suction piping to west diesel fire pump will be changed to conform to NFPA 20 App.
DALE, L.F. Mississippi Power & Light Co. 79/07/03 3pp.

--7908030599 Forwards IE Insp Repts 50-416/79-10 & 50-417/79-10 on 790507-10 & notice of deviation.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/05 2pp.

--7908030603 Notice of deviation from insp on 790507-10.
* Region 2, Atlanta, Office of the Director 79/06/05 1p.

--7908030606 IE Insp Repts 50-416/79-10 & 50-417/79-10 on 790507-10. Noncompliance noted: failure to comply w/NFPA Std 30; failure to provide adequate door installation for openings in fire barriers & failure to provide adequate sys installation.
MILLER, W.H. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/05 8pp.

7908290586 Ack receipt of IE Insp Repts 50-416/79-12 & 50-417/79-12 on 790612-15. No proprietary info.
DALE, L.F. Mississippi Power & Light Co. 79/07/26 1p.

7908160244 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/27 2pp.

7908280447 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B.H. Region 2, Atlanta, Office of the Director 79/08/13 2pp.

S. Reportable occurrences, LERs & related correspondence

7908140634 Submits third interim rept for potential reportable deficiency re failures of Type 12 auxiliry switch assembly installed in 4.16 kV switchgear. Switch assembly returned to supplier for analysis.
DALE, L.F. Mississippi Power & Light Co. 79/07/20 1p.

7908290445 Interim rept of potentially Reportable Deficiency 79/11 re cracked control device assemblies on 4.16 kV switchgear, 6.9 kV switchgear & 480 volt load ctrs. Decision re reportability of deficiency will be submitted by 791103.
DALE, L.F. Mississippi Power & Light Co. 79/08/14 2pp.

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments. W/o encl.
VASSALLO, D.B. Assistant Director for Light Water Reactors
79/04/18 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP / OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D.B. Assistant Director for Light Water Reactors
79/06/06 47pp.

7908010302 Forwards requests for addl info re proposed FSAR amend.
STOLZ, J.F. Light Water Reactors Branch 1 79/06/19 4pp.

7908010651 Requests justification of organizational change re reporting level for QA manager.
HAASS, W.P. Quality Assurance Branch 79/06/19 1p.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

7908080196 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J.R. Assistant Director for Site & Safeguards 79/07/24 2pp.

7908140424 Lists areas of concern re safety-related structures, sys & components May not completely satisfy NRC requirements in FSAR Amends 30 & 31. Requests meeting to clarify differences re license review cycle.
DALE, L.F. Mississippi Power & Light Co. 79/07/30 2pp.

7908080391 Ack receipt of memos documenting NRC 790613 meeting re potential delays due to TMI in issuance of CPs & OLs. Requests NRC treat plant safety review priority on basis of pre-1981 fuel load date.
DALE, L.F. Mississippi Power & Light Co. 79/07/31 2pp.

7908210334 Offers util opportunity to modify 780428 request for extension of CP completion dates. Addl info & Class I & II amend fees required.
STOLZ, J.F. Light Water Reactors Branch 1 79/08/02 3pp.

7908240666 Notification of 790821-22 meeting w/util in Port Gibson, MS to discuss overall project status & detailed project schedule. Will observe const activities in progress to evaluate facility fuel load date. Discussion topics encl.
THOMAS, C.O. Light Water Reactors Branch 1 79/08/06 3pp.

7908210170 Notification of 790815 meeting w/util in Bethesda, MD to discuss positions & applicant responses re in-phase & out-of-phase bubble oscillation loads & GE "Interim Containement Loads Rept," Revision II.
THOMAS, C.O. Light Water Reactors Branch 1 79/08/07 2pp.

7908280687 Forwards affidavit of svc re distribution of Amend 32.
DALE, L.F. Mississippi Power & Light Co. 79/08/22 2pp.

F. Security, medical, emergency & fire protection plans

7908210007 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790).
STAMPLEY, N.L. Mississippi Power & Light Co. 79/08/17 1p.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908160473 Forwards Amend 32 to FSAR.
STAMPLEY, N.L. Mississippi Power & Light Co. 79/08/15 1p.

--7908160486 Amend 32 to FSAR.
STAMPLEY, N.L. Mississippi Power & Light Co. 79/08/10 96pp.

P. Operating license stage documents & correspondence

7908140704 Notifies that utils will form Intermediate BWR Plant Owners Group to evaluate lessons learned from TMI. Requests meeting on 790816 to discuss proposed actions.
DALE, L.F. Mississippi Power & Light Co. 79/08/10 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908020517 Ack receipt of IE Insp Repts 50-416/79-08 & 50-417/79-08. No proprietary info.
DALE, L.F. Mississippi Power & Light Co. 79/06/18 1p.

--7908020520 Forwards IE Insp Repts 50-416/79-08 & 50-417/79-08 on 790501-04. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/22 2pp.

--7908020526 IE Insp Rpts 50-416/79-08 & 50-417/79-08 on 790501-04 No noncompliance noted. Major areas inspected: Unit 1 steel structures & supports work & Unit 2 progress on installation of safety-related major mechanical components.
VALLISH, E. ; BRYANT, J. C. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 79/05/22. 3pp.

7908020533 Ack receipt of IE Insp Rpts 50-416/79-09 & 50-417/79-09 on 790502-04. No proprietary info.
DALE, L. F. Mississippi Power & Light Co. 79/06/18. 1p.

--7908020539 Forwards IE Insp Rpts 50-416/79-09 & 50-417/79-09 on 790502-04. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 79/05/18. 2pp.

--7908020544 IE Insp Rpts 50-416/79-09 & 50-417/79-09 on 790502-04. No noncompliance noted. Major areas inspected: QA program implementation, electrical cable clamps, control of weld filler matl, weld procedure revision & insp of const.
RAUSCH, J. K. Region 2, Atlanta. Office of the Director.
HERDT, A. R. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 79/05/18. 5pp.

7908030071 Responds to IE Bulletin 79-09 re failure of GE Type AK-2 circuit breakers in safety-related sys. Plant uses circuit breakers in 125-volt dc sys. Breakers do not have undervoltage tripping devices.
DALE, L. F. Mississippi Power & Light Co. 79/06/18. 1p.

7908160557 Responds to IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." All pipe anchors w/base plates using expansion anchors reanalyzed to account for plate flexibility.
DALE, L. F. Mississippi Power & Light Co. 79/07/06. 73pp.

7908030137 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta. Office of the Director.
79/07/13. 2pp.

7908010416 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta. Office of the Director.
79/07/17. 2pp.

7908030017 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta. Office of the Director.
79/07/18. 2pp.

7908080050 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta. Office of the Director.
79/07/18. 2pp.

7908130126 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta. Office of the Director.
79/07/18. 2pp.

7908030591 Ack receipt of 790703 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-416/79-10 & 50-417/79-10.
MURPHY, C. E. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 79/07/19. 1p.

--7908030596 Responds to NRC 790605 ltr re violations noted in IE Insp Rpts 50-416/79-10 & 50-417/79-10. Corrective actions: eccentric tapered reducer in suction piping to west diesel fire pump will be changed to conform to NFPA 20 App.
DALE, L. F. Mississippi Power & Light Co. 79/07/03. 3pp.

--7908030599 Forwards IE Insp Rpts 50-416/79-10 & 50-417/79-10 on 790507-10 & Notice of deviation.
MURPHY, C. E. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 79/06/05. 2pp.

--7908030603 Notice of deviation from insp on 790507-10.
* Region 2, Atlanta. Office of the Director. 79/06/05. 1p.

--7908030606 IE Insp Rpts 50-416/79-10 & 50-417/79-10 on 790507-10. Noncompliance noted: failure to comply w/NFPA Std 30, failure to provide adequate door installation for openings in fire barriers & failure to provide adequate sys installation.
MILLER, W. H. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 79/06/05. 8pp.

7908290586 Ack receipt of IE Insp Rpts 50-416/79-12 & 50-417/79-12 on 790612-15. No proprietary info.
DALE, L. F. Mississippi Power & Light Co. 79/07/26. 1p.

7908160244 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta. Office of the Director.
79/07/27. 2pp.

7908280447 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta. Office of the Director. 79/08/13. 2pp.

S. Reportable occurrences, LERs & related correspondence

7908140634 Submits third interim rept for potential reportable deficiency re failures of Type 12 auxiliry switch assembly installed in 4.16 kV switchgear. Switch assembly returned to supplier for analysis.
DALE, L. F. Mississippi Power & Light Co. 79/07/20. 1p.

7908290445 Interim rept of potentially Reportable Deficiency 79/11 re cracked control device assemblies on 4.16 kV switchgear, 6.9 kV switchgear & 480 volt load ctrs. Decision re reportability of deficiency will be submitted by 791130.
DALE, L. F. Mississippi Power & Light Co. 79/08/14. 2pp.

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

7908300435 Ack receipt of 790509 draft request to extend const completion date for CPPR-113 until Nov 1985. Requests detailed supporting info to justify extension.
PARR, O. D. Light Water Reactors Branch 3. 79/06/29. 3pp.

7908100263 Requests amend of CPPR-113 to extend completion date to Dec 1985 W/commercial operation scheduled for May 1986; extension necessary due to two deferrals of inservice date.
COUNSIL, W. G. Northeast Utilities. 79/08/03. 7pp.

G. Inspection reports, IE Bulletins & correspondence

7908020590 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 breakers will be used in safety-related sys.
COUNSIL, W. G. Northeast Utilities. 79/06/15. 1p.

7908130609 Forwards IE Insp Rept 50-423/79-04 on 790424-26. No noncompliance noted.
CARLSON, R. T. Region 1, Philadelphia. Reactor Construction & Engineering Support Branch. 79/06/21. 2pp.

--7908130621 IE Insp Rept 50-423/79-04 on 790424-26. No noncompliance noted. Major areas inspected: const work activities in progress & licensee corporate ofc insp of quality verification records.
TOTH, A. D. Region 1, Philadelphia. Office of the Director.
MCGAUGHY, R. W. Region 1, Philadelphia. Reactor Construction & Engineering Support Branch. 79/06/20. 7pp.

7908160575 Submits review results of IE Bulletin 79-02, Revision 1. Requirements to torque test all Category 1 anchor bolts, provide greater confidence that less defective anchors are installed in any one sys.
COUNSIL, W. G. Northeast Utilities. 79/07/07. 3pp.

7908200053 Advises that C-E generic rept responding to IE Bulletin 78-12, adequately represents reactor pressure vessel data for facility.
COUNSIL, W. G. Northeast Utilities. 79/07/12. 1p.

7908010504 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia. Office of the Director.
79/07/17. 1p.

7908060383 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia. Office of the Director.
79/07/18. 1p.

7908030255 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia. Office of the Director.
79/07/19. 1p.

7908100240 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/07/26 1p

7908280139 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/07 1p

7908280292 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/13 1p

7908310286 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/14 1p

7908300146 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director
79/08/15 1p

DOCKET 50-424 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908010615 Concurs w/deletion of spare multiport diffuser planned for facility Requests notification of plans for optimization of redesigned diffuser dispersion characteristics, including diffuser design & 5 F isotherm characteristics.
REGAN, W.H. Environmental Projects Branch 2 79/06/22 2pp

7908140495 Responds to 790511 ltr to R Boyd. Use of pozzolan concrete mixes for Category I structures is acceptable. Requests amend to PSAR for incorporating use of mixes.
RUBENSTEIN, L.S. Light Water Reactors Branch 4 79/07/13 2pp

7908160032 Notification of 790808 meeting w/util in Bethesda, MD to discuss removing enclosure bldg.
STAHLE, C. Light Water Reactors Branch 4 79/07/20 2pp.

7908070621 Forwards R. Choi testimony & sys expansion projections re NRC considerations on revoking CPs. Evidence indicates const will produce generating capacity greater than required through 1989.
FLACK, G. Myer, Bauman, Stroup & Flack 79/08/02 20pp

7908240442 Forwards Suppl 6 to CP & OL application.
WHITMER, C.F. Georgia Power Co. 79/08/21 2pp

--7908240446 Suppl 6 to application for CP & OL. Includes revised analysis of radiological consequence of LOCA.
WHITMER, C.F. Georgia Power Co. 79/08/21 105pp

G. Adjudicatory correspondence

7906010094 Forwards HR Denton denial of 10CFR2.206 request.
MCGURREN, H.J. Branch 1 79/04/18 1p

7908200289 Requests addl attention to request of Georgians Against Nuclear Energy re rehearing on const & licensing of proposed plant.
WOOLF, S.W. Affiliation Unknown 79/08/09 2pp

7908280536 Requests consideration of Georgians Against Nuclear Energy request for rehearing on const license for facility.
APPELSON, G. Affiliation Unknown 79/08/21 1p.

O. Inspection reports, IE Bulletins & correspondence

7908010340 Forwards IE Insp Repts 50-424/79-08 & 50-425/79-08 on 790425-27 & notice of violation.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 2pp

--7908010344 Notice of violation from insp on 790425-27.
* Region 2, Atlanta, Office of the Director 79/05/24 1p

--7908010349 IE Insp Repts 50-424/79-08 & 50-425/79-08 on 790425-27. Noncompliance noted: failure to document & perform required completion tests.
HARRIS, J.R., BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/24 4pp.

7908030031 Forwards response to NRC 790525 ltr as clarification of info provided to NRC during 790522 & 0613 meetings. Discusses IE issues re corporate QA direction, PSAR requirements & training program.
EHRENSPERGER, W. Georgia Power Co. 79/06/15 5pp.

7908020553 Discusses util 790511 ltr clarifying reasons for use of 91-day compressive strength concrete instead of 28-day compressive strength concrete. NRC has no further concerns re concrete placement.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/20 1p.

7908070142 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/06/26 2pp

7908140528 Forwards C-E 790608 confirmation that C-E generic rept re atypical weld matl in reactor vessel welds is applicable to licensee equipment & Westinghouse 790620 endorsement of rept, per IE Bulletins 78-12, 12A & 12B.
STAFFA, R.W. Georgia Power Co. 79/06/29 6pp

7908310027 Forwards response to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion anchor bolts. Only cast-in-place embed plates used for pipe supports at facility. Design methods outlined for concrete-type plates.
STAFFA, R.W. Georgia Power Co. 79/07/06 4pp.

7908030134 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/13 2pp

7908010414 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/17 2pp

7908030013 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908080046 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908130124 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 2pp.

7908070760 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/26 2pp

7908160236 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/27 2pp

7908160334 Ack receipt of IE Insp Repts 50-424/79-12 & 50-425/79-12 on 790619-22. No proprietary info.
DUTTON, D. Georgia Power Co. 79/07/30 1p.

--7908160338 Forwards IE Insp Repts 50-424/79-12 & 50-425/79-12 on 790619-20. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/12 2pp.

--7908160349 IE Insp Repts 50-424/79-12 & 50-425/79-12 on 790619-22. No noncompliance noted. Major areas inspected: nonconforming items control, drawing & spec control, concrete placements & review of noncompliance.
HUNT, M.D., BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/10 4pp.

7908290620 Responds to NRC 790522 ltr re IE Bulletin 79-11. Util is not using Westinghouse Type DB-75 or DB-50 breakers w/end caps in any safety-related sys.
DUTTON, D. Georgia Power Co. 79/07/30 1p.

7908270232 Ack receipt of 790731 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/79-11 & 50-425/79-11.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/08/03 1p.

--7908270242 Responds to NRC 790705 ltr re violations noted in IE Insp Repts 50-424/79-11 & 50-425/79-11. Corrective actions pan dry method of testing will be utilized for future tests w/addl matl taken from test hole for oven dry analysis.
DUTTON, D. Georgia Power Co. 79/07/31. 2pp.

--7908270248 Forwards IE Insp Repts 50-424/79-11 & 50-425/79-11 on 790612-14 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/05. 2pp.

--7908270253 Notice of violation from insp on 790612-14.
* Region 2, Atlanta, Office of the Director. 79/07/03. 1p.

--7908270262 IE Insp Repts 50-424/79-11 & 50-425/79-11 on 790612-14. Noncompliance noted: infraction re backfill moisture control & deficiency in backfill work stoppage.
HARRIS, J. R. Region 2, Atlanta, Office of the Director.
CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/03. 4pp.

7908220638 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

7908280462 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

5. Reportable occurrences, LERs & related correspondence

7908060376 Summary of actions taken since submittal of 790601 status rept re potential significant deficiency of embed assemblies. Embed testing scheduled to begin 790801. Addl update & date for final rept will be provided 791001.
DUTTON, D. Georgia Power Co. 79/07/31. 2pp.

7908140719 Describes testing to date of embed assemblies. Pull test procedures modified. Advises that addl update & date for final rept will be provided by 791001.
DUTTON, D. Georgia Power Co. 79/07/31. 2pp.

DOCKET 50-425 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908010615 Concurs w/deletion of spare multiport diffuser planned for facility. Requests notification of plans for optimization of redesigned diffuser dispersion characteristics, including diffuser design & 5 F isotherm characteristics.
REGAN, W. H. Environmental Projects Branch 2. 79/06/22. 2pp.

7908140495 Responds to 790511 ltr to R. Boyd. Use of pozzolan concrete mixes for Category I structures is acceptable. Requests amend to PSAR for incorporating use of mixes.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/07/13. 2pp.

7908160032 Notification of 790808 meeting w/util in Bethesda, MD to discuss removing enclosure bldg.
STAHLE, C. Light Water Reactors Branch 4. 79/07/20. 2pp.

7908070621 Forwards K. Choi testimony & sys expansion projections re NRC considerations on revoking CPs. Evidence indicates const will produce generating capacity greater than required through 1999.
FLACK, G. Myer, Bauman, Stroup & Flack. 79/08/02. 20pp.

7908240442 Forwards Suppl 6 to CP & OL application.
WHITMER, C. F. Georgia Power Co. 79/08/21. 2pp.

--7908240446 Suppl 6 to application for CP & OL. Includes revised analysis of radiological consequence of LOCA.
WHITMER, C. F. Georgia Power Co. 79/08/21. 105pp.

9. Adjudicatory correspondence

7906010094 Forwards HR Denton denial of 10CFR2.206 request.
MCGURREN, H. J. Branch 1. 79/04/18. 1p.

7908200289 Requests addl attention to request of Georgians Against Nuclear Energy re rehearing on const & licensing of proposed plant.
WOOLF, S. W. Affiliation Unknown. 79/08/09. 2pp.

7908280536 Requests consideration of Georgians Against Nuclear Energy request for rehearing on const license for facility.
APPELSON, G. Affiliation Unknown. 79/08/21. 1p.

9. Inspection reports, IE Bulletins & correspondence

7908280462 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 2, Atlanta, Office of the Director. 79/08/13. 2pp.

7908010340 Forwards IE Insp Repts 50-424/79-08 & 50-425/79-08 on 790425-27 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/24. 2pp.

--7908010344 Notice of violation from insp on 790425-27.
* Region 2, Atlanta, Office of the Director. 79/05/24. 1p.

--7908010349 IE Insp Repts 50-424/79-08 & 50-425/79-08 on 790425-27. Noncompliance noted: failure to document & perform required compaction tests.
HARRIS, J. R., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/24. 4pp.

7908030031 Forwards response to NRC 790525 ltr as clarification of info provided to NRC during 790522 & 0613 meetings. Discusses IE issues re corporate QA direction, PSAR requirements & training program.
EHRENSPERGER, W. Georgia Power Co. 79/06/15. 5pp.

7908020553 Discusses util 790511 ltr clarifying reasons for use of 91-day compressive strength concrete instead of 28-day compressive strength concrete. NRC has no further concerns re concrete placement.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/20. 1p.

7908070142 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908140528 Forwards C-E 790608 confirmation that C-E generic rept re atypical weld matl in reactor vessel welds is applicable to licensee equipment & Westinghouse 790620 endorsement of rept, per IE Bulletins 78-12, 12A & 12B.
STAFFA, R. W. Georgia Power Co. 79/06/29. 6pp.

7908310027 Forwards response to IE Bulletin 79-02 re pipe support base plate designs using concrete expansion anchor bolts. Only cast-in-place embed plates used for pipe supports at facility. Design methods outlined for concrete-type plates.
STAFFA, R. W. Georgia Power Co. 79/07/06. 4pp.

7908030134 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908010414 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030013 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080046 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130124 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908070760 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160236 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908160334 Ack receipt of IE Insp Repts 50-424/79-12 & 50-425/79-12 on 790619-22. No proprietary info.
DUTTON, D. Georgia Power Co. 79/07/30. 1p.

--7908160338 Forwards IE Insp Repts 50-424/79-12 & 50-425/79-12 on 790619-20. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/12. 2pp.

--7908160349 IE Insp Repts 50-424/79-12 & 50-425/79-12 on 790619-22. No noncompliance noted. Major areas inspected: nonconforming items control, drawing & spec control, concrete placements & review of noncompliance.
HUNT, M. D., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 4pp.

7908290620 Responds to NRC 790522 ltr re IE Bulletin 79-11. Util is not using Westinghouse Type DB-75 or DB-50 breakers w/end caps in any safety-related sys.
DUTTON, D. Georgia Power Co. 79/07/30. 1p.

7908270232 Ack receipt of 790731 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/79-11 & 50-425/79-11.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/08/03. 1p.

--7908270242 Responds to NRC 790705 ltr re violations noted in IE Insp Repts 50-424/79-11 & 50-425/79-11. Corrective actions: pan dry method of testing will be utilized for future tests w/addl matl taken from test hole for oven dry analysis.
DUTTON, D. Georgia Power Co. 79/07/31. 2pp.

--7908270248 Forwards IE Insp Repts 50-424/79-11 & 50-425/79-11 on 790612-14 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/05. 2pp.

--7908270253 Notice of violation from insp on 790612-14.
* Region 2, Atlanta, Office of the Director. 79/07/03. 1p.

--7908270262 IE Insp Repts 50-424/79-11 & 50-425/79-11 on 790612-14. Noncompliance noted: infraction re backfill moisture control & deficiency in backfill work stoppage.
HARRIS, J. R. Region 2, Atlanta, Office of the Director.
CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/03. 4pp.

7908220638 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

S Reportable occurrences, LERs & related correspondence

7908060376 Summary of actions taken since submittal of 790601 status rept re potential significant deficiency of embed assemblies. Embed testing scheduled to begin 790801. Addl update & date for final rept will be provided 791001.
DUTTON, D. Georgia Power Co. 79/07/31. 2pp.

7908140719 Describes testing to date of embed assemblies. Pull test procedures modified. Advises that addl update & date for final rept will be provided by 791001.
DUTTON, D. Georgia Power Co. 79/07/31. 2pp.

DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7908170047 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10. 1p.

7908310193 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

DOCKET 50-434 SURRY POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

7908030306 Lists corrective actions proposed by util re potential electrical problems noted in EL Jordan 790604 memo.
LAINAS, G. Plant Systems Branch. 79/06/21. 2pp.

7908080683 Responds to FOIA request for documents re North Anna nuclear power plants.
FELTON, J. M. Division of Rules and Records. 79/08/03. 2pp.

--7908080692 Responds to 770401 request for info re investigations of allegations of withholding steam generator info. Technical staff responses encl.
SHAPAR, H. K. Office of the Executive Legal Director. 77/05/05. 12pp.

DOCKET 50-435 SURRY POWER STATION, UNIT 4

A Application/construction stage documents & correspondence

7908030306 Lists corrective actions proposed by util re potential electrical problems noted in EL Jordan 790604 memo.
LAINAS, G. Plant Systems Branch. 79/06/21. 2pp.

7908080683 Responds to FOIA request for documents re North Anna nuclear power plants.
FELTON, J. M. Division of Rules and Records. 79/08/03. 2pp.

--7908080692 Responds to 770401 request for info re investigations of allegations of withholding steam generator info. Technical staff responses encl.
SHAPAR, H. K. Office of the Executive Legal Director. 77/05/05. 12pp.

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

A Application/construction stage documents & correspondence

7908090164 Advises of delay in responding to questions in 790329 ltr, due to TMI incident.
SOHINKI, S. M. Branch 3. 79/05/21. 1p.

7908030349 Summary of 790627 meeting w/ACRS Subcommittee on Floating Nuclear Plants in Washington, DC re applicant's proposed core ladle design using magnesium oxide bricks. Agenda & attendance list encl.
BIRKEL, R. A. Light Water Reactors Branch 2. 79/07/06. 7pp.

7908230685 Summary of 790608 meeting w/OPS in Bethesda, MD re core debris particle size distribution.
HAUPT, C. A. Environmental Projects Branch 1. 79/07/06. 3pp.

7908070733 Notification of 790724 meeting w/util in Bethesda, MD to discuss state-of-technology applicable to safety evaluation of floating nuclear plant core ladle design.
BIRKEL, R. A. Light Water Reactors Branch 2. 79/07/10. 4pp.

7908080247 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/19. 2pp.

7908090475 Submits comments to be transmitted to util re util 790605 summary of documents & drawings concerning matl toughness test program MTP-302, sys specs SS15A19, prequalification test program & other related matters.
CARD, J. C. Coast Guard, Transportation, Dept. of. 79/08/02. 2pp.

7908270497 Summary of 790724 meeting w/applicant re evaluation of floating nuclear power plant core ladle design. Attendance list, agenda, Sandia presentation & ladle design adequacy testing program encl.
* Light Water Reactors Branch 2. 79/08/02. 26pp.

G Adjudicatory correspondence

7908020290 Discusses SAND-77-1927, "Transport of Radionuclides in Urban Environs: Working Draft Assessment." Identifies general objectives & topics discussed. No regulatory action necessary per SECY-78-311 & SECY-78-311A.
SOHINKI, S. M. Branch 3. 79/04/25. 2pp.

--7908020302 Forwards info potentially relevant to ASLB & ASLAB in NRC proceedings re analyses of sabotage attacks on spent fuel transportation sys & description of damages caused by various types of high explosive attacks. W/o encl.
CARTER, T. F. Division of Safeguards. 79/01/22. 2pp.

7908020224 Order granting extension until 790822 to file proposed partial findings of fact in response to NRC 790613 request.
WOLFE, S. J. Atomic Safety and Licensing Board Panel. 79/06/27. 1p.

DOCKETED ITEMS

7908140048 Board notification Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1 79/06/29 1p

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division 79/03/05 1p

O Advisory Committee on Reactor Safeguards reports & correspondence

7908090641 Transcript of ACRS Subcommittee 790627 meeting in Washington, DC re floating nuclear plant. Pp 1-192. Supporting documentation encl.
SIESS, C. ; ETHERINGTON, H. ; SHEWMON, P. ACRS - Advisory Committee on Reactor Safeguards 79/06/27 250pp

Q Inspection reports, IE Bulletins & correspondence

7908070187 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/06/26 1p

7908030152 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/13 1p

7908010419 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/17 1p

7908030046 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/18 1p

7908130134 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/18 1p

7908160283 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/27 1p

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908010699 Summary of 790614 meeting w/util & US Geological Survey re opportunity for util to justify restriction of 1897 Intensity VIII Giles County earthquake to east-west zone crossing northern part of southern Appalachian sector.
MCMULLEN, R. B. Geosciences Branch 79/06/29 4pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908080183 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
PARR, O. D. Light Water Reactors Branch 3 79/07/11 2pp

7908130549 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
PARR, O. D. Light Water Reactors Branch 3 79/08/02 4pp

7908170442 Forwards "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp & "Justification of Seismic Design Criteria Used for Facilities, Phase II, Responses to NRC Questions 1 Through 6."
MILLS, L. M. Tennessee Valley Authority 79/03/09 2pp

--7908170449 "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp.
* Tennessee Valley Authority 79/02/28 114pp

--7908170454 "Justification of Seismic Design Criteria Used for Facilities, Phase II, Responses to NRC Questions 1 Through 6."
* Tennessee Valley Authority 79/06/30 100pp

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L. M. Tennessee Valley Authority 79/08/23 2pp

F Security, medical, emergency & fire protection plans

7906130208 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch 79/07/03 2pp

7908210314 Forwards security personnel training & qualification plans. Plans withheld (ref 10CFR2.790).
MILLS, L. M. Tennessee Valley Authority 79/08/17 1p

H General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Dfc of Power.
MILLS, L. M. Tennessee Valley Authority 79/08/07 2pp

Q Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority 79/05/29 3pp

7908290131 Forwards IE Insp Repts 50-438/79-13 & 50-439/79-13 on 790522-25. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/18 2pp

--7908290138 IE Insp Repts 50-438/79-13 & 50-439/79-13 on 790522-25. No noncompliance noted. Major areas inspected: const status & housekeeping, follow-up inspector items re IE bulletins & follow-up action on licensee-identified items.
WRIGHT, R. W. Region 2, Atlanta, Office of the Director
CANTRELL, F. S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/14 5pp

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09 re GE Type AK-2 circuit breakers.
GILLELAND, J. E. Tennessee Valley Authority 79/06/20 4pp

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/06/26 3pp

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L. M. Tennessee Valley Authority 79/07/0[illegible] 40pp

7908150310 Ack receipt of 790626 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-438/79-12 & 50-439/79-12.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/13 2pp

--7908150322 Responds to NRC 790531 ltr re violation noted in IE Insp Repts 50-438/79-12 & 50-439/79-12. Corrective actions: welds will be corrected by 800306.
GILLELAND, J. E. Tennessee Valley Authority 79/06/26 2pp

--7908150331 Forwards IE Insp Repts 50-438/79-1[illegible] & 50-439/79-12 on 790425-0511 & notice of violation.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/05/31 2pp

--7908150337 Notice of violation from insp on 790425-0511.
* Region 2, Atlanta, Office of the Director 79/05/31 1p

--7908150345 IE Insp Repts 50-438/79-12 & 50-439/79-12 on 790425-0511. Noncompliance noted pipe welds in waste disposal sys were welded w/o purge.
MCGUIRE, D. R.; LONG, F. J. Region 3, Chicago, Office of the Director; CROWLEY, B. R. Region 3, Chicago, Reactor Construction & ENgineering Support Branch. 79/05/31. 11pp.

7908150355 Ack receipt of 790626 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-438/79-11 & 50-439/79-11.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/13. 2pp.

--7908150372 Responds to NRC 790531 ltr re violation noted in IE Insp Repts 50-438/79-11 & 50-439/79-11. Corrective actions: personnel have been reinstructed re importance of proper filler metal control.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/26. 2pp.

--7908150378 Forwards IE Insp Repts 50-438/79-11 & 50-439/79-11 on 790515-18 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/31. 2pp.

--7908150385 Notice of violation from insp on 790515-18.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/30. 1p.

--7908150394 IE Insp Repts 50-438/79-11 & 50-439/79-11 on 790515-18. Noncompliance noted: failure to follow procedure for control of welding matls.
VALLISH, E. J.; BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/30. 4pp.

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellafonte to be submitted before 790914. Pipe stools not used.
MILLS, L. M. Tennessee Valley Authority. 79/07/13. 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L. M. Tennessee Valley Authority. 79/07/20. 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 3pp.

7908230175 Responds to IE Bulletin 79-14. Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L. M. Tennessee Valley Authority. 79/07/27. 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

7908270272 Submits updated response to IE Bulletin 79-03 requested by FS Cantrell on 790807. Investigations have revealed that no ASME SA-312 stainless steel piping mfg by Youngstown Welding & Engineering Co has been used.
MILLS, L. M. Tennessee Valley Authority. 79/08/08. 1p.

7908290502 Forwards suppl response to deficiency noted in IE Insp Repts 50-438/79-11 & 50-439/79-11 re failure to follow procedures for control of welding matl.
MILLS, L. M. Tennessee Valley Authority. 79/08/21. 3pp.

5. Reportable occurrences, LERs & related correspondence

7908030427 Forwards first interim deficiency rept re failure of Penn Ventilator Co to implement QA program. Next rept will be submitted by 790815.
MILLS, L. M. Tennessee Valley Authority. 79/07/16. 2pp.

--7908030432 Interim deficiency rept re Penn Ventilator Co failure to implement QA program. Util still investigating.
* Tennessee Valley Authority. 79/07/16. 1p.

7908010434 Forwards fifth interim deficiency rept re failure of expansion anchors to pass qualification tests.
MILLS, L. M. Tennessee Valley Authority. 79/07/20. 1p.

--7908010438 Fifth interim deficiency rept re failure of expansion anchors to pass qualification tests. Failure of initial tests due to installation of test anchors in concrete containing 9% entrained air, contrary to Tech Specs.
* Tennessee Valley Authority. 79/07/20. 1p.

7908140681 Forwards second interim deficiency rept re possibly conservative seismic response for primary branch lines.
MILLS, L. M. Tennessee Valley Authority. 79/07/26. 1p.

--7908140685 Second interim deficiency rept re possibly conservative seismic response for primary branch lines. Reanalysis of primary branch lines will be performed.
* Tennessee Valley Authority. 79/07/26. 1p.

7908060286 Forwards third interim deficiency rept re progressive cracking of heat-affected zone of welded stud anchors in flexible plate connections.
MILLS, L. M. Tennessee Valley Authority. 79/07/30. 1p.

--7908060292 Third interim deficiency rept re progressive cracking of heat-affected zone of welded stud anchors in flexible plate connections. Corrective action will be taken at completion of evaluation. Final rept due by 791219.
* Virginia Electric & Power Co. 79/07/30. 1p.

7908140838 Forwards third interim deficiency rept re tensile anchor capacities lower than design allowables.
MILLS, L. M. Tennessee Valley Authority. 79/07/30. 2pp.

--7908140843 Third interim deficiency rept. Progressive cracking of heat-affected zone of welded stud anchors in flexible plate connections occurred in general R&D program tests. Data under investigation.
* Tennessee Valley Authority. 79/07/30. 1p.

7908140563 Second interim deficiency rept re defective welding in waste disposal sys. Investigation continuing. Next rept will be submitted by 791016.
MILLS, L. M. Tennessee Valley Authority. 79/08/06. 1p.

7908140731 Responds to CE Murphy 790717 ltr re activities apparently in violation of NRC regulations. Corrective actions: insp, storage & periodic maint cards reviewed & completed by transfer of data from temporary forms.
MILLS, L. M. Tennessee Valley Authority. 79/08/08. 3pp.

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908010699 Summary of 790614 meeting w/util & US Geological Survey re opportunity for util to justify restriction of 1897 Intensity VIII Giles County earthquake to east-west zone crossing northern part of sourthern Appalachian sector.
MCMULLEN, R. B. Geosciences Branch. 79/06/29. 4pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908080183 Notifies that license amends resulting from program to upgrade bases section of GTS are exempt from fees.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 2pp.

7908130549 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
PARR, O. D. Light Water Reactors Branch 3. 79/08/02. 4pp.

7908170442 Forwards "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp & "Justification of Seismic Design Criteria Used for Facilities, Phase II, Responses to NRC Questions 1 Through 6."
MILLS, L. M. Tennessee Valley Authority. 79/08/09. 2pp.

--7908170449 "Earthquake Ground Motion Study in Vicinity of Facility" by Weston Geophysical Corp.
* Tennessee Valley Authority. 79/02/28. 114pp.

--7908170454 "Justification of Seismic Design Criteria Used for Facilities, Phase II, Responses to NRC Questions 1 Through 6."
* Tennessee Valley Authority. 79/06/30. 100pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L. M. Tennessee Valley Authority. 79/08/23. 2pp.

F. Security, medical, emergency & fire protection plans

7908130208 Notifies that review of safeguards contingency plan involves consideration of safeguards issue, requiring payment of Class III fee. Plans should be submitted by 790823.
DIGGS, R. M. License Fee Management Branch. 79/07/03. 2pp.

7908210314 Forwards security personnel training & qualification plans. Plans withheld (ref 10CFR2.790).
MILLS, L. M. Tennessee Valley Authority. 79/08/17. 1p.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L. M. Tennessee Valley Authority. 79/08/07. 2pp.

I. Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority. 79/05/29. 3pp.

7908290131 Forwards IE Insp Repts 50-438/79-13 & 50-439/79-13 on 790522-25. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/18. 2pp.

--7908290138 IE Insp Repts 50-438/79-13 & 50-439/79-13 on 790522-25. No noncompliance noted. Major areas inspected: const status & housekeeping, follow-up inspector items re IE bulletins & follow-up action on licensee-identified items.
WRIGHT, R. W. Region 2, Atlanta, Office of the Director.
CANTRELL, F. S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/14. 5pp.

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09 re GE Type AK-2 circuit breakers.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/20. 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 3pp.

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L. M. Tennessee Valley Authority. 79/07/05. 40pp.

7908150310 Ack receipt of 790626 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-438/79-12 & 50-439/79-12.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/13. 2pp.

--7908150322 Responds to NRC 790531 ltr re violation noted in IE Insp Repts 50-438/79-12 & 50-439/79-12. Corrective actions: welds will be corrected by 800306.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/26. 2pp.

--7908150331 Forwards IE Insp Repts 50-438/79-12 & 50-439/79-12 on 790425-0511 & notice of violation.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/05/31. 2pp.

--7908150337 Notice of violation from insp on 790425-0511.
* Region 2, Atlanta, Office of the Director. 79/05/31. 1p.

--7908150345 IE Insp Repts 50-438/79-12 & 50-439/79-12 on 790425-0511. Noncompliance noted: pipe welds in waste disposal sys were welded w/o purge.
MCGUIRE, D. R., LONG, F. J. Region 3, Chicago, Office of the Director. CROWLEY, B. R. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/05/31. 11pp.

7908150355 Ack receipt of 790626 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-438/79-11 & 50-439/79-11.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/13. 2pp.

--7908150372 Responds to NRC 790531 ltr re violation noted in IE Insp Repts 50-438/79-11 & 50-439/79-11. Corrective actions: personnel have been reinstructed re importance of proper filler metal control.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/26. 2pp.

--7908150378 Forwards IE Insp Repts 50-438/79-11 & 50-439/79-11 on 790515-18 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/31. 2pp.

--7908150385 Notice of violation from insp on 790515-18.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/30. 1p.

--7908150394 IE Insp Repts 50-438/79-11 & 50-439/79-11 on 790515-18. Noncompliance noted: failure to follow procedure for control of welding matls.
VALLISH, E. J., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/30. 4pp.

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellafonte to be submitted before 790914. Pipe stools not used.
MILLS, L. M. Tennessee Valley Authority. 79/07/13. 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or plannned for use.
MILLS, L. M. Tennessee Valley Authority. 79/07/20. 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete.Unable to meet response date of 790801.Will submit response before 790815.
MILLS,L.M. Tennessee Valley Authority. 79/07/27. 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

7908270272 Submits updated response to IE Bulletin 79-03 requested by FS Cantrell on 790807.Investigations have revealed that no ASME SA-312 stainless steel piping mfg by Youngstown Welding & Engineering Co has been used.
MILLS,L.M. Tennessee Valley Authority. 79/08/08. 1p.

S Reportable occurrences, LERs & related correspondence

7908030427 Forwards first interim deficiency rept re failure of Penn Ventilator Co to implement QA program. Next rept will be submitted by 790815.
MILLS,L.M. Tennessee Valley Authority. 79/07/16. 2pp.

--7908030432 Interim deficiency rept re Penn Ventilator Co failure to implement QA program.Util still investigating.
* Tennessee Valley Authority. 79/07/16. 1p.

7908010434 Forwards fifth interim deficiency rept re failure of expansion anchors to pass qualification tests.
MILLS,L.M. Tennessee Valley Authority. 79/07/20. 1p.

--7908010438 Fifth interim deficiency rept re failure of expansion anchors to pass qualification tests.Failure of initial tests due to installation of test anchors in concrete containing 9% entrained air,contrary to Tech Specs.
* Tennessee Valley Authority. 79/07/20. 1p.

7908140681 Forwards second interim deficiency rept re possibly conservative seismic response for primary branch lines.
MILLS,L.M. Tennessee Valley Authority. 79/07/26. 1p.

--7908140685 Second interim deficiency rept re possibly conservative seismic response for primary branch lines.Reanalysis of primary branch lines will be performed.
* Tennessee Valley Authority. 79/07/26. 1p.

7908060286 Forwards third interim deficiency rept re progressive cracking of heat-affected zone of welded stud anchors in flexible plate connections.
MILLS,L.M. Tennessee Valley Authority. 79/07/30. 1p.

--7908060292 Third interim deficiency rept re progressive cracking of heat-affected zone of welded stud anchors in flexible plate connections.Corrective action will be taken at completion of evaluation.Final rept due by 791219.
* Virginia Electric & Power Co. 79/07/30. 1p.

7908140838 Forwards third interim deficiency rept re tensile anchor capacities lower than design allowables.
MILLS,L.M. Tennessee Valley Authority. 79/07/30. 2pp.

--7908140843 Third interim deficiency rept.Progressive cracking of heat-affected zone of welded stud anchors in flexible plate connections occurred in general R&D program tests.Data under investigation.
* Tennessee Valley Authority. 79/07/30. 1p.

7908140563 Second interim deficiency rept re defective welding in waste disposal sys.Investigation continuing.Next rept will be submitted by 791016.
MILLS,L.M. Tennessee Valley Authority. 79/08/06. 1p.

7908140731 Responds to CE Murphy 790717 ltr re activities apparently in violation of NRC regulations.Corrective actions,insp, storage & periodic maint cards reviewed & completed by transfer of data from temporary forms.
MILLS,L.M. Tennessee Valley Authority. 79/08/08. 3pp.

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

7908070790 Requests that info submitted re facilities under const include instances of vandalism,demonstrations & threats of any kind.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/07/13. 1p.

7908080153 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER,J.R. Assistant Director for Site & Safeguards. 79/07/24. 2pp.

G Adjudicatory correspondence

7908010222 Forwards City of Painesville,OH Resolution Number 48-79, urging moratorium on const of nuclear-powered facilities.
BAIJAL,M. Painesville,OH. 79/06/05. 1p.

M Antitrust correspondence

7908160240 Discusses antitrust actions against util per City of Cleveland 780104 request re conditions which require licensees to provide wheeling in combined Central Area Power Coordination territories.Forwards order.
DENTON,H.R. Office of Nuclear Reactor Regulation. 79/06/25. 2pp.

--7908160257 Order modifying antitrust license Condition 3 re wheeling for & at request of other entities in combined Central Area Power Coordination Group territories.
DENTON,H.R. Office of Nuclear Reactor Regulation. 79/06/25. 8pp.

--7908160264 Notice of violation of antitrust license Condition 3 of Licenses NPF-3,CPPR-148 & CPPR-149 & specified const permits re wheeling for other entities in combined Central Area Power Coordination Group.
DENTON,H.R. Office of Nuclear Reactor Regulation. 79/06/25. 4pp.

--7908160272 Specifies recommended changes to svc tariff re transmission of electric power between delivery points of util transmission sys.
DENTON,H.R. Office of Nuclear Reactor Regulation. 79/06/25. 8pp.

--7908160281 Unexecuted transmission svc tariff re transmission of electrical power between delivery points of util to,from or between rural electrical cooperatives or municipalities. Agreements encl.
* Office of Nuclear Reactor Regulation. 79/06/25. 11pp.

--7908160297 Unexecuted amended transmission svc tariff re transmission of electrical power between delivery points of util & any electrical entity.Form of svc agreement & Exhibits A & B encl.
* Office of Nuclear Reactor Regulation. 79/06/25. 11pp.

7908030219 Forwards 790625 order modifying antitrust License Condition 3 of licenses issued in connection w/proceedings.
VOGLER,B.H. Anti-Trust Division. 79/06/28. 1p.

7908070008 Forwards Ofc of Nuclear Reactor Regulation 790625 order modifying Antitrust License Condition 3.W/o encl.
VOGLER,B.H. Anti-Trust Division. 79/06/28. 1p.

7908170261 Forwards 790716 order revising 790625 order re licenses & permits for facilities.
SALTZMAN,J. Antitrust & Indemnity Group. 79/07/16. 1p.

--7908170266 Revises 790625 order,extending deadline by 15 days for request re hearing & filing of transmission tariff.
DENTON,H.R. Office of Nuclear Reactor Regulation. 79/07/16. 2pp.

7908210073 Forwards FR notice to be transmitted to Ofc of FR for filing & publication.
SALTZMAN,J. Antitrust & Indemnity Group. 79/07/16. 1p.

--7908210078 Notice of issuance of order by Ofc of Nuclear Reactor Regulation granting 15-day extension for util to request hearing & file transmission tariff re 790625 order amending Antitrust License Condition 3.
SALTZMAN,J. Antitrust & Indemnity Group. 79/07/16. 1p.

7908060452 Responds to 790625 order re mod of Antitrust License Condition 3,directing amends to transmission svc tariff be filed w/Federal Energy Regulatory Commission effective immediately.Requests 25-day extension.
REYNOLDS,W.B. Shaw, Pittman, Potts, & Trowbridge. 79/08/02. 2pp.

7908070648 Requests opportunity to be heard on two issues set out in 790625 order calling for mod of Antitrust License Condition 3.Issues concern whether util has been in noncompliance since 780127,when first transmission tariff was filed.
REYNOLDS,W.B. Shaw, Pittman, Potts, & Trowbridge. 79/08/06. 2pp.

7908100195 Forwards RJ Mattson 790806 order modifying 790625 order re licenses & permits.
TOALSTON,A.L. Antitrust & Indemnity Group. 79/08/06. 1p.

--7908300206 Orders suspension of immediate effectiveness of 790[illegible]0 order requiring util to file specific transmission tariff. City of Cleveland, OH & DOJ may respond to mod of 790625 order.
MATTSON, R. J. Office of Nuclear Reactor Regulation. 79/[illegible] 3pp.

7908230309 Ack receipt of 790806 order granting City of Cleveland 30 days to respond to util request for stay of 790625 order. Opposes stay & will protest temporary stay.
GOLDBERG, R. Goldberg, Fieldman & Latham, P.C. 79/[illegible] 2pp.

G. Inspection reports, IE Bulletins & correspondence.

7908170235 Forwards IE Insp Repts 50-440/79-05 & 50-441/79-05 on 790522-24 & notice of violation.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/19. 2pp.

--7908170241 Notice of violation from insp on 790522-24.
* Region 3, Chicago, Office of the Director. 79/06/15. 1p.

--7908170246 IE Insp Repts 50-440/79-05 & 50-441/79-05 on 790522-24. Noncompliance noted: failure to perform adequate insp of concrete work activities.
KONKLIN, J. E., MASHELL, G. F., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 79/06/15. 15pp.

7908100170 Responds to IE Bulletin 79-09. No GE Type AK-2 breakers are planned for use in safety-related sys.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/03. 1p.

7908080260 Responds to IE Bulletins 79-02 & 02, Revision 1. Most plates determined to be flexible as defined by NRC 2:1 ratio criteria & were reanalyzed using method where plate flexibility, anchor preload & shear-tension considered.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/06. 17pp.

7908090591 Responds to IE Bulletin 79-11. Westinghouse Type DB breakers are not planned for use at facility.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/11. 1p.

7908300396 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908230108 Ack receipt of 790720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/79-05 & 50-441/79-05.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/08/03. 1p.

--7908230113 Responds to NRC 790619 ltr re violations noted in IE Insp Repts 50-440/79-05 & 50-441/79-05. Corrective actions: insp of concrete preplacement activities & concrete curing has been strengthened. Inadequate conditions corrected.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/20. 3pp.

7908150340 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300270 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence.

7908060320 Submits interim deficiency rept re Rockbestos Co cable not meeting specs re cable hypalon jacket tolerance. Rockbestos to conduct worst case pull test during week of 790813. Final rept will analyze results.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/18. 2pp.

7908010348 Submits final deficiency rept re weld quality of zero degree pipe whip restraint structure, as discussed w/NRC in 790627 telcon. Retesting & repair completed & final insp conducted on 790717. All welds on restraint acceptable.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/23. 4pp.

7908010510 Submits interim deficiency rept re inadequate compaction of Class A backfill & settling of individual pipes of P45 sys. Replacement of backfill has corrected nonconforming, in-place condition.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/25. 3pp.

7908090628 Ack receipt of 790725 interim deficiency rept re inadequate compaction of Class A backfill & settling of individual pipes of P45 sys.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/08/03. 1p.

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence.

7908070790 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/13. 1p.

7908080153 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/24. 2pp.

G. Adjudicatory correspondence.

7908010222 Forwards City of Painesville, OH Resolution Number 48-79, urging moratorium on const of nuclear-powered facilities.
BAIJAL, M. Painesville, OH. 79/06/05. 1p.

M. Antitrust correspondence.

7908[illegible]0240 Discusses antitrust actions against util per City of Cleveland 780104 request re conditions which require licensees to provide wheeling in combined Central Area Power Coordination territories. Forwards order.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 2pp.

--7908160257 Order modifying antitrust license Condition 3 re wheeling for & at request of other entities in combined Central Area Power Coordination Group territories.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 8pp.

--7908160264 Notice of violation of antitrust license Condition 3 of Licenses NPF-3, CPPR-148 & CPPR-149 & specified const permits re wheeling for other entities in combined Central Area Power Coordination Group.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 4pp.

--7908160272 Specifies recommended changes to svc tariff re transmission of electric power between delivery points of util transmission sys.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 8pp.

--7908160281 Unexecuted transmission svc tariff re transmission of electrical power between delivery points of util to/from or between rural electrical cooperatives or municipalities. Agreements encl.
* Office of Nuclear Reactor Regulation. 79/06/25. 11pp.

--7908160297 Unexecuted amended transmission svc tariff re transmission of electrical power between delivery points of util & any electrical entity. Form of svc agreement & Exhibits A & B encl.
* Office of Nuclear Reactor Regulation. 79/06/25. 11pp.

7908030219 Forwards 790625 order modifying antitrust License Condition 3 of licenses issued in connection w/proceedings.
VOGLER, B. H. Anti-Trust Division. 79/06/28. 1p.

7908[illegible]3008 Forwards Ofc of Nuclear Reactor Regulation 790625 order modifying Antitrust License Condition 3 w/o encl.
VOGLER, B. H. Anti-Trust Division. 79/06/28. 1p.

7908170261 Forwards 790716 order revising 790625 order re licenses & permits for facilities.
SALTZMAN, J. Antitrust & Indemnity Group. 79/07/16. 1p.

--7908170266 Revises 790625 order, extending deadline by 15 days for requests re hearing & filing of transmission tariff.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/16. 2pp.

7908[illegible]10073 Forwards FR notice to be transmitted to Ofc of FR for filing & publication.
SALTZMAN, J. Antitrust & Indemnity Group. 79/07/16. 1p.

--7908210078 Notice of issuance of order by Ofc of Nuclear Reactor Regulation granting 15-day extension for util to request hearing & file transmission tariff re 790625 order amending Antitrust License Condition 3.
SALTZMAN, J. Antitrust & Indemnity Group. 79/07/16. 1p.

7908060452 Responds to 790625 order re mod of Antitrust License Condition 3, directing amends to transmission svc tariff be filed w/Federal Energy Regulatory Commission effective immediately Requests 25-day extension.
REYNOLDS, W. B. Shaw, Pittman, Potts, & Trowbridge 79/08/02 2pp.

7908070648 Requests opportunity to be heard on two issues set out in 790625 order calling for mod of Antitrust License Condition 3. Issues concern whether util has been in noncompliance since 780127, when first transmission tariff was filed.
REYNOLDS, W. B. Shaw, Pittman, Potts, & Trowbridge 79/08/06 2pp.

7908300195 Forwards RJ Mattson 790806 order modifying 790625 order re licenses & permits.
TOALSTON, A. L. Antitrust & Indemnity Group 79/08/06 1p.

--7908300206 Orders suspension of immediate effectiveness of 790625 order requiring util to file specific transmission tariff. City of Cleveland, OH & DOJ may respond to mod of 790625 order.
MATTSON, R. J. Office of Nuclear Reactor Regulation 79/08/06 3pp.

7908230308 Ack receipt of 790806 order granting City of Cleveland 30 days to respond to util request for stay of 790625 order. Opposes stay & will protest temporary stay.
GOLDBERG, R. Goldberg, Fieldman & Letham, P. C. 79/08/20 2pp.

9. Inspection reports, IE Bulletins & correspondence

7908170235 Forwards IE Insp Repts 50-440/79-05 & 50-441/79-05 on 790522-24 & notice of violation.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/19 2pp.

--7908170241 Notice of violation from insp on 790522-24.
* Region 3, Chicago, Office of the Director 79/06/15 1p.

--7908170246 IE Insp Repts 50-440/79-05 & 50-441/79-05 on 790522-24. Noncompliance noted: failure to perform adequate insp of concrete work activities.
KONKLIN, J. E., MAXWELL, G. F., WILLIAMS, C. C. Region 3, Chicago, Office of the Director 79/06/15 15pp.

7908100170 Responds to IE Bulletin 79-09. No GE Type AK-2 breakers are planned for use in safety-related sys.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/03 1p.

7908080260 Responds to IE Bulletins 79-02 & 02-Revision 1. Most plates determined to be flexible as defined by NRC 2:1 ratio criteria & were reanalyzed using method where plate flexibility, anchor preload & shear-tension considered.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/06 17pp.

7908090591 Responds to IE Bulletin 79-11. Westinghouse Type DB breakers are not planned for use at facility.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/11 1p.

7908300398 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/26 1p.

7908230108 Ack receipt of 790720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/79-05 & 50-441/79-05.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/08/03 1p.

--7908230113 Responds to NRC 790619 ltr re violations noted in IE Insp Repts 50-440/79-05 & 50-441/79-05. Corrective actions: insp of concrete preplacement activities & concrete curing has been strengthened. Inadequate conditions corrected.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/20 3pp.

7908150340 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/07 1p.

7908300270 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/15 1p.

10. Reportable occurrences, LERs & related correspondence

7908060329 Submits interim deficiency rept re Rockbestos Co cable not meeting specs re cable hypalon jacket tolerance. Rockbestos to conduct worst case pull test during week of 790813. Final rept will analyze results.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/18 2pp.

7908010510 Submits interim deficiency rept re inadequate compaction of Class A backfill & settling of individual pipes of P45 sys. Replacement of backfill has corrected nonconforming, in-place condition.
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/07/25 3pp.

7908090628 Ack receipt of 790725 interim deficiency rept re inadequate compaction of Class A backfill & settling of individual pipes of P45 sys.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/08/02 1p.

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp.

7908080216 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/24 2pp.

7908090368 Forwards memo submitted to NH Public Utils Commission: DN Merril & RJ Harrison testimonies before Commonwealth of MA Dept of Public Utils & RJ Harrison statement before House Commerce & Consumer Affairs Committee, as requested.
BECKLEY, B. B. Public Service Co. of New Hampshire 79/08/06 57pp.

7908140530 Forwards Suppl 2 to Amend 40 to license application & request for partial transfer of CPPR-135 & CPPR-136.
RITSHER, J. A. Ropes & Gray 79/08/10 1p.

--7908140535 Suppl 2 to Amend 40 to application for CP & request for partial transfer of CPPR-135 & CPPR-136. Certificate of Svc & supporting documentation encl.
MERRILL, D. N. Public Service Co. of New Hampshire 79/08/08 8pp.

9. Adjudicatory correspondence

7905150042 Forwards unclassified transmittal memo re info potentially relevant to issue of sabotage of spent nuclear fuel. Also discusses rept SAND77-1927, "Transport of Radionuclides in Urban Environ: Working Draft Assessment."
BRENNER, L. Branch 3 79/04/25 2pp.

7908080589 Transcript of Affirmation Session 79-18 on 790621 in Washington, DC. Pp 1-8.
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/06/21 9pp.

--7908080638 Forwards intervenor E Weinhold 790401 request seeking halt to const of facility until cooling sys redesigned. Requests NRC approval for order denying relief.
FITZGERALD, J. A. Office of the General Counsel SECY-A-79-041 79/04/30 4pp.

7908090450 Discusses NRC 790209 proposed decision. At current stage of proceedings, findings do not have to be on basis of summary disposition. ASLAB can make findings on basis of preponderance of evidence.
BRENNER, L. Branch 3 79/07/02 2pp.

7908020019 Responds to 790701 ltr to HR Denton re concerns over evacuation plans. Reasonable & necessary steps have been taken & will be taken to assure adequate emergency plans before issuance of OL.
KREGER, W. E. Assistant Director for Site Analysis 79/07/20 2pp.

7908170029 Responds to 790701 ltr re evacuation plans. Applicant must submit at OL review stage in June 1980 final plans for coping w/emergencies.
BROWN, N. G. Affiliation Unknown 79/07/20 2pp.

7908210072 Responds to 790702 ltr re evacuation plans. Applicant must submit final plans for coping w/emergencies at OL review stage in June 1980.
KREGER, W. E. Assistant Director for Site Analysis 79/07/20 2pp.

--7908210077 Notifies of concern re evacuation plans. Const should be suspended pending drawing up of evacuation plan.
SANTASUCCI, A. Affiliation Unknown 79/07/02 1p.

7908010538 Forwards intervenor New England Coalition on Nuclear Pollution 790730 memo in support of Seacoast Anti-Pollution League request for show cause order re CP suspension. Notice of appearance encl.
JORDAN, W. S. Sheldon, Harmon, Roisman & Weiss 79/07/30 2pp.

--7908010544 New England Coalition on Nuclear Pollution memo in support of intervenor Seabrook Anti-Pollution League request for show cause order re CP suspension or revocation.
JORDAN, W.S.; SHELDON, K.P. Sheldon, Harmon, Roisman & Weiss. 79/07/30. 31pp.

7908220409 Memo submitting opinion of MC Farrar re dissenting vote concerning portions of ALAB-422 & ALAB-436. Majority will respond after review.
BISHOP, C.J. Atomic Safety and Licensing Appeal Panel. 79/08/03. 58pp.

H. General correspondency

7908070384 Responds to 790522 & 0606 ltrs re evaluation plans & request for plant shutdown. Util must submit final emergency plans by 800630. Intervenor Seacoast Antipollution League 790502 show cause order is under review.
GROSSICK, L.V. Office of the Executive Director for Operations. 79/06/26. 2pp.

--7908090398 Forwards 790401 ltr & copies of two public statements. Demands suspension of const of nuclear power plants. Util has no evacuation plan or means of disposing of radwaste. W/o encl.
PEVEAR, R.C. New Hampshire, State of. 79/05/22. 8pp.

--7908090422 Forwards 790401 ltr & copies of two public statements. Demands suspension of const of nuclear power plants. Util has no evacuation plan or means of disposing of radwaste.
PEVEAR, R.C. New Hampshire, State of. 79/06/06. 10pp.

7908150149 Responds to 790702 ltr addressed to HR Denton. Will take necessary steps to assure adequate emergency plans prior to issuance of OL.
KREGER, W.E. Assistant Director for Site Analysis. 79/07/20. 2pp.

--7908150157 Expresses concerns over util preparedness to deal w/accidents.
SANTASUCCI, A. Affiliation Unknown. 79/07/02. 1p.

7908150207 Ack receipt of 790522 ltr expressing concern re evacuation plans for vicinities surrounding proposed facility. No addl info is available to LV Grossick 790626 reply.
BALLARD, R.L. Environmental Projects Branch 1. 79/07/20. 1p.

I. Financial information

7908170612 Forwards request for addl financial info to suppl info provided in 790423 & 0622 ltrs.
RUBENSTEIN, L.S. Light Water Reactors Branch 4. 79/07/17. 20pp.

7908100441 Responds to 790717 request & forwards addl financial info. Some quarterly repts & Green Mountain Power Co source-of-funds statement will be sent at later date.
RITSHER, J.A. Ropes & Gray. 79/08/09. 900pp.

7908270471 Submits table showing estimated value of bonds issuable by util based upon continuation of present CWIP-based revenue in one case & CWIP-based revenue removed as of 790501 in other case. W/Certificate of Svc.
BECKLEY, B.B. Public Service Co. of New Hampshire. 79/08/13. 3pp.

7908210510 Submits responses by New Bedford Gas & Edison Light Co, New England Power Co & Montaup Electric Co to NRC 790717 request for addl financial info. Affidavits, SEC Form 10-Q for 1978-79 & testimony of E Cheney & R Wright encl.
RITSHER, J.A. Ropes & Gray. 79/08/15. 226pp.

7908210272 Responds to 790717 request on behalf of util. Submits balance sheet & accounting of operating expenses & revenues for 790610-30. Verification of H Huehmer encl.
RITSHER, J.A. Ropes & Gray. 79/08/16. 10pp.

7908280615 Forwards financial data for PSC of NH for second quarter of 1979 in response to NRC 790717 request for addl financial info.
RITSHER, J.A. Ropes & Gray. 79/08/20. 25pp.

O. Inspection reports, IE Bulletins & correspondence

7908080516 Responds to IE Bulletin 79-04 & 790330 ltr. Will use 3-inch valves in primary component cooling sys & 6-inch valves in thermal regenerating sys B. No corrective actions necessary on Velan swing check valves.
SHEPARD, A.M. Public Service Co. of New Hampshire. 79/05/25. 2pp.

7908070344 Responds to IE Bulletins 78-12, 12A & 12B. Requested info was sent to NRC on 790608 in C-E rept "Atypical Weld Matl in Reactor Pressure Vessel Welds." C-E certification encl.
SHEPARD, A.M. Public Service Co. of New Hampshire. 79/06/28. 3pp.

7908080353 Responds to IE Bulletin 79-12, Revision 1, re pipe support base plate designs using concrete expansion anchor bolts. Submits procedure for reviewing calculations to validate effects of plate flexibility.
SHEPARD, A.M. Public Service Co. of New Hampshire. 79/07/06. 3pp.

7908070705 Responds to IE Bulletin 79-11. Westinghouse circuit breakers DB-50 or DB-75 are not used in any safety-related sys at facility.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 79/07/12. 1p.

7908010526 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060497 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030280 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908100276 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908240589 Responds to IE Bulletin 79-03. Submits rept on longitudinal weld defects in ASME SA-312 Type 304 stainless steel pipe spools mfg by Youngstown Welding & Engineering Co. Welds are acceptable.
SHEPARD, A.M. Public Service Co. of New Hampshire. 79/07/27. 12pp.

7908280186 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908280339 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310312 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300193 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments. W/o encl.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908080216 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J.R. Assistant Director for Site & Safeguards. 79/07/24. 2pp.

7908090368 Forwards memo submitted to NH Public Utils Commission. DN Merril & RJ Harrison testimonies before Commonwealth of MA Dept of Public Utils & RJ Harrison statement before House Commerce & Consumer Affairs Committee, as requested.
BECKLEY, B.B. Public Service Co. of New Hampshire. 79/08/06. 57pp.

7908140530 Forwards Suppl 2 to Amend 40 to license application & request for partial transfer of CPPR-135 & CPPR-136.
RITSHER, J.A. Ropes & Gray. 79/08/10. 1p.

--7908140535 Suppl 2 to Amend 40 to application for CP & request for partial transfer of CPPR-135 & CPPR-136 Certificate of Svc & supporting documentation encl.
MERRILL, D. N. Public Service Co. of New Hampshire. 79/08/08. 8pp.

G. Adjudicatory correspondence

7905150042 Forwards unclassified transmittal memo re info potentially relevant to issue of sabotage of spent nuclear fuel. Also discusses rept SAND77-1927, "Transport of Radionuclides in Urban Environ: Working Draft Assessment."
BRENNER, L. Branch 3. 79/04/25. 2pp.

7908080589 Transcript of Affirmation Session 79-18 on 790621 in Washington, DC. Pp 1-8.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commission. 79/06/21. 9pp.

--7908080638 Forwards intervenor E Weinhold 790401 request seeking halt to const of facility until cooling sys redesigned. Requests Commission approval for order denying relief but directing review to be expedited.
FITZGERALD, J. A. Office of the General Counsel. SECY-A-79-041. 79/04/30. 4pp.

7908090450 Discusses NRC 790209 proposed decision. At current stage of proceedings, findings do not have to be on basis of summary disposition. ASLAB can make findings on basis of preponderance of evidence.
BRENNER, L. Branch 3. 79/07/02. 2pp.

7908020019 Responds to 790701 ltr to HR Denton re concerns over evacuation plans. Reasonable & necessary steps have been taken & will be taken to assure adequate emergency plans before issuance of OL.
KREGER, W. E. Assistant Director for Site Analysis. 79/07/20. 2pp.

7908170029 Responds to 790701 ltr re evacuation plans. Applicant must submit at OL review stage in June 1980 final plans for coping w/emergencies.
BROWN, N. Q. Affiliation Unknown. 79/07/20. 2pp.

7908210072 Responds to 790702 ltr re evacuation plans. Applicant must submit final plans for coping w/emergencies at OL review stage in June 1980.
KREGER, W. E. Assistant Director for Site Analysis. 79/07/20. 2pp.

--7908210077 Notifies of concern re evacuation plans. Const should be suspended pending drawing up of evacuation plan.
SANTASUCCI, A. Affiliation Unknown. 79/07/02. 1p.

7908010538 Forwards intervenor New England Coalition on Nuclear Pollution 790730 memo in support of Seacoast Anti-Pollution League request for show cause order re CP suspension. Notice of appearance encl.
JORDAN, W. S. Sheldon, Harmon, Roisman & Weiss. 79/07/30. 2pp.

--7908010544 New England Coalition on Nuclear Pollution memo in support of intervenor Seabrook Anti-Pollution League request for show cause order re CP suspension or revocation.
JORDAN, W. S.; SHELDON, K. P. Sheldon, Harmon, Roisman & Weiss. 79/07/30. 31pp.

H. General correspondence

7908090384 Responds to 790522 & 0606 ltrs re evaluation plans & request for plant shutdown. Util must submit final emergency plans by 800630. Intervenor Seacoast Antipollution League 790502 show cause order is under review.
GROSSICK, L. V. Office of the Executive Director for Operations. 79/06/26. 2pp.

--7908090398 Forwards 790401 ltr & copies of two public statements. Demands suspension of const of nuclear power plants. Util has no evacuation plan or means of disposing of radwaste. W/o encl.
PEVEAR, R. C. New Hampshire, State of. 79/05/22. 8pp.

--7908090422 Forwards 790401 ltr & copies of two public statements. Demands suspension of const of nuclear power plants. Util has no evacuation plan or means of disposing of radwaste.
PEVEAR, R. C. New Hampshire, State of. 79/06/06. 10pp.

7908150149 Responds to 790702 ltr addressed to HR Denton. Will take necessary steps to assure adequate emergency plans prior to issuance of OL.
KREGER, W. E. Assistant Director for Site Analysis. 79/07/20. 2pp.

--7908150157 Expresses concerns over util preparedness to deal w/accidents.
SANTASUCCI, A. Affiliation Unknown. 79/07/02. 1p.

7908150207 Ack receipt of 790522 ltr expressing concern re evacuation plans for vicinities surrounding proposed facility. No addl info is available to LV Gossick 790626 reply.
BALLARD, R. L. Environmental Projects Branch 1. 79/07/20. 1p.

I. Financial information

7908170612 Forwards request for addl financial info to suppl info provided in 790423 & 0622 ltrs.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/07/17. 20pp.

7908100441 Responds to 790717 request & forwards addl financial info. Some quarterly repts & Green Mountain Power Co source-of-funds statement will be sent at later date.
RITSHER, J. A. Ropes & Gray. 79/08/09. 900pp.

7908270471 Submits table showing estimated value of bonds issuable by util based upon continuation of present CWIP-based revenue in one case & CWIP-based revenue removed as of 790501 in other case W/Certificate of Svc.
BECKLEY, B. B. Public Service Co. of New Hampshire. 79/08/13. 3pp.

7908210510 Submits responses by New Bedford Gas & Edison Light Co, New England Power Co & Montaup Electric Co to NRC 790717 request for addl financial info. Affidavits, SEC Form 10-Q for 1978-79 & testimony of E Cheney & R Wright encl.
RITSHER, J. A. Ropes & Gray. 79/08/15. 226pp.

7908210272 Responds to 790717 request on behalf of util. Submits balance sheet & accounting of operating expenses & revenues for 790610-30. Verification of H Huehmer encl.
RITSHER, J. A. Ropes & Gray. 79/08/16. 10pp.

7908280615 Forwards financial data for PSC of NH for second quarter of 1979 in response to NRC 790717 request for addl financial info.
RITSHER, J. A. Ropes & Gray. 79/08/20. 25pp.

G. Inspection reports, IE Bulletins & correspondence

7908080516 Responds to IE Bulletin 79-04 & 790330 ltr. Will use 3-inch valves in primary component cooling sys & 6-inch valves in thermal regenerating sys B. No corrective actions necessary on Velan swing check valves.
SHEPARD, A. M. Public Service Co. of New Hampshire. 79/05/25. 2pp.

7908070344 Responds to IE Bulletins 78-12, 12A & 12B. Requested info was sent to NRC on 790608 in C-E rept "Atypical Weld Matl in Reactor Pressure Vessel Welds." C-E certification encl.
SHEPARD, A. M. Public Service Co. of New Hampshire. 79/06/28. 3pp.

7908080353 Responds to IE Bulletin 79-12, Revision 1, re pipe support base plate designs using concrete expansion anchor bolts. Submits procedure for reviewing calculations to validate effects of plate flexibility.
SHEPARD, A. M. Public Service Co. of New Hampshire. 79/07/06. 3pp.

7908070705 Responds to IE Bulletin 79-11. Westinghouse circuit breakers DB-50 or DB-75 are not used in any safety-related sys at facility.
DEVINCENTIS, J. Public Service Co. of New Hampshire. 79/07/12. 1p.

7908010526 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060497 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030280 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908100276 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908240589 Responds to IE Bulletin 79-03. Submits rept on longitudinal weld defects in ASME SA-312 Type 304 stainless steel pipe spools mfg by Youngstown Welding & Engineering Co. Welds are acceptable.
SHEPARD, A. M. Public Service Co. of New Hampshire. 79/07/27. 12pp.

7908280186 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/07 1p

7908280339 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/13 1p

7908310312 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/14 1p

7908300193 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 79/08/15 1p

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA, UNIT 1

A. Application/construction stage documents & correspondence

7908090467 Forwards matl requested per Question 372.20, re onsite meteorological data used in FSAR, Dames & Moore format info, & sector analysis of exclusion area. W/o encl.
FEIST, C.K. Texas Utilities Services, Inc. 78/07/21 1p

7908090515 Forwards map showing current status of mineral rights ownership in exclusion area, in response to Question 312.2. W/o encl.
FEIST, C.K. Texas Utilities Services, Inc. 78/07/24 1p

7908020549 Forwards request for detailed design drawings for structures & components of primary coolant sys in order to perform desired independent analyses of dynamic asymmetric loads.
BAER, R.L. Light Water Reactors Branch 2 79/05/31 7pp

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D.B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908300465 Forwards request for addl info based on review of FSAR.
BAER, R.L. Light Water Reactors Branch 2 79/07/02 5pp

7908090514 Responds to Question 361.10. Forwards 771221 rept & 780628 update by HJ Gruy & Associates, Inc. Determines max potential of blowout condition, petrophysical properties of subsurface formations & other info re plant site.
WERNER, R. Texas Utilities Services, Inc. 79/07/10 17pp

7908080230 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J.R. Assistant Director for Site & Safeguards 79/07/19 2pp

7908170370 Confirms schedule for second corporate mgt meeting scheduled for 790828. Subjs which NRC is requested to address are listed in encl agenda.
MADSEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/20 3pp

7908010490 Forwards Dames & Moore 790423 ltr documenting telcons w/USGS re non-subsidence potential of cretaceous sandstone.
FEIST, C.K. Texas Utilities Services, Inc. 79/07/27 5pp

7908300428 Notification of 790816 meeting w/licensee in Bethesda, MD to discuss implementing methods for responses to second round questions & NRC positions for maintaining safety review efforts.
BURWELL, B.B. Light Water Reactors Branch 2 79/08/06 3pp

F. Security, medical, emergency & fire protection plans

7908200324 Forwards security training & qualification plan. Plan withheld (ref 10CFR2.790). Affidavit encl.
CLEMENTS, B.R. Texas Utilities Generating Co. 79/08/15 5pp

G. Adjudicatory correspondence

7908130006 Confirms 790717 meeting in Arlington, TX to discuss contentions of Citizens for Fair Util Regulations.
ULMAN, M.B. Operations & Administrative Division 79/07/05 1p

7908150007 Confirms 790718 meeting in Houston, TX to discuss contentions of Citizens Association for Sound Energy.
ULMAN, M.B. Operations & Administrative Division 79/07/05 1p

7908150008 Confirms 790719 meeting in Fort Worth, TX to discuss contentions of intervenor Association of Community Organizations for Reform Now.
ULMAN, M.B. Operations & Administrative Division 79/07/05 1p

7908300027 Notice of appearance of LJ Chandler & MB Ulman on behalf of NRC. Certificate of Svc encl.
CHANDLER, L.J. Branch 1 79/07/06 3pp

7908130168 TX Utils Generating Co opposition to TX LA Electric Cooperative 790702 motion for extension until 790806 re response to TX Utils first set of interrogartories. No objection made to 790724 reply date.
KNOTTS, J.B. Debevoise & Lieberman 79/07/09 2pp

H. General correspondence

7908090594 Notifies of rescheduling of meeting to 790829.
MADSEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/30 1p

7908170351 Ack receipt of ltr commenting on 790613 meeting re industry efforts related to TMI accident.
DENTON, H.R. Office of Nuclear Reactor Regulation 79/08/01 2pp

K. Utility Final Safety Analysis Report (FSAR) & amends

7908140427 Forwards Amend 7 to FSAR.
GARY, R.J. Texas Utilities Generating Co. 79/07/31 2pp

--7908140432 Amend 7 to FSAR. Oversized drawings available in Central Files.
* Texas Utilities Generating Co. 79/07/31 239pp

7908220337 Forwards affidavit of svc for Amend 7 to FSAR.
SCHMIDT, H.C. Texas Utilities Generating Co. 79/08/13 3pp.

M. Antitrust correspondence

7908080525 Submits Apr 1979 discovery rept of Public Utils Board of Brownsville, TX. Responded to two sets of interrogatories & document requests. Certificate of Svc encl.
POIRIER, M.R. Spiegel & McDiarmid 79/05/14 6pp

7908080535 Submits May 1979 discovery rept of Public Utils Board of Brownsville, TX. Worked w/Houston Lighting & Power to provide addl info responsive to util interrogatories & document requests. Certificate of Svc encl.
POIRIER, M.R. Spiegel & McDiarmid 79/06/09 6pp.

7908030230 Forwards copies of NRC response to first set of interrogatories & requests for production of documents. Also forwards util supplemental response to NRC first set of interrogatories & requests for production of documents.
BLUME, M.B. Anti-Trust Division 79/06/29 1p

7908130130 TX-LA Cooperative motion for extension until 790806 to respond to TX Utils Generating Co 790618 first set of interrogatories & request for documents. Nature & extent of info requires addl time. Certificate of Svc encl.
RITTS, F.H. Northcutt Ely 79/07/02 5pp

7908200068 Notifies that City of Austin, TX has not initiated nor received any discovery requests during June 1979. Certificate of Svc encl.
BALOUGH, R.C. Austin, TX 79/07/02 4pp

7908220094 Submits rept of discovery activities by South TX Electric Cooperative, Inc & Medina Electric Cooperative for June 1979. Certificate of Svc encl.
JOHN, D.F. Akin, Gump, Hauer & Feld 79/07/02 5pp

7908130176 Progress rept per ASLB 780621 order re June 79 discovery. Major attention was given to implementation of ASLB 790601 order directing Gulf States Utils to comply w/ASLB 790226 subpoenaduces tecum. Certificate of Svc encl.
HARRIS, J.L., CYPHERT, S.B., CLARK, R.H. Justice, Dept of 79/07/03 9pp

7908200097 Rept of discovery activities of Public Utils Board of Brownsville,TX for June 1979 Inspected documents at ofc of Central & South West Corp & received subpoena for production of documents to El Paso Electric Co Certificate of Svc encl
POIRIER,M R Spiegel & McDiarmid 79/07/05 6pp

7908170115 Third supplemental answer to DOJ first set of interrogatories & request for production of documents. Affidavit,Certificate of Svc & supporting documentation encl.
SERATH,E D Texas Utilities Co 79/07/06 9pp

7908130188 TX Utils Generating Co opposition to TX LA Electric Cooperative 790702 motion for extension until 790806 re response to TX Utils first set of interrogatories.No objection made to 790724 reply date.
KNOTTS,J B Debevoise & Lieberman WORSHAM,J I Worsham, Forsythe & Sampels 79/07/09 2pp

--7908130201 TX Utils Generating Co reply to DOJ & NRC joint motion for partial reconsideration of ASLB 790625 order re discovery & prehearing schedule.Opposes proposed schedule but does not object to dates set forth in order.Certificate of Svc encl
KNOTTS,J B Debevoise & Lieberman WORSHAM,J I Worsham, Forsythe & Sampels 79/07/09 5pp

7908090581 Forwards Lerner testimony.NRC may oppose second deposition, since analysis is only investigative [analytical,not conclusive.W/o encl.
LESSY,R P Anti-Trust Division 79/07/11 2pp

7908130215 Motion to compel Houston Lighting & Power to produce certain documents alleged to be priviledged.Certificate of Svc & supporting documentation encl.
HARRIS,J L ; CYPHERT,S B Justice,Dept of CLARK,R H Interior,Dept of 79/07/11 36pp

7908210612 Forwards Lerner testimony in prior proceedings & list of publications.NRC may oppose second deposition of Lerner if decision to proceed early with 790719 deposition is maintained.W/o encl.
LESSY,R P Anti-Trust Division 79/07/11 1p

7908130223 Supplemental request for production of documents by Houston Lighting & Power & TX Utils Generating Co,per ASLB 790625 order.Certificate of Svc encl.
LESSY,R P Anti-Trust Division 79/07/13 6pp

7908130240 First supplemental response to TX Utils Generating Co 790209 first set of interrogatories & request for production of documents.Certificate of Svc encl.
CYPHERT,S B ; CLARK,R H Justice,Dept of 79/07/13 13pp

7908130246 First supplemental response to Houston Lighting & Power 790209 second set of interrogatories & requests for production of documents.Certificate of Svc encl.
CYPHERT,S B ; CLARK,R H Justice,Dept of 79/07/13 9pp

7908220392 Forwards return on svc of subpoena issued by ASLB to El Paso Electric Co.
POIRER,M R Spiegel & McDiarmid 79/07/16 2pp

7908130261 Motion to quash or modify 790707 subpoena directed to T Sweatman & 790709 subpoena directed to keeper of records of TX Public Util Commission.Certificate of Svc & exhibits encl.
HUGHES,D ; FAINTER,J W Texas, State of 79/07/19 22pp

7908200269 Stipulation among parties for protective order on behalf of Gulf States Utils re ASLB 790226 subpoena issued at request of Public Utils Board of City of Brownsville,TX for production of documents.Order granted by ASLB on 790723.
PADER,R M Gulf States Utilities Co BLUME,M B Anti-Trust Division HARRIS,J L Justice,Dept of 79/07/23 11pp

7908200395 TX-LA Electric Cooperative response to TX Utils Generating Co first set of interrogatories & requests for production of documents.Supporting documentation & Certificate of Svc encl.
BURCHETTE,W H Northcutt Ely 79/07/23 41pp

7908310010 Motion to modify return date of subpoena of C Stover. Requests date be agreed upon by interested parties,due to recent developments requiring review by NRC.Draft order & Certificate of Svc encl.
LESSY,R P ; BLUME,M B Anti-Trust Division 79/07/23 6pp

7908030434 Discusses financial data & antitrust info submitted by TX Utils Generating Co on 790719.Submittal can be treated as financial data.
TOALSTON,A Antitrust & Indemnity Group 79/08/01 1p

--7908030440 Forwards Brazos Power Cooperative responses to NRC antitrust & financial review questions concerning request to amend CPPR-126 & CPPR-127.
GARY,R J Texas Utilities Generating Co 79/07/19 1p

--7908030450 Financial & antitrust review.
* Brazos Electric Power Cooperative, Inc 79/06/15 219pp

G. Inspection reports, IE Bulletins & correspondence

7908020225 Requests extension until 790628 to complete analysis of incorrect weights for Velan swing check valves,in response to IE Bulletin 79-04.
GARY,R J Texas Utilities Generating Co 79/05/23 1p

7908020271 Requests extension until 790628 to complete analysis re IE Bulletin 79-07 concerning seismic stress analysis of safety-related piping.
GARY,R J Texas Utilities Generating Co 79/05/23 1p

7908090524 Responds to IE Bulletin 79-04.No 3-inch,4-inch or 5-inch diameter Velan swing check valves are in use in piping sys.
GARY,R J Texas Utilities Generating Co 79/06/14 1p

7908220623 Responds to IE Bulletin 79-07.None of summation methods in Item I were used for seismic analysis of safety-related piping.Computer program listing is not required since techniques were not used.Plan of action not required.
GARY,R J Texas Utilities Generating Co 79/06/14 2pp

7908070125 Forwards IE Insp Repts 50-445/79-13 & 50-446/79-13 on 790514-31.No noncompliance noted.
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/18 2pp

--7908070130 IE Insp Repts 50-445/79-13 & 50-446/79-13 on 790514-31.No noncompliance noted.Major areas inspected:safety-related const activities,including installation & welding of reactor coolant & other piping sys & piping hangers.
TAYLOR,R G ; CROSSMAN,W A Region 4, Dallas, Office of the Director 79/06/15 5pp

7908150134 Responds to IE Bulletins 78-12,12A & 12B.C-E generic rept re atypical weld matl in reactor pressure vessel welds is satisfactory response.
GARY,R J Texas Utilities Generating Co 79/06/27 1p

7908270118 Forwards IE Insp Repts 50-445/79-15 & 50-446/79-15 on 790529-0604.No noncompliance noted.
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/02 2pp

--7908270123 IE Insp Repts 50-445/79-15 & 50-446/79-15 on 790529-0604.No noncompliance noted.Major areas inspected:alleged poor welding of inter-plate seams.
TAYLOR,R G ; CROSSMAN,W A Region 4, Dallas, Office of the Director 79/06/21 9pp

7908230665 Forwards IE Insp Repts 50-445/79-10 & 50-446/79-10 on 790406-0601.No noncompliance noted.
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/06 2pp

--7908230666 IE Insp Repts 50-445/79-10 & 50-446/79-10 on 790406-0601.No noncompliance noted.Major areas inspected:generation of false QA records by const personnel.
TAYLOR,R G ; CROSSMAN,W A Region 4, Dallas, Office of the Director 79/07/05 4pp

7908310115 Forwards IE Insp Repts 50-445/79-16 & 50-446/79-16 on 790601-30.No noncompliance noted.
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/11 2pp

--7908310116 IE Insp Repts 50-445/79-16 & 50-446/79-16 on 790601-30.No noncompliance noted.Major areas inspected:safety-related const activities including installation & welding of reactor coolant & other piping sys.
TAYLOR,R G ; CROSSMAN,W A Region 4, Dallas, Office of the Director 79/07/10 6pp

7908140357 Responds to IE Bulletin 79-11.No Westinghouse DB-50 or DB-75 circuit breakers incorporating dashpot-type overcurrent trip devices are planned for safety-related use at facility.
GARY,R J Texas Utilities Generating Co 79/07/16 1p

7908010328 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/07/17 1p

DOCKETED ITEMS

7908020402 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/18 1p

7908310021 Responds to NRC Insp Repts 50-445/79-15 & 50-446/79-15 despite absence of noncompliance.Mgt has taken necessary actions to maintain morale of workers since question was raised in cover ltr.
GARY,R.J. Texas Utilities Generating Co 79/07/18 2pp

7908160131 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/06 1p

7908290162 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/14 1p

7908290703 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/15 1p

S Reportable occurrences, LERs & related correspondence

7908160001 Notifies that investigation is continuing of 1981-83 2300 MW pipe supports which may not meet seismic requirements. Situation is considered potentially reportable.
GARY,R.J. Texas Utilities Generating Co 79/07/13 1p

7908170120 Notifies that investigation is continuing of 1981-83 2300 MW pipe wall thicknesses which may not meet specs.Situation is considered potentially reportable.
GARY,R.J. Texas Utilities Generating Co 79/07/17 1p

7908170112 Notifies that investigation is continuing of electrical cable tray hangers w/light penetration welds where full penetration welds were required.Situation is considered potentially reportable.
GARY,R.J. Texas Utilities Generating Co 79/07/18 1p

7908010719 Forwards PNO-79-67AX.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/20 1p

7908140446 Notification that investigation & evaluation re possibility of cooling problem w/diesel generators is continuing.
GARY,R.J. Texas Utilities Generating Co 79/08/10 1p

7908140541 Supplements 790518 info re pipe supports which may not meet seismic requirements.Investigation continuing.
GARY,R.J. Texas Utilities Generating Co 79/08/10 1p

7908210295 Advises that investigation of potentially reportable situation re pipe wall thickness requirements is continuing.
GARY,R.J. Texas Utilities Generating Co 79/08/15 1p

7908210377 Notifies of continuing investigation re three electrical cable tray hangers found to have light partial penetration welds when full penetration welds were required.
GARY,R.J. Texas Utilities Generating Co 79/08/16 1p

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA.,UNIT 2

A Application/construction stage documents & correspondence

7908090467 Forwards matl,requested per Question 372.20,re onsite meteorological data used in FSAR,Dames & Moore format info, & sector analysis of exclusion area W/o encl.
FEIST,C.K. Texas Utilities Services, Inc 78/07/21 1p

7908090515 Forwards map showing current status of mineral rights ownership in exclusion area,in response to Question 312.2 W/o encl.
FEIST,C.K. Texas Utilities Services, Inc 78/07/24 1p

7908020549 Forwards request for detailed design drawings for structures & components of primary coolant sys in order to perform desired independent analyses of dynamic asymmetric loads.
BAER,R.L. Light Water Reactors Branch 2 79/05/31 7pp

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D.B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD,H. Light Water Reactors Branch 2 79/07/02 70pp

7908300465 Forwards request for addl info needed on review of FSAR.
BAER,R.L. Light Water Reactors Branch 2 79/07/02 5pp

7908090514 Responds to Question 361.10 Forwards 771221 rept & 780628 update by HJ Gray & Associates, Inc Determines max potential of blowout condition,petrophysical properties of subsurface formations & other info re plant site.
WERNER,R. Texas Utilities Services, Inc 79/07/10 17pp

7908080230 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER,J.R. Assistant Director for Site & Safeguards 79/07/19 2pp

7908010490 Forwards Dames & Moore 790423 ltr documenting telcons w/USGS re non-subsidence potential of cretaceous sandstone.
FEIST,C.K. Texas Utilities Services, Inc 79/07/27 5pp

7908300428 Notification of 790816 meeting w/licensee in Bethesda,MD to discuss implementing methods for responses to second round questions & NRC positions for maintaining safety review efforts.
BURWELL,S.B. Light Water Reactors Branch 2 79/08/06 3pp

F Security, medical, emergency & fire protection plans

7908200324 Forwards security training & qualification plan.Plan withheld (ref 10CFR2.790). Affidavit encl.
CLEMENTS,B.R. Texas Utilities Generating Co 79/08/15 5pp

G Adjudicatory correspondence

7908150006 Confirms 790717 meeting in Arlington,TX to discuss contentions of Citizens for Fair Util Regulations.
ULMAN,M.B. Operations & Administrative Division 79/07/05 1p

7908150007 Confirms 790718 meeting in Houston,TX to discuss contentions of Citizens Association for Sound Energy.
ULMAN,M.B. Operations & Administrative Division 79/07/05 1p

7908150008 Confirms 790719 meeting in Fort Worth,TX to discuss contentions of intervenor Association of Community Organizations for Reform Now.
ULMAN,M.B. Operations & Administrative Division 79/07/05 1p

7908300027 Notice of appearance of LJ Chandler & MB Ulman on behalf of NRC.Certificate of Svc encl.
CHANDLER,L.J. Branch 1 79/07/06 3pp

H General correspondence

7908170351 Ack receipt of ltr commenting on 790613 meeting re industry efforts related to TMI accident.
DENTON,H.R. Office of Nuclear Reactor Regulation 79/08/01 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

7908140427 Forwards Amend 7 to FSAR.
GARY,R.J. Texas Utilities Generating Co 79/07/31 2pp

--7908140432 Amend 7 to FSAR.Oversized drawings available in Central Files.
* Texas Utilities Generating Co 79/07/31 239pp.

7908220537 Forwards affidavit of svc for Amend 7 to FSAR.
SCHMIDT,H.C. Texas Utilities Generating Co 79/08/13 3pp

M Antitrust correspondence

7908080525 Submits Apr 1979 discovery rept of Public Utils Board of Brownsville,TX.Responded to two sets of interrogatories & document requests.Certificate of Svc encl.
POIRIER,M.R. Spiegel & McDiarmid 79/05/14 6pp

7908080535 Submits May 1979 discovery rept of Public Utils Board of Brownsville,TX.Worked w/Houston Lighting & Power to provide addl info responsive to util interrogatories & document requests.Certificate of Svc encl.
POIRIER,M.R. Spiegel & McDiarmid 79/06/08 6pp

7908030230 Forwards copies of NRC response to first set of interrogatories & requests for production of documents. Also forwards util supplemental response to NRC first set of interrogatories & requests for production of documents. BLUME, M.B. Anti-Trust Division 79/06/29 1p.

7908130130 TX-LA Cooperative motion for extension until 790806 to respond to TX Utils Generating Co 790618 first set of interrogatories & request for documents. Nature & extent of info requires addl time. Certificate of Svc encl. RITTS, F.H. Northcutt Ely 79/07/02 5pp.

7908200068 Notifies that City of Austin, TX has not initiated nor received any discovery requests during June 1979. Certificate of Svc encl. BALOUGH, R.C. Austin, TX 79/07/02 4pp.

7908220094 Submits rept of discovery activities by South TX Electric Cooperative, Inc & Medina Electric Cooperative for June 1979. Certificate of Svc encl. JOHN, D.F. Akin, Gump, Hauer & Feld 79/07/02 5pp.

7908130176 Progress rept per ASLB 780621 order re June 79 discovery. Major attention was given to implementation of ASLB 790601 order directing Gulf States Utils to comply w/ASLB 790226 subpoenaduces tecum. Certificate of Svc encl. HARRIS, J.L., CYPHERT, S.B., CLARK, R.H. Justice, Dept of 79/07/03 9pp.

7908200097 Rept of discovery activities of Public Utils Board of Brownsville, TX for June 1979. Inspected documents at ofc of Central & South West Corp & received subpoena for production of documents to El Paso Electric Co. Certificate of Svc encl. POIRIER, M.R. Spiegel & McDiarmid 79/07/05 6pp.

7908130115 Third supplemental answer to DOJ first set of interrogatories & request for production of documents. Affidavit, Certificate of Svc & supporting documentation encl. SERATH, E.D. Texas Utilities Co 79/07/06 9pp.

7908130188 TX Utils Generating Co opposition to TX LA Electric Cooperative /790702 motion for extension until 790806 re response to TX Utils first set of interrogatories. No objection made to 790724 reply date. KNOTTS, J.B. Debevoise & Lieberman. WORSHAM, J.I. Worsham, Forsythe & Sampels 79/07/09 2pp.

--7908130201 TX Utils Generating Co reply to DOJ & NRC joint motion for partial reconsideration of ASLB 790625 order re discovery & prehearing schedule. Opposes proposed schedule but does not object to dates set forth in order. Certificate of Svc encl. KNOTTS, J.B. Debevoise & Lieberman. WORSHAM, J.I. Worsham, Forsythe & Sampels 79/07/09 5pp.

7908090581 Forwards Lerner testimony. NRC may oppose second deposition, since analysis is only investigative & analytical, not conclusive. W/o encl. LESSY, R.P. Anti-Trust Division 79/07/11 2pp.

7908130215 Motion to compel Houston Lighting & Power to produce certain documents alleged to be priviledged. Certificate of Svc & supporting documentation encl. HARRIS, J.L., CYPHERT, S.B. Justice, Dept of. CLARK, R.H. Interior, Dept of 79/07/11 36pp.

7908210612 Forwards Lerner testimony in prior proceedings & list of publications. NRC may oppose second deposition of Lerner if decision to proceed early with 790719 deposition is maintained. W/o encl. LESSY, R.P. Anti-Trust Division 79/07/11 1p.

7908130223 Supplemental request for production of documents by Houston Lighting & Power & TX Utils Generating Co, per ASLB 790625 order. Certificate of Svc encl. LESSY, R.P. Anti-Trust Division 79/07/13 6pp.

7908130240 First supplemental response to TX Utils Generating Co 790209 first set of interrogatories & request for production of documents. Certificate of Svc encl. CYPHERT, S.B., CLARK, R.H. Justice, Dept of 79/07/13 13pp.

7908130246 First supplemental response to Houston Lighting & Power 790209 second set of interrogatories & requests for production of documents. Certificate of Svc encl. CYPHERT, S.B., CLARK, R.H. Justice, Dept of 79/07/13 9pp.

7908220092 Forwards return on svc of subpoena issued by ASLB to El Paso Electric Co. POIRER, M.R. Spiegel & McDiarmid 79/07/16 2pp.

7908130261 Motion to quash or modify 790707 subpoena directed to T Sweatman & 790709 subpoena directed to keeper of records of TX Public Util Commission. Certificate of Svc & exhibits encl. HUGHES, D., FAINTER, J.W. Texas, State of 79/07/19 22pp.

7908200269 Stipulation among parties for protective order on behalf of Gulf States Utils, re ASLB 790226 subpoena issued at request of Public Utils Board of City of Brownsville, TX for production of documents. Order granted by ASLB on 790723. RADER, R.M. Gulf States Utilities Co. BLUME, M.B. Anti-Trust Division. HARRIS, J.L. Justice, Dept of. 79/07/23 11pp.

7908200395 TX-LA Electric Cooperative response to TX Utils Generating Co first set of interrogatories & requests for production of documents. Supporting documentation & Certificate of Svc encl. BURCHETTE, W.H. Northcutt Ely 79/07/23 41pp.

7908310010 Motion to modify return date of subpoena of C Stover. Requests date be agreed upon by interested parties, due to recent developments requiring review by NRC. Draft order & Certificate of Svc encl. LESSY, R.P., BLUME, M.B. Anti-Trust Division 79/07/23 6pp.

7908030434 Discusses financial data & antitrust info submitted by TX Utils Generating Co on 790719. Submittal can be treated as financial data. TOALSTON, A. Antitrust & Indemnity Group 79/08/01 1p.

--7908030440 Forwards Brazos Power Cooperative responses to NRC antitrust & financial review questions concerning request to amend CPPR-126 & CPPR-127. GARY, R.J. Texas Utilities Generating Co. 79/07/19. 1p.

--7908030450 Financial & antitrust review. * Brazos Electric Power Cooperative, Inc. 79/06/15 219pp.

G. Inspection reports, IE Bulletins & correspondence

7908020225 Requests extension until 790628 to complete analysis of incorrect weights for Velan swing check valves, in response to IE Bulletin 79-04. GARY, R.J. Texas Utilities Generating Co. 79/05/23 1p.

7908020271 Requests extension until 790628 to complete analysis re IE Bulletin 79-07 concerning seismic stress analysis of safety-related piping. GARY, R.J. Texas Utilities Generating Co. 79/05/23 1p.

7908090524 Responds to IE Bulletin 79-04. No 3-inch, 4-inch or 5-inch diameter Velan swing check valves are in use in piping sys. GARY, R.J. Texas Utilities Generating Co. 79/06/14 1p.

7908220623 Responds to IE Bulletin 79-07. None of summation methods in Item 1 were used for seismic analysis of safety-related piping. Computer program listing is not required since techniques were not used. Plan of action not required. GARY, R.J. Texas Utilities Generating Co. 79/06/14 2pp.

7908070125 Forwards IE Insp Rpts 50-445/79-13 & 50-446/79-13 on 790514-31. No noncompliancce noted. SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/18 2pp.

--7908070130 IE Insp Rpts 50-445/79-13 & 50-446/79-13 on 790514-31. No noncompliance noted. Major areas inspected: safety-related const activities, including installation & welding of reactor coolant & other piping sys & piping hangers. TAYLOR, R.G., CROSSMAN, W.A. Region 4, Dallas, Office of the Director 79/06/15 5pp.

7908150134 Responds to IE Bulletins 78-12, 12A & 12B. C-E generic rept re atypical weld matl in reactor pressure vessel welds is satisfactory response. GARY, R.J. Texas Utilities Generating Co. 79/06/27 1p.

7908270118 Forwards IE Insp Rpts 50-445/79-15 & 50-446/79-15 on 790529-0604. No noncompliance noted. SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/02 2pp.

--7908270123 IE Insp Rpts 50-445/79-15 & 50-446/79-15 on 790529-0604. No noncompliance noted. Major areas inspected: alleged poor welding of inter-plate seams. TAYLOR, R.G., CROSSMAN, W.A. Region 4, Dallas, Office of the Director 79/06/21 9pp.

7908230665 Forwards IE Insp Repts 50-445/79-10 & 50-446/79-10 on 790406-0601. No noncompliance noted.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/06 2pp.

--7908230666 IE Insp Repts 50-445/79-10 & 50-446/79-10 on 790406-0601. No noncompliance noted. Major areas inspected: generation of fa se QA records by const personnel.
TAYLOR,R.G.; CROSSMAN,W.A. Region 4, Dallas, Office of the Director. 79/07/05 4pp.

7908310115 Forwards IE Insp Repts 50-445/79-16 & 50-446/79-16 on 790601-30. No noncompliance noted.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/11 2pp.

--7908310116 IE Insp Repts 50-445/79-16 & 50-446/79-16 on 790601-30. No noncompliance noted. Major areas inspected: safety-related const activities including installation & welding of reactor coolant & other piping sys.
TAYLOR,R.G.; CROSSMAN,W.A. Region 4, Dallas, Office of the Director. 79/07/10 6pp.

7908160357 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 circuit breakers incorporating dashpot-type overcurrent trip devices are planned for safety-related use at facility.
GARY,R.J. Texas Utilities Generating Co. 79/07/16 1p.

7908010329 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/07/17 1p.

7908020402 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/07/18 1p.

7908310021 Responds to NRC Insp Repts 50-445/79-15 & 50-446/79-15 despite absence of noncompliance. Mgt has taken necessary actions to maintain morale of workers since question was raised in cover ltr.
GARY,R.J. Texas Utilities Generating Co. 79/07/18 2pp.

7908160131 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/08/06 1p.

7908290162 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/08/14 1p.

7908290703 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/08/15 1p.

S Reportable occurrences, LERs & related correspondence

7908160001 Notifies that investigation is continuing of 1981-83 2300 MW pipe supports which may not meet seismic requirements. Situation is considered potentially reportable.
GARY,R.J. Texas Utilities Generating Co. 79/07/13 1p.

7908170120 Notifies that investigation is continuing of 1981-83 2300 MW pipe wall thicknesses which may not meet specs. Situation is considered potentially reportable.
GARY,R.J. Texas Utilities Generating Co. 79/07/17 1p.

7908170112 Notifies that investigation is continuing of electrical cable tray hangers w/light penetration welds where full penetration welds were required. Situation is considered potentially reportable.
GARY,R.J. Texas Utilities Generating Co. 79/07/18 1p.

7908010719 Forwards PND-79-67AX.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/20 1p.

7908140446 Notification that investigation & evaluation re possibility of cooling problem w/diesel generators is continuing.
GARY,R.J. Texas Utilities Generating Co. 79/08/10 1p.

7908140541 Supplements 790518 info re pipe supports which may not meet seismic requirements. Investigation continuing.
GARY,R.J. Texas Utilities Generating Co. 79/08/10 1p.

7908210295 Advises that investigation of potentially reportable situation re pipe wall thickness requirements is continuing.
GARY,R.J. Texas Utilities Generating Co. 79/08/15 1p.

7908210377 Notifies of continuing investigation re three electrical cable tray hangers found to have light partial penetration welds when full penetration welds were required.
GARY,R.J. Texas Utilities Generating Co. 79/08/16 1p.

DOCKET 50-452 GREENWOOD ENERGY CENTER, UNIT 2

A Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO,D.B. Assistant Director for Light Water Reactors. 79/04/18 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D.B. Assistant Director for Light Water Reactors. 79/06/06 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD,H. Light Water Reactors Branch 2. 79/07/02 70pp.

7908080158 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER,J.R. Assistant Director for Site & Safeguards. 79/07/24 2pp.

G Adjudicatory correspondence

7905140571 Forwards unclassified transmittal memo re info potentially relevant to issue of sabotage of spent nuclear fuel. Also discusses SAND77-1927, "Transport of Radionuclides in Urban Environ: Working Draft Assessment."
SOHINKI,S.M. Branch 3. 79/04/25 2pp.

7908200142 Notifies that scheduled completion dates for facilities have been moved back to 1990 & 1992 per 790625 press release. Caused by suspension of environ & safety reviews until Jan 1980.
VOIGHT,H.H. LeBoeuf, Lamb, Leiby & MacRae. 79/06/29 2pp.

DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D.B. Assistant Director for Light Water Reactors. 79/06/06 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD,H. Light Water Reactors Branch 2. 79/07/02 70pp.

7908080158 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER,J.R. Assistant Director for Site & Safeguards. 79/07/24 2pp.

G Adjudicatory correspondence

7905140571 Forwards unclassified transmittal memo re info potentially relevant to issue of sabotage of spent nuclear fuel. Also discusses SAND77-1927, "Transport of Radionuclides in Urban Environ: Working Draft Assessment."
SOHINKI,S.M. Branch 3. 79/04/25. 2pp.

7908200142 Notifies that scheduled completion dates for facilities have been moved back to 1990 & 1992 per 790625 press release. Caused by suspension of environ & safety reviews until Jan 1980.
VOIGHT,H.H. LeBoeuf, Lamb, Leiby & MacRae. 79/06/29. 2pp.

DOCKET 50-454 BYRON STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applicati...
VASSALLO, J. B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co. 79/07/30 2pp

7908130554 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN, L. S. Light Water Reactors Branch 4 79/08/01 4pp

F. Security, medical, emergency & fire protection plans

7908200226 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/08/16 1p

G. Adjudicatory correspondence

7908080156 Motion requesting postponement of 790725 prehearing conference, to allow for proper preparation of amended contentions. Certificate of Svc encl.
JOHNSON, B. League of Women Voters of Rockford, IL 79/06/27 2pp

7908130102 Motion requesting postponement of prehearing conference until 790825, to adequately prepare amended contentions. Necessary documents are not yet available in Founders Library at Northern IL Univ. Certificate of Svc encl.
VON ZELLEN, B. W. DeKalb Area Alliance for Responsible Energy 79/06/29 2pp

7908150341 Ack receipt of notice re 790725 prehearing conference on OL. Requests postponement of prehearing conference & future 30-day prior notice of hearings.
JOHNSON, B. League of Women Voters of Rockford, IL 79/06/29 1p

--7908150354 Amends 790726 motion to delay prehearing conference until conclusion of NRC special inquiry into TMI event. Certificate of svc encl.
JOHNSON, B. League of Women Voters of Rockford, IL 79/06/29 2pp

7908080188 Forwards response to League of Women Voters of Rockford, IL 790625 ltr requesting postponement of 790725 special prehearing conference.
CUNNINGHAM, G. H. Branch 2 79/07/03 1p

--7908080195 Opposes League of Women Voters of Rockford, IL 790625 request for postponement of 790725 prehearing conference. Failure to receive ASLB 790608 notice is not sufficient to warrant delay. Certificate of Svc encl.
KARMAN, M. Branch 2 79/07/02 4pp

K. Utility Final Safety Analysis Report (FSAR) & amends

7908060106 Forwards affidavit of distribution of Amend 21 to FSAR.
NAUGHTON, W. F. Commonwealth Edison Co. 79/07/31 2pp

O. Inspection reports, IE Bulletins & correspondence

7908070127 Forwards IE Insp Repts 50-454/79-08 & 50-455/79-08 on 790508-09 & notice of violation.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/30 2pp

--7908070138 Notice of violation from insp on 790508-09.
* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/25 2pp

--7908070159 IE Insp Repts 50-454/79-08 & 50-455/79-08 on 790508-09. Noncompliance noted: failure to maintain adequate cleanliness & protection of components & equipment.
KONKLIN, J. E., LIVERMORE, H. H., KNOP, R. C. Region 3, Chicago, Office of the Director 79/05/25 5pp

7908010085 Forwards IE Insp Repts 50-373/79-22, 50-374/79-16, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07. No noncompliance noted.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/12 2pp

--7908010193 IE Insp Repts 50-373/79-22, 50-374/79-09, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07 on 790521. No noncompliance noted. Major areas inspected: fuel loading schedule, electrical area & QA personnel.
HAYES, D. W., BARRETT, P. A., FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/07 4pp

7908080420 Ack 790529 ltr re ASME code committee interpretation of procedure qualification test specimen stds.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/14 1p

--7908080424 Submits addl response to IE Insp Repts 50-454/78-09 & 50-455/78-09. Forwards util 790125 ltr requesting ASME code committee interpertation of procedure qualification test specimen requirements & ASME 790514 response.
REED, C. Commonwealth Edison Co. 79/05/29 3pp

7908020167 Supplements 790529 response to IE Bulletin 79-04. Correct Velan valve weights used in piping analyses.
REED, C. Commonwealth Edison Co. 79/06/19 1p

7908030037 Responds to IE Bulletin 78-12. Plant evaluations were submitted by GE & Westinghouse. Evaluation of LaSalle Unit 2 will be submitted by 790817. Forwards summary of documentation for each plant.
REED, C. Commonwealth Edison Co. 79/06/21 3pp

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co. 79/07/05 9pp.

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc. 79/05/31 24pp.

7908030214 Ack receipt of 790628 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-454/79-08 & 50-455/79-08.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/12 1p

--7908030227 Responds to NRC 790530 ltr re violations noted in IE Insp Repts 50-454/79-08 & 50-455/79-08. Corrective actions: end caps were removed & instrumentation tube ends were reprotected. Rags & debris removed.
REED, C. Commonwealth Edison Co. 79/06/28 4pp

7908130447 Responds to IE Bulletin 79-04. Sixty glove valves per station have incorrect weights when compared to drawings. Deficiency reported as RO & affected drawings corrected in light of recalculation of valves.
NAUGHTON, W. F. Commonwealth Edison Co. 79/07/16 4pp.

7908130455 Responds to IE Bulletin 79-11. Westinghouse DB-50 & DB-75 circuit breakers not used at plants.
REED, C. Commonwealth Edison Co. 79/07/19 1p

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities W/o encl.
REED, C. Commonwealth Edison Co. 79/08/01 2pp

7908150292 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/07 1p

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/15 1p

S. Reportable occurrences, LERs & related correspondence

7908090631 Ack receipt of 790716 interim deficiency rept re Velan valves.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/08/03. 1p.

DOCKET 50-455 BYRON STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/0? 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co. 79/07/30. 2pp.

7908130554 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/08/01. 4pp.

F. Security, medical, emergency & fire protection plans

7908200226 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co. 79/08/16. 1p.

G. Adjudicatory correspondence

7908080156 Motion requesting postponement of 790725 prehearing conference, to allow for proper preparation of amended contentions. Certificate of Svc encl.
JOHNSON, B. League of Women Voters of Rockford, IL. 79/06/27. 2pp.

7908130102 Motion requesting postponement of prehearing conference until 790825, to adequately prepare amended contentions. Necesary documents are not yet available in Founders Library at Northern IL Univ. Certificate of Svc encl.
VON IELLEN, B. W. DeKalb Area Alliance for Responsible Energy. 79/06/29. 2pp.

7908150341 Ack receipt of notice re 790725 prehearing conference on OL. Requests postponement of prehearing conference & future 30-day prior notice of hearings.
JOHNSON, B. League of Women Voters of Rockford, IL. 79/06/29. 1p.

--7908150354 Amends 790726 motion to delay prehearing conference until conclusion of NRC special inquiry into TMI event. Certificate of svc encl.
JOHNSON, B. League of Women Voters of Rockford, IL. 79/06/29. 2pp.

7908080188 Forwards response to League of Women Voters of Rockford, IL 790625 ltr requesting postponement of 790725 special prehearing conference.
CUNNINGHAM, G. H. Branch 2. 79/07/03. 1p.

--7908080195 Opposes League of Women Voters of Rockford, IL 790625 request for postponement of 790725 prehearing conference. Failure to receive ASLB 790608 notice is not sufficient to warrant delay. Certificate of Svc encl.
KARMAN, M. Branch 2. 79/07/02. 4pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908060306 Forwards affidavit of distribution of Amend 21 to FSAR.
NAUGHTON, W. F. Commonwealth Edison Co. 79/07/31. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908070127 Forwards IE Insp Repts 50-454/79-08 & 50-455/79-08 on 790508-09 & notice of violation.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/05/30. 2pp.

--7908070138 Notice of violation from insp on 790508-09.
* Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/05/25. 2pp.

--7908070159 IE Insp Repts 50-454/79-08 & 50-455/79-08 on 790508-09. Noncompliance noted: failure to maintain adequate cleanliness & protection of components & equipment.
KONKLIN, J. E., LIVERMORE, H. H., KNOP, R. C. Region 3, Chicago, Office of the Director. 79/05/25. 5pp.

7908010085 Forwards IE Insp Repts 50-373/79-22, 50-374/79-16, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07. No noncompliance noted.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/12. 2pp.

--7908010193 IE Insp Repts 50-373/79-22, 50-374/79-16, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07 on 790521. No noncompliance noted. Major areas inspected: fuel loading schedule, electrical area & QA personnel.
HAYES, D. W., BARRETT, P. A., FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/07. 4pp.

7908080420 Ack 790529 ltr re ASME code committee interpretation of procedure qualification test specimen stds.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/14. 1p.

--7908080424 Submits addl response to IE Insp Repts 50-454/78-09 & 50-455/78-09. Forwards util 790125 ltr requesting ASME code committee interpertation of procedure qualification test specimen requirements & ASME 790514 response.
REED, C. Commonwealth Edison Co. 79/05/29. 3pp.

7908020167 Supplements 790529 response to IE Bulletin 79-04. Correct Velan valve weights used in piping analyses.
REED, C. Commonwealth Edison Co. 79/06/19. 1p.

7908030037 Responds to IE Bulletin 78-12. Plant evaluations were submitted by GE & Westinghouse. Evaluation of LaSalle Unit 2 will be submitted by 790817. Forwards summary of documentation for each plant.
REED, C. Commonwealth Edison Co. 79/06/21. 3pp.

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co. 79/07/05. 9pp.

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc. 79/05/31. 24pp.

7908030214 Ack receipt of 790628 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-454/79-08 & 50-455/79-08.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/12. 1p.

--7908030227 Responds to NRC [illegible]530 ltr re violations noted in IE Insp Repts 50-454/79-08 & 50-[illegible]79-08. Corrective actions: end caps were removed & instal[illegible]tation tube ends were reprotected. Rags & debris removed.
REED, C. Commonwealth Edison Co. 79/06/28. 4pp.

7908130447 Responds to IE Bulletin 79-04. Sixty glove valves per station have incorrect weights when compared to drawings. Deficiency reported as RO & affected drawings corrected in light of recalculation of valves.
NAUGHTON, W. F. Commonwealth Edison Co. 79/07/16. 4pp.

7907290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908200245 Responds to IE Bulletin 79-14. Item 1.re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED, C. Commonwealth Edison Co. 79/08/01. 2pp.

7908150292 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/07. 1p.

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/15 1p

F Reportable occurrences, LERs & related correspondence

7908090631 Ack receipt of 790716 interim deficiency rept re Velan valves.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/08/03 1p

DOCKET 50-456 BRAIDWOOD STATION, UNIT 1

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL application & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co 79/07/30 2pp

7908130554 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN, L. S. Light Water Reactors Branch 4 79/08/01 4pp

F Security, medical, emergency & fire protection plans

7908200223 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED, C. Commonwealth Edison Co 79/08/1[illegible] 1p

K Utility Final Safety Analysis Report (FSAR) & amends

7908060306 Forwards affidavit of distribution of Amend 21 to FSAR.
NAUG[illegible]JN, W. F. Commonwealth Edison Co 79/07/31 2pp

G Inspection reports, IE Bulletins & correspondence

7908010085 Forwards IE Insp Repts 50-373/79-22, 50-374/79-16, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07. No noncompliance noted.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/12 2pp

--7908010193 IE Insp Repts 50-373/79-22, 50-374/79-16, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07 on 790521. No noncompliance noted. Major areas inspected: fuel loading schedule, electrical area & QA personnel.
HAYES, D. W., BARRETT, P. A., FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/07 4pp

7908020167 Supplements 790529 response to IE Bulletin 79-04. Correct Velan valve weights used in piping analyses.
REED, C. Commonwealth Edison Co 79/06/19 1p

7908030037 Responds to IE Bulletin 78-12. Plant evaluations were submitted by GE & Westinghouse. Evaluation of LaSalle Unit 2 will be submitted by 790817. Forwards summary of documentation for each plant.
REED, C. Commonwealth Edison Co 79/06/21 3pp

7908020324 Responds to 790523 ltr. Accepts interpretation of ASME Code Committee re welding of split backing rings. No noncompliance to IE insp will be noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/27 1p

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED, C. Commonwealth Edison Co 79/07/05 9pp

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc 79/05/31 24pp

7908130447 Responds to IE Bulletin 79-04. Sixty glove valves per station have incorrect weights when compared to drawings. Deficiency reported as RO & affected drawings corrected in light of recalculation of valves.
NAUGHTON, W. F. Cr[illegible]onwealth Edison Co 79/07/16 4pp

7908060171 Ack receipt of 790607 & 25 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-03 & 50-547/79-03.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/18 1p

--7908060180 Responds to NRC 790504 ltr re violations noted in IE Insp Repts 50-546/79-03 & 50-547/79-03. Corrective actions: reinforcing steel was retied & inspected, concrete production areas reinspected & curing checked.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/06/07 5pp

--7908060189 Supplements response to NRC 790504 ltr re violations noted in IE Insp Repts 50-456/79-03 & 50-457/79-03. Corrective actions: contaminants removed & steel reinspected.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/06/25 2pp

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908200245 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED, C. Commonwealth Edison Co 79/08/01 2pp

7908150292 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/07 1p

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/08/15 1p

S Reportable occurrences, LERs & related correspondence

7908090631 Ack receipt of 790716 interim deficiency rept re Velan valves.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/08/03 1p

DOCKET 50-457 BRAIDWOOD STATION, UNIT 2

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908160376 Forwards table showing that manning of technical positions by technical graduates is virtually complete.
LEE, B. Commonwealth Edison Co 79/07/30 2pp

7908130554 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN, L. S. Light Water Reactors Branch 4 79/08/01 4pp

F. Security, medical, emergency & fire protection plans

7908290223 Forwards security personnel training & qualification plan. Plan withheld (ref 10CFR2.790).
REED,C. Commonwealth Edison Co. 79/08/16. 1p.

K. Utility Final Safety Analysis Report (FSAR) & amends

7908060306 Forwards affidavit of distribution of Amend 21 to FSAR.
NAUGHTON,W.F. Commonwealth Edison Co. 79/07/31. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908010085 Forwards IE Insp Repts 50-373/79-22, 50-374/79-16, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07. No noncompliance.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/06/12. 2pp.

--7908010193 IE Insp Repts 50-373/79-22, 50-374/79-16, 50-454/79-09, 50-455/79-09, 50-456/79-07 & 50-457/79-07 on 790521. No noncompliance noted. Major areas inspected: fuel loading schedule, electrical area & QA personnel.
HAYES,D.W., BARRETT,P.A., FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/07. 4pp.

7908020167 Supplements 790529 response to IE Bulletin 79-04. Correct Velan valve weights used in piping analyses.
REED,C. Commonwealth Edison Co. 79/06/19. 1p.

7908030037 Responds to IE Bulletin 78-12. Plant evaluations were submitted by GE & Westinghouse. Evaluation of LaSalle Unit 2 will be submitted by 790817. Forwards summary of documentation for each plant.
REED,C. Commonwealth Edison Co. 79/06/21. 3pp.

7908020324 Responds to 790523 ltr. Accepts interpretation of ASME Code Committee re welding of split backing rings. No noncompliance to IE insp will be noted.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/27. 1p.

7908060111 Responds to IE Bulletin 79-02. Forwards "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete." Comprehensive program undertaken to resolve issues raised in bulletin. Bolt torque audit in progress.
REED,C. Commonwealth Edison Co. 79/07/05. 9pp.

--7908060120 "Evaluation of Analysis Procedures for Design of Expansion-Anchored Plates in Concrete."
* Sargent & Lundy, Inc. 79/05/31. 24pp.

7908130447 Responds to IE Bulletin 79-04. Sixty glove valves per station have incorrect weights compared to drawing. Deficiency reported as RD & affected drawings corrected in light of recalculation of valves.
NAUGHTON,W.F. Commonwealth Edison Co. 79/07/16. 4pp.

7908060171 Ack receipt of 790607 & 25 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-03 & 50-547/79-03.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/18. 1p.

--7908060180 Responds to NRC 790504 ltr re violations noted in IE Insp Repts 50-546/79-03 & 50-547/79-03. Corrective actions: reinforcing steel was retied & inspected, concrete production areas reinspected & curing checked.
COUGHLIN,J. Public Service Co. of Indiana, Inc. 79/06/07. 5pp.

--7908060189 Supplements response to NRC 790504 ltr re violations noted in IE Insp Repts 50-456/79-03 & 50-457/79-03. Corrective actions: contaminants removed & steel reinspected.
COUGHLIN,J. Public Service Co. of Indiana, Inc. 79/06/25. 2pp.

7908290405 Forwards IE Bulletin 79-16, "Vital Area Access Controls." Action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908300455 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908200240 Responds to IE Bulletin 79-14, Item 1, re seismic analysis for as-built safety-related piping sys. Forwards lists of design documents which were sources of input info for seismic analysis of facilities. W/o encl.
REED,C. Commonwealth Edison Co. 79/08/01. 2pp.

7908150292 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300312 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908090631 Ack receipt of 790716 interim deficiency rept re Velan valves.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/08/03. 1p.

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908070030 Responds to 790601 request for return of "Accelerated Aging Procedures," supplemental rept for 480-volt motor control ctrs mfg by Gould, Inc.
VARGA,S.A. Light Water Reactors Branch 4. 79/07/09. 2pp.

7908080164 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook." W/o encl.
MILLER,J.R. Assistant Director for Site & Safeguards. 79/07/24. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908070236 Responds to IE Bulletin 79-04. Velan swing check valves examined & weights verified. If weight changes are identified, further response will be provided.
WEIGAND,J.G. Gulf States Utilities Co. 79/05/25. 2pp.

7908090401 Responds to IE Bulletin 79-07. No computer codes use methods described in Item 1, NUPIPE, Version 03, Levels 03-10, used in seismic stress analysis of safety-related piping.
WEIGAND,J.G. Gulf States Utilities Co. 79/05/25. 1p.

7908010036 Forwards IE Insp Rept 50-458/79-01 on 790529-0601. No noncompliance noted.
SEIDLE,W.C. Region 4, Dallas, Office of the Director. 79/06/15. 2pp.

--7908010043 IE Insp Rept 50-458/79-01 on 790529-0601. No noncompliance noted. Major areas inspected: safety-related concrete specs, licensee action on previously identified insp findings & preparations for resumption of const.
OBERG,C.R., CROSSMAN,W.A. Region 4, Dallas, Office of the Director. 79/06/14. 8pp.

7908090527 Responds to IE Bulletins 78-12A & 12B. Forwards complete response, including info re search of records of manufacturer for atypical weld matl & verification & identification of weld filler matl.
WEIGAND,J.G. Gulf States Utilities Co. 79/06/15. 10pp.

7908150099 Responds to IE Bulletin 79-09 re 790417 ltr. GE Type AK-2 breakers w/faulty trip device are not used or planned for use at facilities.
WEIGAND,J.G. Gulf States Utilities Co. 79/06/22. 1p.

7908030004 Ack receipt of 790525 ltr responding to IE Bulletins 78-12, 12A & 12B. Requests that final reply be submitted by 790723.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/06/27. 1p.

--7908030010 Discusses measures taken to complete response to IE Bulletins 78-12, 12A & 12B. Response will be submitted by 790930.
WEIGAND,J.G. Gulf States Utilities Co. 79/05/25. 1p.

7908010316 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/07/17. 1p.

7908020394 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/07/18. 1p.

7908160122 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/06
1p

7908290142 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/14
1p

7908290693 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/15
1p

S Reportable occurrences, LERs & related correspondence

7908010708 Forwards PNO-79-67AX.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/20 1p

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

7908070030 Responds to 790601 request for return of "Accelerated Aging Procedures," supplemental rept for 480-volt motor control ctrs mfg by Gould,Inc.
VARGA,S.A. Light Water Reactors Branch 4 79/07/09 2pp

7908080164 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook," w/o encl.
MILLER,J.R. Assistant Director for Site & Safeguards 79/07/24
2pp

G Inspection reports, IE Bulletins & correspondence

7908070238 Responds to IE Bulletin 79-04 Velan swing check valves examined & weights verified.If weight changes are identified,further response will be provided.
WEIGAND,J.G. Gulf States Utilities Co. 79/05/25 2pp

7908090401 Responds to IE Bulletin 79-07.No computer codes use methods described in Item 1 NUPIPE,Version 03,Levels 03-10 used in seismic stress analysis of safety-related piping.
WEIGAND,J.G. Gulf States Utilities Co. 79/05/25 1p

7908090527 Responds to IE Bulletins 78-12A & 12B.Forwards complete response,including info re search of records of manufacturer for atypical weld matl & verification & identification of weld filler matl.
WEIGAND,J.G. Gulf States Utilities Co. 79/06/15 10pp

7908150099 Responds to IE Bulletin 79-09 re 790417 ltr.GE Type AK-2 breakers w/faulty trip device are not used or planned for use at facilities.
WEIGAND,J.G. Gulf States Utilities Co. 79/06/22 1p

7908030004 Ack receipt of 790525 ltr responding to IE Bulletins 78-12, 12A & 12B.Requests that final reply be submitted by 790723.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/27 1p

--7908030010 Discusses measures taken to complete response to IE Bulletins 78-12,12A & 12B.Response will be submitted by 790930.
WEIGAND,J.G. Gulf States Utilities Co. 79/05/25 1p

7908010316 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/17
1p

7908020394 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/07/18
1p

7908160122 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/06
1p

7908290142 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/14
1p

7908290693 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director 79/08/15
1p

S Reportable occurrences, LERs & related correspondence

7908010708 Forwards PNO-79-67AX.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/20 1p

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments.W/o encl.
VASSALLO,D.B. Assistant Director for Light Water Reactors 79/04/18 3pp

7908080192 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
PARR,O.D. Light Water Reactors Branch 3 79/07/11 2pp

7908080237 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER,J.R. Assistant Director for Site & Safeguards 79/07/20
2pp

G Inspection reports, IE Bulletins & correspondence

7908280087 Responds to IE Bulletin 79-03.No welded pipe mfg by Youngstown Welding & Engineering Co in use or planned for use in safety-related sys.
RENBERGER,D.L. Washington Public Power Supply System 79/06/06
1p

7908130431 Forwards response to IE Bulletin 79-07.None of methods for analyzing safety-related piping in bulletin are employed. Lists computer programs utilized.
RENBERGER,D.L. Washington Public Power Supply System 79/06/12
6pp

7908230053 Forwards IE Insp Repts 50-460/79-06 & 50-513/79-06 on 790424-27 & notice of deviation.
SPENCER,G.S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/22 2pp

--7908230058 Notice of deviation from insp on 790424-27.
* Region 5, San Francisco, Office of the Director 79/06/22
1p

--7908230061 IE Insp Repts 50-460/79-06 & 50-513/79-06 on 790424-27. Noncompliance noted:one weld on containment equipment & floor drain pipe spool did not meet ASME III Class 3 requirements.
ALBERT,W.G., ECKHARDT,J.H. Region 5, San Francisco, Office of the Director. DODDS,R.T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/14 6pp

--7908230064 Ack receipt of 790719 ltr re steps taken to correct deviation noted in IE Insp Repts 50-460/79-06 & 50-513/79-06.Corrective actions will be verified during future insp.
SPENCER,G.S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/08/01 1p

--7908230067 Forwards response to 790622 ltr re item of deviation noted in IE Insp Repts 50-460/79-06 & 50-513/79-06.Corrective actions:weld & spool piece repaired & deviation documented.
KENBERGER,D.L. Washington Public Power Supply System 79/07/19
2pp

7908070725 Responds to IE Bulletin 79-09.No GE Type AK-2 circuit breakers used or planned for use in safety-related sys at facility.
RENBERGER,D.L. Washington Public Power Supply System 79/06/25
1p

7908010397 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director 79/07/17 1p

7908020411 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908020509 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908060166 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210472 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908280399 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310162 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300256 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908020537 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020033 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908010218 Summary of 790612-13 meeting w/util in Decatur, IL re organization structure, financial plans, load forecast & commitment to generating power.
BUCKLEY, B. C. Light Water Reactors Branch 1. 79/07/06. 7pp.

7908100352 Summary of 790709 meeting w/util re forecast panel findings from 790612-14 site visit.
BUCKLEY, B. C. Light Water Reactors Branch 1. 79/07/09. 4pp.

7908070798 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/13. 1p.

7908080176 Forwards NUREG-0578, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/24. 1p.

G. Inspection reports, IE Bulletins & correspondence

7908020318 Responds to IE Bulletins 78-12, 12A & 12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Encl 790424 ltr by CB&I reports no weld deviations for Unit 1. Unit 2 vessel fabrication is incomplete.
MULLER, G. E. Illinois Power Co. 79/05/29. 1p.

--7908020338 Responds to IE Bulletins 78-12 & 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Welding consumables were rereviewed against original requirements & no deviations were found.
KELLEY, R. C. Chicago Bridge & Iron Co. 79/04/24. 2pp.

7908070747 Responds to IE Bulletin 79-07 re seismic analysis computer codes. Discusses verification of piping computer programs in use.
MULLER, G. E. Illinois Power Co. 79/05/29. 3pp.

7908290361 Forwards response to IE Bulletin 79-02 & 02, Revision 1 action items re structural failures of piping supports for safety equipment.
MULLER, G. E. Illinois Power Co. 79/07/05. 2pp.

7908080417 Ack receipt of 790615 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-461/79-03.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/13. 1p.

--7908080422 Responds to NRC 790509 ltr re violation noted in IE Insp Rept 50-461/79-03. Corrective actions: concrete vibrators tested.
GERSTNER, W. C. Illinois Power Co. 79/06/15. 1p.

7908020335 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908150458 Supplements response to IE Bulletin 79-02. IL Power Co, Comm Ed & three other utils are presently testing expansion anchors. Resulting data will be used to ensure proper design.
MULLER, G. E. Illinois Power Co. 79/07/20. 1p.

7908240634 Responds to IE Bulletin 79-11. Westinghouse DB-75 & DB-50 circuit breakers not used w/safety-related svcs.
MULLER, G. E. Illinois Power Co. 79/07/26. 1p.

7908300411 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908150360 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300280 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908070798 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/13. 1p.

7908080176 Forwards NUREG-0578, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/24. 1p.

G. Inspection reports, IE Bulletins & correspondence

7908020318 Responds to IE Bulletins 78-12, 12A & 12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Encl 790424 ltr by CB&I reports no weld deviations for Unit 1. Unit 2 vessel fabrication is incomplete.
MULLER, G. E. Illinois Power Co. 79/05/29. 1p.

--7908020338 Responds to IE Bulletins 78-12 & 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Welding consumables were rereviewed against original requirements & no deviations were found.
KELLEY, R. C. Chicago Bridge & Iron Co. 79/04/24. 2pp.

7908070747 Responds to IE Bulletin 79-07 re seismic analysis computer codes. Discusses verification of piping computer programs in use.
MULLER, G. E. Illinois Power Co. 79/05/29. 3pp.

7908290361 Forwards response to IE Bulletin 79-02 & 02, Revision 1 action items re structural failures of piping supports for safety equipment.
MULLER, G. E. Illinois Power Co. 79/07/05. 2pp.

7908020335 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908150458 Supplements response to IE Bulletin 79-02. IL Power Co, Comm Ed & three other utils are presently testing expansion anchors. Resulting data will be used to ensure proper design.
MULLER, G. E. Illinois Power Co. 79/07/20. 1p.

7908240634 Responds to IE Bulletin 79-11. Westinghouse DB-75 & DB-50 circuit breakers not used w/safety-related svcs.
MULLER, G. E. Illinois Power Co. 79/07/26. 1p.

7908300411 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908150360 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300280 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

DOCKET 50-463 FULTON GENERATING STATION, UNIT 1

G. Adjudicatory correspondence

7908200129 Responds to 790604 ltr opposing early site review & requesting rejection of application. Discusses objections re density of nuclear facilities in area; absence of evacuation plan & evaluation using pre-TMI stds.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/25. 2pp.

--7908200137 Submits 790604 resolution opposing early site review & requesting rejection of application. Reasons for opposition include excessive density of nuclear facilities in area & lack of emergency evacuation & sheltering plan.
ERB, A., HESS, L. Pequea, PA. 79/06/04. 1p.

H. General correspondence

7908080547 Forwards SAND-77-1972, "Transport of Radionuclides in Urban Environs Working Draft Assessment," SECY-78-311 & 311A.
GRAY, J. R. Branch 1. 79/05/18. 2pp.

U. Congressional/Executive Correspondence

7908150013 Requests careful consideration of Martic Township Supervisors resolution opposing early site review.
WALKER, R. S. House of Rep., Government Operations. 79/07/10. 1p.

DOCKET 50-464 FULTON GENERATING STATION, UNIT 2

G. Adjudicatory correspondence

7908200129 Responds to 790604 ltr opposing early site review & requesting rejection of application. Discusses objections re density of nuclear facilities in area; absence of evacuation plan & evaluation using pre-TMI stds.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/25. 2pp.

--7908200137 Submits 790604 resolution opposing early site review & requesting rejection of application. Reasons for opposition include excessive density of nuclear facilities in area & lack of emergency evacuation & sheltering plan.
ERB, A., HESS, L. Pequea, PA. 79/06/04. 1p.

H. General correspondence

7908080547 Forwards SAND-77-1972, "Transport of Radionuclides in Urban Environs Working Draft Assessment," SECY-78-311 & 311A.
GRAY, J. R. Branch 1. 79/05/18. 2pp.

U. Congressional/Executive Correspondence

7908150013 Requests careful consideration of Martic Township Supervisors resolution opposing early site review.
WALKER, R. S. House of Rep., Government Operations. 79/07/10. 1p.

DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908080168 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/20. 2pp.

790815043w Forwards util response to NRC documents developed as consequence of TMI incident.
NEWMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/08/10. 1p.

--7908150442 Forwards commitments to NUREG-0578, IE Bulletin 79-08 & emergency plan. Commitments will be incorporated into plant design, operating procedures or emergency plans. Details re implementation will be contained in FSAR.
TURNER, E. A. Houston Lighting & Power Co. 79/08/09. 21pp.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

7908090225 Second errata suppl to NUREG-0515, Suppl 2 to SER.
* Office of Nuclear Reactor Regulation. NUREG-0515. 79/03/31. 8pp.

7908100550 Forwards second errata for Suppl 2 to SER re CP application.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/07/09. 7pp.

G. Adjudicatory correspondence

7908160104 Discusses SAND77-1927, "Transport of Radionuclides in Urban Environs: Working Draft Assessment." Identifies general objectives & topics discussed. No action necessary per SECY-78-311 dtd 780614 & SECY-78-311A dtd 781109.
SOHINKI, S. M. Branch 3. 79/04/25. 3pp.

7908150338 Forwards draft testimony prepared by G Gears for Contention 2 of CP hearing. Invites comments.
KLINE, J. B. Environ Protect Standards Branch. 79/06/05. 1p.

--7908150348 Draft supplemental testimony re Contention 2 of CP hearing. NRC does not believe that changes in applicant's proposed design are warranted.
GEARS, G. E. Environ Protect Standards Branch. 79/06/05. 11pp.

7908160017 Expresses concern re nuclear power & radioactive emissions from facility.
STADE, K. L. Affiliation Unknown. 79/06/26. 1p.

7908220614 Second memo re discovery matters concerning Univ of Houston 790607 ltr addressed to author in capacity as Tx PIRG director. Notes resignation from position as of 790601. Forwards 790607 ltr.
DOHERTY, J. F. Intervenor J. F. Doherty. 79/06/26. 2pp.

--7908220662 First set of interrogatories addressed to State of TX. W/Certificate of Svc.
DOHERTY, J. F. Intervenor J. F. Doherty. 79/06/26. 2pp.

7908080072 Response to TX PIRG 790402 interrogatories. Certificate of Svc encl.
LOWERRE, R. W. Texas, State of. 79/06/27. 7pp.

7908130076 Second set of interrogatories & request for production of documents directed to Houston Lighting & Power. Certificate of Svc encl.
WHITE, M., FAINTER, J. W., LOWERRE, R. W. Texas, State of. 79/06/27. 7pp.

7908130089 Responds to first set of interrogatories propounded by intervenor B McCorkle. Certificate of Svc & supporting documentation encl.
WHITE, M. ; FAINTER, J.W. ; LOWERRE, R.W. Texas, State of 79/06/27 9pp.

7908200146 Requests intervenor status in next hearing re licensing of facility.
CLEAVES, W.S. Affiliation Unknown. 79/06/27 1p.

7908080075 Houston Lighting & Power motion for further procedures re TX PIRG intervention Due to resignation of JF Doherty of TX PIRG on 790606. TX PIRG should be required to identify spokesman & reiterate interest W/Certificate of Svc.
NEWMAN, J.R. Lowenstein, Newman, Reis, Axelrad & Toll. COPELAND, J.G. Baker & Botts. 79/06/28 9pp.

7908200139 Opposes const of facility Requests full party status in const permit hearings.
DAY, D. Affiliation Unknown. 79/06/30 1p.

7908080079 Notice of deposition directed to WE Rentfro re Contention 2. Schedule of deposition & Certificate of Svc encl.
COPELAND, J.G. Baker & Botts. 79/07/02 4pp.

7908170637 Requests notification of prehearing date for proposed OL hearing Requests permission to make verbal or written statement.
ROBERTSON, J. Affiliation Unknown. 79/07/02 1p.

7908080092 Houston Lighting & Power second set of interrogatories & requests for production of documents directed to intervenor C Hinderstein Certificate of Svc encl.
COPELAND, J.G. Baker & Botts. NEWMAN, J.R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/03 10pp.

7908200050 Requests opportunity to participate in hearing Files petition to intervene Requests procedural info.
ROBINSON, J.H. Affiliation Unknown. 79/07/03 1p.

7908220304 Houston Lighting & Power second set of interrogatories & requests for production of documents directed to BA McCorkle Certificate of Svc encl.
BIDDLE, C.T. Baker & Botts. NEWMAN, J.R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/03 13pp.

7908230077 Response to C Hinderstein interrogatories Supporting documentation & Certificate of Svc encl.
LOWERRE, R.W. Texas, State of 79/07/03 39pp.

7908220312 Houston Lighting & Power third set of interrogatories & requests for production of documents directed to TX PIRG Certificate of Svc encl.
BIDDLE, C.T. Baker & Botts. NEWMAN, J.R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/05 9pp.

7908220315 Houston Lighting & Power response to intervenor JF Doherty request for production of documents Certificate of Svc encl.
BIDDLE, C.T. Baker & Botts. 79/07/05 4pp.

7908220320 Response to JH Doherty 790606 request for documents Certificate of Svc encl.
SOHINKI, S.M. Branch 3. 79/07/06 4pp.

7908220346 Response to applicant 790628 motion for further procedures requiring TX PIRG to identify authorized representatives & to specify desire to continue participation in proceeding. Motion should be granted.
SOHINKI, S.M. Branch 3. 79/07/06 1p.

--7908220352 Response to ASLB 790625 order & to TX PIRG 790615 amends to Add1 Contentions 28, 35, 38, 40 & 42 Urges rejection of all amended contentions Certificate of Svc encl.
SOHINKI, S.M. Branch 3. 79/07/06 6pp.

7908220327 Petition to intervene as full party in proceeding per 790618 notice. 44FR35062.
HANSON, N. Affiliation Unknown. 79/07/07 1p.

7908150313 Requests halt in facility licensing due to lessons of TMI, radioactive waste disposal problems & proximity to Houston, TX.
DURHAM, N.L. Affiliation Unknown. 79/07/09 1p.

7908150712 Opposes const of nuclear generating station Public Health would be endangered.
WARNER, M.R. Affiliation Unknown. 79/07/09 1p.

7908150019 Requests to intervene re facility const.
MUELLER, E.E. Affiliation Unknown. 79/07/10 1p.

7908170480 Requests to participate in proceedings.
ERICKSON, P. Affiliation Unknown. 79/07/10 1p.

7908220343 Petition to intervene in proceeding as full party per 790618 notice. 44FR35062 Served & ack on 790719.
WEINREB-KUEHM, R. Affiliation Unknown. 79/07/10 1p.

7908140169 Expresses opposition to plant const Requests full party status for future CP hearings.
SCHUESSLER, W.J. Affiliation Unknown. 79/07/11 1p.

7908220355 Petition to intervene as full party in proceedings per 790618 notice. 44FR35062 Served & ack on 790719.
BROWN, S.M. Affiliation Unknown. 79/07/11 1p.

7908220438 Petition to intervene as full party in proceedings per 790618 notice.
BLATT, B. Affiliation Unknown. 79/07/11 1p.

7908220552 Petition to intervene as full party in proceedings per 790618 notice.
CHILUAT, J.E. Affiliation Unknown. 79/07/11 1p.

7908220589 Petition to intervene in proceeding as full participant per 790618 notice.
QINN, B.J. Affiliation Unknown. 79/07/11 1p.

7908220597 Petition to intervene as full party in proceeding per 790618 notice.
KUEHN, R.C. Affiliation Unknown. 79/07/11 1p.

7908230160 Petition to intervene as full party in proceedings per 790618 notice Served & ack on 790719.
AVARROW, J.M. Affiliation Unknown. 79/07/11 1p.

7908220362 Petition to intervene as full party in proceedings per 790618 notice. 44FR35062 Served & ack on 790719.
BRODE, L. Affiliation Unknown. 79/07/12 1p.

7908220365 Memo & order requiring TX PIRG to resubmit answers to applicant first & second sets of interrogatories & to NRC first set of interrogatories.
WOLFE, S.J. Atomic Safety and Licensing Board Panel. 79/07/12 6pp.

7908220368 Order granting applicant 790628 motion. TX PIRG required to state intention to continue full participation & to identify spokesman. TX PIRG response should be filed by 790727.
WOLFE, S.J. Atomic Safety and Licensing Board Panel. 79/07/12 2pp.

7908170348 Requests full party status in CP hearings. Contends present bldg is not designed to resist direct impact of tornado. Requests NRC to deny CP.
DE BREMAECKER, J. Affiliation Unknown. 79/07/13. 2pp.

7908150501 Responses to JF Doherty 790606 third set of interrogatories. Supporting documentation, affidavit & Certificate of Svc encl.
FROCLICH, R.W. Division of Site Safety & Environmental Analysis.
MOON, C.W. Light Water Reactors Branch 4. 79/07/16. 15pp.

7908170534 Requests intervenor status in proceedings. Plant should not be licensed because area is too populated.
LEMMER, R.N. Affiliation Unknown. 79/07/16. 1p.

7908150044 Expresses strong opposition to facility Requsts inclusion in petition to intervene.
ERICKSON, P. Affiliation Unknown. 79/07/17. 1p.

7908170571 Requests intervenor status at public hearing.
FOLEY, H. Affiliation Unknown. 79/07/18. 1p.

7908220349 Petition to intervene as full party in proceedings per 790618 notice. 44FR35062 Served & ack on 790719.
RYAN, D.J. Affiliation Unknown. 79/07/19. 1p.

7908220386 Requests to be named intervenor in facility hearing.
MCGUIRE, S.S. Affiliation Unknown. 79/07/19. 1p.

H. General correspondence

7908150137 Responds to 790426 request for info re BWR feedwater & control rod driver return line nozzle cracking & std design of GE BWRs Lists pertinent documents available for purchase from NTIS.
VARGA, S.A. Light Water Reactors Branch 4. 79/07/11. 3pp.

U. Congressional/Executive Correspondence

7908140506 Requests meeting to discuss timetable for obtaining CP.
PICKLE, J. J. House of Rep., Ways and Means. 79/05/11. 4pp.

DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7906030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908080168 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/20. 2pp.

G. Adjudicatory correspondence

7908080072 Response to TX PIRG 790402 interrogatories. Certificate of Svc encl.
LOWERRE, R. W. Texas, State of. 79/06/27. 7pp.

7908140169 Expresses opposition to plant const. Requests full party status for future CP hearings.
SCHUESSLER, W. J. Affiliation Unknown. 79/07/11. 1p.

U. Congressional/Executive Correspondence

7908140506 Requests meeting to discuss timetable for obtaining CP.
PICKLE, J. J. House of Rep., Ways and Means. 79/05/11. 4pp.

DOCKET STN-50-470 CESSAR SYSTEM 80

K. Utility Final Safety Analysis Report (FSAR) & amends

7908150603 Forwards Amend 4 to predocketing FSAR.
SCHERER, A. E. C-E Power Systems. 79/08/13. 4pp.

--7908150612 Amend 4 to predocketing FSAR.
* C-E Power Systems. 79/08/10. 64pp.

DOCKET 50-471 PILGRIM NUCLEAR POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908130315 Forwards "Rept on Breakwater Damage."
HULMAN, L. G. Hydrology Meteorology Branch. 79/06/25. 2pp.

--7908130324 "Rept on Breakwater Damage." Concentrated localized damage to breakwater is not consistent w/bases on which design was accepted. ASLB should be notified of possible degradation of breakwater.
* Hydrology Meteorology Branch. 79/06/25. 5pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908030168 Notification of 790710 meeting w/util in Bethesda, MD to discuss over-water exclusion area boundary.
LICITRA, E. Light Water Reactors Branch 3. 79/07/09. 3pp.

7908160035 Notification of 790724-25 meeting w/util in Bethesda, MD to discuss impact of TMI task forces on facility.
LICITRA, E. A. Light Water Reactors Branch 4. 79/07/23. 3pp.

7908240630 Forwards NRC direction-dependent accident program in punched card form for use in evaluation of exclusion area offshore direction boundaries. Also forwards card listing, sample run & brief description of program operation. W/o encl.
MARKEE, E. H. Hydrology Meteorology Branch. 79/07/24. 1p.

7908080246 Responds to 790619 ltr to H Denton re NRC 790613 meeting w/util. Apologizes for short notice of meeting. Forwards 790702 meeting summary.
VARGA, S. A. Assistant Director for Light Water Reactors. 79/07/27. 1p.

7908130443 Responds to 790802 request for clarification of 790731 response re monitoring of core conditions by incore thermocouples. IE Bulletin 79-06B, 790724 "Action Plan for Promptly Improving Emergency Preparedness" & NUREG-0578.
CORRY, A. F. Boston Edison Co. NUREG-0578. 79/08/06. 5pp.

7908290480 Responds to NRC 790814 & 22 requests for clarification re 790731 & 0806 ltrs. Forwards replacement to Attachment 1 of 790731 ltr re positions in App A of NUREG-0578. Forwards response to HR Denton 790820 memo re NUREG-0578.
HOWARD, J. E. Boston Edison Co. 79/08/24. 42pp.

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7906110339 Forwards final suppl to environ statement re considerations under Natl Environ Policy Act of 1969 including discussion of problems & objections raised by federal, state & local agencies.
REGAN, W. H. Environmental Projects Branch 2. 79/05/18. 1p.

F. Security, medical, emergency & fire protection plans

7908060238 Confirms util commitment to comply w/requirements of NUREG-0578, IE Bulletin 79-06B & NRC 790724 memo re improvement of emergency preparedness.
LYDON, J. L. Boston Edison Co. 79/07/31. 25pp.

7908090445 Responds to NRC 790720 request re means of informing citizens of need for protective action within 10-mile radius of nuclear emergency.
BUTLER, R. M. Boston Edison Co. 79/08/02. 3pp.

7908280035 Forwards 750831 "Evacuation Analysis for Pilgrim Site," prepared by Environ Research & Technology, Inc.
BUTLER, R. M. Boston Edison Co. 79/08/17. 2pp.

--7908280047 "Evacuation Analysis for Pilgrim Site."
MERLIND, R. J.; MORIYAMA, H. I.; SHERMAN, B. M. Environmental Research & Technology, Inc. 75/08/31. 184pp.

G. Adjudicatory correspondence

7908130064 Responds to telcon request. Forwards NUREG/CR-0250, "Regional Econometric Model for Forecasting Electricity Demand by Sector & by State." W/o encl.
MULKEY, M. E. Branch 2. 79/05/14. 1p.

7908090285 Requests that J Barnet participate in 790524 hearing in Plymouth, MA.
DAWSON, M. H. League of Women Voters of Massachusetts. 79/05/21. 1p.

7908280858 Forwards stipulation by all parties, except applicants, on emergency planning contention. Applicant position re contention is contained in Burt 790614 ltr to BH Smith.
SMITH, B. H. Branch 2. 79/06/18. 1p.

7908080102 Affidavit specifying that deponee is authorized to execute NRC 790625 responses to State of MA interrogatories 14-17 re need for power issue.
CHERN, W. S. Oak Ridge National Laboratory. 79/06/26. 1p.

7908080328 Forwards util objections & motions for protective orders re certain Commonwealth of MA interrogatories concerning need for power issue. Certificate of Svc encl.
LEWALD, G. H. Ropes & Gray. 79/06/26. 1p.

7908270299 Forwards draft "Regional Forecasting Model for Electric Energy, Part I: New England, Mid-Atlantic & South Atlantic Regions." Document is Attachment 2 to NRC 790625 responses to St of MA interrogatories re need for power. W/o encl.
MULKEY, M. E. Branch 2. 79/06/27. 1p.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

7908080315 Response in support of applicant motion to take official notice of certain statutes & court decisions of States of NH, CT, VT & RI. Certificate of Svc encl.
SMITH, B. H. Branch 2. 79/07/02. 3pp.

7908150392 Clarifies withdrawal of 790518 ltr. Withdrawal not intended.
LEWALD, G. H. Ropes & Gray. 79/07/03. 2pp.

7908220546 Forwards OD Parr 790625 memo re breakwater damage, rept re degradation of breakwater & 790608 & 19 site visit rept. No conclusions are modified re breakwaters in NRC safety evaluation rept. W/o encl.
SMITH, B. H. Branch 2. 79/07/05. 2pp.

7908080004 Forwards suppl response to Interrogatory 39, containing missing entries for nuclear fuel data. Certificate of Svc encl.
STOODLEY, D. G. Boston Edison Co. 79/07/11. 1p.

7908090424 Notifies that local newspapers frequently discuss operational problems & radiation releases at plant. Requests stricter supervision & control & suspension of CP. Forwards newspaper articles.
BARTLETT, R. M. Affiliation Unknown. 79/07/14. 4pp.

7908070629 Notifies that C Corkin is no longer employee of MA Atty General Ofc. SM Leonard is now chief of Environ Protection Div & atty of record in const licensing.
BURT, L. Massachusetts, State of. 79/08/03. 1p.

H. General correspondence

7908030210 Forwards Program User's Manual designed to accompany NUREG/CR-0250. NRC 790405 ltr transmitting "NEPOOL Forecast for New England 1979-1989" encl. W/o encl.
MULKEY, M. E. Branch 2. 79/05/16. 1p.

DOCKET 50-472 PILGRIM NUCLEAR POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908300597 Forwards results of petrographic work re concrete samples representative of test cylinders giving low values in compression tests.
BROWN, F. R. Army, Dept. of, Corps of Engineers. 79/07/05. 8pp.

7908270292 Offers no objection to util plan to resume placement of concrete in reactor containment bldg. Decision based on insp monitoring concrete placement activities for safety-related structures during 790305-0514.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/07/12. 2pp.

7908100518 Responds to NA Petrick 790601 ltr to HR Denton. ASME Code Case N-242 acceptable for use on SNUPPS plants, subj to conditions contained in Paragraphs 1.0-4.0 of FSAR.
PARR, O. D. Light Water Reactors Branch 2. 79/07/13. 4pp.

7908080182 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/20. 2pp.

7908140524 Forwards explanation for & correction of errors in 790427 rept re reactor basemat concrete rept forwarded on 790503.
KOESTER, G. L. Kansas Gas & Electric Co. 79/08/09. 4pp.

7908150641 Advises that util intends to replace criteria specified in FES w/limitations set forth in NPDES permit, effective 790831. Change will resolve conflicts & inconsistencies.
KOESTER, G. L. Kansas Gas & Electric Co. 79/08/09. 1p.

G. Adjudicatory correspondence

7908020236 Forwards petition filed on behalf of KS Bldg & Const Trades Council requesting order to show cause why CP should not be revoked.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/06/18. 1p.

--7908020246 Notification of consolidation of petitions from KS citizens & groups opposed to facility. Consideration will be taken under 10CFR2.206. W/notices of petitions in FR, dtd 790201 & 20.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/06/18. 4pp.

7908150298 Renews 790119 request for CP suspension due to QC problems re reactor containment bldg base mat. Discusses seismic character of area. Examination of concrete strength does not consider normal deterioration.
WARD, W. H. Mid-America Coalition for Energy Alternatives. 79/06/29. 6pp.

7908130392 Responds to 790503 request for suspension of const. Request has been consolidated w/similar petitions, per 10CFR2.206.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/07/09. 2pp.

7908130394 Responds to 790520 request for suspension of const. Request has been consolidated w/similar petitions per 10CFR2.206.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/07/09. 2pp.

7908130400 Forwards two ltrs from individuals requesting revocation of CP. Petitions have been consolidated for consideration.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/07/09. 2pp.

7908170522 Denies WH Ward 790611 & 29 petition on behalf of Mid-America Coalition for Energy Alternatives & RP Pollack 781227 petition on behalf of Critical Mass Energy requesting revocation of CP.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/07/12. 8pp.

--7908170530 Summary of concrete problems re reactor containment bldg base mat.
* Region 4, Dallas, Office of the Director. 79/07/18. 3pp.

--7908170535 Forwards "Project Examination of Concrete Samples from Reactor Containment Bldg Base Mat KS," performed by Army Corps of Engineers.
BROWN, F. R. Defense, Dept. of. 79/07/05. 1p.

--7908170483 Forwards evaluation rept re concrete strength of reactor bldg base mat. Base mat concrete strength has not retrogressed, meets original design criteria in PSAR & will withstand specified design loads & load combinations.
VARGA, S. A. Assistant Director for Light Water Reactors. 79/07/10. 7pp.

--7908170539 Petrographic rept, "Project Examination of Concrete Samples from Reactor Containment Bldg Base Mat KS" prepared by Army Corps of Engineers. Concrete samples are of comparable quality to specimens giving normal value.
* Army, Dept. of. 79/07/02. 7pp.

--7908170548 "Evaluation Rept re Concrete Strength of Reactor Bldg Base Mat." Concrete strength has not regressed, strength of base mat meets original design criteria in PSAR & mat will withstand specified design loads.
* Structural Engineering Branch. 79/07/10. 5pp.

7908140223 Notifies of denial of WH Ward 790611 & 29 petitions on behalf of Mid-American Coalition for Energy Alternatives & RP Pollack 781227 petition on behalf of Critical Mass Energy requesting revocation of CP. Forwards decision. W/o encl.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908140261 Notifies of denial of WH Ward 790111 & 0629 petitions on behalf of Mid-America Coalition for Energy Alternatives & RP Pollack 781227 petition on behalf of Critical Mass Energy requesting revocation of CP. Forwards decision. W/o encl.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 2pp.

7908150085 Notifies of denial of WH Ward 790111 & 0629 petition on behalf of Mid-America Coalition for Energy Alternatives RP Pollack 781227 petition for Critical Mass Energy Petitions requested revocation of CP.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908150098 Notifies of denial of WH Ward 790111 & 0629 petitions on behalf of Mid-America Coalition for Energy Alternatives & RP Pollack 781227 petition on behalf of Critical Mass Energy Petitions requested revocation of CP.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908150106 Notifies of denial of WH Ward 790111 & 0629 petitions on behalf of Mid-America Coalition for Energy Alternatives & RP Pollack 781227 petition on behalf of Critical Mass Energy Petitions requested revocation of CP.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908150114 Notifies of denial of WH Ward 790111 & 0629 petitions on behalf of Mid-America Coalition for Energy Alternatives & RP Pollack 781227 petition on behalf of Critical Mass Energy Petitions requested revocation of CP.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908150121 Notifies of denial of WH Ward 790111 & 0629 petitions on behalf of Mid-America Coalition for Energy Alternatives & RP Pollack 781227 petition on behalf of Critical Mass Energy Petitions requested revocation of CP.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908150127 Notifies of denial of WH Ward 790111 & 0629 petitions on behalf of Mid-America Coalition for Energy Alternatives & RP Pollack 781227 petition on behalf of Critical Mass Energy requesting revocation of CP.Forwards decision.W/o encl.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908150156 Notifies of denial of WH Ward 790111 & 0629 petition on behalf of Mid-America Coalition for Energy Alternatives & RP Pollack 781227 petition on behalf of Critical Mass Energy requesting revocation of CP.Forwards decision.W/o encl.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908300345 Notifies of denial of WH Ward 790111 & 0629 petition on behalf of Mid-America Coalition for Energy Alternatives & RP Pollack 781227 petition of behalf of Critical Mass Energy requesting revocation of CP.Forwards decision.W/o encl.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908150451 Requests const on facility be stopped until problem w/cement is corrected.
ELLIS,J.W. Affiliation Unknown. 79/08/06. 1p.

H. General correspondence

7908030581 Ack receipt of 790518 ltr re 790515 meeting in Burlington, KS re concrete trength.Util has implemented approved QA program for const activities.Primary consideration is assurance of min risk to public health & safety.
VASSALLO,D.B. Assistant Director for Light Water Reactors. 79/06/14. 4pp.

7908270534 Denies 790515 petition on behalf of the KS Bldg & Const Trades Council for suspension or revocation of CP.Petition does not establish factual info which would provide basis for proposed action.
STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/07/25. 2pp.

7908300266 Ack receipt of 790702 correspondence re concrete in facility base mat.Forwards 790717 evaluation of concrete.Base mat concrete strength has not retrogressed & meets original design criteria.W/o encl.
VARGA,S.A. Assistant Director for Light Water Reactors. 79/08/02. 1p.

M. Antitrust correspondence

7908080161 Suggests antitrust info for new owners be submitted through util to expedite processing of amend or transfer.
TOALSTON,A. Antitrust & Indemnity Group. 79/07/17. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908010051 Forwards IE Insp Rept 50-482/79-11 on 790430-0501.No noncompliance noted.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/06/14. 2pp.

--7908010060 IE Insp Rept 50-482/79-11 on 790430-0501.No noncompliance noted.Major areas inspected:QA program aspects re control of design & procurement;overall conduct of audit program & document control.
OBERG,C.R., CROSSMAN,W.A. Region 4, Dallas, Office of the Directo MATTIA,J. Region 1, Philadelphia, Office of the Direct 79/06/11. 7pp.

7908150138 Responds to IE Bulletin 79-09 re NRC 790417 ltr.GE Type AK-2 circuit breakers are not included or planned to be included in design of safety-related sys at facility.
KOESTER,G.L. Kansas Gas & Electric Co. 79/06/18. 1p.

7908070526 Responds to IE Bulletins 78-12,12A & 12B.C-E submitted rept containing info requested re atypical weld matl in reactor pressure vessel welds.Westinghouse will inventory archive surveillance weldment matl to be used for verification.
PETRICK,N.A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/06/29. 2pp.

7908080332 Forwards "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts," in response to IE Bulletin 79-02.Response is result of review design & installation practices & procedures for anchor bolts.
PETRICK,N.A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/07/05. 1p.

--7908080352 "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts."
MILLER,C.L., PAGANO,A., PARIKH,K. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/07/31. 27pp.

7908100544 Ack receipt of 790511 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-482/79-04.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/07/16. 1p.

--7908100553 Responds to NRC 790411 ltr re violation noted in IE Insp Rept 50-482/79-04.Corrective actions:QC personnel in concrete lab curing room have been instructed re temp deficiency rept initiation.
KOESTER,G.L. Kansas Gas & Electric Co. 79/05/11. 2pp.

7908010323 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/07/17. 1p.

7908020396 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT,K.V. Region 4, Dallas, Offi of the Director. 79/07/18. 1p.

7908200006 Responds to IE Bulletin 79-11.No Westinghouse Type DB-50 or 75 circuit breakers included in any safety-related applications.
PETRICK,N.A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/07/24. 1p.

7908160121 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/08/06. 1p.

7908290154 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/08/14. 1p.

7908290700 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908010715 Forwards PNO-79-67AX.
SEIDLE,W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/07/20. 1p.

DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments.W/o encl.
VASSALLO,D.B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908080250 Refers to 790422 Columbia,MO Daily Tribune article re evidence of faulty const at facility. Requests NRC supply specific info.
PHILLIP,G.A. Region 3, Chicago, Office of the Director 79/07/12 1p

7908070810 Requests that info submitted re facilities under const include instances of vandalism,demonstrations & threats of any kind.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/13 1p

7908100518 Responds to NA Petrick 790601 ltr to HR Denton. ASME Code Case N-242 acceptable for use on SNUPPS plants,subj to conditions contained in Paragraphs 1.0-4.0 of FSAR.
PARR,O.D. Light Water Reactors Branch 2 79/07/13 4pp

7908080234 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER,J.R. Assistant Director for Site & Safeguards 79/07/20 2pp

9. Inspection reports, IE Bulletins & correspondence

7908020255 Responds to IE Bulletin 79-04 re incorrect weights for swing check valves mfg by Velan Engineering Corp. Submits info re Seismic Category I piping sys w/Velan swing check valves & verification of correct valve weights.
BRYAN,J.K. Union Electric Co. 79/05/29 2pp

7908020261 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. Discusses verification of computer codes used in seismic piping analysis.
BRYAN,J.K. Union Electric Co. 79/05/29 2pp

7908150120 Forwards IE Insp Repts 50-483/79-05 & 50-486/79-02 on 790430-0501. No noncompliance noted.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/25 2pp

--7908150130 IE Insp Repts 50-483/79-05 & 50-486/79-02 on 790430-0501. No noncompliance noted. Major areas inspected: QA program re control of design & procurement & overall conducts of audit program & document control.
SCHWEIBINZ,E.R.; HANSEN,W.A.; KNOP,R.C. Region 3, Chicago, Office of the Director 79/06/21 6pp

7908070526 Responds to IE Bulletins 78-12,12A & 12B. C-E submitted rept containing info requested re atypical weld matl in reactor pressure vessel welds. Westinghouse will inventory archive surveillance weldment matl to be used for verification.
PETRICK,N.A. SNUPPS-Standardized Nuclear Unit Power Plant System 79/06/29 2pp

7908080332 Forwards "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts," in response to IE Bulletin 79-02. Response is result of review design & installation practices & procedures for anchor bolts.
PETRICK,N.A. SNUPPS-Standardized Nuclear Unit Power Plant System 79/07/05 1p

--7908080352 "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts."
MILLER,C.L.; PAGANO,A.; PARIKH,K. Bechtel Power Corp. (subs. of Bechtel Corp.) 79/07/31 27pp

7908130111 Ack receipt of 790627 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-483/79-04.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/18 1p

--7908130118 Responds to NRC 790530 ltr re violation noted in IE Insp Rept 50-483/79-04. Corrective actions, clarifying statement will be made in FSAR.
BRYAN,J.K. Union Electric Co. 79/06/27 3pp

7908020358 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/20 1p

7908200006 Responds to IE Bulletin 79-11. No Westinghouse Type DB-50 or 75 circuit breakers included in any safety-related applications.
PETRICK,N.A. SNUPPS-Standardized Nuclear Unit Power Plant System 79/07/24 1p

7908300429 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908150391 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/08/07 1p

7908300303 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/08/15 1p

S. Reportable occurrences, LERs & related correspondence

7908030365 Ack receipt of 790601 rept on pump anchor belts,per 10CFR50.55. Review will be completed during future insp.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/19 1p

7908200292 Forwards final deficiency rept re defective Type SB12 auxiliary switches.
BRYAN,J.K. Union Electric Co. 79/08/10 1p

--7908200294 Final deficiency rept re defective Type SB12 auxiliary switches on GE metalclad switchgear. "QC Hold" tags placed on all switches. Defective switches will be replaced by GE when proper switches are available.
* Union Electric Co. 79/08/10 6pp

DOCKET S.I-50-484 TYRONE ENERGY PARK, UNIT 1

A. Application/construction stage documents & correspondence

7908150762 Notifies of typographical errors in licensee joint motion for summary disposition of radon issues. Certificate of Svc encl.
SILBERG,J.E. Shaw, Pittman, Potts, & Trowbridge 79/06/05 9pp

7908070802 Requests that info submitted re facilities under const include instances of vandalism,demonstrations & threats of any kind.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/13 1p

7908100518 Responds to NA Petrick 790601 ltr to HR Denton. ASME Code Case N-242 acceptable for use on SNUPPS plants,subj to conditions contained in Paragraphs 1.0-4.0 of FSAR.
PARR,O.D. Light Water Reactors Branch 2 79/07/13 4pp

7908010518 Forwards util 790724 press release re cancellation of project. WI Public Svc Commission 790306 denial of project would prevent completing plant in time to meet projected needs for power.
DIENHART,A.V. Northern States Power Co. 79/07/26 3pp

9. Adjudicatory correspondence

7908270539 Response submitted by intervenor Northern Thunder, Inc to licensees & NRC joint motion for summary disposition of radon issue. Adopts filings made in response to Ecology Action of Oswego & intervenors opposition to TMI.
IHRIG,R. Ihrig, R. 79/06/25 2pp

--7908270545 Notifies of change of address, effective immediately.
IHRIG,R. Ihrig, R. 79/06/26 1p

7908150383 Submits 790710 news release re future of facility. No final decision has been made.
BAXTER,T.A. Shaw, Pittman, Potts, & Trowbridge 79/07/12 2pp

7908240549 Request by Badger Safe Energy Alliance for revocation of CP granted to applicants on 771223. Alliance will be adversely affected by const since all members live within 50 miles of site.
IHRIG,R. Ihrig, R. 79/08/15 5pp

--7908240554 Forwards Northern States Power 790724 news release announcing decision by co-owners to cancel project. Requests termination of proceedings.
BAXTER,T.A. Shaw, Pittman, Potts, & Trowbridge 79/07/25 2pp

--7908240558 Memo informing parties that in absence of objections, ASLAB will issue order terminating proceedings. Copies sent to parties per ALAB-540. Notice of motion for dismissal & order of dismissal. Case 79CV173-civil.
BISHOP,C.J. Atomic Safety and Licensing Appeal Panel 79/07/26 3pp

Q Inspection reports, IE Bulletins & correspondence

7908150160 Forwards IE Insp Rept 50-484/79-01 on 790430-0501 No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/25. 2pp.

--7908150176 IE Insp Rept 50-484/79-01 on 790430-0501 No noncompliance noted. Major areas inspected: QA program re control of design & procurement & overall conduct of audit program & document control.
SCHWEIBINZ, E. R., HANSEN, W. A., KNOP, R. C. Region 3, Chicago, Office of the Director. 79/06/21. 6pp.

7908070526 Responds to IE Bulletins 78-12, 12A & 12B. C-E submitted rept containing info requested re atypical weld matl in reactor pressure vessel welds. Westinghouse will inventory archive surveillance weldment matl to be used for verification.
PETRICK, N. A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/06/29. 2pp.

7908080332 Forwards "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts," in response to IE Bulletin 79-02. Response is result of review design & installation practices & procedures for anchor bolts.
PETRICK, N. A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/07/05. 1p.

--7908080352 "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts."
MILLER, C. L., PAGANO, A., PARIKH, K. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/07/31. 27pp.

7908020343 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908200006 Responds to IE Bulletin 79-11. No Westinghouse Type DB-50 or 75 circuit breakers included in any safety-related applications.
PETRICK, N. A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/07/24. 1p.

7908300422 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908150374 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300287 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

DOCKET STN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT 1

A Application/construction stage documents & correspondence

7908150762 Notifies of typographical errors in licensee joint motion for summary disposition of radon issues. Certificate of Svc encl.
BILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge. 79/06/05. 9pp.

7908100518 Responds to NA Petrick 790601 ltr to HR Denton. ASME Code Case N-242 acceptable for use on SNUPPS plants subj to conditions contained in Paragraphs 1.0 through 4.0 of FSAR.
PARR, O. D. Light Water Reactors Branch 2. 79/07/13. 4pp.

7908310387 Requests reopening of antitrust investigation re CP application. Util refusal to supply power to Massena, NY is coercive attempt to restrain free trade.
WEBER, S. Ecology Action of Oswego. 79/08/25. 1p.

Q Adjudicatory correspondence

7905150034 Forwards unclassified transmittal memo re info potentially relevant to issue of sabotage of spent nuclear fuel. Also discusses rept SAND77-1927, "Transport of Radionuclides in Urban Environs: Working Draft Assessment."
SOHINKI, S. M. Branch 3. 79/04/25. 2pp.

7908290418 Requests antitrust investigation in connection w/facility const be reopened. Special attention should be paid to activities of Niagara Mohawk Power Corp.
WEBER, S. Ecology Action of Oswego. 79/08/25. 3pp.

Q Inspection reports, IE Bulletins & correspondence

7908020127 Forwards IE Insp Rept 50-485/79-01 on 790430-0501. No noncompliance noted.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/06/05. 2pp.

--7908020133 IE Insp Rept 50-485/79-01 on 790430-0501. No noncompliance noted. Major areas inspected: aspects of QA program re control of design & procurement, overall conduct of audit program & document control.
MCGAUGHTY, R., MATTIA, J. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. OBERG, C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/06/04. 7pp.

7908070049 Responds to IE Bulletin 79-09. GE Type AK-2 circuit breakers not used or planned for use in design of safety-related sys.
ARTHUR, J. E. Rochester Gas & Electric Corp. 79/06/15. 1p.

7908070526 Responds to IE Bulletins 78-12, 12A & 12B. C-E submitted rept containing info requested re atypical weld matl in reactor pressure vessel welds. Westinghouse will inventory archive surveillance weldment matl to be used for verification.
PETRICK, N. A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/06/29. 2pp.

7908080332 Forwards "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts," in response to IE Bulletin 79-02. Response is result of review design & installation practices & procedures for anchor bolts.
PETRICK, N. A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/07/05. 1p.

--7908080352 "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts."
MILLER, C. L. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/07/31. 27pp.

7908010527 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060504 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030282 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908200006 Responds to IE Bulletin 79-11. No Westinghouse Type DB-50 or 75 circuit breakers included in any safety-related applications.
PETRICK, N. A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/07/24. 1p.

7908100278 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908280195 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908280352 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310304 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300203 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

DOCKET STN-50-486 CALLOWAY PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments w/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908080290 Refers to 790422 Columbia, MD Daily Tribune article re evidence of faulty const at facility. Requests NRC supply specific info.
PHILLIP, G. A. Region 3, Chicago, Office of the Director. 79/07/12. 1p.

7908070810 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/13. 1p.

7908100518 Responds to NA Petrick 790601 ltr to HR Denton. ASME Code Case N-242 acceptable for use on SNUPPS plants subj to conditions contained in Paragraphs 1.0 through 4.0 of FSAR.
PARR, O. D. Light Water Reactors Branch 2. 79/07/13. 4pp.

7908080234 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/20. 2pp.

Q. Adjudicatory correspondence

7908210324 Forwards request for institution of proceedings to suspend CP, on behalf of MO Public Svc Commission.
HEARNE, T. J. Missouri, State of. 79/08/14. 1p.

--7908210326 Request for suspension of CP granted on 760416. Issuance of order to show cause per 10CFR2.202, is necessary to protect ratepayers. Substantial factual changes have occurred in four yrs. Supporting documentation encl.
HEARNE, T. J. Missouri, State of. 79/08/14. 77pp.

Q. Inspection reports, IE Bulletins & correspondence

7908020255 Responds to IE Bulletin 79-04 re incorrect weights for swing check valves mfg by Velan Engineering Corp. Submits info re Seismic Category I piping sys w/Velan swing check valves & verification of correct valve weights.
BRYAN, J. K. Union Electric Co. 79/05/29. 2pp.

7908020261 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. Discusses verification of computer codes used in seismic piping analysis.
BRYAN, J. K. Union Electric Co. 79/05/29. 2pp.

7908150120 Forwards IE Insp Repts 50-483/79-05 & 50-486/79-02 on 790430-0501. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/25. 2pp.

--7908150130 IE Insp Repts 50-483/79-05 & 50-486/79-02 on 790430-0501. No noncompliance noted. Major areas inspected: QA program re control of design & procurement & overall conducts of audit program & document control.
SCHWEIBINZ, E. R., HANSEN, W. A., KNOP, R. C. Region 3, Chicago, Office of the Director. 79/06/21. 6pp.

7908070526 Responds to IE Bulletins 78-12, 12A & 12B. C-E submitted rept containing info requested re atypical weld matl in reactor pressure vessel welds. Westinghouse will inventory archive surveillance weldment matl to be used for verification.
PETRICK, N. A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/06/29. 2pp.

7908080332 Forwards "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts," in response to IE Bulletin 79-02. Response is result of review design & installation practices & procedures for anchor bolts.
PETRICK, N. A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/07/05. 1p.

--7908080352 "Rept on Pipe-Support Base Plate Designs Using Concrete Expansion Anchor Bolts."
MILLER, C. L. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/07/31. 27pp.

7908020358 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908200006 Responds to IE Bulletin 79-11. No Westinghouse Type DB-50 or 75 circuit breakers included in any safety-related applications.
PETRICK, N. A. SNUPPS-Standardized Nuclear Unit Power Plant System. 79/07/24. 1p.

7908300429 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26. 1p.

7908150391 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07. 1p.

7908300303 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908030365 Ack receipt of 790601 rept on pump anchor belts, per 10CFR50.55. Review will be completed during future insp.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/19. 1p.

DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908140089 Discusses changes in const schedule. Forwards list of info required to assess potential impacts of review on NRC resource needs & priorities.
RUBENSTEIN, L. Operating Reactors Branch 4. 79/07/06. 3pp.

7908060220 Responds to 790706 request re info on potential impacts on NRC resource needs & priorities associated w/decision to delay commercial operation of Cherokee 1 & 2 & postpone financial commitments for Cherokee 3 & Perkins 1, 2 & 3.
DAIL, L. C. Duke Power Co. 79/07/27. 8pp.

Q. Adjudicatory correspondence

7908130319 Suppl to NRC response to Board questions re health & safety aspects omitted from hearing transcript.
* Office of the General Counsel. 79/04/19. 4pp.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

7908300352 Requests issuance of initial decision to provide for CPs in order that planning & scheduling of resources can continue on orderly basis. Notes application is second oldest in NRC history.
PORTER, W. L. Duke Power Co. 79/07/02. 3pp.

7908100189 Responds to 790419 ltr sent to President Carter. Based on FES & rereview of environ impacts, NRC concluded that Perkins site is suitable for proposed power plant.
MULLER, D. R. Division of Site Safety & Environmental Analysis. 79/07/17. 2pp.

--7908100321 Opposes const of (ility for environ reasons.L Kite 790531 response encl.
ALFORD,P R Affiliation Unknown. 79/04/19 4pp

G Inspection reports, IE Bulletins & correspondence

7908070131 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/06/26 2pp.

7908030121 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/13 2pp.

7908230648 Responds to IE Bulletin 79-09.No GE Type AK-2 circuit breakers used or planned for use in safety-related sys.
DAIL,L C Duke Power Co 79/07/16 1p.

7908010407 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/17 2pp.

7908030005 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/18 2pp.

7908130101 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/18 2pp.

7908210114 Responds to IE Bulletin 79-11 No Westinghouse DB-50 or DB-75 circuit breakers are used or planned fo e in safety-related sys.
DAIL,L C Duke Power Co 79/07/19 1p.

7908070730 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/26 2pp.

7908160214 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/27 2pp.

7908220625 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/08/07 3pp.

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D B Assistant Director for Light Water Reactors
79/06/06 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD,H Light Water Reactors Branch 2. 79/07/02 70pp.

7908140089 Discusses changes in const schedule.Forwards list of info required to assess potential impacts of delay on NRC resource needs & priorities.
RUBENSTEIN,L Operating Reactors Branch 4. 79/07/06 3pp.

7908060220 Responds to 790706 request re info on potential impact on NRC resource needs & priorities associated w/decision to delay commercial operation of Cherokee 1 & 2 & postpone financial commitments for Cherokee 3 & Perkins 1,2 & 3.
DAIL,L C Duke Power Co 79/07/27 8pp.

G Adjudicatory correspondence

7908130319 Suppl to NRC response to Board questions re health & safety aspects omitted from hearing transcript.
* Office of the General Counsel 79/04/19 4pp.

7908140048 Board notification.Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment,in response to 790606 request.
BLACK,R L Branch 1 79/06/29 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO,J F Hearings Division 79/03/05 1p.

7908300352 Requests issuance of initial decision to provide for CPs in order that planning & scheduling of resources can continue on orderly basis.Notes application is second oldest in NRC history.
PORTER,W L Duke Power Co. 79/07/02 3pp.

7908100189 Responds to 790419 ltr sent to President Carter.Based on FES & rereview of environ impacts,NRC concluded that Perkins site is suitable for proposed power plant.
MULLER,D R Division of Site Safety & Environmental Analysis
79/07/17 2pp.

--7908100321 Opposes const of facility for environ reasons.L Kite 790531 response encl.
ALFORD,P R Affiliation Unknown. 79/04/19 4pp.

G Inspection reports, IE Bulletins & correspondence

7908070131 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/06/26 2pp.

7908030121 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/13 2pp.

7908230648 Responds to IE Bulletin 79-09.No GE Type AK-2 circuit breakers used or planned for use in safety-related sys.
DAIL,L C Duke Power Co 79/07/16 1p.

7908010407 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/17 2pp.

7908030005 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/18 2pp.

7908130101 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/18 2pp.

7908210114 Responds to IE Bulletin 79-11 No Westinghouse DB-50 or DB-75 circuit breakers are used or planned for use in safety-related sys.
DAIL,L C Duke Power Co 79/07/19 1p.

7908070730 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/26 2pp.

7908160214 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/07/27 2pp.

7908220625 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY,J P Region 2, Atlanta, Office of the Director.
79/08/07 3pp.

DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO,D B Assistant Director for Light Water Reactors
79/06/06 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908140089 Discusses changes in const schedule. Forwards list of info required to assess potential impacts of delay on NRC resource needs & priorities.
RUBENSTEIN, L. Operating Reactors Branch 4. 79/07/06. 3pp.

7908060220 Responds to 790706 request re info on potential impact on NRC resource needs & priorities associated w/decision to delay commercial operation of Cherokee 1 & 2 & postpone financial commitments for Cherokee 3 & Perkins 1, 2 & 3.
DAIL, L. C. Duke Power Co. 79/07/27. 8pp.

Q. Adjudicatory correspondence

7908130319 Suppl to NRC response to Board questions re health & safety aspects omitted from hearing transcript.
* Office of the General Counsel. 79/04/19. 4pp.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

7908300352 Requests issuance of initial decision to provide for CPs in order that planning & scheduling of resources can continue on orderly basis. Notes application is second oldest in NRC history.
PORTER, W. L. Duke Power Co. 79/07/02. 3pp.

7908100189 Responds to 790419 ltr sent to President Carter. Based on FES & rereview of environ impacts, NRC concluded that Perkins site is suitable for proposed power plant.
MULLER, D. R. Division of Site Safety & Environmental Analysis. 79/07/17. 2pp.

--7908100321 Opposes const of facility for environ reasons. L. Kite 790531 response encl.
ALFORD, P. R. Affiliation Unknown. 79/04/19. 4pp.

Q. Inspection reports, IE Bulletins & correspondence

7908070131 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908030121 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908230648 Responds to IE Bulletin 79-09. No GE Type AK-2 circuit breakers used or planned for use in safety-related sys.
DAIL, L. C. Duke Power Co. 79/07/16. 1p.

7908010407 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030005 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130101 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908210114 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 circuit breakers are used or planned for use in safety-related sys.
DAIL, L. C. Duke Power Co. 79/07/19. 1p.

7908070730 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160214 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908220625 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908140089 Discusses changes in const schedule. Forwards list of info required to assess potential impacts of delay on NRC resource needs & priorities.
RUBENSTEIN, L. Operating Reactors Branch 4. 79/07/06. 3pp.

7908270284 Confirms NRC plans & schedule for resumption of work on drains & filters in nuclear svc water dam per 790709 telcon.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/10. 1p.

7908060220 Responds to 790706 request re info on potential impact on NRC resource needs & priorities associated w/decision to delay commercial operation of Cherokee 1 & 2 & postpone financial commitments for Cherokee 3 & Perkins 1, 2 & 3.
DAIL, L. C. Duke Power Co. 79/07/27. 8pp.

Q. Inspection reports, IE Bulletins & correspondence

7908070131 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908240603 Certifies that records search requested by IE Bulletins 79-12, 12A & 12B has been successfully completed. C-E submitted generic rept to NRC on 790608. Licensee satisfied that rept adequately represents data on reactor vessel.
DAIL, L. C. Duke Power Co. 79/07/02. 3pp.

7908160371 Responds to IE Bulletin 79-02, Revision 1, Actions 1-4. Results of cyclic testing re Actions 3-4 will be submitted on 790815.
DAIL, L. C. Duke Power Co. 79/07/05. 3pp.

7908030121 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908230648 Responds to IE Bulletin 79-09. No GE Type AK-2 circuit breakers used or planned for use in safety-related sys.
DAIL, L. C. Duke Power Co. 79/07/16. 1p.

7908010407 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030005 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130101 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908210114 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 circuit breakers are used or planned for use in safety-related sys.
DAIL, L. C. Duke Power Co. 79/07/19. 1p.

7908070730 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160214 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908300470 Ack receipt of IE Insp Repts 50-491/79-11, 50-492/79-11 & 50-493/79-11 on 790705-06. No proprietary info.
DAIL, L. C. Duke Power Co. 79/08/01. 1p.

--7908300480 Forwards IE Insp Repts 50-491/79-11, 50-492/79-11 & 50-493/79-11 on 790705-06. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/19. 2pp.

--7908300487 IE Insp Repts 50-491/79-11, 50-492/79-11 & 50-493/79-11 on 790705-06. No noncompliance noted. Major areas inspected: licensee actions on previous findings.
HARRIS, J. R. ; CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/19. 3pp.

7908300109 Ack receipt of 790720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-491/79-10, 50-492/79-10 & 50-493/79-10.
MURPHY, C. E. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/08/02. 1p.

--7908300119 Responds to NRC 790627 ltr re violations noted in IE Insp Repts 50-491/79-10, 50-492/79-10 & 50-493/79-10. Corrective actions: chimney drain will be removed & verification density testing will be performed.
DAIL, L. C. Duke Power Co. 79/07/20. 4pp.

--7908300129 Forwards IE Insp Repts 50-491/79-10, 50-492/79-10 & 50-493/79-10 on 790612-13 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/27. 2pp.

--7908300136 Notice of violation from insp on 790612-13.
* Region 2, Atlanta, Office of the Director. 79/06/27. 1p.

--7908300149 IE Insp Repts 50-491/79-10, 50-492/79-10 & 50-493/79-10 on 790612-13. Noncompliance noted: placement of dam filter matl of density less than specified.
LENAHAN, J. J. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/27. 3pp.

7908220625 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908140089 Discusses changes in const schedule. Forwards list of info required to assess potential impacts of delay on NRC resource needs & priorities.
RUBENSTEIN, L. Operating Reactors Branch 4. 79/07/06. 3pp.

7908270284 Confirms NRC plans & schedule for resumption of work on drains & filters in nuclear svc water dam per 790709 telcon.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/10. 1p.

7908060220 Responds to 790706 request re info on potential impact on NRC resource needs & priorities associated w/decision to delay commercial operation of Cherokee 1 & 2 & postpone financial commitments for Cherokee 3 & Perkins 1, 2 & 3.
DAIL, L. C. Duke Power Co. 79/07/27. 8pp.

G. Inspection reports, IE Bulletins & correspondence

7908070131 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 2pp.

7908240603 Certifies that records search requested by IE Bulletins 79-12, 12A & 12B has been successfully completed. C-E submitted generic rept to NRC on 790608. Licensee satisfied that rept adequately represents data on reactor vessel.
DAIL, L. C. Duke Power Co. 79/07/02. 3pp.

7908160371 Responds to IE Bulletin 79-02, Revision 1, Actions 1-4. Results of cyclic testing re Actions 3-4 will be submitted on 790815.
DAIL, L. C. Duke Power Co. 79/07/05. 3pp.

7908030121 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/13. 2pp.

7908230648 Responds to IE Bulletin 79-09. No GE Type AK-2 circuit breakers used or planned for use in safety-related sys.
DAIL, L. C. Duke Power Co. 79/07/16. 1p.

7908010407 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 2pp.

7908030005 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908130101 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908210114 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 circuit breakers are used or planned for use in safety-related sys.
DAIL, L. C. Duke Power Co. 79/07/19. 1p.

7908070730 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160214 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 2pp.

7908300470 Ack receipt of IE Insp Repts 50-491/79-11, 50-492/79-11 & 50-493/79-11 on 790705-06. No proprietary info.
DAIL, L. C. Duke Power Co. 79/08/01. 1p.

--7908300480 Forwards IE Insp Repts 50-491/79-11, 50-492/79-11 & 50-493/79-11 on 790705-06. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/19. 2pp.

--7908300487 IE Insp Repts 50-491/79-11, 50-492/79-11 & 50-493/79-11 on 790705-06. No noncompliance noted. Major areas inspected: licensee actions on previous findings.
HARRIS, J. R. ; CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/19. 3pp.

7908300109 Ack receipt of 790720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-491/79-10, 50-492/79-10 & 50-493/79-10.
MURPHY, C. E. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/08/02. 1p.

--7908300119 Responds to NRC 790627 ltr re violations noted in IE Insp Repts 50-491/79-10, 50-492/79-10 & 50-493/79-10. Corrective actions: chimney drain will be removed & verification density testing will be performed.
DAIL, L. C. Duke Power Co. 79/07/20. 4pp.

--7908300129 Forwards IE Insp Repts 50-491/79-10, 50-492/79-10 & 50-493/79-10 on 790612-13 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/27. 2pp.

--7908300136 Notice of violation from insp on 790612-13.
* Region 2, Atlanta, Office of the Director. 79/06/27. 1p.

--7908300149 IE Insp Repts 50-491/79-10, 50-492/79-10 & 50-493/79-10 on 790612-13. Noncompliance noted: placement of dam filter matl of density less than specified.
LENAHAN, J. J. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/27. 3pp.

7908220625 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

A. Application/construction stage documents & correspondence

7908140089 Discusses changes in const schedule. Forwards list of info required to assess potential impacts of delay on NRC resource needs & priorities.
RUBENSTEIN, L. Operating Reactors Branch 4. 79/07/06. 3pp.

7908270284 Confirms NRC plans & schedule for resumption of work on drains & filters in nuclear svc water dam per 790709 telcon.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/10 1p

G. Inspection reports, IE Bulletins & correspondence

7908070131 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/06/26 2pp

7908160371 Responds to IE Bulletin 79-02,Revision 1,Actions 1-4 Results of cyclic testing re Actions 3-4 will be submitted on 790815.
DAIL, L C Duke Power Co 79/07/05 3pp

7908030121 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/13 2pp

7908230648 Responds to IE Bulletin 79-09,No GE Type AK-2 circuit breakers used or planned for use in safety-related sys.
DAIL, L C Duke Power Co 79/07/16 1p

7908010407 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/17 2pp

7908030005 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant,Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908130101 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/18 2pp

7908210114 Responds to IE Bulletin 79-11,No Westinghouse,DB-50 or DB-75 circuit breakers are used or planned for use in safety-related sys.
DAIL, L C Duke Power Co 79/07/19 1p

7908070730 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/26 2pp

7908160214 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/27 2pp

7908300470 Ack receipt of IE Insp Repts 50-491/79-11,50-492/79-11 & 50-493/79-11 on 790705-06.No proprietary info.
DAIL, L C Duke Power Co 79/08/01 1p

--7908300480 Forwards IE Insp Repts 50-491/79-11,50-492/79-11 & 50-493/79-11 on 790705-06.No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/19 2pp

--7908300487 IE Insp Repts 50-491/79-11,50-492/79-11 & 50-493/79-11 on 790705-06.No noncompliance noted.Major areas inspected: licensee actions on previous findings.
HARRIS, J R ; CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/19 3pp

7908300109 Ack receipt of 790720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-491/79-10, 50-492/79-10 & 50-493/79-10.
MURPHY, C E Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/08/02 1p

--7908300119 Responds to NRC 790627 ltr re violations noted in IE Insp Repts 50-491/79-10,50-492/79-10 & 50-493/79-10.Corrective actions chimney drain will be removed & verification density testing will be performed.
DAIL, L C Duke Power Co 79/07/20 4pp

--7908300129 Forwards IE Insp Repts 50-491/79-10,50-492/79-10 & 50-493/79-10 on 790612-13 & notice of violation.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/27 2pp

--7908300136 Notice of violation from insp on 790612-13.
* Region 2, Atlanta, Office of the Director 79/06/27 1p

--7908300149 IE Insp Repts 50-491/79-10,50-492/79-10 & 50-493/79-10 on 790612-13.Noncompliance noted:placement of dam filter matl of density less than specified.
LENAHAN, J J Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/27 3pp

7908220625 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/08/07 3pp

DOCKET STN-50-495 SWESSAR-P1

A. Application/construction stage documents & correspondence

7908010387 Forwards affidavit of distribution of Amend 40 to SWESSAR-P1.
KENNEDY, W J Stone & Webster Engineering Corp 79/07/18 2pp

B. Utility Preliminary Safety Analysis Report, amends

7908230602 Forwards Amend 41 to SWESSAR-P1,revising App 3C in response to NRC comments on Amend 40.
KENNEDY, W J Stone & Webster, Inc 79/08/17 2pp

--7908230605 Amend 41 to S&W Std SAR,SWESSAR-P1.
* Stone & Webster, Inc 79/08/17 6pp

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments.W/o encl.
VASSALLO, D B Assistant Director for Light Water Reactors
79/04/18 3pp

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D B Assistant Director for Light Water Reactors
79/06/06 47pp

7908020259 Confirms NRC understanding of actions & procedures taken re discovery of voids in Unit 1 concrete containment wall, Lift 8 & impact of voids on other safey-related concrete placements on site.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22
2pp

7908170358 Confirms 790628 telcon re reactor containment bldg exterior shell wall concrete placements.Partial release of stop work order will be issued,allowing placement of all safety-related concrete except for exterior shell walls.
TURNER, E A Houston Lighting & Power Co 79/06/28 2pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H Light Water Reactors Branch 2 79/07/02 70pp

7908100520 Forwards request for addl info for review of FSAR re codes & stds.
PARR, O D Light Water Reactors Branch 3 79/07/12 5pp

7908080168 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J R Assistant Director for Site & Safeguards 79/07/20
2pp

7908130544 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation.Model license condition encl.
PARR, O D Light Water Reactors Branch 3 79/08/02 4pp

7908140441 Forwards outline of proposed procedures for performance of soil structure interaction analysis for Category 1 structures.
TURNER, E A Houston Lighting & Power Co 79/08/08 3pp

7908140668 Forwards technical publications re soil structure interaction. Articles provide detailed discussion of analytical methods proposed in performing soil structure interaction studies.
TURNER, E. A. Houston Lighting & Power Co. 79/08/08. 75pp.

G. Adjudicatory correspondence

7908090540 Confirms 790511 telcon. NRC response to applicant brief on appeal from prehearing conference ruling upon intervention petitions reflects understanding that group intends to withdraw petition.
ULMAN, M. B. Operations & Administrative Division. 79/05/14. 1p.

7908070691 Requests addl time for further negotiations among NRC, Citizens for Equitable Utils & Citizens Concerned About Nuclear Power, Inc re language of contentions. Second rept re status of negotiations will be submitted on 790702.
MCGURREN, H. J. Branch 1. 79/05/29. 2pp.

7908080742 Notifies that suppl to petition for to intervene, filed by Citizens for Equitable Utils, is under consideration. Rept to be filed on 790702 by NRC re status of negotiations.
ULMAN, M. B. Operations & Administrative Division. 79/06/19. 1p.

7908080085 Forwards position on revised contentions of Citizens Concerned About Nuclear Power & Citizens for Equitable Utils per NRC 790529 ltr to ASLB & per ASLB 790608 memo & order.
ULMAN, M. B. Operations & Administrative Division. 79/07/02. 2pp.

--7908080088 Statement of position on revised contentions of Citizens Concerned About Nuclear Power & Citizens for Equitable Utils. Certificate of Svc encl.
ULMAN, M. B. Operations & Administrative Division. 79/07/02. 18pp.

7908220334 Ack receipt on behalf of util of NRC statement on Citizens Concerned About Nuclear Power & Citizens for Equitable Utils revised contentions. Agrees w/NRC conclusions & urges issuance of order. Certificate of Svc encl.
NEWMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/10. 8pp.

7908130573 Forwards correspondence & documents, per 790619 ltr & ASLB 790625 order to produce documents to & from experts. NRC will file interrogatory requesting similar documents. W/o encl.
LESSY, R. P. Anti-Trust Division. 79/07/12. 2pp.

H. Antitrust correspondence

7908080525 Submits Apr 1979 discovery rept of Public Utils Board of Brownsville, TX. Responded to two sets of interrogatories & document requests. Certificate of Svc encl.
POIRIER, M. R. Spiegel & McDiarmid. 79/05/14. 6pp.

7908080535 Submits May 1979 discovery rept of Public Utils Board of Brownsville, TX. Worked w/Houston Lighting & Power to provide addl info responsive to util interrogatories & document requests. Certificate of Svc encl.
POIRIER, M. R. Spiegel & McDiarmid. 79/06/08. 6pp.

7908030230 Forwards copies of NRC response to first set of interrogatories & requests for production of documents. Also forwards util supplemental response to NRC first set of interrogatories & requests for production of documents.
BLUME, M. B. Anti-Trust Division. 79/06/29. 1p.

7908130130 TX-LA Cooperative motion for extension until 790806 to respond to TX Utils Generating Co 790618 first set of interrogatories & request for documents. Nature & extent of info requires addl time. Certificate of Svc encl.
RITTS, F. H. Northcutt Ely. 79/07/02. 5pp.

7908200068 Notifies that City of Austin, TX has not initiated nor received any discovery requests during June 1979. Certificate of Svc encl.
BALOUGH, R. C. Austin, TX. 79/07/02. 4pp.

7908220094 Submits rept of discovery activities by South TX Electric Cooperative, Inc & Medina Electric Cooperative for June 1979. Certificate of Svc encl.
JOHN, D. F. Akin, Gump, Hauer & Feld. 79/07/02. 5pp.

7908070074 Submits June 1979 discovery rept. Forwards US District Court for Northern District of TX 790622 order denying West TX Utils & Central Lighting & Power request for stay of injunction pending appeal of Case CA3-76-633-F.
FLYNN, P. G. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/03. 8pp.

7908130176 Progress rept per ASLB 780621 order re June 79 discovery. Major attention was given to implementation of ASLB 790601 order directing Gulf States Utils to comply w/ASLB 790226 subpoenaduces tecum. Certificate of Svc encl.
HARRIS, J. L., CYPHERT, S. B., CLARK, R. H. Justice, Dept. of. 79/07/03. 9pp.

7908140386 Notifies that City of San Antonio has neither initiated nor received any discovery requests during June 1979. Certificate of Svc enc.
WILSON, W. R. Matthews, Nowlin, Macfarlane & Barrett. 79/07/05. 4pp.

7908170336 Submits June 1979 discovery progress rept for City of San Antonio, TX. City neither initiated nor received any discovery requests during June 1979. Certificate of Svc encl.
WILSON, W. R. Matthews, Nowlin, Macfarlane & Barrett. 79/07/05. 4pp.

7908200097 Rept of discovery activities of Public Utils Board of Brownsville, TX for June 1979. Inspected documents at ofc of Central & South West Corp & received subpoena for production of documents to El Paso Electric Co. Certificate of Svc encl.
POIRIER, M. R. Spiegel & McDiarmid. 79/07/05. 6pp.

7908130115 Third supplemental answer to DOJ first set of interrogatories & request for production of documents. Affidavit, Certificate of Svc & supporting documentation encl.
SERATH, E. D. Texas Utilities Co. 79/07/06. 9pp.

7908130188 TX Utils Generating Co opposition to TX LA Electric Cooperative 790702 motion for extension until 790806 re response to TX Utils first set of interrogatories. No objection made to 790724 reply date.
KNOTTS, J. B. Debevoise & Lieberman. WORSHAM, J. I. Worsham, Forsythe & Sampels. 79/07/09. 2pp.

--7908130201 TX Utils Generating Co reply to DOJ & NRC joint motion for partial reconsideration of ASLB 790625 order re discovery & prehearing schedule. Opposes proposed schedule but does not object to dates set forth in order. Certificate of Svc encl.
KNOTTS, J. B. Debevoise & Lieberman. WORSHAM, J. I. Worsham, Forsythe & Sampels. 79/07/09. 5pp.

7908090581 Forwards Lerner testimony. NRC may oppose second deposition, since analysis is only investigative & analytical, not conclusive. W/o encl.
LESSY, R. P. Anti-Trust Division. 79/07/11. 2pp.

7908130215 Motion to compel Houston Lighting & Power to produce certain documents alleged to be priviledged. Certificate of Svc & supporting documentation encl.
HARRIS, J. L., CYPHERT, S. B. Justice, Dept. of. CLARK, R. H. Interior, Dept. of. 79/07/11. 36pp.

7908210612 Forwards Lerner testimony in prior proceedings & list of publications. NRC may oppose second deposition of Lerner if decision to proceed early with 790719 deposition is maintained. W/o encl.
LESSY, R. P. Anti-Trust Division. 79/07/11. 1p.

7908130223 Supplemental request for production of documents by Houston Lighting & Power & TX Utils Generating Co, per ASLB 790625 order. Certificate of Svc encl.
LESSY, R. P. Anti-Trust Division. 79/07/13. 6pp.

7908130240 First supplemental response to TX Utils Generating Co 790209 first set of interrogatories & request for production of documents. Certificate of Svc encl.
CYPHERT, S. B., CLARK, R. H. Justice, Dept. of. 79/07/13. 13pp.

7908130246 First supplemental response to Houston Lighting & Power 790209 second set of interrogatories & requests for production of documents. Certificate of Svc encl.
CYPHERT, S. B., CLARK, R. H. Justice, Dept. of. 79/07/13. 9pp.

7908220092 Forwards return on svc of subpoena issued by ASLB to El Paso Electric Co.
POIRER, M. R. Spiegel & McDiarmid. 79/07/16. 2pp.

7908130261 Motion to quash or modify 790707 subpoena directed to T Sweatman & 790709 subpoena directed to keeper of records of TX Public Util Commission. Certificate of Svc & exhibits encl.
HUGHES, D., FAINTER, J. W. Texas, State of. 79/07/19. 22pp.

7908200269 Stipulation among parties for protective order on behalf of Gulf States Utils, re ASLB 790226 subpoena issued at request of Public Utils Board of City of Brownsville, TX for production of documents. Order granted by ASLB on 790723.
RADER, R. M. Gulf States Utilities Co. BLUME, M. B. Anti-Trust Division. HARRIS, J. L. Justice, Dept. of. 79/07/23. 11pp.

7908200395 TX-LA Electric Cooperative response to TX Utils Generating Co first set of interrogatories & requests for production of documents Supporting documentation & Certificate of Svc encl.
BURCHETTE, W. H. Northcutt Ely. 79/07/23. 41pp.

7908310010 Motion to modify return date of subpoena of C Stover. Requests date be agreed upon by interested parties due to recent developments requiring review by NRC Draft order & Certificate of Svc encl.
LESSY, R. P., BLUME, M. B. Anti-Trust Division. 79/07/23. 6pp.

7908290254 Motion by C Stover of CH Guernsey & Co to modify ASLB subpoena & for issuance of protective order limiting scope of deposition & production of documents Seeks mods to provide time for evaluation Certificate of Svc encl.
O'NEIL, R. A. Wheatley & Wolleson. GALT, J. M. Looney, Nichols, Johnson & Hayes. O'NEIL, R. A. Houston Lighting & Power Co. 79/07/24. 9pp.

G. Inspection reports, IE Bulletins & correspondence

7908170372 Responds to IE Bulletin 79-03. Completion date of insp to determine whether ASME SA-312 Type 304 welded pipe is in use at facilities currently unknown.
TURNER, E. A. Houston Lighting & Power Co. 79/05/14. 1p.

7908090526 Corrects 790524 response to IE Bulletin 79-07. Square root of sum of squares method, not absolute sum combination, was used in analysis of reactor coolant loop. Algebraic technique was not used to combine responses.
TURNER, E. A. Houston Lighting & Power Co. 79/06/15. 1p.

7908090532 Responds to IE Bulletin 79-09. GE AK-2 circuit breakers are not in use at plants.
TURNER, E. A. Houston Lighting & Power Co. 79/06/15. 1p.

7908060465 Ack 790628 ltr re intention to issue partial release from stop work notice to allow placement of all safety-related concrete except containment bldg extension shell walls. Requests util notify NRC if misunderstanding exists.
SEYFRIT, K. V. Region 5, San Francisco, Office of the Director. 79/06/29. 1p.

7908150104 Responds to IE Bulletin 79-02, Revision 1. Only wedge & sleeve type anchors are used at facility. Safety-related piping was analyzed for dynamic loads which proved to be conservative. Detailed response encl.
BARKER, D. G. Houston Lighting & Power Co. 79/07/05. 4pp.

7908310489 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 circuit breakers are in use at facility.
TURNER, E. A. Houston Lighting & Power Co. 79/07/10. 1p.

7908010321 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/07/17. 1p.

7908020395 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/07/18. 1p.

7908160125 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/08/06. 1p.

7908290151 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/08/14. 1p.

7908290698 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908090386 Notifies of merger of problems re fabrication of anchor bolts from improper matl & defects in field-fabricated anchor bolts. One common generic rept will be submitted by 790815, per 10CFR 50.55(e).
TURNER, E. A. Houston Lighting & Power Co. 79/06/05. 2pp.

7908010714 Forwards PNO-79-67AX.
BEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/07/20. 1p.

7908070393 Forwards final deficiency rept re threads in anchor bolts that were fabricated at facility.
OPREA, G. W. Houston Lighting & Power Co. 79/07/30. 2pp.

--7908070400 Final deficiency rept re threads in field-fabricated anchor bolts. Incident determined to be nonreportable, based on site dimensional insp results.
* Houston Lighting & Power Co. 79/07/30. 14pp.

7908230418 Forwards interim deficiency rept re concrete voids behind liner plate in eighth lift on reactor bldg exterior wall.
TURNER, E. A. Houston Lighting & Power Co. 79/06/15. 2pp.

--7908230422 Interim deficiency rept re concrete voids behind liner plate in eighth lift on reactor bldg exterior walls. Addl soundings will be made in three general penetration areas of high stress regions & congestion.
* Houston Lighting & Power Co. 79/08/15. 12pp.

U. Congressional/Executive Correspondence

7908030127 Responds to 790425 ltr which requested info re projects. Forwards NUREG-0523, "Summary of Operating Experience W/Recirculating Steam Generators" listing possible problems w/Westinghouse plants. Describes plant mods & IE program.
HENDRIE, J. M. Commission. 79/06/22. 3pp.

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments. W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020259 Confirms NRC understanding of actions & procedures taken re discovery of voids in Unit 1 concrete containment wall, Lift 8 & impact of voids on other safety-related concrete placements on site.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/06/22. 2pp.

7908170358 Confirms 790628 telcon re reactor containment bldg exterior shell wall concrete placements. Partial release of stop work order will be issued, allowing placement of all safety-related concrete except for exterior shell walls.
TURNER, E. A. Houston Lighting & Power Co. 79/06/28. 2pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908100520 Forwards request for addl info for review of FSAR re codes & stds.
PARR, O. D. Light Water Reactors Branch 3. 79/07/12. 5pp.

7908080168 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/20. 2pp.

7908130544 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
PARR, O. D. Light Water Reactors Branch 3. 79/08/02. 4pp.

7908140441 Forwards outline of proposed procedures for performance of soil structure interaction analysis for Category 1 structures.
TURNER, E. A. Houston Lighting & Power Co. 79/08/08. 3pp.

7908140668 Forwards technical publications re soil structure interaction. Articles provide detailed discussion of analytical methods proposed in performing soil structure interaction studies.
TURNER, E. A. Houston Lighting & Power Co. 79/08/08. 75pp.

G. Adjudicatory correspondence

7908090540 Confirms 790511 telcon. NRC response to applicant brief on appeal from prehearing conference ruling upon intervention petitions reflects understanding that group intends to withdraw petition.
ULMAN, M. B. Operations & Administrative Division. 79/05/14. 1p.

7908070691 Requests addl time for further negotiations among NRC, Citizens for Equitable Utils & Citizens Concerned About Nuclear Power, Inc re language of contentions. Second rept re status of negotiations will be submitted on 790702.
MCGURREN, H. J. Branch 1. 79/05/29. 2pp.

7908080742 Notifies that suppl to petition for to intervene, filed by Citizens for Equitable Utils, is under consideration. Rept to be filed on 790702 by NRC re status of negotiations.
ULMAN, M. B. Operations & Administrative Division. 79/06/19. 1p.

7908080085 Forwards position on revised contentions of Citizens Concerned About Nuclear Power & Citizens for Equitable Utils per NRC 790529 ltr to ASLB & per ASLB 790608 memo & order.
ULMAN, M. B. Operations & Administrative Division. 79/07/02. 2pp.

--7908080088 Statement of position on revised contentions of Citizens Concerned About Nuclear Power & Citizens for Equitable Utils. Certificate of Svc encl.
ULMAN, M. B. Operations & Administrative Division. 79/07/02. 18pp.

7908130188 TX Utils Generating Co opposition to TX LA Electric Cooperative 790702 motion for extension until 790806 re response to TX Utils first set of interrogartories. No objection made to 790724 reply date.
KNOTTS, J. B. Debevoise & Lieberman. 79/07/09. 2pp.

7908220334 Ack receipt on behalf of util of NRC statement on Citizens Concerned About Nuclear Power & Citizens for Equitable Utils revised contentions. Agrees w/NRC conclusions & urges issuance of order. Certificate of Svc encl.
NEWMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/10. 8pp.

7908130573 Forwards correspondence & documents, per 790619 ltr & ASLB 790625 order to produce documents to & from experts. NRC will file interrogatory requesting similar documents W/o encl.
LESSY, R. P. Anti-Trust Division. 79/07/12. 2pp.

M. Antitrust correspondence

7908080525 Submits Apr 1979 discovery rept of Public Utils Board of Brownsville, TX. Responded to two sets of interrogatories & document requests. Certificate of Svc encl.
POIRIER, M. R. Spiegel & McDiarmid. 79/05/14. 6pp.

7908080535 Submits May 1979 discovery rept of Public Utils Board of Brownsville, TX. Worked w/Houston Lighting & Power to provide addl info responsive to util interrogatories & document requests. Certificate of Svc encl.
POIRIER, M. R. Spiegel & McDiarmid. 79/06/08. 6pp.

7908030230 Forwards copies of NRC response to fir[illegible] of interrogatories & requests for production of documents. Also forwards util supplemental response to NRC first set of interrogatories & requests for production of documents.
BLUME, M. B. Anti-Trust Division. 79/06/29. 1p.

7908130130 TX LA Cooperative motion for extension until 790806 to respond to TX Utils Generating Co 790618 first set of interrogatories & request for documents. Nature & extent of info requires addl time. Certificate of Svc encl.
RITTS, F. H. Northcutt Ely. 79/07/02. 5pp.

7908200068 Notifies that City of Austin, TX has not initiated nor received any discovery requests during June 1979. Certificate of Svc encl.
BALOUGH, R. C. Austin, TX. 79/07/02. 4pp.

7908220094 Submits rept of discovery activities by South TX Electric Cooperative, Inc & Medina Electric Cooperative for June 1979. Certificate of Svc encl.
JOHN, D. F. Akin, Gump, Hauer & Feld. 79/07/02. 5pp.

7908070074 Submits June 1979 discovery rept. Forwards US District Court for Northern District of TX 790622 order denying West TX Utils & Central Lighting & Power request for stay of injunction pending appeal of Case CA3-76-633-F.
FLYNN, P. Q. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/03. 8pp.

7908130176 Progress rept, per ASLB 780621 order, re June 1979 discovery. Major attention was given to implementation of ASLB 790601 order directing Gulf States Utils to comply w/ASLB 790226 subpoena duces tecum. Certificate of Svc encl.
HARRIS, J. L. Justice, Dept. of. 79/07/03. 9pp.

7908140386 Notifies that City of San Antonio has neither initiated nor received any discovery requests during June 1979. Certificate of Svc encl.
WILSON, W. R. Matthews, Nowlin, Macfarlane & Barrett. 79/07/05. 4pp.

7908170336 Submits June 1979 discovery progress rept for City of San Antonio, TX. City neither initiated nor received any discovery requests during June 1979. Certificate of Svc encl.
WILSON, W. R. Matthews, Nowlin, Macfarlane & Barrett. 79/07/05. 4pp.

7908200097 Rept of discovery activities by Public Utils Board of Brownsville, TX for June, 1979. Inspected documents at offcs of Central & South West Corp & received subpoena for production of documents to El Paso Electric Co. Certificate of Svc encl.
POIRIER, M. R. Spiegel & McDiarmid. 79/07/05. 6pp.

7908130115 Third supplemental answer to DOJ first set of interrogatories & request for production of documents. Affidavit. Certificate of Svc & supporting documentation encl.
SERATH, E. D. Texas Utilities Co. 79/07/06. 9pp.

7908130201 TX Utils Generating Co reply to DOJ & NRC joint motion for partial reconsideration of ASLB 790625 order re discovery & prehearing schedule. Opposes proposed schedule but does not object to dates set forth in order. Certificate of Svc encl.
KNOTTS, J. B. Debevoise & Lieberman. 79/07/09. 5pp.

7908090581 Forwards Lerner testimony. NRC may oppose second deposition, since analysis is only investigative & analytical, not conclusive. W/o encl.
LESSY, R. P. Anti-Trust Division. 79/07/11. 2pp.

7908130215 Motion to compel Houston Lighting & Power production of certain documents which are believed to be priviledged. Certificate of Svc supporting documentation encl.
HARRIS, J. L. Justice, Dept. of. 79/07/11. 36pp.

7908210612 Forwards Lerner testimony in prior proceedings & list of publications. NRC may oppose second deposition of Lerner if decision to proceed early with 790719 deposition is maintained. W/o encl.
LESSY, R. P. Anti-Trust Division. 79/07/11. 1p.

7908130223 Supplemental request for production of documents by Houston Lighting & Power & TX Utils Generating Co, per ASLB 790625 order. Certificate of Svc encl.
LESSY, R. P. Anti-Trust Division. 79/07/13. 6pp.

7908130240 First supplemental response to TX Utils Generating Co 790209 first set of interrogatories & request for production of documents. Certificate of Svc encl.
CYPHERT, S. B. Justice, Dept. of. 79/07/13. 13pp.

7908130246 First supplemental response to Houston Lighting & Power 790209 second set interrogatories & requests for production of documents. Certificate of Svc encl.
CYPHERT, S. B. Justice, Dept. of. 79/07/13. 9pp.

7908220092 Forwards return on svc of subpoena issued by ASLB to El Paso Electric Co.
POIRER, M. R. Spiegel & McDiarmid. 79/07/16. 2pp.

7908130261 Motion to quash or modify 790707 subpoena directed to T Sweatman & 790709 subpoena directed to keeper of records of TX Public Util Commission. Certificate of Svc & exhibits encl.
HUGHES, D. Texas, State of. 79/07/19. 22pp.

7908200269 Stipulation among parties for protective order in favor of Gulf States Utils, re ASLB 790226 subpoena issued at request of Public Utils Board of City of Brownsville, Tx for production of documents. Order granted by ASLB on 790723.
RADER, R. M. Gulf States Utilities Co. 79/07/23. 11pp.

7908200395 TX-LA Electric Cooperative response to TX Utils Generating Co first set of interrogatories & requests for production of documents. Supporting documentation & Certificate of Svc encl.
BURCHETTE, W. H. Northcutt Ely. 79/07/23. 41pp.

7908310010 Motion to modify return date of subpoena of C Stover. Requests date be agreed upon by interested parties, due to recent developments requiring review by NRC. Draft order & Certificate of Svc encl.
LESSY, R. P. Anti-Trust Division. 79/07/23. 6pp.

7908290254 Motion by C Stover of CH Guernsey & Co to modify ASLB subpoena & for issuance of protective order limiting scope of reposition & production of documents. Seeks mods to provide time for evaluation. Certificate of Svc encl.
O'NEIL, R A. Wheatley & Wolleson. GALT, J M. Looney, Nichols, Johnson & Hayes. O'NEIL, R A. Houston Lighting & Power Co.
7/07/24. 9pp.

G. Inspection reports, IE Bulletins & correspondence

7908170372 Responds to IE Bulletin 79-03. Completion date of insp to determine whether ASME SA-312 Type 304 welded pipe is in use at facilities currently unknown.
TURNER, E A. Houston Lighting & Power Co. 7/05/14. 1p.

7908090526 Corrects 790524 response to IE Bulletin 79-07. Square root of sum of squares method not absolute sum combination, was used in analysis of reactor coolant loop. Algebraic technique was not used to combine responses.
TURNER, E A. Houston Lighting & Power Co. 7/06/15. 1p.

7908090532 Responds to IE Bulletin 79-09. GE AK-2 circuit breakers are not in use at plants.
TURNER, E A. Houston Lighting & Power Co. 7/06/15. 1p.

7908060465 Ack 790628 ltr re intention to issue partial release from stop work notice to allow placement of all safety-related concrete except containment bldg extension shell walls. Requests util notify NRC if misunderstanding exists.
SEYFRIT, K V. Region 5, San Francisco, Office of the Director. 7/06/29. 1p.

7908150104 Responds to IE Bulletin 79-02, Revision 1. Only wedge & sleeve type anchors are used at facility. Safety-related piping was analyzed for dynamic loads which proved to be conservative. Detailed response encl.
BARKER, D G. Houston Lighting & Power Co. 7/07/05. 4pp.

7908310489 Responds to IE Bulletin 79-11. No Westinghouse DB-50 or DB-75 circuit breakers are in use at facility.
TURNER, E A. Houston Lighting & Power Co. 7/07/10. 1p.

7908010321 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
SEYFRIT, K V. Region 4, Dallas, Office of the Director. 7/07/17. 1p.

7908020395 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
SEYFRIT, K V. Region 4, Dallas, Office of the Director. 7/07/18. 1p.

7908160125 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
SEYFRIT, K V. Region 4, Dallas, Office of the Director. 7/08/06. 1p.

7908290151 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
SEYFRIT, K V. Region 4, Dallas, Office of the Director. 7/08/14. 1p.

7908290698 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
SEYFRIT, K V. Region 4, Dallas, Office of the Director. 7/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908090386 Notifies of merger of problems re fabrication of anchor bolts from improper matl & defects in field-fabricated anchor bolts. One common generic rept will be submitted by 790815, per 10CFR 50.55(e).
TURNER, E A. Houston Lighting & Power Co. 7/06/05. 2pp.

7908010714 Forwards PND-79-67AX.
SEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 7/07/20. 1p.

7908070393 Forwards final deficiency rept re threads in anchor bolts that were fabricated at facility.
OPREA, G W. Houston Lighting & Power Co. 7/07/30. 2pp.

--7908070400 Final deficiency rept re threads in field-fabricated anchor bolts. Incident determined to be nonreportable, based on site dimensional insp results.
* Houston Lighting & Power Co. 7/07/30. 14pp.

7908230418 Forwards interim deficiency rept re concrete voids behind liner plate in eighth lift on reactor bldg exterior wall.
TURNER, E A. Houston Lighting & Power Co. 7/08/15. 2pp.

--7908230422 Interim deficiency rept re concrete voids behind liner plate in eighth lift on reactor bldg exterior walls. Addl soundings will be made in three general penetration areas of high stress regions & congestion.
* Houston Lighting & Power Co. 7/08/15. 12pp.

U. Congressional/Executive Correspondence

7908030127 Responds to 790425 ltr which requested info re projects. Forwards NUREG-0523, "Summary of Operating Experience W/Recirculating Steam Generators" listing possible problems w/Westinghouse plants. Describes plant mods & IE program.
HENDRIE, J M. Commission. 7/06/22. 3pp.

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D B. Assistant Director for Light Water Reactors. 7/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 7/07/02. 70pp.

7908090217 Responds to FOIA request for 14 items related to facility. Forwards documents, including insp repts, in response to 3 of 14 items requested & list of addl documents available in LPDR.
FELTON, J M. Division of Rules and Records. 7/07/23. 6pp.

--7908070263 Submits insp items for consideration for forwarding to ASLB. Six items pertain to core lifting, power oscillations, pressurizer level during transients, shutdown margin maint & severe thermal transient.
CRESWELL, J S. Region 3, Chicago, Office of the Director. 7/01/06. 3pp.

M. Antitrust correspondence

7908160240 Discusses antitrust actions against util per City of Cleveland 780104 request re conditions which require licensees to provide wheeling in combined Central Area Power Coordination territories. Forwards order.
DENTON, H R. Office of Nuclear Reactor Regulation. 7/06/25. 2pp.

--7908160257 Order modifying antitrust license Condition 3 re wheeling for & at request of other entities in combined Central Area Power Coordination Group territories.
DENTON, H R. Office of Nuclear Reactor Regulation. 7/06/25. 8pp.

--7908160264 Notice of violation of antitrust license Condition 3 of Licenses NPF-3, CPPR-148 & CPPR-149 & specified const permits re wheeling for & other entities in combined Central Area Power Coordination Group.
DENTON, H R. Office of Nuclear Reactor Regulation. 7/06/25. 4pp.

--7908160272 Specifies recommended changes to svc tariff re transmission of electric power between delivery points of util transmission sys.
DENTON, H R. Office of Nuclear Reactor Regulation. 7/06/25. 6pp.

--7908160281 Unexecuted transmission svc tariff re transmission of electrical power between delivery points of util to, from or between rural electrical cooperatives or municipalities. Agreements encl.
* Office of Nuclear Reactor Regulation. 7/06/25. 11pp.

--7908160297 Unexecuted amended transmission svc tariff re transmission of electrical power between delivery points of util & any electrical entity. Form of svc agreement & Exhibits A & B encl.
* Office of Nuclear Reactor Regulation. 7/06/25. 11pp.

DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D B. Assistant Director for Light Water Reactors. 7/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908090217 Responds to FOIA request for 14 items related to facility. Forwards documents, including insp repts, in response to 3 of 14 items requested & list of addl documents available in LPDR.
FELTON, J. M. Division of Rules and Records. 79/07/23. 6pp.

--7908090263 Submits insp items for consideration for forwarding to ASLB. Six items pertain to core lifting, power oscillations, pressurizer level during transients, shutdown margin maint & severe thermal transient.
CRESWELL, J. S. Region 3, Chicago, Office of the Director. 79/01/08. 3pp.

M. Antitrust correspondence

7908160240 Discusses antitrust actions against util per City of Cleveland 780104 request re conditions which require licensees to provide wheeling in combined Central Area Power Coordination territories. Forwards order.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 2pp.

--7908160257 Order modifying antitrust license Condition 3 re wheeling for & at request fo other entities in combined Central Area Power Coordinati n Group territories.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 8pp.

--7908160264 Notice of violation of antitrust license Condition 3 of Licenses NPF-3, CPPR-148 & CPPR-149 & specified const permits re wheeling for & other entities in combined Central Area Power Coordination Group.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 4pp.

--7908160272 Specifies recommended changes to svc tariff re transmission of electric power between delivery points of util transmission sys.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/25. 8pp.

--7908160281 Unexecuted transmission svc tariff re transmission of electrical power between delivery points of util to, from or between rural electrical cooperatives or municipalities. Agreements encl.
* Office of Nuclear Reactor Regulation. 79/06/25. 11pp.

--7908160297 Unexecuted amended transmission svc tariff re transmission of electrical power between delivery points of util & any electrical entity. Form of svc agreem t & Exhibits A & B encl.
* Office of Nuclear Reactor Regulation. 79/06/25. 11pp.

DOCKET STN-50-502 HAVEN NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908080286 Requests addl info re geology & seismology to complete evaluation of PSAR.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 4pp.

7908270470 Submits responses to requests for addl info re review of PSAR.
FAY, C. W. Wisconsin Electric Power Co. 79/08/15. 8pp.

C. Utility Environmental Report (ER), amends & correspondence

7908173482 Forwards request for addl info re single unit & once-through cooling sys for Amends 13 & 14 to environ rept.
BALLARD, R. L. Environmental Projects Branch 1. 79/07/10. 7pp.

7908210313 Forwards addl info re environ rept in response to 790710 request.
FAY, C. W. Wisconsin Electric Power Co. 79/08/14. 25pp.

7908270417 Comments on Amends 13 & 14 to Environ Rept. Nonradioactive floor & equipment drainage should not be treated at sewage treatment plant. Addl info re toxicity of arsenic & barium should be provided.
DRUCKENMILLER, H. Wisconsin, State of. 79/08/20. 3pp.

G. Adjudicatory correspondence

7908010575 Submits joint applicants response to WI Environ Decade, Inc 790705 ltr supplementing earlier motion to dismiss application or to cease expensing capital carrying charges.
BECKWITH, D. E., WILLIAMS, A. W. Foley & Lardner. 79/07/25. 5pp.

H. General correspondence

7908170300 Approves withholding for public disclosure per 10CFR2.790 Tables 240.2-2 & 240.2-3 re mass & energy release rates & main steam line break.
PARR, O. D. Light Water Reactors Branch 3. 79/07/09. 2pp.

I. Financial information

7908020471 Submits monthly info rept re expenditures & commitments in connection w/proposed Haven plant.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/27. 7pp.

DOCKET STN-50-503 HAVEN NUCLEAR PLANT, UNIT 2

C. Utility Environmental Report (ER), amends & correspondence

7908270417 Comments on Amends 13 & 14 to Environ Rept. Nonradioactive floor & equipment drainage should not be treated at sewage treatment plant. Addl info re toxicity of arsenic & barium should be provided.
DRUCKENMILLER, H. Wisconsin, State of. 79/08/20. 3pp.

G. Adjudicatory correspondence

7908010575 Submits joint applicants response to WI Environ Decade, Inc 790705 ltr supplementing earlier motion to dismiss application or to cease expensing capital carrying charges.
BECKWITH, D. E., WILLIAMS, A. W. Foley & Lardner. 79/07/25. 5pp.

I. Financial information

7908020471 Submits monthly info rept re expenditures & commitments in connection w/proposed Haven plant.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/27. 7pp.

DOCKET STN-50-504 KOSHKONONG NUCLEAR PLANT, UNIT 1

C. Utility Environmental Report (ER), amends & correspondence

7908270417 Comments on Amends 13 & 14 to Environ Rept. Nonradioactive floor & equipment drainage should not be treated at sewage treatment plant. Addl info re toxicity of arsenic & barium should be provided.
DRUCKENMILLER, H. Wisconsin, State of. 79/08/20. 3pp.

G. Adjudicatory correspondence

7908010575 Submits joint applicants response to WI Environ Decade, Inc 790705 ltr supplementing earlier motion to dismiss application or to cease expensing capital carrying charges.
BECKWITH, D. E., WILLIAMS, A. W. Foley & Lardner. 79/07/25. 5pp.

I. Financial information

7908020471 Submits monthly info rept re expenditures & commitments in connection w/proposed Haven plant.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/27. 7pp.

DOCKET STN-50-505 KOSHKONONG NUCLEAR PLANT, UNIT 2

C. Utility Environmental Report (ER), amends & correspondence

7908270417 Comments on Amends 13 & 14 to Environ Rept. Nonradioactive floor & equipment drainage should not be treated at sewage treatment plant. Addl info re toxicity of arsenic & barium should be provided.
DRUCKENMILLER, H. Wisconsin, State of. 79/08/20. 3pp.

7908010575 Submits joint applicants response to WI Environ Decade, Inc 790705 ltr supplementing earlier motion to dismiss application or to cease expensing capital carrying charges.
BECKWITH, D. E. Foley & Lardner 79/07/25 5pp.

I. Financial information

7908020471 Submits monthly info rept re expenditures & commitments in connection w/proposed Haven plant.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/27 7pp.

DOCKET STN-50-506 KOSHKONONG NUCLEAR PLANT, UNIT 3

C. Utility Environmental Report (ER), amends & correspondence

7908270417 Comments on Amends 13 & 14 to Environ Rept Nonradioactive floor & equipment drainage should not be treated at sewage treatment plant Addl info re toxicity of arsenic & barium should be provided.
DRUCKENMILLER, H. Wisconsin, State of 79/08/20 3pp.

G. Adjudicatory correspondence

7908010575 Submits joint applicants response to WI Environ Decade, Inc 790705 ltr supplementing earlier motion to dismiss application or to cease expensing capital carrying charges.
BECKWITH, D. E. Foley & Lardner 79/07/25 5pp.

I. Financial information

7908020471 Submits monthly info rept re expenditures & commitments in connection w/proposed Haven plant.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/27 7pp.

DOCKET STN-50-507 KOSHKONONG NUCLEAR PLANT, UNIT 4

C. Utility Environmental Report (ER), amends & correspondence

7908270417 Comments on Amends 13 & 14 to Environ Rept Nonradioactive floor & equipment drainage should not be treated at sewage treatment plant Addl info re toxicity of arsenic & barium should be provided.
DRUCKENMILLER, H. Wisconsin, State of 79/08/20 3pp.

G. Adjudicatory correspondence

7908010575 Submits joint applicants response to WI Environ Decade, Inc 790705 ltr supplementing earlier motion to dismiss application or to cease expensing capital carrying charges.
BECKWITH, D. E. Foley & Lardner 79/07/25 5pp.

I. Financial information

7908020471 Submits monthly info rept re expenditures & commitments in connection w/proposed Haven plant.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/27 7pp.

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp.

7908080237 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/20 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908280387 Responds to IE Bulletin 79-03 No welded pipe mfg by Youngstown Welding & Engineering Co in use or planned for use in safety-related sys.
RENBERGER, D. L. Washington Public Power Supply System 79/06/06 1p.

7908130441 Responds to IE Bulletin 79-07 Requests extension until 790630 for remainder of response Methods of spectrum model seismic analysis of safety-related piping were not & will not be used in facility.
RENBERGER, D. L. Washington Public Power Supply System 79/06/12 3pp.

7908070714 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers used or planned for use in safety-related sys at facility.
RENBERGER, D. L. Washington Public Power Supply System 79/06/25 1p.

7908130335 Ack receipt of 790530 ltr informing NRC of steps taken to correct violations noted in IE insp on 781113-1229.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/06/26 1p.

--7908130340 Responds to NRC 790122 ltr re violations noted in IE Insp Repts 50-508/79 & 50-509/79 Corrective actions: all Pittsburgh Testing Lab personel certified, test equipment recalibr & all records revised.
RENBERGER, D. L. Washington Public Power Supply System 79/05/30 3pp.

7908160015 Modifies 790606 response to IE Bulletin 79-03 re longitudinal weld defects Discusses use of gas strippers & regenerative heat exchangers mfg by Youngstown Welding & Engineering Co.
RENBERGER, D. L. Washington Public Power Supply System 79/07/10 2pp.

7908010397 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/17 1p.

7908020411 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/18 1p.

7908020509 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/18 1p.

7908060166 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/26 1p.

7908210472 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action Required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/07 1p.

7908280399 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director 79/08/13 1p.

7908310162 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/14 1p.

7908300256 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/15 1p.

S. Reportable occurrences, LERs & related correspondence

7908020537 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/10 1p.

7908020033 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/17 1p.

DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp.

7908080237 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/20 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908280387 Responds to IE Bulletin 79-03. No welded pipe mfg by Youngstown Welding & Engineering Co in use or planned for use in safety-related sys.
RENENBERGER, D. Washington Public Power Supply System 79/06/06 1p.

7908130441 Responds to IE Bulletin 79-07. Requests extension until 790630 for remainder of response. Methods of spectrum model seismic analysis of safety-related piping were not & will not be used in facility.
RENBERGER, D. L. Washington Public Power Supply System 79/06/12 3pp.

7908070714 Responds to IE Bulletin 79-09. No GE Type AK-2 circuit breakers used or planned for use in safety-related sys at facility.
RENBERGER, D. L. Washington Public Power Supply System 79/06/25 1p.

7908130335 Ack receipt of 790530 ltr informing NRC of steps taken to correct violations noted in IE insp on 781113-1229.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/06/26 1p.

--7908130346 Responds to NRC 790122 ltr re violations noted in IE Insp Repts 50-508/79 & 50-509/79. Corrective actions all Pittsburgh Testing Lab personel certified, test equipment recalibr & all records revised.
RENBERGER, D. L. Washington Public Power Supply System 79/05/30 3pp.

7908160015 Modifies 790606 response to IE Bulletin 79-03 re longitudinal weld defects. Discusses use of gas strippers & regenerative heat exchangers mfg by Youngstown Welding & Engineering Co.
RENBERGER, D. L. Washington Public Power Supply System 79/07/10 2pp.

7908010397 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/17 1p.

7908020411 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/18 1p.

7908020509 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/18 1p.

7908060166 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/26 1p.

7908210472 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action Required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/07 1p.

7908280399 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director 79/08/13 1p.

7908310162 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/14 1p.

7908300256 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/15 1p.

S. Reportable occurrences, LERs & related correspondence

7908020537 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/10 1p.

7908020033 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/17 1p.

DOCKET 50-510 BLUE HILLS STATION, UNIT 1

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7908030185 Forwards errata to plant FES (NUREG-0449) sent by NRC on 780717.
BALLARD, R. L. Environmental Projects Branch 1 79/07/03 2pp.

Q. Adjudicatory correspondence

7905150697 Forwards notice of appearance on behalf of NRC. C Woodhead should continue to be on svc list.
BRENNER, L. Branch 3 79/04/24 2pp.

7908010486 Opposes proposed const as threat to people in county due to environ contamination.
HINSON, E. W. Affiliation Unknown 79/04/25 1p.

7905240754 Forwards professional qualifications of NRC panel of witnesses to testify at 790509 hearing in Jasper, TX.
WOODHEAD, C. P. Branch 3 79/04/27 8pp.

7907260001 Forwards State of TX response to Gulf States Utils proposed findings of fact & conclusions of law in form of partial initial decision.
LOWERRE, R. W. Texas, State of 79/06/20 1p.

--7907260002 State of TX response to Gulf States Utils proposed findings of fact & conclusions of law in form of partial initial decision. No objections to proposals & no intention to submit alternative proposals. Certificate of Svc encl.
LOWERRE, R. W. Texas, State of 79/06/20 2pp.

7908080065 Proposed findings of fact, conclusions of law & proposed order in form of partial initial decision. Applicant 790607 proposed findings of fact & conclusions of law are adopted w/exceptions & mods. Certificate of Svc encl.
WOODHEAD, C. P. Branch 3 79/07/05 16pp.

7908170151 Ack receipt of 790425 ltr opposing const. Licensing board decision on environ effects & proposed site suitability expected soon. Safety matters re plant design will be considered w/CP application.
BALLARD, R. L. Environmental Projects Branch 1 79/07/30 1p.

DOCKET 50-511 BLUE HILLS STATION, UNIT 2

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7908030185 Forwards errata to plant FES (NUREG-0449) sent by NRC on 780717.
BALLARD, R. L. Environmental Projects Branch 1 79/07/03 2pp.

Q. Adjudicatory correspondence

7905150697 Forwards notice of appearance on behalf of NRC. C Woodhead should continue to be on svc list.
BRENNER, L. Branch 3 79/04/24 2pp.

7908010486 Opposes proposed const as threat to people in county due to environ contamination.
HINSON, E. W. Affiliation Unknown 79/04/25 1p.

7905240754 Forwards professional qualifications of NRC panel of witnesses to testify at 790509 hearing in Jasper, TX.
WOODHEAD, C. P. Branch 3 79/04/27 8pp.

7907260001 Forwards State of TX response to Gulf States Utils proposed findings of fact & conclusions of law in form of partial initial decision.
LOWERRE, R. W. Texas, State of 79/06/20 1p.

--7907260002 State of TX response to Gulf States Utils proposed findings of fact & conclusions of law in form of partial initial decision. No objections to proposals & no intention to submit alternative proposals. Certificate of Svc encl.
LOWERRE, R. W. Texas, State of 79/06/20 2pp.

7908080065 Proposed findings of fact, conclusions of law & proposed order in form of partial initial decision. Applicant 790607 proposed findings of fact & conclusions of law are adopted w/exceptions & mods. Certificate of Svc encl.
WOODHEAD, C. P. Branch 3 79/07/05 16pp.

7908170151 Ack receipt of 790425 ltr opposing const.Licensing board decision on environ effects & proposed site suitability expected soon.Safety matters re plant design will be considered w/CP application.
BALLARD, R. L. Environmental Projects Branch 1 79/07/30 1p.

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

A Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments.W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp.

7908080192 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
PARR, O. D. Light Water Reactors Branch 3 79/07/11 2pp.

7908080237 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/20 2pp.

O Inspection reports, IE Bulletins & correspondence

7908280387 Responds to IE Bulletin 79-03.No welded pipe mfg by Youngstown Welding & Engineering Co in use or planned for use in safety-related sys.
RENBERGER, D. Washington Public Power Supply System 79/06/06 1p.

7908130431 Forwards response to IE Bulletin 79-07.None of methods for analyzing safety-related piping in bulletin are employed. Lists computer programs utilized.
RENBERGER, D. L. Washington Public Power Supply System 79/06/12 6pp.

7908230053 Forwards IE Insp Repts 50-460/79-06 & 50-513/79-06 on 790424-27 & notice of deviation.
SPENCER, Q. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/22 2pp.

--7908230058 Notice of deviation from insp on 790424-27.
* Region 5, San Francisco, Office of the Director 79/06/22 1p.

--7908230061 IE Ins. Repts 50-460/79-06 & 50-513/79-06 on 790424-27. Noncompliance noted one weld on containment equipment & floor drain pipe spool did not meet ASME III Class 3 requirements.
ALBERT, W. G. ; ECKHARDT, J. H. Region 5, San Francisco, Office of the Director DODDS, R. T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/14 6pp.

--7908230064 Ack receipt of 790719 ltr re steps taken to correct deviation noted in IE Insp Repts 50-460/79-06 & 50-513/79-06.Corrective actions will be verified during future insp.
SPENCER, Q. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/08/01 1p.

--7908230067 Forwards response to 790622 ltr re item of deviation noted in IE Insp Repts 50-460/79-06 & 50-513/79-06.Corrective actions weld & spool piece repaired & deviation documented.
KENBERGER, D. L. Washington Public Power Supply System 79/07/19 2pp.

7908070725 Responds to IE Bulletin 79-09.No GE Type AK-2 circuit breakers used or planned for use in safety-related sys at facility.
RENBERGER, D. L. Washington Public Power Supply System 79/06/25 1p.

7908010397 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/17 1p.

7908020411 Forwards corrected copy of IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/18 1p.

7908020509 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/18 1p.

7908060166 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/26 1p.

7908210472 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action Required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/07 1p.

7908280399 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director 79/08/13 1p.

7908310162 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/14 1p.

7908300256 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/15 1p.

S Reportable occurrences, LERs & related correspondence

7908020537 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/10 1p.

7908020033 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/07/17 1p.

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

Q Adjudicatory correspondence

7908140048 Board notification.Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1 79/06/29 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division 79/03/05 1p.

P Operating license stage documents & correspondence

7908220509 Forwards ACRS questions for facility.Open items remain.
VARGA, S. A. Light Water Reactors Branch 4 77/11/15 1p.

--7908220514 Requests addl info for ACRS review.
* Light Water Reactors Branch 4 77/11/07 13pp.

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda,MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda,MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

G. Adjudicatory correspondence

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

P. Operating license stage documents & correspondence

7908220509 Forwards ACRS questions for facility. Open items remain.
VARGA, S. A. Light Water Reactors Branch 4. 77/11/15. 1p.

--7908220514 Requests addl info for ACRS review.
* Light Water Reactors Branch 4. 77/11/07. 13pp.

DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908080190 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/19. 2pp.

F. Security, medical, emergency & fire protection plans

7908280579 Informs that no security training & qualification program is presently being developed. Due to current project schedule, program would be premature.
PLASKON, R. E. Long Island Lighting Co. 79/08/18. 1p.

G. Adjudicatory correspondence

7908020270 Responds to 790425 ltr re distribution of Board notification to NY Siting Board. Since NY was not on svc list, copies were not sent. Fifteen copies encl.
BORDENICK, B. M. Branch 4. 79/05/28. 2pp.

7908010271 Ack receipt of Resolution 474, adopted by County Legislature of Suffolk County, NY in opposition to plant const.
RYAN, R. G. Office of State Programs. 79/06/14. 1p.

--7908010276 Forwards Resolution 474, adopted by County Legislature of Suffolk County, NY in opposition to plant const.
ROGERS, W. H. Suffolk County, NY. 79/05/28. 1p.

--7908010287 Resolution 474, opposing const of facilities.
MRAZEK, DEVINE, FOLEY Suffolk County, NY. 79/05/08. 1p.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

7908300073 Discusses ASLAB 790607 approval of NRC request for indefinite extension to respond to Suffolk County motion to file supplemental brief. Status rept will be filed 790806. Certificate of Svc encl.
BORDENICK, B. M. Branch 4. 79/07/06. 3pp.

G. Inspection reports, IE Bulletins & correspondence

7908080484 Responds to IE Bulletin 79-04. No purchase orders issued for swing check valves. QA program vendors w/acceptable method for determining & verifying correct valve weights will be selected.
PLASKON, R. E. Long Island Lighting Co. 79/05/25. 1p.

7908070784 Submits response to IE Bulletin 79-02, Revision 1, re plant design. Info pertains to project design procedure & spec for drilled-in anchors, cyclic loadings & pipe support base plate configurations.
PLASKON, R. E. Long Island Lighting Co. 79/07/06. 3pp.

7908010428 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sy. at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/17. 1p.

7908060378 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908030247 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/19. 1p.

7908290732 Responds to IE Bulletin 79-11. Purchase orders for circuit breakers in safety-related sys not placed. Particular circuit breakers to be used are unknown.
PLASKON, R. E. Long Island Lighting Co. 79/07/20. 1p.

7908100232 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/26. 1p.

7908280096 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/07. 1p.

7908280281 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/13. 1p.

7908310311 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/14. 1p.

7908300132 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/15. 1p.

DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908080190 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/19. 2pp.

F. Security, medical, emergency & fire protection plans

7908280579 Informs that no security training & qualification program is presently being developed. Due to current project schedule, program would be premature.
PLASKON, R. E. Long Island Lighting Co. 79/08/18. 1p.

G. Adjudicatory correspondence

7908020270 Responds to 790425 ltr re distribution of Board notification to NY Siting Board. Since NY was not on svc list, copies were not sent. Fifteen copies encl.
BORDENICK, B. M. Branch 4. 79/05/28. 2pp.

7908010271 Ack receipt of Resolution 474, adopted by County Legislature of Suffolk County, NY in opposition to plant const.
RYAN, R. G. Office of State Programs. 79/06/14. 1p.

--7908010276 Forwards Resolution 474, adopted by County Legislature of Suffolk County, NY in opposition to plant const.
ROGERS, W. H. Suffolk County, NY. 79/05/28. 1p.

--7908010287 Resolution 474, opposing const of facilities.
MRAZEK, DEVINE, FOLEY Suffolk County, NY. 79/05/08. 1p.

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division 79/03/05 1p.

7908300073 Discusses ASLAB 790607 approval of NRC request for indefinite extension to respond to Suffolk County motion to file supplemental brief. Status rept will be filed 790806. Certificate of Svc encl.
BORDENICK, B. M. Branch 4 79/07/06 3pp.

G. Inspection reports, IE Bulletins & correspondence

7908080484 Responds to IE Bulletin 79-04. No purchase orders issued for swing check valves. QA program vendors w/acceptable method for determining & verifying correct valve weights will be selected.
PLASKON, R. E. Long Island Lighting Co. 79/05/25 1p.

7908070784 Submits response to IE Bulletin 79-02, Revision 1, re plant design. Info pertains to project design procedure & spec for drilled-in anchors, cyclic loadings & pipe support base plate configurations.
PLASKON, R. E. Long Island Lighting Co. 79/07/06 3pp.

7908010428 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/17 1p.

7908060378 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18. 1p.

7908030247 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/19. 1p.

7908290732 Responds to IE Bulletin 79-11. Purchase orders for circuit breakers in safety-related sys not placed. Particular circuit breakers to be used are unknown.
PLASKON, R. E. Long Island Lighting Co. 79/07/20 1p.

7908100232 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/26. 1p.

7908280096 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/07. 1p.

7908280281 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/13. 1p.

7908310311 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/14. 1p.

7908300132 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/15. 1p.

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908150351 Summary of 790619 meeting w/TVA in Bethesda, MD re code testing requirements for piping embedded in concrete.
BENEDICT, R. A. Light Water Reactors Branch 2 79/07/13. 11pp.

7908130103 Discusses program to upgrade bases section of STS. Resulting Class I, II & III amends will be fee exempt.
BAER, R. L. Light Water Reactors Branch 2 79/07/18 2pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L. M. Tennessee Valley Authority 79/08/23 2pp.

F. Security, medical, emergency & fire protection plans

7908200109 Provides info on safety & emergency planning requirements, in response to 790427 ltr.
RYAN, R. G. Office of State Programs 79/05/23. 2pp.

--7908200115 Requests info re safety & emergency planning requirements.
STEWART, J. H. Tennessee State Univ. 79/04/27 1p.

G. Adjudicatory correspondence

7908290722 Decision ALAB-554. Vacates ASLB granting of licensee motion for summary disposition. Grants judgment to licensee re operational effects on music. Defers decision re effects of const activities.
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 79/07/11. 14pp.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L. M. Tennessee Valley Authority 79/08/07 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority 79/05/29. 3pp.

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09 re GE Type AK-2 circuit breakers.
GILLELAND, J. E. Tennessee Valley Authority 79/06/20. 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/06/26. 3pp.

7908290197 Forwards IE Insp Repts 50-518/79-11, 50-519/79-11, 50-520/79-11 & 50-521/79-11 on 790524-26, 29-30 & 0601-02. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/29. 2pp.

--7908290208 IE Insp Repts 50-518/79-11, 50-519/79-11, 50-520/79-11 & 50-521/79-11 on 790524-26, 29-30 & 0601-02. No noncompliance noted. Major areas inspected: concrete, spray ponds, containments & project status.
SWAN, W. B. Region 2, Atlanta, Office of the Director.
CANTRELL, F. S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/28. 6pp.

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L. M. Tennessee Valley Authority 79/07/05. 40pp.

7908080734 Forwards supplemental response to IE Bulletin 78-12B concerning atypical weld matl in reactor pressure vessel welds. Final responses will be provided after util reviews CB&I & C-E generic repts.
MILLS, L. M. Tennessee Valley Authority 79/07/09. 2pp.

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellafonte to be submitted before 790914. Pipe stools not used.
MILLS, L. M. Tennessee Valley Authority 79/07/13. 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/18. 2pp.

7908080054 Notifies that written responses to IZ Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/18 3pp

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or plannned for use.
MILLS, L. M. Tennessee Valley Authority 79/07/20 1p

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/26 2pp

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/27 3pp

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L. M. Tennessee Valley Authority 79/07/27 1p

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/08/07 3pp

S. Reportable occurrences, LERs & related correspondence

7908140672 Forwards first interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Final rept to be forwarded by 791001.
MILLS, L. M. Tennessee Valley Authority 79/07/05 1p

--7908140684 First interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Cracks observed near weld joints. Investigation & repairs underway.
* Tennessee Valley Authority 79/07/05 3pp

7908230384 Forwards deficiency rept re unacceptable QA documentation for Glazer steel matl.
MILLS, L. M. Tennessee Valley Authority 79/08/15 1p

--7908230402 Interim deficiency rept re questionable QA documentation on steel received from Glazer Steel & Aluminum. Glazer removed from list of approved suppliers of certified matl. Final rept anticipated by 800216.
* Tennessee Valley Authority 79/08/15 2pp

7908230451 Forwards final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear.
MILLS, L. M. Tennessee Valley Authority 79/08/16 1p

--7908230460 Final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear. Caused by worn die used to form holes in contact arms of switches. Elongated holes resulted in improper contact wipe.
* Tennessee Valley Authority 79/08/16 2pp

7908230589 Forwards final deficiency rept re use of non-ASME components on primary containment personnel access airlocks.
MILLS, L. M. Tennessee Valley Authority 79/08/16 1p

--7908230596 Final rept re use of non-ASME components on primary containment personnel access airlocks. Caused by vendor interpretation of GE Specification 300-13. Airlock sys will be redesigned & refabricated.
* Tennessee Valley Authority 79/08/16 2pp

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908150351 Summary of 790619 meeting w/TVA in Bethesda, MD re code testing requirements for piping embedded in concrete.
BENEDICT, R. A. Light Water Reactors Branch 2 79/07/13 11pp

7908130103 Discusses program to upgrade bases section of STS. Resulting Class I, II & III amends will be fee exempt.
BAER, R. L. Light Water Reactors Branch 2 79/07/18 2pp

7908300688 Submits revised fuel load schedule for All TVA plants under const.
MILLS, L. M. Tennessee Valley Authority 79/08/23 2pp

F. Security, medical, emergency & fire protection plans

7908200109 Provides info on safety & emergency planning requirements, in response to 790427 ltr.
RYAN, R. G. Office of State Programs 79/05/23 2pp

--7908200115 Requests info re safety & emergency planning requirements.
STEWART, J. H. Tennessee State Univ. 79/04/27 1p

G. Adjudicatory correspondence

7908290722 Decision ALAB-554. Vacates ASLB granting of licensee motion for summary disposition. Grants judgment to licensee re operational effects on mussels. Defers decision re effects of const activities.
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 79/08/11 14pp

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Dfc of Power.
MILLS, L. M. Tennessee Valley Authority 79/08/07 2pp

I. Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept dtd Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority 79/07/09 3pp

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09 re GE Type AK circuit breakers.
GILLELAND, J. E. Tennessee Valley Authority 79/06/20 4pp

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action require.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/06/26 3pp

7908290197 Forwards IE Insp Repts 50-518/79-11, 50-519/79-11, 50-520/79-11 & 50-521/79-11 on 790524-26, 29-30 & 0601-02. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/29 2pp

--7908290208 IE Insp Repts 50-518/79-11, 50-519/79-11, 50-520/79-11 & 50-521/79-11 on 790524-26, 29-30 & 0601-02. No noncompliance noted. Major areas inspected: concrete, spray ponds, containments & project status.
SWAN, W. B. Region 2, Atlanta, Office of the Director
CANTRELL, F. S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/28 6pp

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L. M. Tennessee Valley Authority 79/07/05 40pp

7908080734 Forwards supplemental response to IE Bulletin 78-12B concerning atypical weld matl in reactor pressure vessel welds. Final responses will be provided after util reviews CB&I & C-E generic repts.
MILLS, L. M. Tennessee Valley Authority 79/07/09 2pp

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellafonte to be submitted before 790914. Pipe stools not used.
MILLS, L. M. Tennessee Valley Authority 79/07/13 2pp

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/17 3pp

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/07/18 3pp

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/18 3pp.

7908170517 Responds to IE Bulletin 79-11 No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L.M. Tennessee Valley Authority 79/07/20 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/26 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/27 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete Unable to meet response date of 790801 Will submit response before 790815.
MILLS, L.M. Tennessee Valley Authority 79/07/27 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/08/07 3pp.

S. Reportable occurrences, LERs & related correspondence

7908140672 Forwards first interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal Final rept to be forwarded by 791001.
MILLS, L.M. Tennessee Valley Authority 79/07/05 1p.

--7908140684 First interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal Cracks observed near weld joints. Investigation & repairs underway.
* Tennessee Valley Authority 79/07/05 3pp.

7908230384 Forwards deficiency rept re unacceptable QA documentation for Glazer steel matl.
MILLS, L.M. Tennessee Valley Authority 79/08/15 1p.

--7908230402 Interim defi ncy rept re questionable QA documentation on steel received from Glazer Steel & Aluminum Glazer removed from list of approv suppliers of certified matl Final rept anticipated by 800216.
* Tennessee Valley Authority 79/08/15 2pp.

7908230451 Forwards final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear.
MILLS, L.M. Tennessee Valley Authority 79/08/16 1p.

--7908230460 Final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear Caused by worn die used to form holes in contact arms of switches Elongated holes resulted in improper contact wipe.
* Tennessee Valley Authority 79/08/16 2pp.

7908230589 Forwards final deficiency rept re use of non-ASME components on primary containment personnel access airlocks.
MILLS, L.M. Tennessee Valley Authority 79/08/16 1p.

--7908230596 Final rept re use of non-ASME components on primary containment personnel access airlocks Caused by vendor interpretation of GE Specification 300-13 Airlock sys will be redesigned & refabricated.
* Tennessee Valley Authority 79/08/16 2pp.

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

A. Application/construction stage documents & correspondence

7908150351 Summary of 790619 meeting w/TVA in Bethesda, MD re code testing requirements for piping embedded in concrete.
BENEDICT, R.A. Light Water Reactors Branch 2 79/07/13 11pp.

7908130103 Discusses program to upgrade bases section of STS Resulting Class I, II & III amends will be fee exempt.
BAER, R.L. Light Water Reactors Branch 2 79/07/18 2pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L.M. Tennessee Valley Authority 79/08/23 2pp.

F. Security, medical, emergency & fire protection plans

7908200109 Provides info on safety & emergency planning requirements, in response to 790427 ltr.
RYAN, R.Q. Office of State Programs 79/05/23 2pp.

--7908200115 Requests info re safety & emergency planning requirements.
STEWART, J.H. Tennessee State Univ 79/04/27 1p.

Q. Adjudicatory correspondence

7908290722 Decision ALAB-554 Vacates ASLB granting of Licensee motion for summary disposition Grants judgment to licensee re operational effects on mussels Defers decision re effects of const activities.
BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 79/07/11 14pp.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L.M. Tennessee Valley Authority 79/08/07 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts Westinghouse generic rept due Oct 1979.
GILLELAND, J.E. Tennessee Valley Authority 79/05/29 3pp.

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09 re GE Type AK-2 circuit breakers.
GILLELAND, J.E. Tennessee Valley Authority 79/06/20 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/06/26 3pp.

7908290197 Forwards IE Insp Repts 50-518/79-11, 50-519/79-11, 50-520/79-11 & 50-521/79-11 on 790524-26, 29-30 & 0601-02. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/29 2pp.

--7908290208 IE Insp Repts 50-518/79-11, 50-519/79-11, 50-520/79-11 & 50-521/79-11 on 790524-26, 29-30 & 0601-02 No noncompliance noted Major areas inspected: concrete, spray ponds, containments & project status.
SWAN, W.B. Region 2, Atlanta, Office of the Director
CANTRELL, F.S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/28 6pp.

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L.M. Tennessee Valley Authority 79/07/05 40pp.

7908080734 Forwards supplemental response to IE Bulletin 78-12B concerning atypical weld matl in reactor pressure vessel welds. Final responses will be provided after util reviews CB&I & C-E generic repts.
MILLS, L.M. Tennessee Valley Authority 79/07/09 2pp.

7908170208 Responds to NRC 790312 ltr Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03 Final response for Watts Bar & Bellafonte to be submitted before 790914 Pipe stools not used.
MILLS, L.M. Tennessee Valley Authority 79/07/13 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/07/17 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18. 3pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L.M. Tennessee Valley Authority. 79/07/20. 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/26. 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14. Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L.M. Tennessee Valley Authority. 79/07/27. 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/08/07. 3pp.

S. Reportable occurrences, LERs & related correspondence

7908140672 Forwards first interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Final rept to be forwarded by 791001.
MILLS, L.M. Tennessee Valley Authority. [illegible]/07/05. 1p.

--7908140684 First interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Cracks observed near weld joints. Investigation & repairs underway.
* Tennessee Valley Authority. 79/07/05. 3pp.

7908230384 Forwards deficiency rept re unacceptable QA documentation for Glazer steel matl.
MILLS, L.M. Tennessee Valley Authority. 79/08/15. 1p.

--7908230402 Interim deficiency rept re questionable QA documentation on steel received from Glazer Steel & Aluminum. Glazer removed from list of approved suppliers of certified matl. Final rept anticipated by 800216.
* Tennessee Valley Authority. 79/08/15. 2pp.

7908230451 Forwards final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear.
MILLS, L.M. Tennessee Valley Authority. 79/08/16. 1p.

--7908230460 Final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear. Caused by worn die used to form holes in contact arms of switches. Elongated holes resulted in improper contact wipe.
* Tennessee Valley Authority. 79/08/16. 2pp.

7908230589 Forwards final deficiency rept re use of non-ASME components on primary containment personnel access airlocks.
MILLS, L.M. Tennessee Valley Authority. 79/08/16. 1p.

--7908230596 Final rept re use of non-ASME components on primary containment personnel access airlocks. Caused by vendor interpretation of GE Specification 300-13. Airlock sys will be redesigned & refabricated.
* Tennessee Valley Authority. 79/08/16. 2pp.

DOCKET S:N-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

A. Application/construction stage documents & correspondence

7908150351 Summary of 790619 meeting w/TVA in Bethesda, MD re code testing requirements for piping embedded in concrete.
BENEDICT, R.A. Light Water Reactors Branch 2. 79/07/13. 11pp.

7908130103 Discusses program to upgrade bases section of STS. Resulting Class I, II & III amends will be fee exempt.
BAER, R.L. Light Water Reactors Branch 2. 79/07/18. 2pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L.M. Tennessee Valley Authority. 79/08/23. 2pp.

F. Security, medical, emergency & fire protection plans

7908200109 Provides info on safety & emergency planning requirements, in response to 790427 ltr.
RYAN, R.G. Office of State Programs. 79/05/23. 2pp.

--7908200115 Requests info re safety & emergency planning requirements.
STEWART, J.H. Tennessee State Univ. 79/04/27. 1p.

G. Adjudicatory correspondence

7908290722 Decision ALAB-554 Vacates ASLB granting of licensee motion for summary disposition. Grants judgment to licensee re operational effects on mussels. Defers decision re effects or const activities.
BISHOP, C.J. Atomic Safety and Licensing Appeal Panel. 79/07/11. 14pp.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L.M. Tennessee Valley Authority. 79/08/07. 2pp.

O. Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J.E. Tennessee Valley Authority. 79/05/29. 3pp.

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09.
GILLELAND, J.E. Tennessee Valley Authority. 79/06/20. 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/06/26. 3pp.

7908290197 Forwards IE Insp Repts 50-518/79-11, 50-519/79-11, 50-520/79-11 & 50-521/79-11 on 790524-26, 29-30 & 0601-02. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/29. 2pp.

--7908290208 IE Insp Repts 50-518/79-11, 50-519/79-11, 50-520/79-11 & 50-521/79-11 on 790524-26, 29-30 & 0601-02. No noncompliance noted. Major areas inspected: concrete, spray ponds, containments & project status.
SWAN, W.B. Region 2, Atlanta, Office of the Director. 79/06/28. 6pp.

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L.M. Tennessee Valley Authority. 79/07/05. 40pp.

7908080734 Forwards supplemental response to IE Bulletin 78-12B concerning atypical weld matl in reactor pressure vessel welds. Final responses will be provided after util reviews CB&I & C-E generic repts.
MILLS, L.M. Tennessee Valley Authority. 79/07/09. 2pp.

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellafonte to be submitted before 790914. Pipe stools not used.
MILLS, L.M. Tennessee Valley Authority. 79/07/13. 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L.M. Tennessee Valley Authority. 79/07/20. 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908140252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L.M. Tennessee Valley Authority. 79/07/27. 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

S. Reportable occurrences, LERs & related correspondence

7908140672 Forwards first interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Final rept to be forwarded by 791001.
MILLS, L.M. Tennessee Valley Authority. 79/07/05. 1p.

--7908140684 First interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Cracks observed near buttered weld joints. Investigation & repairs underway.
* Tennessee Valley Authority. 79/07/05. 3pp.

7908230384 Forwards deficiency rept re unacceptable QA documentation for Glazer steel matl.
MILLS, L.M. Tennessee Valley Authority. 79/08/15. 1p.

--7908230402 Interim deficiency rept re questionable QA documentation on steel received from Glazer Steel & Aluminum. Glazer removed from list of approved suppliers of certified matl. Final rept anticipated by 800216.
* Tennessee Valley Authority. 79/08/15. 2pp.

7908230451 Forwards final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear.
MILLS, L.M. Tennessee Valley Authority. 79/08/16. 1p.

--7908230460 Final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear. Caused by worn die used to form holes in contact arms of switches. Elongated holes resulted in improper contact wipe.
* Tennessee Valley Authority. 79/08/16. 2pp.

7908230589 Forwards final deficiency rept re use of non-ASME components on primary containment personnel access airlocks.
MILLS, L.M. Tennessee Valley Authority. 79/08/16. 1p.

--7908230596 Final rept re use of non-ASME components on primary containment personnel access airlocks. Caused by vendor interpretation of GE Specification 300-13. Airlock sys will be redesigned & refabricated.
* Tennessee Valley Authority. 79/08/16. 2pp.

DOCKET STN-50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908130334 Summary of 790418 meeting w/util to discuss questions raised about geology of region during review & public hearing. Remaining geological data will be submitted by 790515. Presentation matl & technical discussion encl.
PELTIER, I.A. Light Water Reactors Branch 1. 79/06/06. 19pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROUD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908070797 Ack receipt of NRC 790628 ltr re risk of military aviation accidents. Requests updated info re accident frequency for type of aircraft operating from Whidbey Island Naval Air Station.
LEED, R.M. Leed, Roger M. 77/07/07. 2pp.

7908080224 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J.R. Assistant Director for Site & Safeguards. 79/07/24. 2pp.

7908230082 Notification of 790803 meeting w/util in Bethesda, MD to discuss PSAR amend in response to lessons learned from TMI.
PELTIER, I.A. Light Water Reactors Branch 1. 79/07/31. 3pp.

7908140544 Forwards responses & commitments to NUREG-0578, IE Bulletin 79-08 & SECY-79-450 as result of study of implications of TMI incid[illegible].
JACOBSEN, W. Puget Sound Power & Light Co. 79/08/13. 24pp.

D. NRC D Final Environmental Statements, supplements & correspondence

7908080601 Requests assistance of & consultation w/Secretary of Interior re 1978 amends to Endangered Species Act. Requests info re species listed or proposed as endangered. Forwards Figures 2.1 & 3.4 of PES which provide regional maps.
SELLS, D.E. Environmental Projects Branch 2. 79/07/12. 3pp.

G. Adjudicatory correspondence

7908140677 Forwards supplemental testimony of DL Schreiber & NRC assessment of impacts associated w/delivery of reactor pressure sys.
BLACK, R.L. Branch 1. 79/06/01. 2pp.

--7908140682 Supplements testimony presented at 780217 proceeding re util use of piping test data to predict yield of proposed Ranney collector sys & drawdown effects of Ranney collectors on nearby Red Cabin & Muddy Creeks.
SCHREIBER, D.L. Puget Sound Power & Light Co. 79/06/01. 11pp.

--7908140689 NRC assessment of impacts associated w/delivery of reactor pressure vessel. Affidavits of WS Bivens & RM Goldstein encl.
BIVINS, W.S. Hydrology Meteorology Branch. GOLDSTEIN, R.M. Argonne National Laboratory. 79/06/01. 19pp.

7908300517 Requests permission to appear before ASLB at Jul 1979 hearing re licensing of facility.
SKELLY, R.E. Canada. 79/06/15. 1p.

7908300521 Requests permission to present brief at Seattle hearing & notification of time & place of hearing.
SMITH, E.M. White Rock & District Council of Women (B.C.). 79/06/20. 1p.

7908300523 Requests permission to appear at Seattle hearings re licensing of facility.
HARTLEY, G. Consumer's Assoc. of Canada (B.C.). 79/06/26. 1p.

7908300528 Requests permission to make oral presentation & present written brief at Seattle hearings re licensing of facility.
JACOBS, B. Affiliation Unknown. 79/06/15. 1p.

7908280359 Forwards NRC responses to 790529 interrogatories & document requests.
BLACK, R.L. Branch 1. 79/06/18. 1p.

--7908280370 Responses to Interrogatories 1-7. Objects to Interrogatories 1 & 6 because of untimeliness & lack of relevancy. Affidavits of SL Wastler, PH Leech & IA Peltier encl.
* Office of the Executive Legal Director. 79/06/18. 21pp.

7908300763 Interrogatories & document requests submitted by intervenor Skagitonians Against Nuclear Plants to applicants. Requests info re jointly owned independent subsidiary. Seattle Times 790607 article & Certificate of Svc encl.
* Leed, Roger M. 79/06/25. 7pp.

7908300309 Brief submitted by Forelaws on Board & Coalition for Safe Power in support of Natwe American Tribes 780613 petition for late intervention. ASLB acted arbitrarily & prejudiced rights of petitioners. Certificate of Svc encl.
ETACHON, E. Forelaws on Board 79/06/27 6pp.

7908080233 Forwards JA Martin testimony on evacuation planning, supplemental testimony of RL Gotchy on health effects, supplemental testimony of L Gittleman on financial qualifications & updated cost/benefit analysis.
BLACK, R. L. Branch 1 79/06/29 1p.

--7908080241 Testimony of JA Martin re evacuation planning. Evacuation of area within five-mile radius would take between 2-h & 6-h & up to 10-h to evacuate area withhin 10 miles. Prof qualifications encl.
MARTIN, J. A. Analysis Branch 79/06/29 2 'pp.

--7908080249 Supplemental testimony of RL Gotchy re health effects attributable to coal & nuclear fuel cycle alternatives. Revises use of WASH-1400 analyses of serious reactor accidents. Does not affect conclusion of 780621 testimony.
GOTCHY, R. L. Division of Site Safety & Environmental Analysis 79/06/29. 5pp.

--7908080255 Supplemental testimony of L Gittleman re financial qualifications. Licensees have reasonable assurance of obtaining necessary funds to cover estimated const & related fuel cycle costs.
GITTLEMAN, L. Assistant Director for Quality Assurance & Operations 79/06/29. 7pp.

--7908080263 Supplemental testimony of TL Winters re update of costs to reflect schedule changes. Testimony based on update of fuel & capital plant costs, which are 20% higher than 1978 estimates.
WINTERS, T. L. Cost Benefit Analysis Branch 79/06/29 2pp.

7908090300 Order for evidentiary hearings to resume on 790717. Prefiling & discovery deadlines are imposed. Grants limited appearances to RE Skelly, Municipal Council of Surrey, British Columbia Medical Association & Greenpeace.
DEALE, V. B. Atomic Safety and Licensing Board Panel 79/06/29 8pp.

7908140048 Board notification forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1 79/06/29 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment.
SCINTO, J. F. Hearings Division 79/03/05 1p.

7908150017 Discusses proposed order of presentation for 790707 evidentiary session. Presentation may be postponed until subsequent evidentiary session, due to status of review re applicant geology/seismology evidence.
THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams 79/06/29. 4pp.

7908150460 Describes proposed PR Huber testimony re Ranney wells & alternate energy sources. Testimony will be available for filing before 790710. Certificate of Svc encl.
LEED, R. M. Leed, Roger M. 79/06/29 8pp.

7908300004 Brief submitted by licensee re Indian tribes appeal of ASLB order denying untimely petition to intervene. Urges affirmation of ASLB order per 10CFR2.714(a)(1). Certificate of Svc encl.
THOMSEN, F. T., LITTLE, D. S. Perkins, Coie, Stone, Olsen & Williams 79/06/29. 33pp.

7908300024 Testimony of JE Mecca re amended license application & complete PSAR. Verifies application as amended through Amend 4 & PSAR as amended through Amend 20 & Suppl 1B.
MECCA, J. E. Puget Sound Power & Light Co. 79/06/29 4PP.

--7908300028 Testimony of JW Ellis re QA program. Util has implemented QA program that fully complies with all state & federal regulations.
ELLIS, J. W. Puget Sound Power & Light Co. 79/06/29. 3pp.

--7908300034 Testimony of WJ Ferguson re engineering, QA & const project organizations. QA program is autonomous & objective. Bechtel has primary responsibility for review of design & procurement documents.
FERGUSON, W. J. Puget Sound Power & Light Co. 79/06/29. 14pp.

--7908300047 Testimony of EV Padgett re QA program. QA program was developed to meet requirements of 10CFR50, App B & ANSI N45.2 as set forth in Chapter 17.
PADGETT, E. V. Puget Sound Power & Light Co. 79/06/29 5pp.

--7908300051 Testimony of RN Hettinger re QA program. Describes current level of QA activities. Certificate of Svc encl.
HETTINGER, R. N. Puget Sound Power & Light Co. 79/06/29. 5pp.

7908080280 Forwards NRC 790702 supplemental testimony re alternative sites comparison, per 790629 ltr.
BLACK, R. L. Branch 1 79/07/02 1p.

--7908080288 Supplemental testimony re alternative site comparison. Skagit site is less expensive & not inferior to Pebble Springs & Hanford site. EA Stull prof qualifications & Certificate of Svc encl.
LEECH, P., DVORAK, A., LEFEVRE, H. Assistant Director for Site Technology 79/07/02. 116pp.

--7908080307 Testimony of RB Eastvedt re bulk transmission sys requirements associated w/alternate sites.
EASTVEDT, R. B. Energy, Dept of 79/07/02. 38pp.

7908080002 Requests arrangement through Pacific Power & Light to provide qualified witness to describe West Rooselvelt alternative site rept results.
LEED, R. M. Leed, Roger M. 79/07/06. 2pp.

7908150005 Forwards prof qualifications of RB Eastvedt from DOE. Eastvedt has assisted in review of alternate sites & testified re bulk transmission sys requirements for NRC 790702 alternative site comparison testimony.
BLACK, R. L. Branch 1 79/07/06. 4pp.

7908170350 Requests postponement of geology/seismology presentation until next session. NRC/USGS review of evidence has not reached point at which NRC counsel is prepared to cross-examine witnesses at 790717 session.
THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams 79/07/06 3pp.

7908300724 Objection submitted by util to intervenor Skagitonians Concerned About Nuclear Plants 790625 interrogatories & document requests. Questions are untimely & not prompted by util 790619 responses. Certificate of Svc encl.
THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams 79/07/06. 4pp.

7908300099 Memo & order, ALAB-552. Tribes may file supplemental memo within 21 days to correct deficiencies in presentation re misrepresentation by federal agencies.
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 79/07/09. 20pp.

7908300747 Request submitted by Skagitonians Concerned About Nuclear Power that licensees be compelled to respond to 790625 interrogatories & document requests. Allegation of lateness lacks merit. Certificate of Svc encl.
LEED, R. M. Leed, Roger M. 79/07/10. 4pp.

7908150014 Requests to appear at 790717 hearings in Seattle, WA.
SMITH, J. M. Affiliation Unknown 79/07/11 1p.

7908170331 Discusses inaccurate info received in 790629 ltr on behalf of Skagitonians Concerned About Nuclear Plants. RT Green has not consented to testify. Requests clarification of matter.
GISH, N. R. Canada 79/07/11. 6pp.

7908220392 Ack receipt of 790620 ltr re presentation of brief at 790717 public hearing. Limited appearances will be taken on 790717. Forwards hearing order. W/o encl.
MITCHELL, P. Atomic Safety and Licensing Board Panel 79/07/11. 1p.

7908230248 Ack receipt of R Leed 790629 ltr re testimony by RT Green on behalf of util. Green has not agreed to provide testimony.
GISH, N. R. Canada 79/07/11. 6pp.

7908300008 Forwards ES Cheney 790712 prefile testimony re alternative sites.
GENDLER, M. W. Leed, Roger M. GENDLER, M. V. Skagitonians Concerned About Nuclear Plants 79/07/11. 2pp.

--7908300010 Supplemental testimony of ES Cheney re alternative site comparison, submitted on behalf of Skagitonians Concerned About Nuclear Power. Goshen, Hanford & Pebble Springs are better sites than Skagit.
CHENEY, E. S. Skagitonians Concerned About Nuclear Plants 79/07/12. 15pp.

7908080025 Memo to file re limited appearances at 790717 hearing. DJ McCloskey from Canada, JL McCann of Rand Society in Canada & representative of Consumers Association of Canada will appear.
MITCHELL, P. Atomic Safety and Licensing Board Panel 79/07/12. 1p.

7908170326 Responds to 790706 ltr requesting witness to testify re West Roosevelt site. Area is not ideal, because investigations are incomplete & CP applications have not been filed. Therefore, no witness will be presented.
THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams 77/07/12 3pp.

7908220911 Order denying intervenor Skagitonians Concerned About Nuclear Plants motion to govern future presentations of evidence re intervenor contentions. Licensee informal meetings w/NRC conform to 10CFR2.102(a).
DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/07/12 3pp.

7908300014 Refers intervenors Forelaws on Boards & Coalition for Safe Power 790716 motion for disqualification of ASLB Chairman VB Deale to ASLAB per 10CFR2.704(c). Chairman did not remove himself.
HOOPER, F. F., LINENBERGER, G. A. DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/07/18 2pp.

--7908300018 Motion submitted by intervenors Forelaws on Board & Coalition for Safe Power that VB Deale disqualify himself as chairman of ASLB in proceeding. Affidavit of E Stachon encl.
STACHON, E. Forelaws on Board * Coalition for Safe Power. 79/07/16 6pp.

7908300617 Confirms previous telegram NRC testimony needed only on site suitability questions re demography & 10-mile evacuation feasibility during LWA hearing on 790827-30. Requests that witness Martin be released to testify.
FERGUSON, W. J. Puget Sound Power & Light Co. 79/08/27 1p.

H. General correspondence

7908200354 Responds to 790717 ltr re concerns about proposed plant to be located in Skagit County, WA. NRC thoroughly evaluates environ effects of proposed plants, prepares EIS & solicits comments from govt & public.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/08/07 ,, 3pp.

--7908200357 Expresses concern, due to seismic activity, about proposed plant to be located in Skagit County, WA.
MILES, E. Affiliation Unknown 79/07/17 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908150188 Forwards IE Insp Repts 50-522/79-01 & 50-523/79-01 on 790515-18 & 22. No noncompliance noted.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/27 12 pp.

--7908150199 IE Insp Repts 50-522/79-01 & 50-523/79-01 on 790515-18 & 22. No noncompliance noted. Major areas inspected: QA procedures, QA manual review & concrete acceptance tests & qualification.
ALBERT, W. Q., HERNANDEZ, O. Region 5, San Francisco, Office of the Director. DODDS, R. T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/27 4pp.

T. Hearing transcripts on non-antitrust matters

7908070283 Transcript of 790720 hearing in Seattle, WA. Pp. 12,544-12,760.
DEALE, V. B., LINENBERGER, G. A. HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/20 227pp.

7908060056 Transcript of 790721 hearing in Seattle, WA. Pp. 12,761-12,890.
DEALE, V. B., LINENBERGER, G. A. HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/21 130pp.

7908070277 Transcript of 790723 hearing in Seattle, WA. Pp. 12,891-13,088.
DEALE, V. B., LINENBERGER, G. A. HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/23 198pp.

7908060086 Transcript of 790724 hearing in Seattle, WA. Pp. 13,089-13,227.
DEALE, V. B., LINENBERGER, G. A. HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/24 139pp.

7908060037 Transcript of 790725 hearing in Seattle, WA. Pp. 13,228-13,458. Testimony of TL Winters encl.
DEALE, V. B., LINENBERGER, G. A. HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/25 272pp.

7908030272 Transcript of 790726 hearing in Seattle, WA. Pp. 13,459-13,670. Testimonies by util & intervenor encl.
DEALE, V. B., LINENBERGER, G. A. HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/26 254pp.

7908090644 Transcript of 790727 meeting in Seattle, WA. Pp. 13,671-13,912.
DEALE, V. B., LINENBERGER, G. A. HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/27 241pp.

7908100401 Transcript of 790730 meeting in Seattle, WA. Pp. 13,913-14,171.
DEALE, V. B., LINENBERGER, G. A. HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/30 258pp.

7908090619 Transcript of 790731 meeting in Seattle, WA. Pp. 14,172-14,387.
DEALE, V. B., LINENBERGER, G. A. HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/31 215pp.

DOCKET STN-50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908130334 Summary of 790418 meeting w/util to discuss questions raised about geology of region during review & public hearing. Remaining geological data will be submitted by 790515. Presentation matl & technical discussion encl.
PELTIER, I. A. Light Water Reactors Branch 1 79/06/06 19pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

7908070797 Ack receipt of NRC 790628 ltr re risk of military aviation accidents. Requests updated info re accident frequency for type of aircraft operating from Whidbey Island Naval Air Station.
LEED, R. M. Leed, Roger M. 77/07/07 2pp.

7908080224 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/24 2pp.

7908230082 Notification of 790803 meeting w/util in Bethesda, MD to discuss PSAR amend in response to lessons learned from TMI.
PELTIER, I. A. Light Water Reactors Branch 1 79/07/31 3pp.

7908140544 Forwards responses & commitments to NUREG-0578, IE Bulletin 79-08 & SECY-79-450 as result of study of implications of TMI incident.
JACOBSEN, G. W. Puget Sound Power & Light Co. 79/08/13 24pp.

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7908080601 Requests assistance of & consultation w/Secretary of Interior re 1978 amends to Endangered Species Act. Requests info re species listed or proposed as endangered. Forwards Figures 2.1 & 3.4 of FES which provide regional maps.
SELLS, D. E. Environmental Projects Branch 2 79/07/12 3pp.

Q. Adjudicatory correspondence

7908140677 Forwards supplemental testimony of DL Schreiber & NRC assessment of impacts associated w/delivery of reactor pressure sys.
BLACK, R. L. Branch 1 79/06/01 2pp.

--7908140682 Supplements testimony presented at 780217 proceeding re util use of piping test data to predict yield of proposed Ranney collector sys & drawdown effects of Ranney collectors on nearby Red Cabin & Muddy Creeks.
SCHREIBER, D. L. Puget Sound Power & Light Co. 79/06/01 11pp.

--7908140689 NRC assessment of impacts associated w/delivery of reactor pressure vessel. Affidavits of WS Bivens & RM Goldstein encl.
BIVINS, W. S. Hydrology Meteorology Branch. GOLDSTEIN, R. M. Argonne National Laboratory. 79/06/01 19pp.

7908300517 Requests permission to appear before ASLB at Jul 1979 hearing re licensing of facility.
SKELLY, R. E. Canada 79/06/15 1p.

7908300521 Requests permission to present brief at Seattle hearing & notification of time & place of hearing.
SMITH, E. M. White Rock & District Council of Women (B. C.). 79/06/20. 1p.

7908300523 Requests permission to appear at Seattle hearings re licensing of facility.
HARTLEY, G. Consumer's Assoc. of Canada (B. C.). 79/06/26. 1p.

7908300528 Requests permission to make oral presentation & present written brief at Seattle hearings re licensing of facility.
JACOBS, B. Affiliation Unknown. 79/06/15. 1p.

7908280359 Forwards NRC responses to 790529 interrogatories & document requests.
BLACK, R. L. Branch 1. 79/06/18. 1p.

--7908280370 Responses to Interrogatories 1-7. Objects to Interrogatories 1 & 6 because of untimeliness & lack of relevancy. Affidavits of SL Wastler, PH Leech & IA Peltier encl.
* Office of the Executive Legal Director. 79/06/18. 21pp.

7908300763 Interrogatories & document requests submitted by intervenor Skagitonians Against Nuclear Plants to applicants. Requests info re jointly owned independent subsidiary. Seattle Times 790607 article & Certificate of Svc encl.
* Leed, Roger M. 79/06/25. 7pp.

7908300309 Brief submitted by Forelaws on Board & Coalition for Safe Power in support of Natwe American Tribes 780613 petition for late intervention. ASLB acted arbitrarily & prejudiced rights of petitioners. Certificate of Svc encl.
STACHON, E. Forelaws on Board. 79/06/27. 6pp.

7908080233 Forwards JA Martin testimony on evacuation planning, supplemental testimony of RL Gotchy on health effects, supplemental testimony of L Gittleman on financial qualifications & updated cost/benefit analysis.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908080241 Testimony of JA Martin re evacuation planning. Evacuation of area within five-mile radius would take between 2-h & 6-h & up to 10-h to evacuate area withhin 10 miles. Prof qualifications encl.
MARTIN, J. A. Analysis Branch. 79/06/29. 29pp.

--7908080249 Supplemental testimony of RL Gotchy re health effects attributable to coal & nuclear fuel cycle alternatives. Revises use of WASH-1400 analyses of serious reactor accidents. Does not affect conclusion of 780621 testimony.
GOTCHY, R. L. Division of Site Safety & Environmental Analysis. 79/06/29. 5pp.

--7908080255 Supplemental testimony of L Gittleman re financial qualifications. Licensees have reasonable assurance of obtaining necessary funds to cover estimated const & related fuel cycle costs.
GITTLEMAN, L. Assistant Director for Quality Assurance & Operations. 79/06/29. 7pp.

--7908080263 Supplemental testimony of TL Winters re update of costs to reflect schedule changes. Testimony based on update of fuel & capital plant costs, which are 20% higher than 1978 estimates.
WINTERS, T. L. Cost Benefit Analysis Branch. 79/06/29. 2pp.

7908090300 Order for evidentiary hearings to resume on 790717. Prefiling & discovery deadlines are imposed. Grants limited appearances to RE Skelly, Municipal Council of Surrey, British Columbia Medical Association & Greenpeace.
DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/06/29. 8pp.

7908140048 Board notification: forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

7908150012 Discusses proposed order of presentation for 790707 evidentiary session. Presentation may be postponed until subsequent evidentiary session, due to status of review re applicant geology/seismology evidence.
THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams. 79/06/29. 4pp.

7908150460 Describes proposed PR Weber testimony re Ranney wells & alternate energy sources. Testimony will be available for filing before 790710. Certificate of Svc encl.
LEED, R. M. Leed, Roger M. 79/06/29. 8pp.

7908300004 Brief submitted by licensee re Indian tribes appeal of ASLB order denying untimely petition to intervene. Urges affirmation of ASLB order per 10CFR2.714(a)(1). Certificate of Svc encl.
THOMSEN, F. T.; LITTLE, D. S. Perkins, Coie, Stone, Olsen & Williams. 79/06/29. 33pp.

7908300024 Testimony of JE Mecca re amended license application & complete PSAR. Verifies application as amended through Amend 4 & PSAR as amended through Amend 20 & Suppl 18.
MECCA, J. E. Puget Sound Power & Light Co. 79/06/29. 4PP.

--7908300028 Testimony of JW Ellis re QA program. Util has implemented QA program that fully complies with all state & federal regulations.
ELLIS, J. W. Puget Sound Power & Light Co. 79/06/29. 3pp.

--7908300034 Testimony of WJ Ferguson re engineering, QA & const project organizations. QA program is autonomous & objective. Bechtel has primary responsibility for review of design & procurement documents.
FERGUSON, W. J. Puget Sound Power & Light Co. 79/06/29. 14pp.

--7908300047 Testimony of EV Padgett re QA program. QA program was developed to meet requirements of 10CFR50, App B & ANSI N45.2 as set forth in Chapter 17.
PADGETT, E. V. Puget Sound Power & Light Co. 79/06/29. 5pp.

--7908300051 Testimony of RN Hettinger re QA program. Describes current level of QA activities. Certificate of Svc encl.
HETTINGER, R. N. Puget Sound Power & Light Co. 79/06/29. 5pp.

7908080280 Forwards NRC 790702 supplemental testimony re alternative sites comparison, per 790629 ltr.
BLACK, R. L. Branch 1. 79/07/02. 1p.

--7908080288 Supplemental testimony re alternative site comparison. Skagit site is less expensive & not inferior to Pebble Springs & Hanford site. EA Stull prof qualifications & Certificate of Svc encl.
LEECH, P.; DVORAK, A.; LEFEVRE, H. Assistant Director for Site Technology. 79/07/02. 116pp.

--7908080307 Testimony of RB Eastvedt re bulk transmission sys requirements associated w/alternate sites.
EASTVEDT, R. B. Energy, Dept of. 79/07/02. 38pp.

7908080002 Requests arrangement through Pacific Power & Light to provide qualified witness to describe West Rooselvelt alternative site rept results.
LEED, R. M. Leed, Roger M. 79/07/06. 2pp.

7908150005 Forwards prof qualifications of RB Eastvedt from DOE. Eastvedt has assisted in review of alternate sites & testified re bulk transmission sys requirements for NRC 790702 alternative site comparison testimony.
BLACK, R. L. Branch 1. 79/07/06. 4pp.

7908170350 Requests postponement of geology/seismology presentation until next session. NRC/USGS review of evidence has not reached point at which NRC counsel is prepared to cross-examine witnesses at 790717 session.
THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams. 79/07/06. 3pp.

7908300724 Objection submitted by util to intervenor Skagitonians Concerned About Nuclear Plants 790625 interrogatories & document requests. Questions are untimely & not prompted by util 790619 responses. Certificate of Svc encl.
THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams. 79/07/06. 4pp.

7908300099 Memo & order, ALAB-552. Tribes may file supplemental memo within 21 days to correct deficiencies in presentation re misrepresentation by federal agencies.
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 79/07/09. 20pp.

7908300747 Request submitted by Skagitonians Concerned About Nuclear Power that licensees be compelled to respond to 790625 interrogatories & document requests. Allegation of lateness lacks merit. Certificate of Svc encl.
LEED, R. M. Leed, Roger M. 79/07/10. 4pp.

7908150014 Requests to appear at 790717 hearings in Seattle, WA.
SMITH, J. M. Affiliation Unknown. 79/07/11. 1p.

7908170331 Discusses inaccurate info received in 790629 ltr on behalf of Skagitonians Concerned About Nuclear Plants. RT Green has not consented to testify. Requests clarification of matter.
GISH, N. R. Canada. 79/07/11. 6pp.

DOCKETED ITEMS

7908220392 Ack receipt of 790620 ltr re presentation of brief at 790717 public hearing. Limited appearances will be taken on 790717. Forwards hearing order. W/o encl.
MITCHELL, P. Atomic Safety and Licensing Board Panel. 79/07/11. 1p.

7908230248 Ack receipt of R Leed 790629 ltr re testimony by RT Green on behalf of util. Green has not agreed to provide testimony.
GISH, N. R. Canada. 79/07/11. 6pp.

7908300008 Forwards ES Cheney 790712 prefile testimony re alternative sites.
GENDLER, M. W. Leed, Roger M. GENDLER, M. V. Skagitonians Concerned About Nuclear Plants. 79/07/11. 2pp.

--7908300010 Supplemental testimony of ES Cheney re alternative site comparison, submitted on behalf of Skagitonians Concerned About Nuclear Power. Goshen, Hanford & Pebble Springs are better sites than Skagit.
CHENEY, E. S. Skagitonians Concerned About Nuclear Plants. 79/07/12. 13pp.

7908080025 Memo to file re limited appearances at 790717 hearing. DJ McCloskey from Canada, JL McCann of Rand Society in Canada & representative of Consumers Association of Canada will appear.
MITCHELL, P. Atomic Safety and Licensing Board Panel. 79/07/12. 1p.

7908170326 Responds to 790706 ltr requesting witness to testify re West Roosevelt site. Area is not ideal, because investigations are incomplete & CP applications have not been filed. Therefore, no witness will be presented.
THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams. 79/07/12. 3pp.

7908220011 Order denying intervenor Skagitonians Concerned About Nuclear Plants motion to govern future presentations of evidence re intervenor contentions. Licensee informal meetings w/NRC conform to 10CFR2.102(a).
DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/07/12. 3pp.

7908300014 Refers intervenors Forelaws on Boards & Coalition for Safe Power 790716 motion for disqualification of ASLB Chairman VB Deale to ASLAB per 10CFR2.704(c). Chairman did not remove himself.
HOOPER, F. F., LINENBERGER, G. A., DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/07/18. 2pp.

--7908300018 Motion submitted by intervenors Forelaws on Board & Coalition for Safe Power that VB Deale disqualify himself as chairman of ASLB in proceeding. Affidavit of E Stachon encl.
STACHON, E. Forelaws on Board * Coalition for Safe Power. 79/07/16. 6pp.

7908300617 Confirms previous telegram. NRC testimony needed only on site suitability questions re demography & 10-mile evacuation feasibility during LWA hearing on 790827-30. Requests that witness Martin be released to testify.
FERGUSON, W. J. Puget Sound Power & Light Co. 79/08/27. 1p.

H. General correspondence

7908200354 Responds to 790717 ltr re concerns about proposed plant to be located in Skagit County, WA. NRC thoroughly evaluates environ effects of proposed plants, prepares EIS & solicits comments from govt & public.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/08/07. 3pp.

--7908200357 Expresses concern, due to seismic activity, about proposed plant to be located in Skagit County, WA.
MILES, E. Affiliation Unknown. 79/07/17. 2pp.

O. Inspection reports, IE Bulletins & correspondence

7908150188 Forwards IE Insp Repts 50-522/79-01 & 50-523/79-01 on 790515-18 & 22. No noncompliance noted.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/27. 12 pp.

--7908150199 IE Insp Repts 50-522/79-01 & 50-523/79-01 on 790515-18 & 22. No noncompliance noted. Major areas inspected: QA procedures, QA manual review & concrete acceptance tests & qualification.
ALBERT, W. G., HERNANDEZ, G. Region 5, San Francisco, Office of the Director. DODDS, R. T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/27. 4pp.

T. Hearing transcripts on non-antitrust matters

7908070283 Transcript of 790720 hearing in Seattle, WA. Pp 12,544-12,760.
DEALE, V. B., LINENBERGER, G. A., HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/20. 227pp.

7908060056 Transcript of 790721 hearing in Seattle, WA. Pp 12,761-12,890.
DEALE, V. B., LINENBERGER, G. A., HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/21. 130pp.

7908070277 Transcript of 790723 hearing in Seattle, WA. Pp 12,891-13,088.
DEALE, V. B., LINENBERGER, G. A., HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/23. 198pp.

7908060086 Transcript of 790724 hearing in Seattle, WA. Pp 13,089-13,227.
DEALE, V. B., LINENBERGER, G. A., HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/24. 139pp.

7908060037 Transcript of 790725 hearing in Seattle, WA. Pp 13,228-13,458. Testimony of TL Winters encl.
DEALE, V. B., LINENBERGER, G. A., HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/25. 272pp.

7908030272 Transcript of 790726 hearing in Seattle, WA. Pp 13,459-13,670. Testimonies by util & intervenor encl.
DEALE, V. B., LINENBERGER, G. A., HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/26. 254pp.

7908090644 Transcript of 790727 meeting in Seattle, WA. Pp 13,671-13,912.
DEALE, V. B., LINENBERGER, G. A., HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/27. 241pp.

7908100401 Transcript of 790730 meeting in Seattle WA. Pp 13,913-14,171.
DEALE, V. B., LINENBERGER, G. A., HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/30. 258pp.

7908090619 Transcript of 790731 meeting in Seattle, WA. Pp 14,172-14,387.
DEALE, V. B., LINENBERGER, G. A., HOOPER, F. F. Atomic Safety and Licensing Board Panel. 79/07/31. 215pp.

DOCKET 50-524 BARTON, UNIT 1

G. Adjudicatory correspondence

7908090099 Forwards SAND 77-1972, "Transport of Radionuclides in Urban Environs Working Draft Assessment," SECY-78-311.dtd 780614 & SECY-78-311A.dtd 781109.
GRAY, J. R. Office of the General Counsel. 79/05/18. 1p.

DOCKET 50-525 BARTON, UNIT 2

G. Adjudicatory correspondence

7908090099 Forwards SAND 77-1972, "Transport of Radionuclides in Urban Environs Working Draft Assessment," SECY-78-311.dtd 780614 & SECY-78-311A.dtd 781109.
GRAY, J. R. Office of the General Counsel. 79/05/18. 1p.

DOCKET 50-526 BARTON, UNIT 3

G. Adjudicatory correspondence

7908090099 Forwards SAND 77-1972, "Transport of Radionuclides in Urban Environs Working Draft Assessment," SECY-78-311.dtd 780614 & SECY-78-311A.dtd 781109.
GRAY, J. R. Office of the General Counsel. 79/05/18. 1p.

DOCKET 50-527 BARTON, UNIT 4

G. Adjudicatory correspondence

7908090099 Forwards SAND 77-1972, "Transport of Radionuclides in Urban Environs Working Draft Assessment," SECY-78-311.dtd 780614 & SECY-78-311A.dtd 781109.
GRAY, J. R. Office of the General Counsel. 79/05/18. 1p.

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments. W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908080256 Discusses upcoming 790706 second briefing re nuclear energy. Submits list of published documents addressing 11 concerns, as requested in 790615 conversation. Separate ltr will address one other expressed area of concern.
MCCARTHY, E. Office of State Programs. 79/07/03. 3pp.

7908080172 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 2pp.

7908090014 Approves ASME code cases listed in 790507 request for use in const of plants. Lists case codes approved & bases for approval.
PARR, O. D. Light Water Reactors Branch. 79/07/11. 4pp.

7908080140 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/20. 2pp.

M. Antitrust correspondence

7908160358 Responds to NRC 790511 request for antitrust review info. Forwards util opening brief of E-7777 proceeding for San Onofre 2 & 3.
BARRY, D. N. Southern California Edison Co. 79/08/10. 10pp.

Q. Inspection reports, IE Bulletins & correspondence

7908140363 Ack receipt of 790605 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/79-01 & 50-529/79-01.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/25. 1p.

--7908140375 Responds to NRC 790426 ltr re violations noted in IE Insp Repts 50-528/79-01 & 50-529/79-01. Corrective actions all drawings marked "for info only" have been destroyed.
VAN BRUNT, E. E. Arizona Public Service Co. 79/06/05. 3pp.

--7908140385 Forwards IE Insp Repts 50-528/79-01 & 50-529/79-01 on 790212-15 & 28 & notice of violation.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/04/26. 2pp.

--7908140392 Notice of violation from insp on 790212-15 & 28.
* Region 5, San Francisco, Office of the Director. 79/04/25. 1p.

--7908140397 IE Insp Repts 50-528/79-01 & 50-529/79-01 on 790212-15 & 28. Noncompliance noted drawing control.
VORDERBRUEGGEN, HUTSON, T. W. Region 5, San Francisco, Office of the Director. HAYNES, R. C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/04/25. 8pp.

7908010384 Forwards IE Info Notice 79-[illegible] "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908020491 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908020403 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/19. 1p.

7908060048 Forwards IE Bulletin 79-16, "Vital Area Access Control." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908060141 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210462 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908280372 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310126 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300219 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908020521 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020024 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments. W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908080256 Discusses upcoming 790706 second briefing re nuclear energy. Submits list of published documents addressing 11 concerns, as requested in 790615 conversation. Separate ltr will address one other expressed area of concern.
MCCARTHY, E. Office of State Programs. 79/07/03. 3pp.

7908080172 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 2pp.

7908090014 Approves ASME code cases listed in 790507 request for use in const of plants. Lists case codes approved & bases for approval.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 4pp.

7908080140 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/20. 2pp.

M. Antitrust correspondence

7908160358 Responds to NRC 790511 request for antitrust review info. Forwards util opening brief of E-7777 proceeding for San Onofre 2 & 3.
BARRY, D. N. Southern California Edison Co. 79/08/10. 10pp.

Q. Inspection reports, IE Bulletins & correspondence

7908140363 Ack receipt of 790605 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/79-01 & 50-529/79-01.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/06/25. 1p.

--7908140375 Responds to NRC 790426 ltr re violations noted in IE Insp Repts 50-528/79-01 & 50-529/79-01. Corrective actions all drawings marked "for info only" have been destroyed.
VAN BRUNT, E. E. Arizona Public Service Co. 79/06/05. 3pp.

--7908140385 Forwards IE Insp Repts 50-528/79-01 & 50-529/79-01 on 790212-15 & 28 & notice of violation.
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/04/26. 2pp.

--7908140392 Notice of violation from insp on 790212-15 & 28.
* Region 5, San Francisco, Office of the Director. 79/04/20. 1p.

--7908140397 IE Insp Repts 50-528/79-01 & 50-529/79-01 on 790212-15 & 28. Noncompliance noted: drawing control.
VORDERBRUEGGEN, HUTSCH, T. W. Region 5, San Francisco, Office of the Director. HAYNES, H. " Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/04/25. 8pp.

7908010384 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908020491 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908020403 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/19. 1p.

7908060141 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210462 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908280372 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310126 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300219 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

J8020521 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020024 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROSS, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908080256 Discusses upcoming 790706 second briefing re nuclear energy. Submits list of published documents addressing 11 concerns, as requested in 790615 conversation. Separate ltr will address one other expressed area of concern.
MCCARTHY, E. Office of State Programs. 79/07/03. 3pp.

7908080172 Notifies that license amends resulting from program to upgrade bases section of STS are exempt from fees.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 2pp.

7908090014 Approves ASME code cases listed in 790507 request for use in const of plants. Lists case codes approved & bases for approval.
PARR, O. D. Light Water Reactors Branch 3. 79/07/11. 4pp.

7908080140 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/20. 2pp.

M. Antitrust correspondence

7908160358 Responds to NRC 790511 request for antitrust review info. Forwards util opening brief of E-7777 proceeding for San Onofre 2 & 3.
BARRY, D. N. Southern California Edison Co. 79/08/10. 10pp.

Q. Inspection reports, IE Bulletins & correspondence

7908010384 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

7908020491 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/18. 1p.

7908020403 Forwards corrected copy of IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/19. 1p.

7908060141 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/26. 1p.

7908210462 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/07. 1p.

7908280372 Forwards IE Bulletin 79-21, "Temp Effects on Level Measurements." No action required.
GRIER, B. H. Region 5, San Francisco, Office of the Director. 79/08/13. 1p.

7908310126 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/14. 1p.

7908300219 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/15. 1p.

S. Reportable occurrences, LERs & related correspondence

7908020521 Forwards PNO-79-67AW.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/10. 1p.

7908020024 Forwards PNO-79-67AX.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/07/17. 1p.

DOCKET STN-50-535 GASSAR-6

A. Application/construction stage documents & correspondence

7908280801 Summary of 790628 meeting w/GA Co in Bethesda, MD re revised design of gas cooled fast breeder.
WILLIAMS, P. M. Division of Project Management. 79/08/02. 25pp.

DOCKET 50-538 MEMPHIS STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

7908150690 Forwards Amend 1 to License R-127.
JONES, D.W. Memphis State Univ. 79/08/03. 1p.

--7908150693 Amend 1 to License R-127 modifying operating procedures & Tech Specs to permit operating levels up to 20 watts & authorizing addl 700 g U-235.
JONES, B.M. Memphis State Univ. 79/07/31. 55pp.

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908100365 Reviews discussions between NRC & licensee re quality of concrete const activities at reactor sites & licensee-agreed evaluation action. Immediate response by util required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/06/27. 2pp.

7908210039 Notifies that util application for OLS is being forwarded under separate cover. Documents should be filed with other Marble Hill matl.
SOUDER, J.L. Division of Rules and Records. 79/07/09. 1p.

7908070807 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/13. 1p.

7908200291 Submits revision to 790703 ltr re implementation of 100% QC overview of certain safety-related concrete activities. Attachment B has been superseded by later memo stating that all hold points are in effect until rescinded in writing.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/07/18. 2pp.

--7908200295 Discusses 100% QC overview program encompassing safety-related concrete activities performed by Gust A Newberg Co. Util has instituted hold point program.
HODGES, F.R. Public Service Co. of Indiana, Inc. 79/07/03. 4pp.

7908080167 Ack receipt of application for OL. Notifies that NRC will initiate acceptance review of application by Jan 1980. Discusses NRC Caseload Forecast Panel projections & reasons for review delay.
RUBENSTEIN, L.S. Light Water Reactors Branch 4. 79/07/23. 5pp.

7908280582 Expresses NRC understanding from 790720 meeting re proposed program concerning quality of concrete const activities at plant.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/23. 1p.

7908080211 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J.R. Assistant Director for Site & Safeguards. 79/07/24. 2pp.

7908160029 Notification of 790802 meeting, rescheduled from 790503, w/util in Bethesda, MD to discuss caseload forecast panel estimate for fuel load at facility.
WILSON, J.N. Light Water Reactors Branch 4. 79/07/24. 4pp.

7908130561 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN, L.S. Light Water Reactors Branch 4. 79/08/01. 4pp.

G. Adjudicatory correspondence

7908150281 Expresses concern re cement pouring problems at facility. Suggests complete investigation.
GRAY, R. Save the Valley - Save Marble Hill. SCOTT, G.R. Affiliation Unknown. NRC. 79/07/05. 1p.

7908160024 Requests revocation of CP, reopening of NRC safety hearings & start of planned congressional hearings.
* Paddlewheel Alliance. 79/08/12. 6pp.

7908210506 Requests safety hearings be reopened at once, CP be revoked & congressional investigation initiated.
* Affiliation Unknown. 79/08/21. 1p.

7908290489 Petition objecting to problems at plant. Problems include poor const & QA, nuclear waste storage & lack of demonstrated need for plant. Requests that CP be revoked, safety hearings be reopened & congressional hearings be initiated.
CURTIS, D. Affiliation Unknown. 79/08/29. 2pp.

H. General correspondence

7908150306 Press release re series of situations at facility that could adversely affect health & safety.
GRAY, R. Save the Valley - Save Marble Hill. 79/07/10. 1p.

7908170398 Requests that all official correspondence be addressed to SW Shields. Chapter 13 of FSAR & application vol will be revised to reflect organizational changes.
SHIELDS, S.W. Public Service Co. of Indiana, Inc. 79/08/09. 1p.

7908210483 Expresses concern re questionable quality of facility const. Lists problems & suggests issues to be examined prior to permitting const to resume. Doubts facility is needed. Believes licensee shareholders should pay for errors.
LAUDIG, S. Laudig, S. 79/08/13. 2pp.

O. Inspection reports, IE Bulletins & correspondence

7908070308 Forwards IE Insp Repts 50-546/79-04 & 50-547/79-04 on 790430-0503 & notice of violation.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/05/29. 2pp.

--7908070319 Notice of violation from insp on 790430-0503.
* Region 3, Chicago, Office of the Director. 79/05/19. 4pp.

--7908070340 IE Insp Repts 50-546/79-04 & 50-547/79-04 on 790430-0503. Noncompliance noted: two const deficiencies were not handled in expeditious manner; governing QA procedure not specific enough to comply w/reporting requirements of 10CFR50.55(e).
GALLAGHER, E.J., HAWKINS, F.C., HAYES, D.W. Region 3, Chicago, Office of the Director. 79/05/19. 13pp.

7908080722 Forwards IE Insp Repts 50-546/79-06 & 50-547/79-06 on 790529-0601. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/19. 2pp.

--7908080737 IE Insp Repts 50-546/79-06 & 50-547/79-06 on 790529-0601. No noncompliance noted. Major areas inspected: licensee actions & procedures on IE bulletins & circulars, 10CFR50.55(e) reportable items & reactor coolant pressure boundary.
SCHWEIBINZ, E.R., LEE, E.W., WILLIAMS, C.C. Region 3, Chicago, Office of the Director. 79/06/14. 10pp.

7908080546 Responds to IE Bulletin 79-04. Identifies three sets of Velan globe valves that showed incorrect weights. Will perform formal piping analysis.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/06/28. 2pp.

7908080514 Responds to IE Bulletins 79-12, 12A & 12B. Weld matl data & other relevant info included in C-E generic rept, "Atypical Weld Matl in Reactor Pressure Vessel Welds," sent to NRC on 790608.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/07/02. 1p.

7908290304 Responds to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Forwards "Evaluation of Analysis Procedures For Design of Expansion Anchored Plates in Concrete" by Sargent & Lundy Engineers.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/07/03. 3pp.

--7908290328 "Evaluation of Analysis Procedures For Design of Expansion Anchored Plates in Concrete."
KOSTAL, K. Sargent & Lundy, Inc. 79/05/31. 25pp.

7908020352 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/07/20. 1p.

7908150445 Responds to IE Bulletin 79-11. Evaluation of faulty overcurrent trip devices in circuit breakers for engineered safety sys is complete. No Westinghouse Type DB circuit breakers are currently in use or planned for use.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/07/20. 1p.

7908280513 Ack receipt of 790706 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-04 & 50-547/79-04.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/24. 1p.

--7908280565 Responds to NRC 790529 ltr re violations noted in IE Insp Repts 50-546/79-04 & 50-547/79-04. Corrective actions reporting deficiencies brought to attention of applicable personnel & solutions discussed & agreed upon.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/07/06 5pp.

7908300425 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/26 1p.

7908150379 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07 1p.

7908300297 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15 1p.

S. Reportable occurrences, LERs & related correspondence

7908010668 Ack receipt of 790608 interim repts re welders & procedures qualifications. Rept on qual: cation of welding procedures not considered final as previously stated. Final rept to be submitted by 790702.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/26 1p.

7908160523 Ack receipt of 790629 interim rept re possible damage to Unit 1 containment liner.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/13 1p.

7908140252 Ack 790605 interim rept re 1x25x9 ft void in slab in auxiliary bldg. Will review final rept upon receipt.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/17 1p.

7908170296 Ack receipt of 790706 interim rept re welder qualification. Final rept will be reviewed upon receipt. Welding procedure qualification item reported 790509 determined by util to be not reportable.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/17 1p.

7908170116 Ack receipt of 790706 rept re socket welded fitting in reactor coolant sys. Review will be completed during future insp.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/07/23 1p.

7908290500 Interim deficiency rept re failure to incorporate contractor Change Request 200 into concrete pour in auxiliary bldg. Caused by QA program breakdown. Review conducted to assure presence of hold tags at pour locations.
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 79/08/23 2pp.

DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908100365 Reviews discussions between NRC & licensee re quality of concrete const activities at reactor sites & licensee-agreed evaluation action. Immediate response by util required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/27 2pp.

7908210039 Notifies that util application for OLS is being forwarded under separate cover. Documents should be filed with other Marble Hill matl.
SOUDER, J. L. Division of Rules and Records. 79/07/09 1p.

7908070807 Requests that info submitted re facilities under const include instances of vandalism, demonstrations & threats of any kind.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/13 1p.

7908200291 Submits revision to 790703 ltr re implementation of 100% QC overview of certain safety-related concrete activities. Attachment B has been superseded by later memo stating that all hold points are in effect until rescinded in writing.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/07/18 2pp.

--7908200295 Discusses 100% QC overview program encompassing safety-related concrete activities performed by Gust A Newberg Co. Util has instituted hold point program.
HOOVER, F. R. Public Service Co. of Indiana, Inc. 79/07/03 4pp.

7908080167 Ack receipt of application for OL. Notifies that NRC will initiate acceptance review of application by Jan 1980. Discusses NRC Caseload Forecast Panel projections & reasons for review delay.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/07/23 5pp.

7908280582 Expresses NRC understanding from 790720 meeting re proposed program concerning quality of concrete const activities at plant.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/23 1p.

7908080211 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/24 2pp.

7908160029 Notification of 790802 meeting, rescheduled from 790503, w/util in Bethesda, MD to discuss caseload forecast panel estimate for fuel load at facility.
WILSON, J. N. Light Water Reactors Branch 4. 79/07/24 4pp.

7908130561 Requests util submit proposed secondary water chemistry program to be incorporated in new license condition. Current STS for all PWRs are ineffective re steam generator tube degradation. Model license condition encl.
RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/08/01 4pp.

G. Adjudicatory correspondence

7908150281 Expresses concern re cement pouring problems at facility. Suggests complete investigation.
GRAY, R. Save the Valley - Save Marble Hill. SCOTT, G. R. Affiliation Unknown. NRC. 79/07/05 1p.

7908160024 Requests revocation of CP, reopening of NRC safety hearings & start of planned congressional hearings.
* Paddlewheel Alliance. 79/08/12. 6pp.

7908210506 Requests safety hearings be reopened at once, CP be revoked & congressional investigation initiated.
* Affiliation Unknown. 79/08/21. 1p.

7908290489 Petition objecting to problems at plant. Problems include poor const & QA, nuclear waste storage & lack of demonstrated need for plant. Requests that CP be revoked, safety hearings be reopened & congressional hearings be initiated.
CURTIS, D. Affiliation Unknown. 79/08/29. 2pp.

H. General correspondence

7908150306 Press release re series of situations at facility that could adversely affect health & safety.
GRAY, R. Save the Valley - Save Marble Hill. 79/07/10. 1p.

7908170398 Requests that all official correspondence be addressed to SW Shields. Chapter 13 of FSAR & application vol will be revised to reflect organizational changes.
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 79/08/09 1p.

7908210483 Expresses concern re questionable quality of facility const. Lists problems & suggests issues to be examined prior to permitting corr: to resume. Doubts facility is needed. Believes licensee shareholders should pay for errors.
LAUDIG, S. Laudig, S. 79/08/13. 2pp.

O. Inspection reports, IE Bulletins & correspondence

7908070319 Notice of violation from insp on 790430-0503.
* Region 3, Chicago, Office of the Director. 79/05/19. 4pp.

7908070308 Forwards IE Insp Repts 50-546/79-04 & 50-547/79-04 on 790430-0503 & notice of violation.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/05/29. 2pp.

--7908070340 IE Insp Repts 50-546/79-04 & 50-547/79-04 on 790430-0503. Noncompliance noted: two const deficiencies were not handled in expeditious manner, governing QA procedure not specific enough to comply w/reporting requirements of 10CFR50.55(e).
GALLAGHER, E. J., HAWKINS, F. C., HAYES, D. W. Region 3, Chicago, Office of the Director. 79/05/19. 13pp.

7908080722 Forwards IE Insp Repts 50-546/79-06 & 50-547/79-06 on 790529-0601. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/19. 2pp.

--7908080737 IE Insp Repts 50-546/79-06 & 50-547/79-06 on 790529-0601 No noncompliance noted Major areas inspected licensee actions & procedures on IE bulletins & circulars.10CFR50.55(e) reportable items & reactor coolant pressure boundary.
SCHMEISINZ,E.R.; LEE,E.W.; WILLIAMS,C.C. Region 3, Chicago, Office of the Director 79/06/14 10pp

7906080546 Responds to IE Bulletin 79-04 Identifies three sets of Velan globe valves that showed incorrect weights Will perform formal piping analysis
COUGHLIN,J. Public Service Co. of Indiana, Inc. 79/06/28 2pp

7908080514 Responds to IE Bulletins 79-12,12A & 12B Weld matl data & other relevant info included in C-E generic rept, "Atypical Weld Matl in Reactor Pressure Vessel Welds," sent to NRC on 790608
COUGHLIN,J. Public Service Co. of Indiana, Inc. 79/07/02 1p

7908290304 Responds to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Forwards "Evaluation of Analysis Procedures For Design of Expansion Anchored Plates in Concrete" by Sargent & Lundy Engineers.
COUGHLIN,J. Public Service Co. of Indiana, Inc. 79/07/03 3pp

--7908290328 "Evaluation of Analysis Procedures For Design of Expansion Anchored Plates in Concrete."
KOSTAL,K. Sargent & Lundy, Inc. 79/05/31 25pp

7908020352 Forwards IE Bulletin 79-14,Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/20 1p

7908150445 Responds to IE Bulletin 79-11 Evaluation of faulty overcurrent trip devices in circuit breakers for engineered safety sys is complete.No Westinghouse Type DP circuit breakers are currently in use or planned for use.
COUGHLIN,J. Public Service Co. of Indiana, Inc. 79/07/20 1p

7908280513 Ack receipt of 790706 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-04 & 50-547/79-04
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/24 1p

--7908280565 Responds to NRC 790529 ltr re violations noted in IE Insp Repts 50-546/79-04 & 50-547/79-04 Corrective actions reporting deficiencies brought to attention of applicable personnel & solutions discussed & agreed upon.
COUGHLIN,J. Public Service Co. of Indiana, Inc. 79/07/06 5pp

7908300425 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/07/26 1p

7908150379 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/08/07 1p

7908300297 Forwards IE Bulletin 79-14,Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER,J.G. Region 3, Chicago, Office of the Director 79/08/15 1p

S. Reportable occurrences, LERs & related correspondence

7908010668 Ack receipt of 790608 interim repts re welders & procedures qualifications.Rept on qualification of welding procedures not considered final as previously stated.Final rept to be submitted by 790702
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/26 1p

7908160523 Ack receipt of 790629 interim rept re possible damage to Unit 1 containment liner.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/13 1p

7908140252 Ack 790605 interim rept re 1x25x9 ft void in slab in auxiliary bldg.Will review final rept upon receipt.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/17 1p

7908170296 Ack receipt of 790706 interim rept re welder qualification. Final rept will be reviewed upon receipt.Welding procedure qualification item reported 790509 determined by util to be not reportable.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/17 1p

7908170116 Ack receipt of 790706 rept re socket welded fitting in reactor coolant sys Review will be completed during future insp.
FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/23 1p

7908290500 Interim deficiency rept re failure to incorporate contractor Change Request 200 into concrete pour in auxiliary bldg. Caused by QA program breakdown.Review conducted to assure presence of hold tags at pour locations.
SHIELDS,S.W. Public Service Co. of Indiana, Inc. 79/08/23 2pp

DOCKET 50-548 FORT CALHOUN STATION, UNIT 2

G. Adjudicatory correspondence

7908300582 Forwards SAND-77-1972, "Transport of Radionuclides in Urban Environs Working Draft Assessment," SECY-78-311 dtd 780614 & SECY-78-311A dtd 781109
GRAY,J.R. Branch 1 79/05/18 1p

DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT

A. Application/construction stage documents & correspondence

7908170636 Discusses review of "The Zirconium Connection" forwarded 790501.Paper contains great deal of incorrect info. NRC did not conceal nature of Zircaloy-water reaction or source of hydrogen in TMI-2.Response to paper encl.
DENTON,H.R. Office of Nuclear Reactor Regulation 79/07/24 12pp

G. Adjudicatory correspondence

7908140048 Board notification Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK,R.L. Branch 1 79/06/29 1p

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO,J.F. Hearings Division 79/03/05 1p

H. General correspondence

7908030102 Grants 30-day extension for comments.Requests notification when schedule set.
SELLS,D.E. Environmental Projects Branch 2 79/07/21 1p

DOCKET STN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908150351 Summary of 790619 meeting w/TVA in Bethesda,MD re code testing requirements for piping embedded in concrete.
BENEDICT,R.A. Light Water Reactors Branch 2 79/07/13 11pp

7908150223 Concurs w/conclusions reached in util rept re transverse fault beneath south component cooling water trench in Unit 2 turbine bldg.Fault noncapable,per 10CFR100,App A.
JACKSON,R.E. Geosciences Branch 79/07/18 1p

7908200154 Responds to 790103 request for approval of proposed changes to certain environ commitments under CPPR-162 & CPPR-163. Requests submittal of Class I & II amend fees.
MILLER,W.O. License Fee Management Branch 79/07/27 1p

7908240078 Forwards Amend 1 to CPPR-162 & CPPR-163.Notice of issuance of agends encl.
SELLS,D.E. Environmental Projects Branch 2 79/08/06 2pp

--7908240081 Amend 1 to CPPR-162 & CPPR-163,modifying commitments & requirements re environ review,as specified in CP & FES.
VASSALLO,D.B. Division of Project Management 79/08/06 4pp

--7908240086 Notice of issuance of Amend 1 to CPPR-162 & CPPR-163.
SELLS,D.E. Environmental Projects Branch 2 79/08/06 2pp

7908210301 Forwards detailed description of fault discovered at Unit 2 turbine bldg area.Does not consider fault capable,per 10CFR100,App B.
MILLS,L.M. Tennessee Valley Authority 79/08/14 4pp

7908220268 Forwards 790629 rs from util to SW Harvey & JC White of EPA re aquatic monitoring programs including proposed amend to EPA license.
ZELLER,H.D. Environmental Protection Agency 79/08/14 8pp

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L. M. Tennessee Valley Authority. 79/08/23. 2pp.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L. M. Tennessee Valley Authority. 79/08/07. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority. 79/05/29. 3pp.

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/20. 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 3pp.

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L. M. Tennessee Valley Authority. 79/07/05. 40pp.

7908080734 Forwards supplemental response to IE Bulletin 78-12B concerning atypical weld matl in reactor pressure vessel welds. Final responses will be provided after util reviews CB&I & C-E generic repts.
MILLS, L. M. Tennessee Valley Authority. 79/07/09. 2pp.

7908020066 Ack receipt of 790626 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts. 50-553/79-05 & 50-554/79-05.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 1p.

--7908020075 Responds to NRC 790531 ltr re violations noted in IE Insp. Repts. 50-553/79-05 & 50-554/79-05. Corrective actions: concrete test sieves recalibr, curing room temp corrected & rebar repositioned to provide circulation.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/26. 4pp.

--7908020080 Forwards IE Insp. Repts. 50-553/79-05 & 50-554/79-05 on 790508-11 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/31. 2pp.

--7908020084 Notice of violation from insp on 790508-11.
* Region 2, Atlanta, Office of the Director. 79/05/30. 1p.

--7908020089 IE Insp. Repts. 50-553/79-05 & 50-554/79-05 on 790508-11. Noncompliance noted: failure to calibr concrete test sieves, properly cure concrete test cylinders & properly store reinforcing steel.
HARRIS, J. R., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/30. 4pp.

7908170277 Forwards IE Insp. Repts. 50-553/79-08 & 50-554/79-08 on 790621-22. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/12. 2pp.

--7908170283 IE Insp. Repts. 50-553/79-08 & 50-554/79-08 on 790621-22. No noncompliance noted. Major areas inspected: dust abatement, fuel storage, waste oil storage & site insp.
CUNNINGHAM, A. L. Region 2, Atlanta, Office of the Director. ANDREWS, D. L., HUFHAM, J. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/11. 3pp.

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellafonte to be submitted before 790914. Pipe stools not used.
MILLS, L. M. Tennessee Valley Authority. 79/07/13. 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L. M. Tennessee Valley Authority. 79/07/20. 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L. M. Tennessee Valley Authority. 79/07/27. 1p.

7908300516 Responds to NRC 790711 ltr re violations noted in IE Insp. Repts. 50-553/79-07 & 50-554/79-07. Corrective actions: QC welding personnel must confirm complete knowledge of Const Engineering Procedure 12.01.
MILLS, L. M. Tennessee Valley Authority. 79/07/31. 4pp.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

S. Reportable occurrences, LERs & related correspondence

7908140672 Forwards first interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Final rept to be forwarded by 791001.
MILLS, L. M. Tennessee Valley Authority. 79/07/05. 1p.

--7908140684 First interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Cracks observed near buttered weld joints. Investigation & repairs underway.
* Tennessee Valley Authority. 79/07/05. 3pp.

7908280606 Forwards second interim deficiency rept re tensile anchor capacities lower than assumed in design allowables. Final rept to be transmitted by 791221.
MILLS, L. M. Tennessee Valley Authority. 79/08/13. 1p.

--7908280611 Second interim deficiency rept re tensile anchor capabilities lower than assumed in design allowables. Final rept will be forwarded by 791221.
MILLS, L. M. Tennessee Valley Authority. 79/08/13. 1p.

7908230451 Forwards final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear.
MILLS, L. M. Tennessee Valley Authority. 79/08/16. 1p.

--7908230460 Final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear. Caused by worn die used to form holes in contact arms of switches. Elongated holes resulted in improper contact wipe.
* Tennessee Valley Authority. 79/08/16. 2pp.

7908230589 Forwards final deficiency rept re use of non-ASME components on primary containment personnel access airlocks.
MILLS, L. M. Tennessee Valley Authority. 79/08/16. 1p.

--7908230596 Final rept re use of non-ASME components on primary containment personnel access airlocks. Caused by vendor interpretation of GE Specification 300-13. Airlock sys will be redesigned & refabricated.
* Tennessee Valley Authority. 79/08/16. 2pp.

DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908150351 Summary of 790619 meeting w/TVA in Bethesda, MD re code testing requirements for piping embedded in concrete.
BENEDICT, R. A. Light Water Reactors Branch 2. 79/07/13. 11pp.

7908150223 Concurs w/conclusions reached in util rept re transverse fault beneath south component cooling water trench in Unit 2 turbine bldg. Fault noncapable per 10CFR100, App A.
JACKSON, R. E. Geosciences Branch. 79/07/18. 1p.

7908200154 Responds to 790103 request for approval of proposed changes to certain environ commitments under CPPR-162 & CPPR-163. Requests submittal of Class I & II amend fees.
MILLER, W. D. License Fee Management Branch. 79/07/27. 1p.

7908240078 Forwards Amend 1 to CPPR-162 & CPPR-163, Notice of issuance of amends encl.
SELLS, D. E. Environmental Projects Branch 2. 79/08/06. 2pp.

--7908240081 Amend 1 to CPPR-162 & CPPR-163, modifying commitments & requirements re environ review as specified in CP & FES.
VASSALLO, D. B. Division of Project Management. 79/08/06. 4pp.

--7908240086 Notice of issuance of Amend 1 to CPPR-162 & CPPR-163.
SELLS, D. E. Environmental Projects Branch 2. 79/08/06. 2pp.

7908210301 Forwards detailed description of fault discovered at Unit 2 turbine bldg area. Does not consider fault capable per 10CFR100, App B.
MILLS, L. M. Tennessee Valley Authority. 79/08/14. 4pp.

7908220268 Forwards 790629 ltrs from util to SW Harvey & JC White of EPA re aquatic monitoring programs including proposed amend to EPA license.
ZELLER, H. D. Environmental Protection Agency. 79/08/14. 8pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L. M. Tennessee Valley Authority. 79/08/23. 2pp.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Dfc of Power.
MILLS, L. M. Tennessee Valley Authority. 79/08/07. 2pp.

B. Inspection reports, IE Bulletins & correspondence

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority. 79/05/29. 3pp.

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/20. 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/26. 3pp.

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L. M. Tennessee Valley Authority. 79/07/05. 40pp.

7908080734 Forwards supplemental response to IE Bulletin 78-12B concerning atypical weld matl in reactor pressure vessel welds. Final responses will be provided after util reviews CE&I & C-E generic repts.
MILLS, L. M. Tennessee Valley Authority. 79/07/09. 2pp.

7908020066 Ack receipt of 790626 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/79-05 & 50-554/79-05.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/10. 1p.

--7908020075 Responds to NRC 790531 ltr re violations noted in IE Insp Repts 50-553/79-05 & 50-554/79-05. Corrective actions: concrete test sieves recalibr, curing room temp corrected & rebar repositioned to provide circulation.
GILLELAND, J. E. Tennessee Valley Authority. 79/06/26. 4pp.

--7908020080 Forwards IE Insp Repts 50-553/79-05 & 50-554/79-05 on 790508-11 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/31. 2pp.

--7908020084 Notice of violation from insp on 790508-11.
* Region 2, Atlanta, Office of the Director. 79/05/30. 1p.

--7908020089 IE Insp Repts 50-553/79-05 & 50-554/79-05 on 790508-11. Noncompliance noted: failure to calibr concrete test sieves, properly cure concrete test cylinders & properly store reinforcing steel.
HARRIS, J. R., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/30. 4pp.

7908170277 Forwards IE Insp Repts 50-553/79-08 & 50-554/79-08 on 79062 -22. No noncompliance noted.
SUTHE LAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/12. 2pp.

--7908170283 IE Insp Repts 50-553/79-08 & 50-554/79-08 on 790621-22. No noncompliance noted. Major areas inspected: dust abatement, fuel storage, waste oil storage & site insp.
CUNNINGHAM, A. L. Region 2, Atlanta, Office of the Director. ANDREWS, D. L., HUFHAM, J. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/11. 3pp.

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellafonte to be submitted before 790914. Pipe stools not used.
MILLS, L. M. Tennessee Valley Authority. 79/07/13. 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L. M. Tennessee Valley Authority. 79/07/20. 1p.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L. M. Tennessee Valley Authority. 79/07/27. 1p.

7908300516 Responds to NRC 790711 ltr re violations noted in IE Insp Repts 50-553/79-07 & 50-554/79-07. Corrective actions: QC welding personnel must confirm complete knowledge of Const Engineering Procedure 12.01.
MILLS, L. M. Tennessee Valley Authority. 79/07/31. 4pp.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

S. Reportable occurrences, LERs & related correspondence

7908140672 Forwards first interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Final rept to be forwarded by 791001.
MILLS, L. M. Tennessee Valley Authority. 79/07/05. 1p.

--7908140684 First interim deficiency rept re faulty welding by Lakeside Bridge & Steel Co on drywell vent structure & reactor pressure vessel pedestal. Cracks observed near buttered weld joints. Investigation & repairs underway.
* Tennessee Valley Authority. 79/07/05. 3pp.

7908280606 Forwards second interim deficiency rept re tensile anchor capacities lower than assumed in design allowables. Final rept to be transmitted by 791221.
MILLS, L. M. Tennessee Valley Authority. 79/08/13. 1p.

--7908280611 Second interim deficiency rept re tensile anchor capabilities lower than assumed in design allowables. Final rept will be forwarded by 791221.
MILLS, L. M. Tennessee Valley Authority. 79/08/13. 1p.

7908230451 Forwards final deficiency rept re defective Type GE SB-12 auxiliary switches in safety-related switchgear.
MILLS, L. M. Tennessee Valley Authority. 79/08/16. 1p.

--7908230460 Final deficiency rept re defective GE Type SB-12 auxiliary switches in safety-related switchgear. Caused by worn die used to form holes in contact arms of switches. Elongated holes resulted in improper contact wipe.
* Tennessee Valley Authority. 79/08/16. 2pp.

7908230589 Forwards final deficiency rept re use of non-ASME components on primary containment personnel access airlocks.
MILLS, L. M. Tennessee Valley Authority. 79/08/16. 1p.

--7908230596 Final rept re use of non-ASME components on primary containment personnel access airlocks. Caused by vendor interpretation of GE Specification 300-13. Airlock sys will be redesigned & refabricated.
* Tennessee Valley Authority. 79/08/16. 2pp.

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908140197 Responds to 790605 ltr requesting release of safety hearing transcripts in licensing proceedings & Reed rept. Info cannot be released due to proprietary status.
ENGELHARDT, T. F. Deputy Executive Legal Director. 79/06/21. 2pp.

--7908140204 Requests release of transcripts of safety hearings & Reed rept.
BRYANT, B. Affiliation Unknown. 79/06/05. 1p.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908010693 Notification of 790719 meeting w/PSC of OK in Bethesda, MD to discuss util evaluation of impact of TMI incident or proposed station.
THOMAS, C. O. Light Water Reactors Branch 1. 79/07/12. 4pp.

7908200131 Discusses 790629 & 790707 site meetings re requirements for allowing resumption of placement of concrete for safety-related structures, concrete activities overview & concrete testing program.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/13. 3pp.

--7908200134 Discusses contents of overview program for safety-related concrete activities.
HODGES, F. R. Public Service Co. of Indiana, Inc. 79/07/03. 6pp.

7908080219 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/24. 2pp.

7908150260 Authorizes to conduct addl limited work specified in 790710 ltr re Amend 3 to 780726 LWA for facility. FR notice encl.
VASSALLO, D. B. Division of Project Management. 79/07/24. 4pp.

--7908150267 Notice of issuance of amend to LWA published on 780811.
SELLS, D. E. Environmental Projects Branch 2. 79/07/24. 2pp.

7908010573 Responds to NUREG-0578, "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations." IE Bulletin 79-08 & selected emergency preparedness issues. Reiterates 790615 analyses in new format. Certificate of Svc encl.
EWING, T. N. Public Service Co. of Oklahoma. 79/07/27. 64pp.

7908170591 Summary of 790719 meeting w/licensee in Bethesda, MD re implications of TMI accident.
THOMAS, C. O. Light Water Reactors Branch 1. 79/08/01. 5pp.

7908150481 Clarifies util 790727 response to CP requirements re TMI-2. Analysis of accidents & anticipated operational occurrences will use Reg Guide 1.70, Revision 2. Util will maintain as-built drawings.
EWING, T. N. Public Service Co. of Oklahoma. 79/08/08. 3pp.

G. Adjudicatory correspondence

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1. 79/06/29. 1p.

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division. 79/03/05. 1p.

7908030598 Responds to 790416 ltr re Reed rept. ASLB received rept under protective order. Evidence presented during environ hearings indicates plant does not present cancer risk due to radiological emissions.
SHAPAR, H. K. Office of the Executive Legal Director. 79/07/05. 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908100227 Forwards IE Insp Repts 50-556/79-03 & 50-557/79-03 on 790530-0601. No noncompliance noted.
SEIPLE, W. C. Region 4, Dallas, Office of the Director. 79/06/20. 2pp.

--7908100235 IE Insp Repts 50-556/79-03 & 50-557/79-03 on 790530-0601. No noncompliance noted. Major areas inspected: const activities & status, concrete mix designs, QA audits, concrete seal slab placement & geologic mapping.
TAPIA, J. I., CROSSMAN, W. A. Region 4, Dallas, Office of the Director. HALL, R. E. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/06/20. 4pp.

DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908140197 Responds to 790605 ltr requesting release of safety hearing transcripts in licensing proceedings & Reed rept. Info cannot be released due to proprietary status.
ENGELHARDT, T. F. Deputy Executive Legal Director. 79/06/21. 2pp.

--7908140204 Requests release of transcripts of safety hearings & Reed rept.
BRYANT, B. Affiliation Unknown. 79/06/05. 1p.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908010693 Notification of 790719 meeting w/PSC of OK in Bethesda, MD to discuss util evaluation of impact of TMI incident or proposed station.
THOMAS, C. O. Light Water Reactors Branch 1. 79/07/12. 4pp.

7908200131 Discusses 790629 & 790707 site meetings re requirements for allowing resumption of placement of concrete for safety-related structures, concrete activities overview & concrete testing program.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/13. 3pp.

--7908200134 Discusses contents of overview program for safety-related concrete activities.
HODGES, F. R. Public Service Co. of Indiana, Inc. 79/07/03 6pp

7908080219 Forwards NUREG-0578, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. F. Assistant Director for Site & Safeguards 79/07/24 2pp

7908150260 Authorizes to conduct addl limited work specified in 790710 ltr re Amend 3 to 780726 LWA for Facility FR notice encl.
VASSALLO, D. B. Division of Project Management 79/07/24 4pp.

--7908150267 Notice of issuance of amend to LWA published on 780811.
SELLS, D. E. Environmental Projects Branch 2 79/07/24 2pp.

7908010573 Responds to NUREG-0578, "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations." IE Bulletin 79-08 & selected emergency preparedness issues. Reiterates 790615 analyses in new format. Certificate of Svc encl.
EWING, T. N. Public Service Co. of Oklahoma 79/07/27 64pp.

7908170591 Summary of 790719 meeting w/licensee in Bethesda, MD re implications of TMI accident.
THOMAS, C. O. Light Water Reactors Branch 1 79/08/01 5pp

7908150481 Clarifies util 790727 response to CP requirements re TMI-2. Analysis of accidents & anticipated operational occurrences will use Reg Guide 1.70, Revision 2. Util will maintain as-built drawings.
EWING, T. N. Public Service Co. of Oklahoma 79/08/08 3pp

6. Adjudicatory correspondence

7908140048 Board notification. Forwards NRC 781017 memo re post-LOCA hydrogen production from matls inside containment, in response to 790606 request.
BLACK, R. L. Branch 1 79/06/29 1p

--7908140052 Forwards NRC 781017 memo re post-LOCA hydrogen generation from matls inside containment.
SCINTO, J. F. Hearings Division 79/03/05. 1p.

7908030598 Responds to 790416 ltr re Reed rept ASLB received rept under protective order. Evidence presented during environ hearings indicates plant does not present cancer risk due to radiological emissions.
SHAPAR, H. K. Office of the Executive Legal Director 79/07/05 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908100227 Forwards IE Insp Repts 50-556/79-03 & 50-557/79-03 on 790530-0601. No noncompliance noted.
SEIDLE, W. C. Region 4, Dallas, Office of the Director 79/06/20 2pp.

--7908100235 IE Insp Repts 50-556/79-03 & 50-557/79-03 on 790530-0601. No noncompliance noted. Major areas inspected: const activities & status, concrete mix designs, QA audits, concrete seal slab placement & geologic mapping.
TAPIA, J. I., CROSSMAN, W. A. Region 4, Dallas, Office of the Director HALL, R. E. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/20 4pp

DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908150351 Summary of 790619 meeting w/TVA in Bethesda, MD re code testing requirements for piping embedded in concrete.
BENEDICT, R. A. Light Water Reactors Branch 2 79/07/13 11pp

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L. M. Tennessee Valley Authority 79/08/23 2pp

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L. M. Tennessee Valley Authority 79/08/07. 2pp.

G. Inspection reports, IE Bulletins & correspondence

7908020200 Forwards IE Insp Repts 50-566/79-07 & 50-567/79-07 on 790508-11. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 2pp

--7908020205 IE Insp Repts 50-566/79-07 & 50-567/79-07 on 790508-11. No noncompliance noted. Major areas inspected: const status, containment welding, 10CFR21 posting & QA implementing procedures for containment & other steel structures.
GOUGE, M. J., HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 5pp.

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J. E. Tennessee Valley Authority 79/05/29 3pp.

7908210575 Forwards IE Insp Repts 50-566/79-08 & 50-567/79-08 on 790521-24. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/05. 2pp.

--7908210583 IE Insp Repts 50-566/79-08 & 50-567/79-08 on 790521-24. No noncompliance noted. Major areas inspected: structural concrete work activities, quality records, level C & D storage const status & licensee actions on previous finding.
LENAHAN, J. J., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/04. 5pp.

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09.
GILLELAND, J. E. Tennessee Valley Authority 79/06/20. 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/06/26. 3pp.

7908060142 Responds to IE Bulletins 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L. M. Tennessee Valley Authority 79/07/05. 40pp.

7908080734 Forwards supplemental response to IE Bulletin 78-12B concerning atypical weld matl in reactor pressure vessel welds. Final responses will be provided after util reviews CB&I & C-E generic repts.
MILLS, L. M. Tennessee Valley Authority 79/07/09. 2pp.

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellefonte to be submitted before 790914. Pipe stools not used.
MILLS, L. M. Tennessee Valley Authority 79/07/13. 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L. M. Tennessee Valley Authority 79/07/20. 1p.

7908060062 Ack receipt of 790712 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/79-09 & 50-567/79-09.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/23. 1p.

--7908060235 Responds to NRC 790620 ltr re violations noted in IE Insp Repts 50-566/79-09 & 50-567/79-09. Corrective actions: out-of-spec samples will be handled in accordance w/procedures. Addl line of fog nozzles installed.
MILLS, L. M. Tennessee Valley Authority 79/07/12. 6pp.

--7908060271 Forwards IE Insp Repts 50-566/79-09 & 50-567/79-09 on 790605-08 & notice of violation.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/20. 2pp.

--7908060288 Notice of violation from insp on 790605-08.
* Region 2, Atlanta, Office of the Director. 79/06/20. 2pp.

--7908060308 IE Insp Repts 50-566/79 & 50-567/79-09 on 790606-08. Noncompliance noted: failure to follow procedures re concrete activities & failure to follow procedures to control chemical concentrations in bulkweld powdered metal.
GOUGE, M.J. Region 2, Atlanta, Office of the Director.
CANTRELL, F.S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/20. 6pp.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for Item 1 not complete. Unable to meet response date of 790801. Will submit response before 790815.
MILLS, L.M. Tennessee Valley Authority. 79/07/27. 1p.

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/08/07. 3pp.

DOCKET: STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908150351 Summary of 790619 meeting w/TVA in Bethesda, MD re code testing requirements for piping embedded in concrete.
BENEDICT, R.A. Light Water Reactors Branch 2. 79/07/13. 11pp.

7908300688 Submits revised fuel load schedule for all TVA plants under const.
MILLS, L.M. Tennessee Valley Authority. 79/08/23. 2pp.

H. General correspondence

7908150469 Forwards list of requested changes to distribution list re correspondence addressed to TVA & listing of principal officers for TVA Ofc of Power.
MILLS, L.M. Tennessee Valley Authority. 79/08/07. 2pp.

O. Inspection reports, IE Bulletins & correspondence

7908020200 Forwards IE Insp Repts 50-566/79-07 & 50-567/79-07 on 790508-11. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/24. 2pp.

--7908020205 IE Insp Repts 50-566/79-07 & 50-567/79-07 on 790508-11. No noncompliance noted. Major areas inspected: const status, containment welding, 10CFR21 posting & QA implementing procedures for containment & other steel structures.
GOUGE, M.J.; HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/24. 5pp.

7908010158 Forwards response to IE Bulletins 78-12, 12-A & 12-B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Discusses vendor repts. Westinghouse generic rept due Oct 1979.
GILLELAND, J.E. Tennessee Valley Authority. 79/05/29. 3pp.

7908210575 Forwards IE Insp Repts 50-566/79-08 & 50-567/79-08 on 790521-24. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/05. 2pp.

--7908210583 IE Insp Repts 50-566/79-08 & 50-567/79-08 on 790521-24. No noncompliance noted. Major areas inspected: structural concrete work activities, quality records, level C & D storage const status & licensee actions on previous finding.
LENAHAN, J.J.; BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/04. 5pp.

7908010692 Submits results of investigations for various plants in response to 790417 IE Bulletin 79-09.
GILLELAND, J.E. Tennessee Valley Authority. 79/06/20. 4pp.

7908070150 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/06/26. 3pp.

7908060142 Responds to IE Bulletin 79-02 & 02, Revision 1. Forwards results of pipe support base plate design investigations.
MILLS, L.M. Tennessee Valley Authority. 79/07/05. 40pp.

7908080734 Forwards supplemental response to IE Bulletin 78-12B concerning atypical weld matl in reactor pressure vessel welds. Final responses will be provided after util reviews CE&I & C-E generic repts.
MILLS, L.M. Tennessee Valley Authority. 79/07/09. 2pp.

7908170208 Responds to NRC 790312 ltr. Forwards final response for Hartsville, Phipps Bend & Yellow Creek plants to IE Bulletin 79-03. Final response for Watts Bar & Bellafonte to be submitted before 790914. Pipe stools not used.
MILLS, L.M. Tennessee Valley Authority. 79/07/13. 2pp.

7908230198 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No actions required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/17. 3pp.

7908020316 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908030033 Forwards IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs," which was omitted from IE Info Notice 79-19.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18. 2pp.

7908080054 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/18. 3pp.

7908170517 Responds to IE Bulletin 79-11. No DB-50 or DB-75 circuit breakers w/overcurrent trip devices in use or planned for use.
MILLS, L.M. Tennessee Valley Authority. 79/07/20. 1p.

7908060062 Ack receipt of 790712 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/79-09 & 50-567/79-09.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/07/23. 1p.

--7908060235 Responds to NRC 790620 ltr re violations noted in IE Insp Repts 50-566/79-09 & 50-567/79-09. Corrective actions: out-of-spec samples will be handled in accordance w/procedures. Addl line of fog nozzles installed.
MILLS, L.M. Tennessee Valley Authority. 79/07/12. 6pp.

--7908060271 Forwards IE Insp Repts 50-566/79-09 & 50-567/79-09 on 790605-08 & notice of violation.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/20. 2pp.

--7908060288 Notice of violation from insp on 790605-08.
* Region 2, Atlanta, Office of the Director. 79/06/20. 2pp.

--7908060308 IE Insp Repts 50-566/79 & 50-567/79-09 on 790606-08. Noncompliance noted: failure to follow procedures re concrete activities & failure to follow procedures to control chemical concentrations in bulkweld powdered metal.
GOUGE, M.J. Region 2, Atlanta, Office of the Director.
CANTRELL, F.S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/20. 6pp.

7908080749 Forwards IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/26. 2pp.

7908160252 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/07/27. 3pp.

7908230475 Responds to IE Bulletin 79-14 Investigations for I[illegible]1 not complete Unable to meet response date of 790801 Will submit response before 790815
MILLS, L. M. Tennessee Valley Authority 79/07/27 1p

7908220650 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/08/07 3pp

DOCKET STN-50-568 NEP NUCLEAR, UNIT 1

A. Application/construction stage documents & correspondence

7908060088 Denies 790209 request to withhold, per 10CFR2.790, Revision 3 of CP application Discusses reasons for denial SEC ltr dtd 781214 re release of final info encl
PARR, O. D. Operating Reactors Branch 3 (Pre 790625) 79/03/12 7pp

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908080199 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/20 2pp

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7905160395 Response to 790419 ltr re Section 8.5.2 of DES on economics of early operation Defends method of analysis & capacity factor assumptions Forwards JW Dick 790430 memo re assumptions used in Section 8
FULKERSON, W. Oak Ridge National Laboratory 79/05/08 5pp

7908130566 Forwards DES for facility Comments due by 790807 W/o encl
BALLARD, R. L. Environmental Projects Branch 1 79/05/31 2pp

7908080556 Comments on draft EIS submitted by Conservation Law Foundation of RI Statement on long-term negative impact on terrestial & aquatic wildlife made w/paucity of data Unclear justification for use of once-through cooling sys
VIOLET, S. A. Conservative Law Foundation of Rhode Island 79/07/30 3pp

7908100474 Forwards technical reviews of DES Comments are provisional in nature
KELLEHER, S. A. Rhode Island, State of 79/08/03 95pp

7908070399 Submits comments re review of DES, including daily commuting of laborers & evaluation of energy needed to operate cooling alternatives
KEOHANE, H. J. Energy, Dept of 79/08/07 1p

7908300676 Forwards comments re review of draft EIS Statement of Compliance w/EPA U fuel cycle std needed Transportation section requires inclusion of measures to insure public safety during shipment
CUSTARD, C. Health, Education & Welfare, Dept of 79/08/08 3pp

7908300684 Submits comments on DES Comparison of health consequences to background is totally irrelevant & contrary to NEPA
LOCHSTET, W. A. Affiliation Unknown 79/08/12 12pp

7908210545 Forwards comments on DES by Natl Weather Notes two meteorological deficiencies re fastest mile wind speeds & storm surge from hurricanes & tropical storms
GALLER, S. R. Commerce, Dept of 79/08/17 2pp

E. NRC Safety Evaluation Report (SER), suppls & correspondence

7908080474 SER re const of facility, Suppl 1
* Office of Nuclear Reactor Regulation. NUREG-0424 79/07/20. 68pp. Available at NTIS.

G. Adjudicatory correspondence

7908020320 Responds to objection to two paragraphs in 790103 site visit rept re assurances given by govt officials re community attitudes towards proposed facility Site visit was preliminary & did not bias licensing process
BALLARD, R. L. Environmental Projects Branch 1 79/06/22 2pp

7908300264 Motion by intervenor Concerned Citizens of RI in opposition to util motion to continue proceedings Requests NRC reconsider application Notice of appearance of WS Jordan on behalf of Concerned Citizens of RI encl
JORDAN, W. S., SHELDON, K. P. Sheldon, Harmon, Roisman & Weiss 79/07/13 3pp

--7908300281 Request submitted by intervenor Concerned Citizens of RI that NRC issue order to show cause why CP application should not be dismissed Application is unacceptable & does not meet docketing criteria Certificate of Svc encl
JORDAN, W. S., SHELDON, K. P. Sheldon, Harmon, Roisman & Weiss 79/07/13 7pp

M. Antitrust correspondence

7908240443 Notifies that review of facility purchase by MA Municipal Wholesale Electric Co & ME Public Svc Co has disclosed no evidence or situation inconsistent w/antitrust laws No NRC antitrust hearing will be necessary
SHAPAR, H. K. Office of the Executive Legal Director 79/08/20 2pp

DOCKET STN-50-569 NEP NUCLEAR, UNIT 2

A. Application/construction stage documents & correspondence

7908060088 Denies 790209 request to withhold, per 10CFR2.790, Revision 3 of CP application Discusses reasons for denial SEC ltr dtd 781214 re release of final info encl
PARR, O. D. Operating Reactors Branch 3 (Pre 790625) 79/03/12 7pp

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp

7908080199 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/20 2pp

D. NRC Draft/Final Environmental Statements, suppls & correspondence

7905160395 Response to 790419 ltr re Section 8.5.2 of DES on economics of early operation Defends method of analysis & capacity factor assumptions Forwards JW Dick 790430 memo re assumptions used in Section 8
FULKERSON, W. Oak Ridge National Laboratory 79/05/08 5pp

7908130566 Forwards DES for facility Comments due by 790807 W/o encl
BALLARD, R. L. Environmental Projects Branch 1 79/05/31 2pp

7908080556 Comments on draft EIS submitted by Conservation Law Foundation of RI Statement on long-term negative impact on terrestial & aquatic wildlife made w/paucity of data Unclear justification for use of once-through cooling sys
VIOLET, S. A. Conservative Law Foundation of Rhode Island 79/07/30 3pp

7908100474 Forwards technical reviews of DES Comments are provisional in nature
KELLEHER, S. A. Rhode Island, State of 79/08/03 95pp

7908070399 Submits comments re review of DES, including daily commuting of laborers & evaluation of energy needed to operate cooling alternatives
KEOHANE, H. J. Energy, Dept of 79/08/07 1p

7908300676 Forwards comments re review of draft EIS Statement of Compliance w/EPA U fuel cycle std needed Transportation section requires inclusion of measures to insure public safety during shipment.
CUSTARD, C. Health, Education & Welfare, Dept. of. 79/08/08. 3pp.

7908300684 Submits comments on DES Comparison of health consequences to background is totally irrelevant & contrary to NEPA.
LOCHSTET, W.A. Affiliation Unknown. 79/08/12. 12pp.

7908210545 Forwards comments on DES by Natl Weather Notes two meteorological deficiencies re fastest mile wind speeds & storm surge from hurricanes & tropical storms.
QALLER, S.R. Commerce, Dept of. 79/08/17. 2pp.

E. NRC Safety Evaluation Report (SER), supplS & correspondence

7908080474 SER re const of facility, Suppl 1.
* Office of Nuclear Reactor Regulation. NUREG-0424. 79/07/20. 68pp. Available at NTIS.

G. Adjudicatory correspondence

7908020320 Responds to objection to two paragraphs in 790103 site visit rept re assurances given by govt officials re community attitudes towards proposed facility Site visit was preliminary & did not bias licensing proce.
BALLARD, R.L. Environmental Projects Branch 1. 79/06/22. 2pp.

7908300264 Motion by intervenor Concerned Citizens of RI in opposition to util motion to continue proceedings Requests NRC reconsider application Notice of appearance of WS Jordan on behalf of Concerned Citizens of RI encl.
JORDAN, W.S., SHELDON, K.P. Sheldon, Harmon, Roisman & Weiss. 79/07/13. 3pp.

--7908300281 Request submitted by intervenor Concerned Citizens of RI that NRC issue order to show cause why CP application should not be dismissed Application is unacceptable & does not meet docketing criteria Certificate of Svc encl.
JORDAN, W.S., SHELDON, K.P. Sheldon, Harmon, Roisman & Weiss. 79/07/13. 7pp.

M. Antitrust correspondence

7908240443 Notifies that review of facility purchase by MA Municipal Wholesale Electric Co & ME Public Svc Co has disclosed no evidence of situation inconsistent w/antitrust laws No NRC antitrust hearing will be necessary.
SHAPAR, H.K. Office of the Executive Legal Director. 79/08/20. 2pp.

DOCKET STN-50-574 BAGNAC NUCLEAR POWER PROJECT

A. Application/construction stage documents & correspondence

7908300340 Forwards 790626 ltr to Philippine President F Marcos re access to info & public participation in review of safety of operating reactor.
HAYES, P. Concerned Citizens Reactor Export Review Board. 79/06/26. 4pp.

7908160295 Forwards FOIA request from MB Bogin requesting copy of IAEA rept re export of reactor to Philippines & all related documents.
SLAWSON, R.N. Energy, Dept of. 79/07/26. 1p.

--7908160300 FOIA request for copy of IAEA rept re export of reactor to Philippines; all related documents.
BOGIN, M.B. Asher, T.R. PC. 79/07/12. 1p.

7908240219 FOIA request for all documents re Westinghouse export License Applications XR 120, XCOM-0013 & XSNM-1471, Philippine power reactor project ? procedures & policies related to export licensing.
BUCKLEY, C.H. Beveridge, Fairbanks, & Diamond. 79/08/01. 2pp.

7908210159 Expresses concern re safety factors surrounding proposed Westinghouse nuclear installation in Philippines Petition to intervene & request for public hearings should be granted.
DURNAN, R., SHAW, Q., RIX, S. Australia. 79/08/03. 2pp.

7908160290 Responds to DOE referral of documents originated by NRC re export of reactor to Philippines NRC has no objection to release of documents.
FELTON, J.M. Division of Rules and Records. 79/08/06. 1p.

7908240085 Responds to FOIA request for documents re Westinghouse export applications & Philippine power reactor project. Forwards list of documents & 60 documents pertaining to request Document 61 on list withheld (ref FOIA exemption 1).
FELTON, J.M. Division of Rules and Records. 79/08/23. 180pp.

G. Adjudicatory correspondence

7908080591 Opposes const of Philippine plant Cites proximity of earthquake fault & volcanoes, resulting in inability to dispose of waste via burial.
MCHENRY, M. Affiliation Unknown. 79/05/17. 1p.

7903010242 Requests Westinghouse be denied license to build proposed facility in Philippines.
HEDGECOTH, L.J. Affiliation Unknown. 79/06/04. 1p.

7908060445 Supports Philippine Movement for Environ Protection 790419 petition to intervene & request for hearing Proposed nuclear exports present serious risks to health, safety & well-being of public.
SISTER M THERES Affiliation Unknown. 79/06/15. 2pp.

7908030184 Ack receipt of 790531 ltr supporting petition to intervene & request for hearing filed by Philippine Movement for Environ Protection.
CHILK, S.J. Office of the Secretary of the Commission. 79/06/21. 1p.

--7908030189 Supports 790419 petition to intervene & request for hearing filed by Philippine Movement for Environ Protection re proposed export of nuclear power reactor & fuel by Westinghouse.
TIRONA, N.J.T. Philippines. 79/05/31. 2pp.

7908060204 Ack receipt of 790615 ltr supporting Philippine Movement for Environ Protection 790419 petition to intervene & request for hearing.
CHILK, S.J. Office of the Secretary of the Commission. 79/06/21. 1p.

--7908060249 Supports Philippine Movement for Environ Protection 790419 petition to intervene & request for hearing Proposed nuclear exports pose serious risks to health, safety & well-being of public.
SISTER LEONILE Affiliation Unknown. 79/05/30. 2pp.

7908060424 Ack receipt of 790529 ltr supporting Philippine Movement for Environ Protection 790419 petition to intervene & request for hearing.
CHILK, S.J. Office of the Secretary of the Commission. 79/06/21. 1p.

7908060445 Supports Philippine Movement for Environ Protection 790419 petition to intervene & request for hearing Proposed nuclear exports present serious risks to health, safety & well-being of public.
SISTER M THERES Affiliation Unknown. 79/06/15. 2pp.

7908090677 Ack receipt of 790607 ltr supporting petition to intervene for hearing filed by Philippine Movement for Environ Protection Returns money sent to defray postal expenses.
CHILK, S.J. Office of the Secretary of the Commission. 79/06/21. 1p.

--7908090683 Requests NRC grant hearing re serious risks to [illegible] safety & well-being of Filipino public posed by proposed nuclear exports Requests copies of future decisions or orders concerning proceedings.
* Philippines. 79/06/07. 2pp.

--7908090683 Requests NRC grant hearing re serious risks to health, safety & well-being of Filipino public posed by proposed nuclear exports Requests copies of future decisions or orders concerning nuclear exports.
* Philippines. 79/06/07. 2pp.

7908290352 Forwards Concerned Citizens Reactor Export Review Board request for public hearings on proposed Philippine export.
HANCHETT, J.G. Region 5, San Francisco, Office of the Director. 79/06/27. 1p.

--7908290363 Notifies NRC of formation of Concerned Citizens Reactor Export Review Board Requests public hearings in US on proposed reactor export to Philippines.
ZARSKY, L. Concerned Citizens Reactor Export Review Board. 79/06/20. 28pp.

7908140262 Protests granting of export license to Westinghouse for sale of reactor to Philippines.
BINGHAM, D. ; MONTGOMERY, L. ; BARTLETT, P. Affiliation Unknown. 79/07/09 11pp

7908210055 Opposes sale of nuclear reactors to third world & Philippines in particular.
* Affiliation Unknown. 79/07/14 1p

7908170627 Expresses opposition to granting export license to Westinghouse to export reactor to Philippines.
MAZANO, A. Affiliation Unknown. 79/07/16 1p

7908210540 Ltrs opposing export of reactor to Philippines.
LACK, V. ; HARMON, M. ; HODGES, C. W. Affiliation Unknown. 79/07/20 16pp

7908220383 Letters expressing opposition to sale of reactors to Philippines & to reactor sales in general.
LACK, V. Affiliation Unknown. 79/07/20 14pp

7908240320 Ltrs opposing sale of nuclear reactors to Philippine govt.
LACK, V. Affiliation Unknown. 79/07/20 16pp

7908210054 Opposes sale of any nuclear reactors to Philippines due to potential for terrorism.
* Affiliation Unknown. 79/07/23 2pp

7908210058 Opposes sale of nuclear reactor to Philippines due to seismic activity at proposed site.
* Affiliation Unknown. 79/07/23 1p

7908220042 Ltrs opposing sale of nuclear reactor to Philippines.
GLASSMAN, N. ; LASSILA, J. D. ; SMITH, P. Affiliation Unknown. 79/07/23 42pp

7908220159 Ltrs opposing sale of Westinghouse reactor to Philippines. Certificate of Svc encl.
SITERBURN, T. ; CHRISTIAN, C. ; LOCKWOOD, C. A. Affiliation Unknown. 79/07/23 16pp

7908240166 Ltrs opposing sale of nuclear reactors to Philippine govt.
SOIRTA, V. ; GLASSMAN, N. ; LASSILA, J. D. Affiliation Unknown. 79/07/23 27pp

7908240180 Ltrs opposing sale of nuclear reactors to Philippine govt.
JOY, W. F. ; HENNEMAN, N. ; ROLEY, P. Affiliation Unknown. 79/07/23 6pp

DOCKET STN-50-580 ERIE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06 47pp

7908270181 Forwards discussion of floodplain issues to be included in FES per request.
BIVINS, W. S. Hydrology Meteorology Branch. 79/06/26 2pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02 70pp

7908080204 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/19 2pp

G. Inspection reports, IE Bulletins & correspondence

7908020349 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20 1p

7908150377 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07 1p

7908300294 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15 1p

DOCKET STN-50-581 ERIE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06 47pp

7908270181 Forwards discussion of floodplain issues to be included in FES per request.
BIVINS, W. S. Hydrology Meteorology Branch. 79/06/26 2pp

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02 70pp

7908080204 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/19 2pp

G. Inspection reports, IE Bulletins & correspondence

7908020349 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/07/20 1p

7908150377 Forwards IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." No action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/07 1p

7908300294 Forwards IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/08/15 1p

DOCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/04/18 3pp

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06 47pp

7908080140 Forwards NUREG-0576, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards. 79/07/20 2pp

7908230403 Advises that AZ Public Svc, acting for joint applicants, has decided not to continue w/licensing or other preliminary activities. NRC review process terminated. FES will not be published.
SELLS, D. E. Environmental Projects Branch 2. 79/07/25 2pp

B. Utility Preliminary Safety Analysis Report, amends

7908150034 Forwards errata pages for list of effective pages, Amend 3, to PSAR.
VAN BRUNT, E. E. Arizona Public Service Co. 79/06/27 3pp

C. Utility Environmental Report (ER), amends & correspondence

7908010478 Forwards comments on May 1979 environ rept, Suppl 2, re changes in original rept & provision of alternative suppl water source.
YOUNGBLOOD, J. A. ; MANN, J. Arizona, State of. 79/07/23 7pp

G. Adjudicatory correspondence

7905140562 Forwards unclassified transmittal memo re info potentially relevant to issue of sabotage of spent nuclear fuel. Also discusses SAND77-1927, "Transport of Radionuclides in Urban Environs Working Draft Assessment."
SOHINKI, S. M. Branch 3 79/04/25 2pp.

7906020258 First set of interrogatories & requests for production of documents, submitted to intervenor L. Bard. Certificate of Svc encl.
SOHINKI, S. M. Branch 3 79/05/14 21pp.

7908090292 Motion for extension until 790626 to comment on DES.
BARD, L. L. Bard - Intervenor 79/06/05 1p.

7908080301 State of CA & CA Public Utils Commission comments on adequacy of DES. Alleges failure of DES to comply w/NEPA provisions & urges State of CA & CA Public Utils Commission be listed as commenting agencies.
WEISMAN, S. A. California, State of 79/06/25 16pp.

7908080293 First set of interrogatories & requests for production of documents directed to joint applicants. Certificate of Svc encl.
BARD, L. L. Bard - Intervenor 79/06/28 15pp.

7908130028 Motion for extension until 790716 to respond to Carolina Energy Commission & Carolina Public Utils Commission 790620 statements of issues. Large number & detail of questions require addl time to study issues. Certificate of Svc encl.
GEHR, A. C. Snell & Wilmer 79/07/05 5pp.

M. Antitrust correspondence

7908160358 Responds to NRC 790511 request for antitrust review info. Forwards util opening brief of E-7777 proceeding for San Onofre 2 & 3.
BARRY, D. N. Southern California Edison Co. 79/08/10 10pp.

DOCKET STN-50-593 PALO VERDE NUCLEAR STATION, UNIT 5

A. Application/construction stage documents & correspondence

7908070310 Forwards NUREG/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments w/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908080140 Forwards NUREG-0578, "Nuclear Power Reactor Security Personnel Training & Qualification Plan Reviewer Workbook."
MILLER, J. R. Assistant Director for Site & Safeguards 79/07/20 2pp.

7908230403 Advises that AZ Public Svc, acting for joint applicants, has decided not to continue w/licensing or other preliminary activities. NRC review process terminated. FES will not be published.
SELLS, D. E. Environmental Projects Branch 2 79/07/25 2pp.

B. Utility Preliminary Safety Analysis Report, amends

7908130034 Forwards errata pages for list of effective pages, Amend 3, to PSAR.
VAN BRUNT, E. E. Arizona Public Service Co. 79/06/27 3pp.

C. Utility Environmental Report (ER), amends & correspondence

7908010478 Forwards comments on May 1979 environ rept, Suppl 2, re changes in original rept & provision of alternative suppl water source.
YOUNGBLOOD, J. A., MANN, J. Arizona, State of 79/07/23 7pp.

G. Adjudicatory correspondence

7905140562 Forwards unclassified transmittal memo re info potentially relevant to issue of sabotage of spent nuclear fuel. Also discusses SAND77-1927, "Transport of Radionuclides in Urban Environs Working Draft Assessment."
SOHINKI, S. M. Branch 3 79/04/25 2pp.

7906020258 First set of interrogatories & requests for production of documents, submitted to intervenor L. Bard. Certificate of Svc encl.
SOHINKI, S. M. Branch 3 79/05/14 21pp.

7908090292 Motion for extension until 790626 to comment on DES.
BARD, L. L. Bard - Intervenor 79/06/05 1p.

7908080301 State of CA & CA Public Utils Commission comments on adequacy of DES. Alleges failure of DES to comply w/NEPA provisions & urges State of CA & CA Public Utils Commission be listed as commenting agencies.
WEISMAN, S. A. California, State of 79/06/25 16pp.

7908080293 First set of interrogatories & requests for production of documents directed to joint applicants. Certificate of Svc encl.
BARD, L. L. Bard - Intervenor 79/06/28 15pp.

7908130028 Motion for extension until 790716 to respond to Carolina Energy Commission & Carolina Public Utils Commission 790620 statements of issues. Large number & detail of questions require addl time to study issues. Certificate of Svc encl.
GEHR, A. C. Snell & Wilmer 79/07/05 5pp.

M. Antitrust correspondence

7908160358 Responds to NRC 790511 request for antitrust review info. Forwards util opening brief of E-7777 proceeding for San Onofre 2 & 3.
BARRY, D. N. Southern California Edison Co. 79/08/10 10pp.

DOCKET STN-50-596 NEW HAVEN, UNIT 1

A. Application/construction stage documents & correspondence

7908010663 Forwards 790511 Town of Gardiner amended petition to intervene.
LEWIS, S. H. Branch 2 79/05/25 1p.

--7908010691 Amend to 790313 petition to intervene, adding new considerations.
KEEPING, W. Gardiner, NY 79/05/11 7pp.

7908140359 Discusses proposed suspension of CP application until Jan 1980. Requests environ review be given preferential treatment.
MULLER, D. R. Division of Site Safety & Environmental Analysis 79/06/01 2pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/06/06 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2 79/07/02 70pp.

7908170636 Discusses review of "The Zirconium Connection" forwarded 790501. Paper contains great deal of incorrect info. NRC did not conceal nature of Zircaloy-water reaction or source of hydrogen in TMI-2. Response to paper encl.
DENTON, H. R. Office of Nuclear Reactor Regulation 79/07/24 12pp.

7908070636 Responds to 790614 request for info. No endangered or threatened species known to exist in project impact area.
PUSHEE, G. F. Interior, Dept. of, Fish & Wildlife Service 79/07/31 1p.

B. Utility Preliminary Safety Analysis Report, amends

7908140522 Forwards Affidavit of Svc for Amend 4 to PSAR & CP application. Distribution list encl.
KINTIGH, A. E. New York State Electric & Gas Corp. 79/08/08 4pp.

C. Utility Environmental Report (ER), amends & correspondence

7908010646 Discusses 790419 & 24 meetings w/NY Public Svc Commission & util re statistical analysis of ecological data in environ rept.
GREY, R. New York, State of 79/05/17 2pp.

7908010493 Requests info w/respect to cost of coal re environ rept.
GREY, R. New York, State of. 79/05/18. 2pp.

7909270412 Forwards joint applicant response to util 790629 ltr re clarification of environ rept Amends 13 & 14.
BURSTEIN, S. Wisconsin Electric Power Co. 79/07/31. 5pp.

7908310504 Forwards Amend 5 to environ rept for review.
KINTIGH, A. E. New York State Electric & Gas Corp. 79/08/23. 2pp.

--7908310508 Amend 5 to environ rept for facility.
* New York State Electric & Gas Corp. 79/08/23. 250pp.

G. Adjudicatory correspondence

7908150234 Forwards NY State Siting Board order directing remand.
MATIAS, T. R. New York, State of. 79/01/10. 11pp.

7906070324 Forwards copy of 10CFR2 in response to 790424 telcon. W/o encl.
LEWIS, S. H. Branch 2. 79/04/25. 1p.

7905310456 Forwards portions of util environ rept re alternate site issue W/copy of NRC ltr to util requesting addl info on alternate sites Response from util will be sent to LPDR.
MULKEY, M. E. Branch 2. 79/04/27. 1p.

7908150076 Requests all rights & remedies of interested state in power plant siting cases under 10CFR2 715(c).
FEIRSTEIN, R. P. New York, State of. 79/05/04. 2pp.

7908170639 Opposes NRC recommendation that Ulster County, NY be allowed to intervene on discretionary basis limited to alternate site issue County affected by TMI radiation Amends petition to intervene.
EGEMEIER, S. J. Kingston, NY. 79/05/11. 5pp.

7908030269 Forwards Resolution 112 passed by Columbia County Board of Supervisors objecting to location of hearing outside of county.
LANE, C. D. New York, State of. 79/05/14. 1p.

--7908030275 Resolution 112 objecting to location of public hearings outside of county.
* Columbia County, NY. 79/05/09. 1p.

7906280061 Initial answer to petitions to intervene Recommends all petitioners be accepted as parties Defers response to petitions of Village of Mexico, NY & Oswego County, NY. Certificate of Svc encl.
MULKEY, M. E. Branch 2. 79/05/18. 17pp.

7908020392 Resolution authorizing county legislature chairman to file w/NRC appropriate petition & other documents on behalf of county, so as to become party-at-interest re NY State Electric & Gas Co application for two nuclear units.
SCHMIDT, R. W. Oswego, NY. 79/06/19. 2pp.

7908030007 Response to util 790611 proposed joint protocol & discovery rules submitted by intervenors Columbia County, Town of Stuyvesant & Concerned Citizens For Safe Energy Definitions of issues violate NRC rules.
KAFIN, R. J. Miller, Mannix, Lemery & Kafin. 79/06/26. 5pp.

7908210061 Opposes applicant 790611 comments on proposed protocol for joint hearings re consolidation of govt parties & proposed requirement to file lists of contested issues.
FEIRSTEIN, R. P. New York, State of. 79/06/26. 3pp.

7908150011 Replies to util comments re proposed protocol for hearings before ASLB & NY State Siting Board Urges rejection of proposals to modify proposed protocol or hearing schedule.
ENGEL, D. A. New York, State of. 79/06/27. 4pp.

7908300224 Forwards comments by State of NY Dept of Public Svc on proposed protocol for conduct of joint hearings before NRC & NY State Board on Electric Generation Siting & Environ.
INDYKE, C. M. New York, State of. 79/06/27. 1p.

--7908300248 Comments by State of NY Dept of Public Svc on proposed protocol for conduct of joint hearings before NRC & NY State Board on Electric Generation Siting & Environ Issue. Identification should occur after issuance of DES.
GREY, R. New York, State of. 79/06/27. 17pp.

7908300186 Response to filings re joint protocol submitted by licensee, intervenor Ecology Action of Oswego & NY State Public Svc Board. NRC will not participate as active party in proceedings. Certificate of Svc encl.
MULKEY, M. E., LEWIS, S. H. Branch 2. 79/07/03. 13pp.

7908170253 Submits comprehensive list of alternative sites & modes of generation in Case 80008 in compliance w/notice requirements of 16 NYCRR List will be narrowed after further review of sites is conducted. Maps w/site locations encl.
GREY, R. New York, State of. 79/07/05. 11pp.

7908300741 Notice per 16NYCRR70.20 Columbia County, NY, Town of Stuyvesant & Concerned Citizens for Safe Energy will testify re alternate site facilities & source of power as discussed in draft EIS Certificate of Svc encl.
KAFIN, R. J. Miller, Mannix, Lemery & Kafin. 79/07/05. 2pp.

7908230256 Forwards addl interrogatories re alternate sites & sources, aquatic ecology, land use & aesthetics & terrestrial ecology.
ENGEL, D. A. New York, State of. 79/07/06. 13pp.

7908080269 Forwards ASLB 790620 prehearing conference rept.
LEWIS, S. H. Branch 2. 79/07/10. 1p.

--7908080273 Notifies of procedural schedule set at 79-23 prehearing conference.
WENNER, S., PARIS, O. H., JORDAN, W. H. Atomic Safety and Licensing Board Panel. 79/06/20. 2pp.

7908300007 Statement of State of NY Dept of Environ Conservation per 16NYCRR70.20 Lists alternate sites & modes of generation. Fossil alternative site must be considered in conjunction w/use of refuse-derived fuel.
ENGEL, D. A. New York, State of. 79/07/10. 9pp.

7908170337 Responds to D Kiefer 790629 ltr re Case 80008 Applicant opposes request of League of Women Voters & Ecology Action of Tompkins County to place transcript in library Applicant must publish notice only on facility location.
SPINDEL, N. W. Huber, Magill, Lawrence & Farrell. 79/07/11. 3pp.

7908300732 Order certifying intervenor Ecology Action of Oswego 790426 interlocutory apppeal to NY State Board for Electric Siting & Environ w/recommendation for dismissal of CP proceedings. Application is premature & legally insufficient.
MADISON, S. R. New York, State of. 79/07/11. 10pp.

DOCKET STN-50-597 NEW HAVEN, UNIT 2

A. Application/construction stage documents & correspondence

7908010663 Forwards 790511 Town of Gardiner amended petition to intervene.
LEWIS, S. H. Branch 2. 79/05/25. 1p.

--7908010691 Amend to 790313 petition to intervene, adding new considerations.
KEEPING, W. Gardiner, NY. 79/05/11. 7pp.

7908140359 Discusses proposed suspension of CP application until Jan 1980 Requests environ review be given preferential treatment.
MULLER, D. R. Division of Site Safety & Environmental Analysis. 79/06/01. 2pp.

7908030263 Notification of 790613 meeting w/utils in Bethesda, MD to discuss policies re review of current CP & OL applications & criteria for establishing priorities for review of such applications.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/06/06. 47pp.

7908020041 Summary of 790613 meeting w/util representatives in Bethesda, MD to discuss current NRC CP & OL application review policies & to discuss criteria for establishing review priorities.
ROOD, H. Light Water Reactors Branch 2. 79/07/02. 70pp.

7908170636 Discusses review of "The Zirconium Connection" Forwarded 790501 Paper contains great deal of incorrect info. NRC did not conceal nature of Zircaloy-water reaction or source of hydrogen in TMI-2 Response to paper encl.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/24. 12pp.

7908070636 Responds to 790614 request for info No endangered or threatened species known to exist in project impact area.
PUSHEE, G. F. Interior, Dept of, Fish & Wildlife Service. 79/07/31. 1p.

B. Utility Preliminary Safety Analysis Report, amends

7908140522 Forwards Affidavit of Svc for Amend 4 to PSAR & CP application Distribution list encl.
KINTIGH, A. E. New York State Electric & Gas Corp. 79/08/08. 4pp.

C. Utility Environmental Report (ER), amends & correspondence

7908010446 Discusses 790419 & 24 meetings w/NY Public Svc Commission & util re statistical analysis of ecological data in environ rept.
GREY,R. New York, State of. 79/05/17. 2pp.

7908010483 Requests info w/respect to cost of coal,re environ rept.
GREY,R. New York, State of. 79/05/18. 2pp.

7908070412 Forwards joint applicant response to util 790629 ltr re clarification of environ rept Amends 13 & 14.
BURSTEIN,S. Wisconsin Electric Power Co. 79/07/31. 5pp.

7908310504 Forwards Amend 5 to environ rept for review.
KINTIGH,A.E. New York State Electric & Gas Corp. 79/08/23. 2pp.

--7908310508 Amend 5 to environ rept for facility.
* New York State Electric & Gas Corp. 79/08/23. 250pp.

Q. Adjudicatory correspondence

7908150234 Forwards NY State Siting Board order directing remand.
MATIAS,T.R. New York, State of. 79/01/10. 11pp.

7906070324 Forwards copy of 10CFR2 in response to 790424 telcon. W/o encl.
LEWIS,S.H. Branch 2. 79/04/25. 1p.

7905310456 Forwards portions of util environ rept re alternate site issue W/copy of NRC ltr to util requesting addl info on alternate sites Response from util will be sent to LPDR.
MULKEY,M.E. Branch 2. 79/04/27. 1p.

7908150076 Requests all rights & remedies of interested state in power plant siting cases under 10CFR2.715(c).
FEIRSTEIN,R.P. New York, State of. 79/05/04. 2pp.

7908170639 Opposes NRC recommendation that Ulster County,NY be allowed to intervene on discretionary basis limited to alternate site issue County affected by TMI radiation Amends petition to intervene.
EGEMEIER,S.J. Kingston, NY. 79/05/11. 5pp.

7908030269 Forwards Resolution 112 passed by Columbia County B... * Supervisors objecting to location of hearing outside of county.
LANE,C.D. New York, State of. 79/05/14. 1p.

--7908030275 Resolution 112 objecting to location of public hearings outside of county.
* Columbia County, NY. 79/05/09. 1p.

7906280061 Initial answer to petitions to intervene.Recommends all petitioners be accepted as parties.Defers response to petitions of Village of Mexico,NY & Oswego County,NY. Certificate of Svc encl.
MULKEY,M.E. Branch 2. 79/05/18. 17pp.

7908020392 Resolution authorizing county legislature chairman to file w/NRC appropriate petition & other documents on behalf of county, so as to become party-at-interest re NY State Electric & Gas Co application for two nuclear units.
SCHMIDT,R.W. Oswego, NY. 79/06/19. 2pp.

7908030007 Response to util 790611 proposed joint protocol & discovery rules submitted by intervenors Columbia County,Town of Stuyvesant & Concerned Citizens For Safe Energy.Definitions of issues violate NRC rules.
KAFIN,R.J. Miller, Mannix, Lemery & Kafin. 79/06/26. 5pp.

7908210061 Opposes applicant 790611 comments on proposed protocol for joint hearings re consolidation of govt parties & proposed requirement to file lists of contested issues.
FEIRSTEIN,R.P. New York, State of. 79/06/26. 3pp.

7908150011 Replies to util comments re proposed protocol for hearings before ASLB & NY State Siting Board.Urges rejection of proposals to modify proposed protocol or hearing schedule.
ENGEL,D.A. New York, State of. 79/06/27. 4pp.

7908300224 Forwards comments by State of NY Dept of Public Svc on proposed protocol for conduct of joint hearings before NRC & NY State Board on Electric Generation Siting & Environ.
INDYKE,C.M. New York, State of. 79/06/27. 1p.

--7908300248 Comments by State of NY Dept of Public Svc on proposed protocol for conduct of joint hearings before NRC & NY State Board on Electric Generation Siting & Environ Issue Identification should occur after issuance of DES.
GREY,R. New York, State of. 79/06/27. 17pp.

7908300196 Response to filings re joint protocol submitted by licensee, intervenor Ecology Action of Oswego & NY State Public Svc Board.NRC will not participate as active party in proceedings.Certificate of Svc encl.
MULKEY,M.E., LEWIS,S.H. Branch 2. 79/07/03. 13pp.

7908170253 Submits comprehensive list of alternative sites & modes of generation in Case 80008 in compliance w/notice requirements of 16 NYCRR.List will be narrowed after further review of sites is conducted.Maps w/site locations encl.
GREY,R. New York, State of. 79/07/05. 11pp.

7908300741 Notice per 16NYCRR70.20.Columbia County,NY,Town of Stuyvesant & Concerned Citizens for Safe Energy will testify re alternate site,facilities & source of power as discussed in draft EIS.Certificate of Svc encl.
KAFIN,R.J. Miller, Mannix, Lemery & Kafin. 79/07/05. 2pp.

7908230256 Forwards addl interrogatories re alternate sites & sources, aquatic ecology, land use & aesthetics & terrestrial ecology.
ENGEL,D.A. New York, State of. 79/07/06. 13pp.

7908080269 Forwards ASLB 790620 prehearing conference rept.
LEWIS,S.H. Branch 2. 79/07/10. 1p.

--7908080273 Notifies of procedural schedule set at 790523 prehearing conference.
WENNER,S., PARIS,O.H., JORDAN,W.H. Atomic Safety and Licensing Board Panel. 79/06/20. 2pp.

7908300007 Statement of State of NY Dept of Environ Conservation per 16NYCRR70.20.Lists alternate sites & modes of generation. Fossil alternative site must be considered in conjunction w/use of refuse-derived fuel.
ENGEL,D.A. New York, State of. 79/07/10. 9pp.

7908170332 Responds to D.Kiefer 790629 ltr re Case 80008.Applicant opposes request of League of Women Voters & Ecology Action of Tompkins County to place transcript in library.Applicant must publish notice only on facility location.
SPINDEL,N.W. Huber, Magill, Lawrence & Farrell. 79/07/11. 3pp.

7908300732 Order certifying intervenor Ecology Action of Oswego 790426 interlocutory apppeal to NY State Board for Electric Siting & Environ w/re commendation for dismissal of CP proceedings. Application is premature & legally insufficient.
MADISON,S.R. New York, State of. 79/07/11. 10pp.

DOCKET 50-599 CARROLL FACILITY I

Q. Adjudicatory correspondence

7908020558 Forwards State of IL petition to intervene.W/o encl.
KARMAN,M. Branch 2. 79/06/20. 1p.

--7908020561 Requests copy of State of IL petition to intervene.
SCHWAB,J.C. Iowa Public Interest Research Group. 79/06/15. 1p.

7908300533 Requests permission to make limited appearance statement at early site review hearing.
DOUGLAS,W.R. Iowa Socialist Party. 79/06/23. 1p.

--7908300543 Requests opportunity to testify before NRC at upcoming early site review hearing.
GRAVES,J. Association of Community Organizations for Reform Now-IA. 79/06/29. 1p.

7908170519 Requests to make limited appearance at hearing re licensee application for CP.
HOELSCHER,J. Affiliation Unknown. 79/06/29. 1p.

7908080179 Applicant response to State of IL 790615 brief opposing early site review.Urges rejection of IL request that review not be undertaken at this time.Certificate of Svc encl.
STEPTOE,P. Isham, Lincoln & Beale. 79/07/03. 7pp.

7908150227 Requests to speak at facility hearings as individual petitioner.
EBENER,D.R. Affiliation Unknown. 79/07/03. 1p.

7908080200 Forwards J Runyon, E Gogel & Citizens Against Nuclear Power petition for intervention re CP & early site review.
KODNER, J L. Affiliation Unknown. 79/07/06. 1p.

--7908080207 Petition for intervention & request for hearing filed pro se & as representatives of Citizens Against Nuclear Power. Affidavits encl.
RUNYON, J ., GOGEL, E. Affiliation Unknown. 79/07/12. 8pp.

7908080344 Forwards response to J Runyon 790705 petition to intervene, w/corrected page 2.
GOLDBERG, S C. Branch 2. 79/07/06. 1p.

--7908080351 Response to J Runyon & E Gogel 790611 intervention filed pro se & as members of Citizens Against Nuclear Power. Supports J Runyon as individual petitioner but opposes E Gogel & Citizens Against Nuclear Power. W/Certificate of Svc.
GOLDBERG, S C. Branch 2. 79/07/05. 8pp.

7908080170 Applicant answer to J Runyon, E Goge & Citizens Against Nuclear Power 790706 & JL Priske 790625 petition to intervene. Suggests limited participation of J Runyon et al & denial of J Priske. W/Certificate of Svc.
STEPTOE, P. Isham, Lincoln & Beale. 79/07/12. 5pp.

H. General correspondence

7908100412 Notifies of placement on direct distribution list.
NAUGHTON, W F. Commonwealth Edison Co. 79/07/25. 1p.

7908100444 Notifies of placement on direct distribution list.
NAUGHTON, W F. Commonwealth Edison Co. 79/07/25. 1p.

DOCKET 50-600 CARROLL FACILITY II

G. Adjudicatory correspondence

7908020558 Forwards State of IL petition to intervene. W/o encl.
KARMAN, M. Branch 2. 79/06/20. 1p.

--7908020561 Requests copy of State of IL petition to intervene.
SCHWAB, J C. Iowa Public Interest Research Group. 79/06/15. 1p.

7908300533 Requests permission to make limited appearance statement at early site review hearing.
DOUGLAS, W R. Iowa Socialist Party. 79/06/23. 1p.

--7908300543 Requests opportunity to testify before NRC at upcoming early site review hearing.
GRAVES, J. Association of Community Organizations for Reform Now-IA. 79/06/29. 1p.

7908170519 Requests to make limited appearance at hearing re licensee application for CP.
HOELSCHER, J. Affiliation Unknown. 79/06/29. 1p.

7908080179 Applicant response to State of IL 790615 brief opposing early site review. Urges rejection of IL request that review not be undertaken at this time. Certificate of Svc encl.
STEPTOE, P. Isham, Lincoln & Beale. 79/07/03. 7pp.

7908150227 Requests to speak at facility hearings as individual petitioner.
EBENER, D R. Affiliation Unknown. 79/07/03. 1p.

7908080200 Forwards J Runyon, E Gogel & Citizens Against Nuclear Power petition for intervention re CP & early site review.
KODNER, J L. Affiliation Unknown. 79/07/06. 1p.

--7908080207 Petition for intervention & request for hearing filed pro se & as representatives of Citizens Against Nuclear Power. Affidavits encl.
RUNYON, J ., GOGEL, E. Affiliation Unknown. 79/07/12. 8pp.

7908080344 Forwards response to J Runyon 790705 petition to intervene, w/corrected page 2.
GOLDBERG, S C. Branch 2. 79/07/06. 1p.

--7908080351 Response to J Runyon & E Gogel 790611 intervention filed pro se & as members of Citizens Against Nuclear Power. Supports J Runyon as individual petitioner but opposes E Gogel & Citizens Against Nuclear Power. W/Certificate of Svc.
GOLDBERG, S C. Branch 2. 79/07/05. 8pp.

7908080170 Applicant answer to J Runyon, E Goge & Citizens Against Nuclear Power 790706 & JL Priske 790625 petition to intervene. Suggests limited participation of J Runyon et al & denial of J Priske. W/Certificate of Svc.
STEPTOE, P. Isham, Lincoln & Beale. 79/07/12. 5pp.

H. General correspondence

7908100412 Notifies of placement on direct distribution list.
NAUGHTON, W F. Commonwealth Edison Co. 79/07/25. 1p.

7908100444 Notifies of placement on direct distribution list.
NAUGHTON, W F. Commonwealth Edison Co. 79/07/25. 1p.

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

7908280871 Forwards safeguards contingency plan, revised 790501 to address requests of NRC 790306 ltr. Plan withheld (ref 10CFR2.790).
TOY, H L. Physical Security Licensing Branch. 79/05/23. 2pp.

7908020175 Forwards L. ..p Rept 70-0008/79-03 & 30-05728/79-02 on 790507-11. No noncompliance noted.
DAVIS, A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/11. 2pp.

--7908020180 IE Insp Rpts 70-0008/79-03 & 30-5728/79-02 on 790507-11. No noncompliance noted. Major areas inspected: health & safety, including organization, criticality safety, facility mods & safety committees.
PECK, E E., FISHER, W L. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/07. 6pp.

7908080123 Requests schedule for qualifying security personnel in order to complete review of site security personnel training plan. Schedule should be submitted by 790715 so that plan can be approved by 790731.
MCCORKLE, G W. Physical Security Licensing Branch. 79/06/29. 2pp.

7908130219 Notifies of review of conceptual decommissioning plan w/cost estimate & financial plan in 781122, 1215 & 790425 submittals. Commitments will be made conditions of Licenses SNM-7 & 34-6854-5 when financial plan is implemented.
ROUSE, L C. Fuel Reprocess. & Recycle Branch (Pre 790727). 79/06/29. 2pp.

7908150... F...wards "Seismic Risk Analysis for Battelle Memorial Inst, Nuclear Research Facility, West Jefferson, OH."
ROUSE, L C. Fuel Reprocess. & Recycle Branch (Pre 790727). 79/07/09. 1p.

--7908150393 "Seismic Risk Analysis for Battelle Memorial Inst, Nuclear Research Facility, West Jefferson, OH."
* TERA Corp. 78/12/29. 41pp.

7908210556 Forwards revised responsibility matrix for safeguards contingency plan.
TOY, H L. Battelle Memorial Institute, Columbus Laboratories. 79/07/09. 1p.

7908240344 Forwards revisions to App E of emergency plans & procedures.
TOY, H L. Battelle Memorial Institute, Columbus Laboratories. 79/07/23. 33pp.

7908170330 Informs that revised safeguards contingency plan is acceptable. Advises of incorporation of present plan in addition to physical security & site security personnel training plans into license.
MCCORKLE, G W. Physical Security Licensing Branch. 79/07/31. 2pp.

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP.

7908140464 Forwards comprehensive evaluation rept containing consolidated observations of evaluation teams which visited Canoga Park, CA facility. Rept withheld (ref 10CFR2.790).
BURNETT, R F. Division of Safeguards. 79/04/03. 2pp.

7908090442 Notifies of impending R&D effort re process for removal of Zr cladding & U-Zr intermetallic compound. Work is authorized under License SNM-21 m& requires no license amend or mod.
REMLEY, M E. Rockwell International Corp. 79/06/21. 2pp.

7908210083 Responds to 790621 ltr describing R&D work involving irradiated SNM. R&D work is within intent of 10CFR70.31(e); no addl info required at this time.
PARTLOW, J O. Material Control Licensing Branch. 79/06/24. 1p.

7908030527 Discusses amend of Sections 2 & 9 of Matl & Plant Protection Amend MPP-1. Ofc of Controller notified to refund amend fee overpayment.
MILLER, W. O. License Fee Management Branch 79/06/25 1p.

7908140452 Notifies that 790601 safeguards contingency plan acceptable. Physical security plan & safeguards contingency plan have been incorporated into Amend MPP-1 License SNM-21. Plan is withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch 79/06/27 2pp.

7908220079 Forwards "Seismic Risk Analysis for Atomics Intl Nuclear Matls Development Facility, Santa Susana, CA."
ROUSE, L. C. Fuel Reprocess. & Recycle Branch (Prn 790727) 79/07/09 1p.

7908220084 "Seismic Risk Analysis for Atomics Intl Nuclear Matls Development Facility, Santa Susana, CA."
* TERA Corp 78/12/29 48pp.

7908070823 Notifies that license review has been assigned to H Bartz effective 790709. Arrangements will be made to visit facility.
PARTLOW, J. G. Material Control Licensing Branch 79/07/10 1p.

7908290716 Discusses decladding tests on fuel proposed by Energy Sys Group. No license amend is necessary per 10CFR70.51(e). Forwards draft ltr re NRC requirements for SNM control or production quantities W/o encl.
BARTZ, H. Material Control Licensing Branch 79/07/23 2pp.

7908220596 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/10 1p.

DOCKET 70-0027 BABCOCK & WILCOX CO.

7908150332 Expresses concern over certification & use of KAPL std in measurement control program.
PARTLOW, J. G. Material Control Licensing Branch 79/05/25 1p.

7908280859 IE Insp Rept 70-0027 on 790514-18. No noncompliance noted. Major areas inspected: security organization, access controls, detection aids, response controls & rept of incidents.
MOORE, D. E., TOBIN, W. J. Region 2, Atlanta, Office of the Director 79/06/06 1p.

7908140135 Discusses certification & use of finished fuel std in measurement control program. Testing shows no significant bias introduced by major constituents in std matl.
MCCLANAHAN, M. H. Babcock & Wilcox Co. 79/06/12 2pp.

7908140316 Requests suspension of activity on MG Dameron 790117 request for exception to portion of 10CFR70.24 for License SNM-42. Addl info concerning emergency evacuations will be submitted by 790715.
MCCLANAHAN, M. H. Babcock & Wilcox Co. 79/06/12 1p.

7908170152 Forwards IE Insp Rept 70-027/79-09 on 790529-0601. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/12 2pp.

7908170158 IE Insp Rept 70-027/79-09 on 790529-0601. No noncompliance noted. Major areas inspected: facility changes & mods; safety committees, operations; maint & packaging radioative matls.
KAHLE, J. B. Region 2, Atlanta, Office of the Director.
POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/12 6pp.

7908150244 Requests revisions to "Security Personnel Training & Equipment Requirements" submitted in 790219 ltr. Revision request list encl. Info contained in 790215 ltr will be withheld per 10CFR2.790.
MCCORKLE, G. W. Physical Security Licensing Branch 79/06/14 3pp.

7908210600 Forwards revision to MG Dameron 790117 ltr re license change requests.
MCCLANAHAN, M. H. Babcock & Wilcox Co. 79/07/11 1p.

7908210601 Requests amend to License SNM-42 to delete night shift mgt audit & change emergency plan. Discusses & justifies request. Forwards amend fee.
MCCLANAHAN, M. H. Babcock & Wilcox Co. 79/07/11 7pp.

7908210144 Adds license condition to license Amend MPP-1, requiring that two people attest to contents of containers & vaults prior to tamper-safing.
PARTLOW, J. G. Material Control Licensing Branch 79/07/12 1p.

7908240392 Forwards preliminary limit of error discussion based on in-depth reviews by Statistical Section. Matl withheld (ref 10CFR2.790). Several changes will be incorporated in May/June inventory.
MCCLANAHAN, M. H. Babcock & Wilcox Co. 79/07/16 1p.

7908070292 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/20 1p.

7908170624 Forwards revised pages to measurement control plan for review. Forwards amend fee. Supporting info withheld (ref Atomic Energy Act of 1954).
MCCLANAHAN, M. H. Babcock & Wilcox Co. 79/07/20 3pp.

7908150140 Forwards B&W check which accompanied 790720 ltr. Page changes to measurement control plan are not subj to fees.
WEISS, D. License Fee Management Branch 79/07/25 1p.

7908090611 Responds to 790716 ltr & 27 telcon re limit of error calculations. Objects to lack of statistical info for operations & misleading ref to milestones. "Jaech rules" used by util for item & measurement covariance.
PARTLOW, J. G. Material Control Licensing Branch 79/08/03 1p.

7908170003 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/08/08 1p.

DOCKET 70-0033 TEXAS INSTRUMENTS, INC.

7908[illegible]26 Requests amend to License SNM-23, Amend 8, permitting use of bor[illegible]4 phenolic foam insulated shipping container for storage & transfer of U-235 fuel elements. Supporting info encl.
HOPPER, C. M. Texas Instruments, Inc. 79/05/01 13pp.

7908140067 Notifies that 790412 revision to safeguards contingency plan is acceptable. Plan is incorporated in Amend MPP-1 of License SNM-23. Plan withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch 79/06/06 2pp.

7908150517 Revises 790501 request for amend to License SNM-23. Cover ltr replaces 790501 cover ltr. Requests Amend 8 re temporary storage of loaded shipping containers & use of new insulating foam. Supporting documentation encl.
HOPPER, C. M. Texas Instruments, Inc. 79/06/12 13pp.

7908200249 Determines that request to begin inventory on 790625 is acceptable. Requests that subsequent inventories follow previously designated schedule.
PARTLOW, J. G. Material Control & Accountability Development Branch 79/06/13 1p.

7908150296 Forwards request for changes to "General Criteria for Security Personnel." Requests revision within 30 days. Encl to 790215 ltr withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch 79/06/19 4pp.

7908130657 Forwards revision to fundamental nuclear matl control plan for License SNM-23. Revision provides updates of plan for consistency w/procedural rept. names & assignments of duties. Encl withheld (ref 10CFR2.790).
HOOPER, C. M. Texas Instruments, Inc. 79/06/20 2pp.

7908070408 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 3pp.

7908030120 Discusses open items re scrap recovery & use of gamma scan procedures to validate quantity of U oxide powder at time of physical inventory.
BARTZ, H. Material Control Licensing Branch 79/06/25 1p.

7908230252 Submits correction to copying error discovered in 790501 request for license amend.
HOOPER, C. M. Texas Instruments, Inc. 79/06/27 2pp

7908080101 Approves 790620 revisions to Fundamental nuclear matl control plan. License Condition 2.1 of Amend MPP-1 to License SNM-33 is revised.
PARTLOW, J. G. Material Control Licensing Branch 79/07/09 1p

7908070833 Notifies that license review has been assigned to DA Huff, effective 790709. Arrangements will be made to visit facility.
PARTLOW, J. G. Material Control Licensing Branch 79/07/10 1p

7908300065 Responds to 790605 ltr re Apr 1979 comprehensive evaluation rept. Actions are acceptable. Ltr withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch 79/07/10 1p

7908150190 Advises of fee overpayment for Amend MPP-1 to License SNM-23, incorporating safeguards contingency plan. Ofc of Controller notified to issue refund.
MILLER, W. O. License Fee Management Branch 79/07/16 1p

7908070215 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/18 1p

7908140016 Ack receipt of NRC 790619 ltr & forwards criteria for security personnel. Recommends waiver of education requirement to avoid discrimination. Encl withheld (Ref Atomic Energy Act of 1954).
SHERMAN, F. L. Texas Instruments, Inc. 79/07/18 1p

7908220328 Notifies that review of manpower expenditures required for review of application for Amend 11 to License SNM-23 was lower than amend fee. NRC Ofc of Controller has been notified to forward refund.
MILLER, W. O. License Fee Management Branch 79/08/02 1p

7908280199 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

DOCKET 70-0036 COMBUSTION ENGINEERING, INC.

7908150170 Submits review of 790112 license amend application & 790308 suppl re Decommissioning Plan PC 79047A. Recommends amend be issued.
STEVENSON, R. L. Fuel Process. & Fab. Branch (Pre 790727) 79/05/05 2pp

7908140222 Responds to Item B of attachment to 790118 ltr. Forwards analysis supported by experimental data. Release of spent limestone for unrestricted use will have negligible short or long-term environ impact.
ESKRIDGE, H. E. C-E Power Systems 79/06/08 4pp

7908150262 Approves 790604 requests for hearings & reanalysis re necessity of License Conditions 4.3 & 4.5 of matls & plant protection Amend MPP-3. Info forwarded in 790604 ltr will be withheld (ref 10CFR2.790).
BURNETT, R. F. Division of Safeguards 79/06/18 1p

7908210380 Responds to 790516 request for assessment of potential magnitude of undetected bias in inventory difference due to degree of verification performed on ref stds. Undetected bias is not significant.
ESKRIDGE, H. E. C-E Power Systems 79/07/11 1p

DOCKET 70-0135 BABCOCK & WILCOX CO.

7908080646 Confirms 790606 meeting w/vendor in King of Prussia, PA re findings of IE Insp Rept 70-0135/78-25 & corrective actions per 790501 ltr.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/01 1p

7908130620 Forwards revised page 6 for inclusion in safeguards contingency plan, Revision 0. Page withheld (ref 10CFR2.790).
AUSTIN, M. A. Babcock & Wilcox Co. 79/06/06 1p

7908150275 Forwards revised pages for Licenses SNM-145 & SNM-414, reflecting deletion of regulatory projects coordinator & alternation of requirements for licensing & nuclear safety specialist. Remits fee under separate cover.
AUSTIN, M. A. Babcock & Wilcox Co. 79/06/18 7pp

7908140312 Responds to 790531 ltr re security training & qualification plan for Licenses SNM-145 & SNM-414. Forwards revisions to supersede Sections 3.1-3.3, inclusive, of both licenses. Encl withheld (ref Atomic Energy Act of 1954).
AUSTIN, M. A. Babcock & Wilcox Co. 79/06/19 2pp

7908210152 Forwards IE Insp Repts 70-0135/79-10 & 70-0364/79-11 on 790409-13. No noncompliance noted.
MARTIN, W. G. Region 1, Philadelphia, Safeguards Branch 79/06/19 2pp

--7908210158 IE Insp Repts 70-0135/79-10 & 70-0364/79-11 on 790409-13. No noncompliance noted. Major areas inspected: facility operations, shipping & receiving, inventory reconciliation & records & repts.
RATTA, A. D., BISSETT, P. H. Region 1, Philadelphia, Office of the Director JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch 79/06/15 4pp

7908090582 Requests approval of Tech Spec changes for Licenses SNM-145 & SNM-414. Factory Mutual Engineering ltr supporting proposed changes encl.
AUSTIN, M. A. Babcock & Wilcox Co. 79/06/21 4pp

--7908090590 Tech Spec changes for Licenses SNM-145 & SNM-414 re personnel replacement procedures, Safety Advisory Board meeting minutes & storage of contaminated & combustible solid matls.
AUSTIN, M. A. Babcock & Wilcox Co. 79/06/21 10pp

7908160209 Advises that Section 9 of Matls & Plant Protection Amend MPP-1 to License SNM-145 is amended. Physical security plan, safeguards contingency plan & guard training & qualification plan incorporated in amend.
MCCORKLE, G. W. Physical Security Licensing Branch 79/06/29 1p

--7908160217 Amend to License SNM-145, Section 9 of Matls & Plant Protection Amend MPP-1, "Physical Protection Requirements."
* Physical Security Licensing Branch 79/06/29 1p

7908140095 Forwards updated Tech. Spec. I.B.5.1.4.A.1 for License SNM-145, re handling of contaminated, combustible solid matl in low enriched U process areas. Supporting demonstration pages encl.
AUSTIN, M. A. Babcock & Wilcox Co. 79/07/02 4pp

7908170178 Determines that 790105, 0226 & 0612 submittals do not adversely effect safeguards plan. Amends conditions of Amend. MPP-1 to Licenses SNM-145 & SNM-414. Submittals withheld (ref 10CFR2.790).
PARTLOW, J. G. Material Control Licensing Branch 79/07/10 3pp

7908240375 Requests approval for replacement of Sections 7-9 of physical security plan. Matl withheld (ref 10CFR2.790).
AUSTIN, M. A. Babcock & Wilcox Co. 79/07/12 1p

7908280151 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/10 1p

7908220347 Approves revised pages to Nuclear Matls Div. PA Operations, security training & qualification plan & 790219 request to replace commitments in Apollo & Parks Township security plans. Plan withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch 79/08/13 1p

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC.

7908130378 Requests indefinite suspension of stack fluoride program due to labor problems. Sampling will resume upon plant startup.
MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/05/01 1p

--7908130381 Notifies that 790501 request for sus[illegible]sion of monitoring program will require licens[illegible] amend fee of $1[illegible]
WEISS, D. License Fee Management Branch 79/05/11 2pp

--7908130383 Forwards $150 for license amend fee, as requested in 790511 ltr. W/o encl.
MANSER, W. C. Babcock & Wilcox Co. 79/05/29 1p

DOCKETED ITEMS

7908060476 Ack 790527 ltr re discrepancy between 790316 ltr & Condition 29 of renewed license.Emergency evacuation drill is required annually for each shift.
CROW,W.T. Fuel Process. & Fab. Branch (Pre 790727) 79/05/23 1p.

7908030605 Responds to I & I Insp Rept 70-0143/79-17.Required weekly test on criticality alarm sys reinstated.
MANSER,W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/06/05 2pp.

7908140081 Responds to 790504 ltr re License Conditions 9.3.10.L, 9.3.10.2.& 9.3.10.3.Postponement of closing of barriers is acceptable.Amends Section 9 of Amend MPP-1 to License SNM-124.
MCCORKLE,D.W. Physical Security Licensing Branch 79/06/06 2pp.

7908140159 Forwards Amend MPP-1 to SNM-124 & amend fee. Encl withheld (ref 10CFR2.790).
HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/06/06 2pp.

7908170479 Forwards IE Insp Rept 70-0143/79-20 on 790523-25.No noncompliance noted.Details of insp rept withheld (ref 10CFR2.790).
KENNA,W.B. Region 2, Atlanta, Safeguards Branch 79/06/12 2pp.

--7908170486 IE Insp Rept 70-0143/79-20 on 790523-25.No noncompliance noted.Major areas inspected:security organization including keys,locks,combinations, response,controls & records & repts.Details withheld (ref 10CFR2.790).
MOORE,D.E. Region 2, Atlanta, Office of the Director
TOBIN,W.J. Region 2, Atlanta, Safeguards Branch 79/06/12 1p.

7908140210 Discusses WC Manser 790501 request for indefinite suspension of stack fluoride monitoring program required by Condition 46 of License SNM-124.Recommends suspension of program until two weeks after settlement of current strike.
MANSER,W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/06/13 1p.

7908080413 Ack 790620 ltr & grants 30-day extension of 790618 submittal date for Section 7.0 revision to fundamental nuclear material control plan.Urges submittal before 790718 extended due date.
PARTAIN,J.O. Material Control Licensing Branch 79/06/22 1p.

7908140327 Notifies of strike at plant.Revision of MBA.6 scanning procedure & mixing & sampling tests for License SNM-124 will be completed 60 days after return to work of striking workers.
HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/06/22 1p.

7908150427 Discusses NFS request for extension to 790818 for inventory date or conducting early inventory on 790618.If 790507 holdup values for 790618 inventory could be booked.
JOY,D.R. Office of Nuclear Material Safety & Safeguards 79/06/22 1p.

7908150031 Forwards matl balances covering inventory period 790309-0507 for highly enriched U & Pu.Withheld (ref 10CFR2.790).
HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/06/26 2pp.

7908150043 Forwards info re compliance w/10CFR70.52,per Plant 1 790507 physical inventory of high enriched U exceeding limit of error.Encl withheld (ref 10CFR2.790).
HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/06/26 2pp.

7908140024 Forwards matl balances for inventory period 790512-0618.Encl withheld (ref Atomic Energy Act of 1954).
HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/07/04 1p.

7908160088 Notifies that partial refund of amend fee re site security training plan is being processed.
MILLER,W.O. Licensing Management Branch 79/07/05 1p.

7908170447 Notifies that Nuclear Fuel Svcs,Inc amend fee should be partially refunded.
MILLER,W.O. License Fee Management Branch 79/07/05 1p.

7908150242 Forwards comments re NRC 790525 ltr.Comments withheld (ref 10CFR2.790).
HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/07/06 2pp.

7908150543 Forwards IE Insp Rept 70-0143/79-22 on 790604-08.No noncompliance noted.
KENNA,W.B. Region 2, Atlanta, Safeguards Branch 79/07/06 2pp.

--7908150553 IE Insp Rept 70-0143/79-22 on 790604-08.No noncompliance noted.Major areas inspected:physical inventory verification. Details withheld (ref 10CFR2.790).
CLAY,E.L., TODD,G.A., GILLESPIE,F.P. Region 2, Atlanta, Office of the Director 79/07/06 1p.

7908220224 Requests registration as user of Model RMG-172.Forwards fee for Category IIC renewal.
MICHEL,C.J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/07/06 1p.

7908240143 Ack receipt of 790626 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0143/79-11.
KENNA,W.B. Region 2, Atlanta, Safeguards Branch 79/07/06 1p.

--7908240152 Responds to NRC 790417 ltr re violation noted in IE Insp Rept 70-0143/79-11.Corrective actions withheld (ref 10CFR2.790).
MANSER,W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/06/26 1p.

--7908240157 Request 30-day extension for response to NRC 790417 ltr re violation noted in IE Insp Rept 70-0143/79-11.Delay is due to labor problems at facility.
MANSER,W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/05/01 1p.

--7908240160 Forwards IE Insp Rept 70-0143/79-11 on 790326-30 & notice of violation.Notice of violation withheld (ref 10CFR2.790).
KENNA,W.B. Region 2, Atlanta, Safeguards Branch 79/04/17 2pp.

--7908240164 IE Insp Rept 70-0143/79-11 on 790326-30.Noncompliance noted: failure to submit rept within 30 days of taking physical inventory on 790109 & failure to measure stds over range. Details withheld (ref 10CFR2.790).
BATES,J.W., ROBERTSON,J.S.C., GILLESPIE,F.P. Region 2, Atlanta, Office of the Director 79/04/09 1p.

7908270115 Discusses IE insp of License 70-0143-24 on 790618-22.No noncompliance noted.Major areas inspected:program for safeguarding SNM under 10CFR70 provisions.
KENNA,W.B. Region 2, Atlanta, Safeguards Branch 79/07/10 2pp.

7908170067 Ack receipt of IE Insp Rept 70-0143/79-19 on 790529-0601.No proprietary info.
MANSER,W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/07/11 1p.

--7908170071 Forwards IE Insp Rept 70-0143/79-19 on 790529-0601.No noncompliance noted.
SUTHERLAND,J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/19 1p.

--7908170074 IE Insp Rept 70-0143/79-19 on 790529-0601.No noncompliance noted.Major areas inspected:radiological monitoring program, mgt controls,environ monitoring stations & monitoring data.
SUTHERLAND,J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. PEERY,W.W. Region 2, Atlanta, Office of the Director 79/06/18 3pp.

7908220072 Responds to 790706 ltr requesting investigation of facility. Current monitoring activities reveal no imminent danger. Further insps being made.Will contact local representative.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/12 1p.

7908210606 Notifies that mods outlined in '81229 ltr will be complete 60 days after union members return to work.
MICHEL,C.J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/07/13 1p.

7908020017 Advises that actual fee for license Amend MPP-1, re safeguards emergency plan is less than amount paid w/790216 application.Overpayment will be refunded.
MILLER,W.O. License Fee Management Branch 79/07/16 1p.

7908080019 Discusses 790709-13 NFS site visit & audit review of NFS 70.57 plan.Review proposes to establish whether measurement control program was fully implemented & to verify adequacy of calibr procedures.
ROY,D. Material Control Licensing Branch 79/07/18 2pp.

7908070299 Requests cooperation in data-gathering activities to provide NRC Commissioners,public & media w/up-to-date operating status of power reactors.Info requests will not be made while plant is in shutdown mode.
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 79/07/20 1p.

7908140073 Finds Section 7.0 revision to fundamental nuclear matl control plan submitted w/790717 ltr acceptable License Condition 2.1 of Amend MMP-1 to License SNM-124 revised to incorporate Section 7.0.
PARTLOW, J. G. Material Control Licensing Branch. 79/07/26. 1p.

7908270275 Ack receipt of IE Insp Rept 70-0143/79-29 on 790703-08. No proprietary info.
MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 79/07/31. 1p.

--7908270278 Forwards IE Insp Rept 70-0143/79-29 on 790703-08. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/16. 2pp.

--7908270282 IE Insp Rpt 70-0143/79-29 on 790723-08. No noncompliance noted. Major areas inspected: air sampling data; contamination surveys; effluent controls & review of operator qualifications.
KAHLE, J. B. Region 2, Atlanta, Office of the Director.
POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/16. 4pp.

7908300506 Ack receipt of IE Insp Rept 70-0143/79-29 on 790716. No proprietary info.
MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 79/07/31. 1p.

7908300554 Ack receipt of IE Insp Rept 70-0143/79-31 on 790719-21. No proprietary info.
MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 79/08/06. 1p.

--7908300563 Forwards IE Insp Rept 70-0143/79-31 on 790719-21. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/26. 1p.

--7908300568 IE Insp Rept 70-0143/79-31 on 790719-21. No noncompliance noted. Major areas inspected: NRC surveillance logs & concerns; followup on U spill & followup on concerns of workers.
KAHLE, J. B.; POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/26. 5pp.

7908170005 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08. 1p.

7908210126 Ack receipt of 790801 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/79-30.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/08/10. 1p.

--7908210130 Ack receipt of NRC 790816 ltr re violations noted in IE Insp Rept 79-0143/79-30. No proprietary info.
MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 79/08/01. 2pp.

--7908210137 Forwards IE Insp Rept 70-0143/79-30 on 790703-08 & notice of violation.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/08/16. 2pp.

--7908210141 Notice of violation from insp on 790703-08.
* Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/16. 1p.

--7908210148 IE Insp Rept 70-0143/79-30 on 790703-08. Noncompliance noted: failure to conform to specific posted limits at one work station.
CORYELL, G. P. Region 2, Atlanta, Office of the Director.
POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/07/13. 4pp.

7908160360 Forwards complete NRC Task Force Rept (proprietary) & 781227 Task Force Rept summary (nonproprietary). Requests application for withholding info within 20 days if desired.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/12/12. 2pp.

--7908160361 Finds no proprietary info in Task Force Rept summary on matl control & accountability.
MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 79/01/05. 1p.

--7908160364 Nonproprietary summary of "NRC Task Force Rept on Matl Control & Accountability Nuclear Fuel Svcs, Inc."
* Commission. 78/12/27. 4pp.

DOCKET 70-0152 PURDUE UNIV.

7908130612 Requests amends to Sections III.B.1-5 of security plan. Amends withheld (ref 10CFR2.790).
CLIKEMAN, F. M. Purdue Univ. 79/06/01. 1p.

DOCKET 70-0157 TEXAS, UNIV. OF

7908030575 Ack receipt of 790507 ltr responding to 790410 notice of violation. Corrective actions will be reviewed during next insp. Corrective actions withheld (ref 10CFR2.790).
NORDERHAUG, L. R. Region 5, San Francisco, Office of the Director. 79/06/08. 1p.

DOCKET 70-0310 SCHLUMBERGER WELL SERVICES

7908290027 Informs applicant that 780530 application for renewal of License SNM-287 is timely & license will not expire until final determination of application.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727). 79/07/12. 1p.

DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO.

7908130384 Forwards listing of physical inventories requested in 790313 ltr seeking addition of window to Pu plant physical inventory schedule. Listing withheld (ref 10CFR2.790).
AUSTIN, M. A. Babcock & Wilcox Co. 79/05/01. 1p.

--7908130385 Forwards $150 fee for consideration of Pu physical inventory schedules.
AUSTIN, M. A. Babcock & Wilcox Co. 79/05/22. 1p.

--7908130388 Notifies of acceptance of 790501 request for Pu physical inventories. Fee of $150 is required for license amend. as specified in 10CFR170.
WEISS, D. License Fee Management Branch. 79/05/11. 7pp.

7908150036 Discusses B&W request for relief from Condition 37 to License SNM-414 re mods of certain ventilation sys by 791231. Acceptable to postpone mods until starting of activities.
BURKHARDT, W. Fuel Reprocess. & Recycle Branch (Pre 790727). 79/06/18. 1p.

7908150275 Forwards revised pages for Licenses SNM-145 & SNM-414, reflecting deletion of regulatory projects coordinator & alternation of requirements for licensing & nuclear safety specialist. Remits fee under separate cover.
AUSTIN, M. A. Babcock & Wilcox Co. 79/06/18. 7pp.

7908170310 Notifies that License SNM-414 is amended to revise time required in License Condition 37 for completion of ventilation mods for hot cell & Fab 6 areas, until process activities are scheduled for these areas.
ROUSE, L. C. Fuel Process. & Fab. Branch (Pre 790727). 79/06/18. 1p.

7908140312 Responds to 790531 ltr re security training & qualification plan for Licenses SNM-145 & SNM-414. Forwards revisions to supersede Sections 3.1-3.3, inclusive, of both licenses. Encl withheld (ref Atomic Energy Act of 1954).
AUSTIN, M. A. Babcock & Wilcox Co. 79/06/19. 2pp.

7908210152 Forwards IE Insp Repts 70-0135/79-10 & 70-0364/79-11 on 790409-13. No noncompliance noted.
MARTIN, W. G. Region 1, Philadelphia, Safeguards Branch. 79/06/19. 2pp.

--7908210158 IE Insp Repts 70-0135/79-10 & 70-0364/79-11 on 790409-13. No noncompliance noted. Major areas inspected: facility operations; shipping & receiving; inventory reconciliation & records & repts.
RATTA, A. D.; BISSETT, P. H. Region 1, Philadelphia, Office of the Director. JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch. 79/06/15. 4pp.

7908220034 Notifies that all Region 1 comments discussed 781221 were considered in formulation of 790202 license conditions for SNM-414.
CROCKER, H. W. Region 1, Philadelphia, Office of the Director. 79/06/20. 1p.

7908090582 Requests approval of Tech Spec changes for Licenses SNM-145 & SNM-414.Factory Mutual Engineering ltr supporting proposed changes encl.
AUSTIN, M. A. Babcock & Wilcox Co. 79/06/21 4pp.

7908070367 Notifies of intent to install second communications sys. linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/06/22 3pp.

7908130347 Forwards NUREG-0547, "Effects of Natural Phenomena on B&W Plutonium Fabrication Plants at Parks Township Site, Leechburg Pa." Accepts rept as summary of findings of analysis.
AYER, J. E. ; BURKHARDT, W. Fuel Reprocess. & Recycle Branch (Pre 790727) 79/06/27 1p.

7908150571 Forwards NUREG-0547, "Effects of Natural Phenomena on B&W plutonium Fabrication Plant at Parks Township Site, Leechburg, PA." Summary supports renewal of License SNM-4 4.
ROUSE, L. C. Fuel Process. & Fab. Branch (Pre 790727) 79/06/27 1p.

7908300719 Responds to 790418 & 0426 ltrs forwarding safeguards contingency plan. Revision 0 Finds plan acceptable & appropriate to incorporate into matl & plant protection amend to license.
MCCORKLE, G. W. Physical Security Licensing Branch. 79/06/27 2pp.

7908100355 Requests submittal of administrative fee required for amend to License SNM-414, revising physical security plan.
WEISS, D. License Fee Management Branch. 76/06/29 1p.

7908170178 Determines that 790105, 0226 & 0612 submittals do not adversely affect safeguards plan. Amends conditions of Amend MPP-1 to Licenses SNM-[illegible] & SNM-414. Submittals withheld (ref 10CFR2.790).
PARTLOW, J. G. Material Control Licensing Branch. 79/07/10 3pp.

7908240381 Requests approval for replacement of Sections 7 & 8 of physical security plan, Revision 1, for SNM-414. Forwards Sections 7 & 8. Matl withheld (ref 10CFR2.790).
AUSTIN, M. A. Babcock & Wilcox Co. 79/07/13 1p.

7908070202 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18 1p.

7908140137 Requests amend fee for amend to License SNM-414 for exception from 10CFR73.60(a)(1) requirements.
WEISS, D. License Fee Management Branch. 79/07/19 1p.

7908220303 Forwards drawing 11-B-349, Revision 14, for inclusion in Parks Township Site physical security plan Revision 1 withheld (ref 10CFR2.790).
AUSTIN, M. A. Babcock & Wilcox Co. 79/08/02 1p.

7908090615 Forwards NRC 790629 request for amend fee for revisions to License SNM-414, re physical security plan. Requests remittance of fee within 15 days.
WEISS, D. License Fee Management Branch. 79/08/06 1p.

7908280151 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/10 1p.

7908220347 Approves revised pages to Nuclear Matls Div, PA Operations, security training & qualification plan & 790219 request to replace commitments in Apollo & Parks Township security plans. Plan withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch. 79/08/13 1p.

7908220358 Approves limited exception from requirements of 10CFR73.60 to allow storage of inactive administrative documents within isolated part of matl access area by amending Section 9 of Amend MPP-1. Amend withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch. 79/08/13 1p.

DOCKET 70-0371 UNITED NUCLEAR CORP.

7908010255 Requests changes to Naval Products Div training & qualification plan submitted in 790213 ltr. Encl to 790213 ltr is being withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Development Branch. 79/06/18. 3pp.

7908160533 Forwards comments on proposed physical protection plan revisions for new License Condition 9.3.59. Requests mod in order to assure that inoperative security equipment is returned to svc promptly. Details withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch. 79/06/18. 3pp.

7908070411 Notifies of intent to install second communications sys. linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/06/22 3pp.

7908070836 Notifies that license review has been assigned to C Emeigh, effective 790709. Arrangements will be made to visit facility.
PARTLOW, J. G. Material Control Licensing Branch. 79/07/10 1p.

7908170182 Accepts Revision 1 to safeguards contingency plan. Amends encl to Section 9 of Amend MPP-1 to License SNM-368 Plan withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch. 79/07/10 2pp.

7908170156 Finds 790801 target date acceptable for [illegible] giving shipper-receiver difference between Naval Products Div & licensee recovery sys. Requests to be kept informed of progress.
PARTLOW, J. G. Material Control Licensing Branch. 79/07/11 1p.

7908160030 Notifies that elements of nuclear matl control programs should be combined into one unclassified comprehensive document. Ltr amends should be in form of revised pages to plan.
PARTLOW, J. G. Material Control Licensing Branch. 79/07/13 1p.

7908070216 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/07/18 1p.

7908220169 Forwards revised sections of training & qualification plan for review & approval as requested in NRC 790618 ltr. Details withheld (ref Atomic Energy Act of 1954e).
GUSTAFSON, R. B. United Nuclear Corp. 79/07/18 1p.

7908150171 Responds to 790615 ltr re schedule for completion of actions per comprehensive evaluation rept, Section 4.2.1. Actions are acceptable. Completion by 790815 is granted.
MCCORKLE, G. W. Physical Security Licensing Branch. 79/07/20 1p.

7908280205 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/09/10. 1p.

DOCKET 70-0572 MONSANTO RESEARCH CORP.

7908280118 Forwards IE Insp Rept 70-0572/79-01 on 790521-24 & notice of violation.
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/07/06 2pp.

--7908280127 Notice of violation from insp on 790521-24.
* Region 3, Chicago, Office of the Director. 79/07/05 1p.

--7908280136 IE Insp Rept 70-0572/79-01 on 790521-24. Noncompliance noted failure to limit extremity exposures for one radiation worker & failure to record action to prevent intake by individual of excess concentrations of radioactive matl.
PAUL, R. A. ; SRENIAWSKI, D. J. ; PAGLIARO, J. A. Region 3, Chicago, Office of the Director. 79/07/05 11pp.

7908170518 Forwards file info on Pu-239 call-in which occurred in early 1970s.
SCHIMMEL, R. L. Monsanto Co. 79/07/16. 21pp.

--7908170520 Authorizes retention of 15 of plutonium-beryllium neutron sources for use in shipments to univ.
WALKER, E. A. Atomic Energy Commission (Pre 1975). 73/06/13. 10pp.

--7908170525 Request for grant or return of Pu held under AEC loan. Pu may be converted to private ownership at no cost to univ provided request for grant forms are completed & accepted by appropriate AEC division.
CRAIG, P. A. Atomic Energy Commission (Pre 1975). 73/03/30. 7pp.

--7908170527 Forwards list of Pu sealed sources mfg at facility which have not been located.
LAVER, R. J. Atomic Energy Commission (Pre 1975) 73/01/19 13pp

--7908170531 Notifies that review of Monsanto 720915 ltr re FR notice concerning discontinuance of leasing small quantities of Pu-239 is complete. Policy does not apply to govt agencies & Pu inventory will not be affected.
CRAIG, P. A. Atomic Energy Commission (Pre 1975) 72/10/05 10pp

--7908170542 Requests info re sealed sources containing 1 g or more Pu or 4 mg or more Pu-238 in posession as of 720701.
PAGE, R. G. Atomic Energy Commission (Pre 1975) 72/08/14 4pp

--7908170547 Lists sealed Pu sources in possession.
NELSON, H. A. Monsanto Co. 72/08/29 5pp

--7908170553 Requests names & addresses of each of plutonium-beryllium recipients, model & serial number of each source transferred, dates of transfer & quantity of Pu transferred.
LOW, L. D. Atomic Energy Commission (Pre 1975) 72/05/03 1p

--7908170557 Forwards results of Phases I & II of 239 plutonium-beryllium neutron source surveillance program.
CAVE, W. T. Monsanto Co. 72/02/08 4pp

--7908170564 Confirms 720131 telcon re delivery of 239 plutonium-beryllium deltron. Source has been transferred to Mound Lab for disposal.
GIBSON, J. R. Monsanto Co. 72/02/10 5pp

--7908170567 Discusses status of neutron source surveillance program. Present requirement to lease plutonium-beryllium neutron sources w/Mound Lab fabricated sources satisfactory.
CAVE, W. T. Monsanto Co. 71/12/22 9pp

--7908170572 Forwards tentative plan for sampling, examining & destructively analyzing plutonium-beryllium neutron sources.
CAVE, W. T. Monsanto Co. 71/03/01 24pp

DOCKET 70-0597 CENTRAL MICHIGAN UNIV.

7908170575 Raises questions re effect of fire on 5-Ci plutonium-beryllium neutron source in radioactive matl emergency procedures. Requests safety criteria under which product was originally licensed.
JACOBSON, B. S. Central Michigan Univ. 79/07/11 1p

DOCKET 70-0734 GENERAL ATOMIC CO.

7908110109 Responds to NRC 790430 ltr re revisions to License SNM-696 plan for guard training per 10CFR73. Forwards changed pages which modify text as recommended. Encl withheld (ref 10CFR2.790).
MOWRY, W. R. General Atomic Co. (subs. of Gulf Oil Corp.) 79/06/15 2pp

7908160048 Submits plan for decommissioning of facility. Includes level effort required, specific problems at each facility, amount of waste generated & costs & destination of burial waste. Plan withheld (ref 10CFR2.790).
MOWRY, W. R. General Atomic Co. (subs. of Gulf Oil Corp.) 79/06/15 3pp

7908140127 Forwards revised page 10 to guard training plan revisions, forwarded 790615. Revised page withheld (ref 10CFR2.790).
MOWRY, W. R. General Atomic Co. (subs. of Gulf Oil Corp.) 79/06/18 2pp

7908140493 Forwards revised contingency plan. Plan supersedes 780919 version. Plan withheld (ref 10CFR2.790).
MOWRY, W. R. General Atomic Co. (subs. of Gulf Oil Corp.) 79/06/29 2pp

7908210392 Discusses planned receipt of formula quantity of highly enriched U by 790730. Requests confirmation of shipping requirements & that generic License Condition 10.3.1 re audits need not be performed.
MOWRY, W. R. General Atomic Co. (subs. of Gulf Oil Corp.) 79/07/02 2pp

7908070829 Notifies that license review has been assigned to J Blaylock effective 790709. Arrangements will be made to visit facility.
PARTLOW, J. O. Material Control Licensing Branch 79/07/10 1p

7908210134 Ack receipt of 790702 ltr re transport of SNM. GA Co needs no separate transportation contingency plan since carrier & coordinating agnecy plans are compatible w/fixed contingency plan.
MCCORKLE, G. N. General Atomic Co. (subs. of Gulf Oil Corp.) 79/07/13 1p

7908150092 FOIA request for any matl relevant to U shipments to GA Co.
THOMPSON, D. D. Affiliation Unknown 79/07/17 1p

7908210098 Accepts revised security guard training & qualification plan & incorporates it into license along w/physical security & safeguards contingency plans. Ltr of 790626 & encls to 790615 ltr withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch 79/07/17 2pp

7908240387 Forwards revised Page 1-1 of revised contingency plan. Change substitutes word "armed" for "unarmed" in Paragraph 2. Info withheld (ref 10CFR2.790).
MOWRY, W. R. General Atomic Co. (subs. of Gulf Oil Corp.) 79/07/20 1p

7908080206 Responds to 781214 ltr re applicability of amend fees charged for review of safeguards contingency plan. Determines that fuel cycle facility contingency plans require major review & major amend fees.
MILLER, W. D. License Fee Management Branch 79/07/24 2pp

7908170140 Revises Amend MPP-1 to License SNM-696 by rescinding obsolete requirements for auditing transportation security program.
MCCORKLE, G. W. Physical Security Licensing Branch 79/07/24 1p

7908170339 Advises that June 1979 contingency plan submitted by 790629 & 0720 ltrs has been reviewed & accepted. Forwards amended Section 9.0 to Amend MPP-1 to License SNM-696 reflecting mod of Condition 9.1B.
MCCORKLE, G. W. Physical Security Licensing Branch 79/07/31 2pp

7908150097 Responds to FOIA request for matl re U shipments to GA Co. No documents located.
FELTON, J. M. Division of Rules and Records 79/08/10 1p

7908170031 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 79/08/10 1p

DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO.

7908030209 Forwards IE Insp Rept 70-0754/79-04 on 790322 & notice of violation.
BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/05/01 2pp

--7908030211 Notice of violation from insp on 790322.
* Region 5, San Francisco, Office of the Director 79/05/01 1p

--7908030223 IE Insp Rept 70-0754/79-04 on 790322. Noncompliance noted: changes were made on shipping casks w/o notifying NRC. Shipping cask not tested for leaks.
COOLEY, W. J., REIDLINGER, B. A., BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/04/30 9pp

7908130607 Forwards revised safeguards plan containing changes to matl control & accounting program. Plan withheld (ref 10CFR2.790).
MOSCHNER, R. A. General Electric Co., Nuclear Energy Products Div. 79/05/07 2pp

7908140335 Responds to GW McCorkle 790530 ltr re security personnel training & qualification plan. Revision of plan unnecessary because SNM inventories will be below 5 kg prior to agreed date of 790831.
MOSCHNER, R. A. General Electric Co. 79/06/05 1p

7908090466 Notifies that security personnel training & qualification plan problems have been resolved. Revision to facility safeguards contingency plans will be provided by 790720.
MOSCHNER, R. A. General Electric Co., Nuclear Energy Products Div. 79/06/22 2pp

7908170110 Accepts 790507 proposed changes to safeguards plan. Forwards Revision 3 to Amend MPP-2 of License SNM-960. Plan withheld (ref 10CFR2.790).
PARTLOW, J. O. Material Control Licensing Branch 79/06/27 2pp

7908130179 Responds to request for suspension of License SNM-960 & removal of all Pu from site.License will not be suspended at this time.Forwards decision.
DIRCKS,W J Office of Nuclear Material Safety & Safeguards
79/06/29 2pp

--7908130186 Denies petitions,submitted by Friends of Earth & Congressmen J Burton & RV Dellums,to suspend License SNM-960 & remove all Pu from site.Analysis in 771107 preliminary SER is essentially sound.
DIRCKS,W J Office of Nuclear Material Safety & Safeguards
79/06/29 15pp

--7908130190 Notice of issuance of decision,per 10CFR2.206.License SNM-960 will not be suspended.
DIRCKS,W J Office of Nuclear Material Safety & Safeguards
79/06/29 2pp

--7908130197 Notifies of denial of Friends of Earth 781214 petition to suspend License SNM-960 & remove all Pu from site.Forwards list of petitioners supporting Friends of Earth petition.
DIRCKS,W J Office of Nuclear Material Safety & Safeguards
79/06/29 2pp

--7908130203 Notifies of denial of decision re Friends of Earth 781214 petition to suspend License SNM-960 & remove all Pu from site.
DIRCKS,W J Office of Nuclear Material Safety & Safeguards
79/06/29 1p

--7908130212 "Source Term & Radiation Dose Estimates for Postulated Damage to 102 Bldg at GE Vallecitos Nuclear Ctr."
MISHIMA,J ; MCPHERSON,R B ; SCHWENDIMAN,L Brookhaven National Laboratory EY-76DC00601830 79/02/28 87pp

7908140066 Requests concurrence in consolidating large number of tamper-safed small Pu packages into smaller number of larger packages.
CUNNINGHAM,G E General Electric Co.,Nuclear Energy Products Div
79/07/12 1p

7908290246 Requests that survey be conducted of proposed route for shipment of 50 kg of U-235,in form of unirradiated GE test reactor fuel elements,from Pleasanton,CA to ID Engineering Lab at Idaho Falls,ID.
MASCHNER,R A General Electric Co.,Nuclear Energy Products Div
79/07/13 1p

7908210535 Forwards revised security training & qualification plan.Comments on revisions suggested by NRC encl.
CUNNINGHAM,G E General Electric Co.,Nuclear Energy Products Div
79/07/16 2pp

7908020010 Order extending time until 790731 for NRC to determine whether NMSS 790629 decision should be reviewed.
CHILK,S J Office of the Secretary of the Commission 79/07/17
1p

7908150128 Forwards addendum to Director 790629 decision per 10CFR2.206.
DIRCKS,W J Office of Nuclear Material Safety & Safeguards
79/07/20 3pp

--7908150136 Addendum to Director 790629 decision,per 10CFR2.206,re allegation that National Phenomena Review Team has conflicts of interests interferin, w/objectivity.No conflicts exist which would affect conduct of duties.
DIRCKS,W J Office of Nuclear Material Safety & Safeguards
79/07/20 2pp

7908150730 Forwards revised Amend MPP-2 to License SNM-960,in response to 790712 ltr re matls & plant protection.Changes do not decrease effectiveness of safeguards program.
PARTLOW,J G Material Control Licensing Branch 79/07/20 2pp

7908220671 Submits info required by effluent monitoring reporting requirements.Due to complexity of site & use of single liquid effluent discharge point,not possible to differentiate between liquid effluent generation activities.
CUNNINGHAM,G E. ; MOHR,H C General Electric Co.,Nuclear Energy Products Div 79/07/24 1p

7908230582 Forwards revised Section 13.0 to application for renewal of License SNM-960.Section 10 of proposed App A to License SNM-960 has been reissued.
CUNNINGHAM,G E General Electric Co.,Nuclear Energy Products Div
79/07/24 18pp

7908230161 Responds to 790716 ltr.Forwards decision per 10CFR2.260 re activities under License SNM-960.W/o encl.
DIRCKS,W J Office of Nuclear Material Safety & Safeguards
79/07/27 1p

7908170345 Advises that revised security guard training & qualification plan,transmitted by 790716 ltr,has been reviewed & accepted.Recommends incorporation of said plan w/physical security & safeguards contingency plans into license.
MCCORKLE,G W Physical Security Licensing Branch 79/07/31
2pp

7908220594 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN,R H Region 5, San Francisco, Office of the Director
79/08/10 1p

DOCKET 70-0820 UNITED NUCLEAR CORP

7908090374 Emergency plan for License SNM-777.
* United Nuclear Corp., UNC Recovery Systems Div 79/06/04 56pp

7908080097 Forwards "Special Safeguards Review of United Nuclear Corp Fuel Recovery Operation at Wood River Junction,RI," conducted 781031-1103.Requests comments W/o encl.
GRIER,B H Region 1, Philadelphia, Office of the Director
78/12/08 2pp

7908130362 Notifies of review & acceptance of revised measurement control plan in May 1978 ltr & revision in 780628 & 1231 ltrs.New conditions for matl control & accounting program & revised Conditions 2.1 & 4.1 of Amend MPP-2 encl.
PARTLOW,J G Material Control Licensing Branch 79/03/08 9pp

7908170218 Forwards changes to contingency & training plans pursuant to request.
GIGLIOTTI,R J United Nuclear Corp., UNC Recovery Systems Div
79/05/21 13pp

7908090367 Forwards emergency plan for Licence SNM-777.
BOWERS,C E United Nuclear Corp., UNC Recovery Systems Div
79/06/05 1p

7908210602 Requests extension to 790720 for normal reporting time for June 1979 high & low enriched inventory repts,due to 790611-0701 plant vacation.Matl safeguards amend classification encl.
GREGG,R J United Nuclear Corp., UNC Recovery Systems Div
79/06/11 2pp

--7908210603 Notifies that amend fee of $150 is required for extension of reporting time requested in 790611 ltr.
WEISS,D License Fee Management Branch 79/06/21 1p

7908010103 Grants request for 30-day delay in reconciling Apr 1979 physical inventory.
PARTLOW,J G Material Control Licensing Branch 79/06/18 1p

7908090528 Forwards "Proposed Waste Mgt Plan for Disposal of Process Wastes." Rept submittal complies w/Condition 15 of License SNM-777,Amend 6.
BOWERS,C E United Nuclear Corp 79/06/20 1p

--7908090567 "Proposed Waste Mgt Plan for Disposal of Process Wastes."
* United Nuclear Corp 79/06/20 4pp

7908010669 Ack receipt of 790611 ltr re extension in reporting time for License SNM-777.Requests amend fee.
WEISS,D License Fee Management Branch 79/06/21 1p

7908070414 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda,MD ofc.Second line will be used to relay radiologic & environ data during emergencies.Testing procedures encl.
GRIER,B H Region 1, Philadelphia, Office of the Director
79/06/22 3pp

7908080415 Ack 790611 ltr requesting 16-day delay in reconciling June 1979 physical inventories.Request granted.
PARTLOW,J G Material Control Licensing Branch 79/06/22 1p

7908150321 Notifies that revised training & qualification plans will be acceptable upon receipt of schedule re security personnel qualification.License SNM-777 will be amended accordingly. Encls to 790115 & 0521 ltrs withheld (ref 10CFR2.790).
MCCORKLE,G W Physical Security Licensing Branch 79/06/22
2pp

7908140074 Notifies that 790219 Revision 1 to safeguards contingency plan & 790521 corrected pages are acceptable.Plan is incorporated in Amend MPP-1 of License SNM-777.Plan withheld (ref 10CFR2.790).
MCCORKLE,G W Physical Security Licensing Branch 79/06/27
2pp

7908140287 Withdraws 790622 ltr re training & qualification program, per 790627 telcon. Ltr was sent inadvertently prior to fee payment.
MCCORKLE, G. W. Physical Security Development Branch 79/06/28 1p.

7908070837 Notifies that license review has been assigned to C Emeigh, effective 790709. Arrangements will be made to visit facility.
PARTLOW, J. G. Material Control Licensing Branch 79/07/10 1p.

7908210139 Adds license condition to Amend MPP-2 requiring that two people attest to contents of containers & vaults prior to tamper-safing.
PARTLOW, J. G. Material Control Licensing Branch 79/07/12 1p.

7908170075 Discusses insp findings. Serious concerns exist re licensee ability to maintain effective security at facility or to control SNM. Forwards notice of proposed imposition of civil penalties. Encl withheld (ref 10CFR2.790).
STELLO, V. Office of Inspection & Enforcement, Office of the Director 79/07/16 2pp.

7908070219 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/10 1p.

7908170618 Ack receipt of 790627 ltr advising that safeguards contingency plan is acceptable. Requests extension for implementation of plan to 790827, due to transition of guard force.
BOWERS, C. E. United Nuclear Corp., UNC Recovery Systems Div 79/07/19 1p.

7908280245 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/10 1p.

DOCKET 70-0824 BABCOCK & WILCOX CO

7908020587 Forwards IE Insp Rept 70-0824/79-04 on 790508-11. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/30 2pp.

--7908020591 IE Insp Rept 70-0824/79-04 on 790508-11. No noncompliance noted. Major areas inspected: radiological environ monitoring program, including mgt controls, stations, data & procedures.
MACARTHUR, T. C., HUFHAM, J. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/25 3pp.

7908140101 Notifies that 781221 safeguards contingency plan & 790508 Revision 1 are acceptable. Plan is incorporated in Amend MPP-1 of License SNM-778. Plan withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch 79/06/06 2pp.

7908210021 Forwards draft EIA re license renewal action of B&W Lynchburg Research Ctr. Requests comments by 790716. W/o encl.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727) 79/06/14 1p.

7908290228 Forwards IE Insp Rept 70-0824/79-05 on 790611-13. No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/27 2pp.

--7908290237 IE Insp Rept 70-0824/79-05 on 790611-13. No noncompliance noted. Major areas inspected: review of license renewal application, 10CFR21 & procurement documents, sludge buildup in large tanks & other areas.
KAHLE, J. B. Region 2, Atlanta, Office of the Director
POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/26 3pp.

7908070818 Summary of 790611-13 visit to B&W Lynchburg, VA Research Ctr.
KETZLACH, N. Fuel Process. & Fab. Branch (Pre 790727) 79/07/02 2pp.

7908070820 Notifies that license review has been assigned to G Gundersen, effective 790709. Arrangements will be made to visit facility.
PARTLOW, J. G. Material Control Licensing Branch 79/07/10 1p.

7908020015 Advises that actual fee for license Amend MPP-1 re safeguards contingency plan is less than amount paid w/781221 request. Overpayment will be refunded.
MILLER, W. O. License Fee Management Branch 79/07/16 1p.

7908100561 Requests registration as user of Model CNSI 15-1608.
OLSEN, A. F. Babcock & Wilcox Co. 79/07/10 1p.

7908150729 Forwards B&W check re 790718 ltr accompanying page changes to fundamental nuclear matl control plan. Changes are not subj to fee.
WEISS, D. License Fee Management Branch 79/07/18 1p.

7908070294 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/07/20 1p.

DOCKET 70-0925 CIMMARON FACILITY, KERR-MCGEE CORP.

7908290218 Submits change to 790102 ltr. No further increase in possession limit for License SNM-928 is necessary. Requests Paragraph 8 be changed to reduce possession limit.
SHELLEY, W. J. Kerr-McGee Nuclear Corp. 79/06/13 1p.

7908070639 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/22 3pp.

7908070327 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/19 1p.

DOCKET 70-0959 NUCLEAR FUEL SERVICES, INC., (SUBS. OF GETTY OIL CO.)

7908280157 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/10 1p.

7908310221 Forwards IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals." No action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/08/14 1p.

DOCKET 70-0984 PACIFIC NORTHWEST LAB

7908030513 Requests renewal of License SNM-942, covering receipt possession & use of SNM for R&D. Forwards 790501 PNL-MA-527, Revision 5 (BNWL-CC-284).
AMBROSE, T. W. Battelle Memorial Institute, Pacific Northwest Laboratory 79/05/09 2pp.

--7908030523 Notifies of license condition. Max quantity of license matl at BNWL at any given time will be less than 1 kg of U-233 & U-235 & less than 200 g Pu. Class 1G renewal fee encl.
FUQUAY, J. J. Battelle Memorial Institute, Pacific Northwest Laboratory 79/06/05 1p.

--7908030533 Application to renew License SNM-942 for possession, use & receipt of SNM for R&D.
* Battelle Memorial Institute, Pacific Northwest Laboratory 79/05/01 148pp.

7908170119 Forwards IE Insp Rept 70-0984/79-01 on 790516-18. No noncompliance noted.
BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/06/19 2pp.

--7908170129 IE Insp Rept 70-0984/79-01 on 790516-18. No noncompliance noted. Major areas inspected: organization, mods & changes to facilities & sys, record control & storage, internal review & audit.
COOLEY, W. J. Region 5, San Francisco, Office of the Director
BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/06/18 9pp.

7908170638 Establishes review schedule for 790501 license renewal application. Schedule prepared per "Plan for Licensing Review & Insp Related to Major Licensing Actions for Fuel Cycle Facilities."
CROW, W. T. Division of Fuel Cycle & Material Safety 79/06/20 2pp.

7908230122 Forwards application for renewal of License SNM-942.
FUQUAY, J. J. Battelle Memorial Institute, Pacific Northwest Laboratory. 79/07/02 2pp.

--7908230126 Revision 6 of application for renewal of License SNM-942, authorizing changes affecting radiation protection organization.
* Battelle Memorial Institute, Pacific Northwest Laboratory. 79/07/02 41pp.

7908220600 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10 1p.

DOCKET 70-1007 GENERAL ELECTRIC CO.

7908220594 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/08/10 1p.

DOCKET 70-1100 COMBUSTION ENGINEERING, INC.

7908070777 Forwards revised emergency plan for License SNM-1067. Previous submittal, dtd 790410, should be withdrawn.
LICHTENBERGER, H. C-E Power Systems. 79/06/08 1p.

--7908070782 Emergency plan for License SNM-1067.
* C-E Power Systems. 79/06/08 41pp.

7908150221 Contends that added license restrictions involving traceability to NBS stds of volumetric glassware used in analytic lab are not cost justified. Effort-benefit analysis is resubmitted for approval.
LICHTENBERGER, H. C-E Power Systems. 79/06/04 5pp.

7908160539 Grants limited exemption from requirements of 10CFR70.51(e)(3), delaying start of next physical inventory. Condition 5.5 of Amend MPP-3 authorizes next physical inventory no later than 791219.
PARTLOW, J. G. Material Control & Accountability Development Branch 79/06/13 1p.

7908140165 Responds to request for addl info re 790423 application for amend to License SNM-1067. Forwards revised pages.
LICHTENBERGER, H. C-E Power Systems. 79/06/27 20pp.

7908220285 Forwards emergency plan for License SNM-1067.
LICHTENBERGER, H. C-E Power Systems. 79/07/30 1p.

--7908220293 Emergency plan for License SNM-1067.
* C-E Power Systems. 79/07/30 45pp.

7908210135 Forwards 790622 ltr, requesting $150 fee for NRC approval of delay in June physical inventory. Fee not received. Requests payment within 15 days from date of ltr. W/o encl.
WEISS, D. License Fee Management Branch. 79/08/06 1p.

7908230240 Forwards revised pages to 790423 amend application for License SNM-1067.
PIANA, F. J. C-E Power Systems. 79/08/07 18pp.

7908200040 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial." Action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/08/10 1p.

DOCKET 70-1113 GENERAL ELECTRIC CO.

7908140157 Notifies that Conservation Chemical Co is being contracted to transfer liquid hydrogen fluoride under License SNM-1097. Forwards Conservation Chemical Co 790516 ltr of certification.
KAPLAN, A. L. General Electric Co., Nuclear Energy Products Div. 79/05/24 3pp.

7908140236 Forwards addl info to 790524 ltr re transfer of matl by Conservation Chemical Co. Discusses method of extracting hydrogen fluoride from ore, handling of waste streams & processes utilized in production of beryllium metal.
KAPLAN, A. L. General Electric Co., Nuclear Energy Products Div. 79/05/25 1p.

7908150180 Submits review of 780714 license amend application & 790514 suppl re Decommissioning Plan PC 78109A. Addl details to support estimated cost of decommissioning should be provided by 800701.
STEVENSON, R. L. Fuel Process. & Fab. Branch (Pre 790727). 79/06/05 2pp.

7908140486 Responds to request for addl info to 790524 & 25 ltrs re intended transfer of liquid hydrogen fluoride solution to Conservation Chemical Co. Forwards Brush Wellman, Inc 790613 ltr re use of hydrofluoric acid w/enriched U.
KAPLAN, A. L. General Electric Co., Nuclear Energy Products Div. 79/06/20 3pp.

7908170180 Notifies that 790402 application for Amend S-8 for physical inventory of U oxide pellets & certain containers of SNM does not meet stds of 10CFR70. Physical inventory must be annual. Licensee must reconcile difference within 30 days.
BURNETT, R. F. Division of Safeguards 79/06/20 1p.

7908010268 Confirms 790529 telcon. Administrative fee of $150 is due for amend of License SNM-1097.
WEISS, D. License Fee Management Branch 79/06/21 1p.

7908030109 Evaluates licensee request to delay implementation of 10CFR70.57 beyond 790603 implementation date. Revises current License Condition 2.1. Urges approval of both requests.
JACKSON, R. Material Control Licensing Branch 79/06/21 2pp.

7908080409 Discusses request to delay initiating certain portions of matl measurement control plan, per 790313, 0529 & 0601 ltrs & 790531 meeting. Grants modified delays & outlines revisions to license condition.
PARTLOW, J. G. Material Control Licensing Branch 79/06/22 2pp.

7908290084 Notifies that License Condition 4.7 of Amend MPP-2 to License SNM-1097 is revised. Licensee may accumulate combustible waste generated in plant until 811231. Util 781113 ltr withheld (10CFR2.790).
PARTLOW, J. G. Material Control Licensing Branch 79/07/03 1p.

7908020012 Advises that actual fee for amend of License SNM-1097, denied on 790620, is less than amount paid w/790402 request. Overpayment will be refunded.
MILLER, W. O. License Fee Management Branch 79/07/16 1p.

7908230651 Ack receipt of NRC ltr reporting results of IE Insp Rept 70-1113/79-14 on 790530.
KAPLAN, A. L. General Electric Co., Nuclear Energy Products Div. 79/07/16 1p.

--7908230655 Forwards IE Insp Rept 70-1113/79-14 on 790530. No noncompliance noted.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 79/07/11 2pp.

--7908230658 IE Insp Rept 70-1113/79-14 on 790530. No noncompliance noted. Major areas inspected: storage & internal control. Details withheld (ref 10CFR2.790).
TODD, G. A. Region 2, Atlanta, Office of the Director.
GILLESPIE, F. P. Region 2, Atlanta, Safeguards Branch 79/07/10 1p.

7908220058 Forwards list of NRC Region 3 personnel for whom permanent, nonemployee, no escort badges are requested. Also requests site orientation re issuance of badges, escort duties & emergency evacuation.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 79/07/17 2pp.

7908160075 Forwards list of NRC Region 2 personnel for whom "permanent non-employee, no escort required" badges are requested. Requests site orientation re issuance of badges, escort duties & emergency evacuation.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 79/07/20 2pp.

7908220592 Notifies of 790703 revision of License Condition 4.7 of Amend MPP-2 to License SNM-1097 in response to 781113 application for amend. As result of review of manpower expenditures, $2,968 will be refunded.
MILLER, W. O. License Fee Management Branch 79/07/30 1p.

7908170004 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/08/08 1p.

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP.

7908080026 Recommends approval of Amend 16 to License SNM-1120 to approve JJ Bastin as facility manager.
BROWNE, W.G. , ROUSE, L.C. Fuel Reprocess. & Recycle Branch (Prv 790727). 79/04/12. 2pp.

7908140088 Forwards list of SNM currently declared as scrap for License SNM-1120 Requests exemption per 10CFR70.56(i)(e). Encl withheld (ref 10CFR2.790).
PETRAREA, D.J. Westinghouse Electric Corp. 79/06/01. 3pp.

7908140423 Notifies that 780908 safeguards contingency plan & 790312 Revision 1 are acceptable Plan will be incorporated in matl & plant protection amend of License SNM-1120 Plan withheld (ref 10CFR2.790).
MCCORKLE, G.W. Physical Security Licensing Branch. 79/06/06. 2pp.

7908150040 Submits rept re of 790613 meeting w/PA Dept of Environ Resources to present EIA for review Questions were raised re effluent accident analysis & environ impact associated w/operation of facility.
AYER, J.E. Fuel Reprocess. & Recycle Branch (Prv 790727). 79/06/18. 1p.

7908150049 Submits trip rept of meeting on 790613 w/PA Dept of Environ Resources to present EIA for review Questions were raised re effluent accident analysis & environ impact associated w/operation of facility.
AYER, J.E. Fuel Reprocess. & Recycle Branch (Prv 790727). 79/06/18. 1p.

7908170091 Forwards IE Insp Rept 70-1143/79-07 on 790416-19 No noncompliance noted.
MARTIN, W.G. Region 1, Philadelphia, Safeguards Branch. 79/06/19. 2pp.

--7908170093 IE Insp Rept 70-1143/79-07 on 790416-19 No noncompliance noted Major areas inspected facility organization, inventory verification & licensee action on previously identified items of noncompliance.
RATTA, A.D., COHEN, I. Region 1, Philadelphia, Office of the Director. JOYNER, J.H. Region 1, Philadelphia, Safeguards Branch. 79/06/18. 3pp.

7908140500 Determines Revision 6 to "Plan for Providing Physical Security at Cheswick Site" will be acceptable after minor mod in plan to provide for training in other weapons Plan withheld (ref 10CFR2.790).
MCCORKLE, G.W. Physical Security Licensing Branch. 79/06/20. 2pp.

7908070416 Notifies of intent to install second communications sys. linking facilities w/NRC regional ofc & main Bethesda, MD ofc Second line will be used to relay radiologic & environ data during emergencies Testing procedures encl.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/06/22. 3pp.

7908080381 Summary of 790621 meeting w/Westinghouse in Silver Spring, MD re changed pages for license renewal application.
BROWNE, W.G. Fuel Reprocess. & Recycle Branch (Prv 790727). 79/06/25. 1p.

7908160532 Revises Amend MPP-1 to License SNM-1120 re retaining scrap w/measurement greater than 10% for more than six months License revision encl Info contained in 790507 & 0601 ltrs withheld (ref 10CFR2.790).
PARTLOW, J.G. Material Control & Accountability Development Branch. 79/06/26. 2pp.

7908140139 Forwards Revision 7 to "Plan for Providing Physical Security at Cheswick Site," in response to NRC 790620 request Encl withheld (ref 10CFR2.790).
DIPIAZZA, R.P. Westinghouse Electric Corp. 79/07/02. 2pp.

7908160571 Requests registration as user of Model 6272.
DIPIAZZA, R.P. Westinghouse Electric Corp. 79/07/03. 1p.

7908070839 Notifies that license review has been assigned to H Barti; effective 790709 Arrangements will be made to visit facility.
PARTLOW, J.G. Material Control Licensing Branch. 79/07/10. 1p.

7908240606 Forwards Revision 1 of License SNM-1120, Amend 1, Sections 1.0-8.0, re matls & plant protection.
PARTLOW, J.G. Material Control Licensing Branch. 79/07/12. 1p.

--7908240610 Revision 1 to License SNM-1120, Amend 1, Sections 1.0-8.0, re matls & plant protection.
* Material Control Licensing Branch. 79/07/12. 4pp.

7908150181 Advises of fee overpayment for Amend MPP-1 to License SNM-1120, incorporating safeguard contingency plan Ofc of Controller notified to issue refund.
MILLER, W.O. License Fee Management Branch. 79/07/16. 1p.

7908160027 Forwards draft comprehensive evaluation rept consolidating observations of four teams which visited facility during Sept 1978 W/o encl.
MCCORKLE, G.W. Physical Security Licensing Branch. 79/07/16. 1p.

7908070221 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors Info requests will not be made while plant is in shutdown mode.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/07/18. 1p.

7908210594 Submits addl info supporting renewal of License SNM-1120. Submittal includes results of discussions w/NRC re criticality & other mods requested by W Browne Commitments contained in 781122 ltr have been completed.
DIPIAZZA, R.P. Westinghouse Electric Corp. 79/07/19. 2pp.

--7908210598 Revision 5 to application for amend to License SNM-1120
* Westinghouse Electric Corp. 79/07/31. 23pp.

7908150697 Ack 790716 ltr re amend to License SNM-1120 to delay physical inventory Amend fee of $150 required.
WEISS, D. Licensing Management Branch. 79/07/26. 1p.

7908300626 Notifies that Section 9 of Matls & Plant Protection Amend MPP-1 to License SNM-1120 is amended by revising encl License Condition 9.A per revised security guard training & qualification plan Revised plan acceptable.
MCCORKLE, G.W. Physical Security Licensing Branch. 79/07/31. 2pp.

7908200312 Recommends approval of Westinghouse request for 14-day extention to complete chemical analysis & compute limit of error for inventory difference Delay caused by bargaining unit strike.
BARTZ, H. Material Control Licensing Branch. 79/08/02. 1p.

7908280251 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transportation & Burial," Action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/08/10. 1p.

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP.

7908270131 Requests extension until 790717 to submit LE/MUF calculations for 790519-20 physical inventory for License SNM-1107.
FOSTER, H. Westinghouse Electric Corp. 79/05/02. 1p.

--7908270136 Notifies that Amend SG-4 to License SNM-1107 requires $150 payment.
WEISS, D. License Fee Management Branch. 79/07/05. 1p.

7908060140 Discusses review of 790424 application for withholding pages 76, 77, 122, 122a & 122b of 790403 application for amend to License SNM-1107 Withholding of application is approved (ref 10CFR2.790).
CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety. 79/06/07. 2pp.

7908130531 Forwards addl info to support application for amend to License SNM-1107, expanding facility Addl info withheld (ref 10CFR2.790).
DIPIAZZA, R.P. Westinghouse Electric Corp. 79/06/12. 1p.

7908130542 Forwards responses to 790522 request for addl info re amend of License SNM-1107 for expansion facility.
DIPIAZZA, R.P. Westinghouse Electric Corp. 79/06/12. 13pp.

7908140170 Notifies of inability to meet 790630 deadline for Sections 4.1.2 & 4.5 of SNM measurement control plan Requests extension until 790731.
GOODWIN, W.L. Westinghouse Electric Corp. 79/06/18. 1p.

7908020538 Responds to 790618 ltr & telcon requesting delay in initiation of matl measurement control plan Delay granted. Forwards revision to Condition 2.1.1 of Amend SG-4 to License SNM-1107.
PARTLOW, J.G. Division of Fuel Facility & Materials Safety. 79/06/22. 1p.

7908030087 Transfers review responsibility for Westinghouse-Columbia low enriched U fuel fabrication facility from R Jackson to E McAlpine. Describes plant status & possible NRC action.
JACKSON, R. Material Control Licensing Branch 79/06/25 2pp.

7908030519 Discusses Amend SG-4 to License SNM-1107. Ofc of Controller notified to refund amend fee overpayment of $1,866.
MILLER, W.O. License Fee Management Branch 79/06/28 1p.

7908140123 Forwards legible page 122b of plant expansion license submittal. Info withheld (ref 10CFR2.790).
REITLER, E.K. Westinghouse Electric Corp 79/07/02 2pp.

7908070840 Notifies that license review has been assigned to E.J McAlpine, effective 790709. Arrangements will be made to visit facility.
PARTLOW, J.G. Material Control Licensing Branch 79/07/10 1p.

7908150583 Ack receipt of 790627 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1151/79-08.
SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/12 1p.

--7908150587 Responds to NRC 790530 ltr re violation noted in IE Insp Rept 70-1151/79-08. Corrective actions: storage shelf separations were corrected in QC lab cabinet.
D'AMORE, M. Westinghouse Electric Corp 79/06/27 2pp.

--7908150590 Forwards corrected notice of violation to IE Insp Rept 70-1151/79-08.
SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/13 1p.

--7908150594 Corrected notice of violation from insp on 790508-11.
* Region 2, Atlanta, Office of the Director 79/05/29 1p.

--7908150597 Forwards IE Insp Rept 70-1151/79-08 on 790508-11 & notice of violation.
SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/30 2pp.

--7908150602 Notice of violation from insp on 790508-11.
* Region 2, Atlanta, Office of the Director 79/05/29 1p.

--7908150609 IE Insp Rept 70-1151/79-08 on 790508-11. Noncompliance noted: failure to store SNM in accordance w/posted instructions.
KAHLE, J.B. Region 2, Atlanta, Office of the Director.
POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/29 7pp.

7908170616 Ack receipt of 790712 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/79-09.
KENNA, W.B. Region 2, Atlanta, Safeguards Branch 79/07/26 1p.

--7908170623 Responds to NRC 790620 ltr re violations noted in IE Insp Rept 70-1151/79-09. Corrective actions withheld (ref 10CFR2.790).
GOODWIN, W.L., D'AMORE, M. Westinghouse Electric Corp 79/07/12 1p.

--7908170628 Forwards IE Insp Rept 70-1151/79-09 on 790507-09, 14-23 & 31. Notice of violation withheld (ref 10CFR2.790).
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/06/20 2pp.

--7908170634 IE Insp Rept 70-1151/79-09 on 790507-09, 14-23 & 31. Noncompliance noted: failure to make correct measurements, to verify seal integrity, or to maintain tamper-safing procedures. Details withheld (ref 10CFR2.790).
BATES, J.W., CLAY, E.L., WILKINS, T.D. Region 2, Atlanta, Office of the Director 79/06/19 2pp.

7908170006 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/08 1p.

7908210435 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." Action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/08 1p.

DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP

7908070639 Notifies of intent to install second communications sys, linking facilities w/NRC regional ofc & main Bethesda, MD ofc. Second line will be used to relay radiologic & environ data during emergencies. Testing procedures encl.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/06/22 3pp.

7908020254 Forwards IE Insp Rept 70-1193/79-03 on 790614-15. No noncompliance noted.
HIND, J.A. Region 3, Chicago, Safeguards Branch 79/07/10 2pp.

--7908020260 IE Insp Rpet 70-1193/79-03 on 790614-15. No noncompliance noted. Major areas inspected: nuclear matl control & accountability. Details withheld (ref 10CFR2.790).
PATTERSON, J.P., HIND, J.A. Region 3, Chicago, Safeguards Branch 79/07/09 1p.

7908070327 Requests cooperation in data-gathering activities to provide NRC Commissioners, public & media w/up-to-date operating status of power reactors. Info requests will not be made while plant is in shutdown mode.
KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/07/19 1p.

DOCKET 70-1201 UF 6 CONVERSION FACILITY, BABCOCK & WILCOX CO

7908130530 Submits implementation schedule re measurement control plan.
ZEFF, D.W. Babcock & Wilcox Co 79/06/12 2pp.

7908020524 Responds to 790612 ltr re phased implementation plan. New plan is within scope of measurement control plan. If rescheduling of bimonthly statistical analysis of control data is anticipated, NRC approval should be requested.
PARTLOW, J.G. Material Control Licensing Branch 79/06/22 1p.

7908030093 Discusses H Bartz & J Blaylock 790619 visit to B&W re review of data required on sampling & analytical chemistry, review of proposed revision to Chapter 5 (physical inventory) & review of measurement control plan implementation date.
BARTZ, H., BLAYLOCK, J. Material Control Licensing Branch 79/06/22 2pp.

7908020280 Reviews safety & environ effects of B&W application to amend License SNM-1168. Amend would revise surface contamination action levels in several areas & permit SNM storage in multitier array. Recommends issuance of amend.
KETZLACH, N. Fuel Process. & Fab. Branch (Pre 790727) 79/07/02 3pp.

7908030212 Amends License SNM-1168 to authorize use of new special matl storage array & to revise surface contamination action levels & survey frequencies.
CROW, W.T. Fuel Process. & Fab. Branc (Pre 790727) 79/07/02 1p.

7908200416 Reassigns case to DA Huff, effective 790709. Site visit will soon be arranged.
PARTLOW, J.G. Material Control Licensing Branch 79/07/10 1p.

7908220138 Transmits License Condition 4.10 (Formerly 4.12) which had been mistakenly omitted from 781221 ltr.
PARTLOW, J.G. Material Control Licensing Branch 79/07/18 1p.

7908230100 Advises that Amend MPP-2 to License SNM-1168 is being revised to reflect changes specified in encl license amend for SNM safeguards, per 790515 ltr transmitting revision to Sectionns 3.0 & 4.0.
PARTLOW, J.G. Material Control Licensing Branch 79/07/27 1p.

--7908230103 Amend MPP-2 to License SNM-1168, superseding all previous safeguards amends incorporating requirements for control & accounting of SNM.
* Material Control Licensing Branch 79/07/27 5pp.

7908220496 Discusses revision of "Content of Emergency Procedure" to increase effectiveness of emergency plan. Procedure addresses each class of emergency outlining immediate response actions, responsibilities & authority of offsite agencies.
ZEFF, D.W. Babcock & Wilcox Co 79/07/31 2pp.

7908170347 Advises that no addl fee is required for Amend 10 to License SNM-1168 issued on 790721 in response to 781013 application.
MILLER, W.O. License Fee Management Branch 79/08/02 1p.

7908290623 Forwards effluent monitoring rept for period Jan-June 1979.
ZEFF, D.W. Babcock & Wilcox Co 79/08/06 2pp.

7908170002 Forwards IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus." No action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/08/08 1p.

DOCKET 70-1207 NAVY, DEPT OF

7908140439 Endorses & forwards application for extension of License SNM-1147.
VOGT, J.F. Navy, Dept of, Naval Nuclear Power Unit 79/07/18 2PP.

--7908140590 Requests 90-day extension of 790731 expiration date for License SNM-1147 to allow for revision & timely submittal of renewal application.
TOWNSEND, J E Navy, Dept of, Naval Nuclear Power Unit 79/07/11 2pp

DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO., INC.

7908070241 Forwards application for renewal of License SNM-1227 Annual Financial Rept 1978 encl as part of application.
NILSON, R Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/05/31 4pp

--7908070257 Application for renewal of License SNM-1227, authorizing possession & use of 10,000 kg U-235 enriched to 19.99%, & 100 kg Pu contained in sealed sources & stds.
* Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/04/30 319pp

7908150258 Forwards Apr 1979 supplemental environ rept by applicant & Apr 1979 "Summary 1977-78 Occupational Radiation Exposures." Repts forwarded in support of application for license renewal.
ESTEY, H P Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/05/29 1p

--7908150263 "Summary 1977-1978 Occupational Radiation Exposures."
* Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/04/30 9pp

--7908150269 "Addendum 5 to Applicant's Environ Rept, Expanded U Oxide Fuel Plant."
* Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/04/30 24pp

7908200418 Responds to 790518 application & amends License SNM-1227 to authorize possession & grinding of U dioxide pellets.
CROW, W T Fuel Process. & Fab. Branch (Pre 790727) 79/06/08 1p

7908210047 Reviews proposed 790518 license amend for grinding of safe batch in process engineering lab Recommends approval.
STEVENSON, R L Fuel Process. & Fab. Branch (Pre 790727) 79/06/08 2pp

7908130599 Forwards "Structural Condition Documentation & Structural Capacity Evaluation for Earthquake & Flood," Task II, structural capacity evaluation Vol I, seismic evaluation, prepared by Engineering Decision Analysis Co, Inc.
ROUSE, L C Fuel Process. & Fab. Branch (Pre 790727) 79/06/11 1p

--7908130600 "Structural Condition Documentation & Structural Capacity Evaluation for Earthquakes & Flood," Task II, structural capacity evaluation, Vol I, seismic evaluation, prepared for LLL.
* Engineering Decision Analysis Company, Inc 79/04/30 165pp

7908200106 Forwards application for renewal of License SNM-1227, document XN-2 NRC requests that document be filed in Richland Public Library, Richland, WA.
ESTEY, H P Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/06/19 1p

7908090535 Requests that Amend 9 to License SNM-1227 be reinstated w/expiration date of 791231 Administrative fee encl.
ESTEY, H P Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/06/20 1p

7908080369 Ack 790525 ltr submitting safeguards contingency plan, Revision 1 Accepts revised & corrected plan.
MCCORKLE, G W Physical Security Licensing Branch 79/06/22 2pp

7908090624 Notifies of plans to modify & expand plant facilities Includes bases for expansions & mods, as well as summary of activities involved in individual parts of program Environ impact info will be submitted separately Floor plan encl.
ESTEY, H P Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/06/22 8pp

7908150309 Forwards request for mods to security guard training & qualification plan Requests revision within 30 days Encl to 790220 ltr withheld (ref 10CFR2 790).
MCCORKLE, G W Physical Security Licensing Branch 79/06/26 2pp

7908200069 Provides milestones for review of 790531 license renewal application Requests comments, recommendations & notification of scheduled insps of facility.
CROW, W T Division of Fuel Cycle & Material Safety 79/06/27 2pp

7908030535 Discusses Amend 18 to License SNM-1227 Ofc of Controller to refund amend fee overpayment of $1,250.
MILLER, W O License Fee Management Branch 79/06/28 1p

7908140320 Forwards Revision 9 of XN-12, "Nuclear Matl Safeguaards Procedures Description for Fuel Fabrication Plants" for License SNM-1227 Encl withheld (ref 10CFR2 790).
NILSON, R Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/06/29 2pp

7908140113 Comments on i..o sent by LC Rouse re mixed oxide fuel plant response to earthquakes.
NILSON, R Exxon Nuclear Co., Inc (subs of Exxon Corp.) 79/07/02 1p

7908150648 Forwards "Seismic Risk Analysis for Exxon Nuclear Pu Facility, Richland, WA."
ROUSE, L C Fuel Reprocess. & Recycle Branch (Pre 790727) 79/07/09 1p

--7908150652 "Seismic Risk Analysis for Exxon Nuclear Pu Facility, Richland, WA."
* TERA Corp 78/09/29 58pp

7908070826 Notifies that license review has been assigned to H Bartz, effective 790709 Arrangements will be made to visit facility.
PARTLOW, J G Material Control Licensing Branch 79/07/10 1p

7908030497 Forwards revised evaluation of possible flooding at facility.
ROUSE, L C Fuel Reprocess. & Recycle Branch (Pre 790727) 79/07/11 1p

7908170146 Notifies that old Condition 6.4.2 to License SNM-1227 should not have been deleted Revised & incorporated as new condition to Amend MPP-2 of license.
PARTLOW, J G Material Control Licensing Branch 79/07/24 1p

7908220078 Discusses 790622 ltr re proposed mods & expansion, which stated no addl info will be submitted Notes some relevant sections of fundamental nuclear matl control plan that will require revision & approval prior to beginning operations.
PARTLOW, J G Material Control Licensing Branch 79/07/26 1p

7908210102 Notice of upcoming $12,090 refund of fee for Amend MPP-2 to License SNM-960 re safeguards contingency plan.
MILLER, W O License Fee Management Branch 79/07/30 1p

7908230301 Notes that contrary to statement in "Revised Evaluation of Possible Flooding at Exxon Nuclear Fuels Facility," approximate analysis of Yakima River in vicinity of Richland, WA was performed by Bulme Forwards rept, W/o encl.
NILSON, R Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 79/08/09 1p

7908220587 Forwards IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial." Action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/10 1p

DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO.

7908010116 Responds to 790416 ltr reporting changes made to facility physical security plan Mods do not reduce effectiveness of physical protection plan & are acceptable.
MCCORKLE, G W Physical Security Licensing Branch 79/06/14 1p

7908010108 Forwards request for changes & additions to 790215 "Security Personnel Training & Qualification Plan," to make document acceptable.
MCCORKLE, G W Physical Security Licensing Branch 79/06/18 4pp

7908080243 Summary of 790613 meeting w/GE & Comm Ed re proposed license amend application to permit testing of decontamination of 6 x 6 BWR assemblies.
EMPSON, F M Fuel Reprocess. & Recycle Branch (Pre 790727) 79/06/21 2pp

7908150303 Confirms 790620 telcon directing licensee to disregard last sentence of first paragraph of NRC 790618 ltr re security personnnel training & qualification plan.
MCCORKLE, G W Physical Security Licensing Branch 79/06/27 1p

7908140131 Notifies of unchanged status of fuel stored in May & June Table showing current status attached.
DAWSON, D M General Electric Co 79/07/02 2pp

7908170159 Forwards NRC Translations 161 & 458 in response to 790703 request W/o encl.
EMPSON, F. M. Fuel Reprocess. & Recycle Branch (Pre 790727) 79/07/09 1p

7908210065 Responds to McCorkle 790504 ltr. Forwards revised safeguards contingency plan w/responses & commentary re NRC-requested changes. Encl withheld (ref 10CFR2.790). After approval, revised plan will be issued in revision NEDG-14507.
DAWSON, D. M. General Electric Co. 79/07/18 2pp.

7908140060 Requests extension to 790730 for filing revision of security personnel training & qualification plan.
DAWSON, D. M. General Electric Co., Nuclear Energy Products Div. 79/07/19 1p.

7908240338 Forwards revised page A-7, App A of NEDG-14507C2, physical security plan. Matl withheld (ref 10CFR2.790).
DAWSON, D. M. General Electric Co. 79/07/26 2pp.

DOCKET 70-1319 U.S. NUCLEAR, INC.

7908060470 Responds to 790514 ltr re retention of US Nuclear Inc records. If corp goes out of business, records should be transferred to NRC. Final decontamination survey is being scheduled.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727) 79/06/07 1p.

7908170607 Ack receipt of 790607 ltr. Requests that documents be given to ANI for storage after statutory requirements for storage terminate.
WAITE, R. T. American Nuclear Insurers 79/06/21 1p.

7908210088 Discusses problems w/transfer of US Nuclear, Inc records to American Nuclear Insurers.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727) 79/07/19 1p.

DOCKET 70-1379 PARKWELL LABORATORIES, INC.

7908130299 Submits decontamination plan for License SNM-1347.
WELLS, C. E. Parkwell Laboratories, Inc. 79/06/18 1p.

7908160023 Discusses 790710-11 meeting w/NRC & ack plans to decontaminate facility, dispose of matl & release facility for unrestricted use. Requests schedule for implementation of program within two weeks. Decontamination plan encl.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/17 7pp.

--7908160026 Draft "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct, Source or SNM," App A.
* Division of Fuel Cycle & Material Safety 79/07/17 4pp.

DOCKET 70-1426 TRANSNUCLEAR, INC.

7908170417 Submits security plan for general license per 10CFR70.20a. During security shipment per 10CFR73, company does not have physical possession of matl but is in control of transportation of formula quantities of SNM.
MANGUSI, J. Transnuclear, Inc. 79/05/21 1p.

7908130630 Forwards 790601 modified contigency plan. Plan withheld (ref 10CFR2.790).
MANGUSI, J. Transnuclear, Inc. 79/06/08 1p.

7908140018 Requests 2-wk extension for submittal of training program plan.
MANGUSI, J. Transnuclear, Inc. 79/06/26 1p.

7908140021 Submits training & qualifications plan. Inland transports & transfer points will utilize Tri-State Motor approved armed guards. Trained police officers will be used during rare instances when approved guards not available.
MANGUSI, J. Transnuclear, Inc. 79/06/26 1p.

7908130592 Notifies of approval of 771215 security plan for shipments of strategic matl. Revision 10, & 790601 safeguards contingency plan. Plans withheld (ref 10CFR2.790).
MCCORKLE, Q. W. Physical Security Licensing Branch 79/07/05 1p.

7908140468 Notifies that extension to 790731 has been granted for submittal of training & qualification plan. Pending approval of plan, drivers & escorts must annually qualify per SNM Manual 2-A & 760514 license condicions.
MCCORKLE, Q. W. Physical Security Licensing Branch 79/07/06 1p.

7908300072 Notifies of minor revisions to 790626 training & qualification plan. W/revisions, plan meets requirements of 10CFR70.20(a), 73.30(e) & 110.50 & is approved. Plan is proprietary per 10CFR2.790(d).
MCCORKLE, Q. W. Physical Security Licensing Branch 79/07/09 1p.

7908160083 Submits addl info to 790713 ltr re irradiated reactor fuel transport route per 10CFR73.37. Discusses escort arrangements made w/Portsmouth, VA police dept.
JOSEPHS, B. Transnuclear, Inc. 79/07/20 1p.

DOCKET 70-1489 GOODYEAR AEROSPACE CORP.

7908240331 Forwards nine revised pages for Part I application for renewal of source matl & SNM-1461.
HESS, G. L. Goodyear Aerospace Corp. (subs. of Goodyear Tire & Rubber Co.). 79/07/24 10pp.

DOCKET 70-1510 NUCLEAR ASSURANCE CORP.

7908010613 Denies 790423 application for renewal of License SNM-1473 re possession of loaded packages for purpose of delivery to carrier for transport between licensed facilities in US.
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety 79/06/14 1p.

7908090609 Notification of 790703 meeting w/Nuclear Assurance Corp in Bethesda, MD to discuss status of request for addl info on QA program for transportation packages.
CONWAY, J. T. Quality Assurance Branch 79/06/27 1p.

DOCKET 70-1622 TENNESSEE VALLEY AUTHORITY

7908010320 Forwards application to renew License SNM-1476 to reflect personnel changes & give util option to process waste at any plant or ship waste to approved burial site.
GILLELAND, J. E. Tennessee Valley Authority 79/06/20 2pp.

--7908010332 Application to renew License SNM-1476 to reflect personnel changes & give util option to process waste at any plant or ship waste to approved burial site.
* Tennessee Valley Authority. 79/05/29. 14pp.

DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO.

7908140457 Notifies of approval of 780912 contingency plan for road transportation. Plan withheld (ref 10CFR2.790).
MCCORKLE, Q. W. Physical Security Licensing Branch 79/06/06 1p.

7908300078 Notifies of extension until 790731 to submit training & qualification plan per 10CFR73.30(e). Pending approval, drivers & escorts must be trained in accordance w/Manual 2-A & NRC 760514 generic license conditions.
MCCORKLE, Q. W. Physical Security Licensing Branch 79/07/09 1p.

7908240191 Forwards training & qualification plan for driver/guards. Plan withheld (ref 10CFR2.790).
MAYER, C. H. Tri-State Motor Transit Co. (subs. of Georgia Pacific Corp.). 79/07/24 1p.

7908300767 Ack receipt of 790724 ltr forwarding guard training & qualification plan. Fee to be assessed upon completion of review.
CABELL, A. S. License Fee Management Branch 79/08/09 1p.

DOCKET 70-1810 WESTINGHOUSE ELECTRIC

7908290650 FOIA request for info re Westinghouse Electric Corp License SNM-1506, operative procedures & definitional stds between NRC & DOE. Draft DOE-NRC agreement encl.
FORSYTH, A. W. Affiliation Unknown 79/08/07. 9pp.

DOCKET 70-1852 WESTINGHOUSE ELECTRIC CORP.

7908240492 Summary of 790717 & 18 trip to facility to view equipment in plant expansion area & to discuss pending amend application w/Westinghouse representatives.
SOONG, A. L., STEVENSON, R. L. Fuel Process. & Fab. Branch (Pre 790727) 79/06/20 2pp.

DOCKET 70-1968 STATE DEPT OF

7908170601 Requests waiver of Condition 10.2.4 of License SNM-960 to permit two export shipments of Pu to Belgium in Aug 1979, w/each shipment being made on separate vessel.
CUNNINGHAM, G.E. General Electric Co., Nuclear Energy Products Div. 79/07/12. 2pp.

7908280784 Discusses IE Insp Rept 70-1968/79-01 on 790525 & 0606. No noncompliance noted.
NORDERHAUG, L.R. Region 5, San Francisco, Safeguards Branch. 79/07/23. 1p.

DOCKET 70-2064 EXXON NUCLEAR FUEL FABRICATION PLANT

7908240489 Summary of 790626-27 & 28 trip to Exxon nuclear fuel fabrication plant & proposed experimental testing facility to BNWL in Richland, WA to conduct site visit & environ review for licensing action.
SHUM, E.Y. Fuel Process. & Fab. Branch (Pre 790727). 79/07/12. 2pp.

DOCKET 70-2130 EXXON NUCLEAR FUEL FABRICATION PLANT

7908240487 Summary of 790626-27 & 28 trip to Exxon nuclear fuel fabrication plant & proposed experimental testing facility to BNWL in Richland, WA to conduct site visit & environ review for licensing action.
SHUM, E.Y. Fuel Process. & Fab. Branch (Pre 790727). 79/07/12. 2pp.

DOCKET 70-2155 WESTINGHOUSE ELECTRIC CORP

7908240492 Summary of 790717 & 18 trip to facility to view equipment in plant expansion area & to discuss pending amend application w/Westinghouse representatives.
SOONG, A.L., STEVENSON, R.L. Fuel Process. & Fab. Branch (Pre 790727). 79/06/20. 2pp.

DOCKET 70-2201 WESTINGHOUSE ELECTRIC CORP

7908240492 Summary of 790717 & 18 trip to facility to view equipment in plant expansion area & to discuss pending amend application w/Westinghouse representatives.
SOONG, A.L., STEVENSON, R.L. Fuel Process. & Fab. Branch (Pre 790727). 79/06/20. 2pp.

DOCKET 70-2219 EXXON NUCLEAR CO., INC

7908150163 Requests assistance of DP Notley in fire safety review of license application. Submits schedule.
CROW, W.T. Fuel Process. & Fab. Branch (Pre 790727). 79/06/05. 1p.

7908240489 Summary of 790626-27 & 28 trip to Exxon nuclear fuel fabrication plant & proposed experimental testing facility to BNWL in Richland, WA to conduct site visit & environ review for licensing action.
SHUM, E.Y. Fuel Process. & Fab. Branch (Pre 790727). 79/07/12. 2pp.

DOCKET 70-2319 OUR LADY OF LOURDES HOSP, CAMDEN, NJ

7908170367 Forwards IE Insp Repts 30-02488/79-01 & 70-2319/79-01 on 790323. Forwards notice of violation.
MCCLINTOCK, R.O. Region 1, Philadelphia, Office of the Director. 79/05/08. 2pp.

7908170360 Ack receipt of 790608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-02488/79-01 & 70-2319/79-01.
MCCLINTOCK, R.O. Region 1, Philadelphia, Office of the Director. 79/07/02. 1p.

--7908170363 Responds to NRC 790508 ltr re violations noted in IE Insp Repts 30-02488/79-01 & 70-2319/79-01. Corrective actions: NRC will be notified of deaths of patients w/nuclear pacemakers & return of pacemakers to manufacturers.
SISTER NORMA. Our Lady of the Lourdes Hosp, Camden, NJ. 79/06/08. 2pp.

--7908170369 Notice of violation from insp on 790323: failure to notify NRC of death of patient w/nuclear pacemaker whithin 24-h, failure to continue followup on pacemaker patients & failure to return pacemaker from deceased patient to manufacturer.
*** Region 1, Philadelphia, Office of the Director. 79/05/08. 2pp.

DOCKET 70-2443 TENNESSEE VALLEY AUTHORITY

7908140163 Forwards application for renewal of license SNM-1476.
GILLELAND, J.E. Tennessee Valley Authority. 79/05/29. 1p.

--7908140166 Application for renewal of License SNM-1476 authorizing receipt, possession, storage, use, testing & transfer of LWR fuel matl at ofc of Power Central Lab in Chattanooga, TN.
GILLELAND, J.E. Tennessee Valley Authority. 79/05/29. 14pp.

7908170610 Requests that License SNM-1716 be extended to 800101, due to const delays.
MILLS, L.M. Tennessee Valley Authority. 79/07/05. 1p.

DOCKET 70-2323 MCGUIRE SPENT FUEL POOL, DUKE POWER CO

7908130360 Response to intervenor NRDC request for Admissions 9-12. Discusses risk of release of fuel in transport, sabotage & potential damage. Page 6 from NRC resopnse to Admissions 1-8 & Certificate of Svc encl.
KETCHEN, E.G. Branch 4. 79/04/18. 10pp.

7908030190 Forwards 790510 ltr to WJ Dircks re amend to License SNM-1773.
PORTER, W.L. Duke Power Co. 79/05/18. 1p.

--7908030197 Forwards response to NRC questions re shipment of spent fuel from Oconee to McGuire, as requested in 790508 telcon.
PARKER, W.O. Duke Power Co. 79/05/10. 4pp.

7906210363 Forwards response to NRDC 790501 interrogatories. Intends to have testimony of CB Sawyer sponsor Interrogatory 1. No witness shall sponsor Interrogatory 2 as cask defect issue will be reviewed in Docket 71-6698. CB Sawyer resume encl.
HOEFLING, R.K. Branch 4. 79/05/21. 4pp.

--7906210370 Responds to NRDC 790501 interrogatories. Provides info re spent fuel transportation & sabotage vulnerability & order to show cause concerning cask defects. Affidavits, documentation & Certificate of Svc encl.
ODEGAARDEN, R.H. Transportation Branch. GIARRATAN, A.C. Technology Assessment Branch. 79/05/21. 30pp.

7906310535 Requests extension until 790528 for filing affidavit re summary disposition of Carolina Environ Study Group contentions.
RILEY, J.L. Carolina Environmental Study Group. 79/05/21. 1p.

7908010662 Forwards 790330 NUREG-0535, "Review & Assessment of Package Requirements (Yellowcake) & Emergency Response to Transportation Accidents." W/o encl.
HELFLING, R.K. Branch 4. 79/05/25. 1p.

7908070104 Forwards SECY-79-278 & SECY-79-278A re physical protection of irradiated fuel shipments. W/o encl.
HOEFLING, R.K. Branch 4. 79/05/25. 1p.

--7908070160 Forwards draft NUREG-0535, "Review & Assessment of Package Requirements (Yellowcake) & Emergency Response to Transportation Accidents." W/o encl.
HOEFLING, R.K. Branch 4. 79/05/25. 1p.

7908240170 Requests copy of new regulations w/regard to hijackings & sabotage re shipment of spent nuclear fuel through urban areas.
BLUM, S. Blum & Shelley. 79/05/25. 1p.

7908020480 Discusses changes in schedule for taking depositions past 790531 close of discovery period. Depositions of D Rotow, A Tamplin & T Cochran will be taken during the first week in June.
KETCHEN, E.G. Branch 4. 79/05/31. 1p.

7908020277 Responds to interrogatory request re spent fuel transportation & storage. Forwards IE repts & info re measurements of fuel shipping casks affected by 790406 show cause order & shipping cask drawings. W/o encls.
HOEFLING, R.K. Branch 4. 79/06/04. 1p.

7908010266 Invites citizens to make limited appearance at 790618-29 proceedings to consider amend to License SNM-1773.
MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/06/08. 1p.

7908060132 Discusses review of 790413 spent fuel storage physical security & interim safeguards contingency plans. Plans not approved. Forwards comments re plans, requests revisions. Attachment to 790413 ltr will be withheld (ref 10CFR2.790).
MCCORKLE, G. W. Physical Security Licensing Branch. 79/06/11. 4pp.

7908200076 Forwards "Rept to President by Interagency Review Group on Nuclear Waste Mgt," in support of citizen group testimony. W/o encl.
ROISMAN, A. Z. Natural Resources Defense Council. 79/06/26. 1p.

7908130169 Notification of 790711 meeting w/util in Silver Spring, MD to discuss matls & info required to comply w/10CFR73.37, "Requirements for Physical Protection of Irradiated Reactor Fuel in Transit."
SPITALNY, B. S. Fuel Reprocess. & Recycle Branch (Pre 790727). 79/07/06. 1p.

7908130230 Notice of resumption of evidentiary hearing on 790806.
MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/07/13. 1p.

7908...0088 Requests approval for W McNeill to participate in 790806 evidentiary hearings re Duke Power Co proposed shipment of spent fuel for storage at McGuire.
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 79/07/18. 1p.

7908030435 Responds to FOIA request for documents prepared by NRC &/or NRC consultants re alternatives to Duke Power Co proposal to ship spent fuel from Oconee to McGuire.
FELTON, J. M. Division of Rules and Records. 79/07/19. 2pp.

--7908030472 Forwards responses to Carolina Environ Study Group first set of interrogatories re licensing action under review for amend of License SNM-1773.
SPITALNY, B. S. Fuel Reprocess. & Recycle Branch (Pre 790727). 78/10/27. 7pp.

7908210614 Summary of 790711 closed meeting w/util re physical protection of shipments of spent fuel from Oconee to McGuire. Meeting info withheld (ref 10CFR2.790).
HILLMAN, C. A. Physical Security Licensing Branch. 79/07/19. 2pp.

7908220049 Forwards addl direct & rebuttal testimony of Nash, Pittiglio, Nahem[illegible] & Parsont re amend of License SNM-1773 concerning tran[illegible]t of Oconee spent fuel to McGuire for storage.
KETCHEN, E. G. Branch 4. 79/07/20. 23pp.

7908220505 Forwards addl info re communication network to be used during shipment of fuel. Requests that network be approved as equivalent to communication w/radiotelephone. Info withheld (ref 10CFR2.790).
PARKER, W. O. Duke Power Co. 79/07/30. 1p.

7908100472 Forwards "Cask Drop Analysis" using Natl Lead Industries 1/2 cask.
RAER, R. L. Duke Power Co. 79/08/02. 1p.

--7908100473 "Cask Drop Analysis."
* Duke Power Co. 79/08/02. 6pp.

7908150037 Transcript of 790806 hearing in Charlotte, NC. Pp 2,887-3,118.
MILLER, M. E., LUEBKE, E. A., HAND, C. H. Atomic Safety and Licensing Board Panel. 79/08/06. 231pp.

7908150042 Transcript of 790807 hearing in Charlotte, NC. Pp 3,119-3,357.
MILLER, M. E., LUEBKE, E. A., HAND, C. H. Atomic Safety and Licensing Board Panel. 79/08/07. 238pp.

7908150022 Transcript of 790808 hearing in Charlotte, NC. Pp 3,358-3,590.
MILLER, M. E., LUEBKE, E. A., HAND, C. H. Atomic Safety and Licensing Board Panel. 79/08/08. 232pp.

7908150722 Transcript of 790809 hearing in Charlotte, NC. Pp 3,591-3,844.
MILLER, M. E., LUEBKE, E. A., HAND, C. H. Atomic Safety and Licensing Board Panel. 79/08/09. 253pp.

DOCKET 70-2684 TRANSNUCLEAR, INC.

7908080482 Responds to FOIA request for documents re insp performed in Mar & Apr 1979 of Baystate Medical Ctr, Springfield, MA. Forwards McClintock 790402 & 0510 ltrs Ctr & Brahmaver 790411 ltr to McClintock.
FELTON, J. M. Division of Rules and Records. 79/08/02. 1p.

--7908080505 Forwards IE Insp Rept 70-2684/79-01 on 790306 & notice of violation. Insp rept not encl.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 79/04/02. 2pp.

--7908080566 Notice of violation from insp on 790306.
* Region 1, Philadelphia, Office of the Director. 79/08/03. 2pp.

--7908080577 Responds to 790402 ltr. Submits explanations & corrective actions for each item in notice of violation re disposal of [illegible]ing containers, receipt of radioactive matl, radiation area & records. Forwards 790307 & 0413 ltrs.
ZU[illegible]BI, S. M., QIF/ORD, H. C. F. Baystate Medical Center MA/SP. 79/04/11. 14 p.

DOCKET 70-2696 ALBERT EINSTEIN MEDICAL CENTER, PHILADELPHIA, PA

7908240082 Ack receipt of 790517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 40-8002/79-01 & 70-2696/79-01.
MCCLINTOCK, R. O. Region 1, Philadelphia, Safeguards Branch. 79/06/15. 1p.

--7908240088 Responds to NRC 790508 ltr re violations noted in IE Insp Repts 40-8002/79-01 & 70-2696/79-01. Corrective actions: proposal submitted for const of barrier which will seal corridor to storage area.
BAKER, A. S. Albert Einstein Medical Center. 79/05/17. 1p.

--7908240099 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 40-8002/79-01 & 70-2696/79-01. Addl info required re periodic audits of every authorized user & limits on continuous individual exposure.
MCCLINTOCK, R. O. Region 1, Philadelphia, Safeguards Branch. 79/05/08. 1p.

--7908240113 Responds to NRC 790320 ltr re violations noted in IE Insp Repts 40-8002/79-01 & 70-2696/79-01. Corrective actions: procedures explained to technician, "hot trash" to be monitored & lead bricks properly replaced.
BAKER, A. S. Albert Einstein Medical Center. 79/04/03. 2pp.

--7908240117 Forwards notice of violation from IE Insp Repts 40-8002/79-01 & 70-2696/79-01.
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/03/20. 3pp.

--7908240122 Notice of violation from IE insp on 790215-16. Items of noncompliance: failure to adequately evaluate quantity & distribution of contamination on hands of nuclear medicine technician & failure to properly survey trash cans.
* Region 1, Philadelphia, Office of the Director. 79/03/20. 2pp.

DOCKET 70-2804 TRANSNUCLEAR, INC.

7908310102 Forwards IE Insp Rept 70-2804/79-01 on 790509. No noncompliance noted. Insp rept withheld (ref 10CFR2.790).
NORDERHAUG, L. R. Region 5, San Francisco, Safeguards Branch. [illegible]/06/13. 2pp.

DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO.

7908230125 Forwards documents used to determine acceptance for 10CFR70 license to possess nuclear fuel. License & two amend encl.
BARTH, C. A. Branch 3. 79/07/03. 1p.

--7908230129 Notifies of Amend 2 to License SNM-1823 re authorized use of enriched U per 10CFR70.9.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727). 79/05/03. 1p.

--7908230134 Recommends approval of util 790412 application for amend of License SNM-1823. License should be revised re types & capacities of fuel handling cranes for receipt & storage of fuel assemblies.
DELANEY, J. C. Fuel Process. & Fab. Branch (Pre 790727). 79/05/03. 1p.

--7908230139 Notifies of Amend 1 to License SNM-1823 per 10CFR70.4 & 70.9. Revises conditions re expiration date, authorized use & leak testing.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727). 79/03/06. 2pp.

--7908230144 Recommends approval of util 790202 application for amend to License SNM-1823. License should be revised to allow use of nominal 5 Ci Pu-beryllium neutron source & expiration date should be contingent upon conversion to CP.
DELANEY, J. C. Fuel Process. & Fab. Branch (Pre 790727). 79/03/06 2pp.

--7908230147 Forwards License SNM-1823 & Indemnity Agreement B-85. Indemnity Agreement not encl.
ROUSE, L. C. Fuel Process. & Fab. Branch (Pre 790727). 78/06/26. 2pp.

--7908230152 License SNM-1823 authorizing receipt, possession, insp, storage & packaging of U-235 by util.
ROUSE, L. C. Fuel Process. & Fab. Branch (Pre 790727). 78/06/26. 2pp.

--7908230157 Safety evaluation rept re util 780308 application & 780331 suppl re storage of fuel & accessories. Proposed activities will not endanger health & safety of public. Recommends approval.
DELANEY, J. C. Fuel Process. & Fab. Branch (Pre 790727). 78/06/26. 3pp.

--7908230164 Forwards four revised pages to 780314 license application re storage of unirradiated reactor fuel & radioactive matl. Revisions concern fuel handling cranes.
FLYNN, J. D. Cincinnati Gas & Electric Co. 79/04/12. 5pp.

--7908230186 Requests amend to License SNM-1823. Requests use of 5 Ci Pu-beryllium neutron source & expiration date be made contingent upon conversion to CP.
FLYNN, J. D. Cincinnati Gas & Electric Co. 79/02/02. 2pp.

--7908230192 Forwards revised page to 780314 license application re storage of unirradiated reactor fuel & radioactive matl. Revision corrects typographical error.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 78/03/31. 2pp.

--7908230197 Submits license application for storage of unirradiated reactor fuel & radioactive matl per 10CFR70.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 78/03/14. 1p.

7908310448 Requests amend of final sentence re fuel bundling operations on page 8 of license application for storage of unirradiated reactor fuel & associated matl. Temporary wheel mounted crane must be operated by Kaiser employees.
FLYNN, J. D. Cincinnati Gas & Electric Co. 79/07/30. 1p.

DOCKET 70-2842 TRANSNUCLEAR, INC.

7908270105 Forwards IE Insp Rept 70-2842/79-01 on 790601-03. No noncompliance noted.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/06/25. 1p.

--7908270109 IE Insp Rept 70-2842/79-01 on 790601-03. No noncompliance noted. Major areas inspected: export shipment of SNM.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/06/25. 1p.

DOCKET 70-2884 LONG ISLAND LIGHTING CO.

7908150009 Responds to 790608 ltr re util 780925 application for 10CFR70 license. No requirements for hearing prior to issuance of license.
HOEFLING, R. K. Branch 4. 79/07/03. 1p.

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY

7908240177 Forwards application for SNM license per 10CFR70. Includes Sections 9.1 & 4.3.2.7 of FSAR re spent fuel pit storage racks & nuclear safety analysis. Fuel delivery to site will begin 790901.
GILLELAND, J. F. Tennessee Valley Authority. 79/06/08. 1p.

--7908240183 Application for SNM license. Includes Sections 9.1 & 4.3.2.7 of FSAR re spent fuel pit storage racks & nuclear safety analysis.
* Tennessee Valley Authority. 79/06/08. 49pp.

7908240468 Advises that 790608 application for SNM license has been filed under new docket. License cannot be issued until review completed.
CROW, W. T. Fuel Process. & Fab. Branch (Pre 790727). 79/07/17. 1p.

DOCKET 70-2911 CAROLINA POWER & LIGHT CO.

7908240057 Notifies that util will continue shipment of irradiated reactor fuel for storage per encl schedule & DLs. Encls withheld (ref 10CFR2.790).
* Carolina Power & Light Co. 79/06/28. 2pp.

DOCKET 70-9021 TECH/OPS RADIATION PRODUCTS DIV.

7908290422 Requests renewal of Certificate of Compliance 9021 issued for Technical Operations Manual B Package. Forwards "Package Description" & renewal fee.
MUNRA, J. J. Tech/Ops (Technical Operations, Inc.). 79/07/25. 59pp.

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0005 MAGNAFLUX CORP.

7908070804 Requests extension until 790730 to submit addl data requested re QA program.
HALL, J. Magnaflux Corp. (subs. of Peabody Caliou Corp.). 79/06/29. 1p.

7908290036 Forwards QA program per 10CFR71.51.
HALL, J. Magnaflux Corp. (subs. of Peabody Caliou Corp.). 79/07/27. 1p.

--7908290040 QA program.
GRELLA, A. W. Magnaflux Corp. (subs. of Peabody Caliou Corp.). 79/07/28. 17pp.

DOCKET 71-0009 ISOMEDIX, INC.

7908070838 Responds to NRC 790601 request for info re design control in QA program. Forwards 790625 Suppl 1 to QA program for control & shipment of 20WC-5 shipping containers.
DIETZ, G. R. Isomedix, Inc. (subs. of Maesfield Enterprises, Inc.). 79/06/28. 1p.

--7908070843 Suppl 1 to QA program for control & shipment of 20WC-5 shipping containers.
DIETZ, G. R. Isomedix, Inc. (subs. of Maesfield Enterprises, Inc.). 79/06/25. 2pp.

7908200411 Notifies that 790628 ltr only partially responded to NRC 790601 requests. Two items in design control area must be answered. QA program should be applied to all aspects of radioactive shipping packages.
MACDONALD, C. E. Transportation Branch. 79/07/30. 1p.

DOCKET 71-0010 GAMMA INDUSTRIES

7908010297 Responds to 790530 ltr re QA program. Requests 30-day extension to prepare response.
RICHARDSON, H. D. Nuclear Systems, Inc., Gamma Industries, Inc. Div. 79/06/11. 2pp.

7908020332 Ack receipt of 790611 comments on NRC 790530 ltr re Gamma Industries QA program for radioactive matl transportation packages. Clarifies NRC requirements for QA programs.
MACDONALD, C. E. Transportation Branch. 79/06/25. 3pp.

7908160150 Forwards App 1 to QA program, inadvertently omitted from 790713 ltr.
RICHARDSON, H. D. Gamma Corp. 79/07/16. 1p.

--7908160156 App 1 to Gamma Industries QA program.
* Gamma Corp. 79/07/16. 1p.

DOCKET 71-0013 NAVY, DEPT. OF

7908230057 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 780606, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-0014 ADIRONDACK STEEL CASTING CO.

7908200159 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

--7908200161 QA program approval for radioactive matl package 0014, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29. 1p.

DOCKET 71-0016 NORTHWEST AIRLINES, INC

7908090265 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29. 1p.

--7908090269 QA program approval for radioactive matl package 0016, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

DOCKET 71-0018 NUCLEAR ASSURANCE CORP

7908100567 Responds to NRC 790530 ltr requesting addl info on QA program. Forwards draft QA manual.
ROLLINS, J. D. Nuclear Assurance Corp. 79/07/02. 2pp.

--7908100590 Draft QA manual.
SCHUTT, P. F.; ROLLINS, J. D.; WEBSTER, D. A. Nuclear Assurance Corp. 79/07/03. 123pp.

7908070788 Supplements 790702 QA program. Forwards organization chart.
ROLLINS, J. D. Nuclear Assurance Corp. 79/07/05. 1p.

--7908070792 Suppl to 790702 QA program. Figure 1-corporate & engineering & transportation svc organization chart.
* Nuclear Assurance Corp. 79/07/05. 1p.

DOCKET 71-0020 INTERNATIONAL TESTING LABS

7908090602 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

--7908090608 QA program approval for radioactive matl package 0020, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

DOCKET 71-0021 UNIV. TECH. TESTING LABS., INC.

7908230023 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 780630, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP

7908140399 Forwards Revision 5 to QA program.
ROWE, B. Hittman Nuclear & Development Corp. (subs. of Hittman Corp.). 79/07/09. 1p.

--7908140406 QA program, Revision 5.
* Hittman Nuclear & Development Corp. (subs. of Hittman Corp.) 79/07/09. 57pp.

DOCKET 71-0030 GENERAL ATOMIC CO

7908090307 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908090312 QA program approval for radioactive matl package 0030, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0031 MARYLAND SHIPBUILDING & DRY DOCK CO

7908090177 Forwards QA program for shipping packages.
CARTER, W. K. Maryland Shipbuilding & Drydock Co. (Subs. of Fruehauf Corp.). 79/06/18. 1p.

--7908090179 QA program for shipping packages.
CARTER, W. K. Maryland Shipbuilding & Drydock Co. (Subs. of Fruehauf Corp.). 79/06/18. 3pp.

7908280424 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/08/03. 1p.

--7908280430 QA program approval for radioactive matl package 0031, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/08/03. 1p.

DOCKET 71-0033 IND. TEST. LAB. SERVICES CORP.

7908280333 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/11. 1p.

--7908280338 QA program approval for radioactive matl package 0033, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/11. 1p.

DOCKET 71-0036 ITT GRINNELL CORP.

7908280458 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/11. 1p.

7908280463 QA program approval for radioactive matl package 0036, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/11. 1p.

DOCKET 71-0040 TECHNICAL OPERATIONS, INC.

7908100373 Forwards revised description of QA program, in response to NRC 790606 ltr.
MUNRO, J. J. Tech/Ops (Technical Operations, Inc.). 79/07/09. 1p.

--7908100374 QA Program, Revision 1.
* Tech/Ops (Technical Operations, Inc.). 79/07/09. 14pp.

DOCKET 71-0044 UNITED AIR LINES

7908140757 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

--7908140762 QA program approval for radioactive matl package 0044, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

DOCKET 71-0049 NAVY, DEPT OF

7908230046 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 780615, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-0053 BOEING SERVICES INTERNATIONAL, INC.

7908230638 Requests submittal of revised application in support of 780621 request for approval of QA program. Original submittal did not meet requirements of 10CFR Part 71. Sample QA program encl. Application due within 30 days.
MACDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-0058 NAVY, DEPT OF

7908230039 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 780623, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-0064 PEABODY TESTING/X-RAY ENG. CO.

7908230630 Requests addl info re annual audits in order to complete review of 780623 application requesting approval of QA program. Info should be submitted within 30 days.
MACDONALD, C. E. Transportation Branch. 79/08/03. 2pp.

DOCKET 71-0066 CERTIFIED TESTING LABS., INC.

7908280285 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/11. 1p.

--7908280293 QA program approval for radioactive matl package 0066, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/11 1p.

DOCKET 71-0067 MEDI-PHYSICS, INC.

7908240282 Responds to 790601 ltr re QA program per 10CFR71, App E. Forwards QA program for shipping packages of radioactive matl.
BARAK, M. Medi-Physics, Inc. 79/07/19 1p.

--7908240286 QA program for shipping packages of radioactive matl
RUDLEY, W. W. Medi-Physics, Inc. 79/07/18 3pp.

7908230092 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

--7908230116 QA program approval for radioactive matl package 0067, Revision 0.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

DOCKET 71-0070 GENERAL MOTORS CORP.

7908090474 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/11 1p.

--7908090479 QA program approval for radioactive matl package 0070, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/11 1p.

DOCKET 71-0072 BABCOCK & WILCOX CO.

7908160534 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908160536 QA program approval for radioactive matl package 0072, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0081 ITT GRINNELL INDUSTRIAL PIPING, INC.

7908090132 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908090137 QA program approval for radioactive matl package 0081, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0084 HUICO, INC.

7908220504 Forwards sample QA program for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 790608, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch 79/08/03 3pp.

DOCKET 71-0085 NAVY, DEPT. OF

7908140384 Forwards Section H of QA program.
KINNEAR, R. J. Navy, Dept. of 79/07/05 3pp.

7908230206 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

--7908230209 QA program approval for radioactive matl package 0085, Revision 0.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

DOCKET 71-0091 EASTERN AIRLINES, INC.

7908090127 Forwards request for addl info to complete review of QA program.
MACDONALD, C. E. Transportation Branch 79/07/05 2pp.

7908200101 Forwards revised QA program.
CHATTIN, H. S. Eastern Airlines, Inc. 79/07/17 1p.

--7908200103 Revised QA program.
* Eastern Airlines, Inc. 79/07/17 5pp.

7908230033 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

--7908230037 QA program approval for radioactive matl package 0091, Revision 0.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

DOCKET 71-0092 EASTMAN KODAK CO.

7908080386 Forwards request for addl info to complete review of QA program.
MACDONALD, C. E. Transportation Branch 79/07/19 4pp.

7908270375 Forwards revised description of duties & qualifications of marketing education specialist, w/organization chart requested in 790719 ltr.
HARTER, E. S. Eastman Kodak Co. 79/07/30 3pp.

DOCKET 71-0093 HUNTINGTON TESTING

7908090252 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/11 1p.

--7908090258 QA program approval for radioactive matl package 0093, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/11 1p.

DOCKET 71-0097 NONDESTRUCTIVE TESTING SERVICE

7908230034 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 780622, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch 79/08/03 3pp.

DOCKET 71-0099 FOSTER WHEELER ENERGY CORP.

7908010145 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010151 QA program approval for radioactive matl package 0099, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0100 VENEGAS IND. TEST LABS., INC.

7908280298 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/11 1p.

--7908280313 QA program approval for radioactive matl package 0100, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/11 1p.

DOCKET 71-0109 UNION CARBIDE CORP.

7908160350 Forwards "Radioactive Matl Packaging QA Program."
PERHAUCH, J. C. Union Carbide Corp. 79/07/18 1p.

--7908160353 "Radioactive Matl Packaging QA Program."
* Union Carbide Corp. 79/05/18 37pp.

DOCKET 71-0111 MATERIAL TESTING LAB. OF VIRGINIA, INC.

7908280408 Requests cancellation of request for approval application for QA program.
JORDAN, D. S. The Stanwick Corp. 79/06/26 1p.

--7908280417 Forwards revision of QA program for review.
STEELE, W. F. Materials Testing Laboratory 79/06/15 9pp.

7908030091 Forwards QA program revision, in response to NRC 790427 ltr.
STEEL, W. F. Materials Testing Laboratory 79/07/05 1p.

--7908030097 QA program for industrial radiography.
* Materials Testing Laboratory 79/07/05 8pp.

7908100146 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

--7908100148 QA program approval for radioactive matl package:111.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

DOCKET 71-0116 NAVY, DEPT OF

7908080368 Endorses QA program for "USS Prairie."
VOGT, J. F. Navy, Dept of, Naval Nuclear Power Unit 79/07/16 1p.

--7908080372 Forwards "USS Prairie" QA program for receipt handling, storage & transfer of special forms of radioactive matls.
HELMS, R. E. Navy, Dept of 79/06/27 1p.

--7908080375 QA program for "USS Prairie."
HELMS, R. E. Navy, Dept of 79/06/27 13pp.

DOCKET 71-0117 ABEX CORP

7908230432 Requests submittal of revised application in support of 780630 request for approval of QA program. Original submittal did not meet requirements of 10CFR71. Sample QA program encl. Application due within 30 days.
MACDONALD, C. E. Transportation Branch 79/08/03 3pp.

DOCKET 71-0125 TESTCO, INC

7908080625 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/11 1p.

--7908080629 QA program approval for radioactive matl package:0125, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/11 1p.

DOCKET 71-0126 STANWICK CORP

7908280408 Requests cancellation of request for approval application for QA program.
JORDAN, D. S. The Stanwick Corp 79/06/26 1p.

--7908280417 Forwards revision of QA program for review.
STEELE, W. F. Materials Testing Laboratory 79/06/15 9pp.

DOCKET 71-0128 AMOCO OIL CO

7908010671 Forwards organization chart to complete info on QA program.
NORGAARD, J. A. Amoco Corp 79/06/06 2pp.

7908010129 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010135 QA program approval for radioactive matl package:0128, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0129 NAVY, DEPT OF

7908230051 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 780628, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch 79/08/03 3pp.

DOCKET 71-0131 WELDING INSTITUTE OF ALASKA

7908150329 Forwards QA program for License 50-17446-01.
LOCKMAN, D. M. Welding Institute of Alaska 79/05/25 1p.

--7908150333 QA program for License 50-17446-01.
LOCKMAN, D. M. Welding Institute of Alaska 79/05/25 4pp.

7908150699 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/10 1p.

--7908150701 QA program approval for radioactive matl package:131, Revision 0.
MACDONALD, C. E. Transportation Branch 79/05/21 1p.

DOCKET 71-0137 METALS TESTING CO., INC

7908150168 Forwards Revision 1 to QA program.
DELISLE, R. Metals Testing Co., Inc 79/06/11 1p.

--7908150174 Revision 1 to QA program.
* Metals Testing Co., Inc 79/06/11 3pp.

DOCKET 71-0141 ROCKWELL INTERNATIONAL

7908270368 Forwards Supply & Mass Transit Div QA program.
WEAVER, M. L. Rockwell International Corp 79/08/01 3pp.

DOCKET 71-0146 GLOBE X-RAY SERVICES, INC

7908160538 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908160542 QA program approval for radioactive matl package:0146, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0147 AMOCO OIL CO

7908230632 Requests addl info re organizational description in order to complete review of 780629 application requesting approval of QA program. Info should be submitted within 30 days.
MACDONALD, C. E. Transportation Branch 79/08/03 2pp.

DOCKET 71-0149 MIDWEST INSPECTION SERVICES

7908140315 Forwards QA program for transport packages per 10CFR71.
PASCHEN, D. Midwest Inspection Services, Inc 79/06/30 1p.

--7908140329 QA program for transport packages.
* Midwest Inspection Services, Inc 79/06/30 6pp.

7908090395 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090399 QA program approval for radioactive matl package:0149, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0155 BATH IRON WORKS CORP

7908090385 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090390 QA program approval for radioactive matl package:0155, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0158 X-RAY INDUSTRIES, INC

7908090377 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090382 QA program approval for radioactive matl package:0158, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0167 FINLAY TESTING LABORATORIES

7908080363 Forwards revised page of QA manual providing requested addl info re audits.
FINLAY, G. W. Finlay Testing Laboratories 79/06/22 2pp.

7908230097 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/08/03. 1p.

--7908230098 QA program approval for radioactive matl package 0167, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/08/03. 1p.

DOCKET 71-0172 EMPIRE STEEL CASTINGS, INC.

7908090317 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908090324 QA program approval for radioactive matl package 0172, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0175 GC SERVICES, INC.

7908010106 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

--7908010109 QA program approval for radioactive matl package 0175, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

DOCKET 71-0176 NAVY, DEPT OF

7908230062 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 780629, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-0181 CONSOLIDATED X-RAY SERVICE CORP.

7908010100 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

--7908010104 QA program approval for radioactive matl package 0181, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

DOCKET 71-0186 HIGH STEEL STRUCTURES, INC.

7908090370 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908090373 QA program approval for radioactive matl package 0186, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0188 MAYNARD STEEL CASTING CO.

7908020037 Forwards second revision to QA program.
FAIST, C. A. Maynard Steel Casting Co. 79/06/08. 1p.

--7908020042 QA program, Revision 2.
* Maynard Steel Casting Co. 79/06/08. 6pp.

7908070740 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

--7908070746 QA program approval for radioactive matl package 0188, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

DOCKET 71-0189 TODD SHIPYARDS CORP.

7908100582 Requests extension of 60 days from 790611 to submit QA program description, to comply w/criteria in NRC 790605 ltr.
HATWAY, C. W. Todd Shipyards. 79/06/22. 1p.

DOCKET 71-0190 TEXAS INSTRUMENTS, INC.

7908160081 Denies 790508 request for withdrawal of QA program submitted 780807. Response to 790427 ltr re QA program due by 790810. Registration required prior to addl shipment of packages w/more than Type A quantity of matl.
MACDONALD, C. E. Transportation Branch. 79/07/05. 1p.

DOCKET 71-0196 SOONER X-RAY & MAG., INC.

7908230030 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 780718, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-0197 BETHLEHEM STEEL CORP.

7908230024 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 781005, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-0198 NUCLEAR FUEL SERVICES, INC.

7908090448 Discusses licensee plans to submit info requested in NRC 790706 ltr re West Valley QA program. Requests meeting w/NRC to determine NRC safety-related criteria as applied to shipping packages.
CLARK, J. R. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/07/06. 1p.

DOCKET 71-0199 NAVY, DEPT OF

7908080410 Forwards request for addl info to complete review of QA program.
MACDONALD, C. E. Transportation Branch. 79/07/19. 4pp.

DOCKET 71-0200 INDUSTRIAL INSPECTION & TEST CO.

7908220498 Forwards sample QA program for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 791024, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

7908220541 Submits revised QA program for shipping containers.
WINGET, R. H. Industrial Inspection Test. 79/08/09. 3pp.

DOCKET 71-0201 DURALLOY BLAW-KNOX, INC.

7908230636 Requests addl info in order to complete review of 781101 application requesting approval of QA program. Info pertains to document control, audits & insp, test & operating status & should be submitted within 30 days.
MACDONALD, C. E. Transportation Branch. 79/08/03. 2pp.

DOCKET 71-0206 PRYOR FOUNDRY, INC.

7908230027 Forwards sample QA program dtd 790402 for industrial radiography licensees. Requests revised application for QA program approval. Original application, dtd 781130, did not meet 10CFR71.51 requirements.
MCDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-0209 JACKSONVILLE SHIPYARDS, INC.

7908090362 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908090365 QA program approval for radioactive matl package 0209, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0210 GULF OIL CORP.

7908170510 Submits info requested by NRC 790702 ltr re QA application.
MALEK, F. A. Gulf Nuclear, Inc. 79/07/20. 2pp.

DOCKET 71-0212 GENERAL ELECTRIC CO.

7908020138 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/29. 1p.

--7908020145 QA program approval for radioactive matl package 0212, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0213 INTERMOUNTAIN TESTING CO.

7908010598 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010602 QA program approval for radioactive matl package 0213, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0214 GAS RENTALS, INC.

7908010583 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010586 QA program approval for radioative matl package 0214, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0215 SPACE SCIENCE SERVICES

7908010015 Confirms NRC telcon re clarification of radiation safety officer & radiation protection officer positions. Both are applicable to DA Geiger.
GEIGER, D. A. Space Science Services, Inc. 79/06/07 1p.

7908010592 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010595 QA program approval for radioactive matl package 0215, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0220 GENERAL DYNAMICS CORP.

7908010114 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29.

--7908010120 QA program approval for radioactive matl package 0220, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0221 ALLIS CHALMERS CORP.

7908010406 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010409 QA program approval for radioactive matl package 0221, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0222 ST. LOUIS TESTING LABS, INC.

7908010411 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010413 QA program approval for radioactive matl package 0222, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0223 B. F. SHAW, INC.

7908010452 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010460 QA program approval for radioactive matl package 0223, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0224 GUYON POWER & PROCESS PIPING

7908010464 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010466 QA program approval for radioactive matl package 0224, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0229 WORD INDUSTRIES PIPE FABRICATING, INC.

7908010473 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010477 QA program approval for radioactive matl package 0229, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0231 CHEM-NUCLEAR SYSTEMS, INC.

7908160076 Forwards request for addl info & revised QA-AD-001, "QA Program," for review of 781221 application seeking QA program approval.
MACDONALD, C. E. Transportation Branch 79/07/05 3pp.

7908200074 Requests extension of response deadline to 790910 w/regard to 790705 request for addl info.
REYNOLDS, L. E. Chem-Nuclear Systems, Inc. 79/07/31 1p.

DOCKET 71-0232 LAKEHEAD TESTING LAB., INC.

7908010170 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010177 QA program approval for radioactive matl package 0232, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0233 O'NEILL TANK CO., INC.

7908010201 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010209 QA program approval for radioactive matl package 0233, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0234 X-RAY, INC.

7908090490 Forwards QA program for X-Ray, Inc.
CONNEL, L. G. X-Ray, Inc. 79/06/01 1p.

--7908090495 QA program for X-Ray, Inc.
* X-Ray, Inc. 79/06/01 3pp.

7908010230 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010237 QA program approval for radioactive matl package 0234, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0237 COLUMBIA GAS TRANSMISSION CO.

7908210192 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908210195 QA program approval for radioactive matl package 0237, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0238 AGRICULTURE, DEPT. OF

7908150025 Forwards revised USDA QA program for packaging & shipment of radioactive matls, per 781226 & 790427 ltrs.
KWAST, C. Z. Agriculture, Dept. of 79/07/03 1p.

--7908150030 Revised USDA QA program for packaging & shipment of radioactive matls.
* Agriculture, Dept. of 79/07/03 4pp.

7908200417 Responds to 790703 application re approval of QA program per 10CFR71.51 Program does not specify that members of audit team have no responsibility in activity being audited.
MACDONALD, C. E. Transportation Branch 79/07/27 1p.

DOCKET 71-0241 UNITED NUCLEAR CORP.

7908140476 Forwards revised QA program for radioactive matl shipping containers, per 790420 request for addl info.
BOWERS, C. E. United Nuclear Corp. 79/07/03 1p.

--7908140479 QA program for radioactive matl shipping containers.
GREGG, B. United Nuclear Corp. 79/06/03 15pp.

DOCKET 71-0242 LAW ENGINEERING TESTING CO.

7908010403 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010404 QA program approval for radioactive matl package 0242, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0243 TRANSEASTERN INSPECTION, INC.

7908010188 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010195 QA program approval for radioactive matl package 0243, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0244 NL INDUSTRIES, INC.

7908140011 Forwards drawing of NL-1 10/24 rail cask as requested by C Williams.
STUKENBROEKER, G. NL Industries, NL Nuclear Div. 79/07/[illegible] 2pp.

DOCKET 71-0245 NAVY, DEPT OF

7908090418 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090421 QA program approval for radioactive matl package 0245, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0246 INSPECTION SERVICES CORP.

7908270461 Responds to 790705 ltr requesting addl info for QA program. Forwards revised QA program document to meet NRC requirements.
ALEXANDER, H. Inspection Services Corp. 79/07/24 2pp.

--7908270467 QA program for facility.
* Inspection Services Corp. 79/07/24 4pp.

DOCKET 71-0247 IRT CORP.

7908010217 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010225 QA program approval for radioactive matl package 0247, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0248 MONSANTO RESEARCH CORP.

7908080357 Requests 30-day extension of 790711 resubmittal date for QA program info. Original program requires significant revision & will not be completed until 790810.
TAYLOR, R. R. Monsanto Research Corp. 79/07/09 1p.

DOCKET 71-0253 TWIN PORTS TESTING, INC.

7908010588 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010590 QA program approval for radioactive matl package 0253, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0254 GENERAL ELECTRIC CO.

7908010091 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/06 1p.

--7908010095 QA program approval for radioactive matl package 0254, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/06 1p.

DOCKET 71-0255 WALWORTH CO.

7908140103 Forwards QA program, Revision 1.
PLESZ, E. N., DELYNKO, R. Walworth Co. (subs. of IU International Corp.) 79/07/11 1p.

--7908150110 Revision 1 of QA program for radiographic operations. Outlines duties & responsibilities for mgt in administration of QA for radiographics.
DELYNKO, R., PLESZ, E. N., CURRY, P. T. Walworth Co. (subs. of IU International Corp.) 79/07/02 6pp.

DOCKET 71-0257 INDUSTRIAL LABS, INC.

7908010600 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Licensing Management Branch 79/06/29 1p.

--7908010605 QA program approval for radioactive matl package 0257, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/19 1p.

DOCKET 71-0258 NUCLEAR ENGINEERING CO., INC.

7908210051 Responds to 790521 ltr re QA program submitted by Nuclear Engineering Co. QA program must be revised to reflect transfer of ownship to Teledyne Energy Sys. Program must also address six waste package designs.
MACDONALD, C. E. Transportation Branch 79/07/27 1p.

DOCKET 71-0261 NAVY, DEPT. OF

7908230673 Forwards for approval QA program for radioactive matl shipping packages associated w/radiography, per License 31-18182-01.
BEARD, P. M. Navy, Dept. of 79/07/10 1p.

--7908230675 QA program for radioactive matl associated w/radiography.
BEARD, P. M. Navy, Dept. of 79/07/10 5pp.

7908270314 Forwards QA program re receipt, use & transfer of radioactive matl shipping packages for License 31-18182-01.
BEARD, P. M. Navy, Dept. of 79/07/10 2pp.

--7908270317 QA program re receipt, use & transfer of radioactive matl shipping packages for License 31-18182-01.
* Navy, Dept. of 79/07/10 4pp.

7908090675 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

--7908090676 QA program approval for radioactive matl package 0261, Revision 0.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

DOCKET 71-0264 AUTOMATON INDUS., INC.

7908150522 Responds to 790615 ltr. Forwards revised QA program for shipping packages.
SANTORO, M. P. Automation Industries, Inc. 79/07/09 1p.

--7908150527 Revised QA program re design, fabrication, testing, maint & use of shipping packages for radioactive matl.
* Automation Industries, Inc. 79/07/09 22pp.

7908240199 Forwards request for addl info to complete review of QA program.
MACDONALD, C. F. Transportation Branch 79/08/15 7pp.

DOCKET 71-0268 NAVY, DEPT. OF

7908090405 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090407 QA program approval for radioactive matl package 0268, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0269 LEHIGH TESTING LABORATORIES, INC.

7908090355 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090358 QA program approval for radioactive matl package 0269, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0270 FACTORY MUTUAL ENGINEERING CORP.

7908090492 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29.

--7908090497 QA program approval for radioactive matl package 0270, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0272 CRANE CO.

7908010378 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908010382 QA program approval for radioactive matl package 0272, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0274 NAVY, DEPT. OF

7908090436 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090439 QA program approval for radioactive matl package 0274, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0276 NAVY, DEPT. OF

7908090426 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090432 QA program approval for radioactive matl package 0276, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0279 UNIVERSAL TESTING, INC.

7908020095 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

--7908020098 QA program approval for radioactive matl package 0279, Revision 0.
MACDONALD, C. E. Transportation Branch 79/06/29 1p.

DOCKET 71-0280 ABCO PERFORATORS, INC.

7908090329 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090339 QA program approval for radioactive matl package 0280, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0282 WKM WELLHEAD SYSTEMS, INC.

7908090343 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090347 QA program approval for radio- tive matl package 0282, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0285 BELL GEOPHYSICS

7908090349 Forwards QA program approval for radioacitve matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090351 QA program approval for radioactive matl package 0285, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0286 BPB INSTRUMENTS, INC.

7908090411 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908090414 QA program approval for radioactive matl package 0286, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0287 CARSON NON-DESTRUCTIVE TESTING

7908100136 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

--7908100142 QA program approval for radioactive matl package 287.
MACDONALD, C. E. Transportation Branch 79/08/03 1p.

DOCKET 71-0288 NORTH DAKOTA STATE WATER COMMISSION

7908030200 Submits QA program organization chart, per NRC 790413 ltr.
MCVAUGH, R. W. Carson Heliocopter, Inc., Non Destructive Testing Div. 79/07/02 2pp.

7908170242 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908170244 QA program approval for radioactive matl package 0288, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0289 TERRADATA GEOPHYSICAL, INC.

7908170231 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908170233 QA program approval for radioactive matl package 0289, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0290 UNITED TESTING SERVICES, INC.

7908170257 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908170262 QA program approval for radioactive matl package 0290, Revision 0.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

DOCKET 71-0291 DJ INSPECTION SERVICES, INC.

7908160562 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch 79/07/19 1p.

--7908160564 QA program approval for radioactive matl package 0291, Revision 0.
MACDONALD, C. E. Tra- portation Branch 79/07/19 1p.

DOCKET 71-0293 BRAND X PERFORATORS, INC

7908280475 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908280481 QA program approval for radioactive matl package 0293, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0295 ACUREX CORP

7908160546 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160550 QA program approval for radioactive matl package 0295, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0297 E. LEWIS COOK & ASSOCIATES

7908160503 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160509 QA program approval for radioactive matl package 0297, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0299 QUALITY CONTROL SERVICES, INC

7908160554 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160559 QA program approval for radioactive matl package 0299, Revision 0.
MACDONALD, D. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0300 INDEPENDENT TESTING LABORATORIES

7908290336 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/20. 1p.

--7908290341 QA program approval for radioactive matl package 0300, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/20. 1p.

DOCKET 71-0301 CTL ENGINEERING, INC

7908160513 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160519 QA program approval for radioactive matl package 0301, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0302 JOHNSON CONTROLS

7908090274 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/06/20. 1p.

--7908090280 QA program approval for radioactive matl package 0302, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/06/20. 1p.

DOCKET 71-0303 MEMPHIS TESTING SERVICES, INC

7908170288 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908170290 QA program approval for radioactive matl package 0303, Revisions 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0309 WORTHINGTON PUMP CORP. (USA)

7908160572 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160574 QA program approval for radioactive matl package 0309, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 7 0311 LOGWELL, INC

7908160499 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160505 QA program approval for radioactive matl package 0311, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1pp.

DOCKET 71-0312 METALFORMS, INC

7908160525 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160528 QA program approval for radioactive matl package 0312, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0313 PRECISION INSPECTION, LTD

7908160517 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160522 QA program approval for radioactive matl package 0313, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0315 RADIOGRAPHY INSPECTION, INC

7908160510 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160515 QA program approval for radioactive matl package 0315, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0317 HUDSON PRODUCTS CORP

7908160524 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

--7908160527 QA program approval for radioactive matl package 0317, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/07/19. 1p.

DOCKET 71-0318 MARATHON OIL CO

7908160567 Forwards revised organization chart re QA program.Radiation safety officer & radiation protection officer are identical positions.
BARRE, C. H. Marathon Oil Co. 79/07/10. 1p.

7908090679 Forwards QA program approval for radioactive matl package.
MACDONALD, C. E. Transportation Branch. 79/08/03. 1p.

--7908090682 QA program approval for radioactive matl package 0318, Revision 0.
MACDONALD, C. E. Transportation Branch. 79/08/03. 1p.

DOCKET 71-0321 EXAM CO

7908220544 Submits QA program organization chart in response to NRC 790705 ltr.
MOBLEY, J. D. Exam Co. 79/08/06. 2pp.

DOCKET 71-0329 HOWMET TURBINE COMPONENTS CORP

7908240531 Forwards QA program.
BRANDSTETTER, C. Howmet Turbine Components Corp. (Subs. Pechiney Ugine Kuhlmann). 79/06/08. 1p.

--7908240534 QA program
BRANDSTETTER,C. Howmet Turbine Components Corp. (Subs Pechiney Ugine Kuhlmann). 78/06/08 9pp.

7908280366 Forwards QA program approval for radioactive matl package
MACDONALD,C.E. Transportation Branch. 79/06/29 1p.

--7908280369 QA program approval for radioactive matl package 0329, Revision 0.
MACDONALD,C.E. Transportation Branch. 79/06/29 1p.

DOCKET 71-0330 ALLIED INSPECTION SERVICES INC.

7908280487 Forwards QA program of Allied Insp Svc,Inc implemented for License 21-18428-01.
GRASHAW,T.D. Allied Inspection Services, Inc. 79/06/15 1p.

--7908280492 QA program of Allied Insp Svc,Inc.
GRASHAW,T.D. Allied Inspection Services, Inc. 79/06/15 1p.

7908280375 Forwards QA program approval for radioactive matl package
MACDONALD,C.E. Transportation Branch. 79/06/29 1p.

--7908280380 QA program approval for radioactive matl package 0330, Revision 0.
MACDONALD,C.E. Transportation Branch. 79/06/29 1p.

DOCKET 71-0331 NORTH CAROLINA STATE UNIVERSITY AT RALEIGH

7908280390 Forwards QA procedure for shipment of R-63 reactor fuel to DOE Savannah River operations,Aiken,SC Forwards 790613 ltr requesting registration as user of BMI-1 cask.
ELLEMAN,T.S. North Carolina State Univ 79/06/13 1p.

--7908280396 Requests that NC State Univ nuclear operations administrator,JR Bohannon,be listed as user of BMI-1 cask.
ELLEMAN,T.S. North Carolina State Univ. 79/06/13 1p.

--7908280403 QA procedure re shipment of R-63 reactor fuel elements to DOE in Aiken,SC.
* North Carolina State Univ 79/06/13 6pp.

DOCKET 71-0332 FLORIDA POWER CORP

7908280754 Discusses util application of portions of QA program to transport radioactive packages.
STEWART,W.P. Florida Power Corp. 79/06/15 2pp.

7908280354 Forwards QA program approval for radioactive matl package.
MACDONALD,C.E. Transportation Branch. 79/06/29 1p.

--7908280360 QA program approval for radioactive matl package 0332, Revision 0.
MACDONALD,C.E. Transportation Branch. 79/06/29 1p.

DOCKET 71-0333 ALABAMA POWER CO

7908280785 Notifies of application of QA program to radwaste transportation activities per 10CFR71.51.Util has delegated development of QA program re radwaste shipment activities performed by contractor Chem Nuclear Inc.
CLAYTON,F.L. Alabama Power Co. 79/06/22 1p.

7908280780 Submits info in response to 790705 ltr.Util QA program is located in Section 17.2 of FSAR & applied to radioactive waste transportation activities in accordance w/10CFR71.51.
CLAYTON,F.L. Alabama Power Co. 79/07/16 1p.

7908280435 Forwards QA program approval for radioactive matl package.
MACDONALD,C.E. Transportation Branch. 79/07/31 1p.

--7908280438 QA program approval for radioactive matl package 0333, Revision 0.
MACDONALD,C.E. Transportation Branch. 79/07/31 1p.

DOCKET 71-0335 CITY OF BURLINGTON

7908280455 Forwards QA program for City of Burlington,NC.
HOPE,F.F. North Carolina, State of. 79/03/16 1p.

--7908280460 QA program for City of Burlington,NC.
HOPE,F.F. North Carolina, State of. 79/03/16 2pp.

7908280241 Responds to 790316 application re approval of QA program per 10CFR71.51.Licensee must submit organization chart identified in Section 1 of QA program.
MACDONALD,C.E. Transportation Branch. 79/07/27 1p.

DOCKET 71-0336 CLEVELAND X-RAY INSPECTION

7908240045 Forwards QA program for License 35-15205-01.
CURTIS,F.D. Cleveland X-Ray Inspection, Inc. 79/07/02 1p.

--7908240048 QA program for License 35-15205-01.
CURTIS,F.D. Cleveland X-Ray Inspection, Inc. 79/07/02 7pp.

7908280315 Forwards QA program approval for radioactive matl package.
MACDONALD,C.E. Transportation Branch. 79/08/03 1p.

--7908280320 QA program approval for radioactive matl package 0336, Revision 0.
MACDONALD,C.E. Transportation Branch. 79/08/03 1p.

DOCKET 71-0337 CALUMET TESTING SVC, INC

7908280227 Forwards QA program re shipping of radioisotopes for License 13-16347-01.
VIDUKA,R.V. Calumet Testing Services, Inc. 79/06/08 1p.

--7908280230 QA program re shipping of radioisotopes for License 13-16347-01.
VIDUKA,R.V. Calumet Testing Services, Inc. 79/06/08 3pp.

DOCKET 71-0338 METILS, INC.

7908240051 Forwards QA program re shipping radioisotopes for License 42-16534-01 per 10CFR71.
WALL,L. Metils, Inc. 79/07/16 1p.

--7908240055 QA program re shipping radioisotopes under License 42-16534-01.
WALL,L. Metils, Inc. 79/07/16 3pp.

7908280323 Forwards QA program approval for radioactive matl package.
MACDONALD,C.E. Transportation Branch. 79/08/03 1p.

--7908280349 QA program approval for radioactive matl package 0338, Revision 0.
MACDONALD,C.E. ansportation Branch. 79/08/03 1p.

DOCKET 71-0340 PUBLIC SERVICE CO. OF COLORADO

7908240204 Notification of registration as user of Model FSV-1 in response to 790627 request.
MACDONALD,C.E. Transportation Branch. 79/07/24 1p.

DOCKET 71-0341 ARKANSAS POWER & LIGHT CO.

7908240197 Notification of registration as user of Model CNSI-21-300 in response to 790711 request.
MACDONALD,C.E. Transportation Branch. 79/07/24 1p.

DOCKET 71-0342 WISCONSIN INDUSTRIAL TESTING, INC.

7908240483 Forwards QA program.
COMBS,R. Wisconsin Industrial Testing, Inc. 79/07/12 1p.

--7908240484 QA program.
COMBS,R. Wisconsin Industrial Testing, Inc. 79/07/12 3pp.

DOCKET 71-0345 CAROLINA POWER & LIGHT CO.

7908240478 Discusses intention to apply approved QA program to use of radioactive matl packages.
UTLEY,E.E. Carolina Power & Light Co. 79/07/30 3pp.

DOCKET 71-4986 MODEL RA-2, EXXON NUCLEAR CO., INC.

7908170323 Responds to GE 790709 application requesting type B(U) certification for RA series packages. RA series authorized by Certificate of Compliance 4986 & meets IAEA requirements for B(U) packages.
MACDONALD, C.E. Transportation Branch 79/07/31 1p.

DOCKET 71-5026 MODEL BC-48-220, ATCOR, INC.

7908020510 Requests registration as user of Model BC-48-220.
BAYNARD, P.Y. Florida Power Corp. 79/06/15 1p.

7908100574 Requests registration as user of Model BC-48-220.
ANDOGNINI, G.C. Boston Edison Co. 79/07/05 1p.

7908080555 Notification of registration as user of Model BC-48-220 in response to 790614 request.
MACDONALD, C.E. Transportation Branch 79/07/19 1p.

7908300401 Requests registration as user of Model CNSI BC-48-220.
MAIER, J.B. Allied General Nuclear Services 79/08/03 1p.

DOCKET 71-5149 MODEL B14A, BABCOCK & WILCOX CO.

7908070334 Notifies of expiration of Certificate of Compliance 5149 for Model B14A. To continue using package, should submit consolidated application for renewal.
MACDONALD, C.E. Transportation Branch 79/06/18 1p.

7908100538 Requests that Pittsburgh Naval Reactors Ofc & Bettis Atomic Power Lab continue to be registered as users of certificates of compliance per 49CFR173.393. B&W will submit request for certificate renewal prior to expiration date.
ODDIS, C.E. Energy, Dept. of 79/06/29 1p.

DOCKET 71-5274 MODEL UNC-1634, UNITED NUCLEAR CORP.

79082 .360 Requests registration as user of Model UNC-1634.
CUNNINGHAM, G.E. General Electric Co., Nuclear Energy Products Div. 79/08/02 1p.

DOCKET 71-5331 MODEL BP-2, GENERAL ELECTRIC CO.

7906280782 Requests registration as user of Model BP-2.
KAPLAN, A.L. General Electric Co., Nuclear Energy Products Div. 79/06/19 1P.

7908280345 Forwards Revision 2 to Certificate of Compliance 5331 for shipping package Model BP-2.
MACDONALD, C.E. Transportation Branch 79/07/12 1p.

--7908280351 Certificate of Compliance 5331, Revision 2, for radioactive matl shipping package Model BP-2.
MACDONALD, C.E. Transportation Branch 79/07/12 2pp.

DOCKET 71-5364 MODEL NPI-67-0442 NEUTRON PRODUCTS, INC.

7908010623 Application for renewal of Certificate of Compliance 5364 for Model NPI-67-0442.
KREYSA, F.J. Neutron Products, Inc. 79/04/19 1p.

DOCKET 71-5450 MODEL RCC-1,-2,-3, WESTINGHOUSE ELECTRIC CORP.

7908140594 Submits addl info to support application for revision of Certificate of Compliance 5450. Info describes differences between RCC-4 containers & previously licensed RCC-type containers.
DIPIAZZA, R.P. Westinghouse Electric Corp. 79/07/27 2pp.

DOCKET 71-5563 MODEL 660C, BABCOCK & WILCOX CO.

7908020557 Notifies of expiration of Certificate of Compliance 5563 for Models 660B & 660C. To continue using package, should request renewal.
MACDONALD, C.E. Transportation Branch 79/06/18 1p.

DOCKET 71-5597 MODEL TUNGSTEN SHIELDED CASK, ENERGY, DEPT OF

7908030041 Submits Suppl 1 to 781229 "Structural Review of ORNL Tungsten-Shielded Cask." Forwards addl versions of initial structural review, concerns of project manager & commentaries.
CLARY, R. Transportation Branch 79/04/13 12pp.

--7908030049 "Results of Initial Structural Review of ORNL Tungsten-Shielded Cask, Version B."
CLARY, R. Transportation Branch 79/04/13. 33pp.

--7908030054 "Results of Initial Structural Review of ORNL Tungsten-Shielded Cask, Version C."
CLARY, R. Transportation Branch 79/04/13. 33pp.

--7908030057 "Recommendations on Concerns Expressed by Project Manager."
CLARY, R. Transportation Branch 79/04/13. 19pp.

--7908030061 "Commentary on Interpretation & Application of Technical Ref."
CLARY, R. Transportation Branch 79/04/13. 21pp.

--7908030064 "Commentary on Applicability of Staff Expressions Described as Differing Views W/Recommendations."
CLARY, R. Transportation Branch 79/04/13. 275pp.

--7908030070 Comments on results of initial structural review for ORNL tungsten-shielded Cask. Review is incomplete & unacceptable.
MACDONALD, C.E. Transportation Branch 79/01/30. 2pp.

--7908030079 Notifies of completion of initial review of ORNL tungsten-shielded casks. Forwards request for addl info & summary of initial structural review performed.
CLARY, R. Transportation Branch 78/12/29. 16pp.

--7908030083 Requests confirmation of NRC regulatory positions & policies re licensing actions. Some practices cause inefficiency & ineffectiveness & are not relevant to public safety.
CLARY, R. Transportation Branch 77/11/04. 15pp.

DOCKET 71-5754 MODEL RMG-172, NUCLEAR FUEL SERVICES, INC.

7908220224 Requests registration as user of Model RMG-172. Forwards fee for Category 11C renewal.
MICHEL, C.J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/07/06 1p.

DOCKET 71-5768 MODEL BB-250-2, COMBUSTION ENGINEERING CO., INC.

7908310008 Requests renewal of registration as user of Models BB-250-2 & CE-250-2.
NECHODOM, W.S. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 79/07/27 1p.

7908290538 Requests registration as user of Model BB-250-2.
ZEFF, D.W. Babcock & Wilcox Co. 79/07/30 1p.

DOCKET 71-5796 MODEL 181361, PICKER CORPORATION

7908280765 Requests amend to Certificate of Compliance 5796, adding Cs-137 as alternate radioactive source.
PENGOV, C.A. Picker Corp. 79/05/29 2pp.

7908280829 Requests Drawing 13709A for Cs-137 source holder, to complete review of 790529 application requesting amend to Model 181361 packaging.
MACDONALD, C.E. Transportation Branch 79/08/09 1p.

DOCKET 71-5901 MODEL NFS 100, NUCLEAR FUEL SERVICES, INC.

7908300406 Requests renewal of registration as user of Models LL-50-100, 6144 & NFS 100.
BIXEL, D.A. Consumers Power Co. 79/07/30 1p.

DOCKET 71-5910 MODEL NNFD-6A-2, BABCOCK & WILCOX CO.

7908100538 Requests that Pittsburgh Naval Reactors Ofc & Bettis Atomic Power Lab continue to be registered as users of certificates of compliance per 49CFR173.393. B&W will submit request for certificate renewal prior to expiration date.
ODDIS, C.E. Energy, Dept. of 79/06/29 1p.

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO.

7908030525 Discusses Revision 2 to Certificate of Compliance 5926. Ofc of Controller notified to refund amend fee overpayment of $1,128.
MILLER, W. O. License Fee Management Branch 79/06/25 1p.

DOCKET 71-5950 MODEL BCL-4, BATTELLE COLUMBUS LABS

7908280751 Requests registration as user of Model BCL-4.
OLSEN, A. F. Babcock & Wilcox Co. 79/05/30. 1p.

7908280064 Notification of registration as user of Model BCL-4 in response to request.
MACDONALD, C. E. Transportation Branch 79/07/30. 1p.

DOCKET 71-5957 MODEL BMI-1, ENERGY, DEPT OF

7908090393 Requests listing as user of BMI-1 cask. QA program will be forwarded.
ELLEMAN, T. S. North Carolina State Univ. 79/06/13. 1p.

7908290433 Notification of registration as user of Model BMI-1 in response to request.
MACDONALD, C. E. Transportation Branch 79/07/30. 1p.

DOCKET 71-5971 MODEL GE-200 GENERAL ELECTRIC CO.

7908280832 Requests registration as user of Model GE-200 shipping cask.
ROSS, D. M. Energy, Dept. of. 79/06/25. 1p.

7908280744 Notification of registration as user of Model GE-200.
MCDONALD, C. E. Transportation Branch 79/08/01. 1p.

DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO.

7908140309 Notifies of intention to ship radioactive matl model GE-600.
MAYER, L. D. Northern States Power Co. 79/07/05. 1p.

DOCKET 71-6058 MODEL B3-1, NUCLEAR ENGINEERING CO.

7908280757 Requests registration as user of Model B3-1.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/20. 1p.

7908010718 Requests registration as user of Models LL-50-100, PB-1, B3-1, LL-28-4, BC-48-220 & 6144.
PROFFITT, W. L. Virginia Electric & Power Co. 79/06/27. 1p.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19. 2pp.

7908200202 Requests registration as user of Model B-31. Certificate of Compliance 6058.
KWIRANT, E. M. Argonne National Laboratory 79/07/24. 1p.

7908300389 Requests registration as user of Models B3-1, 6144, Poly Panther, Super Tiger & 1/2 Super Tiger.
BAER, T. S. Nuclear Engineering Co. 79/08/02. 2pp.

DOCKET 71-6144 MODEL 6144, NUCLEAR ENGINEERING CO.

7908020170 Requests registration as user of Model 6144.
BAYNARD, P. Y. Florida Power Corp. 79/06/26. 1p.

7908020189 Requests registration as user of Model 6144 B.
WISLA, S. F. Consolidated Edison Co. of New York. 79/06/26. 1p.

7908060516 Requests registration as user of Model 6144.
MAYER, L. D. Northern States Power Co. 79/06/25. 1p.

7908020179 Requests registration as user of Models NECO B-2 & CNS 15-1608.
EMSWILER, T. R. Battelle Memorial Institute, Columbus Laboratories. 79/06/27. 1p.

7908020211 Requests registration as user of Model 6144.
LEWIS, L. Duke Power Co. 79/06/28. 1p.

7908020221 Requests registration as user of Model 6144.
REMLEY, M. E. Rockwell International Corp. 79/06/28. 1p.

7908020117 Requests registration as user of Model 6144.
CORBETT, J. S. Chem-Nuclear Systems, Inc. 79/06/29. 1p.

7908100335 Requests registration as user of Model CNSI 6144 radioactive matls shipping cask.
TURKANIS, M. M. Neutron Products, Inc. 79/07/10. 1p.

7908100561 Requests registration as user of Model CNSI 15-1608.
OLSEN, A. F. Babcock & Wilcox Co. 79/07/10. 1p.

7908170538 Requests registration as user of Model 6144.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/16. 1p.

7908290443 Notification of registration as user of Model 6144 in response to request.
MACDONALD, C. E. Transportation Branch 79/07/30. 1p.

7908310013 Requests renewal of registration as user of Models LL-50-100, 6144 & NFS 100.
BIXEL, D. A. Consumers Power Co. 79/07/30. 1p.

7908300368 Requests registration as user of Models B3-1, 6144, Poly Panther, Super Tiger & 1/2 Super Tiger.
BAER, T. S. Nuclear Engineering Co. 79/08/02. 2pp.

DOCKET 71-6172 MODEL 961A, BABCOCK & WILCOX CO.

7908100593 Requests that Bettis Atomic Power Lab & Pittsburgh Naval Reactors Ofc be registered as users of Certificate of Compliance 6172.
DDDIS, C. E. Energy, Dept. of. 79/06/22. 1p.

DOCKET 71-6244 MODEL: 6244, CHEM-NUCLEAR SYSTEMS, INC.

7908170605 Forwards Revision 3 to Certificate of Compliance 6244 for shipping package Model 6244.
MACDONALD, C. E. Transportation Branch 79/07/30. 2pp.

--7908170613 Certificate of Compliance 6244, Revision 3 for radioactive matl shipping package Model 6244.
MACDONALD, C. E. Transportation Branch 79/07/30. 3pp.

DOCKET 71-6272 MODEL: POLY PANTHER, TELEDYNE ENERGY SYSTEMS

7908150048 Requests registration as user of Model Poly Panther.
DIPIAZZA, R. P. Westinghouse Electric Corp. 79/07/03. 1p.

7908160571 Requests registration as user of Model 6272.
DIPIAZZA, R. P. Westinghouse Electric Corp. 79/07/03. 1p.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19. 2pp.

7908300376 Requests registration as user of Models B3-1, 6144, Poly Panther, Super Tiger & 1/2 Super Tiger.
BAER, T. S. Nuclear Engineering Co. 79/08/02. 2pp.

DOCKET 71-6291 MODEL: 400

7908090256 Requests extension of Certificate of Compliance 6291 for pacemaker Model 400.
WORZEWSKI, W. Biotronic Sales, Inc. 79/06/25. 1p.

DOCKET 71-6346 MODEL: FSV-1, GENERAL ATOMIC CO.

7908210050 Requests registration as user of Model FSV-1.
FULLER, J. K. Public Service Co. of Colorado. 79/06/27. 2pp.

7908240204 Notification of registration as user of Model FSV-1 in response to 790627 request.
MACDONALD, C. E. Transportation Branch. 79/07/24. 1p.

DOCKET 71-6357 MODEL NNFD-10. BABCOCK & WILCOX

7908100538 Requests that Pittsburgh Naval Reactors Ofc & Bettis Atomic Power Lab continue to be registered as users of certificates of compliance per 49CFR173.393. B&W will submit request for certificate renewal prior to expiration date.
GDDIS, C. E. Energy, Dept. of. 79/06/29. 1p.

7908020229 Requests registration as user of Model NNFD-10.
KIRK, W. F. United Nuclear Corp. 79/07/02. 1p.

7908150551 Requests registration as user of Model NNFD-10.
EMSWILER, T. B. Battelle Memorial Institute, Columbus Laboratories. 79/07/17. 1p.

DOCKET 71-6375 MODEL PB-1. CHEM-NUCLEAR SYSTEMS, INC

7908150335 Intends to ship radioactive matl from facilities using package PB-1.
MAYER, L. O. Northern States Power Co. 79/06/08. 1p.

7908030020 Requests continued use of Model PB-1 cask in response to NRC 790517 ltr.
FOX, H. S. Tennessee Valley Authority. 79/06/19. 1p.

7908010718 Requests registration as user of Models LL-50-100, PB-1, B3-1, LL-28-4, BC-48-220 & 6144.
PROFFITT, W. L. Virginia Electr. & Power Co. 79/06/27. 1p.

7908100128 Requests registration as user of Model PB-1.
ANDOGNINI, G. C. Boston Edison Co. 79/07/05. 1p.

DOCKET 71-6387 MODEL 60. BATTELLE MEMORIAL INSTITUTE

7908200085 Requests lab be registered as shipper for container.
RAMSEY, J. Los Alamos Scientific Laboratory. 79/07/30. 1p.

DOCKET 71-6400 MODEL SUPER TIGER. WESTINGHOUSE ELECTRIC CORP

7908090493 Application for administrative amend to Certificate of Compliance 6400. Requests change to rigid 30-gallon fiber drum w/interior impregnated w/polyethylene to prevent corrosion. License limits & requirements encl.
DIPIAZZA, R. P. Westinghouse Electric Corp. 79/06/07. 3pp.

7908280446 Forwards Revision 6 of Certificate of Compliance 6400 for shipping package Model Super Tiger.
* Transportation Branch. 79/06/26. 3pp.

--7908280450 Certificate of Compliance 6400, Revision 6 for radioactive matl shipping package Model Super Tiger.
MACDONALD, C. E. Transportation Branch. 79/06/26. 5pp.

7908020040 Forwards Revision 7 to Certificate of Compliance 6400 for shipping package Model Super Tiger.
MACDONALD, C. E. Transportation Branch. 79/07/12. 3pp.

--7908020045 Certificate of Compliance 6400, Revision 7, for radioactive matl shipping package Model Super Tiger.
MACDONALD, C. E. Transportation Branch. 79/07/12. 6pp.

--7908020046 Forwards SAR for Pu packaging requested in NRC 790530 ltr.
MICHEL, C. J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 79/07/06. 1p.

--7908020049 SAR for Pu packaging.
* Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 79/07/06. 2pp.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch. 79/07/19. 2pp.

7908300383 Requests registration as user of Models B3-1, 6144, Poly Panther, Super Tiger & 1/2 Super Tiger.
BAER, T. S. Nuclear Engineering Co. 79/08/02. 2pp.

DOCKET 71-6478 MODEL 4T. ENERGY, DEPT. OF

7908280749 Requests registration as user of Model 4T neutron source cask.
HALSTED, C. G. Energy, Dept. of, Savannah River Operations. 79/06/07. 1p.

7908240023 Notification of registration as user of Model 4T, Certificate of Compliance 6478.
MCDONALD, C. E. Transportation Branch. 79/08/01. 1p.

DOCKET 71-6568 MODEL LL-60-150. TVA

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch. 79/07/19. 2pp.

DOCKET 71-6574 MODEL HN-200. HITTMAN NUCLEAR & DEVELOPMENT CORP

7908020166 Requests registration as user of Model HN-200.
WISLA, S. F. Consolidated Edison Co. of New York. 79/06/25. 1p.

7908090484 Requests revision to Certificate of Compliance 6574 to permit use of disposable inner containers other than HN-200-LC.
TRIGILIO, G. Hittman Nuclear & Development Corp. (subs. of Hittman Corp.). 79/07/02. 1p.

7908020108 Requests registration as user of Model HN-200.
MOOD, D. E. Yankee Atomic Electric Co. 79/07/03. 1p.

7908210027 Requests registration as user of Model HN-200 Series 1 radioactive matls shipping cask.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/07/05. 1p.

7908310147 Requests registration as user of Model HN-200.
DOLAN, J. E. Indiana & Michigan Power Co. 79/07/09. 2pp.

7908030441 Forwards Revision 2 to Certificate of Compliance 6574, Revision 2, for shipping package Model HN-200.
MACDONALD, C. E. Transportation Branch. 79/07/10. 2pp.

--7908030446 Certificate of Compliance 6574, Revision 2, for radioactive matl shipping package Model HN-200.
MACDONALD, C. E. Transportatinn Branch. 79/07/10. 3pp.

7908150542 Requests registration as user of Model HN-200.
TRIMBLE, D. C. Arkansas Powe- & Light Co. 79/07/17. 1p.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch. 79/07/19. 2pp.

7908290448 Notification of registration as user of Model HN-200 in response to request.
MACDONALD, C. E. Transportation Branch. 79/07/30. 1p.

DOCKET 71-6581 MODEL 51032-1 & 1A. EXXON NUCLEAR CO., INC

7908230089 Forwards Revision 10 to Certificate of Compliance 6581 for shipping package Models 51032-1 & 51032-1A.
MACDONALD, C. E. Transportation Branch. 79/08/13. 1p.

--7908230090 Certificate of Compliance 6581, Revision 10, for radioactive matl shipping Models 51032-1 & 51032-1A.
MACDONALD, C. E. Transportation Branch. 79/08/13. 6pp.

DOCKET 71-6601 MODEL LL-50-100. CHEM-NUCLEAR SYSTEMS, INC

7908010612 Responds to 790517 ltr. Consolidated application for renewal of Certificate of Compliance 6601 is being prepared. Application will include Drawing 1042-D-0021.
REYNOLDS, L. E. Chem-Nuclear Systems, Inc. 79/06/07. 1p.

7908130049 Forwards oversized drawings 1042-D-001, Revision B & 1042-C-0002, Revision D. Drawings omitted from 790124 submittal.
REYNOLDS, L. E. Chem-Nuclear Systems, Inc. 79/06/15. 3pp.

7908010696 Requests registration as user of Model LL-50-100.
LINDER, F. Dairyland Power Cooperative. 79/06/27. 2pp.

7908010718 Requests registration as user of Models LL-50-100, PB-1, B3-1, LL-28-4, BC-48-220 & 6144.
PROFFITT, W. L. Virginia Electric & Power Co. 79/06/27. 1p.

7908010674 Requests registration as user of Model LL-50-100.
OPEKA, J. F. Northeast Utilities. 79/07/02. 1p.

7908100565 Requests registration as user of Model LL-50-100.
ANDOGNINI, G. C. Boston Edison Co. 79/07/05. 1p.

7908100570 Requests registration as user of Model CNSI LL-50-100.
CLARK, L. Massachusetts Institute of Technology. 79/07/09. 1p.

7908150547 Requests registration as user of Model LL-50-100.
FAY, C. W. Wisconsin Electric Power Co. 79/07/16. 1p.

7908150663 Requests all drawings for Model LL-50-100 packaging, delineating changes & discussing safety significance re request for amend.
MACDONALD, C. E. Transportation Branch. 79/07/23. 1p.

7908290460 Notification of registration as user of Model LL-50-100 in response to request.
MACDONALD, C. E. Transportation Branch. 79/07/30. 1p.

7908290607 Requests registration as user of Model LL-50-100 package.
CORBETT, J. S. Chem-Nuclear Systems, Inc. 79/07/30. 1p.

7908310012 Requests renewal of registration as user of Models LL-50-100, 6144 & NFS 100.
BIXEL, D. A. Consumers Power Co. 79/07/30. 1p.

DOCKET 71-6639 MODEL: MH-1A, ARMY, DEPT OF

7908020126 Requests cancellation of License 51-127-58-3 issued to Dept of Army. Cask has been transferred to DOE.
TARAS, D. W. Army, Dept. of. 79/05/17. 1p.

DOCKET 71-6679 MODEL: 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, DH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch. 79/07/19. 2pp.

7908300395 Requests renewal of registration as user of Models B3-1, 6144, Poly Panther, Super Tiger & 1/2 Super Tiger.
BAER, T. S. Nuclear Engineering Co. 79/08/02. 2pp.

DOCKET 71-6697 MODEL: 8500 PKG, GENERAL ELECTRIC CO.

7908150496 Requests registration as user of Model QE-8500.
GUNN, S. L. Missouri, Univ. of, Columbia. 79/07/18. 1p.

DOCKET 71-6698 MODEL: NFS-4, NUCLEAR FUEL SERVICES, INC.

7908070115 Forwards draft IE Insp Rept 71-6698/79-01 on 790419-20, documenting insp activity, per Shiezek 790503 request.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/18. 1p.

--7908070120 Draft IE Insp Rept 71-6698/79-01 on 790419-20. No noncompliance noted. Major areas inspected: spent fuel casks & dimensional examination per order to suspend use of casks under Certificate of Compliance 6698.
MCNEILL, W. M., WHITESELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 79/05/18. 8pp.

7908100577 Discusses IE Insp Rept 71-6698/79-01 on 790419-20. No noncompliance noted.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/16. 2pp.

7908200088 Requests that Certificate of Compliance 6698 be changed to ref Revision 18 of NFS Drawing E10080 which incorporates changes in dimensions, tolerances & notations resulting from drawing reviews. Forwards drawings.
ROLLINS, J. D. Nuclear Assurance Corp. 79/07/26. 4pp.

--7908200092 "NFS-4 Spent Fuel Shipping Cask," sheets 1-4.
* Nuclear Assurance Corp. 79/07/26. 4pp.

DOCKET 71-6717 MODEL: 6717 B

7908230225 Requests registration as user of Model 6717-B.
DALLINGER, J. F. General Dynamics Corp., Electric Boat Div. 79/05/21. 1p.

7908290323 Notification of registration as user of Model 6717-B in response to request.
MACDONALD, C. E. Transportation Branch. 79/07/30. 1p.

DOCKET 71-6722 MODEL: BS-33-180, TENNESSEE VALLEY AUTHORITY

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, DH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch. 79/07/19. 2pp.

7908160112 Notifies of deficiency in shipping container Model 6722/B. Top corner drop analysis of SAR is inadequate. Requests revision of Certificate of Compliance 6722 from Type B to A.
FOX, H. S. Tennessee Valley Authority. 79/07/25. 1p.

7908230032 Forwards Certificate of Compliance 6722, Revisions 3, re Model BS-33-180 shipping package. Certificate of Compliance 6722, Revision 2, dtd 770722, is superseded by present encl.
MCDONALD, C. E. Transportation Branch. 79/08/01. 1p.

--7908230237 Certificate of Compliance 6722, Revision 3, for radioactive matl package Model BS-33-180.
MACDONALD, C. E. Transportation Branch. 79/08/01. 3pp.

DOCKET 71-6744 MODEL: POLY TIGER, NUCLEAR ENGINEERING CO.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, DH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch. 79/07/19. 2pp.

DOCKET 71-9001 MODEL: IF-300, GENERAL ELECTRIC CO.

7908160100 Notifies that util intends to apply accepted 10CFR50, App B, QA program to use of radioactive matl packages. Forwards summary of applicability of portions of App E, 10CFR71.
UTLEY, E. E. Carolina Power & Light Co. 79/07/30. 3pp.

DOCKET 71-9006 MODEL: 500 SU, ARGONNE NATIONAL LABORATORY

7908150524 Requests registration as user of Model 9006.
RAMSEY, J. Los Alamos Scientific Laboratory. 79/07/09. 1p.

DOCKET 71-9007 MODEL: 520, ARGONNE NATIONAL LABORATORY

7908020216 Requests registration as user of Model 520 isotope camera.
GAMBLE, O. C. Nuclear Energy Service, Inc. 79/06/29. 5pp.

7908290440 Notification of registration as user of Model 520 in response to request.
MACDONALD, C. E. Transportation Branch. 79/07/30. 1p.

DOCKET 71-9009 MODEL: FL 10-1, GENERAL ELECTRIC CO.

7908280776 Concludes that GE Model FL 10-1 packaging meets 1973 IAEA requirements.
MACDONALD, C. E. Transportation Branch. 79/06/22. 1p.

7908020113 Requests registration as user of Model FL 10-1.
DIPIAZZA, R. P. Westinghouse Electric Corp. 79/07/03. 1p.

DOCKET 71-9010 MODEL: NLI-1/2, NL INDUSTRIES, INC.

7907260035 Requests registration as user of Model NLI-1/2.
UHRIG, R. E. Florida Power & Light Co. 79/06/11. 1p.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19 2pp.

7908290321 Notification of registration as user of Model NLI-1/2 in response to request.
MACDONALD, C. E. Transportation Branch 79/07/30 1p.

7908290614 Requests registration as user of Model NLI-1/2.
SMITS, C. J. Energy, Dept. of 79/07/31 2pp.

DOCKET 71-9018 MODEL: BU-6, GENERAL ELECTRIC CO.

7908010710 Requests registration as user of Model BU-6.
KAPLAN, A. L. General Electric Co., Nuclear Energy Products Div. 79/06/19 1p.

7908010706 Forwards Revision 2 to Certificate of Compliance 9018 for shipping package Model BU-6.
MACDONALD, C. E. Transportation Branch 79/07/12 1p.

--7908010711 Certificate of Compliance 9018, Revision 2, for radioactive matl shipping package Model BU-6.
MACDONALD, C. E. Transportation Branch 79/07/12 3pp.

DOCKET 71-9019 MODEL: BU-7, GENERAL ELECTRIC CO.

7908200413 Requests registration as user of Model BU-7.
GREGG, R. J. United Nuclear Corp. 79/04/23 1p.

7908020107 Requests registration as user of Model BU-7.
KAPLAN, A. L. General Electric Co., Nuclear Energy Products Div. 79/06/19 1p.

7908330352 Forwards Revision 2 to Certificate of Compliance 9019, Revision 2, for shipping package Model BU-7.
MACDONALD, C. E. Transportation Branch 79/07/12 2pp.

--7908030358 Certificate of Compliance 7919, Revision 2, for radioactive matl shipping package Model BU-7.
MACDONALD, C. E. Transportation Branch 79/07/12 3pp.

7908080429 Notification of registration as user of Model BU-7 in response to request.
MACDONALD, C. E. Transportation Branch 79/07/20 1p.

DOCKET 71-9021 MODEL: 750, TECHNICAL OPERATIONS, INC.

7908280774 Notifies of expiration of Certificates of Compliance 9021 & 9033 for Models 750, 660 & 660E. To continue using package, should submit consolidated application for renewal.
MACDONALD, C. E. Transportation Branch 79/06/06 1p.

DOCKET 71-9022 MODEL: CE-250-2, COMBUSTION ENGINEERING CO., INC.

7908300778 Requests registration as user of Models BB-250-2 & CE-250-2.
NECHODOM, W. S. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 79/07/27 1p.

DOCKET 71-9023 MODEL: NLI-10/24, NL INDUSTRIES, INC.

7908140297 Responds to NRC 790301 ltr re Certificate of Compliance 9023, Revision 0. Forwards revised pages & drawings.
WILLIAMS, C. E. NL Industries, NL Nuclear Div. 79/07/06 67pp.

DOCKET 71-9033 MODEL: 660 & 660E, TECHNICAL OPERATIONS, INC.

7908300431 Requests registration as user of Model 660.
CHATTIN, H. S. Eastern Airlines, Inc. 79/05/10 1p.

7908280774 Notifies of expiration of Certificates of Compliance 9021 & 9033 for Models 750, 660 & 660E. To continue using package, should submit consolidated application for renewal.
MACDONALD, C. E. Transportation Branch 79/06/06 1p.

7908020158 Requests registration as user of Models 660 & 660E.
BUSHKIL, S. Babcock & Wilcox Co. 79/06/25 1p.

7908020182 Requests registration as user of Models 660 & 660E.
REMLEY, M. E. Rockwell International Corp. 79/06/28 1p.

7908020123 Requests registration as user of Models 600 & 660E.
DALEY, R. L. Morrison Knudsen Company, Inc. 79/06/29 1p.

7908200196 Requests registration as user of Models 660 & 660E, Certificate of Compliance 9033.
KWIRANT, E. M. Argonne National Laboratory 79/07/24 1p.

7908160552 Forwards Revision 3 to Certificate of Compliance 9033 for shipping package Model 660 & 660E.
MACDONALD, C. E. Transportation Branch 79/07/25 5pp.

--7908160560 Certificate of Compliance 9033, Revision 3, for radioactive matl shipping package Model 660 & 660E.
MACDONALD, C. E. Transportation Branch 79/07/25 2pp.

7908290552 Requests registration as user of Models 660 & 660E.
WEHRLE, R. R. Chicago Bridge & Iron Co. 79/07/30 1p.

7908290598 Requests registration as user of Models 660 & 660E.
ANDERSON, D. M. Bethlehem Steel Corp. 79/07/31 1p.

7908290611 Requests registration as user of Models 660 & 660E shipping packages.
SOENEN, E. A. Trans World Airlines, Inc. 79/08/02 1p.

7908310009 Requests renewal of registration as user of Models 660 & 660E.
CHIN, S. Lawrence Livermore Laboratory 79/08/02 1p.

7908300412 Requests renewal of registration as user of Model 660.
KOVACS, F. B. Foster Wheeler Corp. 79/08/03 1p.

7908220551 Requests continuation as user of Certificate of Compliance 9033, Revision 3.
MCCORMACK, J. B. Chicago Bridge & Iron Co. 79/08/07 1p.

DOCKET 71-9039 MODEL: 715, TECHNICAL OPERATIONS, INC.

7908100325 Requests registration as user of Model 715.
RIDDLE, D. H. Nuclear Systems, Inc., Gamma Industries, Inc. Div. 79/06/28 1p.

DOCKET 71-9044 MODEL: GE-1600, GENERAL ELECTRIC CO.

7908090701 Notification of registration as user of Model GE-100, in response to request.
MACDONALD, C. E. Transportation Branch 79/07/20 1pp.

DOCKET 71-9070 MODEL: N-55, ENERGY, DEPT. OF

7908020039 Requests registration as user of Model NUPAC N-55 USA DOT Type B Overpack.
KRIEG, D. M. Rockwell International Corp. 79/06/2. 1p.

DOCKET 71-9071 MODEL: AP-101, CHEM-NUCLEAR SYS, INC.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19 2pp.

DOCKET 71-9073 MODEL: OH-142, NUCLEAR PACKAGING, INC.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19 2pp.

DOCKET 71-9074 MODEL: AP-100, ANEFCO, INC.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19 2pp.

DOCKET 71-9079 MODEL: HN-100 SERIES 2. HITTMAN NUCLEAR & DEVELOPMENT

7908280464 Forwards Revision 3 of Certificate of Compliance 9079 for shipping package Model HN-100, Series 2.
MACDONALD, C. E. Transportation Branch 79/06/14 2pp.

--7908280470 Certificate of Compliance 9079, Revision 3, for radioactive matl shipping package Model HN-100, Series 2.
MACDONALD, C. E. Transportation Branch 79/06/14 3pp.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19 2pp.

DOCKET 71-9080 MODEL: HN-600. HITTMAN NUCLEAR & DEVELOPMENT CORP.

7908290454 Notification of registration as user of Model HN-600 in response to request.
MACDONALD, C. E. Transportation Branch 79/07/30 1p.

DOCKET 71-9081 MODEL: CNSI-1600. CHEM-NUCLEAR SYSTEMS, INC.

7908150204 Requests amend to Certificate of Compliance 9081/B, Condition 5(b)(iii), as part of TMI support preparation. Forwards SAR & fee.
CORBETT, J. S. Chem-Nuclear Systems, Inc. 79/07/17 1p.

--7908150209 Ack receipt of 790717 amend request & fee. Requests addl fee.
WEISS, D. License Fee Management Branch 79/07/19 1p.

--7908150215 Responds to 790719 request. Forwards addl amend fee of $2000.
CORBETT, J. S. Chem-Nuclear Systems, Inc. 79/07/24 1p.

--7908150219 SAR, Revision 2, for Model CNSI 1600.
* Chem-Nuclear Systems, Inc. 79/07/09 68pp.

7908140146 Submits corrected page 1-3 of SAR for CNSI 1600 shipping cask.
CORBETT, J. S. Chem-Nuclear Systems, Inc. 79/07/20 2pp.

7908200199 Requests registration as user of Model 1600.
EMSWILER, T. R. Battelle Memorial Institute, Columbus Laboratories. 79/07/23 1p.

DOCKET 71-9086 MODEL: HN-100 SERIES 1. HITTMAN NUCLEAR & DEVELOPMENT

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19 2pp.

DOCKET 71-9089 MODEL: HN-100 S. HITTMAN NUCLEAR & DEVELOPMENT CORP.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19 2pp.

DOCKET 71-9092 MODEL: HN-300. HITTMAN NUCLEAR & DEVELOPMENT CORP.

7908230292 Notification of registration as user of Models B3-1, HN-200, Poly Panther, Super Tiger, LL-60-150, Half Super Tiger, NLI-1/2, BS-33-180, Poly Tiger, AP-101, OH-142, AP-100, HN-100 Series 2, HN-100 Series 1, HN-100s, & HN-300 as requested in 790511 ltr.
MACDONALD, C. E. Transportation Branch 79/07/19 2pp.

DOCKET 71-9094 MODEL: CNSI-14-195-H. CHEM-NUCLEAR SYSTEMS, INC.

7908150520 Requests registration as user of Model CNSI 14-195H.
CRANE, P. A. Pacific Gas & Electric Co. 79/07/18 1p.

7908300399 Requests registration as user of Model CNSI 14-195H.
WANDKE, N. E. Commonwealth Edison Co. 79/08/02 1p.

DOCKET 71-9095 MODEL: CNSI-6-80. CHEM-NUCLEAR SYSTEMS, INC.

7908280762 Denies 770802 application for approval of Model CNSI-6-80 shipping package.
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 79/07/09 1p.

DOCKET 71-9096 MODEL: CNSI-21-300. CHEM-NUCLEAR SYSTEMS, INC.

7908100320 Requests registration as user of Model CNS 21-300 radioactive matl shipping cask.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/11 1p.

7908240197 Notification of registration as user of Model CNSI-21-300 in response to 790711 request.
MACDONALD, C. E. Transportation Branch 79/07/24 1p.

DOCKET 71-9097 MODEL: CNSI-14-195L. CHEM-NUCLEAR SYSTEMS, INC.

7908090294 Forwards answers to 781211 questions re certificate of compliance for Model CNSI-14-195L.
HANSEN, L. J. Nuclear Packaging, Inc. 79/06/21 8pp.

7908150493 Requests registration as user of Model HN-100, Series 2.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/07/17 1p.

DOCKET 71-9104 MODEL: BL-33-90. ATCOR, INC.

7908280870 Denies 780203 application for approval of Model BL-33-90 shipping package.
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 79/07/09 1p.

DOCKET 71-9111 MODEL: CN6-80A. CHEM-NUCLEAR, INC.

7908140475 Requests changes to Certificate of Compliance 9111 & 9113. Changes involve replacement of threaded studs w/bolts. Drawings BC-20-200D & BA-20-200D encl.
CORBETT, J. S. Chem-Nuclear Systems, Inc. 79/06/29 2pp.

7908010680 Requests registration as user of Model CNSI 6-80-2.
KALIVIANAKIS, N. Commonwealth Edison Co. 79/07/03 1p.

7908290318 Notification of registration as user of Model CN6-80A in response to request.
MACDONALD, C. E. Transportation Branch 79/07/30 1p.

7908290628 Forwards Revision 1 to Certificate of Compliance 9111 for shipping package Model CN6-80A.
MACDONALD, C. E. Transportation Branch 79/08/01 2pp.

--7908290634 Certificate of Compliance 9111, Revision 1, for radioactive matl shipping package Model CN6-80A.
MACDONALD, C. E. Transportation Branch 79/08/01 3pp.

DOCKET 71-9112 MODEL: AL-31-120. ATCOR, INC.

7908280843 Denies 780322 application for approval of Model AL-31-120 shipping package.
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 79/07/09 1p.

DOCKET 71-9113 MODEL: 7-100. CHEM-NUCLEAR SYSTEMS, INC.

7908130502 Notifies of intent to ship radioactive matl using certified shipping package Model 7-100.
MAYER, L. O. Northern States Power Co. 79/06/19 1p.

7908140475 Requests changes to Certivicate of Compliance 9111 & 9113. Changes involve replacement of threaded studs w/bolts. Drawings BC-20-200D & BA-20-200D encl.
CORBETT, J. S. Chem-Nuclear Systems, Inc. 79/06/29 2pp.

7908100568 Requests registration as user of Model 7-100.
ANDOGNINI, G. C. Boston Edison Co. 79/07/05 1p.

7908200192 Requests registration as user of Model 9113A radioactive matls shipping cask
KALIVIANAKIS, N. Commonwealth Edison Co. 79/07/05. 1p.

--7908200263 Requests continuation of registraton as user of Model ZN-200, Series 1 radioactive matls shipping cask for License 19-17039-01
KALIVIANAKIS, N. Commonwealth Edison Co. 79/07/05. 1p.

7908290437 Notification of registration as user of Model 7-100 in response to request
MACDONALD, C. E. Transportation Branch. 79/07/30. 1p.

7908270366 Forwards Revision 1 to Certificate of Compliance 9113 for shipping package Model 7-100.
MACDONALD, C. E. Transportation Branch. 79/08/03. 2pp.

--7908270371 Certificate of Compliance 9113, Revision 1, for radioactive matl shipping package Model 7-100.
MACDONALD, C. E. Transportation Branch. 79/08/03. 3pp.

DOCKET 71-9114 MODEL: NP-50CFL, NUCLEAR PACKAGING, INC.

7908080291 Denies 790320 application for approval of Model NP-50CFL shipping package.
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 79/07/25. 1p.

DOCKET 71-9118 MODEL: 4 INCH LEAD, PROTECTIVE PACKAGING, INC.

7908240027 Denies 780322 application to deliver disposable liners & shield packages to carrier, since no response was received to NRC 780907 ltr requesting addl info.
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 79/07/09. 1p.

DOCKET 71-9121 MODEL: 1.25 INCH LEAD, PROTECTIVE PACKAGING, INC.

7908240027 Denies 780322 application to deliver disposable liners & shield packages to carrier, since no response was received to NRC 780907 ltr requesting addl info.
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 79/07/09. 1p.

DOCKET 71-9130 MODEL: NP-50-XXL, NUCLEAR PACKAGING, INC.

7908170174 Forwards request for addl info to complete review of 780811 application for approval to deliver Model NP-50-XXL packaging to carrier for transport.
MCDONALD, C. E. Transportation Branch. 79/07/31. 3pp.

DOCKET 71-9132 MODEL: T-3, NUCLEAR PACKAGING, INC.

7908150732 Forwards request for addl info needed for review of 781020 application requesting approval for T-3 packaging delivery to carrier. Info should be submitted in form of revised pages to original SAR.
MCDONALD, C. E. Transportation Branch. 79/07/25. 3pp.

DOCKET 71-9133 MODEL: C-10, GAMMA INDUSTRIES

7908230560 Forwards application for certificate of compliance authorizing shipment of radioactive matl in Model C-10 Type B shipping containers.
RICHARDSON, H. D. Nuclear Systems, Gamma Industries Div. 79/07/09. 1p.

--7908230564 Application for certificate of compliance authorizing shipment of radioactive matl in shipping container source exchanger Model C-10 Type B shipping containers.
RICHARDSON, H. D. Nuclear Systems, Gamma Industries Div. 79/07/25. 149pp.

DOCKET 71-9134 MODEL: ETR FUEL ELEMENT SHIPPING CONTAINER,

7908280853 Discusses request for approval of ETR fuel element shipping containers. Concludes that ETR fuel element shipping container fulfills safety requirements of ERDA Manual Chapter 0529, 10CFR71 & 49CFR100-199.
WILLIAMS, C. E. Energy, Dept. of. PR-T-79-012. 79/08/08. 24pp.

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

7908010682 Discusses reviews of response to GAO rept on radiological emergencies. Response is vague re requirement of nuclear facilities to provide state & local radiological emergency response plans.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/05/15. 1p.

7907030417 Transcript of 790615 public meeting in Washington, DC on proposed 8-3 rule. Pp 1-26.
HENDRIE, J. M., BRADFORD, P. A., GILINSKY, V. Commission. 79/06/15. 27pp.

--7908030142 Summarizes 790523 opinion by DC Circuit Court in State of MN v NRC & its relation to 8-3 proceeding. Recommends prompt conclusion of proceeding, issuance of final 8-3 rule & statement & appointment of hearing board re waste disposal.
EILPERIN, S. F. Office of the General Counsel. 79/06/11. 13pp.

7908010033 Transcript of 790605 Affirmative Session 76-16 in Washington DC to discuss Secy-A-79-42 re show cause order for License 13-10042-01.
HENDRIE, J. M., GILINSKY, V., BRADFORD, P. A. Commission. 79/06/05. 3pp.

--7908010039 SECY-A-79-042
Seeks approval of memo & order sustaining immediate effectiveness of NRC show cause order per 10CFR2.202 & notice of hearing.
BICKWIT, L. Office of the General Counsel. 79/05/04. 4pp.

--7908010045 Draft notice of hearing re show cause order to terminate License 13-10042-01.
CHILK, S. J. Office of the Secretary of the Commission. 79/04/30. 3pp.

--7908010050 Draft memo & order re Nuclear Engineering Co refusal to maintain & monitor Sheffield site.
CHILK, S. J. Office of the Secretary of the Commission. 79/04/30. 10pp.

--7908010057 SECY-79-351
Seeks approval under Atomic Energy Act of 1954, Section 145B, for members of President's Commission on Accident at TMI to have access to restricted data & natl security info.
BRADY, R. J. Division of Security. 79/05/24. 5pp.

--7908010065 Forwards White House 790412 press release & memo of understanding between OSA & President's Commission on accident at TMI. Requests names of individuals who will require NRC clearance.
CLINKSCALES, W. A. General Services Administration. 79/05/04. 7pp.

7908010611 Transcript of 790615 meeting in Washington, DC. Pp 1-56.
HENDRIE, J. M., BRADFORD, P. A., GILINSKY, V. Commission. 79/06/15. 57pp.

7908010636 Transcript of 790605 public meeting in Washington, DC re hearing board rept in clearance rule proceeding. Pp 1-42.
HENDRIE, J. M., GILINSKY, V., BRADFORD, P. A. Commission. 79/06/05. 43pp.

--7908010640 SECY-79-319
Presents alternatives for Commissioner consideration of clearance rule hearing board rept. Proposed order encl.
BICKWIT, L. Office of the General Counsel. KENNEKE, A. P. Office of Policy Evaluations. 79/05/08. 7pp.

--7908010644 Draft order requesting NRC comments re hearing board 790402 rept. Comments should include legal analysis re DOE SNM access stds & determination of sufficiency of records to support decision.
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission. 79/05/08. 2pp.

7908010658 Transcript of 790607 meeting in Washington, DC re emergency planning. Pp 1-48.
HENDRIE, J. M., GILINSKY, V., BRADFORD, P. A. Commission. 79/06/07. 49pp.

--7908010661 SECY-79-343
Submits to Congress proposed NRC comments re GAO rept on radiological emergencies.
RYAN, R. G. Office of State Programs. 79/05/18. 11pp.

--7908010666 Discusses review of response to GAO rept on radiological emergencies. Concurs w/basic responses. Paper is deficient; fails to provide Commission w/alternative responses.
MINOGUE, R. B. Office of Standards Development. 79/05/15. 1p.

--7908010687 Comments on proposed NRC response to GAO rept on radiological emergencies. Suggests more explicit statement of NRC position on emergency planning.
DEYOUNG, R. C. Division of Site Safety & Environmental Analysis. 79/05/17. 2pp.

--7908010690 Comments on proposed NRC response to GAO rept on radiological emergencies. Concurs on condition that requirement for NRC approval of state & local emergency plans is deleted.
SNIEZEK, J. H. Division of Fuel Facility & Materials Safety. 79/05/11. 1p.

--7908010695 Requests comments on draft memo which would recharter existing NRC Task Force on Emergency Planning w/objective of coordinating activities re emergency planning.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/06/05. 3pp.

--7908010702 Discusses 790425 Commission briefing. Listing of staff action re emergency preparedness encl.
CHILK, S. J. Office of the Secretary of the Commission. 79/04/30. 3pp.

7908030336 Transcript of 790724 public affirmation session 79-21 in Washington, DC. Pp 1-4.
HENDRIE, J. M., KENNEDY, R. T., BRADFORD, P. A. Commission. 79/07/24. 5pp.

7908080150 Transcript of 790712 meeting & affirmation session re SECY-79-347 & Hungerford FOIA appeal, in Washington, DC. Pp 1-3.
HENDRIE, J. M., KENNEDY, R. T., BRADFORD, P. A. Commission. 79/07/12. 3pp.

7908080536 Transcript of 790711 meeting in Washington, DC to discuss responses to IE Bulletin 79-01 & UCS petition on qualification of electrical equipment. Pp 1-58.
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission. 79/07/11. 59pp.

7908080589 Transcript of Affirmation Session 79-18 on 790621 in Washington, DC. Pp 1-8.
HENDRIE, J. M. Commission. 79/06/21. 9pp.

--7908080595 SECY-78-682-A
Discusses revision of NRC regulations governing ownership of stocks, bonds & other security interests by NRC employees. Summary of employee comments encl.
FITZGERALD, J. A. Office of the General Counsel. 79/05/14. 14pp.

--7908080599 Responds to L. Bickwit 790402 memo re proposed mod of regulations which would prohibit NRC employees from owning stocks, bonds & securities in some companies. Will cause problems for ASLB members who own stock in Union Carbide.
YORE, J. R. Atomic Safety and Licensing Board Panel. 79/04/27. 2pp.

--7908080604 Submits recommendations re proposed mod of regulations concerning ownership of securities by NRC employees.
MINOGUE, R. B. Office of Standards Development. 79/04/13. 4pp.

--7908080607 Discusses views of NRC employees re proposed mod to regulations on securities ownership. List of stocks to be prohibited is unreasonable; many companies only minimally involved in nuclear industry.
GODDARD, R. J. Branch 2. 79/04/10. 24pp.

--7908080650 SECY-79-038
Recommends NRC approval of revised proposed amends. re physical protection measures to detect theft of SNM of moderate or low importance, to 10CFR70.73 & 150 for publication in final form.
MINOGUE, R. B. Office of Standards Development. DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/01/16. 76pp.

--7908080657 Draft Reg Guide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance."
* Office of Standards Development. 79/01/16. 37pp.

--7908080662 Value/impact assessment supporting proposed mods to 10CFR70.73 & 150. Mods will further intl safeguard objectives & upgrade domestic safeguards. Public announcement encl.
* Office of Standards Development. 79/01/16. 43pp.

7908090566 Transcript of 790731 Affirmation Session 79-23 in Washington, DC. Pp 1-7.
HENDRIE, J. M.; KENNEDY, R. T.; GILINSKY, V. Commission. 79/07/31. 8pp.

7908090583 Transcript of 790730 public meeting in Washington, DC. Pp 1-103. NRC briefing encl.
HENDRIE, J. M.; AHEARNE, J. F. Commission. 79/07/30. 143pp.

7908090604 Transcript of 790731 public meeting in Washington, DC re Ofc of Nuclear Reactor Regulation budget. Pp 1-133.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commission. 79/07/31. 134pp.

7908090607 Transcript of 790712 meeting in Washington, DC re current & planned enforcement program. Pp 1-83. Viewgraphs encl.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commission. 79/07/12. 129pp.

7908090614 Transcript of 790716 meeting in Washington, DC re authorization bill amends. Pp 1-75.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commission. 79/07/16. 77pp.

--7908090621 Forwards Deconcini amend. to Senate Bill 562 re NRC authorization. Requests informal comment.
* Office of Congressional Affairs. 79/07/26. 10pp.

7908100315 Transcript of ORNL 790524 briefing in Washington, DC re 1958 Soviet nuclear accident. Pp 1-33. Supporting documentation encl.
GILINSKY, V.; KENNEDY, R. T.; BRADFORD, P. A. Commission. 79/05/24. 51pp.

7908100524 Transcript of 790712 public meeting in Washington, DC re licensing schedules. Pp 1-31.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commission. 79/07/12. 37pp.

--7908100527 SECY-79-427
Provides requested data re upcoming power reactor licensing cases.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/05. 3pp.

7908170018 Notice of NRC determination to withhold transcript of 790315 discussion re litigation implications of Commission testimony on recent shutdown orders.
CHILK, S. J. Office of the Secretary of the Commission. 79/07/27. 1p.

7908170020 Notice of NRC determination to withhold tape of 790718 personnel matter discussion.
CHILK, S. J. Office of the Secretary of the Commission. 79/07/19. 1p.

7908170309 Transcript of 790731 public meeting re FY80 budget presentations, in Washington, DC. Pp 1-102.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commission. 79/07/31. 103pp.

7908170503 Transcript of Affirmation Session 79-20 on 790719 in Washington, DC. Pp 1-3.
HENDRIE, J. M.; BRADFORD, P. A.; AHEARNE, J. F. Commission. 79/07/19. 5pp.

--7908170507 SECY-79-443
Recommends Commissioners approve publication in FR of proposed new sys of records, Special Inquiry File NRC-33 & proposed amends of routine uses of records sys.
DONOGHUE, D. J. Office of Administration. 79/07/18. 14pp.

7908170576 Discusses NRC determination re public disclosure of transcript of 790724 discussion of personnel matter. Portions withheld (ref 10CFR9.108). Transcript encl.
CHILK, S. J. Office of the Secretary of the Commission. 79/07/31. 1p.

--7908170587 Transcript of 790724 discussion of personnel matter. Pp 1-35.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commission. 79/07/24. 36pp.

7908170593 Transcript of 790725 public meeting in Washington, DC re annual review of NRC budget. Pp 1-110. Ofc of Stds handouts encl.
HENDRIE, J. M.; KENNEDY, R. T.; BRADFORD, P. A. Commission. 79/07/25. 138pp.

7908170633 Transcript of 790726 public meeting in Washington, DC re annual review of NRC budget. Pp 1-111. IE handouts encl.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commission. 79/07/26. 139pp.

7908210101 Transcript of Commissioners 790724 public meeting in Washington, DC re SECY-79-187A. Pp 1-49.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commissio[illegible] /07/24. 50pp.

--7908210104 SECY-79-187A
SECY-79-187A change to upgrade rule-making "high assurance" requirement an objective.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/07/13. 5pp.

7908210364 Unofficial transcript of 790727 Affirmation Session 79-22.
HENDRIE, J. M.; GILINSKY, V.; KENNEDY, R. T. Commission. 79/07/22. 6pp.

--7908210372 SECY-79-163
Recommends NRC approve petition for rulemaking 10CFR2.802. Notice of rulemaking encl.
DONOGHUE, D. J. Office of Administration. 79/03/07. 84pp.

7908220055 Minutes of closed NRC adjudicatory sessions for 1977.
CHILK, S. J. Office of the Secretary of the Commission. 79/07/19. 55pp.

7908230043 Summary of NRC 790717 meeting in Washington, DC re procedures needed to govern further proceedings in restart of TMI-1.
CHILK, S. J. Office of the Secretary of the Commission. 79/07/20. 2pp.

7908230187 Commission determination to withhold from public disclosure portions of transcript of 790524 discussion City of Lancaster, PA lawsuit.
CHILK, S. J. Office of the Secretary of the Commission. 79/07/13. 1p.

7908230315 NRC determination regarding public disclosure of briefing on SECY-78-35A, NMSS role in intl safeguards & physical security determinations. Submits list of documents withheld.
CHILK, S. J. Office of the Secretary of the Commission. 79/07/05. 2pp.

--7908230417 Transcript of briefing on SECY-78-35A, NMSS role in intl safeguards & physical security determinations.
BROWN, C. H. Office of the Secretary of the Commission. 78/11/21. 54pp.

--7908230424 Responds to 781204 ltr re review of briefing on SECY-78-35A & proposed deletions to allow declassification.
NOSENZO, L. V. State Dept. of. 78/12/18. 4pp.

7908230670 Minutes of closed NRC adjudicatory sessions for 1978.
CHILK, S. J. Office of the Secretary of the Commission. 79/07/19.
6lpp.

7908300086 Notice of NRC determination re public disclosure under Govt in Sunshine Act. Tape of 790717 discussion of personnel matter is proprietary per 10CFR9.108(c) & 10CFR9.104(a)(6).
CHILK, S. J. Office of the Secretary of the Commission. 79/07/18.
1p.

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

7908020162 Transcript of ACRS Subcommittee on Evaluation of LERs 790628 meeting in Washington, DC. Pp 1-200.
* ACRS - Advisory Committee on Reactor Safeguards. 79/06/28. 200pp.

7908030317 Transcript of ACRS Subcommittee on Combination of Dynamic Loads 790711 meeting in Washington, DC. Pp 1-144. S&W presentation encl.
BENDER, M., SHEWMON, P., ETHERINGTON, H. ACRS - Advisory Committee on Reactor Safeguards. 79/07/11. 246pp.

7908030364 Transcript of ACRS Subcommittee on Extreme External Phenomena 790711 meeting in Washington, DC. Pp 1-138. Presentation encl.
OKRENT, D., SHEWMON, P., BENDER, M. ACRS - Advisory Committee on Reactor Safeguards. 79/07/11. 226pp.

7908030382 Transcript of ACRS Subcommittee on Advanced Reactors 790711 meeting in Washington, DC. Pp 1-110. Presentation encl.
KERR, W., MARK, J. C. ACRS - Advisory Committee on Reactor Safeguards. 79/07/11. 124pp.

7908070046 Concurs w/Reg Guide 1.9, Revision 2, as result of 230th ACRS meeting on 790614-16 re selection, design & qualification of diesel generator units used as standby electric power sys at nuclear power plants.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/06/19. 1p.

7908090523 Transcript of 790627 meeting of ACRS Subcommittee on Radiological Effects & Site Evaluation. Pp 1-210. Chapter 8 re radiological effects, from 1978 rept, encl. W/supporting documentation.
MOELLER, D. W., LAWROSKI, S., OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 79/06/27. 345pp.

7908130031 Responds to info request following 790531-0601 subcommittee meeting on TMI-2 incident. Discusses differences between design basis accidents & core melt accidents.
THEOFANOUS, T. G. Purdue Univ. 79/06/08. 3pp.

7908150053 Transcript of 790808 meeting on regulatory activities in Washington, DC. Pp. 1-56.
SIESS, C. P., BENDER, M., ETHERINGTON, H. ACRS - Advisory Committee on Reactor Safeguards. 79/08/08. 56pp.

7908150060 Transcript of Subcommittee on Advanced Reactors 790807 meeting in Washington, DC. Pp 1-257.
KERR, W. ACRS - Advisory Committee on Reactor Safeguards. 79/08/07. 257pp.

7908160370 Questions present balance of responsiveness of research program to regulatory needs & freedom for research office to sponsor own research programs. Recommends re-evaluation of existing internal NRC procedures.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/07/19. 1p.

7908170200 Submits recommendations for improving reactor safety research in DOE & NRC programs reviewed at ACRS 790712-14 meeting. Believes NRC should provide guidance.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/07/18. 5pp.

7908170229 Submits TMI-related comments re natural circulation, steam generator model, pressurizer sizing & operator awareness.
CATTON, I. ACRS - Advisory Committee on Reactor Safeguards. 79/06/14. 4pp.

7908170237 Discusses reaction of Skirpa granite in Sweden to heat applied to bore holes. Recommends that experiments at Skirpa include steel casing of drill holes.
PHILBRICK, S. S. Affiliation Unknown. 79/04/24. 1p.

7908170298 Forwards viewgraphs presented at NRC/DOE 790523 meeting re DOE environ survey programs concerning natl waste terminal storage program. NRC shows limited capabilities to provide critical input into subsurface side of waste mgt process.
PHILBRICK, S. S. Affiliation Unknown. 79/05/24. 92pp.

7908170302 Comments on revisions to 10CFR50, Apps G & H & use of ASME III or ASME XI codes & stds.
BUSH, S. H. Battelle Memorial Institute, Pacific Northwest Laboratory. 79/05/31. 2pp.

7908170303 Forwards write-ups of "class of event" subj discussed at 790525 meeting. Analysis of LERs allows for comparisons of utils & NRC regional ofcs.
SEALE, R. L. Arizona, Univ. of. 79/05/30. 6pp.

7908200098 Minutes of ACRS Ad Hoc Subcommittee on Spent Fuel Storage Pool Design 790103 meeting in Washington, DC. FR notice, attendance list, schedule & copy of proposed 10CFR72 encl.
* ACRS - Advisory Committee on Reactor Safeguards. 79/05/31. 75pp.

7908210024 Minutes of ACRS Subcommittee on Power & Electrical Sys 790330 meeting in Phoenix, AZ to review adverse interactions through interconnection of protection & safety sys w/reactor control sys on RESAR-414 integrated protection sys design.
* ACRS - Advisory Committee on Reactor Safeguards. 79/05/09. 34pp.

7908210093 Discusses LER review w/emphasis on util reluctance to ascribe error to design inadequacy & overloading of human operators w/duties & responsibility, especially during emergency situations.
EPLEY, E. P. Elbert P. Epler. 79/05/29. 19pp.

7908210109 Discusses concerns re OPS defense in depth & interrelation f control & protection sys, both in operation & testing. Detailed evaluation of IPS control structure needed.
DITTO, S. J. Oak Ridge National Laboratory. 79/05/07. 2pp.

7908210115 Notifies ACRS of inability to attend subcommittee meeting on LERs due to hazards of US air travel. Compares techniques of safety investigation in nuclear & airline industries.
PARKER, H. M. Battelle Memorial Institute, Pacific Northwest Laboratory. 79/06/18. 3pp.

7908220214 Forwards rept on inadvertent safety injections & summary of investigation into causes of relief valve failures. New ANSI stds on valves for nuclear svc being developped by ASME & IEEE require prototype testing to ensure reliability.
CROMER, S. Affiliation Unknown. 79/06/19. 7pp.

7908230281 Discusses review of NUREG-0578, short-term recommendations of TMI-2 Lessons Learned Task Force. Ultimate responsibility for operational reliability lies w/licensee.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/08/13. 3pp.

7908290477 Recommends extension of scope of pipe cracking review beyond that examined in NUREG-0531. High frequency of BWR pipe cracking suggests probability of LOCA & need for examination of detection capability & safety procedures.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/08/16. 2pp.

7908290496 Forwards recommendations for studies to improve reactor safety in areas of accident analysis, reduction of accident probability, operating procedures, review of design, const & operation, decay heat removal sys in ECCS & other items.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/08/14. 4pp.

7908300458 Minutes of ACRS Subcommittee on Regulatory Activities 790404 meeting in Washington, DC to review proposed Reg Guides, revisions to existing Reg Guides & other matters re current Reg Guide procedures.
* ACRS - Advisory Committee on Reactor Safeguards. 79/05/01. 11pp.

AGREEMENT STATE AGREEMENTS AND PROGRAMS

7908030625 Responds to encl 790423 ltr to DOE re transportation of radioactive matl through Missoula, MT area. Forwards computer printout of transportation of various radionuclides during 1975.
JANINEK, M. Office of State Programs. 79/06/25. 10pp.

7908140032 Submits fourth quarter (second year) progress rept for period 790307-0607 re transportation surveillance program.
FRANCIS, B. J. Illinois, State of. 79/07/13. 3p.

7908070052 Notice of NRC assessment of proposed agreement w/State of RI re RI program for assumption of some NRC regulatory authority over state sources of radiation. Public comments desired within 30 days of publication. W/documentation.
RYAN, R. G. Office of State Programs. 79/06/25. 61pp.

--7908070057 Requests agreement w/NRC providing for discontinuance of certain NRC authority over sources of ionizing radiation. Proposed agreement covering radiation control program & supporting documentation encl.
GARRAHY, J. J. Rhode Island, State of. 79/05/25. 472pp.

7908070193 Forwards "Radioactive Matl Transportation Surveillance Program," quarterly progress rept for Mar-May 1979. Rept submitted by St of MI.
JANINEK, M. Office of State Programs. 79/07/18. 1p.

--7908070201 "Radioactive Matls Transportation Surveillance Program," quarterly progress rept for Mar-May 1979.
* Michigan, State of. NRC-06-77-05L. 79/07/18. 24pp.

7908090441 Forwards IE Investigation Rept 078-154 w/results of radiation survey efforts in Norton & Attleboro, MA through 781231. Responsibility for remedial action not determined.
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/06/04. 1p.

--7908090449 IE Investigation Rept 078-154 on 781024, 1031-1102, 1114, 1128-1201 & 21 Radiological survey found radium at Finberg Field, Attleboro, MA & various forms of U at private landfill in Norton, MA. "No trespassing" signs posted at Norton site.
STOHR, J. F., ROTH, J. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. KOTTAN, J. J. Region 1, Philadelphia, Office of the Director. 79/02/12. 30pp.

7908140029 Forwards fourth quarter (second year) progress rept for period 790307-0607 from IL re transportation surveillance program under agreement w/DOE & NRC.
JANINEK, M. Office of State Programs. 79/08/02. 1p.

7908140346 Forwards progress rept submitted by State of SC re transportation surveillance program from 781001-790630.
JANINEK, M. Office of State Programs. 79/07/10. 2pp.

--7908140355 Forwards third quarter progress rept for 781001-790630 re transportation surveillance program. State concentrated exclusively on monitoring shipments of radwaste for Barnwell disposal site.
WILLIAMS, E. F. South Carolina, State of. 79/07/02. 5pp.

7908140521 Agreement between VA State Water Control Board & NRC per Federal Water Pollution Control Act Amends of 1972.
GOSSICK, L. V. Office of the Executive Director for Operations.
DAVIS, R. V. Virginia, State of. 77/09/07. 5pp.

7908160368 Recommends consideration of replacement for M Van Nostrand as IA liason officer to NRC.
RYAN, R. G. Office of State Programs. 79/07/20. 1p.

7908170631 Forwards third quarter progress rept from State of KY on transportation & surveillance program. Rept covers 790329-0628.
JANINEK, M. Office of State Programs. 79/07/17. 1p.

--7908170632 Third quarter progress rept for "State Transportation Surveillance Program," for 790329-0628.
MILLS, D. Kentucky, State of. NRC-06-78-359. 79/07/09. 2pp.

COMMISSION NRC COMMISSIONERS

7907310621 Explains intent of Congress in U Mill Tailings Radiation Control Act of 1978. NRC has immediate authority over mill tailings in non-agreement states & there is three year period for agreement states to meet new statute requirement.
RANDOLPH, J. Senate. DINGELL, J. D., UDALL, M. K. House of Rep. 79/04/26. 2pp.

7908010040 Requests support for legislation to resolve questions re effective-date provisions of U Mill Tailings Radiation Control Act of 1978. Forwards draft of statutory language & section-by-section analysis.
HENDRIE, J. M. Commission. 79/06/06. 8pp.

7908010047 Requests support for legislation to resolve questions re effective-date provisions of U Mill Tailing Radiation Control Act of 1978. Forwards draft of statutory language & section-by-section analysis.
HENDRIE, J. M. Commission. 79/06/06. 8pp.

7908010054 Provides info re impact of shutdown of 16 reactors on installed reserve margins of potentially-affected utils.
HENDRIE, J. M. Commission. 79/06/01. 2pp.

--7908010058 Provides info re impact of shutdown of 16 reactors on installed reserve margins of potentially-affected utils.
HENDRIE, J. M. Commission. 79/06/01. 6pp.

7908010633 Weekly info rept for week ending 790622.
REHM, T. A. Office of the Executive Director for Operations. 79/06/28. 21pp.

7908010698 Weekly info rept for week ending 790629.
REHM, T. A. Office of the Executive Director for Operations. 79/07/05. 26pp.

7908030188 Ack receipt of 790508 ltr re C Petersen request for funding of study of low level ionizing radiation health effects. NRC has no record or knowledge of receipt of Petersen ltr.
HENDRIE, J. M. Commission. 79/06/15. 1p.

--7908030193 Requests info & comments on status of C Petersen request for funding to complete study of low level ionizing radiation health effects.
KENNEDY, E. M., HATCH, O. G. Senate, Committee on Human Resources. 79/05/08. 1p.

7908030205 Ack receipt of 790508 ltr re C Petersen request for funding of study of low level ionizing radiation health effects. NRC has no record or knowledge of receipt of Petersen ltr.
HENDRIE, J. M. Commission. 79/06/15. 1p.

7908030216 Requests support in restoring reductions to NRC FY80 budget request recommended by House Appropriations Committee, Subcommittee on Energy & Water Development. Forwards summary of markup of NRC FY80 budget, appeal & Senate authorization.
HENDRIE, J. M. Commission. 79/06/14. 54pp.

7908030225 Requests approval of estimated $450,000 6-month contract w/independent firm to conduct objective investigation into NRC activities re TMI accident.
HENDRIE, J. M. Commission. 79/06/13. 1p.

7908030235 Requests approval of estimated $450,000 6-month contract w/independent firm to conduct objective investigation into NRC activities re TMI accident.
HENDRIE, J. M. Commission. 79/06/13. 1p.

7908030249 Forwards "Rept to Congress of US Assessment of Capabilities & Research Needs of EPA & NRC in Area of Health Effects of Low Level Ionizing Radiation." Rept was directed by Congress in Public Law 95-601, Section 5(c). W/o encl.
HENDRIE, J. M. Commission. 79/06/08. 1p.

--7908030260 Forwards "Rept to Congress of US Assessment of Capabilities & Research Needs of EPA & NRC in Area of Health Effects of Low Level Ionizing Radiation." Rept was directed by Congress in Public Law 95-601, Section 5(c). W/o encl.
HENDRIE, J. M. Commission. 79/06/08. 1p.

--7908030278 Forwards "Rept to Congress of US Assessment of Capabilities Capabilities & Research Needs of EPA & NRC in Area of Health Effects of Low Level Ionizing Radiation." Rept was directed by Congress in Sec 5(c) of Public Law 95-601. W/o encl.
HENDRIE, J. M. Commission. 79/06/08. 1p.

--7908030321 Forwards "Report to Congress of US Assessment of Capabilities & Research Needs of EPA & NRC in Area of Health Effects of Low Level Ionizing Radiation." Rept was directed by Congress in Sec 5(c) of Public Law 95-601. W/o encl.
HENDRIE, J. M. Commission. 79/06/08. 1p.

--7908030325 Forwards "Rept to Congress of US Assesment of Capabilities & Research Needs of EPA & NRC in Area of Health Effects of Low Level Ionizing Radiation." Rept was directed by Congress in Public Law 95-601, Section 5(c).
HENDRIE, J. M. Commission. 79/06/08. 1p.

--7908030334 "Rept to Congress of US Assessment of Capabilities & Research Needs of EPA & NRC in Area of Health Effects of Low Level Ionizing Radiation.
* Commission. * Environmental Protection Agency. 79/05/24. 86pp.

7908030339 Forwards "Annual Rept for 1978 on Administration of Govt in Sunshine Act of 1976," per Section 3(j) of Public Law 94-409. W/o encl.
HENDRIE, J. M. Commission. 79/06/08. 1p.

--7908030343 Forwards "Annual Rept for 1978 on Administration of Govt in Sunshine Act of 1976," per Section 3(j) of Public Law 94-409. W/o encl.
HENDRIE, J. M. Commission. 79/06/08. 1p.

--7908030351 Forwards "Annual Rept for 1978 on Administration of Govt in Sunshine Act of 1976," per Section 3(j) of Public Law 94-409. W/o encl.
HENDRIE, J.M. Commission. 79/06/08. 1p.

--7908030359 Forwards "Annual Rept for 1978 on Administration of Govt in Sunshine Act of 1976," per Section 3(j) of Public Law 94-409.
HENDRIE, J.M. Commission. 79/06/08. 1p.

7908030376 Responds to 790501 ltr re GSA proposal to relocate NRC Region 4 ofc from Arlington, TX to Fort Worth. As result of 790518 meeting w/GSA, NRC has requested 2-yr extension of present lease.
HENDRIE, J.M. Commission. 79/06/11. 1p.

--7908030384 Requests comments on GSA proposal to relocate NRC Region 4 ofc from Arlington, TX to Fort Worth.
FROST, M. House of Rep. 79/05/01. 1p.

7908030475 Responds to ltr re 100 addl NRC employees for Ofc of Nuclear Reactor Regulation. Proposed addl staffing will be suppl to FY79 budget. Discusses reasons for addl staffing need & answers specific questions. Forwards 790608 ltr to JP White.
HENDRIE, J.M. Commission. 79/06/11. 4pp.

--7908030486 Expresses thanks for 790601 ltr which offered help in obtaining assistance from other agencies to deal w/increased workload imposed by TMI accident.
HENDRIE, J.M. Commission. 79/06/08. 2pp.

--7908030491 Offers help in obtaining assistance from other agencies to deal w/increasing workload imposed by TMI accident. Forwards ltrs to JR Schlesinger, CL Alexander & CD Andrus which requested assistance.
WHITE, J.P. Office of Management & Budget. 79/06/01. 4pp.

7908060022 Submits names & titles of chairperson & members of NRC Executive Resources Board, in response to 790514 FPM Bulletin Number 920-17, "Establishment of Executive Resources Boards."
HENDRIE, J.M. Commission. 79/07/12. 3pp.

7908060454 Forwards comparison of decay heat & isotope inventory core operation, as discussed in R Mattson TMI testimony.
HENDRIE, J.M. Commission. 79/07/11. 2pp.

--7908060458 Submits response to question re decay heat & isotopes from extended operation for TMI-2. Info includes table providing decay heat for TMI-2 operating history & for several assumed operating histories.
RICHINGS, H.J. Core Performance Branch. 79/06/05. 3pp.

--7908060462 Submits recent results of calculation of decay heat for TMI-2. Calculations use new decay heat info as supplied in most recent draft of ANS Std 5.1.
RICHINGS, H.J. Core Performance Branch. 79/05/09. 4pp.

7908070794 Accepts invitation to speak at 800405-11 ANS topical meeting re thermal reactor safety in Knoxville, TN.
HENDRIE, J.M. Commission. 79/07/02. 1p.

7908080558 Weekly info rept for week ending 790713.
REHM, T.A. Office of the Executive Director for Operations. 79/07/17. 32pp.

7908080652 Makes no recommendations re awarding of Presidential Medal of Freedom.
HENDRIE, J.M. Commission. 79/07/03. 1p.

--7908080670 Requests recommendations for Presidential Medal of Freedom by 790630. Forwards list of previous recipients.
SCHNEIDERS, G. President of US & Executive Offices. 79/06/11. 6pp.

7908090451 Responds to 790523 request for info re recent NRC actions per U Mill Tailings Radiation Control Act of 1978. Outlines proposed amends & course to be followed until amends are enacted. Ltr to Representative O'Neill encl.
HENDRIE, J.M. Commission. 79/06/07. 2pp.

--7908090459 Requests support for clarifying legislation to resolve questions re effective date provisions of U Mill Tailings Radiation Control Act of 1978. Draft of statutory language & section-by-section analysis encl.
HENDRIE, J.M. Commission. 79/05/30. 8pp.

--7908090464 Requests info re recent NRC actions on U Mill Tailings Radiation Control Act of 1978.
KING, B. New Mexico, State of. 79/05/23. 1p.

7908090501 Ack receipt of 790525 ltr & Nuclear Power Plant Emergency Response Panel rept.
HENDRIE, J.M. Commission. 79/06/05. 1p.

--7908090505 Forwards Nuclear Power Plant Emergency Response Panel 790518 rept re emergency response capabilities.
SCHWEICKART, R.L. California, State of. 79/05/25. 14pp.

7908100022 Weekly info rept for week ending 790706.
REHM, T.A. Office of the Executive Director for Operations. 79/07/10. 23pp.

7908100179 Responds to four points in 790710 ltr re program for improvements in packaging, transport & disposal of low level nuclear wastes.
HENDRIE, J.M. Commission. 79/07/18. 3pp.

--7908100197 Responds to four points in 790710 ltr re program for improvements in packaging, transport & disposal of low level nuclear wastes.
HENDRIE, J.M. Commission. 79/07/18. 3pp.

--7908100203 Responds to four points in 790710 ltr re program for improvements in packaging, transport & disposal of low level nuclear wastes.
HENDRIE, J.M. Commission. 79/07/18. 3pp.

7908130372 Weekly Info Rept for week ending 790601.
REHM, T.A. Office of the Executive Director for Operations. 79/06/11. 22p.

7908140275 Ack receipt of 790404 ltr forwarded by Representative K Holland. Describes federal & State of SC regulations re transportation of radioactive waste. Special procedures are established by NRC for shipping TMI waste. DOT rules encl.
HENDRIE, J.M. Commission. 79/06/30. 5pp.

--7908140285 Notice of issuance for comment of 10CFR73 interim final rule, "Physical Protection of Irradiated Reactor Fuel in Transit." DOT notice of issuance encl.
CHILK, S.J. Office of the Secretary of the Commission. 79/06/12. 11pp.

--7908140291 Forwards 790404 ltr from L Jordan re nuclear power & transportation of nuclear waste.
HOLLAND, K. House of Rep. 79/04/23. 2pp.

--7908140299 NUREG-0535
"Review & Assessment of Package Requirements (Yellowcake) & Emergency Response to Transportation Accidents." Draft rept.
* Office of Nuclear Material Safety & Safeguards. *
Transportation, Dept. of. 79/10/31. 230pp.

--7908140306 NUREG-0170 V1
"FES on Transportation of Radioactive Matl by Air & Other Modes."
* Office of Standards Development. 77/12/31. 300pp. Available at NTIS.

--7908140326 NUREG-0170 V2
"FES on Transportation of Radioactive Matl by Air & Other Modes," Vol 2.
* Office of Standards Development. 77/12/31. 450pp.

7908150468 Weekly info rept for week ending 790725.
REHM, T.A. Office of the Executive Director for Operations. 79/07/25. 36pp.

7908170286 Ack receipt of 790715 ltr notifying of formation of Energy & Environ Ctr. Offers best wishes for success.
HENDRIE, J.M. Commission. 79/07/23. 1p.

--7908170295 Notifies of formation of new Energy & Environ Ctr to make univ resources available in search for solutions to energy & environ problems.
FLETCHER, J.C. Pittsburgh, Univ. of. 79/07/15. 1p.

7908170305 Notifies of completed action on petition for rulemaking re stds for shallow land disposal of transuranic radioactive waste. Portion of petition re implementation of immediate regulations denied. Forwards notice of action on petition.
CHILK, S.J. Office of the Secretary of the Commission. 79/07/18. 2pp.

--7908170308 Notice of action on NRDC 760806 petition for rulemaking. Request for implementation of immediate regulations denied.
CHILK, S.J. Office of the Secretary of the Commission. 79/07/18. 31pp.

7908170314 Refers to 781222 ltr. Forwards NRC systematic review guidelines for natl security info prepared after consultation w/NARS personnel & reviewed by Info Security Oversight Ofc per 781222 request.
HENDRIE, J. M. Commission. 79/07/18. 13pp.

--7908170317 Expresses concern that no systematic review guidelines cover 20-year-old classified info under NRC jurisdiction. Requests immediate consideration. Forwards 781222 request.
RHOADS, J. B. National Archives & Records Service. 79/04/26. 1p.

--7908170322 Reminds NRC that Executive Order 12065 re natl security info, effective 781201, requires issuance of guidelines within 180 days for systematic review of 20-year-old classified info under NRC jurisdiction. Outline of topics encl.
RHOADS, J. B. National Archives & Records Service. 78/12/22. 1p.

7908170327 Expresses appreciation for 790621 ltr offering assistance in improving safety of nuclear energy program. Suggestions of failure mode studies & operator training studies are items for consideration. Encourages participation.
HENDRIE, J. M. Commission. 79/07/18. 1p.

--7908170332 Offers assistance of membership in aiding federal govt in improving safety of nuclear energy program. Feels Academy might be of svc in conducting studies to analyze operational characteristics of LWRs & training of operators.
HANDLER, P. National Academy of Sciences. 79/06/21. 1p.

7908170344 Submits collected views on NRC regulations for discipling of attorneys in licensing proceedings. Primary objective of enforcing discipline against attorney is maint of good order in proceeding itself.
DEALE, V. B. Valentine B. Deale. 79/06/05. 13pp.

--7908170349 Responds to 790223 comments re methods for improving NRC regulations for handling atty disciplinary matters in adjudicatory proceedings. Recommends 10CFR2.713 be revised.
OLMSTEAD, W. J. Branch 4. 79/03/16. 9pp.

7908170427 Regrets untimely negative remark made in ref to capabilities & achievements of blind during Commissioner meeting on accident at TMI. Press release issued on 790510 encl.
HENDRIE, J. M. Commission. 79/07/06. 2pp.

7908170533 Submits results of JM Hendrie radioactive matl exposure examination for 780408-12. Rept furnished per 10CFR19.
DUBIL, R. W. Metropolitan Edison Co. 79/07/08. 1p.

7908200406 Ack receipt of 790427 ltr re relations between press & Chairman Hendrie.
HENDRIE, J. M. Commission. 79/05/08. 1p.

--7908200408 Comments on NRC press relations during TMI-2 incident. Offers enrollment in media training program.
CRUTCHFIELD, C. H. Media Communications, Inc. 79/04/27. 2pp.

7908210018 Accepts invitation to speak at EEI 791017 finance conference in Miami, FL.
HENDRIE, J. M. Commission. 79/07/12. 1p.

--7908210020 Extends invitation to address meeting of EEI finance conference to be held 791014-17 in Miami, FL. Purpose of meeting is to bring together chief financial officers w/program supporters in util industry.
O'BRIEN, T. H. Long Island Lighting Co. 79/07/05. 2pp.

7908210164 Declines 790625 invitation to speak at 790917-20 conference on energy crisis.
HENDRIE, J. M. Commission. 79/07/02. 1p.

--7908210168 Requests participation in 790917-20 conference on energy crisis in Washington, D. C.
DUSCHA, J. The Washington Journalism Center. 79/06/25. 1p.

7908220069 Ack receipt of 790405 ltr re moisture detection sys. Direct contact w/potential purchasers would be appropriate.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/26. 1p.

--7908220073 Discusses moisture detection sys. Requests circulation of ltr to appropriate individuals. Moisture detection sys are often applied improperly.
WIEDERHOLD, P. R. General Eastern Instruments Corp. 79/04/05. 3pp.

7908220250 Weekly info rept for week ending 790727.
REHM, T. A. Office of the Executive Director for Operations. 79/08/02. 28pp.

7908220336 Weekly info rept for week ending 790810.
REHM, T. A. Office of the Executive Director for Operations. 79/08/15. 28pp.

7908230515 Responds to request for comments on S. 1119, Senate Rept 96-205. Secretary of Interior would be required to rept to Congress on storage or transportation of spent nuclear fuel. Explains NRC neutrality on issue.
HENDRIE, J. M. Commission. 79/07/27. 1p.

--7908230520 Requests view of NRC on S. 1119, Senate Rept 96-205 re reporting by Secretary of Interior to Congress on plans or projects affecting territories & possessions of US. Response needed by 790716.
PETERSON, R. K. Office of Management & Budget. 79/07/02. 1p.

7908230528 Expresses appreciation for concerns re assurance of adequate regionally distributed disposal capacity for low level waste disposal. Assures of positive actions toward formal regulations, supporting reg guides & licensing procedures.
HENDRIE, J. M. Commission. 79/07/27. 2pp.

--7908230535 Comments on issue re safe disposal of radioactive wastes from nuclear fuel cycle. Important for DOE to develop contingency plan which would allow burial sites to accept commercially generated wastes if necessary.
HENDRIE, J. M. Commission. 78/07/07. 2pp.

--7908230540 Expresses concern for high vol of low level waste State of SC receives from operating power reactors & fuel fabricaters. Vol limits should be lower.
RILEY, R. W. South Carolina, State of. 79/04/19. 2pp.

7908240293 Responds to 790712 ltr expressing interest in NRC efforts, working w/Congress & GSA, to consolidate its ofcs into one site. Once favorable action is taken by Congress, President's urban policy will be basis for site determination.
HENDRIE, J. M. Commission. 79/07/27. 1p.

--7908240295 Supports consolidation of various NRC ofcs in leased space in downtown Washington, DC. Cites supporting info found in final EIS.
BARRY, M. S. District of Columbia. 79/07/27. 2pp.

7908240395 Applauds appointment as Chairman for Natl Capital Area.
HENDRIE, J. M. Commission. 79/07/25. 1p.

7908240398 Ack 790703 ltr re assistance provided by Cunningham to State of AZ on American Atomics situation. NRC will continue to provide technical support for license proceeding conducted by AZ Atomic Energy Commission.
HENDRIE, J. M. Commission. 79/07/27. 1p.

--7908240404 Ack quick response to request for assistance from NRC re American Atomics situation in Tucson, AZ.
BABBITT, B. Arizona, State of. 79/07/03. 1p.

7908240473 Forwards rept, "Nuclear Power Attitudes in USSR."
HENDRIE, J. M. Commission. 79/07/27. 1p.

--7908240494 "Nuclear Power Attitudes in USSR."
WILSON, R. Harvard Univ. 79/07/27. 10pp.

7908270247 Forwards list of actions to improve transportation & disposal of low level radioactive waste, to suppl 790718 response to 790710 ltr. W/o encl.
HENDRIE, J. M. Commission. 79/08/09. 1p.

--7908270254 Forwards list of actions to improve transportation & disposal of low level radioactive waste, to suppl 790718 response to 790710 ltr. W/o encl.
HENDRIE, J. M. Commission. 79/08/09. 1p.

--7908270261 Forwards list of actions to improve transportation & disposal of low level radioactive waste, to suppl 790718 response to 790710 ltr.
HENDRIE, J. M. Commission. 79/08/09. 5pp.

7908270325 Submits facts re 790724 communication w/Commissioners concerning memo of understanding w/Equal Employment Opportunity Commission proposing that latter investigate individual complaints of discrimination against NRC.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/08/02. 2PP.

7908280001 Ack invitation to be included in sampling of opinions of "energy elite." Invitation must be declined due to insufficient time.
HENDRIE, J. M. Commission. 79/08/10. 1p.

--7908280002 Requests assistance in study being conducted re attitudes & opinions on energy problems by experts & decisionmakers in field.
GREENBERGER, M. Johns Hopkins Univ. 79/08/01. 1p.

7908280006 Invitation to attend sixteenth annual LJ Waldeck Bird Calling Contest on 790524.
FARINSKY, K. W. Affiliation Unknown. 79/04/24. 1p.

7908280187 Forwards case file requested 790702. File will be supplemented at one-to-three-month intervals.
CLARY, R. National Treasury Employee Union. 79/07/17. 1p.

--7908280206 Requests forwarding of union file re RG Clary for review. Copy will be placed in PDR.
HENDRIE, J. M. Commission. 79/07/12. 1p.

--7908280378 Responds to 790702 ltr requesting union file re RG Clary. File will be forwarded as soon as can be copied. Does not contain safety-related info not previously forwarded to Commission.
THOMAS, J. D. National Treasury Employee Union. 79/07/06. 1p.

--7908280400 Discusses 790628 meeting w/N Bentson re 790622 ltr. Withdrawn requests made for union & apologizes for problems that may have resulted. Ofc of Insp & Auditor will be asked to investigate.
THOMAS, J. D. National Treasury Employee Union. 79/06/29. 1p.

--7908280415 Responds to 790622 ltr re proposed firing of RG Clary. Allegations not previously investigated require priority inquiry by Ofc of Insp & Auditor. Requests records described be made available.
HENDRIE, J. M. Commission. 79/07/02. 1p.

--7908280428 Discusses proposed firing of RG Clary. Clary allegedly harassed for several years because of attempts to serve public. File collected detailing harassment.
THOMAS, J. D. National Treasury Employee Union. 79/06/22. 2pp.

7908280287 Responds to criticism of NRC testimony at 790613 hearing.
HENDRIE, J. M. Commission. 79/07/30. 1p.

--7908280308 Requests testimony at 790608, 11-13 hearings re dangers posed by facility to City of New York. Forwards agenda.
ALTER, S. D. Brooklyn, NY. 79/05/23. 3pp.

7908280792 Weekly info rept for week ending 790720.
REHM, T. A. Office of the Executive Director for Operations. 79/07/25. 42pp.

7908290144 Accepts invitation to dinner on 790803.
HENDRIE, J. M. Commission. 79/07/12. 1p.

--7908290150 Invites Hendrie & wife to dinner on behalf of nuclear engineering students & facility of Univ of MD.
LEE, R. Maryland, Univ. of. 79/07/06. 1p.

7908300769 Ack receipt of 790723 ltr forwarding speech given at Commonwealth Club in San Francisco.
HENDRIE, J. M. Commission. 79/07/30. 1p.

--7908300771 Forwards speech given at Commonwealth Club in San Francisco. W/o encl.
AGNEW, H. M. General Atomic Co. (subs. of Gulf Oil Corp.). 79/07/23. 1p.

7908300773 Responds to 790615 ltr re delays in notification of 790613 event containing list of type of events to be reported to NRC by licensee.
HENDRIE, J. M. Commission. 79/07/30. 2pp.

--7908300774 "For Comment" issue of Reg Guide 1.16, Revision 4, "Reporting of Operating Info - App A, Tech Specs."
* Office of Standards Development. 75/08/31. 13pp.

--7908300779 Expresses concern re NRC delay in notifying PA Dept of Environ Resources of 790613 incident at Peach Bottom. Urges enforcement of procedural requirements to eliminate delays in NRC notifying state officials of safety-related events.
THORNBURGH, R. Pennsylvania, State of. 79/06/15. 1p.

7908310003 Weekly info rept for week ending 790803.
REHM, T. A. Office of the Executive Director for Operations. 79/08/08. 32pp.

CONTRACT NRC CONTRACTS AND MODIFICATIONS

7908010202 Notification of contract execution, Mod 1 to "Evaluation of Reactor Radiation Streaming." Contractor: Mathematical Applications Group, Inc.
WOLLETT, S. A. Research Contracts Branch. FIN B-6206. NRC-04-79-179. 79/03/19. 1p.

7908010213 Notification of contract execution, Mod 1 to "Testing of Reinforced Concrete Containments Under Combined Membrane Tension & Tangential Shear." Contractor: Portland Cement Association.
WOLLETT, S. Research Contracts Branch. FIN B-6203. NRC-04-77-118. 79/06/18. 1p.

--7908010216 Mod 1, extending period of performance through 791031 to "Testing of Reinforced Concrete Containment Under Combined Membrane Tension & Tangential Shear."
MORTON, K. V. Division of Contracts. FIN B-6203. NRC-04-77-118. 79/06/18. 1p.

7908020156 Notification of contract execution, Mod 5 to "Radionuclide Retention & Land Form Mod in Surface Pathways." Contractor: State Univ of NY at Albany.
HAGEY, H. Research Contracts Branch. FIN B-6008. NRC-04-77-169. 79/04/01. 1p.

--7908020160 Mod 5, extending period of performance to 790531 to "Radionuclide Retention & Land Form Mod to Surface Pathways."
MORTON, K. V. Research Contracts Branch. FIN B-6008. NRC-04-77-169. 79/05/23. 2pp.

7908020341 Notification of contract execution, Mod 2 to "Kinematics of Translating Tornado Windfields." Contractor: TX Tech Univ.
HAGEY, H. Research Contracts Branch. FIN B-6177. NRC-04-77-016. 78/10/01. 1p.

--7908020346 Mod 2, extending contract for 1 yr & increasing funding to "Kinematics of Translating Tornado Windfields."
MORTON, K. V. Research Contracts Branch. FIN B-6177. NRC-04-77-016. 79/06/11. 4pp.

7908020356 Notification of contract execution, Mod 1 to "Mobility of Radioactive Waste Matls in Subsurface Migration by Particulate Transport." Contractor: GA Inst of Technology.
HAGEY, H. Research Contracts Branch. FIN B-6338. NRC-04-78-253. 79/06/01. 1p.

--7908020497 Mod 1, increasing support ceiling to "Mobility of Radioactive Waste Matls in Subsurface Migration by Particulate Transport."
MORTON, K. V. Research Contracts Branch. FIN B-6338. NRC-04-78-253. 79/06/01. 1p.

7908020388 Notification of contract execution, Mod 1 to "Survey of Current State Radiological Emergency Response Capabilities for Transportation-Related Incidents." Contractor: IN Univ.
* Research Contracts Branch. FIN B-10708. NRC-01-78-013. 79/07/17. 1p.

--7908020390 Mod 1, changing project director, to "Survey of Current State Radiological Emergency Response Capabilities for Transportation-Related Incidents."
MORTON, K. V. Research Contracts Branch. FIN B-10708. NRC-01-78-013. 79/07/17. 1p.

7908030065 Notification of contract execution: "Alcohol & Drug Abuse Awareness Training for Managers," awarded to Atlantic Counseling, Inc.
PEARLMAN, J. Purchasing Section. NRC-10-79-394. 79/06/29. 1p.

--7908030069 Contract: "Alcohol & Drug Abuse Awareness Training for Managers," awarded to Atlantic Counseling, Inc.
MATTIA, M. J. Division of Contracts. NRC-10-79-394. 79/06/29. 4pp.

7908030158 Notification of contract execution, Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt." Contractor: BDM Corp.
LEBO, C. D. Division of Contracts. NRC-02-77-201-17. 79/07/05. 1p.

--7908030164 Mod 5, correcting erroneous assignment of Mod 1 to two different contract mods of "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt."
DOUGHERTY, D. J. Division of Contracts. NRC-02-77-201-17. 79/07/05. 1p.

7908030363 Notification of contract execution: "Economic Definition of Nuclear Power Industry 1979 Update," awarded to Metrics, Inc.
MCNULTY, A. Purchasing Section. FIN B-1697. NRC-07-79-351.
79/07/13. 1p.

--7908030369 Contract: "Economic Definition of Nuclear Power Industry: 1979 Update," awarded to Metrics, Inc.
HARGETT, D. J. Division of Contracts. FIN B-1697. NRC-07-79-351.
79/07/13. 4pp.

7908030368 Notification of contract execution, Mod 30 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt." Contractor: Basic Technology, Inc.
LEBO, C. D. Technical Assistance Contracts Branch. NRC-02-77-201.
79/06/04. 1p.

--7908030375 Mod 3, extending period of performance & updating provisions to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt."
DOUGHERTY, D. J. Division of Contracts. NRC-02-77-201. 79/06/04.
2pp.

7908030373 Notification of contract execution: "Review of Geological Documents Regarding Philippine Reactor 1," awarded to Woodward Clyde Consultants.
PERLMAN, J. Administrative Contracts Branch. FIN B-1314.
NRC-19-79-470. 79/07/13. 1p.

--7908030381 Contract: "Review of Geological Documents Regarding Philippine Reactor 1," awarded to Woodward Clyde Consultants.
HARGETT, D. J. Division of Contracts. FIN B-1314. NRC-19-79-470.
79/06/26. 8pp.

7908030387 Notification of contract execution: "Advisory Committee for Const During Adjudication," awarded to Carolina Environ Study Group.
PERLMAN, J. R. Division of Contracts. FIN B-1560. NRC-17-79-454.
79/07/20. 1p.

--7908030396 Contract: "Advisory Committee for Const During Adjudication," awarded to Carolina Environ Study Group.
HARGETT, D. J. Division of Contracts. FIN B-1560. NRC-17-79-454.
79/07/16. 4pp.

7908030429 Notification of contract execution, Mod 1 to "ALARA in Radiopharmaceutical Industry." Contractor: Ecological Analysts.
LEBO, C. D. Technical Assistance Contracts Branch. FIN [illegible]-0414-9.
NRC-02-79-037. 79/07/23. 1p.

--7908030439 Mod 1, changing project officer for "ALARA in Radiopharmaceutical Industry."
DOUGHERTY, D. J. Division of Contracts. NRC-02-79-037. 79/07/23.
1p.

7908030465 Notification of contract execution, Mod 19 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt." Contractor: TRW Energy Sys Group.
LEBO, C. D. Technical Assistance Contracts Branch. NRC-02-77-201.
79/06/04. 1p.

--7908030470 Mod 19, extending period of performance & updating provisions to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt."
DOUGHERTY, D. J. Division of Contracts. NRC-02-77-201. 79/06/29.
2pp.

7908060098 FOIA request for Contract NRC-03-79-126, "Evaluation of Matl Interactions for Advanced Reactor Sy[illegible]," contractor proposal & source evaluation board rept.
WEAVER, E. A. Westinghouse Electric Corp. 79/07/06. 1p.

7908060100 Responds to FOIA request for Contract NRC-03-79-126, "Evaluation of Matl Interactions for Advanced Reactor Sys," contractor proposal & source evaluation board rept.
FELTON, J. M. Division of Rules and Records. 79/07/30. 1p.

7908070458 Notification of contract execution: "Continued Development & Operation of NPRDS," awarded to Southwest Research Inst.
* Administrative Contracts Branch. NRC-10-79-369. 79/07/01.
1p.

--7908070464 Contract: "Continued Development & Operation of NPRDS," awarded to Southwest Research Inst.
MATTIA, M. J. Administrative Contracts Branch. NRC-10-79-369.
79/07/01. 148pp.

7908070717 Notification of contract execution: "Survey of Snow Loads on Nuclear Power Plant Structures," awarded to NBS.
GUSTAVE, R. P. Research Contracts Branch. FIN B-10879.
NRC-01-79-009. 78/12/15. 1p.

--7908070720 Delineates terms of contract w/NBS, "Survey of Snow Loads on Nuclear Power Plant Structures."
MORTON, K. V. Research Contracts Branch. FIN B-10879.
NRC-01-79-009. 79/01/02. 3pp.

7908080407 Notification of contract execution, Mod 6 to "Geologic Study of Low Level Radioactive Waste Burial Site, West Valley, NY."
Contractor: Univ of NY at Albany.
HAGEY, H. Administrative Contracts Branch. FIN B-6008. 79/07/10.
1p.

--7908080411 Mod 6, broadening scope of work w/addl funds to continue & complete study for final year, to "Geologic Study of Low Level Radioactive Waste Burial Site, West Valley, NY."
MORTON, K. V. Division of Contracts. NRC-04-77-169. 79/02/15.
6pp.

7908080412 Notification of contract execution, Mod 1 to "TMI Incident Special Inquiry Team." Contractor: CO Miller.
MORTON, K. V. Administrative Contracts Branch. FIN B-1560.
NRC-17-79-452. 79/07/12. 1p.

--7908080426 Submits Mod 1, extending period of performance, to "TMI Incident Special Inquiry Team."
DONOGHUE, D. J. Office of Administration. FIN B-1560.
NRC-17-79-452. 79/07/12. 1p.

7908080414 Notification of contract execution, Mod 7 to "Remote Sensing for Cooling Tower Drift Monitoring." Contractor: INTERA Environmental Consultants, Inc.
MYNATT, W. A. Administrative Contracts Branch. FIN B-6205.
79/06/04. 1p.

--7908080418 Mod 7, adding work, funds & time to "Remote Sensing for Cooling Tower Drift Monitoring."
MORTON, K. V. Division of Contracts. FIN B-6205. 79/06/04. 2pp.

7908080431 Notification of contract execution, Mod 2 to "Application of Intensity Response Spectral Amplitude Correlation Seismic Design Problem in Eastern US." Contractor: Computer Sciences Corp.
WOLLETT, S. A. Administrative Contracts Branch. FIN B-6316.
NRC-04-78-237. 79/07/10. 1p.

--7908080435 Mod 2, extending for three months at no addl cost "Application of Intensity Response Spectral Amplitude Correlation Seismic Design Problems in Eastern US."
MORTON, K. V. Division of Contracts. NRC-04-78-237. 79/06/03.
1p.

7908080440 Notification of contract execution, Mod 5 to "Hydrodynamics & Meteorological Measurements of High Wind Over Shallow Water Along East Coast of FL." Contractor: Univ of FL.
HAGEY, H. Administrative Contracts Branch. FIN B-5865.
NRC-04-76-175. 79/04/01. 1p.

--7908080444 Mod 5, extending period of performance at no addl cost to "Hydrodynamics & Meteorological Measurements of High Wind Over Shallow Water Along East Coast of FL."
MORTON, K. V. Division of Contracts. NRC-04-76-175. 79/04/01.
3pp.

7908080453 Notification of contract execution, corrected copy of Mod 5 to "Analysis of Fission Transport & Disposition Within LWRs Under Assumed Accident Conditions." Contractor: Battelle Columbus Lab.
MYNATT, W. A. Administrative Contracts Branch. FIN A-4078.
NRC-04-76-293-0. 79/07/23. 1p.

7908090268 Notification of contract execution: "Licensing Assistance/Tailings Mgt Program Technical Evaluation," awarded to Ofc of Sponsored Research, CO State Univ.
BONNER, J. A. Technical Assistance Contracts Branch. 79/07/03.
1p.

--7908090284 Contract: "Licensing Assistance/Tailings Mgt Program Technical Evaluation," awarded to CO State Univ.
DOUGHERTY, D. J. Technical Assistance Contracts Branch.
NRC-02-79-031-02. 79/07/02. 12pp.

7908090299 Notification of contract execution, Mod 4 to contract w/Small Business Administration, New York, NY.
HAGAN, T. F. Administrative Contracts Branch. FIN B-31X0200.400.
79/05/30. 1p.

7908080412 Notification of contract execution, Mod 4 Contractor: Small Business Administration, Subcontracted to Logical Technical Svcs Corp.
HAGAN, T. F. Administrative Contracts Branch. FIN B-31X0200.400.
79/07/13. 1p.

--7908090397 Mod 4, changing sys name to Decision Unit Tracking Sys, adding programmer labor category, revising total level of effort & increasing funding to contract w/Small Business Administration, New York, NY.
MATTIA, M. J. Administrative Contracts Branch. FIN B-31X0209, 409. 79/06/19. 4pp.

7906090456 Notification of contract execution, Mod 1 to "TMI Incident Special Inquiry Team." Contractor: BC Doyle.
MORTON, K. V. Administrative Contracts Branch. FIN B-1560. NRC-17-79-453. 79/07/12. 1p.

--7908090485 Notifies of Mod 1, extending period of performance to "TMI Incident Special Inquiry Team." Requests acceptance of change.
DONOGHUE, D. J. Office of Administration. 79/07/12. 1p.

7908090556 Notification of contract execution: "Evaluation of Financial Assurance Alternatives for Decommissioning Nuclear Reactors & Their Impact on Rates," awarded to New England Conference Public Util Commissioners.
GUSTAVE, R. P. Research Contracts Branch. FIN B-10189. 79/07/11. 1p.

--7908090562 Contract: "Evaluation of Financial Assurance Alternatives for Decommissioning Nuclear Reactors & Their Impact on Rates," awarded to New England Conference of Public Util Commissioners.
MORTON, K. V. Research Contracts Branch. FIN B-10189. 79/07/13. 12pp.

7908090574 Notification of contract execution: "Advisory Committee for Const During Adjudication," awarded to ER Weiss of Sheldon, Harmon & Roisman.
* Purchasing Section. FIN B-1560. 79/07/18. 1p.

--7908090577 Contract: "Advisory Committee for Const During Adjudication," awarded to ER Weiss of Sheldon, Harmon & Roisman.
* Purchasing Section. FIN B-1560. 79/07/18. 4pp.

7908090600 Notification of contract execution: "Advisory Committee for Const During Adjudication," awarded to AZ Roisman, NRDC.
LITTLE, M Purchasing Section. FIN B-1560. 79/07/18. 1p.

--7908090610 Contract: "Advisory Committee for Const During Adjudication," awarded to AZ Roisman, NRDC.
HARGETT, D. J. Purchasing Section. FIN B-1560. 79/01/18. 1P

7908090620 Notification of contract execution: "Licensing Assistance/Tailings Mgt Program Technical Evaluation," awarded to Fred C Hart Associates, Inc.
BONNER, J. A. Technical Assistance Contracts Branch.
NRC-02-031-04. 79/07/29. 1p.

--7908090629 Contract: "Licensing Assistance/Tailings Mgt Program Technical Evaluation," awarded to Fred C Hart Associates, Inc.
DOUGHERTY, D. J. Technical Assistance Contracts Branch.
NRC-02-031-04. 79/07/09. 13pp.

7908090658 Notification of contract execution: "Advisory Committee for Const During Adjudication," awarded to TQ Dignan, Ropes & Gray.
PERLMAN, J. Purchasing Section. FIN B-1550. NRC-17-79-451. 79/07/18. 1p.

--7908090662 Contract: "Advisory Committee for Const During Adjudication," awarded to TQ Dignan, Ropes & Gray.
PERLMAN, J. Purchasing Section. FIN B-1550. NRC-17-79-451. 79/07/16. 4pp.

7908100248 Notification of contract execution, corrected copy of Mod 1 to "Durability of Crystalline Nuclear Waste - Fgms & Natural Analogs at Geologic Storage Conditions." Contractor: Univ of Toledo.
HAGEY, H. Administrative Contracts Branch. FIN B-6624. NRC-04-78-267. 79/07/12. 1p.

7908100251 Notification of contract execution, Mod 2 to "Economic Consulting Svcs in Connection W/Stanislaus Nuclear Unit." Contractor: PM Gutmann.
GLAGOLA, A F. Technical Assistance Contracts Branch. FIN B-6521. 79/07/09. 1p.

--7908100257 Mod 2, extending period of performance to 791130 to "Economic Consulting Svcs in Connection W/Stanislaus Nuclear Unit."
DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN B-6521. 79/07/09. 1p.

7908100262 Notification of contract execution, corrected copy of Mod 1 to "Evaluation of Bulk Properties of Radwaste Glass & Ceramic Container Matl to Determine Long-Term Stability." Contractor: Catholic Univ of America.
HAGEY, H. Administrative Contracts Branch. FIN B-6330. 79/07/12. 1p.

7908100264 Notification of contract execution, Mod 3 to "Economic Assistance Related to Antitrust Hearings for South Texas Proceeding." Contractor: Transcomm, Inc.
GLAGOLA, A. F. Technical Assistance Contracts Branch. FIN B-6593. 79/07/03. 1p.

--7908100271 Mod 3, modifying scope of work to "Economic Assistance Related to Antitrust Hearings for South Texas Proceeding."
DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN B-6593. 79/06/29. 1p.

7908100277 Notification of contract execution, Mod 1 to "Evaluation of Financial Assurance Alternatives for Decommissioning Nuclear Reactors & Their Impact on Rates," awarded to New England Conference of Public Util Commissioners.
GUSTAVE, R. P. Research Contracts Branch. FIN B-10189. 79/07/11. 1p.

--7908100295 Mod 1, changing contractor address, adding D Fink to key personnel & correcting requisition/purchase request project number to "Evaluation of Financial Assurance Alternatives for Decommissioning Nuclear Reactors."
MORTON, K. V. Research Contracts Branch. FIN B-10189. 79/07/13. 1p.

7908100280 Notification of contract execution, Mod 4 to "Develop Certification Criteria for Industrial Radiographers." Contractor: Univ of Lowell.
GUSTAVE, R. P. Administrative Contracts Branch. FIN B-10276. NRC-01-76-337. 79/07/02. 1p.

--7908100286 Mod 4, extending period of performance to 790715, to "Develop Certification Criteria for Industrial Radiographers."
MORTON, K. V. Division of Contracts. NRC-01-76-337. 79/05/10. 2pp.

7908100300 Notification of contract execution, Mod 4 to "Workshop on Flammability of Solid Polymer Dielectrics," to National Academy of Sciences.
WOLLETT, S. A. Research Contracts Branch. NRC-04-77-144. 79/07/17. 1p.

--7908100307 Mod 4, extending period of performance from 790228 through 791221, to "Workshop on Flammability of Solid Polymer Dielectics."
* Research Contracts Branch. NRC-04-77-144. 79/06/18. 1p.

7908100302 Notification of contract execution, Mod 2 to "Application of Intensity Response Spectral Amplitude Correlation Seismic Design Problems in Eastern US." Contractor: Computer Sciences Corp.
WOLLETT, S. A. Research Contracts Branch. FIN B-6316. NRC-04-78-237. 79/07/10. 1P.

--7908100309 Mod 2, extending period of performance for three months at no cost to "Application of Intensity Response Spectral Amplitude Correlation Seismic Design Problems in Eastern US."
MORTON, K. V. Division of Contracts. NRC-04-78-237. 79/07/10. 1p.

7908100310 Notification of contract execution, Mod 2 to "Thermal Phenomena of Reactor Accidents." Contractor: MIT.
HAGEY, H. Research Contracts Branch. FIN B-6213. 79/06/01. 1p.

--7908100314 Mod 2, extending period of performance from 790531 to 790715 to "Thermal Phenomena of Reactor Accidents."
MORTON, K. V. Research Contracts Branch. FIN B-6213. 79/07/17. 3pp.

7908100340 Notification of contract execution: "Siting of Nuclear Facilities in Karst & Other Areas Susceptible to Ground Collapse," awarded to Dept of Army Waterways Experiment Station.
GUSTAVE, R. P. Research Contracts Branch. FIN A-10869. NRC-01-79-006. 79/07/17. 1p.

--7908100346 Contract: "Siting of Nuclear Facilities in Karst & Other Areas Susceptible to Ground Collapse," awarded to Dept of Army Experiment Station.
MORTON, K. V. Research Contracts Branch. FIN A-10869. NRC-01-79-006. 79/07/17. 4pp.

7908140374 Notification of contract execution, Mod 2 to "Loan Agreement Between State of IL, DOT & NRC to Conduct Joint Study on Transportation of Radioactive Matl in IL." Contractor: Dept of Public Health, State of IL.
WIGGINS, E. Administrative Contracts Branch. NRC-06-78-358.
79/06/15. 1p.

--7908140379 Mod 2, extending period of performance for addl year, to "Loan Agreement Between State of IL, DOT & NRC to Conduct Joint Study on Transportation of Radioactive Matl in IL."
MATTIA, M. J. Administrative Contracts Branch. NRC-06-78-358.
79/06/15. 1p.

7908140440 Notification of contract execution, Mod 1 to "Field & Theoretical Investigations of Mass & Energy Transport in Subsurface Matls at Waste Disposal Sites." Contractor: Univ of AZ.
HAGEY, H. Research Contracts Branch. FIN B-5753. NRC-04-78-275.
79/06/01. 1p.

--7908140444 Mod 1, increasing support ceiling to $352,550, to "Field & Theoretical Investigations of Mass & Energy Transport in Subsurface Matls at Waste Disposal Sites."
MORTON, K. V. Research Contracts Branch. FIN B-5753. NRC-04-78-275. 79/06/01. 1p.

7908150397 Notification of contract execution, Mod 1 to "Mobile Radiotelephones (16) & Accessories." Contractor: Electronics Communications, Inc.
WIGGINS, E. Administrative Contracts Branch. FIN 31-X0200 409.
79/07/27. 1p.

--7908150402 Mod 1, providing funding for freight charges, to "Mobile Radiotelephones (16) & Accessories."
MATTIA, M. J. Administrative Contracts Branch. FIN 31-X0200 409.
79/07/26. 2pp.

7908160329 Notification of contract execution, Mod 2 to "Specially Designed File Folders." Contractor: Ames Color File.
WIGGINS, E. Administrative Contracts Branch. NRC-10-79-374-01.
79/07/10. 1p.

--7908160344 Mod 2 to "Specially Designed File Folders."
MATTIA, M. J. Division of Contracts. 31X0200 409. 79/07/10. 1p.

7908160377 Notification of contract execution, Mod 1 to "Specially Designed File Folders." Contractor: Ames Color File.
WIGGINS, E. Administrative Contracts Branch. NRC-10-79-374-01.
79/07/10. 1p.

--7908160381 Mod 1, changing unit price & amount of supplies & svcs, to "Specially Designed File Folders."
MATTIA, M. J. Division of Contracts. 31X0200 409. 79/07/10.
4pp.

7908160383 Notification of contract execution, Mod 3 to "Electrostatic Copying Svc."
WIGGINS, E. Administrative Contracts Branch. NRC-10-79-361.
79/07/19. 1p.

--7908160385 Mod 3, increasing funding, to "Electrostatic Copying Svc."
MATTIA, M. J. Division of Contracts. 31X0200 409. 79/07/19. 1p.

7908160389 Notification of contract execution, Mod 3 to "Electrostatic Copying Svc." Contractor: Potomac Research, Inc.
WIGGINS, E. Administrative Contracts Branch. NRC-17-77-152.
79/07/13. 1p.

--7908160391 Mod 3 extending period of performance for one year, to "Electrostatic Copying Svc."
MATTIA, M. J. Division of Contracts. 79/07/13. 3pp.

7908160393 Notification of contract executive, Mod 2 to "Shuttle Bus Svc." Contractor: Beltway Limousine Svc, Inc.
WIGGINS, E. Administrative Contracts Branch. NRC-10-78-591.
79/07/10. 1p.

--7908160395 Mod 2, adding addl stop on north & southbound trips, to "Shuttle Bus Svc."
MATTIA, M. J. Division of Contracts. 79/07/10. 3pp.

7908160422 Notification of contract execution, Mod 1 to " Health Effects of Low-Level Ionizing Radiation." Contractor: Mt Sinai School of Medicine.
GUSTAVE, R. P. Research Contracts Branch. NRC-01-78-018.
79/07/09. 1p.

--7908160425 Mod 1, increasing period of performance at no addl cost, to "Health Effects at Low Level Ionizing Radiation."
MORTON, K. V. Division of Contracts. FIN-B-10858. 79/07/11. 1p.

7908160430 Notification of contract execution: "Synthesis of Physical Security & Matl Control & Accounting Assessment Results," awarded to Science Applications, Inc.
SMITH, P. A. Technical Assistance Contracts Branch. NRC-02-79-029.
79/07/23. 1p.

--7908160434 Contract: "Synthesis of Physical Security & Matl Control & Accounting Assessment Results," awarded to Science Applications, Inc.
DOUGHERTY, D. J. Division of Contracts. FIN-B-6412-9. 79/07/23.
15pp.

7908160535 Notification of contract execution: "Finalization of Rept on Evaluation of Cost Effects on Nuclear Power Plant Const Resulting From Increase in Seismic Design Levels," awarded to Woodward-Clyde Consultants.
MCNULTY, A. Purchasing Section. FIN B-6735. NRC-04-79-198.
79/07/25. 1p.

--7908160544 Contract: "Finalization of Rept on Evaluation of Cost Effects on Nuclear Power Plant Const Resulting From Increase in Seismic Design Levels," awarded to Woodward-Clyde Consultants.
HARGETT, D. J. Division of Contracts. FIN B-6735. 79/07/25.
5pp.

7908160537 Notification of contract execution: "Advisory Committee for Const During Adjudication" awarded to Shaw, Pittman, Potts & Trowbridge.
MCNULTY, A. Purchasing Section. NRC-17-79-450. 79/07/25. 1p.

--7908160540 Contract: "Advisory Committee for Const During Adjudication," awarded to Shaw, Pittman, Potts & Trowbridge.
HARGETT, D. J. Division of Contracts. FIN B-1560. 79/07/25.
4pp.

7908160543 Notification of contract execution: "Analysis & Design Activities Required for Development of NRC Automated Personnel Sys," awarded to Small Business Administration.
WIGGINS, E. Administrative Contracts Branch. NRC-10-79-386.
79/07/09. 1p.

--7908160548 Contract: "Analysis & Design Activities Required for Development of NRC Automated Personnel Sys," awarded to Small Business Administration.
CHISHOLM, J. R. Division of Contracts. 3LX0200 409. 79/07/09.
103pp.

7908170054 Notification of contract execution, Mod 1 to "Thermal Hydraulics of Advanced Reactor Accidents."
MENCZER, W. B. Technical Assistance Contracts Branch.
NRC-03-79-123. 79/07/23. 1p.

--7908170056 Mod 1 to "Thermal Hydraulics of Advanced Reactor Accidents."
DOUGHERTY, D. J. Division of Contracts. FIN-1-4042. 79/07/23.
2pp.

7908170060 Notification of contract execution: "Technical Assistance on Development of Regulatory Framework for Nuclear Waste Mgt," awarded to Info Transfer Inc.
LEBO, C. D. Technical Assistance Contracts Branch.
NRC-02-77-201-47. 79/07/24. 1p.

--7908170063 Contract: "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt," awarded to Info Transfer Inc.
DOUGHERTY, D. J. Division of Contracts. 79/07/23. 12pp.

7908170066 Notification of contract execution, Mod 1 to "Transcription of TMI Tapes."
WIGGINS, E. Administrative Contracts Branch. NRC-10-79-400.
79/07/10. 1p.

--7908170070 Mod 1, increasing number of cassettes transcribed, to "Transcription of TMI Tapes."
MATTIA, M. J. Division of Contracts. 31X0200 409. 79/07/02.
2pp.

7908170115 Notification of contract execution: "Electrical Engineering Contractual Assistance for St Lucie 2 Antitrust Proceeding," awarded to JR Lundberg & Associates.
GLAGOLA, A. F. Technical Assistance Contracts Branch. FIN B-6816.
NRC-07 9-158. 79/07/03. 1p.

--7908170122 Contract: "Electrical Engineering Contractual Assistance for St Lucie 2 Antitrust Proceeding," awarded to JR Lundberg & Associates.
DOUGHERTY, D. J. Division of Contracts. FIN B-6816.
NRC-03-79-158. 79/07/03. 6pp.

7908170126 Notification of contract execution: "Presentation of General & Refresher Courses in Concrete Technology & Codes," awarded to Portland Cement Association.
BAISDEN, L. Research Contracts Branch. FIN X-1175.
NRC-05-79-261. 79/07/24. 1p.

--7908170131 Contract: "Presentation of General & Refresher Courses in Concrete Technology & Codes," awarded to Portland Cement Association.
MORTON, K. V. Division of Contracts. FIN X-1175. NRC-05-79-261.
79/07/17. 3pp.

7908170291 Notification of contract execution, Mod 1 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Management."
LEBO, C. D. Technical Assistance Contracts Branch.
NRC-02-77-201-40. 79/07/24. 1p.

--7908170303 Mod 1 extending basic ordering period to 800630, to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Management."
DOUGHERTY, D. J. Division of Contracts. NRC-02-77-201-40.
79/07/25. 17pp.

7908200123 Notification of contract execution: "BWR Refill-Reflood Program Workscope," awarded to GE & Electric Power Research Inst.
MYNATT, W. A. Research Contracts Branch. NRC-04-79-184. 79/07/25.
1p.

--7908200125 Contract: "BWR Refill-Reflood Program Workscope" awarded to GE & Electric Power Research Inst.
MORTON, K. V. Research Contracts Branch. FIN-B-5677. 79/07/25.
180pp.

7908210185 Notification of contract execution: "TMI Special Inquiry Team," awarded to Sys Safety, Inc.
MORTON, K. V. Research Contracts Branch. FIN B-1560.
NRC-17-79-452. 79/08/01. 1p.

--7908210198 Contract: "TMI Special Inquiry Team," awarded to Sys Safety, Inc.
MORTON, K. V. Research Contracts Branch. NRC-17-79-452.
79/08/01. 10pp.

7908210294 Notification of contract execution: "TMI Special Inquiry Team," awarded to BC Doyle.
MORTON, K. V. Research Contracts Branch. FIN B-1560.
NRC-17-79-453. 79/07/31. 1p.

--7908210298 Contract: "TMI Special Inquiry Team," awarded to BC Doyle.
MORTON, K. V. Research Contracts Branch. FIN B-1560.
NRC-17-79-453. 79/08/04. 10pp.

7908220260 Notification of contract execution, Mod 4 to "Environ Survey of U Fuel Cycle." Contractor: NUS Corp.
LEBO, C. D. Technical Assistance Contracts Branch. FIN B-6145, B-9.
NRC-02-78-044. 79/08/14. 1p.

--7908220265 Mod 4, adding socioeconomics study to "Environ Survey of U Fuel Cycle."
DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN
B-6145-9. 79/08/14. 4pp.

7908220324 Notification of contract execution: "Review of Aeromagnetic Rept for Skagit Nuclear Power Plant," awarded to Phoenix Corp.
PERLMAN, J. Administrative Contracts Branch. B-6814.
NRC-03-79-156. 79/07/27. 1p.

--7908220330 Contract: "Review of Aeromagnetic Rept for Skagit Nuclear Plant," awarded to Phoenix Corp.
HARGETT, D. J. Division of Contracts. NRC-03-79-156. 79/07/31.
5pp.

7908220522 Notification of contract execution: "Extension of Skyshine II," awarded to Radiation Research Associates.
PERLMAN, J. Purchasing Section. FIN B-1199. NRC-03-79-159.
79/08/14. 1p.

--7908220533 Contract: "Extension of Skyshine II," awarded to Radiation Research Associates.
HARGETT, D. J. Purchasing Section. FIN B-1199. 79/08/14. 5pp.

7908220616 Notification of contract execution, Mod 5 to "JURIS Automatic Legal Research Sys," awarded to DOJ.
HAGAN, T. F. Administrative Contracts Branch. NRC-10-76-335.
79/08/07. 1p.

7908220618 Notification of contract execution, Mod 5 to "JURIS Automatic Legal Research Sys," awarded to DOJ.
HAGAN, T. F. Administrative Contracts Branch. NRC-10-76-335.
79/08/07. 1p.

--7908220642 Mod 5, changing agreement contract number from NRC-14-76-335 to NRC-10-76-335.
MATTIA, M. J. Administrative Contracts Branch. NRC-10-76-335.
79/07/27. 1p.

--7908220642 Mod 5, changing agreement contract number from NRC-14-76-335 to NRC-10-76-335.
MATTIA, M. J. Administrative Contracts Branch. NRC-10-76-335.
79/07/27. 1p.

7908220645 Notification of contract execution, Mod 4, revised copy. Prime contractor, Small Business Administration & subcontractor, Logical Technical Svc Corp.
HAGAN, T. F. Administrative Contracts Branch. FIN 31X200 409.
NRC-07-77-178. 79/06/19. 1p.

7908220672 Notification of contract execution, Mod 1 to "Alcohol & Drug Abuse Awareness Training for Managers." Contractor: Atlantic Counseling Inc.
PERLMAN, J. Administrative Contracts Branch. NRC-10-79-394.
79/07/27. 1p.

--7908220682 Mod 1, establishing method of partial payment to "Alcohol & Drug Abuse Awareness Training for Managers."
HARGETT, D. J. Division of Contracts. NRC-10-79-394. 79/07/31.
1p.

7908230081 Notification of contract execution: "Professional Secretary Development Program," awarded to Strayer College.
HOYLE, A. Administrative Contracts Branch. 31X0200 409.
NRC-10-79-392. 79/08/01. 1p.

--7908230091 Contract: "Professional Secretary Development Program," awarded to Strayer College.
PERLMAN, J. Division of Contracts. NRC-10-79-392. 79/08/01.
4pp.

7908230094 Notification of contract execution, Mod 2 to "Analysis & Advice on Nuclear Siting Legislative Reform." Contractor: 9 Warburg.
PERLMAN, J. Administrative Contracts Branch. B-1560 31X0200 709.
NRC-17-79-448. 79/07/27. 1p.

--7908230096 Mod 2, adding funds & expanding scope of work, to "Analysis & Advice on Nuclear Siting Legislative Reform."
HARGETT, D. J. Division of Contracts. NRC-17-79-448. 79/07/29.
1p.

7908230099 Notification of contract execution, Mod 33 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt." Contractor: none named.
LEBO, C. D. Administrative Contracts Branch. NRC-02-77-201.
79/06/04. 1p.

--7908230102 Mod 33, extending period of performance & updating provision, to "Technical Assistance in Development of Reg Framework for Nuclear Waste Mgt."
DOUGHERTY, D. J. Division of Contracts. NRC-02-77-201. 79/06/29.
2pp.

7908230101 Notification of contract execution, Mod 2 to "Development & Testing of Model for Fire Potential in Nuclear Power Plants." Contractor: Rensselaer Polytechnic Inst.
HAGEY, H. Research Contracts Branch. NRC-04-78-220. 79/08/14.
1p.

--7908230106 Mod 2, extending period of performance from 790531 to 790630, to "Development & Testing of Model for Fire Potential in Nuclear Power Plants."
MORTON, K. V. Research Contracts Branch. FIN-3-6302. 79/08/14.
2pp.

7908230124 Notification of contract execution: "Vol Reduction Techniques in Low Level Radioactive Waste Mgt." Contractor: Teknekron, Inc.
LEBO, C. D. Technical Assistance Contracts Branch. FIN B-6413-9.
NRC-02-79-024. 79/08/09. 1p.

--7908230156 Contract: "Vol Reduction Techniques in Low Level Radioactive Waste Mgt," awarded to Teknekron, Inc.
DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN
B-6413-9. 79/08/09. 17pp.

7908230136 Notification of contract execution: "Advisory Committee for Const During Adjudication," awarded to Shaw, Pittman, Potts & Troubridge.
MCNULTY, A. Division of Contracts. FIN B-1560. NRC-17 79-450.
79/08/09. 1p.

--7908230150 Contract "Advisory Committee for Const During Adjudication," awarded to Shaw, Pittman, Potts & Trowbridge.
HARGETT, D. J. Technical Assistance Contracts Branch. FIN B-1560. 79/08/15. 4pp.

7908230176 Notification of contract execution, Mod 6 to "Safeguards Suppl to GESMO." Contractor: R&D Associates.
SMITH, P. A. Technical Assistance Contracts Branch. FIN B-1465-7. AT(49-24)-023. 79/07/26. 1p.

--7908230182 Mod 6, deobligating funds to "Safeguards Suppl to GESMO."
DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN B-1465-7. 79/07/26. 1p.

7908230188 Notification of contract execution, Mod 5 to "Study of Chemical Toxicity of Low Level Wastes." Contractor: General Research Corp.
LEBO, C. D. Technical Assistance Contracts Branch. FIN-B-6127. 79/07/20. 1p.

--7908230195 Mod 5, expanding Task 2 draft rept, "Study of Chemical Toxicity of Low Level Wastes."
DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN B-6127. 79/08/13. 6pp.

7908230203 Notification of contract execution, Mod 2 to "Study of Methods for Estimating Parameter of Probability Distributions From Multi-Plant Component Failure Data."
HAGEY, H. Research Contracts Branch. FIN-B-5973. 79/08/09. 1p.

--7908230210 Mod 3, increasing funds & extending period of performance from 780930 to 790831, to "Study of Methods for Estimating Parameter of Probability Distributions From Multi-Plant Component Failure Data."
MORTON, K. V. Research Contracts Branch. FIN B-5973. 79/07/30. 4pp.

7908230215 Notification of contract execution, Mod 5 to "Technical Assistance to Support NRC Technical Personnel in Investigation & Evaluation of Incidents, Allegations & Reported Discrepancies." Contractor: Parameter, Inc.
BAISDEN, L. Technical Assistance Contracts Branch. FIN-A-4015. NRC-05-77-086. 79/08/13. 1p.

--7908230222 Mod 5 to "Technical Assistance to Support NRC Technical Personnel in Investigation & Evaluation of Incidents, Allegations & Reported Discrepancies."
MORTON, K. V. Research Contracts Branch. FIN A-4015. 79/08/13. 1p.

7908270294 Notification of contract execution, Mod 2 to "Seismicity & Tectonic Relationship for Upper Great Lakes Precambrian Shield Province." Contractor: MI Technological Univ.
HAGEY, H. Administrative Contracts Branch. FIN B-6174. NRC-04-77-112. 79/07/25. 1p.

--7908270305 Mod 2, changing incremental funding, to "Seismicity & Tectonic Relationship for Upper Great Lakes Precambrian Shield Province."
MORTON, K. V. Administrative Contracts Branch. NRC-04-77-112. 79/06/28. 1p.

7908270313 Notification of contract execution, Mod 4 to "Seismicity & Tectonic Relationships for Upper Great Lakes Precambrian Shield Province." Contractor: Univ of MN.
HAGEY, H. Administrative Contracts Branch. FIN B-5952. NRC-04-76-289. 79/07/25. 1p.

--7908270318 Mod 4, extending period of performance at no cost, to "Seismicity & Tectonic Relationships for Upper Great Lakes Precambrian Shield Province."
HAGEY, H. Division of Contracts. NRC-04-76-289. 79/07/25. 2pp.

7908270320 Notification of contract execution, Mod 1 to "Radiation Monitoring Svcs." Contractor: Radiation Mgt Corp.
MEDROW, L. K. Administrative Contracts Branch. FIN B-1004. NRC-05-79-265. 79/08/07. 1p.

--7908270322 Mod 1, extending duration of contract, increasing contract ceiling & exercising option to purchase TLD reader & printer, to "Radiation Monitoring Svcs."
MATTIA, M. J. Division of Contracts. FIN B-1004. NRC-05-79-265. 79/07/30. 2pp.

7908270357 Notification of contract execution, Mod 2 to "Solubility of Uraninite & Migration of Fission Products Released From Spent Fuel Matls." Contractor: Harvard Univ.
HAGEY, H. Administrative Contracts Branch. FIN B-6662. NRC-04-78-265. 79/08/08. 1p.

--7908270362 Mod 2, extending at no cost "Solubility of Uraninite & Migration of Fission Products Released From Spent Fuel Matls."
MORTON, K. V. Division of Contracts. NRC-04-78-265. 79/08/08. 2pp.

7908280072 Notification of contract execution, Mod 2 to "Lab Simulation of Tornado Wind Effects on Structures." Contractor: Univ of OK.
HAGEY, H. Administrative Contracts Branch. FIN B-6241. NRC-04-78-207. 79/07/20. 1p.

--7908280077 Mod 2, extending contract period at no cost, to "Lab Simulation of Tornado Wind Effects on Structures."
MORTON, K. V. Research Contracts Branch. NRC-04-78-207. 79/07/31. 2pp.

7908280085 Notification of contract execution, Mod 4 to "Critical Experiments, Measurements & Analysis to Establish Crack Arrest Methodology for Nuclear Pressure Vessel Steels." Contractor: Battelle Columbus Labs.
MYNATT, W. A. Administrative Contracts Branch. FIN A-4046. NRC-04-76-293. 79/07/31. 1p.

--7908280093 Mod 6, adding work & funding & extending term, to "Critical Experiments, Measurements & Analysis to Establish Crack Arrest Methodology for Nuclear Pressure Vessel Steels."
MORTON, K. V. Research Contracts Branch. NRC-04-76-293. 79/07/31. 2pp.

7908290432 Notification of contract execution, Mod 1 to "Investigation Program at Maxey Flats Radioactive Waste Burial Facility."
MYNATT, W. A. Administrative Contracts Branch. 79/07/30. 1p.

--7908290442 Mod 1, adding work & funds, to "Investigation Program at Maxey Flats Radioactive Waste Burial Facility."
MARTON, K. V. Division of Contracts. FIN B-6192. NRC-04078-259. 79/08/03. 2pp.

7908290467 Notification of contract execution, Mod 6 to "Institutional Radioactive Wastes." Contractor: Univ of MD.
HAGEY, H. Administrative Contracts Branch. 79/08/08. 1p.

--7908290471 Mod 6, extending at no cost "Institutional Radioactive Wastes."
MORTON, K. V. Division of Contracts. NRC-04-76-344. 79/08/08. 2pp.

7908290638 Notification of contract execution, Mod 2 to "Research Study Entitled 'Study of Regional Tectonics & Seismicity For IA.'" Contractor: IA Geological Survey.
WOLLETT, S. A. Administrative Contracts Branch. FIN B-6312. NRC-04-78-228. 79/08/03. 1p.

--7908290647 Mod 2, adding funds & scope to second year of five-year program, to "Research Study Entitled 'Study of Regional Tectonics & Seismicity For IA.'"
MORTON, K. V. Division of Contracts. NRC-04-78-228. 79/07/01. 2pp.

7908290662 Notification of contract execution, Mod 26 to "Tech Assistance in Development of Regulatory Framework for Nuclear Waste Mgt." Contractor not listed.
LEBO, C. D. Administrative Contracts Branch. NRC-02-77-201-26. 79/06/04. 1p.

--7908290686 Mod 26, extending period of performance & updating provision, to "Tech Assistance in Development of Regulatory Framework for Nuclear Waste Mgt."
DOUGHERTY, D. J. Division of Contracts. NRC-02-77-201. 79/07/31. 2pp.

7908290694 Notification of contract execution, Mod 7 to "Strength & Ductility of Irradiated Zircaloy Cladding." Contractor: Battelle Columbus Labs.
MYNATT, W. A. Administrative Contracts Branch. FIN A-4068. NRC-04-76-293. 79/08/02. 1p.

--7908290699 Mod 7, extending no-fund term, to "Strength & Ductility of Irradiated Zircaloy Cladding."
MORTON, K. V. Division of Contracts. FIN A-4068. NRC-04-76-293. 79/08/06. 1p.

7908290712 Notification of contract execution, Mod 1 to "Scoping Study, Spent Fuel Transport Accidents" Contractor: Science Applications, Inc.
WOLLETT, S. A. Administrative Contracts Branch. FIN B 5790. NRC-04-78-199. 79/07/25. 1p.

--7908290719 Mod 1 adding funds to cover overrun, to "Scoping Study, Spent Fuel Transport Accidents."
MORTON, K. V. Division of Contracts. FIN B-5790. NRC-04-78-199. 79/07/25. 1p.

7908300611 Notification of contract execution: "Production of Source Document Microfiching & Duplicates," awarded to Microtech Industries, Inc.
HAGAN, T. I. Administrative Contracts Branch. NRC-10-79-651. 79/08/03. 1p.

--7908300615 Contract: "Production of Source Document Microfiching & Duplicates" awarded to Microtech Industries, Inc.
MATTIA, M. J. Division of Contracts. NRC-10-79-651. 79/08/03. 19pp.

7908310130 Notification of contract execution: "Advisory Committee for Const During Adjudication," awarded to Environ Policy Institute.
LITTLE, M. Administrative Contracts Branch. FIN B-1560. 79/08/07. 1p.

--7908310135 Contract: "Advisory Committee for Const During Adjudication," awarded to Environ Policy Institute.
HARGETT, D. J. Administrative Contracts Branch. FIN B-1560. 79/08/09. 4pp.

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

7907310565 Responds to FOIA request for documents re facility & applications XR-120, XCOM-13, & XSNM-1471.
FELTON, J. M. Division of Rules and Records. 79/07/06. 3pp.

7907310599 Ack request for licensing expert to join IAEA team evaluating PSAR for two Westinghouse reactors for mid-June. Senior staff member not available.
CASE, E. G. Office of Nuclear Reactor Regulation. 77/05/24. 1p.

7908030407 Responds to FOIA request for Science Applications, Inc study on safeguards of high level waste repositories.
FELTON, J. M. Division of Rules and Records. 79/07/26. 1p.

7908030411 FOIA request for Science Applications Inc study on safeguards of high level waste repositories & any info utilized by NRC re study.
COCHRAN, T. B. Natural Resources Defense Council. 79/07/06. 1p.

7908030479 Forwards responses to NRDC 790531 discovery request.
NEHEMIAS, J. V. Division of Site Safety & Environmental Analysis. 79/06/13. 4pp.

7908030442 FOIA request for documents required for development of stds related to protective coatings for use in nuclear applications.
PUSCHEL, M. A. Consumers Power Co. PUSC 29-79. 79/06/27. 1p.

7908030445 Responds to FOIA request for S Levine memo to DR Denton re encl request for research on post-LOCA degradation effects & combustible gas generation rates for matls inside containment.
FELTON, J. M. Division of Rules and Records. 79/08/01. 1p.

7908030449 FOIA request for access to SECY-77-601A, "Proposed License to Export Low Enriched U to Brazil, XSNM-909," & any other documents re US involvement in Brazilian nuclear energy programs.
MAREK, K. Center for Development Policy. 79/07/10. 2pp.

7908030451 FOIA request for documents re consequences of nuclear plants meltdown on rivers & effects of contamination of river sediments w/radionuclides released from nuclear power plants.
JOHNSON, B. League of Women Voters of Rockford, IL. 79/06/28. 1p.

7908030453 Responds to FOIA request for documents re US involvement in Brazilian nuclear energy program & documents re XSNM-909. Some documents originated by other agencies have been referred for review response. NRC review not complete.
FELTON, J. M. Division of Rules and Records. 79/08/02. 1p.

7908030457 FOIA request for all nuclear matl transaction repts & all statements of tritium inventory filed by American Atomics Corp between Jan 1975 & present.
SWICK, C. B. Environmental Policy Center. 79/06/20. 1p.

7908030458 Responds to FOIA request for records re consequences of nuclear plant meltdown on rivers & effects of contamination of river sediments w/radionuclides released from nuclear power plants.
FELTON, J. M. Division of Rules and Records. 79/07/26. 2pp.

--7908030464 Discusses review of renewal proposal & annual rept from United Workers re distribution coefficients of radionuclides in marine & fresh waters. Forwards NRC models for evaluating transport of radionuclides in groundwater.
ECKERMAN, K. F. Division of Engineering Standards. 78/07/27. 21pp.

7908030460 Responds to FOIA request for documents relating to tritium inventory filed by American Atomic Corp. Forwards computer printout of American Atomic transfers & receipt of tritium, 1975 to present, & AEC matl status repts, 75701-790401.
FELTON, J. M. Division of Rules and Records. 79/07/21. 125pp.

7908030467 Responds to FOIA request for access to NRC travel expenditures for FY78 budgetary allotment to sponsor & attend conferences & travel expenditures.
FELTON, J. M. Division of Rules and Records. 79/07/26. 12pp.

7908030473 Responds to FOIA request for documents needed to develop stds re protective coatings for use in nuclear applications. Forwards draft interim positions re environ qualifications of electrical equipment, dtd 790611.
FELTON, J. M. Division of Rules and Records. 79/07/20. 1p.

--7908030480 Forwards draft 3 interim positions re environ qualification of electrical equipment. Comments &/or concurrence due by 790622.
* Electric, Instrumentation & Control Systems Branch. 79/06/11. 2pp.

--7908030485 Draft 3 of interim staff position on environ qualification of safety-related electrical equipment. Rept incorporates comments received on draft 2.
* Electric, Instrumentation & Control Systems Branch. 79/06/11. 95pp.

7908060047 FOIA request for records maintained by NRC re loan guarantees authorized & issued pursuant to Defense Production Act, Executive Order 10480 & Regulation V of Federal Reserve Sys.
CONWAY, R. J. Patton, Boggs & Blow. 79/07/09. 3pp.

7908060055 Responds to FOIA request for records re guarantees for loans per Regulation V, Federal Reserve Sys.
FELTON, J. M. Division of Rules and Records. 79/07/24. 1p.

7908060061 FOIA request for info re number, purpose & cost of consultants hired by NRC.
COFFMAN, W. A. Affiliation Unknown. 79/06/14. 1p.

7908060066 Responds to FOIA request for info re number, purpose & cost of consultants hired by NRC.
FELTON, J. M. Division of Rules and Records. 79/07/24. 1p.

7908060081 Responds to FOIA request for listing of out-of-town trips taken; explanation of business conducted & trip duration by each NRC Commissioner & NRC staffers from 780530 to 790101.
FELTON, J. M. Division of Rules and Records. 79/07/19. 1p.

7908060083 Responds to FOIA request for info re nuclear power & function of NRC.
FELTON, J. M. Division of Rules and Records. 79/08/02. 1p.

7908060087 FOIA request for info re nuclear power & function of NRC.
GEE, L. S. Affiliation Unknown. 79/07/18. 1p.

7908060090 FOIA request for barrier penetration database on saboteurs in nuclear power facilities.
LOFTUS, J. Stanford Univ. 79/07/25. 1p.

7908060091 Responds to FOIA request for barrier penetration database re saboteurs in nuclear power facilities.
FELTON, J. M. Division of Rules and Records. 79/08/03. 1p.

7908060098 FOIA request for Contract NRC-03-79-126, "Evaluation of Matl Interactions for Advanced Reactor Sys," contractor proposal & source evaluation board rept.
WEAVER, E. A. Westinghouse Electric Corp. 79/07/06. 1p.

7908060100 Responds to FOIA request for Contract NRC-03-79-126, "Evaluation of Matl Interactions for Advanced Reactor Sys," contractor proposal & source evaluation board rept.
FELTON, J. M. Division of Rules and Records. 79/07/30. 1p.

7908080110 Submits addl info in response to 770726 ltr re FOIA request for all correspondence prepared by JH Conran. Documents listed in App A will be placed in PDR. Portions of certain documents will be withheld.
FELTON, J. M. Division of Rules and Records. 79/07/11. 4pp.

NONDOCKETED ITEMS

7908080118 Responds to 770719 ltr re FOIA request for correspondence prepared by JH Conran. Documents listed in App A will be placed in PDR. Certain documents in App B are withheld.
FELTON, J. M. Division of Rules and Records. 79/07/11. 3pp.

7908080141 Notification of 790628 meeting w/licensees of BWR plants in Bethesda, MD to discuss review of operating BWRs as related to TMI-2 accident.
KANE, W. F. Standardization Branch. 79/06/14. 2pp.

7908080471 FOIA request for insp performed in Mar & Apr 1979 of Baystate Medical Ctr in Springfield, MA. Licenses 29-01412-' & 20-01412-05.
SYED, A. Affiliation Unknown. 79/07/02. 1p.

7908080482 Responds to FOIA request for documents re insp performed in Mar & Apr 1979 of Baystate Medical Ctr, Springfield, MA. Forwards 790402 & 790510 McClintock ltr to ctr & 790411 Brahmaver ltr to McClintock.
FELTON, J. M. Division of Rules and Records. 79/08/02. 1p.

--7908080505 Forwards IE Insp Rept on 790306 & notice of violation. Insp rept not enclosed.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 79/04/02. 2pp.

--7908080566 Notice of violation from insp on 790306.
#. Region 1, Philadelphia, Office of the Director. 79/08/03. 2pp.

--7908080577 Responds to 790402 ltr & App A. Submits explanations & corrective actions for each item in notice of violation re disposal of shipping containers, receipt of radioactive matl, radiation area & records. Forwards 790413 & 790307 ltr.
ZU'81, S. M. Baystate Medical Center MA/SP. 79/04/11. 14pp.

7908080585 FOIA request for documents of SH Hanauer designated as "Nugget File," not previously supplied to UCS.
WEISS, E. R. Sheldon, Harmon, Roisman & Weiss. 79/04/25. 1p.

7908080593 Responds to FOIA request for documents in SH Hanauer "Nugget File." Advises that "Summary of Meeting w/C-E on Safety-Related R&D" by GL Bennett does not contain proprietary info.
FELTON, J. M. Division of Rules and Records. 79/07/24. 2pp.

--7908080600 Forwards summary of 781031 meeting w/C-E in Windsor, CT to discuss safety-related R&D.
BENNETT, G. L. Research Support Branch. 78/12/28. 11pp.

7908080610 FOIA request for Srightsen 790423 ltr re as' ,nments of threat levels for safeguarding fuel facilities & power reactors & any NRC-generated correspondence concerning issues raised by Brightsen.
COCHRAN, T. B. Natural Resources Defense Council. 79/07/06. 1p.

7908080618 Responds to FOIA request for Brightsen 790423 ltr re assignments of threat levels for safeguarding fuel facilities & power reactors & all correspondence generated by NRC re Brightsen issues.
FELTON, J. M. Division of Rules and Records. 79/07/30. 2pp.

--7908080626 Forwards Brightsen 770620 memo to Director of Div of Safeguards documenting that different NRC offices have different approaches to safeguards regulations.
BRIGHTSEN, R. A. Division of Safeguards. 79/04/23. 3pp.

--7908080635 Discusses consequences of NRC failure to resolve problem of dispersion of responsibility & authority for safeguards policies, objectives & criteria among NRC offices.
BRIGHTSEN, R. A. Division of Safeguards. 77/06/20. 3pp.

--7908080649 Addresses 790411 initial discussion of upgrade rule. Brightsen 790326 memo argues for one level of design threats.
KENNEKE, A. Office of Policy Evaluations. 79/04/10. 1p.

--7908080658 Expresses gratitude for 790423 ltr. Assures that issues raised in ltr are identical to concerns of NRC.
HENDRIE, J. M. Commission. 79/05/03. 1p.

7908080666 FOIA request for notice of violation ltrs that include items of noncompliance for CA companies or installations that handle radioactive matls.
THOMPSON, T. Community Supported Television LA, California. 79/06/13. 1p.

7908080672 Confirms that requested info re notice of violations was provided in JG Hanchett 790709 ltr. Action on request completed.
FELTON, J. M. Office of Administration. 79/07/19. 1p.

7908080687 Notifies that permission from Dept of State, Defense Intelligence Agency & CIA to release info has been obtained. List of documents encl.
FELTON, J. M. Division of Rules and Records. NRDC/TBC/79-14. 79/07/20. 2pp.

7908080697 Ack receipt of 790619 ltr re documents which originated in Dept of State, Defense Intelligence Agency & CIA. Requests records identifying title, author, date & classification of documents.
SNYDER, L. Natural Resources Defense Council. NRDC/TBL/79-14. 79/06/21. 1p.

7908080723 Responds to appeal of FOIA denial of JL Kelly 750110 memo to H Shapar re CP for nuclear reactor. Document withheld (ref FOIA Exemption 5).
CHILK, S. J. Office of the Secretary of the Commission. 79/07/12. 2pp.

7908080729 Appeals 790316 decision to withhold JL Kelly 750110 memo to H Shapar as predecisional in nature.
HUNGERFORD, M. Syracuse Univ., College of Law. 79/04/12. 1p.

7908080729 Appeals 790316 decision to withhold JL Kelly 750110 memo to H Shapar as predecisional in nature.
HUNGERFORD, M. Syracuse Univ., College of Law. 79/04/12. 1p.

7908080740 Responds to FOIA request for documents indexed or maintained under name of K Silkwood. Forwards list of documents available for public insp. Documents 4, 27, 42, 61 & 86 withheld (ref FOIA Exemption 6).
FELTON, J. M. Division of Rules and Records. 79/07/24. 8pp.

7908080745 FOIA request for all documents indexed or maintained under name of K Silkwood.
RAYMOND, J., GLASS, M. California, Univ. of, Santa Barbara. 79/06/29. 1p.

7908080750 Responds to FOIA request for records re NRC administration of FOIA. Forwards list of requested documents.
FELTON, J. M. Division of Rules and Records. 79/07/24. 3pp.

7908080751 FOIA request for records re NRC administration of FOIA.
BONINE, J. E. Oregon, Univ. of, School of Law. 79/06/26. 2pp.

7908090096 FOIA request for answers to questions re dry waste stored at naval air station at Point Mugu, CA.
CROSBY, J. Ventura Safe Energy Council. 79/07/05. 1p.

7908090111 Responds to FOIA request for answers to questions re waste matl stored at naval air station at Point Mugu, CA.
FELTON, J. M. Division of Rules and Records. 79/08/02. 1p.

7908090120 FOIA request for documents re development or promulgation of 10CFR140, App A, form of nuclear energy liability policy for facilities.
BRYSON, J. M. Steptoe & Johnson. NRC. 79/06/14. 2pp.

7908090130 Responds to FOIA request for documents re development or promulgation of 10CFR140, App A, form of nuclear energy liability policy for facilities. Request payment for reproducing requested records.
FELTON, J. M. Division of Rules and Records. 79/07/18. 2pp.

7908090140 FOIA request for info re underwater atomic test called "Operation Wigwam."
BROWN, E. C. Brown & Bettencourt. 79/07/23. 1p.

7908090149 Responds to FOIA request for info re 1955 underwater atomic test, "Operation Wigwam." Suggests contacting DOE or DOD for info.
FELTON, J. M. Division of Rules and Records. 79/08/01. 1p.

7908090176 Responds to FOIA request for listing of NRC employees & appointees w/rating of GS-15 & above, job titles & job descriptions.
FELTON, J. M. Division of Rules and Records. 79/07/26. 1p.

7908090178 FOIA request for Form 171, listing GS-15 & above employees & appointees in NRC.
PISANESCHI, J. Americans for Nuclear Energy. 79/07/09. 1p.

7908100505 Requests documents re radiological emergency response plans for nuclear power plants, including info re 10CFR50, App E. NUREG-0396 & NUREG-75/111.
BURT, L. Massachusetts, State of. 79/06/15. 3pp.

7908100507 Responds to 790615 ltr re radiological emergency response plans for nuclear power plants. Forwards partial response. Review of remaining documents has not been completed.
FELTON, J. M. Division of Rules and Records. 79/07/12. 1p.

7908140517 Responds to FOIA request for documents relating to possible const of nuclear plants in next 15 yrs in VA or WV by Appalachian Power Co or GE. App A lists documents encl.
FELTON, J. M. Division of Rules and Records. 79/08/08. 2pp.

--7908140521 Agreement between VA State Water Control Board & NRC per Federal Water Pollution Control Act Amends of 1972.
GOSSICK, L. V. Office of the Executive Director for Operations.
DAVIS, R. V. Virginia, State of. 77/09/07. 5pp.

--7908140526 Forwards press release re program to investigate possibility of bldg nuclear plant in central VA.
TILLINGHAST, J. American Electric Power Co., Inc. 78/07/25. 5pp.

--7908140531 Summary of 781102 telcon w/S Miliati of American Electric Power re Central VA Units 1 & 2.
HARLESS, B. L. Environmental Projects Branch 2. 78/11/07. 2pp.

7908140534 FOIA request for documents relating to possible const of nuclear plants in next 15 yrs in VA or WV by Appalachian Power Co or GE.
MCMAHAN, J. Affiliation Unknown. 79/07/03. 2pp.

7908140709 Responds to 790403 appeal of JM Felton 790313 initial partial denial of 770525 FOIA request for documents approved by Task Force on Allegations. Forwards requested matl. Info partially withheld (ref FOIA Exemptions 1 & 3).
GOSSICK, L. V. Office of the Executive Director for Operations. 79/08/13. 1p.

7908140709 Responds to 790403 appeal of JM Felton 790313 initial partial denial of 770525 FOIA request for documents approved by Task Force on Allegations. Forwards requested matl. Info partially withheld (ref FOIA Exemptions 1 & 3).
GOSSICK, L. V. Office of the Executive Director for Operations. 79/08/13. 1p.

7908140716 Appeals FOIA denial re matl withheld in JM Felton 790313 ltr. Does not appeal statistical matl or other numerical data possibly withheld.
KRANISH, A. Trends Publishing, Inc. 79/04/03. 1p.

7908140716 Appeals FOIA denial re matl withheld in JM Felton 790313 ltr. Does not appeal statistical matl or other numerical data possibly withheld.
KRANISH, A. Trends Publishing, Inc. 79/04/03. 1p.

7908140720 Responds to 790702 FOIA request for info re nuclear energy & engineering. Forwards documents re value, hazards & reprocessing of plutonium.
FELTON, J. M. Division of Rules and Records. 79/08/08. 3pp.

7908140735 FOIA request for info dealing w/nuclear energy & engineering.
SKINNER, L. W. Affiliation Unknown. 79/07/02. 2pp.

7908140776 Responds to FOIA request for info re TMI-2. Forwards updated rept: "Title List of Publicly Available Documents TMI-2." W/o encl.
FELTON, J. M. Division of Rules and Records. 79/08/10. 1p.

7908140779 FOIA request for all available info re TMI-2.
ELKINS, B. T. Affiliation Unknown. 79/05/08. 1p.

7908140809 Responds to FOIA request for info re TMI-2. Forwards updated rept: "Title List of Publicly Available Documents, TMI-2." W/o encl.
FELTON, J. M. Division of Rules and Records. 79/08/10. 1p.

7908140811 FOIA request for all info relevant to TMI.
RUBY, R. The Sun Baltimore, MD. 79/04/10. 1p.

7908140824 FOIA request for correspondence between NRC & Atomic Energy Commission re delegation of authority for nuclear matters & conditions concerning exercise of power.
GIRARD, E. K. Emojean Kerber Girard. 79/07/16. 1p.

7908140829 Responds to 790716 FOIA request for correspondence between NRC & AZ Atomic Energy Commission re delegation of authority on nuclear matters. Forwards three relevant documents.
FELTON, J. M. Division of Rules and Records. 79/08/08. 2pp.

--7908140832 "AZ Program for Control of Ionizing Radiation," prepared by State of AZ Atomic Energy Commission. Includes proposed agreement between AEC & State of AZ re delegation of authority on nuclear power.
* Arizona, State of. 67/01/31. 162pp.

--7908140834 Requests agreement between AEC & State of AZ to delegate authority for regulation of sources of ionizing radiation per Atomic Energy Act of 1954, Section 274. Assumption of authority will further nuclear industry in state.
WILLIAMS, J. Arizona, State of. 67/01/20. 2pp.

--7908140836 Regulations of AZ Atomic Energy Commission effective 770526.
* Arizona, State of. 77/05/26. 170pp.

7908140835 FOIA requests for all matl relevant to TMI-2 incident in preparation of rule increase proceedings.
FILOCCO, N. I. Waters, McPherson, Hudzin & McNeill. 79/06/06. 2pp.

7908140840 Responds to FOIA request for info re TMI-2. Forwards updated rept: "Title List of Publicly Available Documents, TMI-2." W/o encl.
FELTON, J. M. Division of Rules and Records. 79/08/10. 1p.

7908150032 Responds to 790718 FOIA request for all info re People Against Nuclear Power. NRC has no files indexed under that name.
FELTON, J. M. Division of Rules and Records. 79/08/09. 1p.

--7908150035 FOIA requests for all info re People Against Nuclear Power. Affidavit encl.
BELIN, A. Center for Law in the Public Interest. 79/07/18. 2pp.

7908150039 Responds to 790718 FOIA request for all info re Project Survival. NRC has no files indexed under that name.
FELTON, J. M. Division of Rules and Records. 79/08/09. 1p.

--7908150046 FOIA requests for all info re Project Survival. Ltr from Project Survival dtd 781026 authorizing access to relevant matl encl.
BELIN, A. Center for Law in the Public Interest. 79/07/18. 2pp.

7908150058 Responds to 790531 FOIA request for all documents pertaining to importation & disposal of radwaste from foreign countries. Relevant documents listed in app. W/DOE Info Bulletin "DOE Announces New Spent Nuclear Fuel Policy."
FELTON, J. M. Division of Rules and Records. 79/08/08. 5pp.

--7908150065 FOIA requests for all documents re importation & disposal of radwaste from foreign countries.
JENKS, M. C. Affiliation Unknown. 79/05/31. 4pp.

7908150071 Responds to 790709 FOIA request for info as of 790615 re FY79 budget on training & travel for NRC Ofcs of Administration, IE & Nuclear Regulatory Research. Relevant citations encl.
FELTON, J. M. Division of Rules and Records. 79/08/07. 3pp.

--7908150078 FOIA request for info as of 790615 re FY79 budget on training & travel for NRC Ofcs of Administration, IE & Nuclear Regulatory Research.
SIMPSON, G. H. Affiliation Unknown. 79/07/09. 1p.

7908150083 FOIA request for matl prepared by foreign govts making assessments, summaries & recommendations re TMI-2 incident.
WEISS, E. R. Sheldon, Harmon, Roisman & Weiss. 79/07/05. 1p.

7908150089 Responds to FOIA request for matl prepared by foreign govts re TMI-2 incident. Documents will be placed in docket file as translations become available.
FELTON, J. M. Division of Rules and Records. 79/08/10. 2pp.

7908150411 Responds to 790712 FOIA request for Pages 1-7 of RFP RS-NRR-79-134, "Tearing Stability Analysis for LWR Piping." Info forwarded.
FELTON, J. M. Division of Rules and Records. 79/08/09. 1p.

7908150414 FOIA request for Pages 1-7 of RFP 79-134, "Tearing Stability Analysis for LWR Piping."
PIERCE, S. M. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/12. 1p.

7908150416 Responds to 790615 FOIA request for technical proposal submitted by Boeing Computer Svcs in response to contract solicitation NRC RFP RS-NMS-79-028.
FELTON, J. M. Division of Rules and Records. 79/08/09. 1p.

7908150423 FOIA request for technical proposal submitted by Boeing Computer Svc in response to NRC RFP RS RS-NMS-79-028.
FINDLEY, D. E. Science Applications, Inc. 79/06/15. 1p.

7908150429 Responds to 790723 FOIA request all info re TMI-2 incident. Rept, "Title List of Publicly Available Documents, TMI-2," identifies relevant info.
FELTON, J. M. Division of Rules and Records. 79/08/09. 1p.

7908150433 FOIA requests for all info re TMI-2 incident.
BLODGET, T. Affiliation Unknown. 79/07/23. 1p.

7908150440 FOIA request for all info re TMI-2 incident.
OSTI, A. P. Pfizer, Inc. 79/04/12. 1p.

7908150448 Responds to FIOA 790731 request for first & second quarter repts on exposure of station personnel in excess of 3 rem/quarter limit. NRC does not publish quarterly repts dealing w/overexposures. Annual rept on exposures encl.
FELTON, J. M. Division of Rules and Records. 79/08/10. 1p.

7908150453 FOIA request for first & second quarter repts on exposure of station personnel in excess of 3 rem/quarter limit.
COLEMAN, A. C. Affiliation Unknown. 79/07/31. 1p.

7908160305 Responds to FOIA request for all records relating to or mentioning Abalone Alliance. NRC has no files indexed or maintained under Abalone Alliance.
FELTON, J. M. Division of Rules and Records. 79/08/06. 1p.

7908160307 FOIA request for all documents relating to or mentioning Abalone Alliance.
BEL[illegible] Center for Law in the Public Interest. 79/07/25. 1p.

7908160386 FOIA request for info re NRC word processing & duplicating equipment & svcs.
TAYLOR, P. Productivity Study Board. 79/07/30. 1p.

7908160386 FOIA request for info re NRC word processing & duplicating equipment & svcs.
TAYLOR, P. Productivity Study Board. 79/07/30. 1p.

7908160394 Responds to FOIA request re NRC word processing & duplicating equipment & svcs. Request has been forwarded to NRC ofc responsible for purchasing word processing & duplicating equipment. FOIA applies to requests for records.
FELTON, J. M. Division of Rules and Records. 79/07/30. 1p.

7908160394 Responds to FOIA request re NRC word processing & duplicating equipment & svcs. Request has been forwarded to NRC ofc responsible for purchasing word processing & duplicating equipment. FOIA applies to requests for records.
FELTON, J. M. Division of Rules and Records. 79/07/30. 1p.

7908160400 FOIA request for copy of winning contract proposal re NRC solicitation RS-OSD-79-002.
LANDE, J. R. Gray, Plant, Mooty, Mooty & Bennett. 79/07/0[illegible] 1p.

7908160402 Responds to FOIA request for copy of winning proposal re NRC solicitation RS-OSD-79-002. Contract has not yet been awarded & no documents available relative to request.
FELTON, J. M. Division of Rules and Records. 79/08/06. 1p.

7908160404 Responds to FOIA request to be placed on mailing list for NRC publications. FOIA does not apply to records which are to be created at future date. NRC does not have mailing list for distribution of publications.
FELTON, J. M. Division of Rules and Records. 79/08/06. 1p.

7908160407 FOIA request to be placed on mailing list for NRC publications.
* Citizens for Non Nuclear Future. 79/07/09. 1p.

7908160410 Responds to FOIA request for access to documents relating to individuals or groups expressing opposition to govt or util energy policies or practices. NRC has no documents re request.
FELTON, J. M. Division of Rules and Records. 79/08/06. 1p.

7908160416 FOIA request for access to documents relating to individuals or groups who have expressed opposition to govt or util energy policies or practices.
NOVIK, J. D. American Civil Liberties Union. 79/05/04. 2pp.

7908170077 FOIA request for proposal by Science Applications, Inc which was submitted to NRC in response to RFP RS-RES-78-193 & RS-RES-78-193, Amend 1.
COHEN, M. D. Mathematical Applications, Inc. M-9179. 79/04/04. 1p.

7908170083 Responds to FOIA request for copy of winning contract re NRC solicitation RS-OSD-79-002. Contract has not yet been awarded therefore there are no documents in existence.
FELTON, J. M. Division of Rules and Records. 79/08/06. 1p.

7908170085 FOIA request for info re NRC solicitation RS-OSD-79-002.
PYDYCH, J. National Evaluation Systems, Inc. 79/07/05. 1p.

7908170445 FOIA request for documents exchanged between AEC/NRC & Italian govt re probabilistic techniques for reactor safety evaluation since 1974.
HUBBARD, R. B. MHB Technical Associates. 79/06/07. 2pp.

7908170450 Responds to FOIA request for documents exchanged between AEC/NRC & Italian govt re probabilistic techniques for reactor safety. Forwards ltr from SH Hanauer to R Galvagni. Info partially withheld (ref FOIA Exemption 4).
FELTON, J. M. Division of Rules and Records. 79/08/06. 2pp.

--7908170457 Summary of 750527&30 discussions w/Italian officials re method to apply probabilitic techniques to safety evaluation. Scheme not worth any effort by NRC. Proprietery notes encl. Info partially withheld (ref FOIA Exemption 4).
HANAUER, S. H. Office of the Executive Director for Operations. 75/06/09. 2pp.

--7908170462 Ack receipt of 750915 ltr re reactor safety & regulation. Comments on "as se[illegible]as technically achievable (ASATA)." Objects to concept since provides no guidance to designer.
HANAUER, S. H. Office of the Executive Director for Operations. 75/12/16. 3pp.

--7908170469 "Safety Analysis Semiprobabilistic Methodology & Its Applicative Development."
FELICETTI, F., GALVAGNI, R., ZALPPELLINI, G. Italy. 79/08/17. 65pp.

7908170609 FOIA request for copy of rules & regulations used in preparation of strip charts, copies of strip charts prepared for transport of SNM by NMSS & supporting documents identifying safe havens.
PETERSON, J. American Friends Service Committee. 79/06/14. 1p.

7908170621 Responds to FOIA request re strip charts & safe havens. App A lists documents encl. App B lists documents which contain info re procedures for safeguarding SNM. Info partially withheld (ref FOIA Exemption 4).
FELTON, J. M. Division of Rules and Records. 79/08/03. 4pp.

7908200150 FOIA request for info re radioactive fallout from atmospheric testing during yrs 1950-70.
POHLER, P. E. Affiliation Unknown. 79/08/10. 2[illegible]

7908200164 Responds to FOIA request for info re radioactive fallout from atmospheric testing during yrs 1950-70. NRC has no documents re request. Suggests that DOE or DOD may have documents requested.
FELTON, J. M. Division of Rules and Records. 79/08/14. 1p.

7908200167 FOIA request for copy of NRC study re potential hazards to consumers & to environ resulting from use & disposal of ionization type smoke detectors.
SCOTT, B. Affiliation Unknown. 79/07/07. 1p.

7908200171 Responds to FOIA request for copy of study re potential hazards of ionization type smoke detectors. App A lists documents available in PDR re request.
FELTON, J. M. Division of Rules and Records. 79/08/13. 19pp.

7908200251 FOIA request for ltrs & documents re NRC decision to recommend to Dept of Commerce that export license be granted to Westinghouse.
SPODAK, W. M. Westinghouse Electric Corp. 79/06/26. 1p.

7908200255 Responds to FOIA request for documents re NRC decision to recommend to Dept of Commerce that export license be granted to Westinghouse. Forwards J Shea 790615 ltr to Dept of Commerce & 790611 SECY-79-382.
FELTON, J. M. Division of Rules and Records. 79/08/14. 1p.

--7908200260 Recommends that Dept of Commerce action on Case 383135 be deferred. Approval of export application would imply favorable NRC action & would compromise health & safety.
SHEA, J. R. Office of International Programs. 79/06/15. 2pp.

--7908200265 SECY-79-382
Requests NRC views on proposed Westinghouse export of turbine generators to Philippines.
SHEA, J. R. Office of International Programs. 79/06/11. 4pp.

--7908200317 Application by Westinghouse for license to export turbine generator sets, steam turbines, heat exchangers & heat exchanger-type condensors to Philippines.
DUFFY, E. L. Westinghouse Electric Corp. ZEHK-10355. 79/02/21. 5pp.

7908200341 FOIA request for documents cited in 790611 memo from S Eilperin to NRC entitled, "DC Circuit's Remand to State of MN vs NRC."
NEWMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/07/12. 1p.

7908200348 Responds to FOIA request for documents cited in 790611 memo from S Eilperin to NRC entitled, "DC Circuits Remand in State of MN vs NRC." Document withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records. 79/08/17. 2pp.

--7908200330 Informs Commissioners that oral argument in NRDC vs NRC is set for 790315 in Second Circuit court, New York, NY.
EILPERIN, S. F. Office of the General Counsel. 78/02/24. 1p.

--7908200375 Forwards draft ltr to J Kearney of OMB re NRC views on proposed presidential decision memo re radioactive waste mgt. W/o encl.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/05/25. 1p.

--7908200378 Comments on solicitors 790611 memo to NRC re State of NM vs NRC. Clarifies points of law.
SHAPAR, H. K. Office of the Executive Legal Director. 79/06/12. 2pp.

--7908200382 Forwards response to AZ Roisman re final GEIS on handling & storage of spent LWR fuel. NUREG-0575.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/07/09. 1p.

--7908200384 Ack receipt of 790612 ltr re GEIS. NMSS staff will follow whatever decision NRC reaches in response to request re issuance of GEIS.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/06/28. 1p.

--7908200387 Requests NMSS staff seek guidance from Commisssion as to proper course of action re draft GEIS on handling & storage of spent fuel. NUREG-0404.
ROISMAN, A. Z. Natural Resources Defense Council. 79/06/12. 1p.

--7908200390 Lists pending applications to increase capacity of spent fuel storage pools.
REIS, E. J. Branch 3. 79/08/20. 4pp.

7908220056 Requests documents developed since 740101 re uncertainty in calculation of event probabilities & consequences & resulting risks, utilizing probabilistic risk assessment methodologies.
HUBBARD, R. B. MHB Technical Associates. 79/06/25. 2pp.

7908220075 "NRC Models for Evaluating Transport of Radionuclides in Groundwater."
CODELL, R. B., SCHREIBER, D. L. Hydrology Meteorology Branch. 77/05/31. 20pp.

--7908220077 Forwards requested documents re uncertainty in calculation of accident probabilities & consequences.
BARNHART, T. S. Office of Management and Program Analysis. 79/07/24. 1pp.

--7908220083 Discusses 780403-04 presentation re reactor safety study. Clarifies position re use of statistical methods. Findings &/or conclusions w/o consideration of probabilistic assumptions & statistical summarizations.
MOORE, R. H. Office of Management and Program Analysis. 78/05/25. 3pp.

--7908220086 Discusses statistical confidence limits on failure rates.
MOORE, R. H. Office of Management and Program Analysis. 78/10/20. 6pp.

--7908220089 Discusses probabilities of next major accident occuring within prescribed intervals.
RUBINSTEIN, D. Office of Management and Program Analysis. 79/03/09. 8pp.

--7908220096 Forwards rept on EPA risk assessment of radioactive waste isolation in deep geologic formations.
ROBERTS, I. C. Assistant Director for Siting Standards.
CULLINGFORD, M. C. Probabilistic Analysis Branch. 79/08/21. 2pp.

--7908220100 Summary of 781204-08 meeting of NRC Review Group for EPA risk assessment of radioactive waste isolation in deep geologic formations.
* Commission. 78/12/08. 56pp.

--7908220105 Forwards memo re recommended interim values of limiting conditions for operation for ECCS components. Concurs in use of recommended values in STS.
STELLO, V. Division of Technical Review (NRR-1975 only). 75/12/04. 1p.

--7908220110 Recommends interim revisions to limiting conditions for operation for ECCS components.
BAER, R. L. Division of Technical Review (NRR-1975 only). 75/12/01. 7pp.

--7908220120 Discusses use of WASH-1400 in regulatory decision making re transportation environ statements, Browns Ferry fire potential, ATWS, liquid pathway generic study & Price-Anderson extension.
PEDERSEN, K. Commission. 78/09/06. 10pp.

--7908220127 Forwards summary of NRC public statements re WASH-1400, reactor safety study.
PEDERSEN, K. Commission. 78/10/11. 8pp.

--7908220143 Forwards final rept on reactor safety study project. Rept reinforces NRC belief of very low likelihood of occurrences which would exceed contingency protection of Price-Anderson Act.
ANDERS, W. A. Commission. 75/10/29. 3pp.

--7908220146 Responds to 751202 ltr re proposed delay of congressional action on Price-Anderson legislation until after review of reactor safety study. Discusses previous review of rept.
ANDERS, W. A. Commission. 75/12/05. 4pp.

--7908220150 Responds to 751129 ltr re reactor safety study. Discusses inputs & reviews which led to NRC endorsement of rept. Expresses concern re release of 751129 ltr to press before receipt at NRC.
ANDERS, W. A. Commission. 75/12/24. 2pp.

--7908220154 Responds to 760907 inquiry re influence of debate on renewal of Price-Anderson Act on decision to release reactor safety study. Rept does not discuss need for Price-Anderson coverage & was adequately reviewed prior to release.
ROWDEN, M. A. Commission. 76/09/17. 3pp.

7908220170 Submits FOIA appeal of deletions made in five documents re Karen Silkwood controversy.
RAYMOND, J., GLASS, M. Common Ground. 79/08/04. 1p.

7908220170 Submits FOIA appeal of deletions made in five documents re Karen Silkwood controversy.
RAYMOND, J., GLASS, M. Common Ground. 79/08/04. 1p.

7908220178 Confirms 790808 telcon re FOIA appeal of deletions made in five documents pertaining to Karen Silkwood controversy. Appeal is being withdrawn & no further action by NRC is necessary.
FELTON, J. M. Division of Rules and Records. 79/08/13. 1p.

7908220178 Confirms 790808 telcon re FOIA appeal of deletions made in five documents pertaining to Karen Silkwood controversy. Appeal is being withdrawn & no further action by NRC is necessary.
FELTON, J. M. Division of Rules and Records. 79/08/13. 1p.

7908220471 FOIA request for info re whether Union Carbide Corp is required to have NRC license to possess & transport U ore through WY.
REID, A. B. Affiliation Unknown. 79/07/30. 1p.

7908220480 Responds to FOIA request for info re whether Union Carbide Corp is required to have NRC license to possess & transport for possession unrefined & unprocessed U ore.
FELTON, J. M. Division of Rules and Records. 79/08/17. 1p.

7908220485 Responds to FOIA request for copy of winning proposal for NRC solicitation RFP RS-RES-78-193. Forwards nonproprietary version. W/o encl.
FELTON, J. M. Division of Rules and Records. 79/08/14. 1p.

7908220685 Supplements response to FOIA request for documents cited in 790611 memo from SF Eilperim to NRC re DC Circuit remand in State of MN vs NRC. Forwards 770201 memo from former NRC General Counsel Strauss to H Saper.
FELTON, J. M. Division of Rules and Records. 79/08/21. 1p.

7906220686 Discusses need for safety finding re waste disposal. Disagrees that no safety finding need be made re NRC disposition of NRDC position. Suggests public inquiry into validity of Congressional assessment of issue.
STRAUSS, P. L. Office of the General Counsel. 77/02/01. 17pp.

7908240085 Responds to FOIA request for documents re Westinghouse export applications & Philippine power reactor project. Forwards list of documents & 60 documents pertaining to request. Document 61 on list withheld (ref FOIA Exemption 1).
FELTON, J. M. Division of Rules and Records. 79/08/23. 180pp.

7908240176 Responds to FOIA request for lists of existing & proposed nuclear waste facilities & of proposed power plants. Forwards lists & map of facilities. DOE will be source of addl info. W/o encl.
FELTON, J. M. Division of Rules and Records. 79/08/22. 4pp.

7908240185 Requests reply to encl 790420 FOIA request for listing of nuclear waste storage areas & power plants.
SNYDER, L. M. Affiliation Unknown. 79/07/25. 1p.

--7908240288 FOIA request for listing of existing & proposed nuclear waste storage facilities & proposed locations of power plants.
SNYDER, L. M. Affiliation Unknown. 79/04/20. 1p.

7908240219 FOIA request for all documents re Westinghouse export license applications XR-120, XCOM-0013 & XSNM-1471, Philippine power reactor project & procedures & policies related to export licensing.
AUCKLEY, C. H. Beveridge, Fairbanks, & Diamond. 828-0270. 79/08/01. 2pp.

7908270549 Forwards addl info to 790511 FOIA request for documents compiled by NRC Mechanical Engineering Branch & Matls Engineering Branch for IE Bulletins 78-12, 78-12A & 78-12B & other info re atypical weld matls in B&W reactors.
FELTON, J. M. Division of Rules and Records. 79/08/22. 3pp.

7908280045 FOIA request for documentation re radiological emergency response plans for nuclear power plants, including documents generated by & received by NRC.
BURT, L. Massachusetts, State of. 79/06/15. 3pp.

7908280052 Supplements response to 790615 FOIA request for documents re radiological emergency response plans for nuclear power plants. List of forwarded documents encl.
FELTON, J. M. Division of Rules and Records. 79/08/23. 3pp.

--7908280055 Notice of issuance of NUREG-0396, "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of LWR Power Plants."
RYAN, R. G. Office of State Programs. 78/12/11. 1p.

--7908280059 Discusses reactor site evaluation policy as proposed in SECY-77-461, SECY-77-433 & SECY-77-288A. Provides general analysis, history of policy development & status of papers on subj. Suggests creation of task force.
PEDERSEN, K. Office of Policy Evaluations. 77/10/20. 8pp.

--7908280063 Discusses Ofc of General Counsel 780214 comments on SECY-78-44. Recommends approval of limited rule change at early policy session. Suggests legal staff involvement in process.
PEDERSEN, K. Office of Policy Evaluations. 78/02/22. 2pp.

--7908280070 Recommends approval of rule change as written in SECY-78-44. Forwards draft memo reflecting recommendation. Requests comments by 780207.
PEDERSEN, K. Office of Policy Evaluations. 78/02/02. 1p.

--7908280076 Draft memo stating NRC approval of Recommendations 1 & 2 as formulated in SECY-78-44 re proposed amend to 10CFR50 App E. Provides detailed changes to FR notice.
CHILK, S. J. Office of the Secretary of the Commission. 78/02/02. 1p.

--7908280081 Submits comments on SECY-78-44, "Issuance of Effective Amend to 10CFR50 App E." Recommends approval of NRC Recommendations 1 & 2, subject to clarifying changes.
PEDERSEN, K. Office of Policy Evaluations. 78/02/23. 2pp.

--7908280087 Comments on SECY-77-461 re current policy on emergency planning in siting & licensing nuclear power plants. Notes points lacking clarity.
PEDERSEN, K. Office of Policy Evaluations. 77/10/20. 3pp.

--7908280092 Summary of 771025 Policy Session 77-48 in Washington, DC.
CHILK, S. J. Office of the Secretary of the Commission. 77/10/28. 4pp.

--7908280114 Extract of Adjudicatory Session 77-25 on 770608 in Washington, DC.
CHILK, S. J. Office of the Secretary of the Commission. 77/06/17. 1p.

--7908280146 Submits Ofc of Nuclear Reactor Regulation (NRR) preliminary recommendations re emergency planning. Addresses NRC directive to establish formal consultation w/Ofc of State Programs & discusses NRR program responsibilities.
BOYD, R. S. Division of Project Management. 77/02/02. 34pp.

--7908280156 Discusses completion of review of proposed emergency planning beyond low population zone. Comments will be completed by 770726.
SCINTO, J. F. Hearings Division. 77/07/19. 1p.

--7908280163 Supplements response to 770524 ltr w/questions re ASLB decision regarding emergency planning beyond low population zone. Submits current NRC views.
GOSSICK, L. V. Office of the Executive Director for Operations. 77/07/25. 8pp.

--7908280173 Draft 2 of "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
* Commission. * Environmental Protection Agency. 78/07/31. 97pp.

--7908280185 Forwards first draft of NRC/EPA Task Force on Emergency Planning, "Planning Basis for Radiological Emergency Response." Next meeting scheduled for 770428 in Bethesda, MD.
COLLINS, H. E. Office of State Programs. 77/04/27. 1p.

--7908280197 "Planning Basis for Radiological Emergency Response." First draft rept of NRC/EPA Task Force on Emergency Planning.
MCGRATH, P. E. Office of Nuclear Regulatory Research. 77/04/27. 24pp.

--7908280209 Draft 2 of "Planning Basis for Development of State & Local Govt Radiological Response Plans in Support of Light Water Nuclear Power Plants."
* Commission. * Environmental Protection Agency. 77/05/20. 42pp.

--7908280218 Forwards Draft 3 of NUREG-0396, "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
GRIMES, B. K. Office of Nuclear Reactor Regulation. COLLINS, H. E. Office of State Programs. 78/10/25. 1p.

--7908280222 Draft 3 (Final) of "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
COLLINS, H. E. Office of State Programs. GRIMES, B. K. Office of Nuclear Reactor Regulation. * Environmental Protection Agency. 78/10/31. 60pp.

--7908280229 Forwards main text of Draft 4 of "More Definitive Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants." Meeting on 770908 in Bethesda, MD.
COLLINS, H. E. Office of State Programs. GRIMES, B. K. Office of Nuclear Reactor Regulation. 77/08/30. 1p.

--7908280234 Draft 4 of "More Definitive Planning Basis for Develpment of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
COLLINS, H. E. Office of State Programs. GRIMES, B. K. Office of Nuclear Reactor Regulation. 77/08/29. 64pp.

--7908280240 Forwards Draft 5 of "Improved Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants." Next meeting on 771013 in Bethesda, MD.
COLLINS, H. E. Office of State Programs. GRIMES, B. K. Office of Nuclear Reactor Regulation. 77/10/11. 2pp.

--7908280252 Draft 5 of "Improved Planning Basis for State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
COLLINS, H. E. Office of State Programs. GRIMES, B. K. Office of Nuclear Reactor Regulation. * Environmental Protection Agency. 77/10/07. 89pp.

--7908280260 Draft of "Modified Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
COLLINS, H. E. Office of State Programs. GRIMES, B. K. Office of Nuclear Reactor Regulation. * Environmental Protection Agency. 77/11/30. 96pp.

--7908290271 Draft "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
COLLINS, H. E. Office of State Programs. GRIMES, B. K. Office of Nuclear Reactor Regulation. GALPIN, F. Environmental Protection Agency. 78/11/30. 120pp.

7908290535 Responds to FOIA request for bibliography & files re UCLA Nuclear Lab. Complete reactor bibliography encl.
FELTON, J. M. Division of Rules and Records. 79/08/27. 50pp.

7908290652 FOIA request for 790618 ltr to Region 3 re allegations made against hospital radiation safety practices.
KUMPURIS, T. M. Harper-Grace Hosps. Detroit, MI. 79/07/30. 1p.

7908290657 Responds to FOIA request for 790618 ltr re allegations made against hospital radiation safety practices. Forwards document W/o encl.
FELTON, J. M. Division of Rules and Records. 79/08/29. 1p.

7908290658 Response to FOIA request for info re License SNM-1506, NRC-DOE operative procedures & stds & NRC power to stop DOE shipment. 780530 Westinghouse ltr & License SNM-1506 encl.
FELTON, J. M. Division of Rules and Records. 79/08/28. 1p.

--7908290664 Requests amend to License SNM-1506 changing Items 6 & 9 to allow Westinghouse to accept possession of SNM at any licensed facility for delivery to carrier for transport per 10CFR71.
DIPIAZZA, R. P. Westinghouse Electric Corp. 78/05/30. 2pp.

--7908290677 License SNM-1506 for Westinghouse authorizing possession & delivery to transport carrier any matl not subj to requirements of 10CFR73, for transport per 10CFR71.
MACDONALD, C. E. Transportation Branch. 78/06/01. 1p.

7908300781 Responds to FOIA request for nonproprietary portions of technical proposal, "Synthesis of Physical Security & Matl Control & Accounting Assessment Results" by Science Applications, Inc. Forwards document W/o encl.
FELTON, J. M. Division of Rules and Records. 79/08/24. 1p.

7908300784 FOIA request for nonproprietary portions of technical proposal, "Synthesis of Physical Security & Matl Control & Accounting Assessment Results" by Science Applications, Inc.
PRICE, J. C. Woodward-Clyde Consultants. 79/08/03. 1p.

7908310037 FOIA request for NRC mailing lists in labeled format.
KEENAN, T. The Washington Monitor. 79/08/03. 2pp.

7908310040 Responds to FOIA request for NRC mailing lists in labeled format.
FELTON, J. M. Division of Rules and Records. 79/08/21. 1p.

7908310043 FOIA request for 1978 telephone log of V Gilinsky.
IRVINE, R. Accuracy in Media. 79/08/23. 1p.

7908310048 Responds to FOIA request for V Gilinsky 1978 telephone log.
FELTON, J. M. Division of Rules and Records. 79/08/27. 1p.

7908310426 Responds to FOIA request for transcripts or recordings of 780304, 0504, 09, 11, 18 & 31 closed NRC meetings. Forwards transcripts for 780509 & 11 meetings & 780531 minutes. Tape of 780531 meeting withheld (ref FOIA Exemption 6).
FELTON, J. M. Division of Rules and Records. 79/08/21. 2pp.

7908310431 FOIA request for transcripts or recordings of 780304, 0504, 09, 11, 18 & 31 closed NRC meetings.
MALE, [illegible]. Affiliation Unknown. 79/07/03. 1p.

7908310437 FOIA request for transcripts re TMI. Appeals re excessive delay in receipt of requested documents & tapes.
WEISS, E. R. Sheldon, Harmon, Roisman & Weiss. 79/07/18. 2pp.

7908310437 FOIA request for transcripts re TMI. Appeals re excessive delay in receipt of requested documents & tapes.
WEISS, E. R. Sheldon, Harmon, Roisman & Weiss. 79/07/18. 2pp.

7908310437 FOIA request for transcripts re TMI. Appeals re excessive delay in receipt of requested documents & tapes.
WEISS, E. R. Sheldon, Harmon, Roisman & Weiss. 79/07/18. 2pp.

7908310442 Responds to FOIA request for transcripts re TMI. Confirms telcon w/Reed & Wagman re placement in PDR by 790824 of transcripts for first five days of incident response ctr conversations.
FELTON, J. M. Division of Rules and Records. 79/08/21. 1p.

7908310442 Responds to FOIA request for transcripts re TMI. Confirms telcon w/Reed & Wagman re placement in PDR by 790824 of transcripts for first five days of incident response ctr conversations.
FELTON, J. M. Division of Rules and Records. 79/08/21. 1p.

7908310527 Responds to FOIA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2, 5, & 7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records. 79/08/27. 21pp.

7908310534 Responds to FOIA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2, 5, & 7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records. 79/08/27. 21pp.

7908310537 Responds to FOA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2, 5, & 7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records. 79/08/27. 21pp.

7908310542 Responds to FOIA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2, 5, & 7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records. 79/08/27. 21pp.

7908310546 Responds to FOIA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2 & 5-7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records. 79/08/27. 21pp.

7908310556 Responds to FOIA request for documents & communications re TMI. Forwards list of documents being partially denied under Exemptions 2, 5, & 7 & totally denied under Exemption 5.
FELTON, J. M. Division of Rules and Records. 79/08/27. 21pp.

7908310586 Appeals initial FOIA decision re continued noncompliance w/UCS FOIA request for tapes & transcripts of conversations recorded at incident response ctr during TMI incident. Requests release of transcripts.
WEISS, E. R. Sheldon, Harmon, Roisman & Weiss. 79/07/18. 2pp.

7908310586 Appeals initial FOIA decision re continued noncompliance w/UCS FOIA request for tapes & transcripts of conversations recorded at incident response ctr during TMI incident. Requests release of transcripts.
WEISS, E. R. Sheldon, Harmon, Roisman & Weiss. 79/07/18. 2pp.

7908310586 Appeals initial FOIA decision re continued noncompliance w/UCS FOIA request for tapes & transcripts of conversations recorded at incident response ctr during TMI incident. Requests release of transcripts.
WEISS, E. R. Sheldon, Harmon, Roisman & Weiss. 79/07/18. 2pp.

7908310587 Responds to 790718 ltr appealing NRC failure to make available tapes or transcripts of conversations recorded at incident response ctr during TMI incident. Transcripts placed in PDR on 790822. No further action to be taken.
FELTON, J. M. Division of Rules and Records. 79/08/23. 1p.

7908310587 Responds to 790718 ltr appealing NRC failure to make available tapes or transcripts of conversations recorded at incident response ctr during TMI incident. Transcripts placed in PDR on 790822. No further action to be taken.
FELTON, J. M. Division of Rules and Records. 79/08/23. 1p.

7908310587 Responds to 790718 ltr appealing NRC failure to make available tapes or transcripts of conversations recorded at incident response ctr during TMI incident. Transcripts placed in PDR on 790822. No further action to be taken.
FELTON, J. M. Division of Rules and Records. 79/08/23. 1p.

7908310588 Responds to FOIA request for documents associated w/briefing of Terrorism Committee or Subcommittee of Private Security Advisory Council by R McCormick, E Richard & J Yardumian.
FELTON, J. M. Division of Rules and Records. 79/08/29. 1p.

7908310589 FOIA request for documents associated w/briefing of Terrorism Committee or Subcommittee of Private Security Advisory Council by R McCormick, E Richard & J Yardumian.
POWER, D. F. Affiliation Unknown. 79/07/24. 1p.

GEN TEC IS GENERIC TECHNICAL ISSUES

7908020472 Forwards background info describing how Div of Sys Safety intends to resolve ATWS & status prior to TMI-2 incident. W/o encl.
CHERNY, F. C. Division of Systems Safety. 79/06/20. 3pp.

7908030217 Recommends that encl form ltr be forwarded to all licensees as means of encouragement to meet fire protection implementation dates.
VOLLMER, R. Assistant Director for Systems Engineering 79/04/28. 3pp.

7908030454 Advises of resource needs to complete generic issues Task B-67, steam generator feedwater flow instability. Addl funding & addl staff member needed.
LAINAS, G. Plant Systems Branch 79/07/17. 4pp.

7908030480 Forwards draft 3 interim positions re environ qualification of electrical equipment. Comments &/or concurrence due by 790622.
* Electric, Instrumentation & Control Systems Branch 79/06/11. 1pp.

--7908030485 Draft 3 of interim staff position on environ qualification of safety-related electrical equipment. Rept incorporates comments received on draft 2.
* Electric, Instrumentation & Control Systems Branch. 79/06/11. 95pp.

7908080106 Submits analyses of probable post-LOCA flow conditions across containment purge valves, for use in evaluating valve operability.
LAINAS, G. Plant Systems Branch 79/07/10. 7pp.

7908090290 Forwards std order for DOE Work: "Sys Interaction Methodology Application."
VASSALLO, D. B. Division of Project Management 79/07/11. 1p.

--7908090301 Std order for DOE work: "Sys Interaction Methodology Application," issued to Albuquerque Operations Ofc.
* Division of Project Management FIN A-1113-9 79/06/14. 1p.

7908130286 Forwards UCRL-52458, "Methods to Develop Site Specific Spectra & Review of Important Parameters That Influence Spectra."
LEVIN, H. A. Assistant Director for Systematic Evaluation Program. 79/07/03. 3pp.

--7908130292 "Methods to Develop Site Specific Spectra & Review of Important Parameters That Influenced Spectra."
BERNRUTER, D. L. Lawrence Livermore Laboratory. URCL-52458. 79/05/31. 45pp.

7908140216 Summary of 790622 meeting w/representatives of Mark I owners group re uncertainties associated w/definition of pool swell pressure loads & relative significance of uncertainties to design of structure.
GRIMES, C. Assistant Director for Systems Engineering 79/07/10. 5pp.

7908170240 Summary of 790404 meeting w/GE in Bethesda, MD re safety relief valve methodology. Summary of multiple quencher methods & NRC questions re methods encl.
SU, T. M. Containment Systems Branch 79/07/16. 30pp.

7908170598 Forwards corrected Figure 1 of Q Lainas 780710 to E Reeves, increasing differential pressure across BWR valve during period of choked flow.
LAINAS, G. Plant Systems Branch 79/07/30. 2pp.

7908220247 Notification of 790808-09 meeting w/Sandia Lab in Albuquerque, NM to discuss results of NRC review of fault trees for reactor coolant pressure boundary safety function.
ANGELO, J. Light Water Reactors Branch 1 79/07/17. 2pp.

7908230078 Summary of 790727 meeting w/Dosimetry Review Group in Oak Ridge, TN re pool side facility irradiation parameters & input to Task A-11.
SERPAN, C. Z. Metallurgy & Materials Branch 79/08/03. 13pp.

7908230193 Requests addl info re generic review of BWR control rod drive sys mod.
LAINAS, G. Plant Systems Branch 79/07/24. 4pp.

7908240018 Summarizes 790725 site visit to Watts Bar Dam, TN to obtain detailed info needed to complete fault trees & evaluation of fault trees for sys interaction study.
ANGELO, J. Light Water Reactors Branch 1 79/07/26. 1p.

7908240021 Forwards draft of 1979 annual rept section on Task A-17. Changes made to prior rept are new date of Mar 1980 for completion of Phase 1 & word change to indicate that Sandia Labs is conducting study.
ANGELO, J. Division of Project Management 79/07/31. 3pp.

7908270084 Notification of 790724 meeting w/Mark I owners group to discuss outstanding issues re load definition for Mark I containment long-term program.
GRIMES, C. Assistant Director for Systems Engineering 79/07/11. 2pp.

7908270087 Forwards draft of acceptance criteria for Mark I Containment Long-Term Program. Requests comments by 790814. Draft transmittal ltr encl.
GRIMES, C. I. Plant Systems Branch 79/08/02. 3pp.

7908270290 Forwards Sandia Labs Figure 5.3 series of fault trees re depiction of reactor coolant pressure boundary safety function. Fault trees in question are under review & will be discussed at 790808-09 meeting w/Sandia.
ANGELO, J. Light Water Reactors Branch 1 79/08/06. 2pp.

7908280840 Summary of 790522 telcon w/R Logue & R Kohrs of Mark I owners group re Mark I long-term program review schedule. Owners group would like to meet w/NRC to discuss matter. Tentative meeting scheduled for 790608.
GRIMES, C. I. Plant Systems Branch 79/05/31. 2pp.

7908280848 Notification of 790725 visit to Watts Bar Dam to develop detailed info on location & operating characteristics of plant equipment needed for evaluation of fault trees.
ANGELO, J. Light Water Reactors Branch 1 79/07/16. 1p.

7908280875 Summary of 790612 meeting w/Sandia Lab in Bethesda, MD to review progress on Task A-17 & assess resources, requirements & time needed to complete Phase 1 of task.
ANGELO, J. Light Water Reactors Branch 1 79/06/19. 21pp.

7908300445 Confirms info re intended approach of Ofc of Nuclear Reactor Regulation to resolve ATWS safety issue. Suggests work on generic analysis verification procedure. TMI-2 incident raises new issues or PWRs.
HANAUER, S. J. Office of Nuclear Reactor Regulation. 79/07/05. 3pp.

--7908300452 Notification of 790725 meeting to discuss possible impact of TMI-2 accident on evaluation of ATWS events for PWRs.
CHERNY, F. C. Office of Nuclear Reactor Regulation. 79/07/05. 2pp.

I&E INSPECTION AND ENFORCEMENT

7811060166 IE Bulletin 78-13, "Failure in Source Heads of Kay-Ray, Inc Gauges, Mods 7050, 7050S, 7051, 7060, 7060B, 7061 & 7061B."
* Office of Inspection & Enforcement, Office of the Director. 78/10/27. 5pp.

7901160383 IE Circular 79-01, "Administration of Unauthorized Byproduct Matl to Humans."
* Office of Inspection & Enforcement, Office of the Director. 79/01/12. 5pp.

7901290277 IE Circular 79-02, "Failure of 120 Volt Vital AC Power Supplies."
* Office of Inspection & Enforcement, Office of the Director. 79/01/16. 7pp.

7905020110 IE Circular 79-06, "Failure to Use Syringe & Bottle Shields in Nuclear Medicine."
* Region 2, Atlanta, Office of the Director. 79/04/19. 5pp.

7906210065 IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem."
* Office of Inspection & Enforcement, Office of the Director. 79/06/21. 1p.

7908020176 IE Bulletin 79-16, "Vital Area Access Control."
* Office of Inspection & Enforcement, Office of the Director. 79/07/26. 7pp.

7908020183 IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants."
* Office of Inspection & Enforcement, Office of the Director. 79/07/26. 11pp.

7908020458 IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
* Office of Inspection & Enforcement, Office of the Director. 79/07/18. 1p.

7908070515 IE Bulletin 79-19, "Packaging of Low Level Radioactive Waste for Transport & Burial."
* Office of Inspection & Enforcement, Office of the Director. 79/08/10. 5pp.

7908080360 IE Bulletin 79-14, Suppl 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
* Office of Inspection & Enforcement, Office of the Director.
79/08/15. 2pp.

7908090193 IE Bulletin 79-21, "Temp Effects on Level Measurements."
* Office of Inspection & Enforcement, Office of the Director.
79/08/13. 2pp.

7908090260 IE Info Notice 79-20, "NRC Enforcement Policy - NRC Licensed Individuals."
* Office of Inspection & Enforcement, Office of the Director.
79/08/14. 3pp.

7908090272 IE Circular 79-17, "Contact Problem in SB-12 Switches on GE Metalclad Circuit Breakers."
* Office of Inspection & Enforcement, Office of the Director.
79/08/14. 1p.

7908160420 IE Circular 79-15, "Bursting of High Pressure Hose & Malfunction of Relief Valve & O-Ring in Certain Self-Contained Breathing Apparatus."
* Office of Inspection & Enforcement, Office of the Director.
79/08/08. 5pp.

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

7908010589 Operating Experience Memo 15 re reliability of emergency onsite diesel generators. Recommends review of NUREG/CR-0660 to determine applicability to plants which have not reached operational status by 790601 & revision of SRP.
EISENHUT, D. G. Division of Operating Reactors. 79/07/02. 4pp.

7908020391 Changes NUREG-0415 to NUREG/CR-0785. Second errata sheet for "COMMIX-1, Three-Dimensional Transient Single-Phase Component Computer Program for Thermal-Hydraulic Analysis."
* Docketing & Services Branch. 79/07/19. 1p.

7908030034 NUREG/CR-0424
"Risk Methodology for Geologic Disposal of Radioactive Waste Sandia Waste Isolation Flow & Transport (SWIFT) Model."
DILLON, R. T. Sandia Laboratories. LANTZ, R. B., PAHWA, S. B. Interra Environmental Consultants, Inc. FIN A-1192. SAND78-1267. 78/10/31. 116pp. Available at NTIS.

7908030044 NUREG/CR-0458
"Risk Methodology for Geologic Disposal of Radioactive Waste," interim rept.
CAMPBELL, J. E., DILLON, R. T., TIERNEY, M. S. Sandia Laboratories. FIN A-1192. SAND78-0029. 78/10/31. 264pp. Available at NTIS. $10.75.

7908030322 Forwards draft IE bulletin re results of Univ of Dayton research on enhancement of onsite emergency diesel generator reliability, originally submitted as NUREG/CR-0660.
GRIMES, B. Assistant Director for Systems Engineering. 79/06/26. 4pp.

7908030420 Replaces Reg Guide 1.104, "Single-Failure-Proof Overhead Crane Handling Sys for Nuclear Power Plants," w/NUREG-0554, "Single-Failure-Proof Cranes for Nuclear Power Plants."
EISENHUT, D. G. Division of Operating Reactors. 79/06/26. 1p.

7908030562 Responds to 790514 ltr re refinement in passive containment sys. Accident at TMI would not have been avoided or mitigated by use of design. Forwards NUREG-0560. W/o encl.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/20. 2pp.

--7908030570 Forwards 790507 ltr re improvements in LWR safety features & rept "Passive Containment Sys, New Concept to Solve Safety Concerns." Requests timely attention to matter. Rept not encl.
FALLS, O. B. NucleDyne Engineering Corp. 79/05/14. 5pp.

--7908030592 Forwards 790507 ltr re improvements in LWR safety features & rept "Passive Containment Sys, New Concept to Solve Safety Concerns." Requests timely attention to matter.
FALLS, O. B. NucleDyne Engineering Corp. 79/05/15. 3pp.

7908060026 Responds to 796607 ltr re implementation of Advisory Council on Historic Preservation 790301 environ quality regulations. NRC is drafting changes in 10CFR51 to accommodate changes.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/26. 2pp.

--7908060050 Notifies of Presidential policy initiatives to increase attention given by federal agencies to environ quality. Requests lead individual to be responsible for NRC procedures to implement Natl Historic Preservation Act.
UTLEY, R. H. Advisory Council on Historic Preservation. 79/06/07. 2pp.

7908060117 NUREG/CR-0606
"Investigation of Two-Phase Flow Regimes in LOFT Piping During Loss-of-Coolant Experiments."
PASSINOS, P. G., LIAO, C. K. Idaho National Engineering Laboratory. FIN A-6048. TREE-1244. 79/06/30. 87pp. Available at NTIS.

7908060197 Responds to 790509 ltr re refinement in passive containment sys. Accident at TMI could not have been avoided or mitigated by use of design. Forwards NUREG-0560. W/o encl.
DENTON, H. R. Operating Reactors Branch 1 (Pre 790625). 79/06/20. 2pp.

--7908060481 Forwards GB Falls 790507 ltr re improvements in LWR safety features & rept "Passive Containment Sys, New Concept to Solve Safety Concerns." Requests timely attention to matter.
KLEIMOLA, F. W. NucleDyne Engineering Corp. 79/05/09. 2pp.

--7908060486 Comments on passive containment sys for LWR plants that would have prevented core damage & release of radioactivity under TMI conditions.
FALLS, O. B. NucleDyne Engineering Corp. 79/05/09. 3pp.

7908070628 NUREG-0217
"NRC Task Force Rept on Review of Federal/State Program for Regulation of Commercial Low Level Radioactive Waste Burial Grounds, Analysis of Public Comments," Suppl 1.
* Office of Nuclear Material Safety & Safeguards. 77/10/31. 17pp.

7908070659 NUREG/CR-0838
"Stability Analysis of Circumferential Cracks in Reactor Piping Systems."
TADA, H. Washington Univ. NRC-03-78-135. 79/06/30. 36pp. Available at NTIS.

7908070694 NUREG/CR-0810
"Preliminary Analysis of Surface Displacement Results in Creepdown Irradiation Experiment HOBBIE-1."
HOBSON, D. O. Oak Ridge National Laboratory. FIN B-0124. ORNL/NUREG/TM-3. 79/06/30. 29pp. Available at NTIS.

7908070709 NUREG/CR-0948
"Nonlinear Structural Dynamic Analysis Procedures for Category I Structures."
* URS/John A. Blume & Assoc. Engineers (subs. of URS). NRC-03-77-173. 79/07/31. 300pp. Available at NTIS.

7908070748 NUREG/CR-0815
"Experiment Data Rept for Semiscale Mod-3 Lower Plenum Injection Test S-07-9 (Baseline Test Series)."
MIYASAKI, D. H., SACKETT, K. E., PACK, D. R. EG & G, Inc. FIN A-6038. TREE-1229. 79/06/30. 253pp. Available at NTIS.

7908070773 NUREG/CR-0707
"Evaluation of Isotope Migration - Land Burial, Water Chemistry at Commercially Operated Low Level Radioactive Waste Disposal Sites," Progress Rept 9, Apr-June 1978.
COLOMBO, P., WEISS, A. J. Brookhaven National Laboratory. FIN A-3042. BNL-NUREG 50965. 79/02/28. 35pp.

7908070781 NUREG/CR-0767
"Application of Static & Dynamic Crack Arrest Theory to Thermal Shock Experiment TSE-4."
CHEVERTON, R. D., ISKANDER, S. K. Oak Ridge National Laboratory. FIN B-0119. ORNL/NUREG-57. 79/06/30. 33pp.

7908070803 NUREG/CR-0522
"Nuclear Reactor Safety," quarterly progress rept, Jul-Sept 1978.
JACKSON, J. F., STEVENSON, M. G. Los Alamos Scientific Laboratory. LA-7567-PR. 78/12/31. 142pp.

7908080087 NUREG-0472
NUREG-0472, Revision 2, "Radiological Effluent Tech Specs for PWRs."
* Assistant Director for Standard & Advanced Reactors. 79/07/31. 77pp.

7908080380 NUREG-0462
"Technical Rept on Operating Experience w/BWR Pressure Relief Sys."
* Office of Nuclear Reactor Regulation. 78/07/31. 33pp. Available at NTIS. $5.25.

7908080408 NUREG/CR-0578
"High Level Waste Repository Site Suitability Study - Status Rept."
HECKMAN, R. A., TOWSE, D. F., ISHERWOOD, D. Lawrence Livermore Laboratory. FIN A-0277-7. UCRL-52633. 79/07/31. 310pp. Available at NTIS.

7908080416 NUREG/CR-0931
"Transportation of Radioactive Matl in GA," Aug 1977 - Sept 1978
CARTER, M. W., GASPER, J. T., KAHN, B. Georgia Institute of Technology FIN B-1612. 79/07/31. 55pp. Available at NTIS.

7908080423 NUREG/CR-0827
"Reference Critical Experiments," Progress Rept, Jan - Mar 1979.
GOEBEL, G. R., OH, I., ROTHE, R. E. Rockwell International Corp. FIN A-1036. RFP2932. 79/08/31. 49pp. Available at NTIS.

7908080437 NUREG/CR-0876
"Regional Tectonics & Seismicity of Eastern NE," Annual Rept 1978
BURCHETT, R. R., MAHONEY, D. G. Nebraska, State of. FIN B-5777. 79/06/30. 169pp. Available at NTIS.

7908090352 Comments on NUREG-0511, Section 6.2.B.2.7.1 re average individual occupational exposure estimates. Th-230 should be included in assessment of occupational exposure from inhalation of yellowcake dust.
TUCHFELD, G. Dames & Moore. 79/06/15. 2pp.

7908090437 Expresses dissatisfaction w/draft GEIS on U milling (NUREG-0511). Newspaper article encl.
LEWIS, M. Affiliation Unknown. 79/07/01. 5p.

7908090470 Ack receipt of draft GEIS re U milling (NUREG-0511). No comments on draft. Requests copy of final statement when available.
HEISS. Pennsylvania, State of. 79/06/29. 1p.

7908090521 NUREG-0332
Draft "Health Effects Attributable to Coal & Nuclear Fuel Cycle Alternatives."
* Office of Nuclear Reactor Regulation. 79/05/23. 7pp.

--7908090522 NUREG-0332
Draft "Health Effects Attributable to Coal & Nuclear Cycle Alternatives."
GOTCHY, R. L. Division of Site Safety & Environmental Analysis. 77/09/30. 29pp.

7908090525 Notifies that IL state environ agencies have been given opportunity to comment on draft GEIS on U milling (NUREG-0511). No comments have been received.
HORNBACKER, T. E. Illinois, State of. 79/06/22. 1p.

7908090530 NUREG/CR-0330
"Ex-Reactor Determination of Thermal Gap & Content Conductance Between U Dioxide-Zircaloy-4 Interfaces. Stage I: Low Gas Pressure."
GARNIER, J. E., BEGEJ, S. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2043. PNL-2696. 79/04/30. 200pp. Available at NTIS.

7908090536 NUREG/CR-0832
"INCAP: Finite Element Program for One-Dimensional Nonlinear Inverse Heat Conduction Analysis."
BASS, B. R. Oak Ridge National Laboratory. FIN B-0125. ORNL/NUREG/CSD/. 79/07/31. 102pp. Available at NTIS.

7908090543 NUREG/CR-0407
"Evaluation & Comparison of Nuclear Powerplant Siting Methodologies."
KEENEY, R. L., KIRKWOOD, C. W., FORD, C. K. Sandia Laboratories. FIN A-1074. SAND78-1284. 79/03/31. 238pp. Available at NTIS.

7908100387 NUREG-0690
"SOLA-DF Solution Algorithm for Nonequilibrium Two-Phase Flow."
HIRT, C. W., ROMERO, N. C., TORREY, M. D. Los Alamos Scientific Laboratory. FIN A-7027. LA-7725-MS. 79/06/30. 90pp.

7908100394 NUREG/CR-0792
"Experiment Data Rept for LOFT Power Ascension Experiment L2-3."
PRASSINOS, P. G., GALUSHA, B. M., ENGELMAN, D. B. EG & G, Inc. FIN A-6048. TREE-1326. 79/07/31. 270pp.

7908100408 NUREG-0584
Draft rept "Assuring Availability of Funds for Decommissioning Nuclear Facilities."
WOOD, R. S. Antitrust & Indemnity Group. 79/07/31. 50pp.

7908130066 Responds to 790621 ltr re comments on Revision 1 to Section 14.2 of SRP (NUREG-75/087).
SKOVHOLT, D. J. Quality Assurance Branch. 79/07/27. 4pp.

7908130139 Requests comments on "Final GEIS on Routine Use of Plutonium-Powered Cardiac Pacemakers," dtd July 1976 & Suppl 1, "Update of Info on Power Sources for Pacemakers."
MINOGUE, R. B. Office of Standards Development. 79/07/27. 1p.

--7908130148 NUREG-0060
"GEIS on Routine Use of Plutonium-Powered Cardiac Pacemakers."
* Office of Nuclear Material Safety & Safeguards. 76/07/31. 300pp. Available at NTIS.

--7908130156 NUREG-0060
"Final GEIS on Routine Use of Pu-Powered Cardiac Pacemakers," Suppl 1.
* Office of Standards Development. 79/05/31. 14pp. Available at NTIS.

7908130504 Notification of 790912-14 & 25-27 meetings in Columbia, SC & Seattle, WA, respectively, to develop more explicit policies for nuclear facility decommissioning.
RYAN, R. G. Office of State Programs. 79/07/20. 2pp.

7908130506 Notification of 790912-14 & 25-27 meetings in Columbia, SC & Seattle, WA, respectively, to develop more explicit policies for nuclear facility decommissioning.
RYAN, R. G. Office of State Programs. 79/07/20. 2pp.

7908130509 Notification of 790912-14 & 25-27 meetings in Columbia, SC & Seattle, WA, respectively, to develop more explicit policies for nuclear facility decommissioning.
RYAN, R. G. Office of State Programs. 79/07/20. 2pp.

7908130510 Notification of 790912-14 & 25-27 meetings in Columbia, SC & Seattle, WA, respectively, to develop more explicit policies for nuclear facility decommissioning.
RYAN, R. G. Office of State Programs. 79/07/20. 2pp.

7908130511 Notification of 790912-14 & 25-27 meetings in Columbia, SC & Seattle, WA respectively, to develop more explicit policies for nuclear facility decommissioning.
RYAN, R. G. Office of State Programs. 79/07/20. 2pp.

7908130512 Notification of 790912-14 & 25-27 meetings in Columbia, SC & Seattle, WA, respectively, to develop more explicit policies for nuclear facility decommissioning.
RYAN, R. G. Office of State Programs. 79/07/20. 2pp.

7908130514 Notification of 790912-14 & 25-27 meetings in Columbia, SC & Seattle, WA, respectively, to develop more explicit policies for nuclear facility decommissioning.
RYAN, R. G. Office of State Programs. 79/07/20. 2pp.

7908140068 NUREG/CR-0640
"Stress Intensity Distributions in Nozzle Corner Cracks of Complex Geometry."
SMITH, C. W., PETERS, W. H., HARDRATH, W. T. Virginia Polytechnic Institute & State Univ. FIN B-0119. ORNL/SUB/7015-2. 79/01/31. 42pp.

7908140084 NUREG/CR-0516
"Experiment Data Rept for Test RIA 1-1 (Reactivity Initiated Accident Test Series)."
BUCKLAND, R. J., ABBOTT, D. G., WHITE, C. E. EG & G, Inc. FIN A-6041. TREE-1236. 79/05/30. 102pp. Available at NTIS.

7908140104 NUREG/CR-0868
"Nuclear Reactor Safety," Quarterly progress rept 790101-0331.
JACKSON, J. F., STEVENSON, M. G. Los Alamos Scientific Laboratory. LA-7867-PR. 79/06/30. 187pp.

7908140116 NUREG/CR-0765
"Experiment Data Rept for Test RIA 1-2 (Reactivity Initiated Accident Test Series)."
ZIMMERMANN, C. L., WHITE, C. E., EVANS, R. P. EG & G, Inc. FIN A-6041. TREE-1271. 79/06/30. 95pp. Available at NTIS.

7908140128 NUREG/CR-0757
"Fuel Rod Matl Behavior During Test PCM-1."
COOK, B. A. EG & G, Inc. FIN A-6041. TREE-1333. 79/06/30. 69pp. Available at NTIS.

7908140145 Comments on NUREG-0511, Vol 1. Requests explanation of Table 6, Page 26, re premature deaths health effects of milling.
CHONG, L. R. Affiliation Unknown. 79/07/09. 1p.

7908140153 NUREG-0452 REV 2
"Standard Tech Specs for Westinghouse PWRs," Revision 2.
* Office of Nuclear Reactor Regulation. 79/07/31. 300pp.

7908140176 NUREG-0533
"Aircraft Impact Risk Assessment Data Base for Assessment of Fixed Wing Air Carrier Impact on Vicinity of Airports."
AASTUMEWICZ, F., READ, J. Accident Analysis Branch. 79/06/30. 103pp.

7908140205 NUREG-0309
"Topical Rept Review Status/Reg Activities Manpower Sys."
Vol 3, Number 1.
* Office of Management and Program Analysis. 79/07/15. 197pp.

7908140275 Ack receipt of 790404 ltr forwarded by Representative K. Holland. Describes federal & State of SC regulations re transportation of radioactive waste. Special procedures are established by NRC for shipping TMI waste. DOT rules encl.
HENDRIE, J.M. Commission. 79/06/30. 5pp.

7908140275 Ack receipt of 790404 ltr forwarded by Representative K. Holland. Describes federal & State of SC regulations re transportation of radioactive waste. Special procedures are established by NRC for shipping TMI waste. DOT rules encl.
HENDRIE, J.M. Commission. 79/06/30. 5pp.

--7908140299 NUREG-0535
"Review & Assessment of Package Requirements (Yellowcake) & Emergency Response to Transportation Accidents." Draft rept.
* Office of Nuclear Material Safety & Safeguards. * Transportation, Dept. of. 79/10/31. 230pp.

--7908140326 NUREG-0170 V2
"FES on Transportation of Radioactive Matl by Air & Other Modes." Vol 2.
* Office of Standards Development. 77/12/31. 450pp.

7908140343 NUREG-0603
"Comments on NRC Safety Research Program Budget."
* ACRS - Advisory Committee on Reactor Safeguards. 79/07/31. 45pp. Available at NTIS.

7908140416 NUREG-0217
"NRC Task Force Rept on Review of Federal/State Program for Regulation of Commercial Low Level Radioactive Waste Burial Grounds."
CUNNINGHAM, R.E., DRAGONETTE, K.S. Division of Fuel Cycle & Material Safety. RAUAN, R.G. Office of State Programs. PB-283 890. 77/03/31. 67pp.

7908140462 NUREG/CR-0080
"Evaluation of Alternative Methods for Disposal of Low Level Radioactive Wastes."
MACBETH, P.J., WEHMANN, G., THAMER, B.J. Ford Bacon & Davis Utah, Inc. FIN B-1521. 79/07/31. 181pp.

7908140707 NUREG-0103
"Std Tech Specs for B&W PWRs," Revision 3.
* Division of Operating Reactors. 79/07/31. 400pp. Available at NTIS.

7908150077 NUREG-0573
"Analysis of ECC Bypass Data."
BECKNER, W.D., REYES, J.N., ANDERSON, R. Division of Reactor Safety Research. 79/07/31. 135pp. Available at NTIS.

7908150088 NUREG-0582
"Water Hammer in Nuclear Power Plants."
* Division of Systems Safety. 79/07/31. 87pp. Available at NTIS.

7908160462 Opposes proposed ruling for inerting BWR Mark I & II containments per NUREG-0578. Cannot justify on risk-benefit basis. Superior BWR core protection assures no significant hydrogen release in TMI-2 type event.
SHERWOOD, G.G. General Electric Co., Nuclear Energy Products Div. MFN-199-79. 79/08/03. 2pp.

7908170603 Forwards comments on draft GEIS on U milling. Discusses problems in addressing dose parameters.
CUSTARD, C. Health, Education & Welfare, Dept. of. 79/07/26. 3pp.

7908170625 Discusses review results of GEIS re U milling. Forwards ID Health & Welfare Dept comments outlining ID regulations re maint of water quality & air pollution control.
DEMO-RYBUS, P. Idaho, State of. 79/07/23. 1p.

--7908170629 Comments on GEIS. Source must comply w/"Rules & Regulations for Control of Air Pollution in ID." Milling operations must comply w/"ID Water Quality Stds & Wastewater Treatment Requirements."
STOKES, L.W. Idaho, State of. 79/07/02. 2pp.

7908200001 NUREG/CR-0723
"Calculations of Skyshine Gamma-Ray Dose Rates From Independent Spent Fuel Storage Installations Under Worst Case Accident Conditions."
PACE, J.V., CRAMER, S.N., KNIGHT, J.R. Oak Ridge National Laboratory. FIN-B-0102. ORNL/NUREG/TM-3. 79/08/02. 45pp.

7908200398 Forwards initial comments on U mills draft generic EIS, submitted by Environ Improvement Div.
WOLFF, T.A. New Mexico, State of. 79/07/05. 15pp.

--7908200399 Testimony of TA Wolff on draft GEIS re continued care fund of U mills.
WOLFF, T.A. New Mexico, State of. 79/07/05. 6pp.

--7908200401 Radiation Protection Act of State of NM.
* New Mexico, State of. 79/07/05. 5pp.

--7908200403 "Phase II, Title I, Engineering Assessment of Inactive U Mill Tailings, Shiprock Site, Shiprock, NM," prepared for ERDA, Grand Junction, Co.
* Ford Bacon & Davis Utah, Inc. E(05-1)-1658. 77/03/31. 6pp.

--7908200404 "Phase II, Title I Engineering Assessment of Inactive U Mill Tailings Vitro Site, Salt Lake City, UT," prepared for ERDA, Grand Junction, Co.
* Ford Bacon & Davis Utah, Inc. E(05-1)-1658. 76/04/30. 5PP.

--7908200407 "Continued Care of U Mill Sites: Some Economic Considerations."
HARRINGTON, W. Resources for the Future, Inc. 78/01/31. 23pp.

7908210172 Comments on Sections 9.2.4 & 9.2.5 of ACI 318-78 open to various interpretations. Requests appropriate clarification re groundwater load factor determination.
LIPIRSKI, R.E. Structural Engineering Branch. 78/11/29. 1p.

7908230345 Submits review of final draft engineering rept & final draft environ analysis prepared for Vitro rare metals plant in Canonsburg, PA. Forwards copy of NUREG-0511. W/o encl.
CROW, T.W. Division of Fuel Cycle & Material Safety. 79/07/24. 2pp.

7908230592 "Regional Tectonics & Seismicity of Eastern NE. "Annual Rept June 1977-May 1978.
BURCHETT, R.R., MARONEY, D.G. Nebraska, Univ. of. FIN B-5777. 79/06/30. 170pp. Available at NTIS.

7908230642 NUREG/CR-0926
"Seismic Study of Pacific Northwest Region of US," Nov 1961-Aug 1965.
RACINE, D. Teledyne Geotech. FIN B-6304. AL-79-1. 79/07/31. 55pp. Available at NTIS.

7908230667 NUREG/CR-0951
"Comparison of Piping Models for Digital Power Plant Similators."
SOWERS, G.W. Arizona, Univ. of. FIN A-4065. 79/08/31. 47pp. Available at NTIS.

7908230679 NUREG/CR-0848
"Summary & Bibliography of Operating Experience W/Valves in LWR Nuclear Power Plants," 1965-1978. Microfiche encl.
SCOTT, R.L., GALLAHER, R.B. Oak Ridge National Laboratory. FIN B-0126. ORNL/NUREG/NSIC. 79/07/31. 21pp. Available at NTIS.

7908230686 NUREG/CR-0855
"Reactor Safety Research Programs," quarterly rept for Jan-Mar 1979.
HOOPER, J.L. Battelle Memorial Institute, Pacific Northwest Laboratory. EY-76-C-06-1830. PNL-3040-1. 79/05/31. 174pp. Available at NTIS.

7908230692 NUREG/CR-0865
"Startup Data Rept for NRC/Pacific Northwest Lab Halden Assembly IFA-513."
LANNING, D.D., CUNNINGHAM, M.E. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2043. PNL-2948. 79/07/31. 76pp. Available at NTIS.

7908240056 NUREG/CR-0910
"Pattern Recognition Methods for Acoustic Emission Analysis."
DOCTOR, P.G., HARRINGTON, T.P., HUTTON, P.H. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2088. PNL-3052. 79/07/31. 59pp. Available at NTIS.

7908240068 NUREG/CR-0609
"Power-Cooling-Mismatch Test Series Fuel Rod Matl Properties Data Rept."
KERWIN, D.K., NOVICK, A.H., OLSEN, C.S. Idaho National Engineering Laboratory. FIN A-6041. TREE-1331. 79/05/31. 86pp. Available at NTIS.

NONDOCKETED ITEMS

7908240106 NUREG-0540 V1 N6
"Title List of Documents Made Publicly Available," for June 1979.
* Division of Technical Information & Document Control. 79/06/30. 429pp. Available at NTIS.

7908240119 NUREG/CR-0922
"User's Manual for TRNSM 2."
WOO, C. W., ANDERSON, G. M. Orincon Corp. FIN A-1173. SAND 78-8197. 79/08/31. 75pp. Available at NTIS.

7908240125 NUREG/CR-0923
"Sensitivity Studies Using TRNSM 2 Computerized Model for NRC Physical Protection Project," Final rept.
ANDERSON, G. M. Orincon Corp. FIN A-1173. SAND 78-8196. 79/08/31. 140pp. Available at NTIS.

7908240135 NUREG/CR-0924
"Computerized Transportation Model for NRC Physical Protection Project, Versions I & II."
ANDERSON, G. M. Orincon Corp. FIN A-1173. SAND 78-8177. 79/08/31. 171pp. Available at NTIS.

7908240142 NUREG/CR-0925
"Development of Transport Network for NRC Physical Protection Project."
ANDERSON, G. M., PAYNE, H. J. Orincon Corp. FIN A-1173. NUREG/CR-0925. 79/08/31. 119pp. Available at NTIS.

7908240198 NUREG-0430 V1 N3
Grey Book. "Licensed Fuel Facility Status Rept," Jul 1979.
* Office of Inspection & Enforcement. Office of the Director. 79/07/31. 77pp. Available at NTIS.

7908240644 NUREG/CR-0834
"Reactor Primary Coolant Sys Pipe Rupture Study Method for Detection of Sensitization in Stainless Steel," Progress Rept 46 for Oct-Dec 1978.
CLARKE, W. L. General Electric Co. FIN B-3012. GEAP-10207-46. 79/08/31. 22pp. Available at NTIS.

7908240659 NUREG/CR-0894
"Power Plant Entrainment Simulation Utilizing Condenser Tube Simulator," Annual Rept Dec 1977-Nov 1978.
O'CONNOR, J. M., POJE, G. V. New York Univ. Medical Center. FIN B-6298. 79/07/31. 118pp. Available at NTIS.

7908240668 NUREG/CR-0901
"Criteria for Safety-Related Nuclear Plant Operator Actions: Preliminary Assessment of Available Data."
HAAS, P. M., BOTT, T. F. Oak Ridge National Laboratory. FIN B-0421-8. ORNL/NUREG/TM-3. 79/07/31. 111pp. Available at NTIS.

7908240673 NUREG/CR-0949
"Analytical/Experimental Correlation of Nonlinear Sys Subjected to Dynamic Load."
ANDERSON, J. C., MASRI, S. F. Southern California, Univ. of. FIN B-5976. 79/07/31. 56pp. Available at NTIS.

7908270077 NUREG/CR-0864
"Physics of Reactor Safety," quarterly rept for Jan-Mar 1979.
* Argonne National Laboratory. FIN A-2015. ANL-79-37. 79/05/31. 46pp. Available at NTIS.

7908270100 NUREG/CR-0752
"LMFBR Aerosol Release & Transport Program," quarterly progress rept for Oct-Dec 1978.
KRESS, T. S., TOBIAS, M. L. Oak Ridge National Laboratory. FIN B-0121. ORNL/NUREG/TM-3. 79/07/31. 45pp. Available at NTIS.

7908270415 Comments on "TMI-2 Lessons Learned Task Force Rept (Short-Term), NUREG-0578." Problem described does not justify solution recommended. Change should be published w/proper opportunity for comment & public discussion.
SHORT, T. E. Omaha Public Power District. 79/08/20. 1p.

7908280052 Supplements response to 790615 FOIA request for documents re radiological emergency response plans for nuclear power plants. List of forwarded documents encl.
FELTON, J. M. Division of Rules and Records. 79/08/23. 3pp.

--7908280035 Notice of issuance of NUREG-0396, "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of LWR Power Plants."
RYAN, R. Q. Office of State Programs. 78/12/11. 1p.

--7908280173 Draft 2 of "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
* Commission. * Environmental Protection Agency. 78/07/31. 97pp.

--7908280260 Draft of "Modified Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
COLLINS, H. E. Office of State Programs. GRIMES, B. K. Office of Nuclear Reactor Regulation. * Environmental Protection Agency. 77/11/30. 96pp.

--7908280271 Draft "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
COLLINS, H. E. Office of State Programs. GRIMES, B. K. Office of Nuclear Reactor Regulation. GALPIN, F. Environmental Protection Agency. 78/11/30. 120pp.

7908290477 Recommends extension of scope of pipe cracking review beyond that examined in NUREG-0531. High frequency of BWR pipe cracking suggests probability of LOCA & need for examination of detection capability & safety procedures.
CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/08/16. 2pp.

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

7907310443 Requires compliance to Criteria VII & XVIII by purchaser of items & svc from firm having ASME Certificates of Authorization. Compliance to Criterion VII of App B re source evaluation & selection should not be required.
HAASS, W. P. Quality Assurance Branch. 79/06/15. 1p.

7908010125 Forwards Region 1 Investigation Rept 078-154-A, Parts 1 & 2, re source of radioactive matl found at Norton, MA privately owned landfill. W/o encl.
STOHR, J. P. Region 1, Philadelphia, Office of the Director. 79/06/26. 1p.

--7908010134 Forwards IE Insp Rept 078-154-A, Parts 1 & 2, re source of radioactive matl found at Norton, MA privately owned landfill. W/o encl.
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/06/26. 1p.

--7908010141 Forwards Investigation Rept 078-154-A, Parts 1 & 2, re source of radioactive matl found at Norton, MA privately owned landfill.
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/06/26. 1p.

7908010205 "Atmosphere-Surface Exchange of Particulate & Gaseous Pollutants (1974)," proceedings of symposium held in Richland, WA, 740904-06. Title pages only.
* Energy Research & Development Admin. (Presently DOE). 76/12/31. 2pp.

7908020366 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."
PAPPAS, I. Region 3, Chicago, Office of the Director. 79/07/20. 2pp.

7908030125 Forwards "ANS-5 Draft Fission Gas Release Std," including recent changes to model for radioactive isotopes.
MEYER, R. O. Core Performance Branch. 79/06/04. 2pp.

--7908030129 "ANS-5 Draft Fission Gas Release Std."
* Core Performance Branch. 79/06/04. 6pp.

7908030493 Summary of AIF Sys & Equipment design criteria Subcommittee 790712-13 meeting.
OLSHINSKI, J. A. TMI-2 Lessons Learned Task Force. 79/07/18. 4pp.

7908030585 Forwards MD Huntington 790425 ltr re threat posed by sympathizers of Palestinian Arabs to nuclear power facilities. Info requested is not within purview of NRC.
MILLER, J. R. Assistant Director for Site & Safeguards. 79/06/15. 10pp.

7908070222 Notifies of review of draft 6 of ASME mgt plan forwarded w/790402 ltr. Several items require further clarification. Forwards request for addl info.
HAASS, W. P. Quality Assurance Branch. 79/06/26. 4pp.

7908070535 "Flatland Deposits of San Francisco Bay Region, CA, Geology & Engineering Properties & Importance to Comprehensive Planning," Geological Survey Professional Paper 943.
HELLEY, E. J., LAJOIE, K. R. Interior, Dept. of, Geological Survey. 943. 79/08/07. 68pp. Available at GPO.

7908080201 Forwards "Testing & Packaging of Scientific & Engineering Software to Achieve Portability," by ANL.
BENNETT, G. L. Research Support Branch. 79/07/12. 2pp.

--7908080205 "Testing & Packaging of Scientific & Engineering Software to Achieve Portability."
BUTLER, M.K.; EDWARDS, H.S.; EYBERGER, L.R. Argonne National Laboratory. 79/07/12. 9pp.

7908090640 Notification of cancellation of 790718 meeting w/EPA to discuss implementation of App I & compliance w/Clean Air Act.
LO, R. Environmental Evaluation Branch. 79/07/17. 2pp.

7908100531 Forwards "Testing & Packaging of Scientific & Engineering Software to Achieve Portability."
BENNETT, G.L. Research Support Branch. 79/07/12. 2pp.

7908140306 NUREG-0170 V1
"FES on Transportation of Radioactive Matl by Air & Other Modes."
* Office of Standards Development. 77/12/31. 300pp. Available at NTIS.

--7908140326 NUREG-0170 V2
"FES on Transportation of Radioactive Matl by Air & Other Modes."
* Office of Standards Development. 77/12/31. 450pp.

7908150465 "Windscale Inquiry." Vol 1 & Annexes 3-5.
PARKER, J. Affiliation Unknown. 78/01/26. 4pp.

--7908150471 "Low-Level Radiation Effects: Mancuso Study."
SAGAN, L.A. Electric Power Research Institute. 79/08/08. 8pp.

--7908150475 "Cancer Mortality in Hanford Workers."
MARKS, S.; GILBERT, E.S.; BREITENSTEIN, B. Battelle Memorial Institute, Pacific Northwest Laboratory. IAEA-SM-224. 79/08/08. 22pp.

--7908150479 Forwards 780201 draft "Review of Mancuso, Stewart & Kneale Radiation Exposures of Hanford Workers Dying From Cancer & Other Causes" & preliminary comments on revised Mancuso, Stewart & Kneale proportional mortality study of workers.
LAND, C.E. HEW, Dept. of, US Public Health Service. 78/03/03. 30pp.

--7908150487 Forwards critique of Mancuso, Stewart & Kneale rept re radiation exposures of workers per request. Supports decision that further analysis of data be handled by different contractor. Rept has no regulatory implications.
KLEITMAN, D.J. Massachusetts Institute of Technology. 78/03/02. 51pp.

--7908150491 "Low Level Radiation & Cancer Deaths." Forwarded 780221 to M Parsont from D Allen.
SANDERS, B.S. Affiliation Unknown. HP 173911. 77/09/15. 18pp.

7908160095 Discusses C Johnson radiation health effects studies of Plutonium releases, published in 790413 Science & 790423 Newsweek. NRC, EPA & NIH found significant errors in draft copy. Second draft submitted for further comment.
GOLDSMITH, R. Radiological Health Standards Branch. 79/06/11. 2pp.

7908160135 Responds to 790501 ltr re Reg Guide 2.36, "Emergency Planning for Research Reactors." Reg Guide amplifies matl in ANS std. Will endorse ANS-15.16 & addl guidance as necessary, especially for high risk facilities.
MINOGUE, R.B. Office of Standards Development. 79/06/15. 2pp.

7908170164 Notification of 790718 meeting w/EPA in Bethesda, MD to discuss implementation of App I & compliance w/Clean Air Act.
LO, R. Environmental Evaluation Branch (Pre 790625). 79/07/17. 2pp.

7908170166 Provides guidance & funding to BNL re evaluations of inservice testing programs for operating nuclear power plants. Requests indication of DOE acceptance of guidance to BNL.
EISENHUT, D.G. Division of Operating Reactors. 79/06/27. 6pp.

7908170175 Requests that encl DOE 790709 ltr re request for rulemaking to exempt low enriched U & Tc-99 in metal scrap be referenced in preliminary DES.
HENRY, J.J. Transportation & Product Standards Branch. 79/07/23. 2pp.

--7908170236 Requests rulemaking to exempt low enriched U & Tc-99 in metal scrap & allow for sale.
VOIGHT, W.R. Energy, Dept. of. 79/07/09. 2pp.

7908170255 Notification of 790809 meeting w/ASME in Bethesda, MD to discuss proposed changes to ASME Section III acceptance stds.
GAMBLE, R.M. Materials Engineering Branch. 79/07/19. 1p.

7908300246 Lists util recipients of IE Circular 79-17, "Contact Problem in SB-12 Switches on GE Metalclad Circuit Breakers."
PAPPAS, H. Region 3, Chicago, Office of the Director. 79/08/15. 2pp.

7908300321 Discusses Personnel Dosimetry Overview Committee. Commercial processor visitation program will be extended. Notice of rulemaking will be published in FR. Rept of activities will be submitted to Congress.
MINOGUE, R.B. Office of Standards Development. 79/08/02. 2pp.

7908300595 Discusses site visitation program to eight commercial suppliers to study inconsistencies on personnel dosimetry pilot study.
CAMPBELL, G.W. Lawrence Livermore Laboratory. 79/06/18. 2pp.

PR PROPOSED RULE

7906210050 Comments on proposed rules 10CFR19 & 20: opposes elimination of dose averaging formula. There is no proof of improvement of worker health environ.
ARNOLD, D. Iowa Electric Light & Power Co. 79/04/23. 1p.

--7906210050 Comments on proposed rules 10CFR19 & 20: opposes elimination of dose averaging formula. There is no proof of improvement of worker health environ.
ARNOLD, D. Iowa Electric Light & Power Co. 79/04/23. 1p.

7907090108 Comments on proposed rule 10CFR35: concurs w/petition of GB Taplin to remove present limitations on use of approved radiopharmaceuticals for non-listed indications.
MECKELNBURG, R.L. Delaware Medical Laboratories, Inc. WI, Delaware. 79/05/10. 1p.

7908010359 Comments on proposed rule 10CFR9: proposed "plain English" revision lacks clarity & is repetitive.
LAWTON, M.D. Affiliation Unknown. 79/06/06. 3pp.

7908010641 Comments on proposed rule 10CFR9 w/minor changes, "plain English" revision of FOIA rule will be understandable to general public.
MCMILLIN, H.W. Navy, Dept. of. 79/06/18. 3pp.

7908020493 Responds to comments on SECY-79-192 re proposed revision of 10CFR71, "Packaging of Radioactive Matl for Transport." General licenses under 10CFR71.12 are justified. NRC working w/DOT to devise better sys for control of exposures.
MINOGUE, R.B. Office of Standards Development. 79/06/20. 2pp.

7908030150 Requests info on any revisions, expansions, amends or final policy statements issued re proposed "Licensing Procedures for Geologic Repositories for High Level Radioactive Wastes."
GARRETT, S.M. Hanford Conversion Project. 79/06/17. 1p.

7908060125 Responds to 790617 ltr. Intends to replace policy statement on licensing procedures for geologic depositories for high level radioactive wastes. Advance notice of rulemaking re technical criteria for licensing being prepared.
DIRCKS, W.J. Office of Nuclear Material Safety & Safeguards. 79/07/11. 1p.

7906140182 Comments on proposed rules 10CFR31 & 32: endorses rules authorizing veterinary use of byproduct matl for in vitro testing.
MICHEL, R.L. Tennessee, Univ. of. 79/05/15. 1p.

7908140182 Comments on proposed rules 10CFR31 & 32: endorses rules authorizing veterinary use of byproduct matl for in vitro testing.
MICHEL, R.L. Tennessee, Univ. of. 79/05/15. 1p.

7908140306 NUREG-0170 V1
"FES on Transportation of Radioactive Matl by Air & Other Modes."
* Office of Standards Development. 77/12/31. 300pp. Available at NTIS.

--7908140326 NUREG-0170 V2
"FES on Transportation of Radioactive Matl by Air & Other Modes," Vol 2.
* Office of Standards Development. 77/12/31. 450pp.

--7908140326 NUREG-0170 V2
"FES on Transportation of Radioactive Matl by Air & Other Modes."
* Office of Standards Development. 77/12/31. 450pp.

7908170189 Notice of final rule 10CFR51, "U Fuel Cycle Imports From Spent Fuel Reprocessing & Radwaste Mgt" effective 790904. Rule establishes revised impact value & specifies fuel & cycle issues to be considered in licensing process.
CHILK, S. J. Office of the Secretary of the Commission. 7590-01. 79/07/27. 63pp.

7908220271 Forwards replacement page to proposed revision of 10CFR50 App J & revised pages for value impact statement.
ARNDT, G. Structures & Components Standards Branch. 79/08/01. 5pp.

7908220609 Comments on proposed Reg Guide 1.XXX: ref 781205 ltr MAPP/0500/s/78 for comments on requirements for delta ferrite content in autogenous welds.
VANKAN, K. V. India. MAPP/05000/S/79. 79/06/07. 1p.

7908230263 Comments on proposed rule 10CFR73: supports proposed rule re shipping of spent matls. Shipper should be required to prepare emergency plans. Suggests embargo on addl domestic shipments until safe permanent waste site is found.
MARTIN, T. Affiliation Unknown. 79/07/10. 1p.

7908230269 Comments on proposed rule 10CFR73: risk probability involving spent fuel too low & cost/benefit ratio too unfavorable to justify regulatory change.
MINGLE, J. O. Kansas State Univ. 79/07/24. 2pp.

7908230274 Comments on proposed rule 10CFR73: opposes rule. Urges suspension of operation of nuclear plants & transportation of spent fuel pending determination that spent fuel poses no hazard to public health.
GOVER, N. Affiliation Unknown. 79/07/01. 2pp.

7908230280 Comments on proposed rule 10CFR9: proposed regulation too difficult to understand. Forwards list of approx 50 other documents re guidance in protection against industrial sabotage. Suggests NRC review for possible consolidation.
DAIL, L. C. Duke Power Co. 79/06/27. 6pp.

7908230285 Comments on proposed rule 10CFR50: supports addl regulation of spent fuel shipments. Period allowed for comments is too short. Forwards list of people to whom notices should be sent.
LEWIS, M. I. Affiliation Unknown. 79/07/23. 2pp.

7908230644 Comments on proposed rule 10CFR73: supports proposed rule on safe shipment of spent fuels. Shipments should not pass through any military ocean terminal or near explosive or volatile matl.
ROGERS, M. L. Affiliation Unknown. 79/08/16. 2pp.

7908310296 Forwards petition for rulemaking 10CFR140 filed by Public Citizen Litigation Group & Critical Mass Energy Project in Washington, DC.
SCHULTZ, W. R. Schultz, W. B. 79/07/25. 1p.

--7908310300 Petition for rulemaking NRC is requested to investigate Mar 1979 TMI accident per 10CFR140.82 & to determine incident as extraordinary nuclear occurrence.
SCHULTZ, W. B. Schultz, W. B. POLLOCK, R. Critical Mass Energy Project. SCHEFFEY, T. B. Public Citizen Litigation Group. 79/07/24. 12pp.

PRM PETITION FOR RULEMAKING

7908030337 Comments on petition for rulemaking 10CFR35-1: supports petition to amend "Human Uses of Byproduct Matl."
CAPITANIO, M. A., HARCKE, H. J., MARKOWITZ, R. I. Affiliation Unknown. 79/05/10. 1p.

7908020501 Comments on petition for rulemaking 10CFR20-13: opposes petition because petitioner personal experience is not representative of health physics programs. Certification program would duplicate current reviews.
HALL, D. C. Affiliation Unknown. 79/05/18. 2pp.

7908030512 Notice that SH Levine has filed petition for rulemaking to amend 10CFR73, "Physical Protection of Plants & Matl." Comments must be submitted by 790911.
HOYLE, J. C. Office of the Secretary of the Commission. 79/07/05. 3pp.

--7908030516 Forwards 790131 ltr to TG Williamson. Supports request that 10CFR73, "Physical Protection of Plants & Matl," be revised. High dose rate creates hardship for educational institutions.
LEVINE, S. H. Pennsylvania State Univ. 79/02/02. 2pp.

7908070628 NUREG-0217
"NRC Task Force Rept on Review of Federal/State Program for Regulation of Commercial Low Level Radioactive Waste Burial Grounds; Analysis of Public Comments," Suppl 1.
* Office of Nuclear Material Safety & Safeguards. 77/10/31. 17pp.

7908070721 Comments on petition for rulemaking 10CFR50-23: 10CFR50 licensees & license applicants should formulate coordinated offsite emergency response plan, but distance should be 30 miles & expense split by licensee/applicant, state & NRC.
BAILEY, P. G. Affiliation Unknown. 79/06/15. 1p.

7908080681 Value impact statement re proposed rule to add veterinarians to in vitro general license. Recommends approval.
BOZIK, D. A. Radiological Health Standards Branch. 79/07/24. 5pp.

7908130353 Comments on petition for rulemaking 10CFR20-13: agrees that NRC certification of health physicist would ensure stds. Favors strictly advisory role for physicist.
RUBY, L. Affiliation Unknown. 79/04/19. 2pp.

7908130560 Comments on petition for rulemaking 10CFR50-23: opposes requirement for annual evacuation drills in sector of 7 degrees to distance of 30 miles from facility.
JOHNSON, W. B. Affiliation Unknown. 79/06/15. 1p.

7908140400 "NRC Div of Waste Mgt Staff Response to NRDC Allegations of Fact."
* Division of Waste Management. 79/08/08. 26pp.

7908140416 NUREG-0217
"NRC Task Force Rept on Review of Federal/State Program for Regulation of Commercial Low Level Radioactive Waste Burial Grounds."
CUNNINGHAM, R. E., DRAGUNETTE, K. S. Division of Fuel Cycle & Material Safety. RAUAN, R. G. Office of State Programs. PB-263 890. 77/03/31. 67pp.

7908150387 Comments on petition for rulemaking 10CFR20-13: govt agencies entering into certification leads to political pressure. Prefers certification by American Board of Health Physics.
COURTNEY, J. C. Affiliation Unknown. 79/04/19. 2pp.

7908160019 Comments on petition for rulemaking 10CFR2-7: requests change in rule to allow Ruzin Alliance to be official intervenor in matters re Shearon Harris plant.
FLAGLER, M. C. Affiliation Unknown. 79/04/09. 1p.

7908160020 Denies 790719 request that NRC form review board of industry members to clarify positions of industry prior to issuance of new regulations. Describes procedures for distributing amends to NRC regulations to licensees & interested persons.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/07/19. 3pp.

--7908160022 Notice of denial of Nondestructive Testing Mgt Association 780719 petition for rulemaking PRM-7-1. Draft public announcement encl.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/07/18. 7pp.

7908170189 Notice of final rule 10CFR51, "U Fuel Cycle Imports From Spent Fuel Reprocessing & Radwaste Mgt" effective 790904. Rule establishes revised impact value & specifies fuel & cycle issues to be considered in licensing process.
CHILK, S. J. Office of the Secretary of the Commission. 7590-01. 79/07/27. 63pp.

7908170247 Submits, for transmittal to PDR, quarterly rept re petitions for rulemaking as of 790630.
FELTON, J. M. Division of Rules and Records. 79/07/19. 17pp.

7908220405 Approves petition for rulemaking 50-17, "No Significant Hazards Consideration," subject to listed text changes.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/08/06. 1p.

7908230445 Submits petition to amend 10CFR73 to make physical security requirement during transport of spent fuel shipments consistent w/philosophical approach wherein responsibility for matl transport lies w/carrier.
EDLOW, S. Edlow International Co. 79/06/29. 2pp.

7908230454 Forwards 11 letters of comment re 10CFR30, petition that NRC be divided into two separate entities, one responsible for fissile matls & another for byproduct matls. W/o encl.
HENRY, J. J. Transportation & Product Standards Branch. 79/07/23. 2pp.

7908240063 Forwards for signature ltr notifying Tech/Ops of denial of petition & FR notice of denial of petition for rulemaking.
MINOGUE, R. B. Office of Standards Development. 79/07/05. 2pp.

--7908240069 Denies 770415 petition re surface radiation level limits for radiographic exposure devices. FR notice of denial encl.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/07/05. 1p.

--7908240072 Notice of denial of 770415 Tech/Ops petition for rulemaking re surface radiation level limit for radiographic exposure devices.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/07/05. 6pp.

7908300237 Ack receipt of 760112 ltr w/rept, "Improvements Needed in Land Disposal of Radioactive Wastes - Problem of Centuries." Forwards statement on actions NRC has taken to implement recommendations in rept.
ANDERS, W. A. Commission. 76/04/02. 10pp.

--7908300244 Forwards statement of actions taken by NRC to implement recommendations in GAO 760112 rept, "Improvements Needed in Land Disposal of Radioactive Wastes - Problem of Centuries." W/o encl.
ANDERS, W. A. Commission. 76/04/02. 2pp.

--7908300251 Forwards statement of actions taken by NRC to implement recommendations in GAO 760112 rept, "Improvements Needed in Land Disposal of Radioactive Wastes - Problem of Centuries." W/o encl.
ANDERS, W. A. Commission. 76/04/02. 2pp.

PROJ PROJECTS - PREDOCKET LICENSING

7908010140 Submits responses to 760614 questions. Proposed embankment will not be overtopped by 100-yr & 1/2 PMF precipitation events. In event of dam failure, flood waters will be out of channel banks for max distance of 3 miles downstream.
HULMAN, L. G. Hydrology Meteorology Branch. 79/07/20. 2pp.

7908010152 "Evaluation of Cost Parameters for Hypothetical U Milling Operations & Ore Transportati Sys in Western US," prepared by Dames & Moore.
* Argonne National Laboratory. 77/07/01. 90pp.

7908010161 Submits responses to questions on tailings disposal below grade, per 780105 ltr.
REHEMEYER, P. C. Union Carbide Corp. 78/02/01. 8pp.

7908010173 Responds to request for info re const of liner installed in tailings pond at Western Nuclear Sherwood Project northwest of Spokane, WA. Submits details of matl specs & costs.
WILLIAMS, R. E. Idaho, Univ. of. 78/03/01. 7pp.

7908010181 "Bond Estimate for Mill & Waste Disposal."
* Utah, State of. 76/09/13. 1p.

7908010187 "Bond Evaluation."
* Lucky Mc Uranium Corp. 77/07/26. 1p.

7908010305 Tailings Abandonment & Stabilization," Rept 2.
* D'Appolonia Consulting Engineers, Inc. 77/09/30. 7pp.

7908010306 Forwards discussion re cost estimates for mill decommissioning.
BEACH, G. Wyoming, State of. 78/02/09. 3pp.

7908010310 Comments on license application & environ rept. Application & rept are too general; subsequent submittals should include subsurface geologic maps & description of aquifer sequence.
SCARANO, R. A. Uranium Recovery Licensing Branch. 79/06/08. 10pp.

7908020582 Submission & description of discovery documents per ASLB 790517-19 request for 50 documents resulting from util "green-dotted" category. Certificate of Svc encl.
GOLDBERG, J. R. Branch 2. VOGLER, B. H. Anti-Trust Division. 79/07/09. 23pp.

7908030001 "Environ Effects of Present & Proposed Tailings Disposal."
* D'Appolonia Consulting Engineers, Inc. 77/10/31. 11pp.

7908030631 Forwards summary of stack tests on yellowcake packaging & drying stacks at U mills. Attempts to correlate emission rate w/mill operating parameters have been unsuccessful.
DOUGLAS, R. L. Environmental Protection Agency. 78/10/02. 5pp.

7908070226 Responds to ASLB 790515-17 request for 50 documents resulting from util production of green-dotted discovery documents. Describes significance of documents & relation to antitrust laws. Certificate of Svc encl.
GOLDBERG, J. R., VOGLER, B. H. Anti-Trust Division. 79/07/09. 400pp.

7908070523 RM77-419
"Tailings Abandonment & Stabilization, Rept 2," engineers rept.
* D'Appolonia Consulting Engineers, Inc. RM77-419. 77/09/30. 4pp.

7908070594 RM77-419
"Environ Effects of Present & Proposed Tailings Disposal Practices, Rept 3," Vol 2, apps.
* D'Appolonia Consulting Engineers, Inc. RM77-419. 77/10/31. 11pp.

7908070831 "Enviro-Clear Delkor Horizontal Belt Vacuum Filter."
* Amstar Corp., Enviro Clear. 79/08/07. 10pp.

7908080346 Discusses D Dressen 790626 trip rept re water & soil sample analysis of Cotter Corp U mill tailing pile impact. Urges consideration of lead isotope mixing ratios for more reliable assessment of tailing pile impact.
GLADNEY, E. S. Los Alamos Scientific Laboratory. H-8-79-221. 79/06/27. 2pp.

--7908080355 Discusses rept, "Lead Isotopes as Indicators of Environ Contamination From U Mining & Milling Industry in Grants Mineral Belt, NM."
DRESSEN, D. R. Los Alamos Scientific Laboratory. H12-79-263. 79/06/26. 14pp.

--7908080358 "Lead Isotopes as Indicators of Environ Contamination From U Mining & Milling Industry in Grants Mineral Belt, NM."
CURTIS, D. B., GANCARZ, A. J. Los Alamos Scientific Laboratory. 79/06/26. 8pp.

7908080709 Forwards DOE & OR State Historic Preservation Ofc comments re DES.
WILCOX, K. Oregon, State of. 79/06/18. 3pp.

7908080717 Forwards 790612 ltr from WA Wahler & Associates re movement of existing tailings, design of tailings dewatering drains & timing of utilization of migration of raffinates criteria, per J Logan 790605 ltr.
MCGRATH, E. J. McGrath, E. J. 79/06/18. 5pp.

7908090016 Petition submitted by util for NRC review of ALAB-550, per 10CFR2.786(b). Decision is erroneous w/respect to important questions of fact, law & policy. Certificate of Svc encl.
BARRY, D. N. Barry, David N. III. WOODLAND, I. F. Gibson, Dunn & Crutcher. 79/06/29. 13pp.

7908090352 Comments on NUREG-0511, Section 6.2.8.2.7.1 re average individual occupational exposure estimates. Th-230 should be included in assessment of occupational exposure from inhalation of yellowcake dust.
TUCHFELD, G. Dames & Moore. 79/06/15. 2pp.

7908090357 Forwards J Logan 790606 ltr re Cannon City mill expansion project.
MCGRATH, E. J. McGrath, E. J. 79/06/14. 6pp.

7908090437 Expresses dissatisfaction w/draft GEIS on U milling (NUREG-0511). Newspaper article encl.
LEWIS, M. Affiliation Unknown. 79/07/01. 5pp.

7908090470 Ack receipt of draft GEIS re U milling (NUREG-0511). No comments on draft. Requests copy of final statement when available.
HEISS Pennsylvania, State of. 79/06/29. 1p.

7908090518 Forwards description & cost estimate for spent fuel storage installation, as requested in 790522 ltr. Concept is viable & offers only storage concept approved by NRC. Info may be used in final GEIS.
CULP, W. G. Stone & Webster, Inc. 79/05/23. 4pp.

--7908090520 Submits estimates of nuclear power growth for 1985-95.
ROBERTS, J. P. Fuel Process. & Fab. Branch (Prm 790727). 79/03/30. 1p.

--7908090521 NUREG-0332
Draft "Health Effects Attributable to Coal & Nuclear Fuel Cycle Alternatives."
* Office of Nuclear Reactor Regulation. 79/05/23. 7pp.

--7908090522 NUREG-0332
Draft "Health Effects Attributable to Coal & Nuclear Cycle Alternatives."
GOTCHY, R. L. Division of Site Safety & Environmental Analysis. 77/09/30. 29pp.

7908090525 Notifies that IL state environ agencies have been given opportunity to comment on draft GEIS on U milling (NUREG-0511). No comments have been received.
HORNBACKER, T. E. Illinois, State of. 79/06/22. 1p.

7908090544 Forwards 790518 newsletter as comment on decision to license Cotter Corp U mills in Canon City, Co.
PULS, M. Folks United to Thwart Unsafe Radiation Emission (FUTURE). 79/05/31. 1p.

7908100588 Comments on draft EIS re U milling. Consideration to be given to emergency fund for use in event of failure of integrity of tailings dump, flood, earthquake or rapid disintegration of cover.
BURNS, J. W. California, State of. M-25. 79/06/22. 3pp.

7908130404 Comments on draft EIS re U mining. If U production is considered in State of VA, various factors addressed in EIS should be evaluated on site-specific basis in terms of physical & cultural conditions.
JACKSON, J. B. Virginia, State of. 79/06/29. 1p.

7908130406 Notifies of review of draft EIS. Forwards comments submitted by Parks & Wildlife Dept, General Land Ofc, Air Control Board, Dept of Water Resources, Railroad Commission & Budget & Planning Ofc of State of TX.
HARLEY, D. E. Texas, State of. 79/07/02. 11pp.

7908140145 Comments on NUREG-0511, Vol 1. Requests explanation of Table 6, Page 26, re premature deaths health effects of milling.
CHONG, L. R. Affiliation Unknown. 79/07/09. 1p.

7908140152 Forwards J Logan 790605 ltr to WA Wahler & Associates re criteria for degradation of water quality. WA Wahler & Associates impoundment drawing & S Ferguson 790523 memo re standardized cancer mortality rate.
MCGRATH, E. J. McGrath, E. J. 79/06/12. 34pp.

7908140198 "Evaluation of Long-Term Stability of U Mill Tailing Disposal Alternatives," final rept.
NELSON, J. D., SHEPHERD, T. A. Argonne National Laboratory. 31-109-38-4199. 9-43-9. 78/04/30. 348pp.

7908140333 Notifies of review of U milling draft GEIS by agencies of State of WA. No substantive comments.
MAHART, A. Washington, State of. 79/07/10. 1p.

7908140489 Forwards summary of Nov 1978 meeting w/American Elec Power. Suggests that util be contacted re status of plans for const of proposed plants.
VASSALLO, D. B. Division of Project Management. 79/07/18. 6pp.

7908140517 Responds to FOIA request for documents relating to possible const of nuclear plants in next 15 yrs in VA or WV by Appalachian Power Co or GE. App A lists documents encl.
FELTON, J. M. Division of Rules and Records. 79/08/08. 2pp.

--7908140526 Forwards press release re program to investigate possibility of bldg nuclear plant in central VA.
TILLINGHAST, J. American Electric Power Co., Inc. 78/07/25. 5pp.

--7908140531 Summary of 781102 telcon w/S Miliati of American Electric Power re Central VA Units 1 & 2.
HARLESS, B. L. Environmental Projects Branch 2. 78/11/07. 2pp.

7908150243 Statement before Senate Subcommittees on Science, Technology, & Space & Surface Transport re transportation of radioactive matls in USA & throughout world.
JEFFERSON, R. M. Sandia Laboratories. 78/08/16. 19pp.

7908160085 Ack receipt of 790611 ltr w/Apr monthly rept. Draft Vol 1 & 3 to final statement undergoing internal review.
ROBERTS, J. P. Fuel Reprocess. & Recycle Branch (Prs 790727). 79/07/05. 1p.

7908170184 Forwards correspondence re suspected molybdenosis in cattle near Bosco well.
MCGRATH, E. J. McGrath, E. J. 79/07/27. 4pp.

7908170215 Ack receipt of draft GEIS re U milling project. As result of review, finds that no comment is necessary at present.
BAGGETT, C. North Carolina, State of. 104-79. 79/07/06. 1p.

7908170258 Forwards comments re draft GEIS for U milling received 790418.
MEIEROTTO, L. E. Interior, Dept. of. 79/07/30. 8pp.

7908170333 Ack receipt of 790720 ltr w/June monthly rept. Arrangements are being made for printing matl.
ROBERTS, J. P. Fuel Reprocess. & Recycle Branch (Prs 790727). 79/08/06. 1p.

7908170465 FBDU 218-1
"Characterization of U Tailings Cover Matls for Radon Flux Reduction," draft rept prepared for ANL.
* Ford Bacon & Davis Utah, Inc. 79/01/31. 150pp.

7908170493 EPRI-N4-768
"Tornado Missile Risk Analysis: Probability Modeling, Simulation Methodology & Case Studies," final rept.
TWISDALE, L. A., DUNN, W. L., CHU, J. Carolina Power & Light Co. NP-768. 78/05/31. 200pp.

7908170603 Forwards comments on draft GEIS on U milling. Discusses problems in addressing dose parameters.
CUSTARD, C. Health, Education & Welfare, Dept. of. 79/07/26. 3pp.

7908170625 Discusses review results of GEIS re U milling. Forwards ID Health & Welfare Dept comments outlining ID regulations re maint of water quality & air pollution control.
DEMO-RYBUS, P. Idaho, State of. 79/07/23. 1p.

--7908170629 Comments on GEIS. Source must comply w/"Rules & Regulations for Control of Air Pollution in ID." Milling operations must comply w/"ID Water Quality Stds & Wastewater Treatment Requirements."
STOKES, L. W. Idaho, State of. 79/07/02. 2pp.

7908200001 NUREG/CR-0723
"Calculations of Skyshine Gamma-Ray Dose Rates From Independent Spent Fuel Storage Installations Under Worst Case Accident Conditions."
PACE, J. V., CRAMER, S. N., KNIGHT, J. R. Oak Ridge National Laboratory. FIN-B-0102. ORNL/NUREG/TM-3. 79/08/02. 45pp.

7908200398 Forwards initial comments on U mills draft generic EIS, submitted by Environ Improvement Div.
WOLFF, T. A. New Mexico, State of. 79/07/05. 15pp.

--7908200399 Testimony of TA Wolff on draft GEIS re continued care fund of U mills.
WOLFF, T. A. New Mexico, State of. 79/07/05. 6pp.

--7908200401 Radiation Protection Act of State of NM.
* New Mexico, State of. 79/07/05. 5pp.

--7908200403 "Phase II, Title I, Engineering Assessment of Inactive U Mill Tailings, Shiprock Site, Shiprock, NM," prepared for ERDA, Grand Junction, Co.
* Ford Bacon & Davis Utah, Inc. E(05-1)-1658. 77/03/31. 6pp.

--7908200404 "Phase II, Title I Engineering Assessment of Inactive U Mill Tailings Vitro Site, Salt Lake City, UT," prepared for ERDA, Grand Junction, Co.
* Ford Bacon & Davis Utah, Inc. E(05-1)-1658. 76/04/30. 5PP.

--7908200407 "Continued Care of U Mill Sites: Some Economic Considerations."
HARRINGTON, W. Resources for The Future, Inc. 78/01/31. 25pp.

7908220180 Forwards 790706 ltr from T Smith of Cotter Corp to CO Dept of Health re U, Ra-226, selenium & molybdenum concentrations in AR River. CO Univ study excerpts will be sent shortly.
MCGRATH, E. J. McGrath, E. J. 79/07/20. 9pp.

7908220560 Forwards interim rept on analyses of water samples collected at Canon City, CO.
DRESSEN, D. R. Los Alamos Scientific Laboratory. 79/08/02. 10pp.

7908220566 Forwards comments on draft GEIS on U milling.
* Alabama, State of. 79/08/10. 2pp.

7908230079 Forwards final selenium analytical rept re samples collected in Lincoln Park/Canon City, CO area in June 1979.
GLADNEY, E. S. Los Alamos Scientific Laboratory. HB-79-277. 79/08/02. 2pp.

7908230133 Testimony of W Bateman before House Committee on Interior & Insular Affairs re spent fuel storage.
BATEMAN, W. Energy, Dept. of. 79/08/01. 7pp.

7908270220 Discusses review of DOE 780511 & 790522 ltrs re changes in light water breeder reactor plant operating pressure & in predicted flow coefficient. No change in conclusions in SER necessary per Jul 1976 SER & two ltrs cited. Ltrs encl.
VARGA, S. A. Assistant Director for Light Water Reactors. 79/07/31 1P

--7908270226 Notifies of two changes made in operating procedures of light water breeder reactor at facility re predicted flow coefficient of reactivity & further reduction in plant operating pressure.
BRODSKY, R. S. Energy, Dept. of. 79/05/11 1p.

7908270346 Responds to 790530 ltr. Defines "base case." Cotter Mill incorporates addl controls to reduce effluents below that of base case. State of CO Dept of Health anticipates no public health hazard from Linclon Park wells.
HAZLE, A. J. Colorado, State of. 79/06/19 6pp.

7908270486 Discusses recomputations of consequence estimates in NUREG-0194, "Calculations of Radiological Consequences From Sabotage of Shipping Casks for Spent Fuel & High Level Waste."
MCGRATH, P. E. Sandia Laboratories. 77/09/20 6pp.

7908280226 Summarizes 781202-04 meeting of Keystone radwaste mgt discussion group re near-term storage of spent fuel from domestic & foreign nuclear power reactors.
[illegible] I. C., CRAIG, R. W., DEERE, D. A. Keystone Center for Continuing Education. 79/01/26 9pp.

7908300032 Response by util to State of CA Dept of Water Resources fourth set of interrogatories. Submits info re neighboring entities. Verification of EF Kaprielian, WM Gallavan & NH Dailies & Certificate of Svc encl.
MEISS, R. L. Pacific Gas & Electric Co. DOYLE, M. M. McCutchen, Doyle, Brown & Emerson. 79/07/16 74pp.

7908300165 "Light-Water Breeder Reactors." Preliminary Safety & Environ Info Document, Vol III.
* Energy, Dept. of. 79/01/31 138pp.

7908300204 "Fuel-Cycle Facilities." Preliminary Safety & Environ Info Document, Vol VII.
* Energy, Dept. of. 79/01/31 230pp.

7908300284 Discusses extension of deadline for public to comment on NUREG-0511. Requests that proposed rules re U milling be sent. Draft GEIS fails to account for total Rn-222 Ci to be released from mill tailings piles.
JOHNSRUD, J. H. Environmental Coalition on Nuclear Power. 79/07/25 2pp.

7908300323 Requests denial of util 790629 request for review of ALAB-550. Petition fails to raise question of fact, law or policy of recurring importance. Decision is well-reasoned & consistent. Certificate of Svc encl.
GOLDBERG, J. R., VOGLER, B. H., RUTBERG, J. Anti-Trust Division. 79/07/16 8pp.

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

7908080714 Submits rept of technical noncompliance re inadequate transfer of licensed matl & failure to comply w/univ matl comply w/univ matl control regulations, per application for License 34-11912-02.
AUSTIN, B. T. Wright State Univ. 79/05/09 2pp.

7908130040 Confirms 790621 telcon w/NC Mosely & SE Bryan. Customers have been informed of substantial safety hazard or significant deficiency & of corrections to steam generator water level protection sys.
ANDERSON, T. M. Westinghouse Electric Corp. NS-TMA-2104. 79/06/22 5pp.

QA999 QUALITY ASSURANCE INSPECTIONS

7908020178 Forwards QA Program Insp Rept 99900001/79-01 on 790508-11. No noncompliance noted.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/22 2pp.

--7908020181 QA Program Insp Rept 99900001/79-01 on 790508-11. No noncompliance noted. Major areas inspected: implementation of 10CFR50, App B.
MCNEILL, W. M., WHITESELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 79/05/22 7pp.

7908020289 Advises that QA program described in rept BG-TOP-1, Revision 2A, is being implemented satisfactorily.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/06/05 2pp.

7908130376 Forwards QA Program Insp Rept 99900346/79-01 on 790521-24 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Office of the Director. 79/06/08 2pp.

7908070165 Ack receipt of 790504 & 0608 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900248/79-01.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/14 1p.

--7908070171 Responds to NRC 790517 ltr re deviation noted in QA Program Insp Rept 99900248/79-01. Corrective actions: post-weld heat treatment procedure revised to include review of accumulated post-weld heat treatment time. HET-1301-3 encl.
WOODS, P. D. Union Pump Co. 79/06/08 3pp.

--7908070177 Ack receipt of 790504 ltr. Requests info re controls needed to assure that review of accumulated post-weld heat treatment time at temp will be accomplished.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/17 1p.

--7908070182 Responds to QA Program Insp 99900248/79-01 on 790129-0202. Corrective actions: welding procedures will be reviewed & revised. GE 790427 ltr encl.
WOODS, P. D. Union Pump Co. 79/05/04 3pp.

--7908070185 Confirms 790330 request for extension until 790420 for reply to QA program Insp Rept 99900248/79-01.
WOODS, P. D. Union Pump Co. 79/03/30 1p.

--7908070188 Forwards QA Program Insp Rept 99900248/79-01 on 790129-0202 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/02/14 2pp.

--7908070191 Notice of deviation from insp on 790129-0202.
* Region 4, Dallas, Vendor Inspection Branch. 79/02/13 2pp.

--7908070195 QA Program Insp Rept 99900248/79-01 on 790129-0202. Noncompliance noted: some weld procedure specs did not list all applicable nonessential variables & specific post-weld heat treatment time at temp was not defined on records.
ELLERSHAW, L. E., HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/02/13 9pp.

7908080001 Forwards QA Program Insp Rept 99900375/79-01 on 790604-08. No noncompliance noted.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/27 2pp.

--7908080003 QA Program Insp Rept 99900375/79-01 on 790604-08. No noncompliance noted. Major areas inspected: implementation of 10CFR50, App B & applicable codes & stds.
SUTTON, J. W., WHITESELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 51200. 79/06/27. 4pp.

7908080005 Forwards QA Program Insp Rept 99900316/79-01 on 790625-29. No noncompliance noted.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 51300. 79/07/18. 2pp.

--7908080006 QA Program Insp Rept 99900316/79-01 on 790626-29. No noncompliance noted. Major areas inspected: action on previous insp findings, vendor activities, nonconformances & corrective actions, training, matl identification & control.
OLLER, R. E., HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/07/17. 10pp.

7908080008 Ack receipt of 790712 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900510/79-02.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/19. 1p.

--7908080009 Responds to NRC 790614 ltr re deviation noted in QA Program Insp Rept 99900510/79-02. Corrective actions: BWS & DWS tanks to be incorporated into Tech Spec 243. Will instruct vendor to reanalyze tank seismic response & resubmit calculations.
DURHAME, R. A. Unitime Corp. 79/07/12. 2pp.

--7908080010 Forwards QA Program Insp Rept 99900510/79-02 on 790521-25 & notice of deviation. Notice of deviation not encl.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/14. 2pp.

--7908080012 QA Program Insp Rept 99900510/79-02 on 790521-25. Noncompliance noted: Tech Spec for borated water storage tank & demineralized water storage tank contained seismic response spectra which had been superseded. COSTELLO, J. R.; ANDERSON, D. G.; HALE, C. J. Region 4, Dallas, Vendor Inspection Branch. 51200 79/06/13. 12pp.

7908080013 Forwards QA Program Insp Rept 99902292/79-01 on 790604-08. No noncompliance noted. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/20. 2pp.

--7908080014 QA Program Insp Rept 99900292/79-01 on 790604-08. No noncompliance noted. Major areas inspected: implementation of 10CFR50, App B & applicable codes & stds. SUTTON, J. W.; WHITESELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 51300 79/06/19. 3pp.

7908090087 Ack receipt of 790612 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900026/79-01. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/22. 1p.

--7908090092 Responds to NRC 790515 ltr re deviation noted in QA Program Insp Rept 99900026/79-01. Corrective actions: new welding procedures encompassing range of essential variables will be written & technicians will have visual examinations. SEME, J. A. Swepco Tube Corp. 79/06/12. 1p.

--7908090104 Forwards QA Program Insp Rept 99900026/79-01 on 790424-27 & notice of deviation. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/15. 2pp.

--7908090109 Notice of deviation from insp on 790424-27. * Region 4, Dallas, Vendor Inspection Branch. 79/05/15. 2pp.

--7908090115 QA Program Insp Rept 99900026/79-01 on 790424-27. Noncompliance noted: welding of SA-312 ASME Code Class 1 & 2 T-304 piping to three job orders not performed in full accordance w/specs. OLLER, R. E.; HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/05/11. 13pp.

7908090183 Forwards QA Program Insp Rept 99900264/79-01 on 790507-11. No noncompliance noted. POTAPOVS, K. D. Region 4, Dallas, Vendor Inspection Branch. 79/05/25. 2pp.

--7908090188 QA Program Insp Rept 99900264/79-01 on 790507-11. No noncompliance noted. Major areas inspected: actions on previous findings, implementation of 10CFR50, App B criteria & mfg process control. SUTTON, J. W.; WHITESELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 79/05/23. 8pp.

7908090209 Forwards QA Program Insp Rept 99900365/79-01 on 790508. No noncompliance noted. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/21. 2pp.

--7908090222 QA Program Insp Rept 99900365/79-01 on 790508. No noncompliance noted. Major areas inspected: followup on 10CFR50.55(e) const deficiency rept re failed resistance welds in strut matl. ELLERSHAW, L. E.; HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/05/17. 4pp.

7908090232 Forwards QA Program Insp Rept 99900277/79-01 on 790423-26. No noncompliance noted. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/11. 2pp.

--7908090237 QA Program Insp Rept 99900277/79-01 on 790423-26. No noncompliance noted. Major areas inspected: QA manual & program, design control, insp & tests & measurement & calibr. AGEE, J. R.; HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/05/10. 9pp.

7908100091 Ack receipt of 790516 & 790608 ltrs informing NRC of steps to correct deviation noted in QA Program Insp Rept 99900021/79-01. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/06. 1p.

--7908100097 Responds to NRC 790522 ltr re deviation noted in QA Program Insp Rept 99900021/79-01. Corrective actions: memo has been issued to all welding supervisors mandating proper welding procedure for specific thickness. HOWARD, R. E. Pullman, Inc.; Pullman Power Products Div. 79/06/08. 2pp.

--7908100104 Ack receipt of 790514 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900021/79-01. Requests addl info re action taken to correct use of unqualified welding procedure on weld C. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/22. 1p.

--7908100109 Responds to NRC 790423 ltr re deviation noted in QA Program Insp Rept 99900021/79-01. Corrective actions: procedure re reporting of out-of-calibr devices will be revised by 790710. HOWARD, R. E. Pullman, Inc.; Pullman Power Products Div. 79/05/14. 3pp.

--7908100114 Forwards QA Program Insp Rept 99900021/79-01 on 790327-30 & notice of deviation. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/04/23. 2pp.

--7908100118 Notice of deviation from insp on 790327-30. * Region 4, Dallas, Vendor Inspection Branch. 79/04/23. 2pp.

--7908100125 QA Program Insp Rept 99900021/79-01 on 790327-30. Noncompliance noted: failure of QA program to correct welding equipment calibr discrepancies; failure to select proper welding procedure spec for weld C. BARNES, I.; HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/04/20. 8pp.

7908100209 Ack receipt of 790619 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900358/79-01. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/06. 1p.

--7908100220 Responds to NRC 790517 ltr re deviation noted in QA Program Insp Rept 99900358/79-01. Corrective actions: procedures being written to identify personnel authorized to review & approve documents prescribing activities affecting quality. USHKA, A. J. ESB, Inc.; Exide Industrial Battery Div. 79/06/19. 3pp.

--7908100252 Forwards QA Program Insp Rept 99900358/79-01 on 790501-04 & notice of deviation. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/11. 2pp.

--7908100256 Notice of deviation from insp on 790501-04. * Region 4, Dallas, Vendor Inspection Branch. 79/05/17. 1p.

--7908100260 QA Program Insp Rept 99900358/79-01 on 790501-04. Noncompliance noted: failure to establish measures that identify personnel authorized to review, approve & release engineering documents per QA manual requirements. FOSTER, W. E.; HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/05/17. 12pp.

7908100388 Ack receipt of 790502 & 790625 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900353/79-01. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/09. 1p.

--7908100390 Responds to NRC 790605 ltr re deviation noted in QA Program Insp Rept 99900353/79-01. Corrective actions: complete Nov 1974 audit on file is available. SMITH, L. J. Gould, Inc. 79/06/25. 1p.

--7908100392 Responds to 790502 ltr. No further questions re items A & C. Item B is still incomplete. Specifies info missing from Nov 1974 audit. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/05. 1p.

--7908100393 Responds to NRC 790322 ltr re deviation noted in QA Program Insp Rept 99900353/79-01. Corrective actions: calibr data recorded in ink. SMITH, L. J. Gould, Inc. 79/05/02. 2pp.

--7908100395 Forwards QA Program Insp Rept 99900353/79-01 on 790205-08 & notice of deviation. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/03/22. 2pp.

--7908100396 Notice of deviation from insp on 790205-08. * Region 4, Dallas, Office of the Director. 79/03/07. 2pp.

--7908100399 QA Program Insp Rept 99900353/79-01 on 790205-08. Noncompliance noted: incomplete QA manual & program; unavailability of QA files re auditor training & qualifications & generic batteries not fully qualified. AGEE, J. R.; HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/03/07. 12pp.

7908100506 Forwards QA Program Insp Rept 99900282/79-02 on 790510. No noncompliance noted.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/29. 2pp.

--7908100508 QA Program Insp Rept 99900282/79-02 on 790510. No noncompliance noted. Major areas inspected: followup on 10CFR50.55(e) const deficiency rept re undersized welds on safety-related pipe hangers.
ELLERSHAW, L. E., HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/05/25. 3pp.

7908130133 Ack receipt of 790626 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 99900311/79-01.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/10. 1p.

--7908130142 Responds to NRC 790615 ltr re deviations noted in QA Program Insp Rept 99900311/79-01. Corrective actions: micrometers & calipers to be calibr on three-month schedule & instruments labeled w/calibr status sticker.
STALCUP, W. C. General Electric Co. 79/06/26. 2pp.

--7908130144 Forwards QA Program Insp Rept 99900311/79-01 on 790521-23 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/15. 2pp.

--7908130166 Notice of deviation from insp on 790521-23.
* Region 4, Dallas, Office of the Director. 79/06/14. 1p.

--7908130170 QA Program Insp Rept 99900311/79-01 on 790521-23. Noncompliance noted: calibr frequency for micrometers & calipers not on three-month schedule & inadequate calibr labeling.
AGEE, J. R., HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/06/14. 11pp.

7908130213 Ack receipt of 790626 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900209/79-01.
POTAPOVS, U. Region 4, Dallas, Office of the Director. 79/07/10. 1p.

--7908130220 Responds to NRC 790515 ltr re deviation noted in QA Program Insp Rept 99900209/79-01. Corrective actions: QA manager will maintain training schedule of personnel in all depts. nonconformance & corrective action activities reviewed.
BECKSTED, W. F. Bergen-Patterson Pipe. 79/06/26. 3pp.

--7908130225 Forwards QA Program Insp Rept 99900209/79-02 on 790424-27 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Office of the Director. 79/05/15. 2pp.

--7908130228 Notice of deviation from insp on 790424-27.
* Region 4, Dallas, Office of the Director. 79/05/15. 3pp.

--7908130235 QA Program Insp Rept 99900209/79-02 on 790424-27. Noncompliance noted: all depts do not have training programs, hold tag not listed in matl contrl log & QC lax in mfg process control.
ELLERSHAW, L. E. Region 4, Dallas, Office of the Director. 79/05/16. 8pp.

7908130366 Ack receipt of 790621 & 25 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900346/79-01.
POTAPOVS, U. Region 4, Dallas, Office of the Director. 79/07/16. 1p.

--7908130370 Responds to NRC 790608 ltr re deviation noted in QA Program Insp Rept 99900346/79-01. W/o corrective actions encl.
STRELCZYK, P. J. Velan Valve Co. 79/06/25. 1p.

--7908130373 Responds to 790608 ltr re deviation noted in QA Program Insp Rept 99900346/79-01. Corrective action taken: small gauges have label stating calibr of gauges. Gauges not calibr removed.
FRANCOIS, E. I. Velan Valve Co. 79/06/21. 3pp.

--7908130379 Notice of deviation from insp on 790521-24.
* Region 4, Dallas, Office of the Director. 79/06/08. 1p.

--7908130382 QA Program Insp Rept 99900346/-01 on 790521-24. Noncompliance noted: calibr labels missing from ten gauges & meters on two welding consoles had not been calibr.
KELLEY, W. D., WHITESELL, D. E. Region 4, Dallas, Office of the Director. 79/06/08. 10pp.

7908130482 Ack receipt of 790620 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900509/79-02.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/10. 1p.

--7908130485 Responds to NRC 790522 ltr re deviation noted in QA Program Insp Rept 99900509/79-02. Corrective actions: missing documents will be placed in records retention ctr files by 790801.
CLEVELAND, N. S. Stone & Webster, Inc. 79/06/20. 2pp.

--7908130487 Forwards QA Program Insp Rept 99900509/79-02 on 790507-11 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/22. 2pp.

--7908130488 Notice of deviation from insp on 790507-11.
* Region 4, Dallas, Office of the Director. 79/05/22. 2pp.

--7908130490 QA Program Insp Rept 99900509/79-02 on 790507-11. Noncompliance noted: documents missing from records retention ctr.
COSTELLO, J. R., BROWN, R. L. Region 4, Dallas, Office of the Director. HALE, C. J. Region 4, Dallas, Vendor Inspection Branch. 79/05/22. 13pp.

7908130615 Ack receipt of 790624 ltr informing NRC of steps taken to correct devation noted in QA Program Insp Rept 99900282/79-01.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/09. 1p.

--7908130625 Responds to NRC 790529 ltr re deviation noted in QA Program Insp Rept 99900282/79-01. Corrective actions: internal audits will verify distribution & retrieval sys & accurate content of hanger fabrication specs & procedures.
MEARS, L. N. ITT Grinnell Industrial Piping, Inc. (subs. of ITT Grinnell). 79/06/24. 2pp.

--7908130634 Forwards QA Program Insp Rept 99900282/79-01 on 790507 & 09-11 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/29. 2pp.

--7908130641 Notice of deviation from insp on 790507 & 09-11.
* Region 4, Dallas, Office of the Director. 79/05/29. 1p.

--7908130651 QA Program Insp Rept 99900282/79-01 on 790507 & 09-11. Noncompliance noted: shielded metal arc welding performed w/o required weld procedure spec being available.
ELLERSHAW, L. E., HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/05/29. 4pp.

7908140064 Ack receipt of 790612 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900525/79-01.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/05. 1p.

--7908140069 Responds to NRC ltr re deviation noted in QA Program Insp Rept 99900525/79-01. Corrective actions: written procedure will be developed to address collection, storage & maint of QA records will be kept locked up.
BARKER, N. R. Commonwealth Assoc., Inc. (subs. of Gilbert Assoc., Inc.). 79/06/12. 3pp.

--7908140071 Forwards QA Program Insp Rept 99900525/79-01 on 790424-27 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/15. 2pp.

--7908140077 Notice of deviation from insp on 790424-27.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/15. 2pp.

--7908140226 QA Program Insp Rept 99900525/79-01 on 790424-27. Noncompliance noted: written records for QA records storage that include attributes discussed in ANSI N45.2.9 have not been prepared.
HALE, C. J., ANDERSON, D. G. Region 4, Dallas, Vendor Inspection Branch. GLYNN, J. C. Region 4, Dallas, Office of the Director. 79/05/16. 14pp.

7908200022 Ack receipt of 790706 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900030/79-01.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/18. 1p.

--7908200026 Responds to NRC 790611 ltr re deviation noted in QA Program Insp Rept 99900030/79-01. Corrective actions: weld procedure revised to include provision for fillet weld & change in voltage parameter to include voltage used.
ROMERO, R. L. Borg Warner Corp., Byron Jackson Pump Div. 79/07/06. 1p.

--7908200028 Forwards QA Program Insp Rept 99900030/79-01 on 790514-17 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/11. 2pp.

--7908200031 Notice of deviation from insp on 790514-17.
* Region 4, Dallas, Vendor Inspection Branch. 79/06/11. 1p.

--7908200032 QA Program Insp Rept 99900030/79-01 on 790514-17. Noncompliance noted: incorrect weld made at incorrect voltage.
HUNTER, V. H., WHITESELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 51300. 79/06/11. 6pp.

7908200036 Ack receipt of 790702 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900339/79-01.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/18. 1p.

--7908200037 Responds to NRC 790606 ltr re deviation noted in QA Program Insp Rept 99900339/79-01. Corrective actions: notifications issued to all foremen & QC inspector re-emphasizing importance of regular calibr checks of insp devices.
GASPARY, G. L. General Electric Co. 79/07/02. 2pp.

--7908200040 Forwards QA Program Insp Rept 99900339/79-01 on 790507-11 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/06. 2pp.

--7908200041 Notice of deviation from insp on 790507-11.
* Region 4, Dallas, Vendor Inspection Branch. 79/06/06. 2pp.

--7908200045 QA Program Insp Rept 99900339/79-01 on 790507-11. Noncompliance noted several gauges & instruments not calibr within specified calibr schedule & several gauges & instruments not in recall cycle for calibr.
AGEE, J. R., HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/06/06. 8pp.

7908210038 Forwards QA Program Insp Rept 99990005/79-03 on 790706.
BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/07/25. 1pp.

--7908210044 QA Program Insp Rept 99990005/79-03 on 790706. Major areas inspected: records which accompanied shipment of radioactive waste from Consumer Power Co to Beatty site. Possible noncompliance exists re shipment of contaminated liquids.
BOOK, H. E., COOLEY, W. J., RIEDLINGER, B. A. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/07/24. 27pp.

7908220277 Ack receipt of 790529 & 0703 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900349/79-01.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/25. 1p.

--7908220282 Responds to NRC 790613 ltr re deviation noted in QA Program Insp Rept 99900349/79-01. Corrective actions: revised filing & storage sys for vendor surveys; addl visitors surveyed by QC & welders instructed re hold points & operator signoff.
ALLEN, W. T. Corner & Lada Co., Inc. 79/07/03. 2pp.

--7908220292 Ack receipt of 790529 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900349/79-01.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/13. 1p.

--7908220301 Responds to NRC 790426 ltr re deviation noted in QA Program Insp Rept 99900349/79-01. Corrective actions: vendor survey to be held by 790727 & session held on 790521 to instruct QC personnel re proper signoff of completed operations.
ALLEN, W. T. Corner & Lada Co., Inc. 79/05/29. 2pp.

--7908220305 Forwards QA Program Insp Rept 99900349/79-01 on 790402-06 & notice of deviation.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/04/26. 2pp.

--7908220308 Notice of deviation from insp on 790402-06.
* Region 4, Dallas, Vendor Inspection Branch. 79/04/26. 2pp.

--7908220316 QA Program Insp Rept 99900349/79-01 on 790402-06. Noncompliance noted: QA approved orders w/vendors w/o ASME certificates or listed as approved vendors & certain completed operations not signed & dtd.
ELLERSHAW, L. E., HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 51300. 79/04/24. 8pp.

7908220628 Forwards QA Program Insp Rept 99900081/79-01 on 790424-26. No noncompliance noted.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/11. 2pp.

--7908220640 QA Program Insp Rept 99900081/79-01 on 790424-26. No noncompliance noted. Major areas inspected: implementation of topical rept including document control, moisture & hydrogen controls, pellet attribute controls & review of mfg.
MCNEILL, W. H. Region 4, Dallas, Office of the Director. 79/05/11. 7pp.

7908220633 Ack receipt of 790711 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900522/79-03.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/07/24. 1p.

--7908220639 Responds to NRC 790613 ltr re deviation noted in QA Program Insp Rept 99900522/79-03. Corrective actions: began survey of final, committed preliminary & preliminary calculation binders for further unchecked calculations.
ALLEN, R. D. Bechtel Power Corp. (subs. of Bechtel Corp.). 51200. 79/07/11. 4pp.

--7908220643 Forwards QA Program Insp Rept 99900522/79-03 on 790522-25 & notice of deviation. Notice of deviation not encl.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/06/13. 2pp.

--7908220646 QA Program Insp Rept 99900522/79-03 on 790522-25. Noncompliance noted: calculation on containment spray sys not checked & supplier performance evaluation not submitted for approval prior to use per procurement spec.
BRICKLEY, R. H., BROWN, R. L., HALE, C. J. Region 4, Dallas, Vendor Inspection Branch. 51200. 79/06/13. 19pp.

7908220667 Forwards QA Program Insp Rept 99900278/79-01 on 790409-12. No noncompliance noted.
POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/05/02. 2pp.

--7908220670 QA Program Insp Rept 99900278/79-01 on 790409-12. No noncompliance noted. Major areas inspected: implementation of 10CFR50 App B including QA manual/program re auditing training, receiving, insp & nonconformances.
AGEE, J. R., HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch. 79/04/30. 11pp.

REGGD REGULATORY GUIDES

7907120319 Comments on proposed Reg Guide 1.75, Revision 2 suggests rewording due to inconsistency w/Reg Guide 1.120 re fire protection guide lines.
SHERWOOD, G. G. General Electric Co. MFN-127-79. 79/05/01. 2PP.

7907190672 Comments on proposed Reg Guide 1.XXX, "Functional Spec for Safety-Related Valve Assemblies in Nuclear Power Plants." No need to format active valve functional requirements.
ANDERSON, T. M. Westinghouse Electric Corp. NS-TMA-2076. 79/05/14. 3pp.

7907310374 Forwards "Review Guideline 24 - Acceptance Criteria for Nuclear Power Plant Safeguards Contingency Plans."
CLARK, R. A. Reactor Safeguards Licensing Branch. 79/05/30. 17pp.

7908010096 Draft value/impact statement of draft Reg Guide 1.XXX, "Ultrasonic Testing of Reactor Vessel Welds During Inservice Examination."
* Office of Standards Development. 79/05/31. 18pp.

7908010539 Comments on proposed Reg Guide 8.23: private installations often have no radiation protection staff, making frequency of surveys required impossible w/o increasing staff. Bioassays would better determine personnel exposure.
LACKER, D. K. Texas, State of. 79/06/05. 2pp.

7908010582 Comments on proposed Reg Guide 8.8, Revision 4 points out typographical error re fission product source term. Figure should be given in microcuries rather thatn millicuries.
WOODS, B. NUS Corp. CD-LIS-4558. 79/06/06. 1p.

7908010587 Comments on proposed Reg Guide 5.57, Revision 1 basic lines of authority not clearly drawn re shipping & receiving SNM which could pose security risks.
LEWIS, M.I. Affiliation Unknown. 79/06/04. 1p.

7908010599 Comments on proposed Reg Guide 1.131, Revision 1 more recent std re thermoplastic insulated cable should be substituted for std on rubber-insulated wire & cables.
SHERWOOD, G.G. General Electric Co., Nuclear Energy Products Div. MFN-149-79. 79/05/21. 1p.

7908010608 Comments on proposed Reg Guide 1.8 should specifically include subcontractor address, staff adequacy & qualifications, licensee surveillance & organizational & technical infrastructure acceptability.
MARGUARDT, G.L. Affiliation Unknown. 79/06/06. 1p.

7908010614 Comments of proposed Reg Guide 8.8, Revision 4 no need for mod of present strict qualifications for radiation protection manager.
JENCKES, T.A. Pacific Gas & Electric Co. 79/06/08. 1p.

7908010618 Comments on proposed Reg Guide 1.35, Revision 3 clarification needed re certain aspects of wedge-anchored tendons & shims. Recommends deletion of requirements re removal of grease cap for surveillance purposes.
REINHARDT, P. Affiliation Unknown. 79/06/15. 4pp.

7908010629 Comments on proposed Reg Guide 1.132, Revision 1 verticality surveys or surveys of horizontal deviation of boreholes would be more appropriate than required surveys of vertical deviation.
JACOBS, S.B. Southwest Econometrics, Inc. 79/06/04. 1p.

7908010645 Comments on proposed Reg Guide 1.52, Revision 1 water spray unacceptable as cooling device because of irreversible damage to charcoal bed. Calculations should be made to determine if charcoal can reach desorption temp w/o cooling.
SHAH, M.M. Affiliation Unknown. 79/06/14. 2pp.

7908010652 Comments on draft Reg Guide 3.XX effects of airborne radionuclides on surface water should be considered in calculation models used in estimating radiation doses to man from U milling operations.
BALSEY, J.R. Interior, Dept. of, Geological Survey. EGS-ER-79/491. 79/06/06. 2pp.

7908010656 Comments on draft Reg Guide 3.XX, "Calculational Models for Estimating Radiation Doses to Man from Airborne Radioactive Matls Resulting from U Milling Operations." due date for comments should be delayed 60 days.
SHELLEY, W.J. Kerr-McGee Nuclear Corp. 79/06/06. 1p.

7908010664 Comments on proposed Reg Guide 1.120, Revision 1 QA program for design, procurement, installation, testing & maint of fire protection sys for safety-related items should be implemented as integral part of overall plant QA program.
LING, J. American Society of Mechanical Engineers. 79/06/05. 1p.

7908010673 Comments on draft Reg Guide 1.XX, "Qualification of QA Program Audit Personnel for Nuclear Power Plants." ASME members favorable toward draft & attached value/impact statement.
LING, J. American Society of Mechanical Engineers. 79/06/06. 2pp.

7908010681 Comments on proposed Reg Guide 5.7, Revision 1 clarification needed re applicability of guide to research reactors. Other proposed guides do not appear to identify same requirements.
CASHWELL, R.J. Wisconsin, Univ. of, Madison. 79/06/05. 1p.

7908020173 Comments on proposed Reg Guide 10.8 certification by American Board of Radiology in general radiology or diagnostic radiology should also serve as evidence of training required for use in Groups 1-3.
HANCOCK, J.A. Affiliation Unknown. 79/05/24. 2pp.

7908030131 Forwards Draft 1 of proposed Reg Guide 1.136, Revision 2, "Matls, Const & Testing of Concrete Containments" & value/impact statement ACRS subcommitte comments & recommendations requested.
ARLOTTO, G.A. Division of Engineering Standards. 79/06/27. 1p.

--7908030135 Draft Reg Guide 1.136, Revision 2, "Matls, Const & Testing of Concrete Containments."
* Division of Engineering Standards. 79/06/01. 7pp.

--7908030143 Value/impact statement for Reg Guide 1.136, Revision 2, "Matls, Const & Testing of Concrete Containments."
* Division of Engineering Standards. 79/06/01. 2pp.

7908030420 Replaces Reg Guide 1.104, "Single-Failure-Proof Overhead Crane Handling Sys for Nuclear Power Plants," w/NUREG-0554, "Single-Failure-Proof Cranes for Nuclear Power Plants."
EISENHUT, D.G. Division of Operating Reactors. 79/06/26. 1p.

7908070046 Concurs w/Reg Guide 1.9, Revision 2, as result of 230th ACRS meeting on 790614-16 re selection, design & qualification of diesel generator units used as standby electric power sys at nuclear power plants.
CARBON, M.W. ACRS - Advisory Committee on Reactor Safeguards. 79/06/19. 1p.

7908070729 Comments on proposed Reg Guide 1.8, Revision 2 wishes to re-evaluate & send comments later re personnel selection & training.
HASHIMOTO, K. Affiliation Unknown. 79/06/07. 1p.

7908070842 "For Comment" issue of Reg Guide 1.XXX, "Qualification Test for Cable Penetration Fire Stops for Use in Nuclear Power Plants."
* Office of Standards Development. 79/07/31. 5pp.

--7908070846 Draft value/impact statement for proposed Reg Guide 1.XXX.
* Office of Standards Development. 79/07/01. 6pp.

7908080262 Discusses concerns expressed in 790423 ltr to V Stello re proposed safeguards upgrade rule & proposed Reg Guide 2.6 "Emergency Planning for Research Reactors." Reg Guide 2.6 will be revised to endorse ANS-15.16.
EISENHUT, D.G. Division of Operating Reactors. 79/07/26.

7908080326 Comments on proposed Reg Guide 1.XX, Functional Spec for Safety-Related Valve Assemblies in Nuclear Power Plant: " use of reg guide to make gross revisions to ANSI stds leads to confusion & compounds difficulty of implementation.
RENBERGER, D.L. Washington Public Power Supply System. 79/06/20. 3pp.

7908080589 Transcript of Affirmation Session 79-18 on 790621 in Washington, DC. Pp 1-8.
HENDRIE, J.M. Commission. 79/06/21. 9pp.

--7908080657 Draft Reg Guide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance."
* Office of Standards Development. 79/01/16. 37pp.

7908090031 "Proposed Guidelines for Lab Testing of Geological Matl for Nuclear Power Facilities."
FRANKLIN, A.G., MARCUSON, W.F. Army, Dept of, Corps of Engineers. AT(49-24)-026. GL-79-9. 79/04/30. 40pp.

7908090100 "For Comment" issue of draft Reg Guide 1.XXX, "Ultrasonic Testing of Reactor Vessel Welds During Inservice Examination."
* Office of Standards Development. 79/05/31. 16pp.

--7908090114 Draft value/impact statement re proposed Reg Guide 1.XXX, "Ultrasonic Testing of Reactor Vessel Welds During Inservice Examination."
* Office of Standards Development. 79/05/31. 17pp.

--7908090128 "Probability of Detecting Planar Defects in Heavy Wall Welds by Ultrasonic Techniques According to Existing Codes."
MEYER, H.J. M.A.N. - Germany. 79/05/31. 17pp.

7908090318 Comments on proposed Reg Guide 3.XXX, "Calculation Models Re U Milling Operations." Computer model used may show higher bone dose but warning should be included that calculation is not realistic.
HARLEY, J.H. Energy, Dept. of. 79/05/23. 1p.

7908100016 Comments on proposed Reg Guide 1.XXX should be one set of comprehensive requirements for valve assembly.
WILLIAMS, F.S. Affiliation Unknown. 79/06/11. 3pp.

7908100144 Reg Guide 8.19, Revision 1, "Occupational Radiation Dose Assessment in LWR Power Plants, Design Stage Man-Rem Estimates."
* Office of Standards Development. 79/06/30. 12pp.

7908100430 "For Comment" issue of draft reg guide "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance."
* Office of Standards Development. 79/07/31. 58pp.

7908150159 Forwards draft Reg Guide 1.136, Revision "Matls, Const & Testing of Concrete Containments." Requests comments. Agenda for ACRS Subcommittee on Regulatory Activties 790608 meeting encl.
ARLOTTO, G.A. Division of Engineering Standards. 79/06/27. 2pp.

--7908150167 "Matls,Const & Testing of Concrete Containments." Proposed Reg Guide offered for comment.
* Division of Engineering Standards. 79/06/01. 7pp.

--7908150172 Draft value/impact statement re Reg Guide 1.136,Revision 2, "Matls,Const & Testing of Concrete Containments."
* Division of Engineering Standards. 79/06/27. 2pp.

--7908150179 Forwards proposed revision to Paragraph III.D.2 of 10CFR50, Appendix J, "Primary Reactor Containment Leakage Testing for Water-Cooled Power Reactors." Preliminary value/impact statement encl.
ARLOTTO,G.A. Division of Engineering Standards. 79/07/16. 4pp.

7908160073 Responds to Ahearne 790430 questions re actions to ensure adequacy of separation guidance for fire protection & resolution of ACRS concerns expressed during review of draft Reg Guide 1.120.
FERGUSON,R.L. Plant Systems Branch. 79/07/03. 6pp.

7908160135 Responds to 790501 ltr re Reg Guide 2.36,"Emergency Planning for Research Reactors." Reg Guide amplifies matl in ANS std. Will endorse ANS-15.16 & addl guidance as necessary, especially for high risk facilities.
MINOGUE,R.W. Office of Standards Development. 79/06/15. 2pp.

7908210424 Submits results of analysis of exclusion area distances based upon method specified in Reg Guide 1.145,per 790710 meeting request.
BUTLER,R.M. Boston Edison Co. 79/08/08. 3pp.

7908230464 Comments on proposed Reg Guide 4.15 opposes required qualifications for individuals performing verification of implementation audit.Suggest rewording of restrictive section.
BAXTER,R.C. Affiliation Unknown. 79/05/23. 1p.

7908270078 Forwards comments on proposed Revision 2 to Reg Guide 1.13, "Design Objectives for LWR Spent Fuel Storage Facilities at Nuclear Power Stations."
EISENHUT,D.G. Division of Operating Reactors. 79/08/06. 2pp.

7908270141 "For Comment" issue of Reg Guidu 1.XXX, "Inservice Insp Code Case Acceptability ASME Section XI Div 1."
* Office of Standards Development. 79/08/31. 6pp.

--7908270150 Draft value/impact statement for Reg Guide 1.XXX, "Inservice Insp Code Case Acceptability ASME Section XI Div 1."
* Office of Standards Development. 78/08/31. 3pp.

7908290161 Forwards Reg Guide 1.101 re emergency planning & V.Gilinsky 790620 ltr to JG Kemeny on basis for evacuation planning for TMI,in response to 790621 request.
MULLER,D.R. Division of Site Safety & Environmental Analysis. 79/07/31. 1p.

--7908290167 Requests Reg Guide 1.101,dtd 770331,re emergency planning for nuclear plants & basis for evacuation planning for TMI.
YELLIN,J. Harvard Univ. 79/06/21. 1p.

7908290166 Comments on proposed Reg Guide 1.139 opposes regulation. Present plant designs are adequate.Safety-grade cooldown to cold shutdown conditions is not significant safety issue.
TAYLOR,J.H. Babcock & Wilcox Co. 79/08/04. 4pp.

--7908290177 Comments on proposed Reg Guide 1.139 opposes regulation. Compounding of conservative assumptions is of too low probability to serve as viable design basis for plant.
ARTHUR,J.E. Rochester Gas & Electric Corp. 79/07/21. 6pp.

--7908290184 Comments on proposed Reg Guide 1.139 guide should be revised.Term "cold shutdown" should be defined.
SHERWOOD,G.G. General Electric Co.,Nuclear Energy Products Div. MFN 321-78. 79/07/27. 2pp.

7908300343 "For comment" issue of Reg Guide 1.58,Revision 1, "Qualification of Nuclear Power Plant Insp,Examination & Testing Personnel."
* Office of Standards Development. 79/07/31. 12pp.

7908300773 Responds to 790615 ltr re delays in notification of 790613 event containing list of type of events to be reported to NRC by licensee.
HENDRIE,J.M. Commission. 79/07/30. 2pp.

--7908300774 "For Comment" issue of Reg Guide 1.16,Revision 4, "Reporting of Operating Info - App A,Tech Specs."
* Office of Standards Development. 75/08/31. 13pp.

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

7908010069 "Dynamic Photoelastic Study of Crack Arrest," progress rept, June 1979.
FOURNEY,W.L. Maryland, Univ. of. 79/07/02. 5pp.

7908010240 "Creare Downcomer Effects Program," interim rept,May 1979.
ROTHE,P.H., CROWLEY,C.J. Creare, Inc. NRC-04-75-162. 79/06/07. 3pp.

7908010256 "PA 37 Pipe Rupture Study," interim rept,Mar 1979.
CLARKE,W.L. General Electric Co. NRC-04-75-202. 79/04/13. 5pp.

7908010274 "Physical Protection of Nuclear Facilities Project," informal monthly ltr rept,Apr 1979.
CHAPMAN,L.D. Sandia Laboratories. FIN A-1060. 79/05/15. 10pp.

7908010283 "PA 37 Pipe Rupture Study," monthly progress rept,Apr 1979.
CLARKE,W.L. General Electric Co. NRC-04-75-202. 79/05/11. 5pp.

7908010301 "Dosimetry Measurement Ref Data Base for LWR Pressure Vessel (LWR-PV) Irradiation Surveillance;Benchmark Field Referencing NBS Fission Chamber Measurements in PV-Simulators."
GRUNDL,J.A. Commerce,Dept.of, National Bureau of Standards. AT-(4925)-9008. 79/07/11. 4pp.

7908010333 "Dosimetry Measurement Ref Data Base for LWR Pressure Vessel (LWR-PV) Irradiation Surveillance;Benchmark Field Referencing NBS Fission Chamber Measurements in PV-Simulators in FY78 Stds Development," interim rept.
GRUNDL,J.A. Commerce,Dept of, National Bureau of Standards. AT-(4925)-9008. 79/05/15. 6pp.

7908010342 "Steam Generator Tube Integrity Program," interim rept,May 1979.
CLARK,R.A. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2097. 79/06/08. 5pp.

7908010352 "Creare Downcomer Effects Program," interim rept,June 1979.
ROTHE,P.H., CROWLEY,C.J. Creare, Inc. NRC-04-75-162. 79/07/06. 4pp.

7908010364 "Power-Cooling-Mismatch Test PCM-7 Experiment Predictions," thermal fuels behavior program;interim rept.
SMITH,R.H., SPARKS,D.T. Idaho National Engineering Laboratory. FIN A-6041. TFBP-TR-321. 79/06/30. 47pp.

7908010375 "Code Assessment & Applications Program;Pretest Prediction of Semiscale Test S-07-10B."
DOBBE,C.A. Idaho National Engineering Laboratory. FIN A-6047. CAAP-TR-052. 79/06/30. 40pp.

7908010437 "RELAP4/MOD6 Predictions Comparisons w/LOFT LOCE L2-2 Data," interim rept.
KEE,E.J., WHITE,J.R. Idaho National Engineering Laboratory. FIN A-6048. 20-100. 79/05/31. 95pp.

7908010447 "Semiscale Program;Analysis of Scaling Semiscale MOD-3 Sys to PWR," interim rept.
ROGERS,G.M. Idaho National Engineering Laboratory. FIN A-6038. SEMI-TR-005. 79/04/30. 188pp.

7908010458 "Cladding Mechanical Limits (CMLIMT)," interim rept.
HAGRMAN,D.L. Idaho National Engineering Laboratory. FIN A-6046. CDAP-TR-056. 79/05/31. 51pp.

7908010472 "Environ Statements Project," interim rept,May 1979.
ZITTEL,H.E. Oak Ridge National Laboratory. FIN B-0001. ORNL/ED/EIS-94. 79/05/31. 5pp.

7908010494 "Seismicity of Southeastern US," interim rept,Jul-Dec 1978.
BOLLINGER,G.A. Virginia Polytechnic Institute & State Univ. 79/05/31. 72pp.

7908010516 "Water Reactor Safety Research;Heat Transfer Highlights," interim rept,Apr 1979.
LEUNG,J.C.M., HENRY,R.E. Argonne National Laboratory. 79/04/30. 25pp.

7908010534 "Quick Look Rept on LOFT Nuclear Experiment L2-3," interim rept.
REEDER,D.L. Idaho National Engineering Laboratory. FIN A-6048. QLR-L2-3. 79/05/31. 75pp.

7908010545 "Thermal Hydraulic LMFBR Safety Experiments: Heat Removal Characteristics of Volume-Heated Boiling Pools w/Inclined Boundaries," interim rept.
GREENE, G. A., JONES, O. C., SCHWARZ, C. E. Brookhaven National Laboratory. FIN A-3024. BNL-NUREG-26325. 79/06/30. 189pp.

7908010563 "Water Reactor Research Directorate Monthly Rept," interim rept. May 1979.
YBARRONDO, L. J. EG & G, Inc. 79/06/30. 200pp.

7908010579 "LWR Thermal Hydraulic Development Program: BNL Instrumentation Program," interim rept.
ABUAF, N., ZIMMER, G. A., JONES, O. C. Brookhaven National Laboratory. FIN A-3045. BNL-NUREG-26051. 79/04/30. 28pp.

7908010591 "Reactor Core Safety Analysis Group: Using Fuel Performance to Determine Operating Limit Uncertainty Allowance," interim rept.
CAREW, J. F., DIAMOND, D. J. Brookhaven National Laboratory. FIN A-3103. BNL-NUREG-26162. 79/05/31. 26pp.

7908020135 "Multirod Burst Tests: Bundle B-1 Test Data," interim rept.
CHAPMAN, R. H., HOBSON, D. O., CROWLEY, C. J. Oak Ridge National Laboratory. FIN B-0120. ORNL/NUREG/TM-3. 79/05/23. 157pp. Available at NTIS.

7908020152 "Stds Steering Committee Code Development & Validation Air Blast Heat Exchanger Sys Model," interim rept.
CADY, K. B. Brookhaven National Laboratory. FIN A-3015-8. BNL-NUREG-26237. 79/06/30. 97pp.

7908020184 "Div of Reactor Safety Research: ORNL Programs," interim rept. June 1979.
MYNATT, F. R. Oak Ridge National Laboratory. 79/07/06. 34pp.

7908020198 "Semiscale Program: Quick Look Rept for Semiscale MOD-3 Tests S-07-8 & S-07-9 (Baseline Test Series)," interim rept. May 1979.
HANSON, R. G. Idaho National Engineering Laboratory. FIN A-6038. SEMI-TR-007. 79/05/31. 53pp.

7908020212 "Structural Integrity of Water Reactor Pressure Boundary Components," interim rept. May 1979.
LOSS, F. J. Navy, Dept. of. 79/06/08. 5pp.

7908020226 "Structural Integrity of Water Reactor Pressure Boundary Components," interim rept. Apr 1979.
LOSS, F. J. Navy, Dept. of. 79/05/08. 5pp.

7908020239 "Crack Arrest Technology," interim rept. Apr 1979.
ROSENFIELD, A. R. Battelle Memorial Institute, Columbus Laboratories. AT(49-24)-0293. 79/05/03. 7pp.

7908020266 "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Bypass Lines & Pipes in BWR Piping Sys," interim rept. 790430-0525.
YEAGER, L. L. Deedalean Associates, Inc. NRC-04-78-242. 79/05/31. 9pp.

7908020275 "LWR Thermal Hydraulic Development Program," interim rept. May 1979.
JONES, O. C. Brookhaven National Laboratory. FIN A-3045. 79/05/31. 4pp.

7908020283 "Thermal Hydraulic LMFBR Safety Experiments," interim rept. May 1979.
JONES, O. C. Brookhaven National Laboratory. FIN A-3024. 79/05/31. 4pp.

7908020292 "Advanced Reactor Safety Analysis Technical Assistance, Reactor Projects," interim rept. May 1979.
BARI, R. A. Brookhaven National Laboratory. FIN A-3000. 79/06/04. 5pp.

7908020301 "Nuclear Power Plant Design Concepts for Sabotage Protection," interim rept. Jan-Mar 1979.
ERICSON, D. Sandia Laboratories. FIN A-1210. 79/04/30. 13pp.

7908020317 "Integration of NDE (Nondestructive Examination) Reliability & Fracture Mechanics," interim rept. May 1979.
BECKER, F. L., BUSH, S. H. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2289. 79/06/22. 6pp.

7908020329 "Div of Reactor Safety Research-ORNL Programs," interim rept. May 1979.
MYNATT, F. R. Oak Ridge National Laboratory. 79/06/07. 32pp.

7908020350 "Kinetics of Chlorine-Ammonia Reactions in Sea Water," interim rept. Oct-Dec 1978.
JOHNSON, J. D., INMAN, G. W. North Carolina, Univ. of. FIN B-6248. 78/12/31. 18pp.

7908020362 "Stress Corrosion Cracking of PWR Steam Generator Tubing," interim rept. May 1979.
VAN ROOYEN, D. Brookhaven National Laboratory. FIN A-3208. 79/06/04. 8pp.

7908020372 "HTGR Safety Program," interim rept. May 1979.
SCHMEITZER, D. G. Brookhaven National Laboratory. FIN A-3016. 79/05/31. 4pp.

7908020379 "Assessment of Radiation Doses Resulting From Releases of Rn-222 & Ra-226 From U Mining & Milling Activities," interim rept. May 1979.
TRAVIS, C. C., MCDOWELL-BOYER, WATSON, A. P. Oak Ridge National Laboratory. FIN B-0281. ORNL/HASRD-41. 79/06/15. 4pp.

7908020387 "Kinetics of Chlorine-Ammonia Reactions in Sea Water," interim rept. Jan-Mar 1979.
JOHNSON, J. D., INMAN, G. W. North Carolina, Univ. of. FIN B-6248. 79/03/31. 20pp.

7908020425 "Matl Control & Accounting Effectiveness Evaluation Development," interim rept. Apr 1979.
HUEBEL, J. Lawrence Livermore Laboratory. FIN A-0115. 79/05/23. 7pp.

7908020433 "Distribution Coefficients for Radionuclides in Aquatic Environ Lab of Radiation Ecology," interim rept. Nov 1978 - Jan 1979.
* Washington, Univ. of. FIN B-5749. 79/01/31. 15pp.

7908020454 "Sediment & Radionuclide Transport in Rivers Field Sampling Program: Cattaraugus & Buttermilk Creeks, NY," interim rept. Oct-Dec 1978.
* Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2294. 78/12/31. 16pp.

7908020462 "Methods to Assess Impacts on Hudson River Striped Bass," interim rept. Jan-Mar 1979.
VAN WINKLE, W., BARNTHOUSE, L. W. Oak Ridge National Laboratory. FIN B-0165. 79/03/31. 13pp.

7908020474 "Thermal Fuels Behavior Program: PBF/LOFT Lead Rod Program Test LLR-4A Quick Look Rept," interim rept.
VARACALLE, D. J., GARNER, R. W. Idaho National Engineering Laboratory. FIN A-6111. TFBP-TR-320. 79/06/30. 64pp.

7908020489 "Semiscale Experiment Data for Determination of Uncertainty of Two-Phase Mass Flow Rate in Semiscale MOD-3 Sys Spool Piece at Karlsruhe Kernforschungzentrum," interim rept.
STEPHENS, A. G. Idaho National Engineering Laboratory. FIN A-6038. SEMI-TR-006. 79/06/30. 125pp.

7908020576 7908020476
"LOFT Monthly Progress Rept," interim rept. Apr 1979.
* Idaho National Engineering Laboratory. 79/04/30. 71pp.

7908020600 "Stds Steering Committee Code Development & Validation," interim rept. May 1979.
AGRAWAL, A. K., GUPPY, J. G. Brookhaven National Laboratory. FIN A-3015-8. 79/06/19. 7pp.

7908030075 "Code Assessment & Applications Program: Assessment of Capability of Existing Heat Transfer Data Base & of Designated Data Sources to Provide Data Over Calculated Heat Transfer Variable Ranges During LOCA Blowdown," interim rept.
LARSON, J. R. Idaho National Engineering Laboratory. FIN A-6047. CAAP-TR-048. 79/05/31. 90pp.

7908030082 "Fission Product Inventories in Tests Irradiated in PBF," interim rept.
OLSON, W. O. Idaho National Engineering Laboratory. FIN A-6041. RE-P-79-043. 79/05/31. 128pp.

7908030090 "Thermal Fuels Behavior Program: Reactivity Initiated Accident Test Series Test REA-1-4 Experiment Operating Spec," interim rept.
STANLEY, C. J., MARTINSON, Z. R. Idaho National Engineering Laboratory. FIN A-6041. TFBP-TR-323. 79/06/30. 70pp.

7908030175 "HEPA Filter Tests," interim rept. Jan-Mar 1979.
HORAK, H., GREGORY, W. S. Los Alamos Scientific Laboratory. FIN A-7028. WX-8-2984. 79/07/10. 21pp.

7908030191 "Dynamic Photoelastic Study ~r Crack Arrest," interim rept, May 1979.
FOURNEY, W. L. Maryland, Univ. of. NRC-04-76-172. 79/06/02. 6pp.

7908030231 "Methods to Assess Impacts on Hudson River White Perch," interim rept, Jan-Mar 1979.
VAN WINKLE, W., NARNTHOUSE, L. W. Oak Ridge National Laboratory. FIN B-0423. 79/03/31. 64pp.

7908030244 "Environ Assessments of Fuel Cycle Facilities," interim rept, May 1979.
ZITTEL, H. E. Oak Ridge National Laboratory. FIN B-0279. ORNL/ED/EIS-93. 79/05/21. 6pp.

7908070548 Progress Rept 21 Discusses results of test 2, calibr of two Shonka-Wyckoff ionization chambers, pilot test phase rept containing delivered & reported doses & pass/fail analysis of 21,000 dosimeters irradiated in study & site visits.
PLATO, P. Michigan, Univ. of. NRC-01-77-180. 79/07/06. 3pp.

--7908070567 7908070548
Ack receipt of rept on site visits to major dosimetry processors. Provides comments re fail rate & contractor lack of effort. NRC should adopt dosimeter design std. Related info encl.
ALEXANDER, R. Occupational Health Standards Branch. 79/06/27. 9pp.

7908080487 "Quick-Look Rept on Loft Nonnuclear Experiment L3-0."
Experiment data presentation rept for July 1979.
JARRELL, D. B. EG & G, Inc. FIN A-6048. GLR-L3-0. 79/07/31. 48pp.

7908080504 "Instrument Development Loop." Foreign trip rept for 790625-29.
MYNATT, F. R. Oak Ridge National Laboratory. FIN B-0427. ORNL/FTR-645. 79/07/16. 8pp.

7908080521 "Physical Protection of Nuclear Facilities Project." Progress rept for May 1979.
CHAPMAN, L. D. Sandia Laboratories. FIN A-1060. 79/06/12. 14pp.

7908080537 "Code Assessment & Applications Program, Preliminary Application of Quantitative Assessment Procedure."
DEARIEN, J. A. EG & G, Inc. FIN A-6047. CAAP-TR-047. 79/04/30. 114pp.

7908080557 "Analysis of Hypothetical Accidents in Core Meltdown." Monthly progress rept for Jan 1979.
DENNING, R. S., CYBULSKIS, P., BAYBUTT, P. Battelle Memorial Institute, Columbus Laboratories. FIN A-4067. 79/06/13. 8pp.

7908080571 "Results of Tests to Evaluate Use of In-Core Liquid Level Transducer to Measure Void Fraction."
HOSKINSON, R. L., HELBERT, H. J. EG & G, Inc. FIN A-6048. LTR-141-103. 79/07/23. 52pp.

7908080583 LOFT monthly progress rept for May 1979.
* EG & G, Inc. FIN A-6048. 79/07/23. 75pp.

7908090626 Progress Rept 20 re dosimeter testing.
PLATO, P. Michigan, Univ. of. NRC-01-77-180. 79/05/31. 12pp.

7908100296 "Physical Protection of Nuclear Facilities." Monthly progress rept for June 1979.
CHAPMAN, L. D. Sandia Laboratories. FIN A-1060. 79/07/11. 9pp.

7908100304 "Physical Protection of Nuclear Matl in Transit." Monthly progress rept for June 1979.
CHAPMAN, L. D. Sandia Laboratories. FIN A-1173. 79/07/11. 3pp.

7908140339 "Accident Aerosol Characterization," progress rept for May 1979.
MISHIMA, J. Brookhaven National Laboratory. FIN B-2267. 79/06/08. 2pp.

7908140349 Forwards "Fuel Cycle Accident Evaluation," monthly activities for Apr & May 1979.
FREDERICK, E. J. Oak Ridge National Laboratory. FIN-B-0425. 79/06/12. 2pp.

--7908140356 "Fuel Cycle Accident Evaluation," monthly activities for Apr & May 1979.
FREDERICK, E. J. Oak Ridge National Laboratory. FIN B-0425. 79/06/21. 1p.

7908140568 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept June 1979.
ZITTEL, H. E. Oak Ridge National Laboratory. FIN B-0279. ORNL/ED/EIS-95. 79/06/30. 6pp.

7908140575 "Environ Statements Project," monthly progress rept for June 1979.
ZITTEL, H. E. Oak Ridge National Laboratory. FIN B-0001. ORNL/ED/EIS-96. 79/06/30. 9pp.

7908140584 "Assessment of Radiation Doses Resulting from Releases of Radon-222 & Radium-226 from Mining & Milling Activities," Monthly progress rept June 1979.
TRAVIS, C. C., MCDOWELL-BOYER, WATSON, A. P. Oak Ridge National Laboratory. FIN B-0281. ORNL/HASRD-44. 79/06/25. 4pp.

7908140592 "Advanced Instrumentation of Reflood Studies," foreign travel rept.
ROBERTS, M. J. Oak Ridge National Laboratory. FIN B-0112-7. ORNL/FTR-646. 79/07/16. 7pp.

7908140610 "Forecasting Electricity Demand by States in US on Annual Basis," progress rept June 1979.
CHERN, W. S. Oak Ridge National Laboratory. FIN B-0190-H. ORNL/ED/EAS-79. 79/07/06. 5pp.

7908140622 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept June 1979.
HOLOWAY, C. F., LANTZ, P. M., DICKSON, H. W. Oak Ridge National Laboratory. FIN A-9085-7. ORNL/HASRD-43. 79/06/30. 8pp.

7908140631 "Investigation of Post-Critical Heat Flux Heat Transfer for Water-Cooled Reactor Application & Development of Two-Phase Flow Instrumentation," monthly progress rept Jul 1979.
CHEN, J. C., SUNDARAM, R. K., NIJHAWAN, S. Lehigh Univ. FIN A-4055. 79/08/03. 5pp.

7908140640 "Evcluation of Radiation Streaming," informal progress rept as of 790715.
COHEN, M. D. Mathematical Applications, Inc. FIN B-6206. 79/07/27. 4pp.

7908140649 "Experimental Evaluation of Ventilation Sys Components During Large Pressure Pulses," monthly progress rept May 1979.
GREGORY, W. S. Los Alamos Scientific Laboratory. FIN A-7028. 79/07/25. 3pp.

7908140659 "Steam Generator Tube Integrity Program," monthly progress rept June-Jul 1979.
CLARK, R. A. Battelle Memorial Institute, Pacific Northwest Laboratory. 79/08/06. 5pp.

7908160172 Forwards monthly progress rept for June 1979, "Analysis of Hypothetical Accidents Resulting in Core Meltdown." Increased funding will be necessary if initial objectives of ongoing tasks are to be met.
DENNING, R. S. Battelle Memorial Institute, Columbus Laboratories. 79/07/16. 1p.

--7908160188 7908160172
"Analysis of Hypothetical Accidents Resulting in Core Meltdown," monthly progress rept for June 1979.
DENNING, R. S., CYBULSKIS, P., BAYBUTT, P. Battelle Memorial Institute, Columbus Laboratories. 79/07/16. 14pp.

7908170500 "LOFT Experimental Program Div: Preliminary Post-Test Analysis of LOFT Loss-of-Coolant Experiment L2-2," interim rept.
WHITE, J. R., GRUSH, W. H., KEELER, C. D. EG & G, Inc. LTR 20-103. 79/06/30. 103pp.

7908270273 Foreign travel rept on behalf of technical assistance program on review of computer-based protection sys. Attended demonstration of German analysis sys STAR planned to provide on-line assistance to reactor operators during disturbance.
BULLOCK, J. B. Oak Ridge National Laboratory. FIN B-0256. ORNL/FTR-628. 79/06/16. 7pp.

7908270342 May 1979 monthly progress rept re Fission product transport analysis. Aerosol deposition experiments will be completed in June; emphasis of program is shifting to anelysis & correlation of accumulated data.
GIESEKE, J. A. Battelle Memorial Institute, Columbus Laboratories. 79/06/22. 3pp.

7908290233 Monthly progress rept for April 1979. Discusses work at NM State Univ re polarization problems w/laser particle counter, meeting w/Mine Safety Appliance Co concerning tornado simultation response & Nuclear Fuel Svc analysis.
GREGORY, W. S. Los Alamos Scientific Laboratory. FIN A-7028. WX-8-2984. 79/06/19. 3pp.

7908300600 Forwards Progress Rept 22 for Jul 1979.
PLATO, P. Michigan, Univ. of. NRC-01-77-180. 79/07/30. 2pp.

--7908300603 7908300600
Progress Rept 22 for Jul 1979.
PLA/D.P. Michigan, Univ. of. NRC-01-77-180. 79/07/30. 70pp.

REVIEW GRP NRC RESEARCH REVIEW GROUPS

7907300139 Summary of 790522 meeting w/Sandia Labs re milestones, upgrade rule task of FY79 program & waste transportation.
ROBINSON, R.C. Division of Safeguards, Fuel Cycle & Environmental Research. 79/07/02. 6pp.

7907300161 Summary of 790328-30 Combined Containment Review Group meeting in Munich, West Germany re LWR containment research conducted in West Germany & US.
CUDLIN, R.L. Office of Nuclear Regulatory Research. 79/05/30. 10pp.

7908010314 Summary of 790115-16 meeting w/Advanced Code Review Group in Silver Spring, MD re review code development programs carried out by G-6 & T-3 groups at LASL.
ZUBER, N. Division of Reactor Safety Research. 79/06/27. 173pp.

7908020576 7908020476
"LOFT Monthly Progress Rept," interim rept, Apr 1979.
* Idaho National Engineering Laboratory. 79/04/30. 71pp.

7908130592 Forwards minutes of Containment Code Review Group 790619 meeting in Silver Spring, MD re Mark I load programs. Agenda encl.
FABIC, S. RRG# 1-15, Containment Code. 79/07/17. 59pp.

7908160347 Submits agenda for Facility Decommissioning Research Review group 790608 meeting, list of attendees & addl matl encl.
SOLBERG, D.E. Systems Performance Branch. 79/07/26. 31pp.

7908300591 Notification of 790905-06 meeting in Silver Spring, MD to discuss TRAC-P1A code.
ZUBER, N. Division of Reactor Safety Research. 79/08/02. 14pp.

RM RULEMAKING

7908140433 Forwards Ofc of Executive Legal Director comments on Access Hearing Board decision re need for clearance rule & NRC legal authority per General Counsel 790612 memo.
SHAPAR, H.K. Office of the Executive Legal Director. 79/07/18. 20pp.

SECY POSITION PAPERS BEFORE THE COMMISSION

7908010039 SECY-A-79-042
Seeks approval of memo & order sustaining immediate effectiveness of NRC show cause order per 10CFR2.202 & notice of hearing.
BICKWIT, L. Office of the General Counsel. 79/05/04. 4pp.

--7908010057 SECY-79-351
Seeks approval under Atomic Energy Act of 1954, Section 145B, for members of President's Commission on Accident at TMI to have access to restricted data & natl security info.
BRADY, R.J. Division of Security. 79/05/24. 5pp.

7908010324 Forwards SECY-79-160A for placement in PDR.
MCGREGOR, E.W. Office of the Secretary of the Commission. 79/06/12. 1p.

--7908010330 SECY-79-160A
Forwards Executive Branch response re application by Edlow Intl Co to export source matl to France & United Kingdom.
SHEA, J.R. Office of International Programs. 79/06/21. 1p.

7908010636 Transcript of 790605 public meeting in Washington, DC re hearing board rept in clearance rule proceeding. Pp 1-42.
HENDRIE, J.M., GILINSKY, V., BRADFORD, P.A. Commission. 79/06/05. 43pp.

--7908010640 SECY-79-319
Presents alternatives for Commissioner consideration of clearance rule hearing board rept. Proposed order encl.
BICKWIT, L. Office of the General Counsel. KENNEKE, A.P. Office of Policy Evaluations. 79/05/08. 7pp.

7908010661 SECY-79-343
Submits to Congress proposed NRC comments re GAO rept on radiological emergencies.
RYAN, R.G. Office of State Programs. 79/05/18. 11pp.

7908020493 Responds to comments on SECY-79-192 re proposed revision of 10CFR71, "Packaging of Radioactive Matl for Transport." General licenses under 10CFR71.12 are justified. NRC working w/DOT to devise better sys for control of exposures.
MINOGUE, R.B. Office of Standards Development. 79/06/20. 2pp.

7908080150 Transcript of 790712 meeting & affirmation session re SECY-79-347 & Hungerford FOIA appeal, in Washington, DC. Pp 1-3.
HENDRIE, J.M., KENNEDY, R.T., BRADFORD, P.A. Commission. 79/07/12. 3pp.

7908080595 SECY-78-682-A
Discusses revision of NRC regulations governing ownership of stocks, bonds & other security interests by NRC employees. Summary of employee comments encl.
FITZGERALD, J.A. Office of the General Counsel. 79/05/14. 14pp.

--7908080550 SECY-79-038
Recommends NRC approval of revised proposed amends, re physical protection measures to detect theft of SNM of moderate or low importance, to 10CFR70.73 & 150 for publication in final form.
MINOGUE, R.B. Office of Standards Development. DIRCKS, H.J. Office of Nuclear Material Safety & Safeguards. 79/01/16. 76pp.

7908080649 Addresses 790411 initial discussion of upgrade rule. Brightsen 790326 memo argues for one level of design threats.
KENNEKE, A. Office of Policy Evaluations. 79/04/10. 1p.

--7908080649 Addresses 790411 initial discussion of upgrade rule. Brightsen 790326 memo argues for one level of design threats.
KENNEKE, A. Office of Policy Evaluations. 79/04/10. 1p.

7908090008 Forwards SECY-79-364 re application of Mitsubishi Intl Corp to export U-235 to Japan.
MCGREGOR, E.W. Office of the Secretary of the Commission. 79/06/12. 1p.

--7908090009 SECY-79-364
Notifies of receipt of application from Mitsubishi Intl Corp to export U-235, contained in 40,023 kg U enriched 3.25%, to Japan.
SHEA, J.R. Office of International Programs. 79/06/04. 1p.

--7908090010 Application by Mitsubishi Intl Corp to export 1,302 kg U-235, contained in 40,023 kg U enriched 3.25%, to Japan. End use statement encl.
TSUJI, K. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). 79/05/23. 2pp.

--7908090011 Forwards application by Mitsubishi Intl Corp to export U-235, contained in 40,023 kg U enriched 3.25%, to Japan.
WATANBEE, N. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). 79/05/23. 2pp.

7908090512 Discusses status of amend requested by Edlow Intl Co to license export of 1,000,000 kg U, contained in 1,180,000 kg natural U, to United Kingdom for conversion to U hexafluoride. Recommends issuance of license.
SHEA, J.R. Office of International Programs. 79/06/11. 3 pp.

--7908090513 License for British Nuclear Fuels Ltd or JEF Andrews as agent to export 5,300,000 kg U, as U-308, to United Kingdom.
PRICE, E.R. Atomic Energy Commission, Directorate of Licensing (Pre-1975). 71/04/01. 1p.

7908090557 SECY-78-678C
Discusses status of GE export of low enriched fuel to Taiwan. Stresses urgency of resolving issue of exports to Taiwan.
SHEA, J.R. Office of International Programs. 79/05/18. 2pp.

--7908090561 Ack receipt of NRC 790404 ltr noting unfinished NRC review of GE export of low enriched fuel to Taiwan. Expects no more unusual delay. License should be received shortly.
WILSON, B.D. General Electric Co., Nuclear Energy Products Div. BDW-79105. 79/04/18. 1p.

--7908090570 Supplements 790418 ltr. Requests issuance of license to export matl to Taiwan by 790701. Notes shipping schedule difficulties. NRC delay is statutory max.
WILSON, B.D. General Electric Co., Nuclear Energy Products Div. BDW-79124. 79/05/08. 2pp.

--7908090589 Supplements 790508 request for expedited processing of export license. Ships are booked to transport fuel on 790608 & 30. Commissioner action required by 790525.
WILSON, B.D. General Electric Co. 79/05/10. 1p.

NONDOCKETED ITEMS

7908090625 Transcript of 790711 meeting in Washington, DC to assess NRC confidence in safe nuclear waste disposal. Pp 1-57, 16
HENDRIE, J.M.; GILINSKY, V.; KENNEDY, R.T. Commission. 79/07/11. 58pp

7908100504 SECY-79-077B
Discusses status of proposed license for GE to export 11,965 kg U enriched to 3.1% to Japan. Recommends approval of export.
SHEA, J.R. Office of International Programs. 79/05/31. 3pp.

7908100527 SECY-79-427
Provides requested data re upcoming power reactor licensing cases.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/07/05. 3pp.

7908130041 Info rept re 790501 application for License XSNM-1517 to export enriched U hexafluoride & U dioxide to Japan. Forwards license application & T Monden 790501 ltr.
SHEA, J.R. Office of International Programs. 79/05/25. 3pp.

7908130053 SECY-79-182A
Forwards Executive Branch response re application by Westinghouse to export U-235 contained in 727,125 kg U enriched to max 3.5% to Korea. License should be granted.
SHEA, J.R. Office of International Programs. 79/06/20. 1p.

7908130070 SECY-79-394
Forwards application by Transnuclear, Inc to export U-235, contained in 33 kg U enriched to 93.3% to France.
SHEA, J.R. Office of International Programs. 79/06/15. 1p.

--7908130078 Forwards application by Transnuclear, Inc to export U-235, contained in 33 kg U enriched to 93.3% to France.
MATSON, V. Transnuclear, Inc. 79/06/05. 1pp.

--7908130084 Application by Transnuclear, Inc to export U-235, contained in 33 kg U enriched to 93.3% to France. Ltr of assurance & reactor checklist encl.
* Transnuclear, Inc. 79/06/05. 8pp.

7908130090 SECY-79-328A
Forwards 790611 Executive Branch response re application by GE to export various thermal sleeves to India. License should be granted.
SHEA, J.R. Office of International Programs. 79/06/15. 1p.

7908130100 SECY-79-218A
Forwards application by Transnuclear, Inc to amend license to export 12,932 kg U-235, contained in 45,113 kg U enriched to max of 45.4%
SHEA, J.R. Office of International Programs. 79/07/02. 1p.

--7908130109 Forwards end use statement for application by Transnuclear, Inc to amend license to export 12,932 kg U-235, contained in 45,113 kg U enriched to max 45.4%, to Greece, Austria, Sweden, Switzerland, Denmark, The Netherlands, Venezuela & Brazil.
MATSON, V. Transnuclear, Inc. 79/06/19. 3pp.

7908130129 SECY-79-655B
Notifies of review of application by Mitsui & Co to export 3,511 kg U-235, contained in 157,382 kg U enriched to 2.55%, to Japan. Recommends license be issued.
SHEA, J.R. Office of International Programs. 79/06/18. 3pp.

--7908130136 Application by Mitsui & Co to export 3,511 kg U-235, contained in 157,382 kg U enriched to 2.55% to Japan.
MONDEN, T. Mitsui & Co., Ltd. 78/11/28. 2pp.

--7908130141 Executive Branch position re Mitsui & Co application for license to export 3,511 kg U-235, contained in 157,382 kg U enriched to 2.55% to Japan. Ltr of assurance encl. License should be granted.
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/05/23. 3pp.

--7908130147 Mitsui & Co license to export 3,511 kg U-235, contained in 157,382 kg U enriched 2to 2.55% to Janpan.
OPLINGER, G.G. Assistant Director for Export/Import & International Safeguards. 79/05/23. 2pp.

7908130151 SECY-79-072B
Recommends Commission approve issuance of proposed license for GE to export 161 kg U-235, contained in 5,875 kg U enriched to max of 3.1% to Japan.
SHEA, J.R. Office of International Programs. 79/06/19. 3pp.

--7908130153 Application by GE to export 161 kg U-235, contained in 5,875 kg U enriched to max 3.1% to Japan.
* General Electric Co. 78/12/22. 1p.

--7908130137 Executive Branch position re GE application for licenso to export 161 kg U-235, contained in 5,875 kg U enriched 3.1% to Japan. Licensee south should be granted. Ltr of assurance encl.
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/05/29. 3pp.

--7908130163 GE license to export 161 kg U-23. intained in 5,875 kg U enriched to max 3.1% o Japan.
* Assistant Director for Export/Import & International Safeguards. 79/05/29. 2pp.

7908130401 SECY-79-327
Seeks NRC approval to publish amend to 10CFR50 & 10CFR70 re onsite ofc space for resident inspectors & immediate facility access to insp personnel.
DAVIS, J.G. Office of Inspection & Enforcement, Office of the Director. 79/05/11. 26pp.

7908130618 SECY-79-282A
Recommends NRC approve application by Mitsubishi Intl Corp for license to export 11,983 kg U-235, enriched to 2.85% to Japan.
SHEA, J.R. Office of International Programs. 79/06/01. 4pp.

--7908130629 Application by Mitsubishi Intl Corp for license to export contained 11,983 kg U-235, enriched to 2.85% to Japan. End use statement encl.
TSUJI, K. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). 78/10/31. 2pp.

--7908130646 Forwards application by Mitsubishi Intl Corp for license to export 11,983 kg U, enriched to 2.85% to Japan.
WATANBE, N. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5479-02. 78/10/31. 3pp.

--7908130653 Executive Branch position re Mitsubishi Intl Corp application for license to export 11,983 kg U-235, enriched to 2.85% to Japan. License should be granted.
NOSENZO, L.V. State, Dept. of. 79/04/16. 2pp.

--7908130659 License for Mitsubishi Intl Corp to export 11,983 kg, enriched to 2.85% to Japan.
OPLINGER, G.G. Assistant Director for Export/Import & International Safeguards. HSA-5479-02. 79/06/01. 2pp.

7908130655 Notifies of receipt of application by GE for license to export six traversing incore probe detector assemblies to India.
SHEA, J.R. Office of International Programs. 79/05/16. 1p.

7908140257 SECY-79-294
Seeks NRC approval to publish amend to 10CFR34 as final rule intended to improve radiography safety & make regulations more compatible w/current licensing practices.
MINOGUE, R.B. Office of Standards Development. 79/04/26. 50pp.

--7908140268 Draft notice of issuance to amend to 10CFR34, "Licenses for Radiography Safety Requirements for Radiography Operations."
CHILK, S.J. Office of the Secretary of the Commission. 7590-01. 79/04/26. 18pp.

--7908140277 Value/impact statement on Amend of 10CFR34.
* Office of Standards Development. 79/04/26. 14pp.

--7908140292 Notifies of review of draft paper re reduction of radiography overexposures. Recommends approval of proposed final rule. Remainder of program may not maintain rate of implementation expected.
RENNEKE, A. Office of Policy Evaluations. 79/03/20. 2pp.

7908140364 SECY-78-671B
Recommends that NRC approve application by Mitsui & Co to export 756 kg U-235, contained in 26,902 kg U enriched to 3.95% w/o max, to Japan.
SHEA, J.R. Office of International Programs. 79/06/15. 3pp.

--7908140370 Application by Mitsui & Co to export 756 kg U-235, contained in 26,[illegible] enriched to 3.95% w/o max, to Japan.
MONDEN, [illegible] Co., Ltd. 78/12/08. 2pp.

--7908140[illegible] License for Mitsui & Co to export 756 kg, enriched to 3.95%, to Japan.
* Office of International Programs. 79/06/15. 1p.

7908140620 Info rept re [illegible]507 application for License XSNM-1510 to export U hexafluoride Japan. Forwards Marubeni America Corp application and 790507 ltr.
SHEA, J.R. Office of International Programs. 79/05/17. 1p.

7908170503 Transcript of Affirmation Session 79-20 on 790719 in Washington, DC. Pp 1-3.
HENDRIE, J. M., BRADFORD, P. A., AHEARNE, J. F. Commission. 79/07/19. 5pp.

--7908170507 SECY-79-443
Recommends Commissioners approve publication in FR of proposed new sys of records, Special Inquiry File NRC-33 & proposed amends of routine uses of records sys.
DONOGHUE, D. J. Office of Administration. 79/07/18. 14pp.

7908200255 Responds to FOIA request for documents re NRC decision to recommend to Dept of Commerce that export license be granted to Westinghouse. Forwards J Shea 790615 ltr to Dept of Commerce & 790611 SECY-79-382.
FELTON, J. M. Division of Rules and Records. 79/08/14. 1p.

--7908200265 SECY-79-382
Requests NRC views on proposed Westinghouse export of turbine generators to Philippines.
SHEA, J. R. Office of International Programs. 79/06/11. 4pp.

7908200330 SECY-79-330
Informs NRC of number of plant superintendents & assistant superintendents holding current operator licenses & how many licensed in past. (L-4-1, pt. 55)
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/14. 2pp.

7908200343 Results of survey to determine profile of operators & senior operators & comparison w/profile of people in other regulated industries. (L-4-1, pt. 55)
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/29. 12pp.

7908200389 SECY-9-330B
Info rept on approach by other agencies to training for unanticipated accident sequences & operator responses by using sys simulators & recommendations for NRC operator licensing program.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/12. 9pp.

7908200391 SECY-79-330C
Info rept on results of examinations administered to licensed operators in facility-administered requalification programs.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/02. 3pp.

7908200393 SECY-79-330D
Info rept on Navy nuclear training & requalification program & comparison of NRC license program w/Navy program. Forwards "Commercial Power Reactor Training Programs Reviewed by NRC" & "Navy Nuclear Propulsion Training Programs."
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/05. 37pp.

7908210101 Transcript of Commissioners 790724 public meeting in Washington, DC re SECY-79-187A. Pp 1-49.
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission. 79/07/24. 50pp.

--7908210104 SECY-79-187A
SECY-79-187A change to upgrade rulemaking "high assurance" requirement an objective.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 79/07/13. 5pp.

7908210156 SECY-78-311A
Discusses status of review of urban transportation safeguards study. Proposed research program requested in Smith 780725 memo is suitable for resolving technical problems raised by Sandia study (SAND 77-1927).
MINOGUE, R. B. Office of Standards Development. 78/11/09. 13pp.

--7908210162 Forwards research requirement describing Div of Safeguards need to support evaluation of spent fuel shipment vulnerability to malevolent events. Requests preparation of work scope, schedule & cost estimate.
SMITH, C. V. Office of Nuclear Material Safety & Safeguards. 78/07/25. 5pp.

7908210364 Unofficial transcript of 790727 Affirmation Session 79-22.
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission. 79/07/22. 6pp.

--7908210372 SECY-79-163
Recommends NRC approve petition for rulemaking 10CFR2.802. Notice of rulemaking encl.
DONOGHUE, D. J. Office of Administration. 79/03/07. 84pp.

7908230163 SECY-78-256
Discusses current status & alternatives on adequate waste disposal capacity for low level wastes. Requests approval of interim program to ship wastes to western sites & contingency plan to back up commercial sites.
SMITH, C. V. Office of Nuclear Material Safety & Safeguards. 79/05/12. 12pp.

--7908230170 Notifies that adequate regionally distributed disposal capacity for low level radwastes will not be available at currently operating facilities. Agencies should work together to examine possible solutions.
HENDRIE, J. M. Commission. 78/07/07. 2pp.

--7908230173 Responds to 780707 ltr re disposal of low level waste. Agencies should work together to examine possible solutions.
MYERS, D. D. Energy, Dept. of. 78/08/04. 1p.

--7908230180 Notifies that Nuclear Engineering Co is closing Sheffield, IL commercial low level radwaste disposal site & terminating lease. DOE should be prepared to take immediate, short-term contingency action for acceptance of radwaste.
MARTIN, J. B. Division of Waste Management. 79/04/05. 1p.

--7908230184 Discusses present status of commercial burial ground. Federal govt must be prepared for contingency re adequate capacity for mgt of commercial low level waste.
DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards. 78/12/12. 1p.

--7908230189 Responds to 781025 request for suggestions re low level waste disposal capacity. Recommends four scenarios.
BELL, R. J. Division of Waste Management. 78/11/30. 2pp.

--7908230194 Notifies of current status of disposal capacity for mgt of low level radwaste. DOE should develop contingency plans for acceptance of commercially generated wastes.
HENDRIE, J. M. Commission. 78/07/07. 4pp.

--7908230199 Notifies of current status of disposal capacity for mgt of low level radwaste. DOE should develop contingency plans for acceptance of commercially generated wastes.
HENDRIE, J. M. Commission. 78/07/07. 3pp.

7908240350 SECY-79-397
Requests initiation of rulemaking proceeding re safe & permanent method of waste disposal.
SHAPAR, H. K. Office of the Executive Legal Director. 79/06/18. 13pp.

--7908240359 Summarizes DC Circuit 790523 opinion in State of MN vs NRC. Prsent S-3 proceeding should be concluded promptly w/issuance of final S-3 rule & statement of considerations.
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission. 79/06/11. 13pp.

--7908240365 Notifies of agreement w/Eilperin 790611 memo re State of MN vs NRC. Generic rulemaking proceeding should be instituted to consider disposal of spent fuel & onsite & offsite storage capacity.
HAPAR, H. K. Office of the Executive Legal Director. 79/06/18. 2pp.

--7908240370 Responds to 790614 memo re proceeding on safe disposal of radwaste. Committee should hear arguments & receive oral & written statements to develop record. No provision for discovery.
DIRCKS, W. J. Office of Nuclear Material Safe., & Safeguards. 79/06/15. 3pp.

7908240520 SECY-79-222B
Commissioner action recomminding issuance of license to Marbeni America Corp to export U-235, contained in 25,723 kg U enriched to 3.9%, to Japan.
SHEA, J. R. Office of International Programs. 79/07/24. 4pp.

--7908240524 Application by Marubeni America Corp to export U-235, contained in 25,723 kg U enriched to 3.90% to Japan.
HIROSHIMA, K. Marubeni America Corp. (subs. of Marubeni Corp.). 240076. 79/03/20. 1p.

--7908240527 Forwards application to export U-235, contained in 25,723 kg U enriched to 3.90% to Japan.
KUBO, H. Marubeni America Corp. (subs. of Marubeni Corp.). MAL-HK-5800. 79/03/20. 1p.

--7908240530 Confirms that SNM covered in Licenses XSNM-1473 & XSNM-1484 will be used in same reactor in Jul 1980 as second reload fuels.
KUBO, H. Marubeni America Corp. (subs. of Marubeni Corp.). MAI-HK-5862. 79/05/11. 1p.

--7908240538 Recommends issuance of license to Marubeni America Corp to export U-235, contained in 25,723 kg U enriched to 3.90% to Japan. Ltr of assurance encl.
NOSENZO, L. V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/06/22. 3pp.

--7908240541 License for Marubeni America Corp to export U-235, contained in 25,723 kg U enriched to 3.90% to Japan.
PETERSON, M.R. Office of International Programs. 2H0076.
79/07/24. 2pp.

7908240545 SECY-79-249C
Recommends issuance of license to GE to export U-235, contained in 29,526 kg U enriched to 3.65% to Japan.
SHEA, J.R. Office of International Programs. 79/07/24. 3pp.

--7908240548 Application by GE for license to export U-235, contained in 29,526 kg U enriched to 3.65% to Japan.
* General Electric Co., Nuclear Energy Products Div. 79093.
79/04/03. 4pp.

--7908240551 Revises 790403 application. First shipment to Japan is rescheduled for 790831.
WILSON, B.D. General Electric Co., Nuclear Energy Products Div.
BDW-79098. 79/04/13. 1p.

--7908240553 Recommends issuance of license to GE to export U-235, contained in 29,526 kg U enriched to 3.65% to Japan. Ltr of assurance encl.
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/06/22. 3pp.

--7908240556 License for GE to export U-235, contained in 29,526 kg U enriched to 3.65% to Japan.
PETERSON, M.R. Office of International Programs. 79093. 79/07/24.
2pp.

7908280867 SECY-79-427
Provides data per NRC 790619 request re deferral of reactor licenses & scheduling.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/07/05. 3pp.

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

7907100694 Discusses repts NEDE-21175-P & NEDO-21175, "BWR/6 Fuel Assembly Evaluation of Combined SSE & LOCA Loadings." Concludes analytical methods described are acceptable for ref in license applications. Staff evaluation encl.
PARR, O.D. Light Water Reactors Branch 3. 79/05/17. 8pp.

7907230388 Forwards draft post-LOCA procedural guidelines as preliminary response to RW Reid 790605 ltr. Question 16 Right to modify guidelines is reserved as analysis results become available.
LIEBLER, G.E. C-E Operating Plants Owners Group. 79/07/20. 13pp.

7907310517 Grants 30-day extension to permit accurate & complete answer to 790430 request for addl info.
HAASS, W.P. Quality Assurance Branch. 79/06/13. 1p.

7908010337 Core performance branch topical rept evaluation "BWR/6 Fuel Assembly Evaluation of Combined SSE & LOCA Loadings." Analytical methods described in rept acceptable. Evaluation includes in NEDO-21175-P & NEDO-21175.
* Core Performance Branch. 79/04/30. 5pp.

7908010374 Comments on EG&G draft repts, "State-of-the-Art Literature Review of Waterhammer," "Analysis Tool for Predicting Hydrodynamics in Nuclear Piping Sys Swing Check Valves" & "Review & Evaluation of Actual & Potential Events."
COLMAR, R. Division of Operating Reactors. 79/07/02. 3pp.

7908010465 Forwards WCAP-9500, "Ref Core Rept 17 x 17 Optimized Fuel Assembly."
ANDERSON, T.M. Westinghouse Electric Corp. NS-TMA-2109. 79/07/30.
2pp.

--7908010471 WCAP-9500 V1
"Ref Core Rept 17 x 17 Optimized Fuel Assembly," Vol 1.
* Westinghouse Electric Corp. 79/08/01. 361pp.

--7908010481 WCAP-9500 V2
"Ref Core Rept 17 x 17 Optimized Fuel Assembly," Vol 2.
* Westinghouse Electric Corp. 79/08/01. 491pp.

--7908010487 WCAP-9500 V3
"Ref Core Rept 17 x 17 Optimized Fuel Assembly," Vol 3.
* Westinghouse Electric Corp. 79/08/01. 444pp.

--7908010488 WCAP-9500 V4
"Ref Core Rept 17 x 17 Optimized Fuel Assembly," Vol 4.
* Westinghouse Electric Corp. 79/08/01. 590pp.

7908010568 Expresses appreciation for NRC recommendations re new requirements for reactor effluent monitoring.
CORTE, E.A. General Atomic Co. (subs. of Gulf Oil Corp.). 79/07/26.
1p.

7908010570 Responds to 790621 request for info re pipe cracks. Forwards topical rept NEDO-23631 re BWR coolant oxygen control & related documents.
GRIDLEY, R.L. General Electric Co., Nuclear Energy Products Div.
MFN-188-79. 79/07/20. 40pp.

--7908010576 NEDO-23631
"BWR Coolant Oxygen Control."
COWAN, R.L., ELLIOTT, J.C., JOHANNESON, O.H. General Electric Co., Nuclear Energy Products Div. 77NED106. 77/06/30. 48pp.

7908010635 Requests addl info re "GE Analytical Model for LOCA analysis in accordance w/10CFR50 App K, Amend 1: Calculation of Low Flow Film Boiling Heat Transfer for BWR LOCA Analysis."
PARR, O.D. Light Water Reactors Branch 3. 79/05/30. 10pp.

7908010649 Forwards BAW-10038A, Suppl 1, "Prototype Vibration Measurement Program for Reactor Internals."
TAYLOR, J.H. Babcock & Wilcox Co. 79/06/18. 1p.

--7908010660 BAW-10038A
"Prototype Vibration Measurement Program for Reactor Internals," Suppl 1.
SIMONIS, J.C., POST, R.C., THOREN, D.E. Babcock & Wilcox Co.
79/06/30. 30pp.

7908020508 Forwards BAW-10051A, Suppl 1, "Structural Anaysis of 177-Fuel Assembly Redesigned Surveillance Specimen Holder Tube."
TAYLOR, J.H. Babcock & Wilcox Co. 79/06/18. 2pp.

--7908020516 BAW-10051A
"Structural Analysis of 177-Fuel Assembly Redesigned Surveillance Specimen Holder Tube," Suppl 1.
PRYOR, C.W., THOREN, D.E., VAMES, G.J. Babcock & Wilcox Co.
79/06/01. 50pp.

7908030370 Forwards NEDE-24645-P, "Analysis of Full Scale Test Facility for Condensation Oscillation Loading." Rept withheld (ref 10CFR2.790). Affidavit of GG Sherwood encl.
SOBON, L.J. General Electric Co., Nuclear Energy Products Div.
MFD-192-79. 79/07/30. 5pp.

7908070446 Notifies that organizational changes have taken place effective 790701, as required by licensing topical rept NEDO-11209-04A.
BREED, A. General Electric Co., Nuclear Energy Products Div.
79/08/02. 3pp.

7908070553 Comments on development of IEEE-566, "Guide for Design of Display & Control Facilities for Central Control Rooms & for Nuclear Generating Stations." Forwards documents re operator-control interface.
STEPHENS, J.V. Brown & Root Corp. (subs. of Halliburton Corp.).
79/07/31. 32pp.

7908070588 Forwards "Auxiliary Feedwater Flow Rate Following Loss of Main Feedwater (177 Fuel Assembly Plants)."
TAYLOR, J.H. Babcock & Wilcox Co. 79/08/01. 1p.

--7908070597 "Auxiliary Feedwater Flow Rate Following Loss of Main Feedwater (177 Fuel Assembly Plants)."
* Babcock & Wilcox Co. 79/08/01. 8pp.

7908070641 Provides requested info re two-loop test apparatus results, mass & energy balance tests, discussion of scaling basis & addl evaluation of LOCA model comparisons.
BUCHHOLZ, R.H. General Electric Co., Nuclear Energy Products Div.
MFN-198-79. 79/07/31. 91pp.

7908070664 Informs that PISYS computer code analysis of five benchmark problems are complete & in general agreement w/values given w/problem definition. Formal rept to follow. W/summary of PISYS code info provided to NRC.
GRIDLEY, R.L. General Electric Co. MFN-195-79. 79/07/31. 3pp.

7908070677 Notifies that friction factor defined in equations 4.7 & 4.8b of "Generic Emergency Cooling Pond Analysis" is incorrect. Forwards derivation of friction factor, as defined in "Open Channel Hydraulics" by V.T. Chow.
GEISLER, A.H. Brown & Root Corp. (subs. of Halliburton Corp.).
79-NL-203. 79/08/01. 2pp.

7908080452 Notifies of organizational changes in Engineering Assurance Div & submits summary description. Will incorporate changes in next QA program revision. W/o encl.
KELLEY, R.B. Southwest Econometrics, Inc. 79/08/01. 1p.

7908080461 Forwards BAW-1517,Revision 1, "Effects on Hydrodgramic Mass Coupling on Transient Response of Reactor Internals to Asymmetric LOCA Load." Rept withheld (ref 10CFR2.790). Affidavit encl.
TAYLOR, J.H. Babcock & Wilcox Co. 79/07/30. 88pp.

7908080468 Advises of need to consult w/util customers before responding to NRC 790712 request re reactor vessel brittle fracture.
TAYLOR, J.H. Babcock & Wilcox Co. 79/08/03. 1p.

7908080481 Advises that no further action is planned re upgraded SIS program unless directed by [illegible]ected utils.
TAYLOR, J.H. Babcock & Wi[illegible]co. 79/08/03. 1p.

7908090247 Forwards nonproprietary version of NEDO-21052-A, "Max Discharge Rate of Liquid-Vapor Mixture from Vessel," submitted by GE.
CAPRA, R.A. Light Water Reactors Branch 3. 79/07/13. 1p.

--7908090254 Forwards revised nonproprietary version of NEDO-21052-A "Max Discharge Rate of Liquid-Vapor Mixtures From Vessels." Includes text of original rept, supplementary info, D Eishenhut 781227 ltr & NRC evaluation.
SOBON, L.J. General Electric Co. 79/06/25. 2pp.

--7908090262 NEDO-21052-A "Max Discharge Rate of Liquid-Vapor Mixtures for Vessels."
MOODY, E.J. General Electric Co. 79/05/31. 78pp.

7908090270 Forwards nonproprietary version of NEDO-24057-2, "Assessment of Reactor Internals Vibration in BWR/4 & BWR/5 Plants, Amend 2," submitted by GE.
CAPRA, R.A. Light Water Reactors Branch 3. 79/07/13. 1p.

--7908090277 Forwards proprietary & nonproprietary versions of NEDO-24057-2, "Assessment of Reacctor Intervals Vibration in BWR/4 & BWR/5 Plants, Amend 2." Proprietary version withheld (ref 10CFR2.790).
GUIRK, J.F. General Electric Co., Nuclear Energy Products Div. 79/06/26. 1p.

--7908090286 NEDO-24057-2 "Assessment of Reactor Internals Vibration in BWR/4 & BWR/5 Plants, Amend 2." NEDO-24057-2
HUTCHINGS, R.E. General Electric Co., Nuclear Energy Products Div. 79/06/30. 38pp.

7908090440 Forwards nonproprietary version of NEDO-24076-1, "Design Rept & Safety Evaluation for High Density Fuel Storage Sys, Amend 1," submitted by GE.
CAPRA, R.A. Light Water Reactors Branch 3. 79/07/13. 1p.

--7908090453 Forwards proprietary & nonproprietary version of NEDO-24076-1, "Design Rept & Safety Evaluation for High Density Fuel Storage Sys, Amend 1." Proprietary version withheld (ref 10CFR2.790).
GUIRK, J.F. General Electric Co. 79/06/08. 1p.

--7908090458 NEDO-24076-1 NEDO-24076-1, "Design Rept & Safety Evaluation for High Density Fuel Storage Sys, Amend 1."
CARR, J.B. General Electric Co. 79/05/31. 42pp.

7908090491 Advises NRC of creation of C-E-designed plant owners' group on post-TMI efforts.
LIEBLER, G.E. C-E Operating Plants Owners Group. PRN-AD-79-83. 79/08/03. 1p.

7908090549 Forwards nonproprietary version of "Blowdown Analysis Method," CENPD-252-P-NP. Responses to NRC request for addl info have been incorporated. Proprietary rept CENPD-252-P-A withheld (ref 10CFR2.790).
SENERER, A.E. C-E Power Systems. LD-79-041. 79/07/31. 1p.

--7908090555 CENPD-252-NP-A Nonproprietary topical rept, CENPD-252-NP-A, "Blowdown Analysis Method - Method for Analysis of Blowdown Induced Forces in Reactor Vessel."
* C-E Power Systems. 79/07/31. 35pp.

7908090539 Forwards second errata sheet to GE rept NEDE-13468-P, "Mark II Suppression Test Program - Phase II & III Tests." Corrections also applicable to nonproprietary rept, NEDO-13468.
SOBON, L.J. General Electric Co., Nuclear Energy Products Div. MFN-203-79. 79/08/06. 2pp.

7908090587 Forwards revised App 1, "Natural Circulation in B&W Operating Plants (Revision 1)," to rept "Evaluation of Transient Behavior & Small RCS Breaks in 177 Fuel Assembly Plant - 790507."
TAYLOR, J.H. Babcock & Wilcox Co. 79/05/08. 1p.

--7908090592 Revised App 1, "Natural Circulation in B&W Operating Plants (Revision 1)," to rept "Evaluation of Transient Behavior & Small RCS Breaks in 177 Fuel Assembly Plants-790507."
* Babcock & Wilcox Co. 79/05/08. 61pp.

7908100236 Forwards proposed revisions to QA program, Braun Topical Rept TR-21A, re organization, const subsidiaries & editorial errors.
RICKFORD, A.E. C. F. Braun & Co. 79/08/03. 10pp.

7908100446 Forwards CEN-114-P, "Review of Small Break Transients in C-E NSSS" in response to 790605 ltr. Affidavit for withholding (ref 10CFR2.790) encl.
LIEBLER, G.E. Florida Power & Light Co. PRN-AD-79-11. 79/07/16. 6pp.

7908130269 Directs LLL to aid NRC in electrical, instrumentation & control sys support. Forwards std work order & scope of work. FY79 financial plan will be modified to include addl funds.
EISENHUT, D.G. Division of Operating Reactors. 79/07/02. 1p.

--7908130275 Std order for DOE work "Electrical, Instrumentation & Control Sys Support," issued to LLL.
TRIPLETT, P. Division of Operating Reactors. FIN-A0231. 79/06/20. 2pp.

7908130449 Forwards "Further Evaluation & Interpretation of BD/ECC-1A Data." Rept includes summary of two-loop test apparatus (TLTA), two-loop break flow study & evaluation of two-loop separator pressure drop.
BURNETTE, G.W. General Electric Co. 79/07/31. 1p.

--7908130451 "Further Evaluation & Interpretation of BD/ECC-1A Data."
* General Electric Co. FIN B-3014. NRC-04-76-215. 79/07/31. 45pp.

7908130450 Forwards May 1979 rept NEDE-25116-P, "Comparison of Mark II Multi-Vent Model w/Preliminary Results From Scaled Multi-Vent Test Program." Encl withheld (ref 10CFR2.790).
SOBON, L.J. General Electric Co., Nuclear Energy Products Div. MFN-194-79. 79/07/30. 2pp.

7908140035 BNL-NUREG-26429 "Dynamic Simulation of LMFBR Sys."
AGRAWAL, A.K., KHATIB-RAHBAR, M. Brookhaven National Laboratory. 79/07/31. 363pp.

7908140398 Forwards proprietary version of BAW-10131P, "Reactor Coolant Sys Hydrodynamic Loadings During LOCA." Rept contains response to requests for addl info. Rept withheld (ref 10CFR2.790).
TAYLOR, J.H. Babcock & Wilcox Co. 79/07/20. 1p.

7908140471 Believes requested info re test & analytical methods & techniques used in measurement of core physics parameters can be found in listed topical repts & ltrs. Submittal of addl topical repts unnecessary.
ANDERSON, T.M. Westinghouse Electric Corp. NS-TMA-2117. 79/08/01. 2pp.

7908140736 Forwards revised SSCD-15215, "Containment Spray Nozzles for Nuclear Power Plants," in response to 790703 request.
GRAY, E.S. Spraying Systems Co. 79/08/03. 1p.

--7908140742 Forwards final evaluation of topical rept SSCD-15215, "Containment Spray Nozzles for Nuclear Power Plants."
BAER, R.L. Light Water Reactors Branch 2. 79/07/03. 2pp.

--7908140747 Topical rept evaluation for SSCD-15215(NP), "Containment Spray Nozzles for Nuclear Power Plants." Rept is acceptable.
* Light Water Reactors Branch 3. 79/07/03. 1p.

--7908140752 Topical Rept SSCD-15215, "Containment Spray Nozzles for Nuclear Power Plants."
* Spraying Systems Co. 77/04/30. 28pp.

7908150161 Forwards Westinghouse TM Anderson 790622 ltr re deficiency on reactor trip initiation from steam generator level.
JORDAN, E.L. Division of Reactor Operations Inspections. 79/07/09. 1p.

--7908150169 Advises that util customers were informed of mods to be applied to steam generator water level protection sys & emergency operating procedures in order to correct deficiency.
ANDERSON, T.M. Westinghouse Electric Corp. NS-TMA-2104. 79/06/22. 5pp.

7908150654 Discusses participation in technical discussion re semi-scale test program. Will review LOCA models to assess potential for downcomer voiding. Proposed completion date 791231.
ANDERSON, T. M. Westinghouse Electric Corp. NS-TMA-2119. 79/08/02. 2pp.

7908150670 Forwards NEDO-24640, "Off-Centerline 1/4-Scale T-Quencher Test Rept," nonproprietary version of NEDE-24640-P.
SOBON, L. J. General Electric Co., Nuclear Energy Products Div. MFN-193-79. 79/07/30. 1p.

--7908150675 NEDO-24640
"Off-Centerline 1/4-Scale T-Quencher Test Rept."
KISS, E., ROGERS, A. E., TOWNSEND, H. E. General Electric Co., Nuclear Energy Products Div. 79NED94. 79/06/30. 70pp.

7908150681 Forwards NEDO-21943, "Mark I Containment Program 1/4-Scale Pressure Suppression Pool Swell Test Program: Download Oscillation Evaluation," nonproprietary version of NEDE-21943-P.
SOBON, L. J. General Electric Co., Nuclear Energy Products Div. MFN-196-79. 79/08/01. 1p.

--7908150687 NEDO-21943
"Mark I Containment Program 1/4-Scale Pressure Suppression Pool Swell Test Program Download Oscillation Evaluation."
HUMPHREY, J. M., WADE, G. E., IANNI, P. W. General Electric Co. 79NED70. 79/06/30. 79pp.

7908160421 Forwards rept, "Assessment of BWR/3 Mark I Mitigation of ATWS in Response to NUREG 0460." Rept withheld (ref 10CFR2.790).
BUCHHOLZ, R. H. General Electric Co., Nuclear Energy Products Div. MFN-191-79. 79/07/27. 1p.

7908170135 Discusses 790702 responses to NRC 790430 questions re QA program description. Forwards regulatory staff position on items of disagreement. Requests response within 45 days.
HAASS, W. P. Quality Assurance Branch. 79/08/06. 3pp.

7908170162 Notification of 790724 meeting w/C-E owners group in Bloomfield, CT to discuss submittals on small break analyses & plans on subsequent submittals expected on 790730.
VILLALVA, I. Standardization Branch. 79/07/17. 2pp.

7908170301 Discusses upgraded STS bases program. Approves exemption from fees for Classes I-III amends which result directly from upgrading program. Requests present status to aid in formulation of schedule.
GIMES, B. K. Assistant Director for Systems Engineering. 79/07/12. 2pp.

7908170316 Forwards nonproprietary version of topical rept BAW-10133P, Revision 1, "Mark C Fuel Assembly LOCA - Seismic Analyses."
TAYLOR, J. H. Babcock & Wilcox Co. 79/07/02. 1p.

--7908170319 BAW-10133 Revision 1, "Mark C Fuel Assembly LOCA Seismic Analyses."
SHAH, S. J., LIDE, R. E. Babcock & Wilcox Co. 79/06/30. 49pp.

7908170336 Forwards proprietary Pages 3 & 5 replacing same pages of encl to 790115 ltr re review of topical rpts on Class IE electrical & control equipment. Recipient requested to destroy old pages per 10CFR2.790 requirements.
STOLZ, J. F. Light Water Reactors Branch 1. 79/08/02. 1p.

7908170403 Forwards WCAP-8183, Revision 8, "Operational Experience w/Westinghouse Cores (Up to 781231)."
ANDERSON, T. M. Westinghouse Electric Corp. FLW-79-021. 79/07/12. 1p.

--7908170407 WCAP-8183
"Operational Experience w/Westinghouse Cores (Up to 781231)."
SKARITKA, J., IORII, J. A., ARLOTTI, M. G. Westinghouse Electric Corp. 79/04/30. 36pp.

7908170416 Discusses re-execution of mainstream analysis extending analysis from one to four seconds for 5% & 2% damping. Determines that structural loading functions had decayed to insignificant levels.
KITZ, G. T. Sargent & Lundy, Inc. 79/08/15. 23pp.

7908200210 Forwards "Solidification Sys Topical Rept."
REYNOLDS, L. E. Chem-Nuclear Systems, Inc. 79/07/20. 1p.

--7908200211 "Solidification Sys Topical Rept."
* Chem-Nuclear Systems, Inc. 79/07/20. 175pp.

7908200304 Forwards "Rept on Small Break Accidents for Westinghouse NSSS Sys," Vols 1-3, Proprietary version, WCAP-9600, transmitted on 790709.
ANDERSON, T. M. Westinghouse Electric Corp. NS-TMA-2121. 79/08/17. 1p.

--7908200310 WCAP-9601 V1
"Rept on Small Break Accidents for Westinghouse NSSS Sys," Vol I.
ANDERSON, T. M. Westinghouse Electric Corp. 79/06/30. 600pp.

--7908200307 WCAP-9601 V2
"Rept on Small Break Accidents for Westinghouse NSSS Sys," Vol II.
ANDERSON, T. M. Westinghouse Electric Corp. 79/06/30. 700pp.

--7908200313 WCAP-9601 V3
"Rept on Small Break Accidents for Westinghouse NSSS Sys," Vol III.
ANDERSON, T. M. Westinghouse Electric Corp. 79/06/30. 800pp.

7908200332 Submits updated info re piping improvement program.
WATANABE, J. T. General Electric Co., Nuclear Energy Products Div. MGN-204-79. 79/08/09. 3PP.

7908210143 Submits proposed schedule for completion of FY79 electrical tasks assigned to LLL.
SHEMANSKI, P. Plant Systems Branch. 79/07/20. 4pp.

7908210296 Forwards "Integrated Control Sys Reliability Analysis," performed at NRC request. Analysis supports sys reliability.
TAYLOR, J. H. Babcock & Wilcox Co. 79/08/17. 2pp.

--7908210299 BAW-1564
"Integrated Control Sys Reliability Analysis."
DUNGAN, R. L., JOYNER, L. L., BENNETT, G. P. Babcock & Wilcox Co. 79/08/31. 100pp.

7908210499 Forwards revised pages of QA program topical rept XN-NF-1A, incorporating minor programmatic changes. Notifies that organizational change, effective 790801, will also be included in next published revision.
PERRY, J. A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/08/14. 1p.

--7908210503 XN-NF-1A
QA program topical rept XN-NF-1A, Revision 3, pages 3.3, 4.1, 5.2 & 20.2, incorporating minor programmatic changes.
* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/08/14. 4pp.

7908210558 Notifies that response to 790713 request re hydraulic oscillations in Semiscale Mod-3 Sys will be completed during Sept.
SCHERER, A. E. C-E Power Systems. LD-79-047. 79/08/15. 1p.

7908210564 Forwards XN-NF-76-6-NP, "Exxon Nuclear Analysis of Power Distribution Measurement Uncertainty for Westinghouse PWRs." Proprietary version withheld (ref 10CFR2.790).
OWSLEY, G. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-79-6. 79/07/19. 2pp.

--7908210569 XN-NF-79-6 (NP)
"Exxon Nuclear Analysis of Power Distribution Measurement Uncertainty For Westinghouse PWRs." Proprietary version withheld (ref 10CFR2.790).
HOLM, J. S., GRAVES, H. M., JAECH, J. L. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/07/31. 70pp.

7908210572 Forwards XN-NF-512-NP, "XN-3 Critical Power Correlation."
OWSLEY, G. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-512. 79/07/20. 1p.

--7908210577 XN-NF-512 (NP)
"XN-3 Critical Power Correlation." Proprietary version withheld (ref 10CFR2.790).
PATTEN, T. W., JAECH, J. L. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/07/31. 50pp.

7908220098 Forwards "Interim Rept on the Results of ATWS Early Verification Analyses." Rept delayed due to TMI-2 event response.
TAYLOR, J. H. Babcock & Wilcox Co. 79/07/11. 1pp.

7908220342 Submits scope & schedule of auxiliary feedwater sys reliability analyses to be submitted to NRC during 1979, as agreed upon during 790809 B&W owners group/NRC meeting. B&W will perform analyses.
TAYLOR, J. H. Babcock & Wilcox Co. 79/08/16. 2pp.

7908230041 Forwards request for addl info re proposed load definition techniques in order to complete evaluation of "Mark I Containment Program Load Definition Rept," NEDO 21888. First round questions transmitted 790503 encl.
EISENHUT, D. G. Office of Nuclear Reactor Regulation. 79/07/30. 5pp.

7908230367 Forwards evaluation of Revision 3 of TVA-TR75-1, "QA Program Description," submitted w/790622 ltr. QA program meets criteria & can be implemented upon issuance.
HAASS, W. P. Quality Assurance Branch. 79/08/14. 1p.

--7908230480 Topical rept evaluation of TVA-TR75-1, "QA Program Description." Rept acceptable.
* Quality Assurance Branch. 79/08/14. 2pp.

7908230443 Forwards responses to questions contained in topical rept BG-TOP-1, in support of previously submitted responses to 790521 ltr. Meeting will be arranged to discuss responses.
DAVIS, W. K. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/08/08. 8pp.

7908240089 GEAP-NUREG-21304-12 "BWR Blowdown Emergency Core Cooling," twelfth quarterly progress rept for Oct-Dec 1978.
FINDLAY, J. A. General Electric Co. NRC-04-76-215. 79/01/31. 24pp. Available at NTIS. $4.00.

7908240363 Notifies that EV DeCarli replaces AL MacKinney as QA manager for B&W Nuclear Power Generation Div. AL MacKinney is now Manager, General Services, Nuclear Generation Div.
TAYLOR, J. H. Babcock & Wilcox Co. 79/08/16. 1p.

7908240400 Responds to 790808 ltr re B&W plans on LOFT Test L2-3. Prior to 790328, B&W was committed to blind analysis of Test L2-3 & had completed significant portion. Work has been halted & no analysis will be submitted.
TAYLOR, J. H. Babcock & Wilcox Co. 79/08/17. 1p.

7908240409 Forwards CREARE rept TN-297, "Conmap Tests Experimental Rept," dtd June 1979. Rept & affidavit withheld (ref 10CFR2.790).
SOBON, L. J. General Electric Co., Nuclear Energy Products Div. MFN-210-79. 79/08/15. 1p.

7908240433 Forwards, "Core Spray Design Methodology Confirmation Tests."
BUCHHOLZ, R. H. General Electric Co. MFN-211-79. 79/08/17. 1p.

--7908240437 "Core Spray Design Methodology Confirmation Tests."
SANDOZ, S. A., MYERS, L. L., SCHUMACHER, D. General Electric Co. 79/08/31. 50pp.

7908240444 Forwards Suppl 3-P to CENPD-225-P & Suppl 3-NP to CENPD-225-NP, "Fuel & Poison Rod Bowing." No operational penalties for C-E plants necessary to account for rod bowing. Suppl 3-P withheld (ref 10CFR2.790).
SCHERER, A. E. Combustion Engineering, Inc. LD-79-042. 79/08/02. 1p.

--7908240449 CENPD-225 Suppl 3-NP to "Fuel & Poison Rod Bowing." Portions withheld (ref 10CFR2.790).
* Combustion Engineering, Inc. 79/06/30. 66pp.

7908240632 Forwards BAW-10120P-A, "Comparison of Core Physics Calculations w/Measurements." Rept contains proprietary info & is located in Central Files only (ref 10CFR2.790).
TAYLOR, J. H. Babcock & Wilcox Co. 79/08/07. 1p.

7908270379 Forwards NEDO-25100, "Mark II Containment Supporting Program, Caorso Safety Relief Valve Discharge Tests, Phase I Test Rept," for Aug 1979.
SOBON, L. J. General Electric Co., Nuclear Energy Products Div. MFN-207-79. 79/08/13. 1p.

--7908270385 NEDO-25100 "Mark II Containment Supporting Program, Caorso Safety Relief Valve Discharge Tests, Phase I Test Rept."
ROGERS, A. S., ENGLISH, W. F., IANNI, P. W. General Electric Co., Nuclear Energy Products Div. 79NED104. 79/08/31. 174pp.

7908280548 Forwards presentation matl from Mark I owners 790815 meeting w/NRC. Attendance list encl.
SOBON, L. J. General Electric Co. MFN-215-79. 79/08/22. 59pp.

7908280550 Forwards revised pages to QA Topical Rept 21A, updating QA program per 790803 ltr.
PICKFORD, A. E. C. F. Braun & Co. 79/08/21. 7pp.

7908280563 Confirms support for upgraded STS bases program in event program is re-established by NRC. Further action not considered until sufficient number of utils express interest in revival of program.
SHERWOOD, G. G. General Electric Co., Nuclear Energy Products Div. MFN-212-79. 79/08/20. 1p.

7908280596 Forwards supplemental info re method used to obtain Mark III structural responses to multivalve loading cases used in piping & equipment evaluations to expedite NRC review. Info withheld (ref 10CFR2.790).
SOBON, L. J. General Electric Co., Nuclear Energy Products Div. MFN-216-79. 79/08/23. 2pp.

7908280648 Forwards "Mark I Containment Program Activity Review" for Jul 1979.
SOBON, L. J. General Electric Co., Nuclear Energy Products Div. MFN-214-79. 79/08/21. 1p.

--7908280652 "Mark I Containment Program Activity Review" for Jul 1979.
* General Electric Co., Nuclear Energy Products Div. 79/07/31. 6pp.

7908290065 Ack receipt of 790619 ltr re recent change description to organization of three divs of util group. Will be presented formally in revised QAI-TR-106 "Util QA Program."
HAASS, W. P. Quality Assurance Branch. QAI-TR-106. 79/07/09. 1p.

7908290463 Notifies that schedule to continue ATWS early verification program will be forwarded by 790831 per 790725 meeting.
SCHERER, A. E. C-E Power Systems. LD-79-049. 79/08/24. 1p.

7908290697 Forwards Amend 4 to CENPD-153, "Measurement Uncertainty for Assembly Power Distributors." Affidavit encl. Proprietary info withheld (ref 10CFR2.790).
SCHERER, A. E. C-E Power Systems. LD-79-046. 79/08/15. 7pp.

--7908290707 Amend 4 to CENPD-153, "Measurement Uncertainty for Assembly Power Distributions."
* C-E Power Systems. 79/08/29. 125pp.

7908300313 Forwards first draft at NRC acceptance criteria for implementation of Mark I containment long-term program.
EISENHUT, D. G. Division of Operating Reactors. 79/08/02. 1p.

--7908300316 Draft NRC acceptance criteria for implementation of Mark I containment long-term program.
* Division of Operating Reactors. 79/08/02. 58pp.

7908300666 Forwards for approval EDR-1, "Ederer's Nuclear Safety-Related Extra Safety & Monitoring (X-SAM) Cranes." Affidavit encl. Proprietary version withheld (ref 10CFR2.790.)
CLARK, C. W. Ederer, Inc. (subs. of Formac International, Inc.). 78/08/22. 8pp.

--7908300672 EDR-1 "Ederer's Nuclear Safety-Related Extra Safety & Monitoring (X-SAM) Cranes," nonproprietary version.
* Ederer, Inc. (subs. of Formac International, Inc.). 79/06/25. 12pp.

7908300733 Forwards "Reduced Notch Worth Procedure, Revision 2." Procedure was updated following issuance of IE Bulletin 79-12. Contains recommendations to prevent scram due to reactivity insertions.
ENGEL, R. E. General Electric Co., Nuclear Energy Products Div. 79/08/24. 10pp.

--7908300737 "Reduced Notch Worth Procedure, Revision 2."
* General Electric Co., Nuclear Energy Products Div. 79/07/31. 10pp.

7908300738 Notification of 790821 meeting w/Bechtel in Bethesda, MD to discuss extent of applying ANSI N45.2.13 in conjunction w/ASME code & effectiveness of QA program on generic basis.
GILRAY, J. W. Quality Assurance Branch. 79/08/10. 1p.

7908310270 Responds to 790801 ltr describing organizational changes in QA program. Approves incorporation of changes in SWSQAP 1-74A.
HAASS, W. P. Quality Assurance Branch. 79/08/24. 3pp.

7908310441 Forwards NEDO-21864, "Mark I Containment Program, Final Rept, Monticello T-Quencher Test."
SOBON, L. J. General Electric Co., Nuclear Energy Products Div. MFN-205-79. 79/08/13. 1p.

--7908310446 NEDO-21864
"Mark I Containment Program.Final Rept,Monticello T-Quencher Test."
TANNER,M.E.; STARKS,S.J.; IANNI,P.W. General Electric Co.,Nuclear Energy Products Div. 79NED73. 79/06/30. 455pp.

7908310493 Discusses company position on ATWS issue in light of TMI event.Many concerns are being addressed by several programs. Presents seven groups of questions needing clarification by NRC & schedule for responding to concerns.
ANDERSON,T.M. Westinghouse Electric Corp. NS-TMA-2125. 79/08/24. 2pp.

WASH REGULATORY PUBLICATIONS - PRE-NUREG SERIES

7908220056 Requests documents developed since 740101 re uncertainty in calculation of event probabilities & consequences & resulting risks,utilizing probabilistic risk assessment methodologies.
HUBBARD,R.B. MHB Technical Associates. 79/06/25. 2pp.

7908220083 Discusses 780403-04 presentation re reactor safety study. Clarifies position re use of statistical methods,findings &/or conclusions w/o consideration of probabilistic assumptions & statistical summarizations.
MOORE,R.H. Office of Management and Program Analysis. 78/05/25. 3pp.

--7908220120 Discusses use of WASH-1400 in regulatory decision making re transportation environ statements,Browns Ferry fire potential,ATWS,liquid pathway generic study & Price-Anderson extension.
PEDERSEN,K. Commission. 78/09/06. 10pp.

--7908220127 Forwards summary of NRC public statements re WASH-1400, reactor safety study.
PEDERSEN,K. Commission. 78/10/11. 8pp.

--7908220142 Forwards final rept on reactor safety study project.Rept reinforces NRC belief of very low likelihood of occurrences which would exceed contingency protection of Price-Anderson Act.
ANDERS,W.A. Commission. 75/10/29. 3pp.

--7908220146 Responds to 751202 ltr re proposed delay of congressional action on Price-Anderson legislation until after review of reactor safety study.Discusses previous review of rept.
ANDERS,W.A. Commission. 75/12/05. 4pp.

--7908220150 Responds to 751129 ltr re reactor safety study.Discusses inputs & reviews which lvd to NRC endorsement of rept. Expresses concern re release of 751129 ltr to press before receipt at NRC.
ANDERS,W.A. Commission. 75/12/24. 2pp.

--7908220154 Responds to 760907 inquiry re influence of debate on renewal of Price-Anderson Act on decision to release reactor safety study.Rept does not discuss need for Price-Anderson coverage & was adequately reviewed prior to release.
ROWDEN,M.A. Commission. 76/09/17. 3pp.

7908220232 Notification of 790920 code assessment review group meeting in Silver Spring,MD to discuss status of projects.
TONG,L.S. Assistant Director for Water Reactor Safety Research. 79/08/02. 3pp.

7908290125 Responds to ltr sent to H Denton re potential dangers of nuclear power plant accidents.Forwards 10CFR100,table of accident classes & summary of specialists group study on reactor safety.TMI accident is being evaluated.
BALLARD,R.L. Environmental Projects Branch 1. 79/08/03. 4pp.

WASTE MGT NUCLEAR WASTE MANAGEMENT

7908160046 "Low-Level Waste Burial Ground Site Closure & Stabilization," Revision 1. Site should be left in condition that requires only passive surveillance & monitoring.
* Low Level Waste Branch (Pre 790501). 79/05/17. 7pp.

7908160055 Comments on Revision 1 to "Low Level Waste Burial Ground Site Closure & Stabilization." Applicant should maintain ultima e responsibility for site.
HANSELL,D. Illinois, State of. 79/07/03. 2pp.

7908230163 SECY-78-256
Discusses current status & alternatives on adequate waste disposal capacity for low level wastes.Requests approval of interim program to ship wastes to western sites & contingency plan to back up commercial sites.
SMITH,C.V. Office of Nuclear Material Safety & Safeguards. 79/05/12. 12pp.

7908300358 Summary of 790614 meeting w/DOE in Germantown,MD to discuss pending travel by NRC to selected facilities re R&D of waste forms & packaging of wastes.
ROHRER,D. High Level Waste Technical Development Branch. 79/06/25. 45pp.

--7908300366 "US Program for Immobilization of High Level Nuclear Wastes."
CRANDALL,J.L. Savannah River Ecology Laboratory. DP-MS-72-2. 79/06/08. 45pp.

XPORTLIC EXPORT AND IMPORT LICENSES

7908090145 Application by Par Sys Corp for license to export 850 neutron absorber tubes to Spain for use in fabrication of racks for storage of spent fuel.
PARSONS,W.B. Par Systems Corp. 79/06/18. 1p.

7907310565 Responds to FOIA request for documents re facility & applications XR-120,XCOM-13, & XSNM-1471.
FELTON,J.M. Division of Rules and Records. 79/07/06. 3pp.

7907310565 Responds to FOIA request for documents re facility & applications XR-120,XCOM-13, & XSNM-1471.
FELTON,J.M. Division of Rules and Records. 79/07/06. 3pp.

7908010282 Requests Executive Branch position re Westinghouse application for license to export nuclear electrical penetration assemblies to Taiwan.
PETERSON,M.R. Assistant Director for Export/Import & International Safeguards. 79/06/25. 1p.

7908010290 Requests Executive Branch position re Westinghouse application for license to export electrical penetration assemblies to Switzerland.
PETERSON,M.R. Assistant Director for Export/Import & International Safeguards. 79/06/25. 1p.

7908010324 Forwards SECY-79-160A for placement in PDR.
MCGREGOR,E.W. Office of the Secretary of the Commission. 79/06/12. 1p.

--7908010330 SECY-79-160A
Forwards Executive Branch response re application by Edlow Intl Co to export source matl to France & United Kingdom.
SHEA,J.R. Office of International Programs. 79/06/21. 1p.

7908010346 Executive Branch position re Marubeni America Corp application for license to export 701 kg U-235,contained in 25,723 kg U in form of U oxide powder enriched to 3.9% to Japan.Ltr of assurance encl.License should be granted.
NOSENZO,L.V. State,Dept.of. 79/06/22. 3pp.

7908010358 Requests Executive Branch position re Transnuclear,Inc application for license to export high enriched U to France.
SHEA,J.R. Office of International Programs. 79/06/13. 1p.

7908010523 Executive Branch position re Mitsubishi Intl Corp application for license to export 40.57 g slightly enriched U,in form of U hexafluoride,to Japan.Ltr of assurance encl. License should be granted.
NOSENZO,L.V. State,Dept.of, Bureau of Oceans & Internatl Environ & Scientific Affairs. 79/06/22. 3p.

7908010530 Executive Branch position re Marubeni America Corp application for license to export 102 kg U-235,contained in 3,799 kg U enriched to max 3.9%,to Japan.Ltr of assurance encl.License should be granted.
NOSENZO,L.V. State,Dept.of, Bureau of Oceans & Internatl Environ & Scientific Affairs. 79/06/22. 3pp.

7908010607 Notifies that Kaiseraugst,toll enrichment customer of Eurodif,has option of 90-day notice,prior to delivery of enriched product,to request that tailing matl be returned. Kaiseraugst does not contemplate requesting return of tails.
EDLOW,J. Edlow International Co. 79/06/19. 1p.

7908010622 Forwards application for export license for minor nuclear export.Ltr of assurance required.W/o encl.
PETERSON,M.R. Assistant Director for Export/Import & International Safeguards. 79/06/27. 1p.

7908010625 Forwards application for export license for minor nuclear export.Ltr of assurance required.W/o encl.
PETERSON,M.R. Assistant Director for Export/Import & International Safeguards. 79/06/27. 1p.

7908020043 Executive Branch position re Transnuclear,Inc application for license to export 3,554 kg U-235,enriched to max of 93.3% U-235,to Austria.Analysis & ltrs of assurance encl.
NOSENZO,L.V. State,Dept.of. 79/07/03. 24pp.

7908020048 Executive Branch position re Westinghouse application for license to export reactor control drive mechanisms, reactor internals & other components/parts to Spain. License should be granted.
NOSENZO, L. V. State, Dept. of. 79/07/02 2pp.

7908020050 Executive Branch position re Reuter Stokes application for license to export two neutron ionization chambers to Greece. License should be granted. Ltr of assurance encl.
NOSENZO, L. V. State, Dept. of. 79/07/05 3pp.

7908020054 Executive Branch position re Marubeni America Corp application for license to export 795 kg U-235, enriched to max of 2.97%, to Japan. License should be granted. Ltr of assurance encl.
NOSENZO, L. V. State, Dept. of. 79/07/02 3pp.

7908020059 Executive Branch position re GA Co application for license to export 1.72 g U-235, enriched to max of 93%, to Philippines. License should be granted. Ltr of assurance encl.
NOSENZO, L. V. State, Dept. of. 79/07/02 3pp.

7908020060 Executive Branch position re GE application for license to export 510 kg U-235, enriched to max of 3.65%, to Japan. License should be granted. Ltr of assurance encl.
NOSENZO, L. V. State, Dept. of. 79/07/02 3pp.

7908020230 Forwards application for export license for minor nuclear export. Ltr of assurance required.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/06/20 1p.

7908020245 Executive Branch position re Byron Jackson Pump Div application for license to export components, specially-designed & prepared for coolant, to India.
NOSENZO, L. V. State, Dept. of. 79/06/15 2pp.

7908020368 Application by Air Products & Chemicals, Inc for license to export 45 g deuterium to United Kingdom.
* Air Products & Chemicals, Inc. 79/07/10 1p.

7908020374 Application by Ventron Corp for license to export 500 g deuterium oxide, 99.8% isotopic purity, to West Germany.
* Ventron Corp. (subs. of Thiokol Corp.). 79/05/29 1p.

7908020375 Application by JT Baker Chemical Co for license to export 14.03 lb U in 25 lb uranyl acetate, to Mexico.
SZABO, R. J. T. Baker Chemical Co. (subs. of Richardson-Merrell, Inc.). 79/07/11 1p.

7908020378 Application by GA Co for license to export specially-designed reactor parts & components to Japan.
MOWRY, W. R. General Atomic Co. (subs. of Gulf Oil Corp.). IEL-1082. 79/07/11 2pp.

7908020380 Application by GE for license to export metal clad experimental & prototypical fuel rods to Taiwan.
WILSON, B. D. General Electric Co. BDW 79187. 79/07/11 1p.

7908020383 Application by Reuter-Stokes, Inc for license to export U-235, deposited as U dioxide on surface of Model RS-P6-2403-114 radiation detector, to Italy. Each detector contains 0.044 g U enriched to 18%.
SKARUPA, J. D. Reuter-Stokes, Inc. V-8228. 79/07/11 2pp.

7908020413 Notifies that, due to urgent requirement of proposed exports, licenses for Hoke, Inc to export valves to Canada were issued w/o customary 15-day waiting period.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/06/27 1p.

7908020413 Notifies that, due to urgent requirement of proposed exports, licenses for Hoke, Inc to export valves to Canada were issued w/o customary 15-day waiting period.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/06/27 1p.

7908020470 Notifies that, due to urgent requirement & small quantity of matl involved, license for TX Nuclear Div to export SNM to Singapore was issued w/o 15-day waiting period.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/06/25 1p.

7908020487 Petition supporting Ctr for Development Policy petition for leave to intervene & request for hearing re nuclear plant being built by Westinghouse at Morong, Philippines.
* Australia. 79/06/20 1p.

7908020560 Application by Westinghouse for license to export two compensated ionization chambers & two fission counters to The Netherlands.
SCHNAUTZ, C. E. Westinghouse Electric Corp. 79/06/13 4pp.

7908030023 Ltr of assurance re Westinghouse applications for licenses to export 3.62 g U, containing 3.336 g U-235, to Sweden.
MONHUSEN, C. Sweden. 79/06/21 2pp.

7908030023 Ltr of assurance re Westinghouse applications for licenses to export 3.62 g U, containing 3.336 g U-235, to Sweden.
MONHUSEN, C. Sweden. 79/06/21 2pp.

7908030099 Submits revised analysis of fuel requirements & schedule for Tarapur reactors. Updates info in 790116 memo.
SNYDER, B. J. Office of Policy Evaluations. 79/06/05 6pp.

7908030228 Ltr of assurance re Reuter-Stokes, Inc application for license to export 40.986 mg U-235, enriched to 93%, to Japan.
MIYABAYASHI, M. Japan. 79/06/22 2pp.

7908030245 Requests Executive Branch position re Westinghouse application for license to export 122,220 kg U, enriched to 3.55% U-235, to Switzerland.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/06/29. 1p.

--7908030253 Application by Westinghouse for license to export 122,220 kg U, enriched to 3.55% U-235, to Switzerland.
KEENAN, R. P. Westinghouse Electric Corp. 79/06/21 1p.

--7908030259 Forwards Westingouse application for license to export 122,220 kg U to Switzerland.
KENNAN, K. P. Westinghouse Electric Corp. ICS-8821. 79/06/21 1p.

7908030347 Requests postponement of expiration date to 811231.
HARMON, D. W. Edlow International Co. 79/06/27 1p.

7908030449 FOIA request for access to SECY-77-601A, "Proposed License to Export Low Enriched U to Brazil, XSNM-909," & any other documents re US involvement in Brazilian nuclear energy programs.
MAREK, K. Center for Development Policy. 79/07/10 2pp.

7908030453 Responds to FOIA request for documents re US involvement in Brazilian nuclear energy program & documents re XSNM-909. Some documents originated by other agencies have been referred for review response NRC review not complete.
FELTON, J. M. Division of Rules and Records. 79/08/02 1p.

7908030549 Supports petition to intervene & request for hearing calling for intensive review & public hearing of all issues re plant const & operation.
SHEPPARD, S., PYE, R., CONNELL, P. Affiliation Unknown. 79/06/29 7pp.

7908030553 Clarifies mathematical inconsistencies in export application. Requests deletion of Soviet Union, Hungary & South Africa from customer list.
HARMON, D. W. Edlow International Co. 79/06/29 2pp.

7908070763 Amend 1 to GE export license, changing address of ultimate consignee.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/06/27. 1p.

7908080021 Waives customary 15-day waiting period for Westinghouse License XCOM-0282 re export of components to France.
PETERSON, M. R. Office of International Programs. 79/07/25 1p.

7908080022 Requests amend to License XB-1018, indicating IAEA as intermediate consignee of Cm-244 for export to Kenya.
HELM, K. Isotope Products Laboratories. 79/07/06 1p.

7908080024 Requests amend to License XCOM-0036, extending expiration date to 800301.
WILSON, B. D. General Electric Co., Nuclear Energy Products Div. BDW-79174. 79/07/02 1p.

7908080463 Executive Branch position re Westinghouse Electric Corp application for license to export 68,609 kg of U-235, in 2,119,531 kg U enriched to max of 3.3% to South Korea. Ltr of assurance encl. License should be granted.
NOSENZO, L. V. State, Dept. of; Bureau of Oceans & Internatl Environ. & Scientific Affairs. 79/06/21. 4pp.

7908080506 Executive Branch position re Transnuclear, Inc application for license to export 411.[illegible] kg U-235, enriched to max 3.55%, & .0355 kg U-235, in 1 kg U, as sampling matl to Switzerland. License should be granted.
NOSENZO, L. V. State, Dept. of. 79/06/20. 4pp.

7908080567 Requests Executive Branch position re JT Baker Chemical Co application for license to export source matl to Mexico.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/20. 1p.

7908080576 Requests Executive Branch position re Mitsui & Co, Inc application for license to export 3,808 kg U to Japan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18. 1p.

7908080580 Requests Executive Branch position re Transnuclear, Inc application for license to export special nuclear matl to The Netherlands.
GOSSICK, L.V. Office of the Executive Director for Operations. 79/07/19. 1p.

7908080586 Requests Executive Branch position re Pechiney Ugine Kuhlmann Development Inc application for license to export U metal to France.
GOSSICK, L.V. Office of the Executive Director for Operations. 79/07/13. 1p.

7908080592 Requests Executive Branch position re Edlow Intl Co application for license to export highly enriched U to France.
GOSSICK, L.V. Office of the Executive Director for Operations. 79/07/12. 1p.

7908080661 Application by Spex Disc, Inc for license to export 8,897 mg U-235 to Japan. End use statement encl.
COYNE, M.J. SPEX Industries, Inc. 79/05/31. 3pp.

7908080668 Application by Conax Corp for license to export feedthrough module & related seal components for containment electric penetration to Spain.
FISHER, E. Conax Corp. 79/06/29. 1p.

7908080748 Application by GE for license to export U-235, enriched U oxide pellets in zirconium rods in various enrichments to Taiwan.
WILSON, B.D. General Electric Co. 79/07/10. 1p.

7908090008 Forwards SECY-79-364 re application of Mitsubishi Intl Corp to export U-235 to Japan.
MCGREGOR, E.W. Office of the Secretary of the Commission. 79/06/12. 1p.

--7908090009 SECY-79-364
Notifies of receipt of application from Mitsubishi Intl Corp to export U-235, contained in 40,023 kg U enriched 3.25% to Japan.
SHEA, J.R. Office of International Programs. 79/06/04. 1p.

--7908090011 Forwards application by Mitsubishi Intl Corp to export U-235, contained in 40,023 kg U enriched 3.25% to Japan.
WATANBEE, N. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). 79/05/23. 2pp.

7908090069 Forwards application for license for minor nuclear export. Ltr of assurance required.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/20. 1p.

7908090082 Requests Executive Branch position re GA Co application for license to export components to Japan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/20. 1p.

7908090101 Requests Executive Branch position re GA Co application for license to export SNM to United Kingdom.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/20. 1p.

7908090118 Requests Exective Branch position re GE application for license to export SNM to Taiwan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/20. 1p.

7908090122 Application by WJ Wooley Co for license to export two personnel airlocks, two emergency airlocks & two 19 ft inside diameter equipment hatch w/hoist to Korea.
KUEHL, C.A. W. J. Woolley Co. 79/06/06. 1p.

7908090151 Notifies that proposal has been submitted to supply 850 neutron absorber tubes to Spain for use in fabrication of spent storage racks.
PARSONS, W.B. Par Systems Corp. 79/04/16. 3pp.

7908090154 Requests Executive Branch position re GE application for license to export SNM to Taiwan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/20. 1p.

7908090239 Forwards application for amend to export license, changing expiration date to 820901.
MOWRY, W.R. General Atomic Co. (subs. of Gulf Oil Corp.). 79/07/10. 2pp.

--7908090250 Application by GA Co for license to export 10 TRIGA fuel elements, enriched to 19.9%, & three fission chambers, enriched to 93.2%, to United Kingdom. Requests extending expiration date to 820901.
MOWRY, W.R. General Atomic Co. (subs. of Gulf Oil Corp.). 79/07/10. 1p.

7908090241 License for NUS Corp to export 16,800 kg U, as depleted U contained in 24,900 kg U hexafluoride, to Taiwan.
SHEA, J.R. Assistant Director for Export/Import & International Safeguards. 79/06/08. 2pp. (

7908090512 Discusses status of amend requested by Edlow Intl Co to license export of 1,000,000 kg U, contained in 1,180,000 kg natural U, to United Kingdom for conversion to U hexafluoride. Recommends issuance of license.
SHEA, J.R. Office of International Programs. 79/06/11. 3pp.

7908090512 Discusses status of amend requested by Edlow Intl Co to license export of 1,000,000 kg U, contained in 1,180,000 kg natural U, to United Kingdom for conversion to U hexafluoride. Recommends issuance of license.
SHEA, J.R. Office of International Programs. 79/06/11. 3pp.

--7908090513 License for British Nuclear Fuels Ltd or JEF Andrews as agent to export 5,300,000 kg U, as U-308, to United Kingdom.
PRICE, E.R. Atomic Energy Commission, Directorate of Licensing (Pre-1975). 71/04/01. 1p.

7908090557 SECY-78-678C
Discusses status of GE export of low enriched fuel to Taiwan. Stresses urgency of resolving issue of exports to Taiwan.
SHEA, J.R. Office of International Programs. 79/05/18. 2pp.

--7908090561 Ack receipt of NRC 790404 ltr noting unfinished NRC review of GE export of low enriched fuel to Taiwan. Expects no more unusual delay. License should be received shortly.
WILSON, B.D. General Electric Co., Nuclear Energy Products Div. BDW-79105. 79/04/18. 1p.

--7908090570 Supplements 790418 ltr. Requests issuance of license to export matl to Taiwan by 790701. Notes shipping schedule difficulties. NRC delay is statutory max.
WILSON, B.D. General Electric Co., Nuclear Energy Products Div. BDW-79124. 79/05/08. 2pp.

--7908090589 Supplements 790508 request for expedited processing of export license. Ships are booked to transport fuel on 790608 & 30. Commissioner action required by 790525.
WILSON, B.D. General Electric Co. 79/05/10. 1p.

7908090652 Amend 1 to Boeing Co export license, extending expiration date from 790901 to 800901.
SHER, J.R. Assistant Director for Export/Import & International Safeguards. 79/07/31. 1p.

7908090657 License for Air Products & Chemicals, Inc to export 45 g deuterium oxide, contained in compounds, to United Kingdom.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/08/02. 2pp.

7908090663 License for Rockwell Intl Corp to export one hydrogen recombiner unit consisting of a recombiner package & control console package, each mounted on separate welded metal skid, to Belgium.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/30. 1p.

7908090666 License for Mitsui & Co (USA), Inc to export 3,511 kg U-235, contained in 157,382 kg U as U hexafluoride or U dioxide, to Tokyo, Japan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/08/02. 2pp.

7908090668 License for Ventron Corp to export 500 g deuterium oxide, contained in compounds, to West Germany.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/08/02. 2pp.

7908100135 Application by Transnuclear, Inc for license to export U hexafluoride, containing 55.98 kg U-235, to France.
MATSON, V. Transnuclear, Inc. 79/07/17 3pp.

7908100139 Application by Transnuclear, Inc for license to export 26.0 kg U hexafluoride enriched to 93.3%, to France.
MATSON, V. Transnuclear, Inc. 79/07/17 3pp.

7908100318 Amend 1 to Mitsui & Co (USA), Inc export license, to include enriched U in form of U dioxide as well as U hexafluoride.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18 1p.

7908100324 License for TX Nuclear Div to export 1.415 mg Pu-238, contained in 1.76 mg Pu as sealed source in TX Nuclear Model 9256 source holder, to Canada.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/12 2pp.

7908100327 License for Carpenter Technology Corp to export 20 2-mm Zircaloy-4 alloy fuel channels to Japan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/12 1p.

7908100333 License for Mitsui & Co (USA), Inc to export 756 kg U-235 as U hexafluoride, enriched to 3.95% max, to Japan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/13 2pp.

7908100339 License for GE to export 161 kg U-235 as U dioxide powder, enriched to 3.1% max, to Japan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/13 2pp.

7908100344 License for Edlow Intl Co to export 50,000 Ci tritium, in bulk gaseous form for non-nuclear end-uses, to United Kingdom.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18 2pp.

7908100348 License for Edlow Intl Co to export 593 kg U-235 as U hexafluoride, enriched to 4.52% max, to Italy.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/20 2pp.

7908100364 Forwards application for license to export SNM to Japan.
MONDER, T. Mitsui & Co., Ltd. 79/07/05 1p.

--7908100367 Application by Mitsui & Co for license to export U hexafluoride, containing 102 kg U-235, to Japan.
MONDEN, T. Mitsui & Co., Ltd. 79/07/05 1p.

7908100376 Executive Branch position re Nissho-Iwai American Corp application for license to export 10 tons heavy water to Japan. License should be granted.
NOSENZO, L.V. State, Dept. of. 79/07/11. 2pp.

7908100377 Executive Branch position re Transnuclear, Inc application for license to export 740.012 kg U-235, contained in 22,089.9 kg U, & 0.034 kg U-235, contained in 1 kg U-235, to Switzerland. License should be granted.
NOSENZO, L.V. State, Dept. of. 79/07/12. 4pp.

7908100378 Submits application to amend license to change Items 18, 19 & 20 re element weight, weight percentage & isotope weight.
OKUDA, H. Marubeni America Corp. (subs. of Marubeni Corp.) 79/07/03 1p.

7908100504 SECY-79-077B
Discusses status of proposed license for GE to export 11,965 kg U, enriched to 3.1%, to Japan. Recommends approval of export.
SHEA, J.R. Office of International Programs. 79/05/31 3pp.

7908100514 Forwards application to export 3.008 kg U, enriched to 93.3% U-235, to The Netherlands. End use statement encl.
MATSON, V. Transnuclear, Inc. 79/07/06 3pp.

--7908100516 Application by Transnuclear, Inc for license to export 3.008 kg U, enriched to 93.3% U-235, to The Netherlands.
MATSON, V. Transnuclear, Inc. 79/07/06 1p.

7908100557 Executive Branch position re Embassy of Korea application for license to export NBS stds, consisting of 26 g natural U metal, to Korea. License should be granted.
NOSENZO, L.V. State, Dept. of. 79/07/19. 3pp.

7908130041 Info rept re 790501 application for License XSNM-1517 to export enriched U hexafluoride & U dioxide to Japan. Forwards license application & T Monden 790501 ltr.
SHEA, J.R. Office of International Programs. 79/05/25. 3pp.

7908130053 SECY-79-182A
Forwards Executive Branch response re application by Westinghouse to export U-235 contained in 727,125 kg U enriched to max 3.5% to Korea. License should be granted.
SHEA, J.R. Office of International Programs. 79/06/20. 1p.

7908130070 SECY-79-394
Forwards application by Transnuclear, Inc to export U-235, contained in 33 kg U enriched to 93.3%, to France.
SHEA, J.R. Office of International Programs. 79/06/15. 1p.

--7908130078 Forwards application by Transnuclear, Inc to export U-235, contained in 33 kg U enriched to 93.3%, to France.
MATSON, V. Transnuclear, Inc. 79/06/05 1pp.

--7908130084 Application by Transnuclear, Inc to export U-235, contained in 33 kg U enriched to 93.3%, to France. Ltr of assurance & reactor checklist encl.
* Transnuclear, Inc. 79/06/05 8pp.

7908130090 SECY-79-328A
Forwards 790611 Executive Branch response re application by GE to export various thermal sleeves to India. License should be granted.
SHEA, J.R. Office of International Programs. 79/06/15 1p.

7908130100 SECY-79-218A
Forwards application by Transnuclear, Inc to amend license to export 12,932 kg U-235, contained in 45,113 kg U enriched to max of 45.4%.
SHEA, J.R. Office of International Programs. 79/07/02. 1p.

--7908130109 Forwards end use statement for application by Transnuclear, Inc to amend license to export 12,932 kg U-235, contained in 45,113 kg U enriched to max 45.4%, to Greece, Austria, Sweden, Switzerland, Denmark, The Netherlands, Venezuela & Brazil.
MATSON, V. Transnuclear, Inc. 79/06/19. 3pp.

7908130129 SECY-79-655B
Notifies of review of application by Mitsui & Co to export 3,511 kg U-235, contained in 157,382 kg U enriched to 2.55%, to Japan. Recommends license be issued.
SHEA, J.R. Office of International Programs. 79/06/18. 3pp.

--7908130136 Application by Mitsui & Co to export 3,511 kg U-235, contained in 157,382 kg U enriched to 2.55% to Japan.
MONDEN, T. Mitsui & Co., Ltd. 78/11/28. 2pp.

--7908130141 Executive Branch position re Mitsui & Co application for license to export 3,511 kg U-235, contained in 157,382 kg U enriched to 2.55%, to Japan. Ltr of assurance encl. License should be granted.
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/05/23. 3pp.

--7908130147 Mitsui & Co license to export 3,511 kg U-235, contained in 157,382 kg U enriched 2to 2.55%, to Janpan.
OPLINGER, G.G. Assistant Director for Export/Import & International Safeguards. 79/05/23. 2pp.

7908130151 SECY-79-072B
Recommends Commission approve issuance of proposed license for GE to export 161 kg U-235, contained in 5,875 kg U enriched to max of 3.1%, to Japan.
SHEA, J.R. Office of International Programs. 79/06/19. 3pp.

--7908130153 Application by GE to export 161 kg U-235, contained in 5,875 kg U enriched to max 3.1%, to Japan.
* General Electric Co. 78/12/22. 1p.

--7908130157 Executive Branch position re GE application for license to export 161 kg U-235, contained in 5,875 kg U enriched 3.1%, to Japan. Licensee south should be granted. Ltr of assurance encl.
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/05/29. 3pp.

--7908130163 GE license to export 161 kg U-235, contained in 5,875 kg U enriched to max 3.1% , o Japan.
* Assistant Director for Export/Import & International Safeguards. 79/05/29. 2pp.

7908130375 Notifies that Transnuclear, Inc is shipper of record for export license XSNM-1477.
DOMINQUEZ, G. Spain. 79/05/24. 1p.

7908130618 SECY-79-282M
Recommends NRC approve application by Mitsubishi Intl Corp for license to export 11,983 kg U-235, enriched to 2.85%, to Japan.
SHEA, J.R. Office of International Programs. 79/06/01. 4pp.

--7908130629 Application by Mitsubishi Intl Corp for license to export contained 11,983 kg U-235, enriched to 2.85%, to Japan. End use statement encl.
TSUJI, K. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). 78/10/31. 2pp.

--7908130646 Forwards application by Mitsubishi Intl Corp for license to export 11,983 kg U, enriched to 2.85%, to Japan.
WATANBE, N. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5479-02. 78/10/31. 3pp.

--7908130653 Executive Branch position re Mitsubishi Intl Corp application for license to export 11,983 kg U-235, enriched to 2.85%, to Japan. License should be granted.
NOBENZO, L.V. State Dept of. 79/04/16. 2pp.

--7908130659 License for Mitsubishi Intl Corp to export 11,983 kg, enriched to 2.85%, to Japan.
OPLINGER, G.G. Assistant Director for Export/Import & International Safeguards. HSA-5479-02. 79/06/01. 2pp.

7908130655 Notifies of receipt of application by GE for license to export six traversing incore probe detector assemblies to India.
SHEA, J.R. Office of International Programs. 79/05/16. 1p.

7908140272 Submits application to amend license to export components & associated equipment of two-unit boiling water reactor power station to Spain.
WILSON, B.D. General Electric Co., Nuclear Energy Products Div. BDW-79162. 79/06/14. 2pp.

7908140364 SECY-78-671B
Recommends that NRC approve application by Mitsui & Co to export 756 kg U-235, contained in 26,902 kg U enriched to 3.95% w/o max, to Japan.
SHEA, J.R. Office of International Programs. 79/06/15. 3pp.

--7908140370 Application by Mitsui & Co to export 75/ kg U-235, contained in 26,902 kg U enriched to 3.95% w/o max, to Japa.
MONDEN, T. Mitsui & Co., Ltd. 78/12/08. 2pp.

--7908140389 License for Mitsui & Co to export 756 kg, enriched to 3.95%, to Japan.
* Office of International Programs. 79/06/15. 1p.

7908140620 Info rept re 790507 application for License XSNM-1510 to export U hexafluoride to Japan. Forwards Marubeni America Corp application and 790507 ltr.
SHEA, J.R. Office of International Programs. 79/05/17. 1p.

7908140664 Forwards application for license to export Zircaloy-4 fuel channels to Japan.
BRISTOL, D.C. Carpenter Technology Corp. 79/06/19. 1p.

--7908140669 Application by Carpenter Technology Corp for li se to export 20 Zircaloy-4 fuel channels to Japan.
* Carpenter Technology Corp. 79/06/19. 2pp.

7908150109 Forwards, for filing & publication FR notice re applications for licenses to export nuclear facilities or matls.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18. 1p.

7908150109 Forwards, for filing & publication FR notice re applications for licenses to export nuclear facilities or matls.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18. 1p.

7908150109 Forwards, for filing & publication FR notice re applications for licenses to export nuclear facilities or matls.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18. 1p.

7908150109 Forwards for filing & publication FR notice re applications for licenses to export nuclear facilities or matls.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18. 1p.

--7908150112 FR notice re applications for licenses to export nuclear facilities or matls.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18. 2pp.

--7908150112 FR notice re applications for licenses to export nuclear facilities or matls.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18. 2pp.

--7908150112 FR notice re applications for licenses to export nuclear facilities or matls.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/18. 2pp.

7908150141 Confirms 790712 telcon. Intl Shipping & Trading Agency will serve as exporter for exports made against License XR-117.
HERSCH, M.M. Westinghouse Electric Corp. 79/07/13. 1p.

7908150143 Submits info requested to permit export license issuance. Lists models, elements & isotopes.
O'HARA, W.J. ARMCO International, Inc. 79/07/19. 1p.

7908150148 Confirms telcon request to cancel application for export license.
JOHNSON, N.R. Eberline Instrument Corp. EI-917514. 79/07/17. 1p.

7908150152 Requests license to import fuel rods containing 8403 g U, 642 g U-235 & 54.1 g plutonium from Norway.
WILSON, B.D. General Electric Co. BDW-79190. 79/07/12. 2pp.

7908150189 Forwards application to export 900 kg U, containing 73.62 kg U-235, to France. End use statement encl.
MATSON, V. Transnuclear, Inc. 79/07/17. 1p.

--7908150197 Application by Transnuclear Inc for license to export 900 kg U, containing 73.62 kg U-235, to France.
MATSON, V. Transnuclear, Inc. 79/07/17. 1p.

7908150301 Request extension of expiration dates for import licenses to 810131.
MATTSON, V. Transnuclear, Inc. 79/07/16. 1p.

7908150301 Request extension of expiration dates for import licenses to 810131.
MATTSON, V. Transnuclear, Inc. 79/07/16. 1p.

7908150424 License for Edlow Intl Co to amend license to import. License is extended until 810731 & principal is changed to Studsvik Energiteknik AB.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/07/09. 1p.

7908150425 Application by Edlow Intl Corp for license to export U contained in 24.31 kg U hexafluoride enriched to 93.5%, to France.
HARMON, D.W. Edlow International Co. 79/07/05. 1pp.

7908150437 Application by Rockwell Intl Corp for license to export hydrogen recombiner unit to Belgium.
WHEELER, L.W. Rockwell International Corp. 79/07/02. 1p.

7908150444 Application by Rockwell Intl Corp for license to export hydrogen recombiner unit to Belgium.
WHEELER, L.W. Rockwell International Corp. 79/07/02. 1p.

7908150456 License for Reuter-Stokes Inc to export two neutron ionization chambers to Greece.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. G-5835. 79/07/10. 1p.

7908150461 Amend 1 to Isotope Products Lab export license adding IAEA as intermediate consignee.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 6702. 79/07/09. 1p.

7908150476 Application by Hoke Inc for license to export two 1.5-inch bellow sealed control valves to Argentina.
* Hoke, Inc. 79/07/19. 1p.

7908150478 Application by Reactor Experiments Inc for license to export Np-237 electroplated on nickel foil to Japan.
HEIMAN, D. Reactor Experiments, Inc. 79/06/29. 1p.

7908150484 Application by Westinghouse for license to export one BF3 detector to France.
POCHAL, W.F. Westinghouse Electric Corp. 79/07/17. 1p.

7908150490 Application by Reactor Experiments Inc for license to export 4.375 mg Np-237, enriched to 97%, to Japan.
HEIMAN, D. Reactor Experiments, Inc. 79/07/09. 1p.

7908150534 Executive Branch position re Transnuclear, Inc application for license to export 6.827 kg U-235 enriched to 20.3%, to West Germany, Austria, The Netherlands, Denmark & Greece. License should be granted.
NOSENZO, L. V. State Dept of. 79/07/19. 3pp.

7908150558 Application by Mitsui & Co for license to export Zircaloy-2 tube shells to Japan.
MONDEN, T. Mitsui & Co., Ltd. 79/06/18. 1p.

7908150565 Application by Reuter-Stokes Inc for license to export U-235, deposited on surfaces of radiation detector, to West Germany.
SKARUPA, J. D. Reuter-Stokes, Inc. 79/07/16. 3pp.

7908150570 Application by Westinghouse for license to export compensated ionization chamber to France.
POCHAL, W. F. Westinghouse Electric Corp. 79/07/16. 1p.

7908150574 Application by Transnuclear, Inc for license to export 100,000 kg U in form of U oxide enriched to .711% to France.
* Transnuclear, Inc. 79/07/18. 2pp.

--7908150579 Forwards application for license to export 100,000 kg U in form of U oxide enriched to .711% to France.
MASON, V. Transnuclear, Inc. 79/07/19. 1p.

7908150589 Amend 1 to GE export license, extending expiration date to 800301.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. BDW-117-78. 79/07/11. 1p.

7908160002 Submits ltr of assurance re Eberline Instrument Corp 79061P application to export Pu-239 to United Kingdom.
GOPPEL, M. European Communities, Commission of. 79/07/30. 1p.

7908160003 Submits ltr of assurance re Westinghouse 790613 application to export U-235 contained in 3.62 g U to The Netherlands.
GOPPEL, M. European Communities, Commission of. 79/07/30. 1p.

7908160004 Forwards application by Micro Display Sys, Inc for license to export watches containing gaseous tritium to all countries except restricted nations. Requests Executive Branch position. W/o encl.
PETERSON, M. R. Office of International Programs. 79/07/31. 1p.

7908160051 Requests license to export 225,000 low carbon balls for flux mapping sys to France.
HERSCH, M. M. Westinghouse Electric Corp. ICS-8979. 79/07/24. 1p.

7908160056 Requests amend to export license authorizing increase in amount of U-235 for export to India.
FLEMING, T. B. Reuter-Stokes, Inc. 79/07/17. 1p.

7908160063 Executive Branch position re Transnuclear, Inc application for license to export 367 kg U-235, contained in 10.794 kg U enriched to max of 3.4%, to United Kingdom. License should be granted. Ltr of assurance encl.
NOSENZO, L. V. State Dept of, Bureau of Oceans & Internatl Environ. & Scientific Affairs. 79/08/01. 3pp.

7908160067 Executive Branch position re Nissho-Iwai American Corp application for license to export 229.14 kg U-235, contained in 15.075 kg U enriched to max of 1.52%, to Japan. License should be granted. Ltr of assurance encl.
NOSENZO, L. V. State Dept of, Bureau of Oceans & Internatl Environ. & Scientific Affairs. 79/07/30. 3pp.

7908160078 Requests amend to correct info in United Kingdom Treasury & Supply Delegation export license. Quantity to be shipped is 1,200.0 kg.
THOMPSON, S. United Kingdom. KE81527/AT 3120. 79/07/31. 1p.

7908160106 Requests amend to Westinghouse export Licnese XCOM-142, adding Sena reactor to list of ultimate consignees.
KEENAN, R. P. Westinghouse Electric Corp. ICS-8981. 79/07/24. 1p.

7908160308 License for Sigma Chemical Co to export 5 kg deuterium oxide, contained in compounds, to Australia.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/07/24. 2pp.

7908160312 License for Hoke Inc to export bellows sealed instrument valves to Canada.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. HNL-01. 79/07/24. 1pp.

7908160317 License for Embassy of Korea to export 26 g U as natural U metal, 2 g U as depleted U & 0.22 g U-235 contained in 5 g U, to Republic of Korea.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/07/24. 2pp.

7908160320 Application by Mitsuiline Travel Svc of America for license to export 1 g U-235, contained in 1.05 g enriched to 95%, to Japan.
YAMAZAKI, M. Mitsuiline Travel Service of America, Inc. 79/07/09. 2pp.

7908160497 Requests Executive Branch position re Rockwell Intl Corp application for license to export one hydrogen recombiner unit to Belgium.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. NRC. 79/07/11. 1p.

7908160504 Requests Exective Branch position re Rockwell Intl Corp application for license to export one hydrogen recombiner unit to Belgium.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/07/11. 1p.

7908160507 Requests Executive Branch position re Conax Corp application for license to export electrical penetration assembly replacement components to Spain.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/07/09. 1p.

7908170033 Forwards Amend 1 to United Kingdom Treasury & Supply Delegation license, increasing amount of matl authorized for shipment. Requests Executive Branch position. W/o encl.
PETERSON, M. R. Office of International Programs. 79/08/07. 1p.

7908170037 Forwards Westinghouse 790713 license application to export 12 radiation surveillance capsules containing Np-237 to Taiwan. Requests Executive Branch position. W/o encl.
PETERSON, M. R. Office of International Programs. 79/08/07. 1p.

7908170042 Forwards Westinghouse amend to application adding Societe d'Energie Nucleaire Franco-Belge des Ardennes facility as additional ultimate consignee. Requests Executive Branch position. W/o encl.
PETERSON, M. R. Office of International Programs. 79/08/07. 1p.

7908170064 Requests Executive Branch position re Dept of Army application for license to export projectiles containing depleted U to France.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/07/09. 1p.

7908170124 Forwards application for license to export timepieces containing gaseous tritium light sources to Condition 2 countries.
RISTAGNO, C. V. Micro Display Systems. 79/07/16. 1p.

--7908170130 Application by Micro Display Sys, Inc for license to export digital electronic watches containing gaseous tritium luminous sources, max 200 mCi per watch, to Condition 2 countries.
RISTAGNO, C. V. Micro Display Systems. 79/06/25. 1p.

7908170134 Forwards application for export license for minor nuclear export. Ltr of assurance required.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/07/27. 1p.

7908170141 Forwards application for export license for minor nuclear export. Ltr of assurance required.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/07/27. 1p.

7908170145 Forwards application for export license for minor nuclear export. Ltr of assurance required.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/07/27. 1p.

7908170194 Notifies that licenses required on rush basis to meet contract shipping date deadline.
LINDNER, T. P. Hoke, Inc. 1078NB. 79/07/30. 1p.

7908170194 Notifies that licenses required on rush basis to meet contract shipping date deadline.
LINDNER, T. P. Hoke, Inc. 1078NB. 79/07/30. 1p.

7908170220 Suggests that validity period of power reactor fuel export license be made coterminus w/applicable enrichment svc contract, if applicant requests. Requests that US officials examine provisions of Nuclear Nonproliferation Act.
HERSCH, M. M. Westinghouse Electric Corp. 79/07/17. 2pp.

7908170220 Suggests that validity period of power reactor fuel export license be made coterminus w/applicable enrichment svc contract, if applicant requests. Requests that US officials examine provisions of Nuclear Nonproliferation Act.
HERSCH, S M. Westinghouse Electric Corp. 79/07/17. 2pp.

7908170249 Requests Executive Branch position re Reuter-Stokes, Inc application for amend to License XSNM-1243 to increase quantity of exportable U-235 to 30 mg.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/07/27. 1p.

7908170254 Requests Executive Branch position re Transnuclear, Inc application for license to export SNM to France.
GOSSICK, L V. Office of the Executive Director for Operations. 79/07/27. 1p.

7908170263 Requests Executive Branch position re Transnuclear, Inc application for license to export 100,000 kg of normal U to West Germany.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/07/27. 1p.

7908170269 Requests Executive Branch position re Mitsui & Co (USA) application for license to export Zircaloy-2 tube shells to Japan.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/07/27. 1p.

7908170281 Application by Matheson Gas Products for license to export 180 g deuterium to Australia.
WOOD, L O. Matheson Gas Products. 79/07/24. 4pp.

7908170287 License for Transnuclear, Inc to export 125,500 kg depleted U ingots & 500 kg of depleted U hexafluoride to France.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/07/27. 2pp.

7908170443 Requests Executive Branch position re Transnuclear, Inc application for license to export SNM to France.
GOSSICK, L V. Office of the Executive Director for Operations. 79/07/27. 1p.

7908200255 Responds to FOIA request for documents re NRC decision to recommend to Dept of Commerce that export license be granted to Westinghouse. Forwards J Shea 790615 ltr to Dept of Commerce & 790611 SECY-79-382.
FELTON, J M. Division of Rules and Records. 79/08/14. 1p.

--7908200317 Application by Westinghouse for license to export turbine generator sets, steam turbines, heat exchangers & heat exchanger type condensors to Phillipines.
DUFFY, E L. Westinghouse Electric Corp. 79/02/21. 5pp.

--7908200317 Application by Westinghouse for license to export turbine generator sets, steam turbines, heat exchangers & heat exchanger-type condensors to Philippines.
DUFFY, E L. Westinghouse Electric Corp. ZEHK-10355. 79/02/21. 5pp.

--7908200317 Application by Westinghouse for license to export turbine generator sets, steam turbines, heat exchangers & heat exchanger-type condensors to Philippines.
DUFFY, E L. Westinghouse Electric Corp. ZEHK-10355. 79/02/21. 5pp.

7908210043 Determines that Transnuclear, Inc application for license to export 11,585 kg U, enriched to 3.55% U-235, to Switzerland is acceptable.
MOORE, R N. Office of International Programs. 79/07/03. 1p.

7908210063 Requests Executive Branch position re Transnuclear, Inc application for license to export SNM to France.
GOSSICK, L V. Office of the Executive Director for Operations. 79/07/27. 1p.

7908210080 Requests authorization to complete order for shipments of nuclear density devices to China.
HAVERKOS, J R. Soiltest, Inc. 79/07/17. 1p.

7908210097 Amend 2 to Transnuclear, Inc import license, increasing enrichment from 0.8% U-235 to 0.92% U-235. All other conditions remain unchanged.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/09. 1p.

7908210182 Requests withdrawal of application to export tritium gas to Israel. Important changes are necessary.
WERNER, L T. Originala, Inc. 79/06/14. 1p.

7908210188 Discusses application for Originala, Inc to export tritium gas to Israel.
WERNER, L T. Originala, Inc. 79/06/14. 1p.

7908210558 Requests extension of import license expiration date to 810101.
MATSON, V. Transnuclear, Inc. 79/07/23. 1p.

7908220253 Application by Westinghouse for license to export three Unit WL23770 BF3 proportional counters to West Germany.
SCHNAUTZ, C E. Westinghouse Electric Corp. ZE-100NA. 79/07/26. 1pp.

7908220255 Amend 1 to Transnuclear, Inc import license extending expiration date to 810101.
SHEA, J R. Assistant Director for Export/Import & International Safeguards. 79/07/31. 1p.

7908220262 Amend 1 to Transnuclear, Inc import license changing expiration date to 810131.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/03. 1p.

7908220264 Amend 1 to Transnuclear, Inc import license changing expiration date to 810131.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/03. 1p.

7908220417 Forwards application for export license for minor nuclear export. Ltr of assurance required.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/10. 1p.

--7908220424 Application by Westinghouse for license to export 12 nuclear fuel pellet samples to Swiss Federal Inst for Reactor Research in Switzerland. Inst Federal 790621 statement encl.
KEENAN, R P. Westinghouse Electric Corp. 79/07/30. 2pp.

7908220427 License for QE to export 510 kgs U-235, contained in 18,452 kg U enriched 3.65 w/o max, to Japan.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/13. 21pp.

7908220510 License for QE to export 796 kg U-235, contained in 29,526 kg U oxide powder enriched 3.65 w/o max, to Japan.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/13. 2pp.

7908220518 License for Marubeni America Corp to export 102 kg U-235, contained in 3,799 kg U enriched to 3.90 w/o max, to Japan.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/14. 2pp.

7908220664 Forwards application for license to export surveillance test capsules to Taiwan. To ensure prompt issuance, requests that no matl change circumstance be applied to application.
HESS, R J. Westinghouse Electric Corp. 79/07/31. 1p.

--7908220666 Application by Westinghouse for license to export 12 radiation surveillance capsules to Taiwan.
HESS, R J. Westinghouse Electric Corp. ICS-9017. 79/07/31. 1p.

7908230065 License for Matheson Gas Products to export 1,000 liters of deuterium, contained in two packages of 5,000 liters each, to Australia.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/14. 2pp.

7908230069 License for Rocky Mountain Nuclear to export one remote operated pipe connector to United Kingdom.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/14. 2pp.

7908230071 License for Isotope Products Labs to export 1 microgram of Pu-238, 1 microgram Pu-239 & 1 microgram Pu-236, contained in plutonium nitrate.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/10. 2pp.

7908230075 License for Eberline Instrument Corp to export 0.1 micrograms of Pu-239, contained in stainless steel disc, to United Kingdom.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/10. 2pp.

7908230083 License for Westinghouse to export 3.36 g U-235, contained in 3.62 g enriched U, to The Netherlands.
PETERSON, M R. Assistant Director for Export/Import & International Safeguards. 79/08/10. 2pp.

7908230087 License for Reuter-Stokes to export 3.565 g U-235, contained in 3.833 g enriched U, to Japan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/08/10. 2pp.

7908230105 Forwards renewal application for License XB-0963.
MORGAN, W.F. Boeing Co. 79/07/25. 1p.

--7908230109 Application by Boeing Co to renew license to export 200 Ci tritium gas-activated radioluminous aircraft exit signs to Romania.
MORGAN, W.F. Boeing Co. 79/07/25. 1p.

7908230343 Executive Branch position re Rockwell Intl Corp application for license to export two hydrogen recombiner unit for use w/nuclear reactors to Belgium. License should be granted.
NOSENZO, L.V. State, Dept. of. 79/07/27. 2pp.

7908230408 Executive Branch position re Rockwell Intl Corp application for license to export two hydrogen recombiner units, for use w/nuclear reactors, to Belgium. License should be granted.
NOSENZO, L.V. State, Dept. of. 79/07/27. 2pp.

7908240031 Submits application for license to import 27 kg of U-235 as spent nuclear research reactor fuel for delivery to DOE Savannah River Project. Forwards data in support of request for import license.
STUKENBROEKER, G. NL Industries, Inc. EY-76-C-09-1033. 79/06/22. 14pp.

--7908240035 Certificate of Compliance 9103 for NL Industries.
MACDONALD, C.E. Transportation Branch. 78/05/03. 4pp.

7908240037 Forwards IE Insp Rept 70-2543/79-01 on 790417. No noncompliance noted.
MARTIN, W.G. Region 1, Philadelphia, Safeguards Branch. 79/06/15. 1p.

7908240040 IE Insp Rept 70-2543/79-01 on 790417. No noncompliance noted. Major areas inspected: export shipment of SNM.
GODY, A., JOYNER, J.H. Region 1, Philadelphia, Safeguards Branch. 79/06/13. 1p.

7908240053 Ltr of assurance re application of Isotope Products Lab to export Pu-238, Pu-239 & Pu-236 to West Germany.
GOPPEL, M. European Communities, Commission of. 79/07/30. 1p.

7908240085 Responds to FOIA request for documents re Westinghouse export applications & Philippine power reactor project. Forwards list of documents & 60 documents pertaining to request. Document 61 on list withheld (ref FOIA Exemption 1).
FELTON, J.M. Division of Rules and Records. 79/08/23. 180pp.

7908240085 Responds to FOIA request for documents re Westinghouse export applications & Philippine power reactor project. Forwards list of documents & 60 documents pertaining to request. Document 61 on list withheld (ref FOIA Exemption 1).
FELTON, J.M. Division of Rules and Records. 79/08/23. 180pp.

7908240212 License for Marubeni America Corp to export 795 kg U-235, contained in 30.382 kg U hexafluoride enriched to 2.97% w/o max, to Japan.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/08/13. 2pp.

7908240219 FOIA request for all documents re Westinghouse export license applications XR-120, XCOM-0013 & XSNM-1471, Philippine power reactor project & procedures & policies related to export licensing.
BUCKLEY, C.H. Beveridge, Fairbanks & Diamond. 828-0270. 79/08/01. 2pp.

7908240219 FOIA request for all documents re Westinghouse export license applications XR-120, XCOM-0013 & XSNM-1471, Philippine power reactor project & procedures & policies related to export licensing.
BUCKLEY, C.H. Beveridge, Fairbanks, & Diamond. 828-0270. 79/08/01. 2pp.

7908240299 Forwards ltr of assurance re JAERI application to export U-235, contained in 3,832.56 mg U, to Japan.
MIYABAYSHI, M. Japan. 79/07/24. 1p.

7908240520 SECY-79-222B
Commissioner action recomminding issuance of license to Marbeni America Corp to export U-235, contained in 25,723 kg U enriched to 3.9%, to Japan.
SHEA, J.R. Office of International Programs. 79/07/24. 4pp.

7908240520 SECY-79-222B
Commissioner action recomminding issuance of license to Marbeni America Corp to export U-235, contained in 25,723 kg U enriched to 3.9%, to Japan.
SHEA, J.R. Office of International Programs. 79/07/24. 4pp.

--7908240524 Application by Marubeni America Corp to export U-235, contained in 25,723 kg U enriched to 3.90%, to Japan.
I'IROSHIMA, K. Marubeni America Corp. (subs. of Marubeni Corp.). 240076. 79/03/20. 1p.

--7908240527 Forwards application to export U-235, contained in 25,723 kg U enriched to 3.90%, to Japan.
KUBO, H. Marubeni America Corp. (subs. of Marubeni Corp.). MAL-HK-5800. 79/03/20. 1p.

--7908240530 Confirms that SNM covered in Licenses XSNM-1473 & XSNM-1484 will be used in same reactor in Jul 1980 as second reload fuels.
KUBO, H. Marubeni America Corp. (subs. of Marubeni Corp.). MAI-HK-5862. 79/05/11. 1p.

--7908240530 Confirms that SNM covered in Licenses XSNM-1473 & XSNM-1484 will be used in same reactor in Jul 1980 as second reload fuels.
KUBO, H. Marubeni America Corp. (subs. of Marubeni Corp.). MAI-HK-5862. 79/05/11. 1p.

--7908240538 Recommends issuance of license to Marubeni America Corp to export U-235, contained in 25,723 kg U enriched to 3.90%, to Japan. Ltr of assurance encl.
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/06/22. 3pp.

--7908240541 License for Marubeni America Corp to export U-235, contained in 25,723 kg U enriched to 3.90%, to Japan.
PETERSON, M.R. Office of International Programs. 2H0076. 79/07/24. 2pp.

7908240545 SECY-79-249C
Recommends issuance of license to GE to export U-235, contained in 29,526 kg U enriched to 3.65%, to Japan.
SHEA, J.R. Office of International Programs. 79/07/24. 3pp.

--7908240548 Application by GE for license to export U-235, contained in 29,526 kg U enriched to 3.65%, to Japan.
* General Electric Co., Nuclear Energy Products Div. 79093. 79/04/03. 4pp.

--7908240551 Revises 790403 application. First shipment to Japan is rescheduled for 790831.
WILSON, B.D. General Electric Co., Nuclear Energy Products Div. BDW-79098. 79/04/13. 1p.

--7908240553 Recommends issuance of license to GE to export U-235, contained in 29,526 kg U enriched to 3.65%, to Japan. Ltr of assurance encl.
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/06/22. 3pp.

--7908240556 License for GE to export U-235, contained in 29,526 kg U enriched to 3.65%, to Japan.
PETERSON, M.R. Office of International Programs. 79093. 79/07/24. 2pp.

7908240624 Executive Branch position re Edlow Intl Co application for license to export 50,000 Ci of tritium to United Kingdom.
NOSENZO, L.V. State, Dept. of. 79/07/13. 2pp.

7908300337 Forwards applications to export 73,556.4 kg U, enriched to 3.15% U-235, to South Africa. End use statement encl.
MATSON, V. Transnuclear, Inc. 79/07/31. 6pp.

--7908300342 Application by Transnuclear, Inc for license to export 73,556.4 kg U, enriched to 3.15% U-235, to South Africa.
MATSON, V. Transnuclear, Inc. 79/07/31. 1p.

7908300361 License for TX Nuclear Div to export 1.415 mg Pu-238, contained in 1.76 mg Pu as sealed source, to United Kingdom.
* Assistant Director for Export/Import & International Safeguards. 79/08/09. 2pp.

7908300365 License for Reactor Experiments Inc to export .2014 mg Np-237 to Japan.
* Assistant Director for Export/Import & International Safeguards. 79/08/08. 2pp.

7908300371 License for Westinghouse to export compensated ionization chamber type WL23944 to France.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/08/07. 1p.

NONDOCKETED ITEMS

7908300375 License for Westinghouse to export BF3 Detector Type WL23744 to France.
PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/08/07. 1p.

7908300380 Application by Sandvik Special Metals Corp for license to export Zr-4 guide thimble tubes to Japan.
* Sandvik Special Metals Corp. 79/07/31. 1p.

7908300384 Application by Sandvik Special Metals Corp for license to export Zr-4 guide thimble tubes to Japan.
* Sandvik Special Metals Corp. 79/07/31. 1p.

7908300420 Application by Sandvik Special Metals Corp for license to export Zr-4 guide thimble tubes to Japan.
* Sandvik Special Metals Corp. 79/07/31. 1pp.

7908300436 Forwards application for license to export tritium gas to Dominican Republic.
HARPER, R.G. Self Powered Lighting, Ltd. 79/08/06. 6pp.

--7908300443 Application by Self-Powered Lighting Ltd for license to export 800,000 Ci tritium gas per yr to Dominican Republic.
HEGARTY, W. Self Powered Lighting, Ltd. 79/08/06. 1p.

7908300462 Forwards amended end use statement from Transnuclear, Inc for export license. W/o encl.
GOSSICK, L.V. Office of the Executive Director for Operations. 79/06/28. 1p.

7908300592 Discusses Apr 1979 application by Transnuclear, Inc to export 10,794 kg U, enriched to 3.4% U-235, to Belgium. Executive Branch approved license. License may be issued.
MOORE, R.N. Office of International Programs. 79/08/08. 1p.

7908300593 Notifies of issuance of license of TX Nuclear Division to export SNM to United Kingdom. Due to urgent requirement & small quantity involved, license was issued w/o 15 day waiting period.
PETERSON, M.R. Office of International Programs. 79/08/15. 1p.

7908300594 Responds to 790726 memo re Zircaloy-4 tube shells. Zirconium require export license per App A, Section(a)(6) of 10CFR110.
CRUTCHFIELD, D.M. Systematic Evaluation Program Branch. 79/08/03. 1p.

7908300596 Submits application to amend license to extend expiration date to 801231.
KENNAN, K.P. Westinghouse Electric Corp. 79/06/19. 1p.

7908310249 Application by Saginaw Steering Gear Div, General Motors Corp for license to export spare parts made from AMS 355 stainless steel to Canada.
SOKOLOWSKI, A. General Motors Corp. 79/08/07. 1p.

--7908310254 Forwards application for license to export matl to Canada.
SOKOLOWSKI, A. General Motors Corp. 79/08/13. 1p.

7908310422 Forwards application for license to export spare parts used in refueling sys to Canada.
SOKOLOWSKI, A. General Motors Corp. 79/08/13. 1p.

--7908310291 Application by Saginaw Steering Gear Div, General Motors, for license to export spare parts made from AMS-335 stainless SAE 4150 & SAE 5620 steel, for use in refueling sys, to Canada.
SOKOLOWSKI, A. General Motors Corp. 79/08/07. 1p.

7908310456 Requests amend of import License ISNM-1757 to increase percentage of U-235 from 0.8% to 0.92%.
MATSON, V. Transnuclear, Inc. 79/08/01. 1p.

7908310495 Application by Westinghouse for license to export two fission chambers to Japan.
POCHAL, W.F. Westinghouse Electric Corp. ZE-604. 79/07/27. 5pp.

7908310505 Application by Mitsui & Co, Inc. for license to export Zircaloy-2 tube shell, co-extruded w/zirconium crystal bar liner, to Japan.
MONDEN, T. Mitsui & Co., Ltd. 79/08/02. 2pp.

7908310520 Forwards application for license to export slightly enriched U-hexafluoride to Japan. End use statement encl.
WATANABE, N. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5479-06. 79/07/31. 4pp.

--7908310525 Application by Mitsubishi Intl Corp for license to export 396 kg U-235, enriched to max of 2.25% in 17,578 kg U, to Japan.
FUKAZAWA, Y. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). 79/07/31. 1p.

7908310557 Application by Eberline Instrument Co for license to export DNS-1 alpha calibr std, w/81.6 microgram Pu-239, to Chile.
JOHNSON, N.R. Eberline Instrument Corp. 79/07/27. 1p.

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index titled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ABBOTT, D. G.	7908140084	NUREG
ABRAMS, M. S.	7908270378*	50-344 P
ABRAMS, M. S.	7908270398*	50-344 P
ABRAMS, M. S.	7908270388*	50-344 P
ABUAF, N.	7908010579	RES
ACOSTA, A. P.	7908160005	40-8584
ADAMS, J. T.	7908220374	50-361 Q
ADAMS, W. E.	7908140536	50-255 R
ADAMS, J.	7908210460*	50-346 S
ADAMS, J. D.	7908210439*	50-346 S
AGEE, J. R.	7908100399*	QA999
AGEE, J. R.	7908220670*	QA999
AGEE, J. R.	7908090237*	QA999
AGEE, J. R.	7908200045*	QA999
AGEE, J. R.	7908130170*	QA999
AGELO, J.	7908270290	GEN TEC IS
AGNEW, H. M.	7908300771*	COMMISSION
AGRAWAL, A. K.	7908020600	RES
AGRAWAL, A. K.	7908140005	TOPREP
AHEARNE, J. F.	7908170503	SECY
AHEARNE, J. F.	7908090583	10CFR
AKSTULEWICZ, F.	7908140176	NUREG
ALBERT, W. G.	7908230061*	50-460 Q
ALBERT, W. G.	7908150199*	50-522 Q
ALDEN, W. M.	7908160451*	50-277 R
ALDEN, W. M.	7908290583	50-171 P
ALDEN, W. M.	7908300691	50-171 R
ALDWIN, W. A.	7908080058	50-70 Q
ALENCOURT, H.	7908140451*	50-259 R
ALENCOURT, H.	7908140445	50-259 R
ALEXANDER, H.	7908270461	71-246
ALEXANDER, D. R.	7908290616*	50-267 R
ALEXANDER, R.	7908070567*	RES
ALFORD, P. R.	7908100321*	50-488 Q
ALGER, D. M.	7908310512*	50-186 P
ALGER, D.	7908140377	50-186 P
ALLEN, R. D.	7908220639*	QA999
ALLEN, W. T.	7908220301*	QA999
ALLEN, W. T.	7908220282*	QA999
ALLEN, P. B.	7908150519*	50-321 R
ALLEN, P. B.	7908150538*	50-366 R
ALLEN, J. M.	7908240036	50-320 P
ALTER, S. D.	7908280309*	COMMISSION
ALTON, C. Q.	7908210440	50-219 J
AMBRO, J. A.	7908080275*	50-322 U
AMBROSE, T. W.	7908030513	70-984
ANDERSON, J. S.	7908210357*	50-309 P
ANDERSON, J. S.	7908270374*	50-344 P
ANDERSON, J. S.	7908270369*	50-344 P
ANDERSON, G. M.	7908240119	NUREG
ANDERSON, G. M.	7908240125	NUREG
ANDERSON, G. M.	7908240135	NUREG
ANDERSON, G. M.	7908240142	NUREG
ANDERSON, J. C.	7908240673	NUREG
ANDERSON, D. M.	7908290598	71-9033
ANDERSON, T. M.	7907190672	REGGD
ANDERSON, T. M.	7908100029	50-275 S
ANDERSON, T. M.	7908130040	PT21
ANDERSON, T. M.	7908150169*	TOPREP
ANDERSON, T. M.	7908200307*	TOPREP
ANDERSON, T. M.	7908200310*	TOPREP
ANDERSON, T. M.	7908200313*	TOPREP
ANDERSON, T. M.	7908170403	TOPREP
ANDERSON, T. M.	7908010465	TOPREP
ANDERSON, T. M.	7908140471	TOPREP
ANDERSON, T. M.	7908150654	TOPREP
ANDERSON, T. M.	7908200304	TOPREP
ANDERSON, T. M.	7908310493	TOPREP
ANDERSON, P. L.	7908010567*	50-309 S
ANDERSON, P. L.	7908030266*	50-309 S
ANDERSON, D. G.	7908140226*	QA999
ANDERSON, D. G.	7908080012*	QA999
ANDERSON, C. J.	7908030124	50-322 A
ANDERSON, C. J.	7908270287	50-358 A
ANDERSON, R.	7908150077	NUREG
ANDERS, W. A.	7908220143*	FOIA
ANDERS, W. A.	7908220142*	FOIA
ANDERS, W. A.	7908220150*	FOIA
ANDERS, W. A.	7908300237	PRM
ANDERS, W. A.	7908300244*	PRM
ANDERS, W. A.	7908300251*	PRM
ANDOGNINI, G. C.	7908030256	50-293 Q
ANDOGNINI, G. C.	7908100128	50-293 P
ANDOGNINI, G. C.	7908100565	71-6601
ANDOGNINI, G. C.	7908100568	71-9113
ANDOGNINI, G. C.	7908100574	71-5026
ANDOGNINI, G. C.	7908070702	50-293 Q
ANDOGNINI, G. C.	7908220648	50-293 Q
ANDOGNINI, G. C.	7908010444	50-293 Q
ANDOGNINI, G. C.	7908080510	50-293 P
ANDOGNINI, G. C.	7908200204	50-293 P
ANDOGNINI, G. C.	7908270454	50-293 P
ANDOGNINI, G. C.	7908280539	50-293 P
ANDOGNINI, G. C.	7908280592	50-293 Q
ANDREWS, R. D.	7908030003	40-8452
ANDREWS, R. D.	7908060503	40-8452
ANDREWS, R. D.	7908100584	40-8452
ANDREWS, R. J.	7908210441	50-285 S
ANDREWS, R. L.	7908210587	50-285 S
ANDREW, C. H.	7908300725*	50-133 P
ANDREWS, D. L.	7908170283*	50-553 Q
ANG, W. P.	7908230684*	50-348 Q
ANGELO, J.	7908240021	GEN TEC IS
ANGELO, J.	7908280875	GEN TEC IS
ANGELO, J.	7908280848	GEN TEC IS
ANGELO, J.	7908220247	GEN TEC IS
ANGELO, J.	7908240018	GEN TEC IS
APPELSON, Q.	7908280536	50-424 Q
ARENAL, A.	7908160427	50-361 S
ARLOTTI, M. Q.	7908170407*	TOPREP
ARLOTTO, Q. A.	7908030131	REGGD
ARLOTTO, Q. A.	7908150159	REGGD
ARLOTTO, Q. A.	7908150179*	REGGD
ARNDT, Q.	7908220270	PR
ARNOLD, D.	7908210050*	PR
ARNOLD, R. C.	7908230331	50-320 P
ARNOLD, R. C.	7908230329	50-320 P
ARTHUR, J. E.	7908070049	50-485 Q
ARTHUR, J. E.	7908290177*	REGGD
ASHENDEN, M. C.	7908090025*	50-269 Q
ASHENDEN, M. C.	7908160194*	50-250 Q
ASWELL, D. L.	7908020276	50-382 Q
ASWELL, D. L.	7908170487	50-382 S
ASWELL, D. L.	7908150111	50-382 Q
ASWELL, D. L.	7908150145	50-382 Q
ASWELL, D. L.	7908150150	50-382 Q
ASWELL, D. L.	7908310475	50-382 Q
ASWELL, D. L.	7908130398	50-382 A

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ASWELL, D. L.	7908270465	50-382 K
AUSTIN, B. T.	7908080714	PT21
AUSTIN, M. A.	7908130384	70-364
AUSTIN, M. A.	7908130385*	70-364
AUSTIN, M. A.	7908130620	70-135
AUSTIN, M. A.	7908150275	70-135
AUSTIN, M. A.	7908140312	70-135
AUSTIN, M. A.	7908090582	70-135
AUSTIN, M. A.	7908090590*	70-135
AUSTIN, M. A.	7908140095	70-135
AUSTIN, M. A.	7908240375	70-135
AUSTIN, M. A.	7908240381	70-364
AUSTIN, M. A.	7908220303	70-364
AUTIO, H. A.	7908020440	50-29 S
AUTIO, H. A.	7908140661	50-29 S
AVARROW, J. M.	7908230160	50-466 Q
AXELRAD, M.	7908300302	50-344 Q
AXELSON, W. L.	7908080700*	50-295 G
AYER, J. E.	7908150040	70-1143
AYER, J. E.	7908150049	70-1143
AYER, J. E.	7908130347	70-364
BABB, A. L.	7908310405	50-139 P
BABBITT, B.	7908240404*	COMMISSION
BABBITT, B.	7908130486	50-320 T
BABBITT, B.	7908030392	50-320 T
BABBITT, B.	7908030604	50-320 T
BABBITT, B.	7908030613	50-320 T
BACA, T. E.	7908060511	40-8726
BACON, J. L.	7908100454	50-329 K
BADGER, W. P.	7908090481*	40-3453
BAER, T. S.	7908090498	27-48
BAER, T. S.	7908300368	71-6144
BAER, T. S.	7908300376	71-6272
BAER, T. S.	7908300383	71-6400
BAER, T. S.	7908300389	71-6058
BAER, T. S.	7908300395	71-6679
BAER, R. L.	7908020549	50-445 A
BAER, R. L.	7908030250	50-382 A
BAER, R. L.	7908020541	50-395 A
BAER, R. L.	7908300439	50-363 P
BAER, R. L.	7908300465	50-445 A
BAER, R. L.	7908140742*	TOPREP
BAER, R. L.	7908100046	50-361 A
BAER, R. L.	7908130103	50-518 A
BAER, R. L.	7908170078	50-382 A
BAER, R. L.	7908150447*	50-382 Q
BAER, R. L.	7908220532	50-382 A
BAER, R. L.	7908300304	50-361 A
BAER, R. L.	7908220110*	FOIA
BAER, R. L.	7908220051	50-395 I
BAGGETT, C.	7908170215	PROJ
BAIJAL, M.	7908010222	50-440 Q
BAILEY, P. G.	7908070721	PRM
BAILY, T. O.	7908300714	40-8674
BAIR, C. G.	7908080473*	50-344 R
BAIR, P.	7908240229	50-320 H
BAISDEN, L.	7908170126	CONTRACT
BAISDEN, L.	7908230215	CONTRACT
BAKER, C. E.	7908130408	40-8681
BAKER, C. E.	7908210209	40-8681
BAKER, A. S.	7908240113*	40-8002
BAKER, A. S.	7908240088*	40-8002
BAKER, C. E.	7908140512	40-8681
BAKER, D. A.	7908300612	50-309 Q
BAKER, D. A.	7908300616*	50-309 Q
BAKER, K. R.	7908160322*	50-346 Q
BAKER, K. R.	7908150382*	50-315 Q
BALLARD, R. L.	7908130566	50-568 D
BALLARD, R. L.	7908020320	50-568 Q
BALLARD, R. L.	7908020353	50-395 D
BALLARD, R. L.	7908020360*	50-395 D
BALLARD, R. L.	7908070037	50-395 D
BALLARD, R. L.	7908070265	50-395 D
BALLARD, R. L.	7908090341	50-395 D
BALLARD, R. L.	7908030185	50-510 D
BALLARD, R. L.	7908170482	50-502 C
BALLARD, R. L.	7908150211	50-341 A
BALLARD, R. L.	7908150207	50-443 H
BALLARD, R. L.	7908170151	50-510 Q
BALLARD, R. L.	7908230243	50-382 C
BALLARD, R. L.	7908290125	WASH
BALOUGH, R. C.	7908200068	50-445 M
BALSEY, J. R.	7908010652	REGGD
BANCROFT, M. H.	7908150735*	50-320 H
BANKS, H. R.	7908030492	50-324 S
BANKS, H. R.	7908030312	50-325 S
BANKS, H. R.	7908030415	50-324 S
BANKS, H. R.	7908060398	50-324 S
BANKS, H. R.	7908060522	50-325 S
BANKS, H. R.	7908060540	50-325 S
BANKS, H. R.	7908060466	50-325 S
BANKS, H. R.	7908140693	50-324 S
BANKS, H. R.	7908150671	50-324 S
BANKS, H. R.	7908200353	50-324 R
BANKS, H. R.	7908200359	50-261 R
BANKS, H. R.	7908200296	50-325 S
BANKS, H. R.	7908200303	50-324 S
BANKS, H. R.	7908210419	50-261 S
BANKS, H. R.	7908230379	50-325 S
BANKS, H. R.	7908230381	50-324 S
BANKS, H. R.	7908230400	50-324 S
BANKS, H. R.	7908210385	50-324 S
BANKS, H. R.	7908210432	50-324 S
BANKS, H. R.	7908230428	50-324 R
BANKS, H. R.	7908230450	50-324 S
BANKS, H. R.	7908230537	50-325 S
BANKS, H. R.	7908230556	50-324 S
BANKS, H. R.	7908270432	50-324 S
BANKS, H. R.	7908240401	50-325 S
BANKS, H. R.	7908240408	50-325 S
BANKS, H. R.	7908240457	50-324 S
BANKS, H. R.	7908290436	50-261 S
BANKS, H. R.	7908300655	50-261 S
BANKS, H. R.	7908300689	50-324 S
BANKS, H. R.	7908290505	50-325 S
BANKS, H. R.	7908290548	50-324 S
BANKS, H. R.	7908310449	50-325 S
BARAKAT, S. F.	7908150324	50-295 H
BARAK, M.	7908240282	71-67
BARBERICK, W.	7908080011	50-387 Q
BARBERICK, W.	7908080060	50-387 Q
BARBOUR, G. H.	7908020386*	50-311 H
BARD, L.	7908090292	50-592 Q
BARD, L.	7908080293	50-592 Q
BARI, R. A.	7908020292	RES
BARKER, N. R.	7908140069*	GA999
BARKER, D. G.	7908150104	50-498 Q
BARKER, F. F.	7908230340*	50-320 Q
BARKER, S. L.	7908010231*	50-10 Q
BARNES, I.	7908100125*	GA999
BARNHART, T. S.	7908220077*	FOIA
BARNTHOUSE, L. W.	7908020462	RES
BARRE, C. H.	7908160567	71-318
BARRETT, P. A.	7908170179*	50-373 Q
BARRETT, P. A.	7908010193*	50-373 Q
BARRETT, P. A.	7908150482*	50-329 Q
BARRY, D. N.	7908090016	PROJ
BARRY, M. S.	7908240295*	COMMISSION
BARRY, D. N.	7908160358	50-361 M
BARTH, C. A.	7906110169	50-455 Q
BARTH, C. A.	7906110175	50-255 P
BARTH, C. A.	7908140641	50-400 Q
BARTH, C. A.	7908220390	50-355 H
BARTH, C. A.	7908230125	50-358 Q
BARTLETT, P.	7908140262	50-574 Q
BARTLETT, R. M.	7908090424	50-293 Q
BARTLETT, J.	7908070795	50-410 Q
BARTLETT, J.	7908070637	50-220 Q
BARTLETT, T.	7908240496	50-220 F
BARTZ, H.	7908030093	70-1201
BARTZ, H.	7908030120	70-33
BARTZ, H.	7908290716	70-25
BARTZ, H.	7908200312	70-1143
BASKIN, K. P.	7908070739	50-361 Q
BASKIN, K. P.	7908280433	50-361 Q
BASKIN, K. P.	7908030160	50-206 P
BASKIN, V. P.	7908170434	50-361 A
BASKIN, K. P.	7908230376	50-206 H
BASKIN, K. P.	7908290474	50-206 F
BASS, B. R.	7908090536	NUREG
BATEMAN, W.	7908230133	PROJ
BATES, R. W.	7908160461*	50-336 S
BATES, R. W.	7908170415*	50-336 S
BATES, J. W.	7908240164*	70-143
BATES, J. W.	7908170634*	70-1151
BAUER, R. H.	7908210121	50-320 P
BAUER, E. G.	7908060397*	50-278 P
BAUER, E. G.	7908230482*	50-277 P
BAUGHMAN, J. D.	7908160044	50-146 H
BAUM, E. A.	7908010354	50-280 P
BAUMAN, R. E.	7907310621*	COMMISSION
BAUNACK, W. H.	7908130660*	50-29 Q
BAXLEY, S. X.	7908240528*	50-366 S
BAXTER, R. C.	7908230464	REGGD
BAXTER, T. A.	7908150383	50-484 Q
BAXTER, T. A.	7908240554*	50-484 Q
BAXTER, R. C.	7908130393	50-332 Q
BAYBUTT, P.	7908080557	RES
BAYBUTT, P.	7908160188*	RES
BAYER, V. S.	7908200005	50-352 Q
BAYNARD, P. Y.	7908020510	71-5026
BAYNARD, P. Y.	7908020170	71-6144
BAYNARD, P. Y.	7908020510	71-5026
BAYNE, J. P.	7908070362	50-286 S
BAYNE, J. P.	7908160570	50-286 Q
BAYNE, J. P.	7908010489	50-286 F
BAYNE, J. P.	7908140510	50-286 R
BAYNE, J. P.	7908170432	50-286 S
BEACH, G.	7908010306	PROJ
BEARD, P. M.	7908230673	71-261
BEARD, P. M.	7908230675*	71-261
BEARD, P. M.	7908270314	71-261
BEATON, R. H.	7908020486	50-70 P
BEATTY, G. P.	7908300775	50-302 Q
BEATTY, G.	7908170413*	50-302 R
BEATTY, G. P.	7908280584	50-302 S
BEATTY, G. P.	7908280594	50-302 S
BECHHOEFER, C.	7908090342	50-358 Q
BECHHOEFER, C.	7908080217	50-358 Q
BECHHOEFER, C.	7908140141	50-358 T
BECHHOEFER, C.	7908150026	50-358 T
BECHHOEFER, C.	7908150727	50-358 T
BECHHOEFER, C.	7908150725	50-358 T
BECHNOEFER, C.	7908130023*	50-255 Q
BECK, J. W.	7908010581	50-271 H
BECK, J. W.	7908130440	50-271 P
BECKER, F. L.	7908020317	RES
BECKIUS, W. J.	7908200386	50-255 P
BECKLEY, B. B.	7908090368	50-443 A
BECKLEY, B. B.	7908270471	50-443 I
BECKNER, W. D.	7908150077	NUREG
BECKSTED, W. F.	7908130220*	GA999
BECKWITH, D. E.	7908010575	50-502 Q
BEDNAR, L. F.	7908010557*	50-298 S
BEDNAR, L. F.	7908080602*	50-298 S
BEDNAR, L. F.	7908310444*	50-298 S
BEGEJ, S.	7908090530	NUREG
BEILMAN, T. P.	7908140656*	50-315 S
BEILMAN, T. P.	7908210525*	50-315 S
BEILMAN, T. P.	7908210534*	50-315 S
BEILMAN, T. P.	7908210541*	50-315 S
BEILMAN, T. P.	7908210546*	50-315 S
BELCHER, R. L.	7908170395	50-166 R
BELIN, A.	7908150035*	FOIA
BELIN, A.	7908150046*	FOIA
BELIN, A.	7908160307	FOIA
BELING, D. C.	7908010675	40-8636
BELISLE, G. A.	7908170202*	50-348 Q
BELL, M. J.	7908230189*	SECY
BENDER, B. B.	7908080684	50-387 S
BENDER, M.	7908030317	ACRS
BENDER, M.	7908030364	ACRS
BENDER, M.	7908150053	ACRS
BENDER, M.	7908220076	50-320 T
BENEDICT, R. A.	7908020248	50-382 A
BENEDICT, R. A.	7908150351	50-518 A
BENEDICT, R. A.	7908150447*	50-382 Q
BENEDICT, R. A.	7908220236	50-363 A
BENINN, R.	7908300624	50-317 S
BENNEDSEN, M. B.	7908010665*	40-8698
BENNETT, G. P.	7908210299*	TOPREP
BENNETT, G. L.	7908080600*	FOIA
BENNETT, G. L.	7908080201	ORG
BENNETT, G. L.	7908100531	ORG
BERATON, L. L.	7908080705*	50-338 P
BERESOVSKI, T.	7908220165	50-320 P
BERK, A. J.	7908210498	50-10 H
BERKSON, H.	7908230544*	50-320 Q
BERNRUTER, D. L.	7908130292*	GEN TEC IS
BERRY, G. T.	7908210539	50-286 Q
BERRY, G. T.	7908220359	50-333 P
BERRY, G. T.	7908280013	50-333 F
BERRY, G. T.	7908280020	50-286 F
BESAW, W. J.	7904270395	50-320 D
BESAW, W. J.	7904260285	50-320 P
BESAW, W. J.	7909230322	50-320 P
BETSILL, J. A.	7908010373	50-302 P
BETTENHAUSEN, L.	7908130291*	50-271 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
BETTENHAUSEN, L.	7908130422*	50-219	Q
BICKWIT, L.	7908010039*	10CFR	
BICKWIT, L.	7908010640*	10CFR	
BICKWIT, L.	7908010616	50-320	H
BICKWIT, L.	7908080612*	50-312	Q
BICKWIT, L.	7908080620*	50-312	Q
BICKWIT, L.	7908080627*	50-312	Q
BICKWIT, L.	7908210082*	50-289	T
BICKWIT, L.	7908210089*	50-289	T
BIDDLE, C. T.	7908220304	50-466	Q
BIDDLE, C. T.	7908220312	50-466	Q
BIDDLE, C. T.	7908220315	50-466	Q
BILBRO, G. L.	7908160435*	50-338	S
BINGHAM, D.	7908140262	50-574	Q
BINION, T.	7908280799	50-320	T
BINION, T.	7908280783	50-320	T
BINION, T.	7908280772	50-320	T
BINION, T.	7908280779	50-320	T
BIRKEL, R. A.	7908030349	50-437	A
BIRKEL, R. A.	7908070733	50-437	A
BISHOP, C. J.	7908300099	50-522	Q
BISHOP, C. J.	7908080056	50-389	Q
BISHOP, C. J.	7908290722	50-518	Q
BISHOP, C. J.	7908080131	50-338	Q
BISHOP, C. J.	7908240558*	50-484	Q
BISHOP, C. J.	7908220409	50-3	Q
BISHOP, T. W.	7908150212*	50-397	Q
BISSETT, P. H.	7908210158*	70-135	
BIVINS, W. S.	7908140689*	50-522	Q
BIVINS, W. S.	7908270181	50-580	A
BIXEL, D. A.	7908020272	50-155	Q
BIXEL, D. A.	7908170165	50-155	Q
BIXEL, D. A.	7908010507	50-155	P
BIXEL, D. A.	7908240523	50-155	Q
BIXEL, D. A.	7908240529	50-155	Q
BIXEL, D. A.	7908300406	71-5901	
BIXEL, D. A.	7908310012	71-6601	
BIXEL, D. A.	7908310013	71-6144	
BIXEL, D. A.	7908240501	50-155	Q
BIXEL, D. A.	7908160359	50-155	Q
BIXEL, D. A.	7908070536	50-255	P
BIXEL, D. A.	7908090350	50-255	P
BIXEL, D. A.	7908140539	50-155	Q
BIXEL, D. A.	7908240165	50-155	Q
BIXEL, D. A.	7908220321	50-155	P
BIXEL, D. A.	7908240455	50-255	P
BIXEL, D. A.	7908280566	50-155	P
BIXEL, D. A.	7908280007	50-155	P
BIXEL, D. A.	7908300449	50-155	P
BLACK, R. L.	7905230354	50-354	Q
BLACK, R. L.	7906070316	50-354	A
BLACK, R. L.	7908020256	50-341	Q
BLACK, R. L.	7908020264*	50-341	Q
BLACK, R. L.	7908140677	50-522	Q
BLACK, R. L.	7908280359	50-522	Q
BLACK, R. L.	7908080233	50-522	Q
BLACK, R. L.	7908140049	50-275	Q
BLACK, R. L.	7908080280	50-522	Q
BLACK, R. L.	7908150005	50-522	Q
BLACKWOOD, E.	7908240181*	50-324	Q
BLAKE, E. L.	7908230238	50-320	P
BLAND, J. S.	7908230634*	50-320	Q
BLAND, J. S.	7908220177	50-320	P
BLATT, B.	7908220438	50-466	Q
BLAYLOCK, J.	7908030093	70-1201	
BLODGET, T.	7908150433	FOIA	
BLOSSOM, J. N.	7908010322	40-8452	
BLUM, S.	7908240170	70-2623	
BLUMBERG, N. J.	7908280225*	50-311	Q
BLUME, M. B.	7908030230	50-445	M
BLUME, M. B.	7908200269	50-445	M
BLUME, M. B.	7908310010	50-445	M
BOBCZYNSKI, N. I.	7908210416	50-275	Q
BODTKE, P. J.	7908140538*	50-255	R
BOGDEN, Q.	7908210204	40-1162	
BOGDEN, Q.	7908170176	40-1162	
BOGIN, M. B.	7908160300*	50-574	A
BOHN, R. J.	7908030147	50-3[illegible]	R
BOHN, R. J.	7908140491	50-367	R
BOHN, R. J.	7908220333	50-367	R
BOHN, R. J.	7908220275	50-367	R
BOHN, R. J.	7908300494	50-367	A
BOLLINGER, G. A.	7908010494	RES	
BONDERMAN, D.	7908170346*	50-329	Q
BONINE, J. E.	7908080751	FOIA	
BONNER, J. A.	7908090268	CONTRACT	
BONNER, J. A.	7908090620	CONTRACT	
BOOK, H. E.	7908030223*	70-754	
BOOK, H. E.	7908030209	70-754	
BOOK, H. E.	7908170466	50-89	G
BOOK, H. E.	7908170472*	50-89	G
BOOK, H. E.	7908170129*	70-984	
BOOK, H. E.	7906170119	70-984	
BOOK, H. E.	7908210044*	GA999	
BOOK, H. E.	7908210038	GA999	
BORDENICK, B. M.	7908020270	50-516	G
BORDENICK, B. M.	7908300073	50-516	G
BORER, P. J.	7908140764*	50-298	R
BORES, R. J.	7908230590*	50-320	G
BORES, R. J.	7908230634*	50-320	G
BORES, R. J.	7908230544*	50-320	G
BORGMANN, E. A.	7908230202*	50-358	G
BORGMANN, E. A.	7908230197*	50-358	G
BORGMANN, E. A.	7908230192*	50-358	G
BORGMANN, E. A.	7908130047	50-358	G
BORGMANN, E. A.	7908030567*	50-358	G
BORGMANN, E. A.	7908270556	50-358	G
BORGMANN, E. A.	7908290368	50-358	G
BORGMANN, E. A.	7908230128*	50-358	G
BORGMANN, E. A.	7908230330	50-358	A
BORTIN, B.	7908200046*	50-280	H
BORYSIAK, M.	7908100467*	50-346	S
BOSNAK, R. J.	7907180165	50-320	P
BOTT, T. F.	7908240668	NUREG	
BOURNIA, A.	7908080619	50-373	A
BOWERS, J.	7908210404*	50-320	Q
BOWERS, J.	7908210400	50-320	Q
BOWERS, C. E.	7908090528	70-820	
BOWERS, C. E.	7908140476	71-241	
BOWERS, C. E.	7908090367	70-820	
BOWERS, C. E.	7908170618	70-820	
BOYD, D. C.	7908280214*	50-155	Q
BOYD, D. C.	7908280233*	50-255	Q
BOYD, D. C.	7908150382*	50-315	Q
BOYD, R. S.	7908020027*	50-10	P
BOYD, R. S.	7908170275*	50-10	P
BOYD, R. S.	7908280264*	50-10	P
BOYD, R. S.	7908280146*	FOIA	
BOYER, V. S.	7908200301*	50-352	Q
BOYER, V. S.	7908160576	50-352	Q
BOZIK, D. A.	7908080681	PRM	
BRADFORD, G.	7908210404*	50-320	Q
BRADFORD, W. H.	7908280817*	50-302	Q
BRADFORD, W. H.	7908300544*	50-269	Q
BRADFORD, P. A.	7908100315	10CFR	
BRADFORD, P. A.	7908010033	10CFR	
BRADFORD, P. A.	7908010636	10CFR	
BRADFORD, P. A.	7908010658	10CFR	
BRADFORD, P. A.	7907030417	10CFR	
BRADFORD, P. A.	7908010611	10CFR	
BRADFORD, P. A.	7908080150	10CFR	
BRADFORD, P. A.	7908170503	SECY	
BRADFORD, P. A.	7908030336	10CFR	
BRADFORD, P. A.	7908080139	50-289	T
BRADFORD, P. A.	7908170593	10CFR	
BRADLEY, E. J.	7908030133	50-277	P
BRADLEY, E. J.	7908060387	50-278	P
BRADLEY, E. J.	7908060397*	50-278	P
BRADLEY, E. J.	7908140454	50-277	P
BRADLEY, E. J.	7908230335	50-277	P
BRADLEY, E. J.	7908230479	50-277	P
BRADLEY, E. J.	7908240466	50-277	P
BRADLEY, E. J.	7908230482*	50-277	P
BRADLEY, E. J.	7908290575	50-277	P
BRADLEY, R. D.	7908160415*	50-400	Q
BRADY, R. J.	7908010057*	10CFR	
BRANDSTETTER, C.	7908240534*	71-329	
BRANDSTETTER, C.	7908240531	71-329	
BREED, A.	7908070446	TOPREP	
BREEDLOVE, P. D.	7908140511	50-302	H
BREITENSTEIN, B.	7908150475*	ORG	
BRENNER, L.	7905150697	50-510	Q
BRENNER, L.	7905150042	50-443	Q
BRENNER, L.	7908090450	50-443	Q
BRENNER, L.	7908030574	27-39	
BRICKLEY, R. H.	7908220646*	GA999	
BRIGGS, K.	7908060491	40-8681	
BRIGGS, L. E.	7908010712*	50-219	G
BRIGHT, R. H.	7908290499	50-302	P
BRIGHT, R. M.	7908210405	50-302	P
BRIGHT, G. O.	7908090342	50-358	Q
BRIGHT, G. O.	7908140141	50-358	T
BRIGHT, G. O.	7908150026	50-358	T
BRIGHT, G. O.	7908150727	50-358	T
BRIGHT, G. O.	7908150725	50-358	T
BRIGHTSEN, R. A.	7908080635*	FOIA	
BRIGHTSEN, R. A.	7908080626*	FOIA	
BRISTOL, , D. C.	7908140664	XPORTLIC	
BRODE, L.	7908220362	50-466	Q
BRODSKY, R. S.	7908270226*	PROJ	
BROEHL, D. J.	7908080020	50-344	Q
BROEHL, D. J.	7908010492	50-344	P
BROEHL, D. J.	7908010531	50-344	H
BROEHL, D. J.	7908150623*	50-344	P
BROEHL, D. J.	7908150618	50-344	P
BROEHL, D. J.	7908170359	50-344	P
BROEHL, D. J.	7908170424	50-344	P
BROEHL, D. J.	7908270401	50-344	P
BROEHL, D. J.	7908210480	50-344	F
BROOKS, E. H.	7908170234*	50-348	Q
BROWN, S. M.	7908220355	50-466	Q
BROWN, N. Q.	7908170029	50-443	Q
BROWN, E. C.	7908090140	FOIA	
BROWN, F. R.	7908170535*	50-482	Q
BROWN, F. R.	7908300597	50-482	A
BROWN, W. W.	7908010370	50-395	D
BROWN, M. S.	7908060422*	50-315	S
BROWN, M. S.	7908140750*	50-315	S
BROWNRIGG, D. L.	7908300722*	50-133	P
BROWN, S. C.	7908010683	50-404	Q
BROWN, S. C.	7908200118	50-339	S
BROWN, S. C.	7908020269	50-404	Q
BROWN, S. C.	7908150192	50-339	S
BROWN, S. C.	7908150365	50-339	Q
BROWN, S. C.	7908010396	50-339	S
BROWN, S. C.	7908170058	50-404	Q
BROWN, S. C.	7908060278	50-339	S
BROWN, S. C.	7908060301*	50-339	S
BROWN, S. C.	7908140553	50-339	S
BROWN, S. C.	7908100407	50-339	S
BROWN, S. C.	7908150578	50-339	A
BROWN, S. C.	7908150673	50-404	A
BROWN, S. C.	7908160467	50-280	P
BROWN, S. C.	7908230449	50-339	S
BROWN, S. C.	7908300727	50-339	S
BROWN, S. C.	7908240452	50-404	A
BROWN, S. C.	7908280558	50-404	A
BROWN, S. C.	7908280560	50-404	A
BROWNLEE, V. L.	7908150274*	50-280	Q
BROWNLEE, V. L.	7908160194*	50-250	Q
BROWN, Q. D.	7908010442*	40-8675	
BROWN, R. L.	7908130490*	GA999	
BROWN, Q. D.	7908010433	40-8675	
BROWN, Q. D.	7908090333*	40-6659	
BROWN, Q. D.	7908090304	40-6659	
BROWN, Q. D.	7908240172*	40-8102	
BROWN, Q. D.	7908240169	40-8102	
BROWN, Q. D.	7908020201*	40-4492	
BROWN, R. L.	7908220646*	GA999	
BROWNE, W. G.	7908080026	70-1143	
BROWNE, W. G.	7908080381	70-1143	
BROWNING, R. E.	7908070488*	50-320	P
BROWN, C. H.	7908230417*	10CFR	
BRUGGER, R. M.	7908310512*	50-186	P
BRUGGER, R. M.	7908080402	50-186	Q
BRUGGER, R. M.	7908310507	50-186	P
BRUGGE, R. D.	7908080524*	50-296	P
BRUGGE, R. D.	7908060403*	50-278	P
BRUGGE, R. D.	7908060407*	50-278	P
BRUNNER, E. J.	7908090693	50-223	Q
BRUNNER, E. J.	7908230594	50-320	Q
BRUNNER, E. J.	7908230637	50-320	Q
BRUNNER, E. J.	7908080160*	50-286	Q
BRUNNER, E. J.	7908020088*	50-245	Q
BRUNNER, E. J.	7908280109*	50-219	Q
BRUNNER, E. J.	7908020110*	50-309	Q
BRUNNER, E. J.	7908010697*	50-219	Q
BRUNNER, , E. J.	7908020139	50-272	Q
BRUNNER, E. J.	7908020092	50-247	Q
BRUNNER, E. J.	7908280221	50-311	Q
BRUNNER, E. J.	7908130626	50-29	Q
BRUNNER, E. J.	7908130288	50-271	Q
BRUNNER, E. J.	7908130386	50-219	Q
BRUNNER, E. J.	7908130417	50-219	Q
BRUNNER, E. J.	7908130652	50-29	Q
BRUNNER, E. J.	7908130662	50-387	Q
BRUNNER, E. J.	7908140049	50-336	Q
BRUNNER, E. J.	7908020103	50-309	Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
BRUNNER, E. J.	7908270117	50-293	Q
BRUNNER, E. J.	7908010676	50-219	Q
BRUNNER, E. J.	7908020076	50-245	Q
BRUNNER, E. J.	7908080152	50-286	Q
BRUNNER, E. J.	7908280100	50-219	Q
BRYANT, J. C.	7908030606*	50-416	Q
BRYANT, B.	7908140204*	50-556	A
BRYANT, J. C.	7908020228	50-317	Q
BRYANT, W. M.	7908030385*	50-220	F
BRYAN, J. K.	7908020255	50-483	Q
BRYAN, J. K.	7908020261	50-483	Q
BRYAN, J. K.	7908130118*	50-483	Q
BRYAN, J. K.	7908200292	50-483	S
BRYAN, S.	7908020044*	50-280	Q
BRYAN, S. E.	7908240256*	50-255	P
BRYAN, S.	7908210201	50-320	A
BRYANT, J. C.	7908240118*	50-339	Q
BRYANT, J. C.	7908020217*	50-338	Q
BRYANT, J. C.	7908020190*	50-327	Q
BRYANT, J. C.	7908020526*	50-416	Q
BRYANT, J. C.	7908010349*	50-424	Q
BRYANT, J. C.	7908020069*	50-553	Q
BRYANT, J. C.	7908150394*	50-438	Q
BRYANT, J. C.	7908030608*	50-327	Q
BRYANT, J. C.	7908210565*	50-366	Q
BRYANT, J. C.	7908210583*	50-566	Q
BRYANT, J. C.	7908240168*	50-281	Q
BRYANT, J. C.	7908170061*	50-369	Q
BRYANT, J. C.	7908160349*	50-424	Q
BRYANT, J. C.	7908160415*	50-400	Q
BRYANT, J. C.	7908230599*	50-395	Q
BRYSON, J. M.	7908090120	FOIA	
BUCHANAN, J. D.	7908150745	50-320	H
BUCHHOLZ, R. H.	7908240433	TOPREP	
BUCHHOLZ, R. H.	7908030393	50-320	Q
BUCHHOLZ, R. H.	7908160421	TOPREP	
BUCHHOLZ, R. H.	7908070641	TOPREP	
BUCKLAND, R. J.	7908140084	NUREG	
BUCKLEY, C. H.	7908240219	FOIA	
BUCKLEY, B. C.	7908010218	50-461	A
BUCKLEY, B. C.	7908100352	50-461	A
BUCKLEY, B. C.	7908060101*	50-275	A
BUCKLEY, B. C.	7908030128	50-275	A
BUCKLEY, B. C.	7908170596	50-275	Q
BUDD, I. C.	7908280226	PROJ	
BULLOCK, J. B.	7908270273	RES	
BURCHETT, R. R.	7908230592	NUREG	
BURCHETTE, W. H.	7908200395	50-445	M
BURCHETT, R. R.	7908080437	NUREG	
BURDETTE, T. E.	7908230599*	50-395	Q
BURDOIN, J.	7908270083	50-295	P
BURKE, D. J.	7908150533*	50-280	Q
BURKHARDT, W.	7908150036	70-364	
BURKHARDT, W.	7908130347	70-364	
BURNETTE, G. W.	7908130449	TOPREP	
BURNETT, P. T.	7908170234*	50-348	Q
BURNETT, P. T.	7908240297*	50-302	Q
BURNETT, R. F.	7908140464	70-25	
BURNETT, R. F.	7908150262	70-36	
BURNETT, R. F.	7908170180	70-1113	
BURNS, J. W.	7908100588	PROJ	
BURSTEIN, S.	7908060537	50-266	Q
BURSTEIN, S.	7908140330	50-301	Q
BURSTEIN, S.	7908150230	50-266	Q
BURSTEIN, S.	7908090416	50-266	Q
BURSTEIN, S.	7908020471	50-502	I
BURSTEIN, S.	7908020423	50-266	H
BURSTEIN, S.	7908070412	50-596	C
BURSTEIN, S.	7908020437	50-266	F
BURSTEIN, S.	7908080475	50-266	Q
BURSTEIN, S.	7908140401	50-266	R
BURSTEIN, S.	7908160448	50-266	R
BURSTEIN, S.	7908140760	50-266	P
BURSTEIN, S.	7908270420	50-266	S
BURSTEIN, S.	7908290411	50-266	F
BURSTEIN, S.	7908270473	50-266	P
BURT, L.	7908100505	FOIA	
BURT, L.	7908280045	FOIA	
BURT, L.	7908070629	50-471	Q
BURWELL, S. B.	7908300428	50-445	A
BURZI, A. V. J.	7908230481*	50-320	Q
BUSH, S. H.	7908170302	ACRS	
BUSH, S. H.	7908020317	RES	
BUSHMIL, S.	7908020158	71-9033	
BUTLER, R. M.	7908090445	50-471	F
BUTLER, R. M.	7908210[illegible]24	REGGD	
BUTLER, R. M.	7908280035	50-471	F
BUTLER, M. K.	7908080205*	ORG	
[illegible]A, E.	7908140465*	50-346	R
[illegible]BELL, A. S.	7908300767	70-1739	
[illegible]BY, K. B.	7908020152	RES	
CAHILL, W. J.	7908080501	50-3	Q
CAHILL, W. J.	7908070043	50-247	Q
CAHILL, W. J.	7908070775	50-3	Q
CAHILL, W. J.	7908090671	50-3	Q
CAHILL, W. J.	7908170368	50-3	Q
CAHILL, W. J.	7908010343	50-3	P
CAHILL, W. J.	7908080527	50-3	P
CAHILL, W. J.	7908070475	50-247	P
CAHILL, W. J.	7908090392	50-247	P
CAHILL, W. J.	7908030174	50-247	P
CAHILL, W. J.	7908070598	50-3	F
CAHILL, W. J.	7908070609	50-247	Q
CAHILL, W. J.	7908090375	50-3	J
CAHILL, W. J.	7908140826	50-247	S
CAHILL, W. J.	7908240372	50-3	P
CAHILL, W. J.	7908280704	50-247	P
CAHILL, W. J.	7908290584	50-3	Q
CALDWELL, B. Q.	7908080631*	50-329	A
CALDWELL, R. A.	7908010679*	50-267	Q
CALDWELL, R. A.	7908080251*	50-252	Q
CALHOUN, J. R.	7908100425	50-259	S
CALHOUN, J. R.	7908140807	50-259	S
CALHOUN, J. R.	7908210425	50-296	S
CALHOUN, J. R.	7908280691	50-296	S
CALHOUN, J. R.	7908280732	50-260	S
CAMPBELL, E.	7908290489	50-546	Q
CAMPBELL, W. R.	7908100066*	50-280	H
CAMPBELL, J.	7908140778*	50-304	S
CAMPBELL, Q. W.	7908300595	ORG	
CAMPBELL, J. E.	7908030044	NUREG	
CANLON, T. E.	7908170217*	50-400	Q
CANNADAY, F. X.	7908140191*	40-8663	
CANTER, H. L.	7908150196*	50-361	Q
CANTRELL, F. S.	7908290138*	50-438	Q
CANTRELL, F. S.	7908060308*	50-566	Q
CANTRELL, F. S.	7908290208*	50-518	Q
CANTRELL, F. S.	7908230691*	50-281	Q
CAPHTON, D. L.	7908140051*	50-336	Q
CAPHTON, D. L.	7908130422*	50-219	Q
CAPHTON, D. L.	7908130663*	50-367	Q
CAPHTON, D. L.	7908130291*	50-271	Q
CAPHTON, D. L.	7908130390*	50-219	Q
CAPITANIO, M. A.	7908020337	PRM	
CAPRA, R. A.	7908090247	TOPREP	
CAPRA, R. A.	7908090270	TOPREP	
CAPRA, R. A.	7908090440	TOPREP	
CAPRA, R. A.	7908080132	50-346	P
CAPRA, R. A.	7908300599	50-269	P
CAPRA, R. A.	7908160239	50-269	P
CARBON, M. W.	7908070046	ACRS	
CARBON, M. W.	7908130063*	50-367	D
CARBON, M. W.	7908170207	50-367	A
CARBON, M. W.	7908170200	ACRS	
CARBON, M. W.	7908160370	ACRS	
CARBON, M. W.	7908030318	50-320	Q
CARBON, M. W.	7908220076	50-320	T
CARBON, M. W.	7908220218*	50-320	P
CARBON, M. W.	7908230281	ACRS	
CARBON, M. W.	7908290496	ACRS	
CARBON, M. W.	7908290477	ACRS	
CARD, J. C.	7908090475	50-437	A
CAREW, J. F.	7908010591	RES	
CARLOS, P. C.	7908130290	40-8636	
CARLOS, P. C.	7908170191	40-8636	
CARLSON, R. T.	7908230635*	50-146	Q
CARLSON, R. T.	7908240597	50-311	S
CARLSON, R. T.	7908230570	50-320	Q
CARLSON, R. T.	7908230486	50-320	Q
CARLSON, R. T.	7908020127	50-485	Q
CARLSON, R. T.	7908090181	50-410	S
CARLSON, R. T.	7908140746	50-387	S
CARLSON, R. T.	7908010299	50-412	S
CARLSON, R. T.	7908200280*	50-387	Q
CARLSON, R. T.	7908170079	50-333	Q
CARLSON, R. T.	7908130492	50-352	Q
CARLSON, R. T.	7908130609	50-423	Q
CARLSON, R. T.	7908200062	50-245	Q
CARLSON, R. T.	7908200051	50-410	Q
CARLSON, R. T.	7908200058	50-336	Q
CARLSON, R. T.	7908140340	50-387	Q
CARLSON, R. T.	7908140652	50-410	S
CARLSON, R. T.	7908270074	50-363	Q
CARLSON, R. C.	7908200364*	50-352	Q
CARLSON, R. T.	7908170087	50-387	S
CARLSON, R. T.	7908210108	50-322	S
CARLSON, R. T.	7908210106	50-410	S
CARLSON, R. T.	7908200297	50-352	Q
CARLSON, R. T.	7908240220	50-410	Q
CARLSON, R. T.	7908200274	50-387	Q
CARLSON, R. T.	7908240604	50-412	S
CARLSON, R. T.	7908170072	50-410	S
CARLSON, R. T.	7908230643	50-320	Q
CARLSON, J.	7908170123*	50-312	Q
CARR, A. V.	7908300302	50-344	Q
CARR, J. B.	7908090459*	TOPREP	
CARRIER, W. C.	7908010491	50-320	J
CARRIER, W. C.	7908220289	50-320	J
CARROLL, J. T.	7908080428	50-219	S
CARROLL, J. T.	7908140670	50-219	S
CARROLL, J. T.	7908230353	50-219	S
CARTER, M. W.	7908080416	NUREG	
CARTER, W. K.	7908090177	71-31	
CARTER, W. K.	7908090179*	71-31	
CARTER, K. W.	7908080015	50-387	Q
CARTER, K. A.	7908080018*	50-387	Q
CARTER, R. S.	7908290490	50-184	P
CARTER, R. S.	7908310553	50-184	F
CARTER, T. F.	7908020302*	50-437	Q
CARTWRIGHT, W. R.	7908070497*	50-338	S
CARTWRIGHT, W. B.	7908070583*	50-338	S
CARTWRIGHT, W. R.	7908130459*	50-338	S
CARTWRIGHT, W. R.	7908100312*	50-338	S
CARTWRIGHT, W. R.	7908160433*	50-338	S
CARTWRIGHT, W. R.	7908240493*	50-338	S
CARTWRIGHT, W. R.	7908240498*	50-338	S
CARTWRIGHT, W. R.	7908240427*	50-338	S
CARTWRIGHT, W. R.	7908280653*	50-338	S
CARTWRIGHT, W. R.	7908280759*	50-338	S
CASE, E. G.	7907310599*	FOIA	
CASHELL, S.	7908010436	50-155	P
CASHWELL, R. J.	7908010681	REGGD	
CASHWELL, R. J.	7908010542	50-156	R
CASHWELL, R. J.	7908010549*	50-156	R
CASHWELL, R. J.	7908140607	50-156	P
CASHWELL, R. J.	7908310298	50-156	P
CASTRO, R.	7908150276	50-312	Q
CATCHPOLE, G. J.	7908080258	40-8693	
CATTON, I.	7908170229	ACRS	
CAVANAUGH, W.	7908090580	50-313	H
CAVANAUGH, W.	7908290419	50-368	P
CAVE, W. T.	7908170572*	70-572	
CAVE, W. T.	7908170567*	70-572	
CAVE, W. T.	7908170557*	70-572	
CAYOT, R. F.	7908300722*	50-133	P
CAYOT, R. F.	7908300725*	50-133	P
CERNE, A. C.	7908200288*	50-387	Q
CERNE, A.	7908130495*	50-352	Q
CHABOT, G. E.	7908010533	50-223	S
CHADWELL, H. M.	7908210551*	50-315	S
CHAN, J.	7908080387*	50-237	S
CHAN, J.	7908220400*	50-237	S
CHANDLER, L. J.	7908150017	50-361	Q
CHANDLER, L. J.	7908230014	50-320	H
CHANDLER, L. J.	7908220087	50-320	Q
CHANDLER, L. J.	7908220093*	50-320	Q
CHANDLER, L. J.	7908150004	50-361	Q
CHANDLER, L. J.	7908300604	50-361	H
CHANDLER, L. J.	7908300027	50-445	Q
CHAPMAN, R. H.	7908020135	RES	
CHAPMAN, L. D.	7908010274	RES	
CHAPMAN, L. D.	7908080521	RES	
CHAPMAN, L. D.	7908100296	RES	
CHAPMAN, L. D.	7908100304	RES	
CHATTIN, H. S.	7908300431	71-9033	
CHATTIN, H. S.	7908200101	71-91	
CHECK, P. S.	7908150767	50-320	H
CHEN, J. C.	7908140631	RES	
CHENEY, E. S.	7908300010*	50-522	Q
CHENG, T. M.	7908070769	50-10	P
CHERN, W. S.	7908080102	50-471	Q
CHERN, W. S.	7908140610	RES	
CHERNY, F. C.	7908300[illegible]	[illegible]	IS
CHERNY, F. C.	7908020[illegible]	[illegible]	IS
CHEVERTON, R. D.	7908070[illegible]	[illegible]	
CHIANGI, N. J.	7908100[illegible]	[illegible]	S
CHILDS, W. V.	7908080[illegible]	[illegible]	S
CHILDS, W. V.	7908080[illegible]*	50-[illegible]33	S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHILDS, W. V.	7908060471*	50-333 S
CHILDS, W. V.	7908060500*	50-333 S
CHILDS, W. V.	7908290464*	50-333 S
CHILK, S. J.	7908280114*	FOIA
CHILK, S. J.	7908280092*	FOIA
CHILK, S. J.	7908280076*	FOIA
CHILK, S. J.	7908140268*	SECY
CHILK, S. J.	7908010045*	10CFR
CHILK, S. J.	7908010050*	10CFR
CHILK, S. J.	7908010702*	10CFR
CHILK, S. J.	7908140285*	COMMISSION
CHILK, S. J.	7908020209*	50-312 T
CHILK, S. J.	7908030184	50-574 Q
CHILK, S. J.	7908060204	50-574 Q
CHILK, S. J.	7908060424	50-574 Q
CHILK, S. J.	7908090677	50-574 Q
CHILK, S. J.	7908160241*	50-346 P
CHILK, S. J.	7908230315	10CFR
CHILK, S. J.	7908300103	50-309 Q
CHILK, S. J.	7908080723	FOIA
CHILK, S. J.	7908230187	10CFR
CHILK, S. J.	7908300055	50-309 Q
CHILK, S. J.	7908020010	70-754
CHILK, S. J.	7908170305	COMMISSION
CHILK, S. J.	7908170308*	COMMISSION
CHILK, S. J.	7908300086	10CFR
CHILK, S. J.	7908170020	10CFR
CHILK, S. J.	7908220055	10CFR
CHILK, S. J.	7908230670	10CFR
CHILK, S. J.	7908230043	10CFR
CHILK, S. J.	7908170018	10CFR
CHILK, S. J.	7908170189	PR
CHILK, S. J.	7908170576	10CFR
CHILUAT, J. E.	7908220552	50-466 Q
CHIN, S.	7908310009	71-9033
CHIRAMAL, M.	7908150608*	50-320 P
CHISHOLM, J. R.	7908160548*	CONTRACT
CHOW, W. Y.	7908150643	50-57 R
CHONG, L. K.	7908140145	PROJ
CHOULES, N. C.	7908280193*	50-305 Q
CHOULES, N. C.	7908290516*	50-305 Q
CHRISTIAN, C.	7908220159	50-574 Q
CHRISTMAN, J. N.	7908080040	50-338 Q
CHRISTMAN, J. N.	7908150252	50-338 Q
CHRISTMAN, J. N.	7908170563	50-338 Q
CHRISTMAN, J. N.	7908170569*	50-338 Q
CHRISTMAN, J. N.	7908080104	50-338 Q
CHRISTENBURY, E.	7908010272	50-320 H
CHU, J.	7908170493	PROJ
CHURCHILL, B. W.	7908160260*	50-346 P
CLARK, L.	7908100570	71-6601
CLARK, L.	7908310402	50-20 P
CLARK, C. W.	7908300666	TOPREP
CLARKE, W. L.	7908010256	RES
CLARKE, W. L.	7908010283	RES
CLARKE, W. L.	7908240644	NUREG
CLARK, J. R.	7908090448	71-198
CLARK, J. R.	7908140367	50-261 P
CLARK, R. H.	7908130215	50-445 M
CLARK, R. H.	7908130176	50-445 M
CLARK, R. H.	7908130240	50-445 M
CLARK, R. H.	7908130246	50-445 M
CLARK, D.	7908140690*	50-254 S
CLARK, R. A.	7908010342	RES
CLARK, R. A.	7908140659	RES
CLARK, R. A.	7907310374	REGGD
CLARY, R.	7908280187	COMMISSION
CLARY, R.	7908030083*	71-5597
CLARY, R.	7908030079*	71-5597
CLARY, R.	7908030041	71-5597
CLARY, R.	7908030049*	71-5597
CLARY, R.	7908030054*	71-5597
CLARY, R.	7908030057*	71-5597
CLARY, R.	7908030061*	71-5597
CLARY, R.	7908030064*	71-5597
CLAY, E. L.	7908170634*	70-1151
CLAY, E. L.	7908150553*	70-143
CLAYTON, F. L.	7908220309	50-348 Q
CLAYTON, F. L.	7908070284*	50-364 Q
CLAYTON, F. L.	7908020389	50-348 Q
CLAYTON, F. L.	7908280785	50-348 P
CLAYTON, F. L.	7908160476*	50-348 Q
CLAYTON, F. L.	7908080240	50-348 Q
CLAYTON, F. L.	7908070817	50-348 Q
CLAYTON, F. L.	7908280780	50-348 P
CLAYTON, F. L.	7908030507	50-348 Q
CLAYTON, F. L.	7908010380	50-348 P
CLAYTON, F. L.	7908020466	50-348 H
CLAYTON, F. L.	7908010543	50-348 S
CLAYTON, F. L.	7908230664	50-348 Q
CLAYTON, F. L.	7908020429	50-348 P
CLAYTON, F. L.	7908070485	50-348 S
CLAYTON, F. L.	7908140569	50-348 P
CLAYTON, F. L.	7908140733	50-348 S
CLAYTON, F. L.	7908140543	50-348 R
CLAYTON, F. L.	7908140662	50-348 S
CLAYTON, F. L.	7908160424	50-348 H
CLAYTON, F. L.	7908200311	50-348 S
CLAYTON, F. L.	7908200327	50-348 F
CLEAVES, W. S.	7908200146	50-466 Q
CLEMENTS, B. R.	7908200324	50-445 F
CLEMENSON, F.	7908030328*	50-261 P
CLEMONS, P. E.	7908230565*	50-320 Q
CLEVELAND, N. B.	7909130485*	QA999
CLIKEMAN, F. M.	7908130612	70-152
CLINKSCALES, W. A.	7908010065*	10CFR
COCHRAN, T. B.	7908030411	FOIA
COCHRAN, T. B.	7908080610	FOIA
CODELL, R. B.	7908220075*	FOIA
COFFMAN, W. A.	7908060061	FOIA
COGGIN, C. L.	7908140806*	50-321 S
COGGIN, C. L.	7908020434*	50-321 S
COGGIN, C. L.	7908020456*	50-366 S
COGGIN, C. L.	7908020426*	50-321 S
COGGIN, C. L.	7908060474*	50-321 S
COGGIN, C. L.	7908130437*	50-366 S
COGGIN, C. L.	7908130345*	50-366 S
COGGIN, C. L.	7908140823*	50-366 S
COGGIN, C. L.	7908200355*	50-366 S
COGGIN, C. L.	7908140837*	50-366 S
COGGIN, C. I.	7908200285*	50-321 S
COGGIN, C. L.	7908200340*	50-366 S
COGGIN, C. L.	7908240393*	50-321 S
COGGIN, C. L.	7908200273*	50-321 S
COGGIN, C. L.	7908240377*	50-321 S
COGGIN, C. L.	7908240362*	50-321 S
COGGIN, C. I.	7908240424*	50-321 S
COGGIN, C. L.	7908240480*	50-366 S
COGGIN, C. L.	7908240486*	50-321 S
COGGIN, C. L.	7908290409*	50-321 S
COGGIN, C. L.	7908310316*	50-366 S
COGGIN, C. L.	7908310406*	50-321 S
COHEN, M. D.	7908170077	FOIA
COHEN, M. D.	7908140640	RES
COHEN, R. C.	7908170346*	50-329 Q
COHEN, I.	7908170093*	70-1143
COHN, W. C.	7908240505*	50-155 Q
COLE, R.	7908090653	50-312 T
COLEMAN, E.	7908200091*	50-280 H
COLEMAN, A. C.	7908220443	50-272 A
COLEMAN, A. C.	7908220458	50-272 A
COLEMAN, A. C.	7908150453	FOIA
COLEMAN, A. C.	7908070406	50-311 Q
COLEMAN, A. C.	7908300783	50-277 P
COLLINS, H. E.	7908280185*	FOIA
COLLINS, H. E.	7908280234*	FOIA
COLLINS, H. E.	7908280229*	FOIA
COLLINS, H. E.	7908280252*	FOIA
COLLINS, H. E.	7908280240*	FOIA
COLLINS, H. E.	7908280260*	FOIA
COLLINS, H. E.	7908280218*	FOIA
COLLINS, H. E.	7908280222*	FOIA
COLLINS, H. E.	7908280271*	FOIA
COLLINS, W. J.	7908090079*	50-331 S
COLLINS, D. M.	7908290714	50-320 T
COLLINS, D. M.	7908290645	50-320 T
COLLINS, D. M.	7908300052	50-320 T
COLLINS, D. M.	7908290574	50-320 T
COLLINS, D. M.	7908290688	50-320 T
COLLINS, D. M.	7908290160	50-320 T
COLLINS, D. M.	7908290324	50-320 T
COLLINS, D. M.	7908280786	50-320 T
COLLINS, P. F.	7908070060	50-131 P
COLLINS, P. F.	7908230167	50-27 P
COLLINS, P. F.	7908230050	50-280 P
COLLINS, J. T.	7908070481	50-320 P
COLLINS, J. T.	7908150668	50-320 P
COLLINS, J. T.	7908240154	50-320 Q
COLMAR, R.	7908010374	TOPREP
COLOMBO, R. W.	7908140482*	50-312 R
COLOMBO, R. W.	7908100337*	50-312 S
COLOMBO, R. W.	7908100482*	50-312 S
COLOMBO, R. W.	7908200372*	50-312 S
COLOMBO, P.	7908070773	NUREG
COMBS, R.	7908240483	71-342
COMBS, R.	7908240484*	71-342
CONLON, T. E.	7908300149*	50-491 Q
CONLON, T. E.	7908270300*	50-369 Q
CONLON, T. E.	7908300583*	50-400 Q
CONLON, T. E.	7908010721*	50-281 Q
CONLON, T. E.	7908020197*	50-390 Q
CONLON, T. E.	7908280138*	50-390 Q
CONLON, T. E.	7908150302*	50-369 Q
CONLON, T. E.	7908240096*	50-395 Q
CONLON, T. E.	7908270262*	50-424 Q
CONLON, T. E.	7908240144*	50-390 Q
CONLON, T. E.	7908300487*	50-491 Q
CONN, W. C.	7908090007*	50-354 Q
CONNELL, P.	7908030049	XPORTLIC
CONNELL, L. G.	7908090490	71-234
CONNER, T. B.	7908030021	50-358 Q
CONNER, T. B.	7908030556	27-39
CONNER, T. B.	7908030543	27-39
CONNER, T. B.	7908030552*	27-39
CONNER, T. B.	7908030579	27-39
CONNELL, C.	7908140516*	50-286 R
CONNER, E. L.	7908140294	50-285 P
CONNER, E. L.	7908100379	50-317 P
CONNER, E. L.	7908100592	50-317 F
CONNER, E. L.	7908170230	50-317 F
CONNOR, E. J.	7908030146	50-317 F
CONRAD, R. W.	7908230257*	50-320 P
CONTE, R. J.	7908200268*	50-311 Q
CONTI, P. L.	7908290511	50-201 J
CONWAY, R. J.	7908060047	FOIA
CONWAY, W. F.	7908060440	50-271 S
CONWAY, W. F.	7908060444*	50-271 S
CONWAY, W. F.	7908140648	50-271 S
CONWAY, W. F.	7908140658*	50-271 S
CONWAY, W. F.	7908210414	50-271 S
CONWAY, W. F.	7908210417*	50-271 S
CONWAY, W. F.	7908280604	50-271 S
CONWAY, W. E.	7908280616*	50-271 S
CONWAY, J. T.	7908090609	70-1510
COOK, B. A.	7908140128	NUREG
COOK, R. J.	7908150627*	50-329 Q
COOLEY, W. J.	7908170129*	70-984
COOLEY, W. J.	7908030223*	70-754
COOLEY, W. J.	7908210044*	QA999
COONEY, M. J.	7908290455*	50-277 S
COONEY, M. J.	7907240386	50-278 S
COONEY, M. J.	7908010536	50-277 S
COONEY, M. J.	7908010546*	50-277 S
COONEY, M. J.	7908020465	50-277 S
COONEY, M. J.	7908020469*	50-277 S
COONEY, M. J.	7908100484	50-278 S
COONEY, M. J.	7908100492	50-277 S
COONEY, M. J.	7908150506	50-277 S
COONEY, M. J.	7908150511*	50-277 S
COONEY, M. J.	7908150600	50-277 S
COONEY, M. J.	7908160447	50-277 R
COONEY, M. J.	7908210531	50-278 S
COONEY, M. J.	7908290444	50-277 S
COOPER, S. H.	7908170394	50-387 D
COOPER, J.	7908030408*	50-302 S
COOPER, J.	7908060514*	50-302 S
COOPER, J.	7908100351*	50-302 S
COOPER, J.	7908210363*	50-302 S
COOPER, J.	7908230548*	50-302 S
COOPER, J.	7908270450*	50-302 S
COOPER, J.	7908290457*	50-302 S
COOPER, J.	7908310309*	50-302 S
COOPER, J.	7908310481*	50-302 S
COOPER, J.	7908280699*	50-302 S
COOPERSTEIN, R.	7908160102	40-8714
COOPERSTEIN, R.	7908090348	40-8693
COOPERSTEIN, R.	7908140187*	40-8693
COPELAND, J. G.	7908080075	50-466 Q
COPELAND, J. G.	7908080079	50-466 Q
COPELAND, J. G.	7908060092	50-466 Q
CORBETT, J. S.	7908020117	71-6144
CORBETT, J. S.	7908140475	71-9111
CORBETT, J. S.	7908150204	71-9081
CORBETT, J. S.	7908140146	71-9081
CORBETT, J. S.	7908150215*	71-9081
CORBETT, J. S.	7908170181	27-47
CORBETT, J. S.	7908290607	71-6601
CORCORAN, J. R.	7908030385*	50-220 F

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CORDARO, R.	7908300533	50-599 Q
CORDOVA, G. E.	7908210128	50-320 H
CORNELL, E. K.	7908230351	50-320 H
CORREA, C.	7908140618	50-89 J
CORRY, A. F.	7908130443	50-471 A
CORTE, E. A.	7908010568	TOPREP
CORYELL, G. P.	7908210148*	70-143
CORYELL, G. P.	7908130399*	50-332 Q
COSTELLO, G. J.	7908160352*	50-280 R
COSTELLO, J. R.	7908130490*	GA999
COSTELLO, J. R.	7908080012*	GA999
COTA, P. C.	7908160064	50-382 A
COTTLE, W.	7908240205*	50-369 Q
COTTLE, W.	7908240316*	50-327 Q
COUGHLIN, L.	7907260305*	50-320 U
COUGHLIN, J.	7908060180*	50-456 Q
COUGHLIN, J.	7908060189*	50-456 Q
COUGHLIN, J.	7908080546	50-546 Q
COUGHLIN, J.	7908080514	50-546 Q
COUGHLIN, J.	7908290304	50-546 Q
COUGHLIN, J.	7908280565*	50-546 Q
COUGHLIN, J.	7908200291	50-546 A
COUGHLIN, J.	7908150445	50-546 Q
COUNCIL, W. Q.	7908160446	50-245 P
COUNSIL, W. Q.	7908060477	50-213 Q
COUNSIL, W. Q.	7908080343	50-213 Q
COUNSIL, W. Q.	7908010529	50-213 P
COUNSIL, W. Q.	7908070542	50-213 P
COUNSIL, W. Q.	7908240458	50-213 P
COUNSIL, W. Q.	7908020083*	50-245 Q
COUNSIL, W. Q.	7908130046	50-245 Q
COUNSIL, W. A.	7908210589	50-213 P
COUNSIL, W. Q.	7908310382	50-245 Q
COUNSIL, W. Q.	7908020590	50-423 Q
COUNSIL, W. Q.	7908030196	50-245 Q
COUNSIL, W. Q.	7908080677	50-336 Q
COUNSIL, W. Q.	7908220613	50-213 Q
COUNSIL, W. Q.	7908160575	50-423 Q
COUNSIL, W. Q.	7908200253	50-213 Q
COUNSIL, W. Q.	7908170365	50-336 Q
COUNSIL, W. Q.	7908270525	50-245 Q
COUNSIL, W. Q.	7908080476	50-213 F
COUNSIL, W. Q.	7908100263	50-423 A
COUNSIL, W. Q.	7908160428	50-336 P
COUNSIL, W. Q.	7908140720	50-336 P
COUNSIL, W. Q.	7908200369	50-336 P
COUNSIL, W. Q.	7908210579	50-336 P
COUNSIL, W. Q.	7908210401	50-213 F
COUNSIL, W. Q.	7908280568	50-245 P
COUNSIL, W. Q.	7908290597	50-336 P
COUNSIL, W. Q.	7908300642	50-336 P
COUNSIL, W. Q.	7908310400	50-336 P
COUNSIL, W. Q.	7908310502	50-336 P
COURCHAINE, R. J.	7908300665	50-341 A
COURTNEY, J. C.	7908150387	PRM
COWAN, R. L.	7908010576*	TOPREP
COWGILL, C.	7908010712*	50-219 Q
COYNE, M. J.	7908080661	XPORTLIC
CRAIG, R. W.	7908280226	PROJ
CRAIG, P. A.	7908170531*	70-572
CRAIG, P. A.	7908170525*	70-572
CRAMER, S. N.	7908200001	PROJ
CRANDALL, J. L.	7908300366*	WASTE MGT
CRANE, P. A.	7908090227*	50-275 S
CRANE, P. A.	7908130421	50-275 Q
CRANE, P. A.	7908280427	50-133 Q
CRANE, P. A.	7908150241*	50-275 Q
CRANE, P. A.	7908170526*	50-275 S
CRANE, P. A.	7908150520	50-133 P
CRANE, P. A.	7908160018	50-275 Q
CRANE, P. A.	7908010462	50-133 P
CRANE, P. A.	7908100175	50-133 Q
CRANE, P. A.	7908220428	50-275 F
CRANE, P. A.	7908230612	50-275 K
CRANE, P. A.	7908300713	50-133 P
CREITZ, W. M.	7908140515	50-320 H
CRERAR, D. A.	7908170280*	50-10 P
CRESWELL, J. S.	7908090263*	50-346 P
CRESWELL, J. S.	7908290532	50-320 T
CRESWELL, J. S.	7908290465	50-320 T
CRESWELL, J. S.	7908300067	50-320 T
CRESWELL, J. S.	7908300202	50-320 T
CRESWELL, J. S.	7908280720	50-320 T
CRESWELL, J. S.	7908290425	50-320 T
CRESWELL, J. S.	7908290441	50-320 T
CRESWELL, J. S.	7908280705	50-320 T
CRESWELL, J. S.	7908280709	50-320 T
CRESWELL, J. S.	7908280715	50-320 T
CRESWELL, J. S.	7908280727	50-320 T
CRESWELL, J. S.	7908280756	50-320 T
CRESWELL, J. S.	7908290485	50-320 T
CRESWELL, J. S.	7908290640	50-320 T
CRESWELL, J. S.	7908290431	50-320 T
CRESWELL, J. S.	7908290491	50-320 T
CRESWELL, J. S.	7908290519	50-320 T
CRESWELL, J. S.	7908290539	50-320 T
CRESWELL, J. S.	7908290067	50-320 T
CRESWELL, J. S.	7908290083	50-320 T
CRESWELL, J. S.	7908290130	50-320 T
CRESWELL, J. S.	7908290186	50-320 T
CRESWELL, J. S.	7908300150	50-320 T
CRESWELL, J. S.	7908290210	50-320 T
CRESWELL, J. S.	7908290256	50-320 T
CRESWELL, J. S.	7908290273	50-320 T
CRESWELL, J. S.	7908280844	50-320 T
CRESWELL, J. S.	7908280856	50-320 T
CRESWELL, J. S.	7908290048	50-320 T
CREWS, E. H.	7908080099	50-395 Q
CREWS, E. H.	7908310111	50-395 Q
CREWS, E. H.	7908230234	50-395 Q
CREWS, E. H.	7908010355	50-395 A
CREWS, E. H.	7908210359	50-395 D
CREWS, E. H.	7908230391	50-395 F
CREWS, E. H.	7908280638	50-395 P
CREWS, J. L.	7908090692*	50-344 Q
CREWS, J. L.	7908130513*	50-312 P
CREWS, J. L.	7908090690	50-344 Q
CREWS, J. L.	7908170117	50-312 Q
CREWS, J. L.	7908150178	50-361 Q
CREWS, J. L.	7908150431	50-326 Q
CREWS, J. L.	7908270006	50-275 Q
CROCKER, H. W.	7908220034	70-364
CROCKER, H. W.	7908230565*	50-320 Q
CROCKER, H. W.	7908270069*	50-271 Q
CROMER, S.	7908220214	ACRS
CROSBY, J.	7908090096	FOIA
CROSSMAN, W. A.	7908010060*	50-482 Q
CROSSMAN, W. A.	7908010043*	50-458 Q
CROSSMAN, W. A.	7908070130*	50-445 Q
CROSSMAN, W. A.	7908100217*	50-382 Q
CROSSMAN, W. A.	7908100235*	50-556 Q
CROSSMAN, W. A.	7908270123*	50-445 Q
CROSSMAN, W. A.	7908230666*	50-445 Q
CROSSMAN, W. A.	7908310116*	50-445 Q
CROW, W. T.	7908170638	70-984
CROW, W. T.	7908200069	70-1257
CROW, T. W.	7908230345	NUREG
CROW, W. T.	7908230139*	50-358 Q
CROW, W. T.	7908230129*	50-358 Q
CROW, W. T.	7908060476	70-143
CROW, W. T.	7908150163	70-2219
CROW, W. T.	7908060470	70-1319
CROW, W. T.	7908200418	70-1257
CROW, W. T.	7908210021	70-824
CROW, W. T.	7908030212	70-1201
CROW, W. T.	7908290027	70-310
CROW, W. T.	7908240468	50-390 A
CROW, W. T.	7908210088	70-1319
CROW, W. T.	7908210041	40-8027
CROWLEY, C. J.	7908210240	RES
CROWLEY, C. J.	7908010352	RES
CROWLEY, C. J.	7908020135	RES
CROWLEY, B. R.	7908160341*	50-395 Q
CROWLEY, B. R.	7908240366*	50-348 Q
CROWLEY, B. R.	7908230662*	50-261 Q
CROWLEY, B. R.	7908150345*	50-438 Q
CRUTCHFIELD, C. H.	7908200408*	COMMISSION
CRUTCHFIELD, D. M.	7908300594	XPORTLIC
CUDLIN, R. L.	7907300161	REVIEW GRP
CULLINGFORD, M. C.	7908220096*	FOIA
CULP, W. G.	7908090318	PROJ
CUNNINGHAM, R. G.	7908310350	50-5 F
CUNNINGHAM, G. E.	7908140066	70-754
CUNNINGHAM, G. E.	7908170601	70-1968
CUNNINGHAM, G. E.	7908210535	70-754
CUNNINGHAM, G. E.	7908220671	70-754
CUNNINGHAM, G. E.	7908230582	70-754
CUNNINGHAM, G. E.	7908240060	71-5274
CUNNINGHAM, M. E.	7908230692	NUREG
CUNNINGHAM, G. H.	7908080188	50-454 Q
CUNNINGHAM, G. H.	7908150740	50-320 Q
CUNNINGHAM, G. H.	7908300268	50-367 Q
CUNNINGHAM, A. L.	7908100386*	50-413 Q
CUNNINGHAM, A. L.	7908290221*	50-302 Q
CUNNINGHAM, A. L.	7908170283*	50-353 Q
CUNNINGHAM, R. E.	7908140416	NUREG
CUNNINGHAM, R. E.	7908060140	70-1151
CUNNINGHAM, R. E.	7908010613	70-1510
CUNNINGHAM, R. E.	7908240027	71-9118
CUNNINGHAM, R. E.	7908280762	71-9095
CUNNINGHAM, R. E.	7908280843	71-9112
CUNNINGHAM, R. E.	7908280870	71-9104
CUNNINGHAM, R. E.	7908220088	70-2623
CUNNINGHAM, R. E.	7908080291	71-9114
CUPP, E. A.	7908020581	50-296 Q
CURNANE, R. A.	7908080009*	GA999
CURRAN, J. M.	7908140487	50-206 R
CURRY, P. T.	7908140110*	71-255
CURTIS, D.	7908290489	50-546 Q
CURTIS, F. D.	7908240045	71-336
CURTIS, F. D.	7908240048*	71-336
CURTIS, N. W.	7908140753*	50-387 S
CURTIS, N. W.	7908030340	50-387 A
CURTIS, N. W.	7908070288	50-387 Q
CURTIS, N. W.	7908070462	50-387 Q
CURTIS, N. W.	7908070682*	50-387 K
CURTIS, N. W.	7908290660	50-387 Q
CURTIS, N. W.	7908060256	50-387 A
CURTIS, N. W.	7908070668	50-387 K
CURTIS, N. W.	7908150655	50-387 A
CURTIS, N. W.	7908140430	50-387 S
CURTIS, N. W.	7908140630	50-387 A
CURTIS, N. W.	7908280670	50-387 A
CURTIS, N. W.	7908280032	50-387 F
CURTIS, D. B.	7908080358*	PROJ
CURTIS, J. R.	7908170472*	50-89 Q
CUSTARD, C.	7908170603	PROJ
CUSTARD, C.	7908300676	50-568 D
CUTCHIN, J. M.	7908020574	50-387 Q
CUTCHIN, J. M.	7908270329	50-387 Q
CUTCHIN, J. M.	7908300128	50-387 Q
CUTLER, R. C.	7908230266*	50-320 P
CYBULSKIS, P.	7908080557	RES
CYBULSKIS, P.	7908160188*	RES
CYPHERT, S. B.	7908130176	50-445 M
CYPHERT, S. B.	7908130215	50-445 M
CYPHERT, S. B.	7908130240	50-445 M
CYPHERT, S. B.	7908130246	50-445 M
D'AMORE, M.	7908150587*	70-1151
D'AMORE, M.	7908170623*	70-1151
DAIL, L. C.	7908100383*	50-413 Q
DAIL, L. C.	7908230280	PR
DAIL, L. C.	7908240603	50-491 Q
DAIL, L. C.	7908080203	50-413 Q
DAIL, L. C.	7908160371	50-491 Q
DAIL, L. C.	7908230230	50-413 Q
DAIL, L. C.	7908230648	50-488 Q
DAIL, L. C.	7908060005	50-413 Q
DAIL, L. C.	7908210114	50-488 Q
DAIL, L. C.	7908140671	50-413 S
DAIL, L. C.	7909300119*	50-491 Q
DAIL, L. C.	7908060220	50-369 A
DAIL, L. C.	7908270306	50-413 Q
DAIL, L. C.	7908300470	50-491 Q
DAIL, L. C.	7908130446	50-413 A
DAIL, L. C.	7908150462	50-413 A
DAIL, L. C.	7908280621	50-413 S
DALE, L. F.	7908020517	50-416 Q
DALE, L. F.	7908020533	50-416 Q
DALE, L. F.	7908030071	50-416 Q
DALE, L. F.	7908030596*	50-416 Q
DALE, L. F.	7908160557	50-416 Q
DALE, L. F.	7908140634	50-416 S
DALE, L. F.	7908290586	50-416 Q
DALE, L. F.	7908140424	50-416 A
DALE, L. F.	7908080391	50-416 A
DALE, L. F.	7908140704	50-416 P
DALE, L. F.	7908290445	50-416 S
DALE, L. F.	7908280687	50-416 A
DALEY, R. L.	7908020123	71-9033
DALLINGER, J. F.	7908230225	71-6717
DALTROFF, S. L.	7908080628	50-277 Q
DALTROFF, S. L.	7908010432	50-277 P
DALTROFF, S. L.	7908070698	50-277 Q
DALTROFF, S. L.	7908160565	50-277 Q
DALTROFF, S. L.	7908200002	50-277 Q
DALTROFF, S. L.	7908230135	50-277 Q
DALTROFF, S. L.	7908130277	50-277 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DALTROFF, S. L.	7908150581	50-277 P
DALTROFF, S. L.	7908240405	50-277 P
DALTROFF, S.	7908240470*	50-277 P
DALTROFF, S.	7908290571*	50-277 P
DANCE, H. C.	7908300100*	50-302 Q
DANCE, H. C.	7908170147*	50-259 Q
DANCE, H. C.	7908060002*	50-259 Q
DANCE, H. C.	7908240205*	50-369 Q
DANCE, H. C.	7908230578*	50-259 Q
DANIELSON, D. H.	7908240284*	50-281 Q
DANIELSON, D. H.	7908100127*	50-305 Q
DANIELSON, D. H.	7908100356*	50 305 Q
DANIELS, F. T.	7908160130*	50-282 Q
DANIELSON, D. H.	7908290529*	50-315 Q
DANIELSON, D. H.	7908240202*	50-281 Q
DANIELSON, D. H.	7908030587*	50-295 Q
DANSON, J. M.	7908090333*	40-6659
DARMITZEL, R. W.	7908230580	50-73 S
DARMITZEL, R. W.	7908310354	50-70 F
DARMITZEL, R. W.	7908240475	50-70 P
DARMITZEL, R. W.	7908280633	50-70 P
DAUGHERTY, T. M.	7908300110	50-338 Q
DAVIDSON, D. R.	7908100170	50-440 Q
DAVIDSON, D. R.	7908080260	50-440 Q
DAVIDSON, D. R.	7908090591	50-440 Q
DAVIDSON, D. R.	7908060329	50-440 S
DAVIDSON, D. R.	7908230113*	50-440 Q
DAVIDSON, D. R.	7908010348	50-440 S
DAVIDSON, D. R.	7908010510	50-440 S
DAVIS, W. K.	7908230443	TOPREP
DAVIS, J. F.	7908300421	50-18 P
DAVIS, R. V.	7908140521*	FOIA
DAVIS, S. M.	7908080457*	50-318 S
DAVIS, S. M.	7908080512*	50-317 S
DAVIS, J. G.	7908030568*	27-39
DAVIS, J. G.	7907020065	50-287 Q
DAVIS, J. G.	7908130401	SECY
DAVIS, J. G.	7906210442	50-320 P
DAVIS, A. B.	7908230601*	50-320 Q
DAVIS, A. B.	7908150364	50-254 Q
DAVIS, A. B.	7908020175	70-8
DAVIS, A. B.	7908010072	50-155 Q
DAVIS, A. B.	7908080680	50-295 Q
DAVIS, A. B.	7908150280	50-315 Q
DAVIS, A. B.	7908210122	50-409 Q
DAVIS, A. B.	7908280503	50-373 Q
DAVIS, A. B.	7908280118	70-572
DAVIS, A. B.	7908100155	50-155 Q
DAWSON, M. H.	7908090285	50-471 Q
DAWSON, D. M.	7908140131	70-1308
DAWSON, D. M.	7908210065	70-1308
DAWSON, D. M.	7908240338	70-1308
DAWSON, D. M.	7908140060	70-1308
DAY, D.	7908200139	50-466 Q
DAY, M.	7908150494*	50-320 Q
DE BREMAECKER, J.	7908170348	50-466 Q
DEAKYNE, K.	7908090573*	50-346 S
DEALE, V. B.	7908170344*	COMMISSION
DEALE, V. B.	7908090300	50-522 Q
DEALE, V. B.	7908090309	50-338 Q
DEALE, V. B.	7908220011	50-522 Q
DEALE, V. B.	7908300014	50-522 Q
DEALE, V. B.	7908070283	50-522 T
DEALE, V. B.	7908060056	50-522 T
DEALE, V. B.	7908070277	50-522 T
DEALE, V. B.	7908060086	50-522 T
DEALE, V. B.	7908060037	50-522 T
DEALE, V. B.	7908030272	50-522 T
DEALE, V. B.	7908090644	50-522 T
DEALE, V. B.	7908100401	50-522 T
DEALE, V. B.	7908090619	50-522 T
DEARIEN, J. A.	7908080537	RES
DEARIEN, J. A.	7908230647	50-282 P
DEARIEN, J. A.	7908200326	50-266 P
DEARTH, A. E.	7908010627	40-3453
DEEG, F. H.	7908220364	50-333 J
DEESE, D. A.	7908280226	PROJ
DELANEY, J. C.	7908230157*	50-358 Q
DELANEY, J. C.	7908230144*	50-358 Q
DELANEY, J. C.	7908230134*	50-358 Q
DELGEORGE, L. O.	7908090558	50-373 I
DELGEORGE, L. O.	7908090344	50-373 A
DELGEORGE, L. O.	7908210571	50-358 A
DELISLE, R.	7908150168	71-137
DELYNKO, R.	7908140110*	71-255
DELYNKO, R.	7908140103	71-255
DEMLOW, D. J.	7908210210	50-320 H
DEMLOW, D. J.	7908130317*	50-329 A
DEMLOW, D. J.	7908130311*	50-329 A
DEMO-RYBUS, P.	7908170625	PROJ
DENISE, R. P.	7904270035	50-320 P
DENNING, R. S.	7908210186	50-320 A
DENNING, R. S.	7908210193*	50-320 A
DENNING, R. S.	7908080557	RES
DENNING, R. S.	7908160172	RES
DENNING, R. S.	7908160188*	RES
DENTON, H. R.	7908070678	50-317 S
DENTON, H. R.	7908230386*	50-317 S
DENTON, H. R.	7908230449	50-320 H
DENTON, H. R.	7908170271*	50-10 P
DENTON, H. R.	7908100055	50-280 H
DENTON, H. R.	7908200330	SECY
DENTON, H. R.	7908200012	50-280 H
DENTON, H. R.	7908200063*	50-280 H
DENTON, H. R.	7908200070*	50-280 H
DENTON, H. R.	7908200078*	50-280 H
DENTON, H. R.	7908200087*	50-280 H
DENTON, H. R.	7908030436*	50-320 P
DENTON, H. R.	7908140498	50-10 P
DENTON, H. R.	7907120284	50-280 Q
DENTON, H. R.	7908210427	50-320 H
DENTON, H. R.	7908210481	50-320 H
DENTON, H. R.	7908200343	SECY
DENTON, H. R.	7908020522	50-346 Q
DENTON, H. R.	7908160267*	50-346 P
DENTON, H. R.	7908160284*	50-346 P
DENTON, H. R.	7908160291*	50-346 P
DENTON, H. R.	7908020232	50-280 U
DENTON, H. R.	7908160339	50-309 F
DENTON, H. R.	7908200389	SECY
DENTON, H. R.	7908010261	50-311 A
DENTON, H. R.	7908030600	50-339 A
DENTON, H. R.	7908020376	50-275 Q
DENTON, H. R.	7908020550	50-271 Q
DENTON, H. R.	7908210223	50-269 H
DENTON, H. R.	7908010273	50-309 H
DENTON, H. R.	7908010105	50-320 U
DENTON, H. R.	7908020203*	50-312 T
DENTON, H. R.	7908030108	50-409 Q
DENTON, H. R.	7908090647	50-312 P
DENTON, H. R.	7908030562	NUREG
DENTON, H. R.	7908160240	50-346 M
DENTON, H. R.	7908160257*	50-346 M
DENTON, H. R.	7908160264*	50-346 M
DENTON, H. R.	7908160272*	50-346 M
DENTON, H. R.	7908060026	NUREG
DENTON, H. R.	7908090409	50-309 Q
DENTON, H. R.	7908090417*	50-309 Q
DENTON, H. R.	7908090529	50-331 Q
DENTON, H. R.	7908090533*	50-331 Q
DENTON, H. R.	7908220069	COMMISSION
DENTON, H. R.	7908150142	50-346 P
DENTON, H. R.	7908150146*	50-346 P
DENTON, H. R.	7908160225	50-346 P
DENTON, H. R.	7908160235*	50-346 P
DENTON, H. R.	7908020339	50-346 P
DENTON, H. R.	7908130333	50-320 P
DENTON, H. R.	7908150492	50-320 Q
DENTON, H. R.	7908230001	50-320 P
DENTON, H. R.	7908020384	50-311 H
DENTON, H. R.	7908090660	50-346 P
DENTON, H. R.	7908200391	SECY
DENTON, H. R.	7908290127	50-302 Q
DENTON, H. R.	7908030589	50-309 H
DENTON, H. R.	7908080232	50-322 A
DENTON, H. R.	7908090503	50-329 A
DENTON, H. R.	7908100527*	10CFR
DENTON, H. R.	7908200393	SECY
DENTON, H. R.	7908280867	SECY
DENTON, H. R.	7908150477	50-320 Q
DENTON, H. R.	7908150488*	50-320 Q
DENTON, H. R.	7908150764	50-320 Q
DENTON, H. R.	7908220228	50-346 P
DENTON, H. R.	7908150755	50-320 P
DENTON, H. R.	7908080142	50-311 A
DENTON, H. R.	7908130309	50-329 A
DENTON, H. R.	7908080623	50-329 A
DENTON, H. R.	7908150470	50-320 P
DENTON, H. R.	7908170266*	50-346 M
DENTON, H. R.	7908250239	50-312 A
DENTON, H. R.	7908150746	50-320 H
DENTON, H. R.	7908150195	50-295 H
DENTON, H. R.	7908150750	50-289 Q
DENTON, H. R.	7908150752	50-289 Q
DENTON, H. R.	7908170216	50-289 P
DENTON, H. R.	7908300154	50-206 S
DENTON, H. R.	7908150273	50-275 H
DENTON, H. R.	7908150405	50-309 P
DENTON, H. R.	7908150763	50-320 H
DENTON, H. R.	7908300253	50-312 H
DENTON, H. R.	7908170636	50-549 A
DENTON, H. R.	7908160111	50-3 Q
DENTON, H. R.	7908200129	50-463 Q
DENTON, H. R.	7908230242	50-3 H
DENTON, H. R.	7908150084	50-155 H
DENTON, H. R.	7908150449	50-320 H
DENTON, H. R.	7908210022	50-10 P
DENTON, H. R.	7908170219	50-280 Q
DENTON, H. R.	7908270098	50-10 D
DENTON, H. R.	7908170351	50-445 H
DENTON, H. R.	7908240175	50-334 P
DENTON, H. R.	7908240182*	50-334 P
DENTON, H. R.	7908170205	50-304 H
DENTON, H. R.	7908220405	PRM
DENTON, H. R.	7908280457	50-295 H
DENTON, H. R.	7908200354	50-522 H
DENTON, H. R.	7908230348	50-334 Q
DENTON, H. R.	7908220212	50-320 P
DENTON, H. R.	7908060197	NUREG
DEROY, J. P.	7908060311*	50-213 S
DEVINE	7908010287*	50-516 Q
DEVINE, H. F.	7908280603	50-409 J
DEVINCENTIS, J.	7908070705	50-443 Q
DEWEASE, J. G.	7908030378	50-259 S
DEWITT, R. B.	7908030597	50-255 Q
DEWITT, R. B.	7908030430*	50-255 P
DEYOUNG, R. C.	7908010687*	10CFR
DIAMOND, D. J.	7908010591	RES
DICKERSON, M. W.	7908300069*	50-267 Q
DICKINSON, I. P.	7908160114*	50-3 Q
DICKSON, H. W.	7908140622	RES
DIECHAMP, H.	7908280003	50-320 P
DIENHART, A. V.	7908010518	50-484 A
DIETZ, G. R.	7908070843*	71-9
DIETZ, G. R.	7908070838	71-9
DIGGS, R. M.	7908080438	50-269 P
DIGGS, R. M.	7908060146	50-269 F
DIGGS, R. M.	7908060154	50-331 F
DIGGS, R. M.	7908060155	50-29 F
DIGGS, R. M.	7908060162	50-317 F
DIGGS, R. M.	7908060163	50-312 F
DIGGS, R. M.	7908060168	50-3 F
DIGGS, R. M.	7908130155	50-313 F
DIGGS, R. M.	7908130159	50-10 F
DIGGS, R. M.	7908130162	50-254 F
DIGGS, R. M.	7908130167	50-155 F
DIGGS, R. M.	7908130180	50-261 F
DIGGS, R. M.	7908130185	50-250 F
DIGGS, R. M.	7908130189	50-321 F
DIGGS, R. M.	7908130192	50-315 F
DIGGS, R. M.	7908130195	50-289 F
DIGGS, R. M.	7908130196	50-245 F
DIGGS, R. M.	7908130200	50-263 F
DIGGS, R. M.	7908130202	50-286 F
DIGGS, R. M.	7908130206	50-206 F
DIGGS, R. M.	7908130208	50-259 F
DIGGS, R. M.	7908130218	50-280 F
DIGGS, R. M.	7908130222	50-266 F
DIGGS, R. M.	7908270203	50-244 F
DIGGS, R. M.	7908270213	50-213 F
DIGGS, R. M.	7908270215	50-409 F
DIGGS, R. M.	7908270221	50-285 F
DIGGS, R. M.	7908270237	50-334 F
DIGGS, R. M.	7908270255	50-302 F
DIGGS, R. M.	7908270260	50-298 P
DIGGS, R. M.	7908270264	50-305 F
DIGGS, R. M.	7908270295	50-346 F
DIGGS, R. M.	7908270298	50-293 F
DIGGS, R. M.	7908160033	50-259 P
DIGGS, R. M.	7908300349	50-245 P
DIIANNI, D. C.	7908150717	50-289 P
DILLON, R. T.	7908030034	NUREG
DILLON, R. T.	7908030044	NUREG
DIMEGLIO, A. F.	7908310536*	50-193 F
DIMEGLIO, A. F.	7908310533	50-193 F
DINGELL, J. D.	7907310621*	COMMISSION
DIPIAZZA, R. P.	7908290664*	FOIA
DIPIAZZA, R. P.	7908090493	71-6400

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DIPIAZZA, R. P.	7908130531	70-1151
DIPIAZZA, R. P.	7908130542	70-1151
DIPIAZZA, R. P.	7908140139	70-1143
DIPIAZZA, R. P.	7908020113	71-9009
DIPIAZZA, R. P.	7908150048	71-6272
DIPIAZZA, R. P.	7908160571	70-1143
DIPIAZZA, R. P.	7908210594	70-1143
DIPIAZZA, R. P.	7908140594	71-5450
DIRCKS, W. J.	7908230184*	SECY
DIRCKS, W. J.	7909080650*	10CFR
DIRCKS, W. J.	7908010682*	10CFR
DIRCKS, W. J.	7908200375*	FOIA
DIRCKS, W. J.	7908150072*	50-201 U
DIRCKS, W. J.	7908240370*	SECY
DIRCKS, W. J.	7909070487*	50-320 P
DIRCKS, W. J.	7908200384*	FOIA
DIRCKS, W. J.	7908130179	70-754
DIRCKS, W. J.	7908130186*	70-754
DIRCKS, W. J.	7908130190*	70-754
DIRCKS, W. J.	7908130197*	70-754
DIRCKS, W. J.	7908130203*	70-754
DIRCKS, W. J.	7908150068	50-201 U
DIRCKS, W. J.	7908200382*	FOIA
DIRCKS, W. J.	7908080125	PR
DIRCKS, W. J.	7908210104*	10CFR
DIRCKS, W. J.	7908150128	70-754
DIRCKS, W. J.	7908150136*	70-754
DIRCKS, W. J.	7908230161	70-754
DISE, D. P.	7908030377	50-220 F
DISE, D. P.	7908030500	50-220 P
DISE, D. P.	7908070620	50-220 P
DISE, D. P.	7908130364	50-220 P
DISE, D. P.	7908220381	50-220 P
DISE, D. P.	7908240464	50-220 F
DISE, D. P.	7908310414	50-220 P
DITTO, S. J.	7908210109	ACRS
DIXON, C. B.	7908210236*	50-269 H
DOBBE, C. A.	7908010375	RES
DOCTOR, P. G.	7908240056	NUREG
DODDS, R. T.	7908170114*	50-361 G
DODDS, R. T.	7908200233*	50-275 G
DODDS, R. T.	7908150233*	50-275 G
DODDS, R. T.	7908230061*	50-460 G
DODDS, R. T.	7908150251*	50-361 G
DODDS, R. T.	7908150199*	50-522 G
DODDS, R. T.	7908150212*	50-397 G
DOHERTY, J. F.	7908220614	50-466 G
DOHERTY, J. F.	7908220662*	50-466 G
DOLAN, J. E.	7908160193*	50-315 G
DOLAN, J. E.	7908230138*	50-315 G
DOLAN, J. E.	7908090311	50-316 G
DOLAN, J. E.	7908080376	50-315 G
DOLAN, J. E.	7908080366	50-315 G
DOLAN, J. E.	7908310147	50-315 H
DOLAN, J. E.	7908130403	50-315 G
DOLAN, J. E.	7908170464	50-315 G
DOLAN, J. E.	7908010562	50-315 P
DOLAN, J. E.	7908240518	50-315 G
DOLAN, J. E.	7908060433	50-316 I
DOLAN, J. E.	7908060233	50-315 P
DOLAN, J. E.	7908060241	50-315 H
DOLAN, J. E.	7908060345	50-315 P
DOLAN, J. E.	7908090508	50-315 P
DOLAN, J. E.	7908140558	50-315 P
DOLAN, J. E.	7908200664	50-315 P
DOLAN, J. E.	7908280671*	50-315 P
DOMINGUEZ, G.	7908130375	XPORTLIC
DONALDSON, D. E.	7908230611*	50-320 G
DONALDSON, D. E.	7908230659*	50-320 G
DONALDSON, D. E.	7908290557	50-320 T
DONALDSON, D. E.	7908290714	50-320 T
DONALDSON, D. E.	7908290579	50-320 T
DONALDSON, D. E.	7908290603	50-320 T
DONALDSON, D. E.	7908290724	50-320 T
DONALDSON, D. E.	7908300061	50-320 T
DONALDSON, D. E.	7908300202	50-320 T
DONALDSON, D. E.	7908280645	50-320 T
DONALDSON, D. E.	7908290565	50-320 T
DONALDSON, D. E.	7908290550	50-320 T
DONALDSON, D. E.	7908300216	50-320 T
DONALDSON, D. E.	7908290453	50-320 T
DONALDSON, D. E.	7908280666	50-320 T
DONALDSON, D. E.	7908290633	50-320 T
DONALDSON, D. E.	7908300247	50-320 T
DONALDSON, D. E.	7908290104	50-320 T
DONALDSON, D. E.	7908300229	50-320 T
DONALDSON, D. E.	7908300274	50-320 T
DONALDSON, D. E.	7908290316	50-320 T
DONALDSON, D. E.	7908280797	50-320 T
DONALDSON, D. E.	7908295568	50-320 T
DONAT, T. J.	7908280155*	50-327 Q
DONAT, T. J.	7908280778*	50-327 Q
DONAT, T. J.	7908240316*	50-327 Q
DONOGHUE, D. J.	7908210372*	10CFR
DONOGHUE, D. J.	7908080426*	CONTRACT
DONOGHUE, D. J.	7908090485*	CONTRACT
DONOGHUE, D. J.	7908170507*	10CFR
DOOLEY, L. G.	7908080265	40-2259
DOUGHERTY, J. B.	7908300754	50-338 Q
DOUGHERTY, D. J.	7908030375*	CONTRACT
DOUGHERTY, D. J.	7908030470*	CONTRACT
DOUGHERTY, D. J.	7908230102*	CONTRACT
DOUGHERTY, D. J.	7908170122*	CONTRACT
DOUGHERTY, D. J.	7908030164*	CONTRACT
DOUGHERTY, D. J.	7908030439*	CONTRACT
DOUGHERTY, D. J.	7908160434*	CONTRACT
DOUGHERTY, D. J.	7908170056*	CONTRACT
DOUGHERTY, D. J.	7908170063*	CONTRACT
DOUGHERTY, D. J.	7908170303*	CONTRACT
DOUGHERTY, D. J.	7908290686*	CONTRACT
DOUGHERTY, D. J.	7908100271*	CONTRACT
DOUGHERTY, D. J.	7908090284*	CONTRACT
DOUGHERTY, D. J.	7908090629*	CONTRACT
DOUGHERTY, D. J.	7908100257*	CONTRACT
DOUGHERTY, D. J.	7908230182*	CONTRACT
DOUGHERTY, D. J.	7908230156*	CONTRACT
DOUGHERTY, D. J.	7908230195*	CONTRACT
DOUGHERTY, D. J.	7908220265*	CONTRACT
DOUGLAS, W. R.	7908300533	50-599 Q
DOUGLAS, R. L.	7908030631	PROJ
DOWELL, S. D.	7908270345	50-329 R
DOYLE, M. M.	7908300032	PROJ
DOYLE, J. E.	7908280646*	50-237 S
DRAGONETTE, K. S.	7908140416	NUREG
DRAGONETTE, K. S.	7908080689	27-39
DRAGONETTE, K. S.	7908100358	27-47
DRAGONETTE, K. S.	7908100361*	27-47
DRAKE, J. H.	7908030186*	50-206 P
DRAKE, J. H.	7908030182	50-206 P
DRAZ, Z.	7908210406	50-320 G
DRAZDOWSKI, T. A.	7908210365	50-387 D
DRESSEN, D. R.	7908080355*	PROJ
DRESSEN, D. R.	7908220560	PROJ
DROMERICK, A.	7908160230	50-311 G
DROMERICK, A.	7908030331	50-311 A
DROMERICK, A.	7908080236	50-311 J
DROMERICK, A.	7908230073	50-311 A
DROMERICK, A.	7908270119	50-338 P
DRUCKENMILLER, H.	7908270417	50-502 C
DRYDEN, M. S.	7908310412*	50-335 P
DUBIL, R. H.	7908170533	COMMISSION
DUCKWORTH, J. P.	7908220679	50-201 R
DUCKWORTH, J. P.	7908230653	50-201 R
DUDA, E.	7908140655*	50-220 S
DUFFY, E. L.	7908200317*	FOIA
DUNCAN, R. L.	7908210299*	TOPREP
DUNHAM, R. S.	7908140695*	50-285 Q
DUNN, W. L.	7908170493	PROJ
DUNN, C. N.	7908030251	50-334 Q
DUNN, C. N.	7908130595	50-334 Q
DUNN, C. N.	7908070303	50-334 Q
DUNN, C. N.	7908150718	50-334 Q
DUNN, C. N.	7908170355	50-334 Q
DUNN, C. N.	7908160147	50-334 S
DUNN, C. N.	7908010574	50-334 P
DUNN, C. N.	7908130273	50-334 Q
DUNN, C. N.	7908240587	50-334 Q
DUNN, C. N.	7908060354	50-334 Q
DUNN, C. N.	7908090480	50-334 P
DUNN, C. N.	7908140518	50-334 R
DUNN, C. N.	7908140578	50-334 Q
DUNN, C. N.	7908140839	50-334 P
DUNN, C. N.	7908220007	50-334 F
DUNN, W. L.	7908160435*	50-338 S
DURHAM, N. L.	7908150313	50-466 Q
DURNAN, R.	7908210159	50-574 A
DURR, J. P.	7908170082*	50-333 Q
DUSCHA, J.	7908210168*	COMMISSION
DUTTON, D.	7908160334	50-424 Q
DUTTON, D.	7908290620	50-424 Q
DUTTON, D.	7908060376	50-424 S
DUTTON, D.	7909140719	50-424 S
DUTTON, D.	7908270242*	50-424 Q
DVORAK, A.	7908080288*	50-522 Q
DYER, J. A.	7908200020*	50-335 Q
DYER, J. A.	7908170545*	50-335 Q
EARLY, P. J.	7908160568	50-286 Q
EARLY, P. J.	7908020420	50-286 Q
EARLY, P. J.	7908020422	50-333 F
EARLY, P. J.	7908020435	50-333 P
EARLY, P. J.	7908140564	50-286 Q
EARLY, P. J.	7908150676	50-333 P
EARLY, P. J.	7908170324	50-286 P
EARLY, P. J.	7908210344	50-333 P
EARLY, P. J.	7908200314	50-333 P
EARLY, P. J.	7908230360	50-286 Q
EARLY, P. J.	7908280551	50-286 Q
EARLY, P. J.	7908280601	50-333 P
EARLY, P. J.	7908280700	50-286 P
EARLY, P. J.	7908310564	50-286 P
EARLY, P. J.	7908310568*	50-286 P
EAST, D. J.	7908230275	40-8721
EAST, J.	7908020567*	50-338 Q
EASTVEDT, R. B.	7908080307*	50-522 Q
EBENER, D. R.	7908150227	50-599 Q
EBNETER, S. D.	7908230524*	50-320 Q
EBNETER, S. D.	7908200054*	50-410 Q
ECKERMAN, K. F.	7908030464*	FOIA
ECKHARDT, J. H.	7908090703*	50-361 Q
ECKHARDT, J. H.	7908230061*	50-460 Q
ECKHARDT, J. H.	7908150251*	50-361 Q
ECONOMOS, N.	7908200221*	50-400 Q
ECONOMOS, N.	7908240127*	50-302 Q
ECONOMOS, N.	7908240311*	50-269 Q
EDGAR, G. L.	7908080061	50-70 Q
EDGAR, E. C.	7908140800*	50-244 S
EDLOW, J.	7908010607	XPORTLIC
EDLOW, S.	7908230445	PRM
EDMUNDS, J. T.	7908170496*	50-280 H
EDWARDS, H. S.	7908080205*	ORG
EGEMEIER, S. J.	7908170639	50-596 Q
EGGER, E. R.	7908280636*	50-333 Q
EHERTS, R. F.	7908230530*	50-317 S
EHERTS, R. F.	7908100491*	50-317 S
EHERTS, R. F.	7908230366*	50-317 S
EHRENSPERGER, W.	7908030031	50-424 Q
EILPERIN, S. F.	7908200350*	FOIA
EILPERIN, S. F.	7908030142*	10CFR
EILPERIN, S. F.	7908080122*	50-338 Q
EISENHUT, D. G.	7908230041	TOPREP
EISENHUT, D. G.	7908030256*	50-213 P
EISENHUT, D. G.	7908030301	50-3 P
EISENHUT, D. G.	7908030420	REGGD
EISENHUT, D. G.	7908080609	50-338 P
EISENHUT, D. G.	7908170166	ORG
EISENHUT, D. G.	7908010589	NUREG
EISENHUT, D. G.	7908130269	TOPREP
EISENHUT, D. G.	7908030310*	50-302 P
EISENHUT, D. G.	7908140267	50-313 S
EISENHUT, D. G.	7908060176	50-271 P
EISENHUT, D. G.	7908060182*	50-271 P
EISENHUT, D. G.	7908140093	50-317 P
EISENHUT, D. G.	7908030292	50-10 P
EISENHUT, D. G.	7908160040	50-327 A
EISENHUT, D. G.	7908020025	50-10 P
EISENHUT, D. G.	7908170265	50-10 P
EISENHUT, D. G.	7908280242	50-10 P
EISENHUT, D. G.	7908080262	REGGD
EISENHUT, D. G.	7908170204	50-295 Q
EISENHUT, D. G.	7908280056	50-272 H
EISENHUT, D. G.	7908280266	50-249 Q
EISENHUT, D. G.	7908300313	TOPREP
EISENHUT, D. G.	7908230217	50-3 P
EISENHUT, D. G.	7908270078	REGGD
EISENHUT, D. G.	7908210045	50-269 F
EISENHUT, D. G.	7908210059	50-317 F
EISENHUT, D. G.	7908240592	50-245 F
EISENHUT, D. G.	7905080181	50-320 H
ELANDERS, D. G.	7908230354	50-320 P
ELDRED, D. T.	7908150504*	50-346 S
ELISLE, G. A.	7908300544*	50-269 Q
ELKINS, B. T.	7908140779	FOIA
ELLEMAN, T. S.	7908090393	50-111 P
ELLEMAN, T. S.	7908280390	50-111 P
ELLEMAN, T. S.	7908280396*	50-111 P
ELLERSHAW, L. E.	7908130235*	QA999
ELLERSHAW, L. E.	7908070195*	QA999
ELLERSHAW, L. E.	7908220316*	QA999

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ELLERSHAW, L. E.	7908090222*	GA999
ELLERSHAW, L. E.	7908100508*	GA999
ELLERSHAW, L. E.	7908130651*	GA999
ELLIOTT, J. C.	7908010576*	TOPREP
ELLIS, J. W.	7908150451	50-482 Q
ELLIS, J. W.	7908300028*	50-522 Q
ELROD, S. A.	7908160457*	50-280 Q
ELROD, S. A.	7908240213*	50-280 Q
EMPSON, F. M.	7908080243	70-1308
EMPSON, F. M.	7908170159	70-1308
EMSWILER, T. R.	7908020179	71-6144
EMSWILER, T. B.	7908150551	71-6357
EMSWILER, T. R.	7908200199	71-9081
ENGELMAN, D. B.	7908100394	NUREG
ENGEL, R. E.	7908300733	TOPREP
ENGEL, D. A.	7908150011	50-596 Q
ENGEL, D. A.	7908230256	50-596 Q
ENGEL, D. A.	7908300007	50-596 Q
ENGELHARDT, T. F.	7908210220	50-320 P
ENGELHARDT, T. F.	7908140197	50-556 A
ENGELHARDT, T. F.	7908210133	50-275 Q
ENGELHARDT, T. F.	7908270140	50-289 Q
ENGELKEN, R. H.	7908030202	50-206 P
ENGELKEN, R. H.	7908090200	50-275 S
ENGELKEN, R. H.	7908130335	50-508 Q
ENGELKEN, R. H.	7908020521	50-528 S
ENGELKEN, R. H.	7908020527	50-133 S
ENGELKEN, R. H.	7908020529	50-344 S
ENGELKEN, R. H.	7908020532	50-206 S
ENGELKEN, R. H.	7908020534	50-312 S
ENGELKEN, R. H.	7908020537	50-397 S
ENGELKEN, R. H.	7908010384	50-528 Q
ENGELKEN, R. H.	7908010389	50-133 Q
ENGELKEN, R. H.	7908010391	50-344 Q
ENGELKEN, R. H.	7908010392	50-206 Q
ENGELKEN, R. H.	7908010394	50-312 Q
ENGELKEN, R. H.	7908010397	50-397 Q
ENGELKEN, R. H.	7908020024	50-528 S
ENGELKEN, R. H.	7908020026	50-133 S
ENGELKEN, R. H.	7908020028	50-344 S
ENGELKEN, R. H.	7908020030	50-206 S
ENGELKEN, R. H.	7908020032	50-312 S
ENGELKEN, R. H.	7908020033	50-397 S
ENGELKEN, R. H.	7908020411	50-397 Q
ENGELKEN, R. H.	7908020491	50-528 Q
ENGELKEN, R. H.	7908020494	50-133 Q
ENGELKEN, R. H.	7908020495	50-275 Q
ENGELKEN, R. H.	7908020498	50-344 Q
ENGELKEN, R. H.	7908020500	50-361 Q
ENGELKEN, R. H.	7908020503	50-206 Q
ENGELKEN, R. H.	7908020507	50-312 Q
ENGELKEN, R. H.	7908020509	50-397 Q
ENGELKEN, R. H.	7908020403	50-528 Q
ENGELKEN, R. H.	7908020405	50-133 Q
ENGELKEN, R. H.	7908020406	50-275 Q
ENGELKEN, R. H.	7908020407	50-344 Q
ENGELKEN, R. H.	7908020408	50-361 Q
ENGELKEN, R. H.	7908020409	50-206 Q
ENGELKEN, R. H.	7908020410	50-312 Q
ENGELKEN, R. H.	7908170213	50-312 Q
ENGELKEN, R. H.	7908060024	50-344 Q
ENGELKEN, R. H.	7908060027	50-206 Q
ENGELKEN, R. H.	7908060028	50-312 Q
ENGELKEN, R. H.	7908060048	50-528 Q
ENGELKEN, R. H.	7908060049	50-133 Q
ENGELKEN, R. H.	7908060054	50-275 Q
ENGELKEN, R. H.	7908060058	50-344 Q
ENGELKEN, R. H.	7908060067	50-206 Q
ENGELKEN, R. H.	7908060071	50-361 Q
ENGELKEN, R. H.	7908060077	50-312 Q
ENGELKEN, R. H.	7908060079	50-397 Q
ENGELKEN, R. H.	7908060141	50-528 Q
ENGELKEN, R. H.	7908060144	50-133 Q
ENGELKEN, R. H.	7908060145	50-275 Q
ENGELKEN, R. H.	7908060150	50-344 Q
ENGELKEN, R. H.	7908060153	50-206 Q
ENGELKEN, R. H.	7908060157	50-361 Q
ENGELKEN, R. H.	7908060160	50-312 Q
ENGELKEN, R. H.	7908060166	50-397 Q
ENGELKEN, R. H.	7908170144	50-275 S
ENGELKEN, R. H.	7908300749	50-361 S
ENGELKEN, R. H.	7908210462	50-528 Q
ENGELKEN, R. H.	7908210472	50-397 Q
ENGELKEN, R. H.	7908210485	50-361 Q
ENGELKEN, R. H.	7908210488	50-133 Q
ENGELKEN, R. H.	790821049_	50-275 Q
ENGELKEN, R. H.	7908210497	50-344 Q
ENGELKEN, R. H.	7908210518	50-312 Q
ENGELKEN, R. H.	7908220183	50-206 Q
ENGELKEN, R. H.	7908140072	50-394 Q
ENGELKEN, R. H.	7908140076	50-228 Q
ENGELKEN, R. H.	7908140078	50-89 Q
ENGELKEN, R. H.	7908140080	50-70 Q
ENGELKEN, R. H.	7908140083	50-375 Q
ENGELKEN, R. H.	7908170031	70-734
ENGELKEN, R. H.	7908170032	50-187 Q
ENGELKEN, R. H.	7908170034	50-133 Q
ENGELKEN, R. H.	7908170035	50-133 Q
ENGELKEN, R. H.	7908170036	50-344 Q
ENGELKEN, R. H.	7908170038	50-206 Q
ENGELKEN, R. H.	7908170039	50-206 Q
ENGELKEN, R. H.	7908170040	50-312 Q
ENGELKEN, R. H.	7908170041	50-106 Q
ENGELKEN, R. H.	7908170043	50-288 Q
ENGELKEN, R. H.	7908170044	50-113 Q
ENGELKEN, R. H.	7908170046	50-224 Q
ENGELKEN, R. H.	7908170047	50-433 Q
ENGELKEN, R. H.	7908170048	50-326 Q
ENGELKEN, R. H.	7908170050	50-142 Q
ENGELKEN, R. H.	7908170051	50-139 Q
ENGELKEN, R. H.	7908170052	50-27 Q
ENGELKEN, R. H.	7908220587	70-1257
ENGELKEN, R. H.	7908220594	70-754
ENGELKEN, R. H.	7908220596	70-25
ENGELKEN, R. H.	7908220600	70-984
ENGELKEN, R. H.	7908310126	50-528 Q
ENGELKEN, R. H.	7908310148	50-133 Q
ENGELKEN, R. H.	7908310151	50-344 Q
ENGELKEN, R. H.	7908310155	50-206 Q
ENGELKEN, R. H.	7908310157	50-312 Q
ENGELKEN, R. H.	7908310162	50-397 Q
ENGELKEN, R. H.	7908310166	50-228 Q
ENGELKEN, R. H.	7908310168	50-94 Q
ENGELKEN, R. H.	7908310171	50-89 Q
ENGELKEN, R. H.	7908310172	50-70 Q
ENGELKEN, R. H.	7908310175	50-187 Q
ENGELKEN, R. H.	7908310177	50-394 Q
ENGELKEN, R. H.	7908310180	50-106 Q
ENGELKEN, P. H.	7908310183	50-288 Q
ENGELKEN, R. H.	7908310185	50-113 Q
ENGELKEN, R. H.	7908310188	50-224 Q
ENGELKEN, R. H.	7908310190	50-326 Q
ENGELKEN, R. H.	7908310192	50-142 Q
ENGELKEN, R. H.	7908310193	50-433 Q
ENGELKEN, R. H.	7908310196	50-139 Q
ENGELKEN, R. H.	7908310190	50-27 Q
ENGELKEN, R. H.	7908300219	50-528 Q
ENGELKEN, R. H.	7908300225	50-133 Q
ENGELKEN, R. H.	7908300240	50-275 Q
ENGELKEN, R. H.	7908300241	50-344 Q
ENGELKEN, R. H.	7908300245	50-361 Q
ENGELKEN, R. H.	7908300249	50-206 Q
ENGELKEN, R. H.	7908300252	50-312 Q
ENGELKEN, R. H.	7908300256	50-397 Q
ENGLE, L.	7908220525	50-289 P
ENGLISH, W. F.	7908270385*	TOPREP
EPLER, E. P.	7908210023	50-269 Q
EPLER, E. P.	7908210093	ACRS
EPPINGER, R. L.	7908280692*	50-213 S
ERB, A.	7908200137*	50-463 Q
ERB, C. M.	7908240284*	50-281 Q
ERB, C. M.	7908240202*	50-281 Q
ERICKSON, P.	7908170480	50-466 Q
ERICKSON, P.	7908150044	50-466 Q
ERICSON, D.	7908020301	RES
ERVIN, A. M.	7908080524*	50-296 P
ERVIN, A. M.	7908060407*	50-278 P
ESKRIDGE, H. E.	7908140222	70-36
ESKRIDGE, H. E.	7908210380	70-36
ESSIG, T. H.	7908010074*	50-155 Q
ESSIG, T. H.	7908080700*	50-295 Q
ESSIG, T. H.	7908290557	50-320 T
ESSIG, T. H.	7908290579	50-320 T
ESSIG, T. H.	7908290603	50-320 T
ESSIG, T. H.	7908290618	50-320 T
ESSIG, T. H.	7908300052	50-320 T
ESSIG, T. H.	7908290724	50-320 T
ESSIG, T. H.	7908300089	50-320 T
ESSIG, T. H.	7908300174	50-320 T
ESSIG, T. H.	7908300260	50-320 T
ESSIG, T. H.	7908290565	50-320 T
ESSIG, T. H.	7908290624	50-320 T
ESSIG, T. H.	7908300254	50-320 T
ESSIG, T. H.	7908290733	50-320 T
ESSIG, T. H.	7908280763	50-320 T
ESSIG, T. H.	7908280666	50-320 T
ESSIG, T. H.	7908280733	50-320 T
ESSIG, T. H.	7908290104	50-320 T
ESSIG, T. H.	7908290140	50-320 T
ESSIG, T. H.	7908300274	50-320 T
ESSIG, T. H.	7908290264	50-320 T
ESSIG, T. H.	7908290283	50-320 T
ESSIG, T. H.	7908290347	50-320 T
ESSIG, T. H.	7908290357	50-320 T
ESSIG, T. H.	7908290379	50-320 T
ESSIG, T. H.	7908290371	50-320 T
ESSIG, T. H.	7908280779	50-320 T
ESSIG, T. H.	7908280797	50-320 T
ESSIG, T. H.	7908280819	50-320 T
ESSIG, T. H.	7908280827	50-320 T
ESSIG, T. H.	7908290202	50-320 T
ESSIG, T. H.	7908290568	50-320 T
ESSIG, T. H.	7908150375*	50-254 Q
ESTEY, H. P.	7908150258	70-1257
ESTEY, H. P.	7908200106	70-1257
ESTEY, H. P.	7908090535	70-1257
ESTEY, H. P.	7908090624	70-1257
ETHERINGTON, H.	7908090641	50-437 O
ETHERINGTON, H.	7908030317	ACRS
ETHERINGTON, H.	7908220115	50-320 T
ETHERINGTON, H.	7908220126	50-320 T
ETHERINGTON, H.	7908150053	ACRS
ETHERINGTON, H.	7908220076	50-320 T
EVANS, R. P.	7908140116	NUREG
EVANS, V. R.	7908200200	50-317 F
EVANS, J.	7908230499	50-320 S
EVANS, C. A.	7908010679*	50-267 Q
EVANS, C. A.	7908080251*	50-252 Q
EVERETT, R. J.	7908090333*	40-6659
EWALD, S. C.	7908150216*	50-280 Q
EWING, T. N.	7908010573	50-556 A
EWING, T. N.	7908150481	50-556 A
EYBERGER, L. R.	7908080205*	ORG
FABIC, S.	7908130592	REVIEW GRP
FAHRNER, W. J.	7908080515	50-341 S
FAHRNER, W. J.	7908140573	50-341 S
FAINTER, J. W.	7908130076	50-466 Q
FAINTER, J. W.	7908130089	50-466 Q
FAINTER, J. W.	7908130261	50-445 M
FAIST, C. A.	7908020037	71-186
FALLS, O. B.	7908060486*	NUREG
FALLS, O. B.	7908030570*	NUREG
FALLS, O. D.	7908030592*	NUREG
FARINSKY, K. W.	7908280006	COMMISSION
FARLEY, J. P.	7908170433	50-272 Q
FARON, R. S.	7908090510	50-244 Q
FASANO, A. N.	7908230601*	50-320 Q
FASANO, A. N.	7908230640*	50-320 Q
FASANO, A. N.	7908280696	50-320 T
FASANO, A. N.	7908290067	50-320 T
FASANO, A. N.	7908290083	50-320 T
FASANO, A. N.	7908290099	50-320 T
FASANO, A. N.	7908290123	50-320 T
FASANO, A. N.	7908290133	50-320 T
FASANO, A. N.	7908290186	50-320 T
FASANO, A. N.	7908290210	50-320 T
FASANO, A. N.	7908290215	50-320 T
FASANO, A. N.	7908290256	50-320 T
FASANO, A. N.	7908290347	50-320 T
FASANO, A. N.	7908290357	50-320 T
FASANO, A. N.	7908290379	50-320 T
FASANO, A. N.	7908280632	50-320 T
FASANO, A. N.	7908290371	50-320 T
FASANO, A. N.	7908290384	50-320 T
FASANO, A. N.	7908280844	50-320 T
FASANO, A. N.	7908290048	50-320 T
FAULKENBERRY, B.	7908170123*	50-312 Q
FAULKENBERRY, B.	7908150196*	50-361 Q
FAULKENBERRY, B.	7908150443*	50-326 Q
FAY, C. W.	79080E0553	50-266 P
FAY, C. W.	7908150547	50-266 P
FAY, C. W.	7908010383	50-266 P
FAY, C. W.	7908010381	50-301 S
FAY, C. W.	7908010385*	50-301 S
FAY, C. W.	7908140687	50-266 P
FAY, C. W.	7908210313	50-302 C
FAY, C. W.	7908270427*	50-266 S
FAY, C. W.	7908270434*	50-266 S

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FAY, C. W.	7908270470	50-502 A
FAY, C. W.	7908300740	50-266 Q
FEE, W. F.	7908210589	50-213 F
FEE, W. F.	7908160446	50-245 P
FEE, W. F.	7908210579	50-336 P
FEE, W. F.	7908210401	50-213 F
FEIERABEND, C. D.	7908160130*	50-282 Q
FEIRSTEIN, R. P.	7908150076	50-596 Q
FEIRSTEIN, R. P.	7908210061	50-596 Q
FEIST, C. K.	7908090467	50-445 A
FEIST, C. K.	7908090515	50-445 A
FEIST, C. K.	7908010490	50-445 A
FELICETTI, F.	7908170469*	FOIA
FELTON, J. M.	7908080672	FOIA
FELTON, J. M.	7908150507	50-334 P
FELTON, J. M.	7908230289*	50-320 P
FELTON, J. M.	7908230365*	50-320 P
FELTON, J. M.	7907310565	FOIA
FELTON, J. M.	7908080110	FOIA
FELTON, J. M.	7908080118	FOIA
FELTON, J. M.	7908100507	FOIA
FELTON, J. M.	7908090130	FOIA
FELTON, J. M.	7908030435	50-269 P
FELTON, J. M.	7908060081	FOIA
FELTON, J. M.	7908170247	PRM
FELTON, J. M.	7908030473	FOIA
FELTON, J. M.	7908080687	FOIA
FELTON, J. M.	7908090171	50-321 Q
FELTON, J. M.	7908030460	FOIA
FELTON, J. M.	7908090217	50-346 P
FELTON, J. M.	7908060055	FOIA
FELTON, J. M.	7908060066	FOIA
FELTON, J. M.	7908080593	FOIA
FELTON, J. M.	7908080740	FOIA
FELTON, J. M.	7908080750	FOIA
FELTON, J. M.	7908030425	50-382 Q
FELTON, J. M.	7908030407	FOIA
FELTON, J. M.	7908030458	FOIA
FELTON, J. M.	7908030467	FOIA
FELTON, J. M.	7908090176	FOIA
FELTON, J. M.	7908060040	50-208 H
FELTON, J. M.	7908060100	FOIA
FELTON, J. M.	7908080540	50-373 A
FELTON, J. M.	7908080618	FOIA
FELTON, J. M.	7908160394	FOIA
FELTON, J. M.	7908030445	FOIA
FELTON, J. M.	7908090149	FOIA
FELTON, J. M.	7908030453	FOIA
FELTON, J. M.	7908060083	FOIA
FELTON, J. M.	7908080482	70-2684
FELTON, J. M.	7908090111	FOIA
FELTON, J. M.	7908060091	FOIA
FELTON, J. M.	7908080683	50-280 P
FELTON, J. M.	7908090090	50-346 P
FELTON, J. M.	7908170621	FOIA
FELTON, J. M.	7908150509	50-280 P
FELTON, J. M.	7908160290	50-574 A
FELTON, J. M.	7908160305	FOIA
FELTON, J. M.	7908160402	FOIA
FELTON, J. M.	7908160404	FOIA
FELTON, J. M.	7908160410	FOIA
FELTON, J. M.	7908170083	FOIA
FELTON, J. M.	7908170450	FOIA
FELTON, J. M.	7908140517	FOIA
FELTON, J. M.	7908140728	FOIA
FELTON, J. M.	7908140829	FOIA
FELTON, J. M.	7908150058	FOIA
FELTON, J. M.	7908150032	FOIA
FELTON, J. M.	7908150039	FOIA
FELTON, J. M.	7908150071	FOIA
FELTON, J. M.	7908150411	FOIA
FELTON, J. M.	7908150416	FOIA
FELTON, J. M.	7908150429	FOIA
FELTON, J. M.	7908140776	FOIA
FELTON, J. M.	7908140809	FOIA
FELTON, J. M.	7908140840	FOIA
FELTON, J. M.	7908150089	FOIA
FELTON, J. M.	7908150097	70-734
FELTON, J. M.	7908150448	FOIA
FELTON, J. M.	7908170065	50-373 A
FELTON, J. M.	7908170581	50-320 P
FELTON, J. M.	7908170586	50-320 P
FELTON, J. M.	7908170594	50-320 P
FELTON, J. M.	7908200171	FOIA
FELTON, J. M.	7908220178	FOIA
FELTON, J. M.	7908200164	FOIA
FELTON, J. M.	7908200255	FOIA
FELTON, J. M.	7908220485	FOIA
FELTON, J. M.	7908200348	FOIA
FELTON, J. M.	7908220446	50-272 A
FELTON, J. M.	7908220480	FOIA
FELTON, J. M.	7908220068	50-320 A
FELTON, J. M.	7908220464	50-272 A
FELTON, J. M.	7908220685	FOIA
FELTON, J. M.	7908310040	FOIA
FELTON, J. M.	7908310426	FOIA
FELTON, J. M.	7908310442	FOIA
FELTON, J. M.	7908310485	50-3 P
FELTON, J. M.	7908310485	50-286 P
FELTON, J. M.	7908240176	FOIA
FELTON, J. M.	7908270549	FOIA
FELTON, J. M.	7908310469	50-320 H
FELTON, J. M.	7908240085	FOIA
FELTON, J. M.	7908280052	FOIA
FELTON, J. M.	7908300787	50-277 P
FELTON, J. M.	7908310587	FOIA
FELTON, J. M.	7908300781	FOIA
FELTON, J. M.	7908290535	FOIA
FELTON, J. M.	7908310048	FOIA
FELTON, J. M.	7908310527	50-320 P
FELTON, J. M.	7908310534	50-320 P
FELTON, J. M.	7908310537	50-320 P
FELTON, J. M.	7908310542	50-320 P
FELTON, J. M.	7908310546	FOIA
FELTON, J. M.	7908310556	50-320 P
FELTON, J. M.	7908290658	FOIA
FELTON, J. M.	7908290657	FOIA
FELTON, J. M.	7908310588	FOIA
FERGUSON, W. J.	7908300034*	50-522 Q
FERGUSON, W. J.	7908300617	50-522 Q
FERGUSON, R.	7908130065	50-317 F
FERGUSON, R. L.	7908160073	REGGD
FIEND, D.	7908220274	50-313 P
FILOCCO, N. I.	7908140835	FOIA
FINDLEY, D. E.	7908150423	FOIA
FINDLAY, J. A.	7908240089	TOPREP
FINFROCK, I. R.	7908230257*	50-320 P
FINFROCK, I. R.	7908080489	50-363 Q
FINFROCK, I. R.	7908010686*	50-219 Q
FINFROCK, I. R.	7908070830	50-363 Q
FINFROCK, I. R.	7908070675	50-363 Q
FINFROCK, I. R.	7908030503	50-363 A
FINFROCK, I. R.	7908130253	50-363 Q
FINFROCK, I. R.	7908230154	50-363 Q
FINFROCK, I. R.	7908130259	50-219 Q
FINFROCK, I. R.	7908060223	50-219 S
FINFROCK, I. R.	7908090408	50-219 H
FINFROCK, I. R.	7908140378	50-219 P
FINFROCK, I. R.	7908160436	50-219 Q
FINFROCK, I. R.	7908210300	50-219 P
FINFROCK, I. R.	7908210426	50-219 R
FINFROCK, I. R.	7908240519	50-219 P
FINFROCK, I. R.	7908210012	50-219 F
FINFROCK, I. R.	7908270469	50-219 P
FINFROCK, I. R.	7908280017	50-219 F
FINKEL, A.	7908230494*	50-320 Q
FINKEL, W. A.	7908230601*	50-320 Q
FINLAYSON, F. C.	7908230469	50-320 P
FINLAY, G. W.	7908080363	71-167
FINLEY, A. G.	7908090257*	50-295 Q
FIORELLI, G.	7908290520	50-315 Q
FIORELLI, G.	7908070127	50-454 Q
FIORELLI, G.	7908150614	50-329 Q
FIORELLI, G.	7908030623	50-329 Q
FIORELLI, G.	7908010193*	50-373 Q
FIORELLI, G.	7908100208	50-341 Q
FIORELLI, G.	7908080420	50-454 Q
FIORELLI, G.	7908030365	50-483 S
FIORELLI, G.	7908030374	50-374 S
FIORELLI, G.	7908030388	50-329 S
FIORELLI, G.	7908080722	50-546 Q
FIORELLI, G.	7908150450	50-329 Q
FIORELLI, G.	7908170239	50-440 Q
FIORELLI, G.	7908100134*	50-305 Q
FIORELLI, G.	7908150120	50-483 Q
FIORELLI, G.	7908150160	50-484 Q
FIORELLI, G.	7908150225	50-266 Q
FIORELLI, G.	7908150255	50-315 Q
FIORELLI, G.	7908230042	50-358 Q
FIORELLI, G.	7908010668	50-546 S
FIORELLI, G.	7908020324	50-456 Q
FIORELLI, G.	7908030582	50-295 Q
FIORELLI, G.	7908170173	50-373 Q
FIORELLI, G.	7908100120	50-305 Q
FIORELLI, G.	7908030214	50-454 Q
FIORELLI, G.	7908270269	50-329 S
FIORELLI, G.	7908270274	50-329 S
FIORELLI, G.	7908270279	50-329 S
FIORELLI, G.	7908080417	50-461 Q
FIORELLI, G.	7908160523	50-546 S
FIORELLI, G.	7908160526	50-358 S
FIORELLI, G.	7906240161	50-409 Q
FIORELLI, G.	7908140252	50-546 S
FIORELLI, G.	7908170296	50-546 S
FIORELLI, G.	7908060171	50-456 Q
FIORELLI, G.	7908060199	50-329 Q
FIORELLI, G.	7908090646	50-373 Q
FIORELLI, G.	7908130111	50-483 Q
FIORELLI, G.	7908150412	50-329 Q
FIORELLI, G.	7908170116	50-546 S
FIORELLI, G.	7908280513	50-546 Q
FIORELLI, G.	7908290118	50-329 S
FIORELLI, G.	7908090628	50-440 S
FIORELLI, G.	7908090631	50-454 S
FIORELLI, G.	7908230108	50-440 Q
FIORELLI, G.	7908230120	50-358 Q
FISHBACK, D. R.	7908020562	50-338 Q
FISHER, E.	7908080668	XPORTLIC
FISHER, W. L.	7908020188*	70-8
FISHER, W. L.	7908150346*	50-315 Q
FISHER, W. L.	7908210131*	50-409 Q
FISHER, W. L.	7908280508*	50-373 Q
FISHER, B. P.	7908170183	40-8698
FITZGERALD, J. A.	7908080638*	50-443 Q
FITZGERALD, J. A.	7908080595*	10CFR
FLACK, Q.	7908070621	50-424 A
FLAGLER, M. C.	7908160019	PRM
FLEMING, T. B.	7908160056	XPORTLIC
FLETCHER, J. C.	7908170295*	COMMISSION
FLINCHBAUGH, D. E.	7908220402	50-320 P
FLYNN, P. G.	7908070074	50-498 M
FLYNN, J. D.	7908230186*	50-358 Q
FLYNN, J. D.	7908230164*	50-358 Q
FLYNN, J. D.	7908030303	50-358 A
FLYNN, J. D.	7908310448	70-2838
FOIRELLI, G.	7908030414	50-329 S
FOLEY, H.	7908170571	50-466 Q
FOLEY	7908010287*	50-516 Q
FOLSOM, S. A.	7908230481*	50-320 Q
FOLSON, S. A.	7908230340*	50-320 Q
FOLSOM, S. A.	7908230334	50-320 Q
FORBES, R. L.	7908280668*	50-255 J
FORD, C. K.	7908090543	NUREG
FORD, E. J.	7908070155*	50-261 Q
FORD, E. J.	7908240196*	50-280 Q
FORD, E. J.	7908240353*	50-338 Q
FORD, E. J.	7908230683*	50-348 Q
FORSYTH, A. W.	7908290650	70-1810
FOSTER, H.	7908270131	70-1151
FOSTER, L. E.	7908240181*	50-324 Q
FOSTER, W. H.	7908290172	50-320 T
FOSTER, J. E.	7908150628*	50-358 Q
FOSTER, J. E.	7908080229*	50-358 Q
FOSTER, W. E.	7908100260*	GA999
FOSTER, W. H.	7908280860	50-320 T
FOSTER, W. H.	7908290067	50-320 T
FOSTER, W. H.	7908290083	50-320 T
FOSTER, W. H.	7908290123	50-320 T
FOSTER, W. H.	7908290191	50-320 T
FOSTER, W. H.	7908290160	50-320 T
FOSTER, W. H.	7908290179	50-320 T
FOSTER, W. H.	7908280791	50-320 T
FOSTER, W. H.	7908280795	50-320 T
FOSTER, W. H.	7908280823	50-320 T
FOSTER, W. H.	7908280852	50-320 T
FOSTER, W. H.	7908280856	50-320 T
FOSTER, W. H.	7908290052	50-320 T
FOSTER, W. H.	7908290224	50-320 T
FOURNEY, W. L.	7908030191	RES
FOURNEY, W. L.	7908010069	RES
FOX, H. S.	7908030020	71-6375
FOX, H. S.	7908160112	71-6722
FOX, H. S.	7908010390	50-296 S
FOX, H. S.	7908010548	50-259 S
FOX, H. S.	7908020447	50-260 S
FOX, H. S.	7908020496	50-260 S
FRALEY, R. F.	7908220221*	50-320 P
FRALEY, R. F.	7908020306	50-336 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FRANCIS, S. L.	7908080733*	50-338 P
FRANCOIS, E. I.	7908130373*	GA999
FRANCIS, B. J.	7908140032*	AGREEMENT
FRANCIS, E.	7908140175	40-8693
FRANKLIN, A. G.	7908090031	REGGD
FRAZIER, H. E.	7908080617*	50-390 A
FREDERICK, E. J.	7908140349	RES
FREDERICK, E. J.	7908140356*	RES
FREEMAN, M. V.	7908170346*	50-329 G
FREEMAN, M. D.	7908130580	40-8064
FREEMAN, M. D.	7908170150	40-8064
FREEMAN, M. D.	7908270502	40-8064
FROCLICH, R. W.	7908150501	50-466 G
FROST, M.	7908030384*	COMMISSION
FUCHKO, J. M.	7908030632*	50-269 G
FUCHKO, J. M.	7908030632*	50-269 G
FUGUAY, J. J.	7908230122	70-984
FUKAZAWA, Y.	7908310525*	XPORTLIC
FULKERSON, W.	7905160395	50-568 D
FULLER, J. K.	7908080470	50-267 G
FULLER, J. K.	7908210050	50-267 P
FULLER, J. K.	7908010501	50-267 P
FULLER, J. K.	7908310458	50-267 P
FULTON, J. M.	7908020416	50-293 S
FULTON, J. M.	7908130363	50-293 S
FULTON, J. M.	7908170423*	50-293 S
FULTON, J. M.	7908280533*	50-293 S
FUQUAY, J. J.	7908030523*	70-984
FURBUSH, M. H.	7908200047	50-133 G
FURR, B. J.	7908070133*	50-261 G
FURR, B. J.	7908090412	50-261 G
FURR, B. J.	7908230585	50-261 G
FURR, B. J.	7908170062	50-261 G
FURR, B. J.	7908300588	50-324 G
FURR, B. J.	7908160369	50-261 G
FURR, B. J.	7908310421	50-261 P
FUSCO, G.	7908200073*	50-280 H
GADDARD, R. J.	7908080289	50-295 G
GAFFNEY, C. M.	7908200233*	50-293 R
GAFFNEY, C. M.	7908290415*	50-293 R
GAGE, L. W.	7908230524*	50-320 G
GAHM, J. W.	7908300539*	50-267 S
GAHM, J. W.	7908160345*	50-267 R
GAHM, J. W.	7908070518*	50-267 S
GAHM, J. W.	7908070686*	50-267 S
GAHM, J. W.	7908140504*	50-267 R
GAHM, J. W.	7908310331*	50-267 S
GAHM, J. W.	7908310353*	50-267 S
GAHM, J. W.	7908200394	50-267 S
GAHM, J. W.	7908310325*	50-267 S
GAHN, J. W.	7908220376*	50-__7 S
GALLAHER, R. B.	7908230679	NUREG
GALLA, R. M.	7908200288*	50-387 G
GALLAGHER, E. J.	7908070340*	50-546 G
GALLAGHER, E. J.	7908150232*	50-266 G
GALLAGHER, E. J.	7908240314*	50-409 G
GALLAGHER, E. J.	7908030633*	50-329 G
GALLER, S. R.	7908210545	50-568 D
GALLINA, C. D.	7908230590*	50-320 G
GALLINA, C. D.	7908230659*	50-320 G
GALPIN, F.	7908290271*	FOIA
GALT, J. M.	7908290254	50-498 M
GALUSHA, B. M.	7908100394	NUREG
GALVAGNI, R.	7908170469*	FOIA
GAMBLE, C. C.	7908020216	71-9007
GAMBLE, R. M.	7908170255	ORG
GAMMILL, W. P.	7908140472	50-309 P
GAMMILL, W. P.	7908290674*	50-346 P
GAMMILL, W. P.	7908030307*	50-302 P
GAMMILL, W. P.	7908150452	50-309 H
GAMMILL, W. P.	7908200132	50-335 P
GAMMILL, W. P.	7908300025	50-247 G
GAMMILL, W. P.	7908300092	50-312 G
GAMMILL, W. P.	7908230155	50-3 P
GAMMILL, W. P.	7908020385	50-267 P
GAMMILL, W. P.	7908080070	50-3 P
GAMMILL, W. P.	7908100290	50-10 P
GANCARZ, A. J.	7908080358*	PROJ
GARCIA, P. J.	7908230172	40-4492
GARNER, R. W.	7908020474	RES
GARNIER, J. E.	7908090530	NUREG
GARRAHY, J. J.	7908070057*	AGREEMENT
GARRETT, S. M.	7908030150	PR
GARY, R. J.	7908020225	50-445 G
GARY, R. J.	7908020271	50-445 G
GARY, R. J.	7908090524	50-445 G
GARY, R. J.	7908220623	50-445 G
GARY, R. J.	7908150134	50-445 G
GARY, R. J.	7908160001	50-445 S
GARY, R. J.	7908160357	50-445 G
GARY, R. J.	7908170120	50-445 S
GARY, R. J.	7908170112	50-445 S
GARY, R. J.	7908310021	50-445 G
GARY, R. J.	7908030440*	50-445 M
GARY, R. J.	7908140427	50-445 K
GARY, R. J.	7908140446	50-445 S
GARY, R. J.	7908140541	50-445 S
GARY, R. J.	7908210295	50-445 S
GARY, R. J.	7908210377	50-445 S
GASPARY, G. L.	7908200037*	GA999
GASPER, J. T.	7908080416	NUREG
GATES, M. E.	7908210110	50-320 P
GEARS, G. E.	7908150348*	50-466 G
GECKLER, R. P.	7908160036	50-367 A
GEE, L. S.	7908060087	FOIA
GEER, R. J.	7908150375*	50-254 G
GEHR, A. C.	7908130028	50-592 G
GEIGER, D. A.	7908010015	71-215
GEISLER, A. H.	7908070677	TOPREP
GENDLER, M. W.	7908300008	50-522 G
GENDLER, M. W.	7908300008	50-522 G
GEORGE, K. D.	7908310333	50-54 F
GERETY, H. F.	7908230375	50-219 J
GERLT, D. H.	7908200319*	50-344 P
GERRETY, H. F.	7908200247	50-289 J
GERSTNER, W. C.	7908080422*	50-461 G
GETTY, B. C.	7908210387*	50-133 R
GIARRATAN, A. C.	7906210370*	70-2623
GIBBONS, T. D.	7908020190*	50-327 G
GIBBONS, T. D.	7908150302*	50-369 G
GIBBONS, T. D.	7908270300*	50-369 G
GIBBS, M. E.	7906280112*	50-329 G
GIBBS, M. E.	7908170549	50-329 G
GIBBS, M. E.	7908220298	50-329 G
GIBSON, J. R.	7908170564*	70-572
GIBSON, A. F.	7906210444	50-320 P
GIBSON, A. F.	7906210432	50-320 P
GIBSON, A. F.	7908280745	50-320 T
GIBSON, A. F.	7908280739	50-320 T
GIBSON, A. F.	7908280791	50-320 T
GIBSON, G. T.	7908210573*	50-124 G
GIESEKE, J. A.	7909270342	RES
GIFFORD, H. C. F.	7908080577*	70-2684
GIGLIOTTI, P. J.	7908170218	70-820
GILBERT, W. D.	7908230511*	50-344 G
GILBERT, E. S.	7908150475*	ORG
GILINSKY, V.	7908020196	50-312 T
GILINSKY, V.	7908010644*	10CFR
GILINSKY, V.	7908100315	10CFR
GILINSKY, V.	7908230011	50-320 P
GILINSKY, V.	7908150473*	50-320 P
GILINSKY, V.	7908010033	10CFR
GILINSKY, V.	7908010636	10CFR
GILINSKY, V.	7908010658	10CFR
GILINSKY, V.	7908240359*	SECY
GILINSKY, V.	7907030417	10CFR
GILINSKY, V.	7908010621	10CFR
GILINSKY, V.	7908080589	50-443 G
GILINSKY, V.	7908010620	50-312 T
GILINSKY, V.	7908080536	10CFR
GILINSKY, V.	7908090625	SECY
GILINSKY, V.	7908090607	10CFR
GILINSKY, V.	7908100524	10CFR
GILINSKY, V.	7908090614	10CFR
GILINSKY, V.	7908170502	50-289 P
GILINSKY, V.	7908210364	10CFR
GILINSKY, V.	7908170587*	10CFR
GILINSKY, V.	7908210101	10CFR
GILINSKY, V.	7908220401	50-289 P
GILINSKY, V.	7908170633	10CFR
GILINSKY, V.	7908090579	50-289 T
GILINSKY, V.	7908090566	10CFR
GILINSKY, V.	7908090604	10CFR
GILINSKY, V.	7908170309	10CFR
GILINSKY, V.	7908210067	50-289 T
GILINSKY, V.	7908210060	50-289 T
GILLETT, W. T.	7908170343*	50-316 R
GILLETT, W. J.	7908310338*	50-315 R
GILLELAND, J. E.	7908240254*	50-259 G
GILLELAND, J. E.	7908070149*	50-390 G
GILLELAND, J. E.	7908010158	50-259 G
GILLELAND, J. E.	7908140163	70-2443
GILLELAND, J. E.	7908140166*	70-2443
GILLELAND, J. F.	7908240177	50-390 A
GILLELAND, J. E.	7908240243*	50-259 G
GILLELAND, J. E.	7908270326	50-259 G
GILLELAND, J. E.	7908010320	70-1622
GILLELAND, J. E.	7908010692	50-327 G
GILLELAND, J. E.	7908090494	40-1341
GILLELAND, J. E.	7908020075*	50-553 G
GILLELAND, J. E.	7908150322*	50-438 G
GILLELAND, J. E.	7908150372*	50-438 G
GILLESPIE, F. P.	7908240164*	70-143
GILLESPIE, F. P.	7908150553*	70-143
GILLESPIE, F. P.	7908230658*	70-1113
GILRAY, J. W.	7908300738	TOPREP
GIMES, B. K.	7908170301	TOPREP
GINN, B. J.	7908220589	50-466 G
GIORGI, J.	7908150494*	50-320 P
GIRARD, E. K.	7908140824	FOIA
GIRARD, E. H.	7908020197*	50-390 G
GIRAUD, A.	7908220102	50-320 U
GISH, N. R.	7908170331	50-522 G
GISH, N. R.	7908230248	50-522 G
GITTLEMAN, L.	7908080255*	50-522 G
GIVVS, M. E.	7908150420	50-329 G
GLADNEY, E. S.	7908080346	PROJ
GLADNEY, E. S.	7908230079	PROJ
GLAGOLA, A. F.	7908100264	CONTRACT
GLAGOLA, A. F.	7908170115	CONTRACT
GLAGOLA, A. F.	7908100251	CONTRACT
GLASER, M. L.	7908030551	50-312 G
GLASER, M. L.	7908220555*	50-312 H
GLASER, M.	7908090653	50-312 T
GLASSMAN, N.	7908220042	50-574 G
GLASSMAN, N.	7908240166	50-574 G
GLASS, M.	7908220170	FOIA
GLASS, M.	7908080745	FOIA
GLEIN, J.	7908210056	50-358 U
GLENN, R. D.	7908030452*	50-269 P
GLENN, R. D.	7908030462*	50-269 P
GLOVER, F. A.	7908290616*	50-267 R
GLYNN, J. C.	7908140226*	GA999
GODBY, W. A.	7908200077	40-8698
GODDARD, R. J.	7908080607*	10CFR
GODDARD, R. J.	7908020365	50-295 G
GODDARD, R. J.	7908020371*	50-295 G
GODWIN, T.	7908080017*	50-320 H
GODY, A.	7908240040*	XPORTLIC
GOEBEL, G. R.	7908080423	NUREG
GOGEL, E.	7908080207*	50-599 G
GOGOL, E.	7908170068	50-373 A
GOLDBERG, R.	7908230308	50-346 M
GOLDBERG, S. C.	7908010630	50-250 P
GOLDBERG, S. C.	7908010634	50-338 G
GOLDBERG, S. C.	7908160065	50-338 G
GOLDBERG, S. C.	7908160068	50-338 G
GOLDBERG, S. C.	7908150001	50-250 G
GOLDBERG, S. C.	7908300122	50-338 G
GOLDBERG, S. C.	7908080351*	50-599 G
GOLDBERG, S. C.	7908300068	50-338 G
GOLDBERG, S. C.	7908080344	50-599 G
GOLDBERG, S. C.	7908300058	50-338 G
GOLDBERG, J. R.	7908020582	PROJ
GOLDBERG, J. R.	7908070226	PROJ
GOLDBERG, J. R.	7908300323	PROJ
GOLDMAN, H. L.	7908060287	50-312 A
GOLDSTEIN, R. M.	7908140689*	50-522 G
GOLDSMITH, R.	7908160095	ORG
GOODWIN, W. L.	7908140170	70-1151
GOODWIN, W. L.	7908170623*	70-1151
GOODWIN, C.	7908090601	50-344 G
GOODWIN, C.	7908060389	50-344 F
GOODWIN, C.	7908070371	50-344 F
GOODWIN, C.	7908080467	50-344 F
GOODWIN, C.	7908270363	50-344 P
GOODWIN, C.	7908280683	50-344 F
GOODWIN, C.	7908280022	50-344 F
GOPPEL, M.	7908160002	XPORTLIC
GOPPEL, M.	7908160003	XPORTLIC
GOPPEL, M.	7908240053	XPORTLIC
GORDON, M. W.	7908290487	50-546 G
GORE, J. W.	7908210280	50-317 E
GORMLY, H. J.	7908080675	50-275 G
GOSSICK, L. V.	7908280163*	FOIA
GOSSICK, L. V.	7908140521*	FOIA
GOSSICK, L. V.	7907020277	50-320 U
GOSSICK, L. V.	7908010695*	10CFR

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GOSSICK, L. V.	7907260314	50-320 U
GOSSICK, L. V.	7907260295	50-320 U
GOSSICK, L. V.	7907960154	50-320 U
GOSSICK, L. V.	7906020111	27-39
GOSSICK, L. V.	7908080419	27-39
GOSSICK, L. V.	7908300462	XPORTLIC
GOSSICK, L. V.	7908240069*	PRM
GOSSICK, L. V.	7908240072*	PRM
GOSSICK, L. V.	7908130302	50-329 A
GOSSICK, L. V.	7908080592	XPORTLIC
GOSSICK, L. V.	7908080586	XPORTLIC
GOSSICK, L. V.	7908160022*	PRM
GOSSICK, L. V.	7908080580	XPORTLIC
GOSSICK, L. V.	7908160020	PRM
GOSSICK, L. V.	7908170488	50-280 H
GOSSICK, L. V.	7908170254	XPORTLIC
GOSSICK, L. V.	7908170443	XPORTLIC
GOSSICK, L. V.	7908210063	XPORTLIC
GOSSICK, L. V.	7908270325	COMMISSION
GOSSICK, L. V.	7908140709	FOIA
GOTCHY, R. L.	7908090522*	PROJ
GOTCHY, R. L.	7908080249*	50-522 Q
GOUGE, M. J.	7908060308*	50-566 Q
GOUGE, M. J.	7908020205*	50-566 Q
GOUGE, M. J.	7908230691*	50-281 Q
GOVER, N.	7908230274	PR
GRACE, R. H.	7908070653	50-271 Q
GRACE, R. H.	7908270511	50-29 Q
GRAHAM, W. E.	7908290388	50-261 J
GRAHAM, M. J.	7908240297*	50-302 Q
GRANT, J. S.	7908030610	50-346 Q
GRANT, J. S.	7908010313	50-346 Q
GRANT, J. S.	7908100583	50-346 Q
GRANT, J. S.	7908080093	50-346 Q
GRANT, J. S.	7908130416	50-346 Q
GRANT, J. S.	7908140109	50-346 Q
GRANT, J. S.	7908200113	50-346 Q
GRANT, J. S.	7908140602	50-346 P
GRASHAW, T. D.	7908280487	71-330
GRASHAW, T. D.	7908280492*	71-330
GRAVES, J.	7908300543*	50-599 Q
GRAVES, H. M.	7908210569*	TOPREP
GRAVES, R. H.	7908280686	50-213 S
GRAVES, R. H.	7908030015	50-213 F
GRAVES, R. H.	7908060304	50-213 S
GRAVES, R. H.	7908100438	50-213 S
GRAVES, R. H.	7908200322	50-213 R
GRAVES, R. H.	7908210333	50-213 S
GRAY, R.	7908150281	50-546 Q
GRAY, R.	7908150306	50-546 H
GRAY, E. S.	7908 407J6	TOPREP
GRAY, J. R.	7905,50714	50-344 Q
GRAY, J. R.	7906110206	50-344 Q
GRAY, J. R.	7906110210*	50-344 Q
GRAY, J. R.	7908080547	50-463 H
GRAY, J. R.	7906100077	50-344 Q
GRAY, J. R.	7908300582	50-548 Q
GRAY, J. R.	7908230456	50-344 Q
GRAY, J. R.	7908220013	50-344 Q
GRAY, J. R.	7908100591	50-344 Q
GRAY, J. R.	7908090099	50-524 Q
GRAY, J. R.	7908090391	50-344 Q
GREENBERGER, M.	7908280002*	COMMISSION
GREEN, D.	7908140451*	50-259 R
GREENE, G. A.	7908010545	RES
GREEVES, J. T.	7908210543	50-409 P
GREGER, L. R.	7908210131*	50-409 Q
GREGG, R. J.	7908200413	71-9019
GREGG, B.	7908140479*	71-241
GREGG, R. J.	7908210602	70-820
GREGORY, W. S.	7908290233	RES
GREGORY, W. S.	7908030175	RES
GREGORY, W. S.	7908140649	RES
GRELLA, A. W.	7908290040*	71-5
GREY, R.	7908010646	50-596 C
GREY, R.	7908010480	50-596 C
GREY, R.	7908300248*	50-596 Q
GREY, R.	7908170253	50-596 Q
GRIDLEY, R. L.	7908070664	TOPREP
GRIDLEY, R. L.	7908010570	TOPREP
GRIER, B. H.	7908080097	70-820
GRIER, B. H.	7908020060*	50-272 Q
GRIER, B. H.	7908230552	50-320 Q
GRIER, B. H.	7906210438	50-320 P
GRIER, B. H.	7907200082	50-317 Q
GRIER, B. H.	7908080646	70-135
GRIER, B. H.	7908080653	50-219 P
GRIER, B. H.	7908070077	50-225 Q
GRIER, B. H.	7908070081	50-57 Q
GRIER, B. H.	7908070084	50-223 Q
GRIER, B. H.	7908070085	50-166 Q
GRIER, B. H.	7908070091	50-22 Q
GRIER, B. H.	7908070092	50-170 Q
GRIER, B. H.	7908070094	50-47 Q
GRIER, B. H.	7908070098	50-184 Q
GRIER, B. H.	7908070101	50-193 Q
GRIER, B. H.	7908070106	50-134 Q
GRIER, B. H.	7908070110	50-5 Q
GRIER, B. H.	7908070367	70-364
GRIER, B. H.	7908070369	50-201 P
GRIER, B. H.	7908070408	70-33
GRIER, B. H.	7908070411	70-371
GRIER, B. H.	7908070414	70-820
GRIER, B. H.	7908070416	70-1143
GRIER, B. H.	7908070422	50-293 P
GRIER, B. H.	7908070424	50-317 P
GRIER, B. H.	7908070428	50-247 P
GRIER, B. H.	7908070430	50-213 P
GRIER, B. H.	7908070434	50-334 P
GRIER, B. H.	7908070436	50-219 P
GRIER, B. H.	7908070450	50-320 P
GRIER, B. H.	7908070453	50-309 P
GRIER, B. H.	7908070456	50-245 P
GRIER, B. H.	7908070459	50-220 P
GRIER, B. H.	7908070461	50-333 P
GRIER, B. H.	7908070463	50-286 P
GRIER, B. H.	7908070466	50-277 P
GRIER, B. H.	7908070467	50-272 P
GRIER, B. H.	7908070469	50-244 P
GRIER, B. H.	7908070472	50-271 P
GRIER, B. H.	7908070474	50-29 P
GRIER, B. H.	7908020052	50-272 Q
GRIER, B. H.	7908030220	50-322 Q
GRIER, B. H.	7908130058	50-334 Q
GRIER, B. H.	7908150747	50-320 Q
GRIER, B. H.	7908280874	50-219 P
GRIER, B. H.	7908150759	50-320 Q
GRIER, B. H.	7908150749	50-320 Q
GRIER, B. H.	7908230619	50-146 Q
GRIER, B. H.	7908010420	50-293 Q
GRIER, B. H.	7908010421	50-317 Q
GRIER, B. H.	7908010422	50-3 Q
GRIER, B. H.	7908010423	50-213 Q
GRIER, B. H.	7908010424	50-412 Q
GRIER, B. H.	7908010425	50-334 Q
GRIER, B. H.	7908010426	50-219 Q
GRIER, B. H.	7908010427	50-363 Q
GRIER, B. H.	7908010428	50-322 Q
GRIER, B. H.	7908010429	50-320 Q
GRIER, B. H.	7908010430	50-309 Q
GRIER, B. H.	7908010504	50-245 Q
GRIER, B. H.	7908010506	50-410 Q
GRIER, B. H.	7908010509	50-220 Q
GRIER, B. H.	7908010513	50-333 Q
GRIER, B. H.	7908010514	50-286 Q
GRIER, B. H.	7908010519	50-277 Q
GRIER, B. H.	7908010521	50-352 Q
GRIER, B. H.	7908010522	50-387 Q
GRIER, B. H.	7908010524	50-311 Q
GRIER, B. H.	7908010526	50-443 Q
GRIER, B. H.	7908010527	50-485 Q
GRIER, B. H.	7908010528	50-29 Q
GRIER, B. H.	7908060010	50-272 Q
GRIER, B. H.	7908060012	50-244 Q
GRIER, B. H.	7908060014	50-271 Q
GRIER, B. H.	7908060207	50-293 Q
GRIER, B. H.	7908060211	50-3 Q
GRIER, B. H.	7908060366	50-213 Q
GRIER, B. H.	7908060368	50-412 Q
GRIER, B. H.	7908060372	50-363 Q
GRIER, B. H.	7908060373	50-219 Q
GRIER, B. H.	7908060378	50-322 Q
GRIER, B. H.	7908060381	50-309 Q
GRIER, B. H.	7908060383	50-245 Q
GRIER, B. H.	7908060385	50-220 Q
GRIER, B. H.	7908060398	50-410 Q
GRIER, B. H.	7908060393	50-286 Q
GRIER, B. H.	7908060395	50-333 Q
GRIER, B. H.	7908060400	50-277 Q
GRIER, B. H.	7908060489	50-352 Q
GRIER, B. H.	7908060492	50-387 Q
GRIER, B. H.	7908060494	50-311 Q
GRIER, B. H.	7908060495	50-272 Q
GRIER, B. H.	7908060497	50-443 Q
GRIER, B. H.	7908060499	50-244 Q
GRIER, B. H.	7908060504	50-485 Q
GRIER, B. H.	7908060505	50-271 Q
GRIER, B. H.	7908060507	50-29 Q
GRIER, B. H.	7908070202	70-364
GRIER, B. H.	7908070213	50-201 P
GRIER, B. H.	7908070215	70-33
GRIER, B. H.	7908070216	70-371
GRIER, B. H.	7908070219	70-820
GRIER, B. H.	7908070221	70-1143
GRIER, B. H.	7908070224	50-293 P
GRIER, B. H.	7908070227	50-317 P
GRIER, B. H.	7908070231	50-247 P
GRIER, B. H.	7908070232	50-213 P
GRIER, B. H.	7908070234	50-334 P
GRIER, B. H.	7908070240	50-219 P
GRIER, B. H.	7908070242	50-309 P
GRIER, B. H.	7908070245	50-245 P
GRIER, B. H.	7908070248	50-220 P
GRIER, B. H.	7908070251	50-286 P
GRIER, B. H.	7908070255	50-333 P
GRIER, B. H.	7908070258	50-277 P
GRIER, B. H.	7908070262	50-272 P
GRIER, B. H.	7908070263	50-244 P
GRIER, B. H.	7908070266	50-271 P
GRIER, B. H.	7908070269	50-29 P
GRIER, B. H.	7908030222	50-293 Q
GRIER, B. H.	7908030226	50-317 Q
GRIER, B. H.	7908030229	50-3 Q
GRIER, B. H.	7908030237	50-213 Q
GRIER, B. H.	7908030238	50-334 Q
GRIER, B. H.	7908030239	50-412 Q
GRIER, B. H.	7908030242	50-363 Q
GRIER, B. H.	7908030246	50-219 Q
GRIER, B. H.	7908030247	50-322 Q
GRIER, B. H.	7908030254	50-309 Q
GRIER, B. H.	7908030255	50-245 Q
GRIER, B. H.	7908030257	50-220 Q
GRIER, B. H.	7908030258	50-410 Q
GRIER, B. H.	7908030261	50-333 Q
GRIER, B. H.	7908030267	50-286 Q
GRIER, B. H.	7908030268	50-352 Q
GRIER, B. H.	7908030270	50-277 Q
GRIER, B. H.	7908030274	50-387 Q
GRIER, B. H.	7908030277	50-311 Q
GRIER, B. H.	7908030279	50-272 Q
GRIER, B. H.	7908030280	50-443 Q
GRIER, B. H.	7908030282	50-485 Q
GRIER, B. H.	7908030285	50-244 Q
GRIER, B. H.	7908030286	50-271 Q
GRIER, B. H.	7908030289	50-29 Q
GRIER, B. H.	7908300288	50-293 P
GRIER, B. H.	7908290606	50-387 F
GRIER, B. H.	7908290612	50-352 F
GRIER, B. H.	7908100212	50-293 Q
GRIER, B. H.	7908100215	50-317 Q
GRIER, B. H.	7908100219	50-3 Q
GRIER, B. H.	7908100221	50-213 Q
GRIER, B. H.	7908100222	50-334 Q
GRIER, B. H.	7908100226	50-412 Q
GRIER, B. H.	7908100228	50-219 Q
GRIER, B. H.	7908100229	50-363 Q
GRIER, B. H.	7908100232	50-322 Q
GRIER, B. H.	7908100233	50-320 Q
GRIER, B. H.	7908100237	50-309 Q
GRIER, B. H.	7908100240	50-245 Q
GRIER, B. H.	7908100241	50-336 Q
GRIER, B. H.	7908100244	50-410 Q
GRIER, B. H.	7908100247	50-220 Q
GRIER, B. H.	7908100250	50-333 Q
GRIER, B. H.	7908100253	50-286 Q
GRIER, B. H.	7908100259	50-352 Q
GRIER, B. H.	7908100261	50-277 Q
GRIER, B. H.	7908100266	50-387 Q
GRIER, B. H.	7908100269	50-272 Q
GRIER, B. H.	7908100273	50-311 Q
GRIER, B. H.	7908100276	50-443 Q
GRIER, B. H.	7908100278	50-485 Q
GRIER, B. H.	7908100282	50-244 Q
GRIER, B. H.	7908100284	50-271 Q
GRIER, B. H.	7908100285	50-29 Q
GRIER, B. H.	7908100328	50-317 Q
GRIER, B. H.	7908100330	50-3 Q
GRIER, B. H.	7908100332	50-213 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
GRIER, B. H.	7908100334	50-334	G
GRIER, B. H.	7908100338	50-320	G
GRIER, B. H.	7908100341	50-309	G
GRIER, B. H.	7908100345	50-336	G
GRIER, B. H.	7908100347	50-286	G
GRIER, B. H.	7908100349	50-272	G
GRIER, B. H.	7908100350	50-244	G
GRIER, B. H.	7908100353	50-29	G
GRIER, B. H.	7908170214	50-271	G
GRIER, B. H.	7908090276	50-293	G
GRIER, B. H.	7908090283	50-317	G
GRIER, B. H.	7908090287	50-3	G
GRIER, B. H.	7908090291	50-213	G
GRIER, B. H.	7908090293	50-334	G
GRIER, B. H.	7908090296	50-219	G
GRIER, B. H.	7908090298	50-322	G
GRIER, B. H.	7908090302	50-320	G
GRIER, B. H.	7908090306	50-309	G
GRIER, B. H.	7908090310	50-245	G
GRIER, B. H.	7908090314	50-220	G
GRIER, B. H.	7908090316	50-286	G
GRIER, B. H.	7908090320	50-333	G
GRIER, B. H.	7908090322	50-277	G
GRIER, B. H.	7908090327	50-387	G
GRIER, B. H.	7908090331	50-272	G
GRIER, B. H.	7908090335	50-244	G
GRIER, B. H.	7908090338	50-271	G
GRIER, B. H.	7908090340	50-29	G
GRIER, B. H.	7908270409	50-293	G
GRIER, B. H.	7908270419	50-317	G
GRIER, B. H.	7908280060	50-3	G
GRIER, B. H.	7908280069	50-213	G
GRIER, B. H.	7908280074	50-412	G
GRIER, B. H.	7908280079	50-334	G
GRIER, B. H.	7908280083	50-363	G
GRIER, B. H.	7908280088	50-219	G
GRIER, B. H.	7908280096	50-322	G
GRIER, B. H.	7908280115	50-320	G
GRIER, B. H.	7908280122	50-309	G
GRIER, B. H.	7908280135	50-245	G
GRIER, B. H.	7908280139	50-423	G
GRIER, B. H.	7908280142	50-410	G
GRIER, B. H.	7908280149	50-220	G
GRIER, B. H.	7908280152	50-286	G
GRIER, B. H.	7908280158	50-333	G
GRIER, B. H.	7908280161	50-277	G
GRIER, B. H.	7908280167	50-352	G
GRIER, B. H.	7908280172	50-387	G
GRIER, B. H.	7908280178	50-311	G
GRIER, B. H.	7908280180	50-272	G
GRIER, B. H.	7908280186	50-443	G
GRIER, B. H.	7908280190	50-244	G
GRIER, B. H.	7908280195	50-485	G
GRIER, B. H.	7908280200	50-271	G
GRIER, B. H.	7908280203	50-29	G
GRIER, B. H.	7908230287	50-293	G
GRIER, B. H.	7908230293	50-317	G
GRIER, B. H.	7908230295	50-3	G
GRIER, B. H.	7908230297	50-213	G
GRIER, B. H.	7908230300	50-334	G
GRIER, B. H.	7908230302	50-219	G
GRIER, B. H.	7908230304	50-320	G
GRIER, B. H.	7908230339	50-309	G
GRIER, B. H.	7908230346	50-245	G
GRIER, B. H.	7908230347	50-220	G
GRIER, B. H.	7908230356	50-286	G
GRIER, B. H.	7908230358	50-333	G
GRIER, B. H.	7908230362	50-277	G
GRIER, B. H.	7908230363	50-272	G
GRIER, B. H.	7908230364	50-244	G
GRIER, B. H.	7908230368	50-271	G
GRIER, B. H.	7908230369	50-29	G
GRIER, B. H.	7908270535	50-293	G
GRIER, B. H.	7908270538	50-317	G
GRIER, B. H.	7908270540	50-3	G
GRIER, B. H.	7908270542	50-334	G
GRIER, B. H.	7908270544	50-219	G
GRIER, B. H.	7908270551	50-309	G
GRIER, B. H.	7908270552	50-245	G
GRIER, B. H.	7908270554	50-220	G
GRIER, B. H.	7908270555	50-286	G
GRIER, B. H.	7908270557	50-333	G
GRIER, B. H.	7908270558	50-277	G
GRIER, B. H.	7908280024	50-272	G
GRIER, B. H.	7908280028	50-244	G
GRIER, B. H.	7908280030	50-271	G
GRIER, B. H.	7908280031	50-29	G
GRIER, B. H.	7908280033	50-193	G
GRIER, B. H.	7908280040	70-1100	
GRIER, B. H.	7908280046	50-170	G
GRIER, B. H.	7908280048	50-47	G
GRIER, B. H.	7908280050	50-184	G
GRIER, B. H.	7908280151	70-135	
GRIER, B. H.	7908280157	50-201	G
GRIER, B. H.	7908280199	70-33	
GRIER, B. H.	7908280201	50-54	G
GRIER, B. H.	7908280205	70-371	
GRIER, B. H.	7908280245	70-820	
GRIER, B. H.	7908280249	50-22	G
GRIER, B. H.	7908280251	70-1143	
GRIER, B. H.	7908280254	50-77	G
GRIER, B. H.	7908280261	50-208	G
GRIER, B. H.	7908280263	50-97	G
GRIER, B. H.	7908280265	50-199	G
GRIER, B. H.	7908280269	50-20	G
GRIER, B. H.	7908280272	50-5	G
GRIER, B. H.	7908280274	50-225	G
GRIER, B. H.	7908280278	50-57	G
GRIER, B. H.	7908280280	50-223	G
GRIER, B. H.	7908280284	50-166	G
GRIER, B. H.	7908280286	50-134	G
GRIER, B. H.	7908280235	50-293	G
GRIER, B. H.	7908280248	50-317	G
GRIER, B. H.	7908280255	50-3	G
GRIER, B. H.	7908280257	50-213	G
GRIER, B. H.	7908280262	50-334	G
GRIER, B. H.	7908280268	50-412	G
GRIER, B. H.	7908280273	50-219	G
GRIER, B. H.	7908280276	50-363	G
GRIER, B. H.	7908280281	50-322	G
GRIER, B. H.	7908280288	50-309	G
GRIER, B. H.	7908280292	50-245	G
GRIER, B. H.	7908280297	50-336	G
GRIER, B. H.	7908280302	50-410	G
GRIER, B. H.	7908280306	50-220	G
GRIER, B. H.	7908280310	50-286	G
GRIER, B. H.	7908280314	50-333	G
GRIER, B. H.	7908280318	50-312	G
GRIER, B. H.	7908280322	50-277	G
GRIER, B. H.	7908280327	50-387	G
GRIER, B. H.	7908280329	50-311	G
GRIER, B. H.	7908280335	50-272	G
GRIER, B. H.	7908280339	50-443	G
GRIER, B. H.	7908280343	50-244	G
GRIER, B. H.	7908280352	50-485	G
GRIER, B. H.	7908280355	50-271	G
GRIER, B. H.	7908280362	50-29	G
GRIER, B. H.	7908310218	50-193	G
GRIER, B. H.	7908310221	50-201	G
GRIER, B. H.	7908310222	50-54	G
GRIER, B. H.	7908210224	50-22	G
GRIER, B. H.	7908310225	50-170	G
GRIER, B. H.	7908310227	50-47	G
GRIER, B. H.	7908310230	50-184	G
GRIER, B. H.	7908310231	50-77	G
GRIER, B. H.	7908310233	50-208	G
GRIER, B. H.	7908310235	50-97	G
GRIER, B. H.	7908310238	50-199	G
GRIER, B. H.	7908310239	50-20	G
GRIER, B. H.	7908310240	50-5	G
GRIER, B. H.	7908310243	50-225	G
GRIER, B. H.	7908310245	50-57	G
GRIER, B. H.	7908310246	50-223	G
GRIER, B. H.	7908310248	50-166	G
GRIER, B. H.	7908310250	50-134	G
GRIER, B. H.	7908310253	50-293	G
GRIER, B. H.	7908310256	50-317	G
GRIER, B. H.	7908310259	50-3	G
GRIER, B. H.	7908310261	50-213	G
GRIER, B. H.	7908310278	50-334	G
GRIER, B. H.	7908310281	50-412	G
GRIER, B. H.	7908310283	50-363	G
GRIER, B. H.	7908310284	50-309	G
GRIER, B. H.	7908310286	50-245	G
GRIER, B. H.	7908310287	50-220	G
GRIER, B. H.	7908310288	50-286	G
GRIER, B. H.	7908310290	50-333	G
GRIER, B. H.	7908310292	50-277	G
GRIER, B. H.	7908310294	50-352	G
GRIER, B. H.	7908310299	50-387	G
GRIER, B. H.	7908310301	50-272	G
GRIER, B. H.	7908310302	50-244	G
GRIER, B. H.	7908310304	50-485	G
GRIER, B. H.	7908310306	50-271	G
GRIER, B. H.	7908310308	50-29	G
GRIER, B. H.	7908310311	50-322	G
GRIER, B. H.	7908310312	50-443	G
GRIER, B. H.	7908310315	50-311	G
GRIER, B. H.	7908300094	50-293	G
GRIER, B. H.	7908300105	50-317	G
GRIER, B. H.	7908300113	50-3	G
GRIER, B. H.	7908300114	50-213	G
GRIER, B. H.	7908300117	50-412	G
GRIER, B. H.	7908300123	50-334	G
GRIER, B. H.	7908300124	50-219	G
GRIER, B. H.	7908300127	50-363	G
GRIER, B. H.	7908300132	50-322	G
GRIER, B. H.	7908300139	50-320	G
GRIER, B. H.	7908300142	50-309	G
GRIER, B. H.	7908300146	50-245	G
GRIER, B. H.	7908300151	50-410	G
GRIER, B. H.	7908300153	50-220	G
GRIER, B. H.	7908300157	50-286	G
GRIER, B. H.	7908300161	50-333	G
GRIER, B. H.	7908300168	50-332	G
GRIER, B. H.	7908300172	50-277	G
GRIER, B. H.	7908300177	50-387	G
GRIER, B. H.	7908300182	50-311	G
GRIER, B. H.	7908300187	50-272	G
GRIER, B. H.	7908300193	50-443	G
GRIER, B. H.	7908300199	50-244	G
GRIER, B. H.	7908300203	50-485	G
GRIER, B. H.	7908300207	50-271	G
GRIER, B. H.	7908300475	50-29	G
GRIER, B. H.	7908280405	50-364	G
GRIER, B. H.	7908280409	50-348	G
GRIER, B. H.	7908280414	50-261	G
GRIER, B. H.	7908280420	50-324	G
GRIER, B. H.	7908280431	50-269	G
GRIER, B. H.	7908280436	50-369	G
GRIER, B. H.	7908280443	50-389	G
GRIER, B. H.	7908280447	50-416	G
GRIER, B. H.	7908280452	50-395	G
GRIER, B. H.	7908280456	50-395	G
GRIER, B. H.	7908280462	50-321	G
GRIER, B. H.	7908280372	50-528	G
GRIER, B. H.	7908280376	50-133	G
GRIER, B. H.	7908280379	50-275	G
GRIER, B. H.	7908280381	50-344	G
GRIER, B. H.	7908280388	50-361	G
GRIER, B. H.	7908280393	50-206	G
GRIER, B. H.	7908280395	50-312	G
GRIER, B. H.	7908280399	50-397	G
GRIMES, B. K.	7908280234*	FOIA	
GRIMES, B. K.	7908280229*	FOIA	
GRIMES, B. K.	7908280252*	FOIA	
GRIMES, B. K.	7908280240*	FOIA	
GRIMES, B. K.	7908280260*	FOIA	
GRIMES, B. K.	7908280218*	FOIA	
GRIMES, B. K.	7908280222*	FOIA	
GRIMES, B. K.	7908280271*	FOIA	
GRIMES, B. K.	7908020192	50-309	P
GRIMES, B.	7908030322	NUREG	
GRIMES, C.	7908140216	GEN TEC	IS
GRIMES, C.	7908270084	GEN TEC	IS
GRIMES, E.	7908170284	50-409	G
GRIMES, B. K.	7908080350	50-10	P
GRIMES, B. K.	7908210201	50-320	A
GRIMES, B.	7908270070	50-344	P
GRIMES, B.	7908240639	50-269	S
GRIMES, C. I.	7908280840	GEN TEC	IS
GRIMES, C. I.	7908080047	50-10	P
GRIMES, C. I.	7908270087	GEN TEC	IS
GRIMES, C. I.	7908270099	50-10	P
GROCE, R. H.	7908080313	50-309	G
GROCE, R. H.	7908080710	50-309	G
GROCE, R. H.	7908220637	50-309	G
GROCE, R. H.	7908170362	50-309	G
GROCE, R. H.	7908270517	50-309	G
GROCE, R. H.	7908170364	50-309	F
GROCE, R. H.	7908230325	50-309	F
GROCE, R. H.	7908090001	50-271	G
GROCE, R. H.	7908070673	50-29	G
GROCE, R. H.	7908010326	50-309	F
GROCE, R. H.	7908140550	50-29	P
GROCE, R. H.	7908170421	50-29	F
GROSSICK, L. V.	7908090384	50-443	H
GROTENHUIS, M. M.	7908200027*	50-280	P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GROTENHUIS, M.	7908300164*	50-280 P
GROWN, G. D.	7908020194	40-4492
GRUNDL, J. A.	7908017333	RES
GRUNDL, J. A.	7908099301	RES
GRUSH, W. H.	7908170500	RES
GUMBLE, F. W.	7908170435*	50-286 S
GUNN, S. L.	7908150496	71-6697
GUNTER, B.	7908150751*	50-320 H
GUPPY, J. G.	7908020600	RES
GUSTAFSON, R. B.	7908220169	70-371
GUSTAVE, R. P.	7908100280	CONTRACT
GUSTAVE, R. P.	7908070717	CONTRACT
GUSTAVE, R. P.	7908160422	CONTRACT
GUSTAVE, R. P.	7908090556	CONTRACT
GUSTAVE, R. P.	7908100277	CONTRACT
GUSTAVE, R. P.	7908100340	CONTRACT
HAAS, F. M.	7908240668	NUREG
HAASS, W. P.	7907310517	TOPREP
HAASS, W. P.	7907310443	ORG
HAASS, W. P.	7908010651	50-416 A
HAASS, W. P.	7908070222	ORG
HAASS, W. P.	7908210394	50-320 P
HAASS, W. P.	7908290065	TOPREP
HAASS, W. P.	7908090552	50-3 P
HAASS, W. P.	7908170135	TOPREP
HAASS, W. P.	7908230367	TOPREP
HAASS, W. P.	7908310270	TOPREP
HAGAN, J. E.	7908300641	50-395 D
HAGAN, T. F.	7908090279	CONTRACT
HAGAN, T. F.	7908220645	CONTRACT
HAGAN, T. F.	7908080412	CONTRACT
HAGAN, T. F.	7908300611	CONTRACT
HAGAN, T. F.	7908220616	CONTRACT
HAGEY, H.	7908270318*	CONTRACT
HAGEY, H.	7908080440	CONTRACT
HAGEY, H.	7908080407	CONTRACT
HAGEY, H.	7908100248	CONTRACT
HAGEY, H.	7908100262	CONTRACT
HAGEY, H.	7908280072	CONTRACT
HAGEY, H.	7908270294	CONTRACT
HAGEY, H.	7908270313	CONTRACT
HAGEY, H.	7908270357	CONTRACT
HAGEY, H.	7908290467	CONTRACT
HAGEY, H.	7908020341	CONTRACT
HAGEY, H.	7908020156	CONTRACT
HAGEY, H.	7908020356	CONTRACT
HAGEY, H.	7908100310	CONTRACT
HAGEY, H.	7908140440	CONTRACT
HAGEY, H.	7908230203	CONTRACT
HAGEY, H.	7908230101	CONTRACT
HAGGERTY, P. E.	7908130486	50-320 T
HAGGERTY, P. E.	7908030392	50-320 T
HAGGERTY, P. E.	7908030604	50-320 T
HAGGERTY, P. E.	7908030613	50-320 T
HAGRMAN, D. L.	7908110456	RES
HAIRSTON, W. G.	7908010547*	50-348 S
HAIRSTON, W. G.	7908140546*	50-348 R
HAIRSTON, W. G.	7908070492*	50-348 S
HAIRSTON, W. G.	7908140745*	50-348 S
HAIRSTON, W. G.	7908140673*	50-348 S
HAIRSTON, W. G.	7908200315*	50-348 S
HAIST, D. P.	7908150251*	50-361 G
HALE, C. J.	7908140226*	GA999
HALE, C. J.	7908130490*	GA999
HALE, C. J.	7908080012*	GA999
HALE, C. J.	7908220646*	GA999
HALL, D. C.	7908020501	PRM
HALL, W. J.	7908030521*	50-201 P
HALL, J.	7908070804	71-5
HALL, J.	7908290036	71-5
HALL, J. D.	7908200083	40-8721
HALL, R. E.	7908020519	50-213 E
HALL, R. E.	7908100185*	50-409 P
HALL, R. E.	7908210046*	50-382 G
HALL, R. E.	7908100217*	50-382 G
HALL, R. E.	7908100235*	50-556 G
HALLIGAN, T. J.	7908300756	50-387 G
HALLIGAN, T. J.	7908230488	50-387 D
HALSTED, C. G.	7908280749	71-6478
HAMMER, S. J.	7908060541*	50-262 S
HAMMER, S. J.	7908140783*	50-263 S
HAMMOND, E. L.	7908030066	50-331 P
HAMMOND, E. L.	7908010443	50-331 S
HAMMOND, E. L.	7908100418	50-331 S
HAMMOND, E. L.	7908130414	50-331 S
HAMMOND, E. L.	7908150045	50-331 S
HAMMOND, E. L.	7908210514	50-331 R
HAMMOND, E. L.	7908310370	50-331 S
HAMMOND, E. L.	7908310487	50-331 S
HANAUER, S. H.	7908170457*	FOIA
HANAUER, S. H.	7908170462*	FOIA
HANAUER, S. J.	7908300445	GEN TEC IS
HANCHETT, J. G.	7908290352	50-574 G
HANCOCK, J. A.	7908020173	REGGD
HAND, R. C.	7908090433	50-322 A
HAND, C. H.	7908150037	70-2623
HAND, C. H.	7908150042	70-2623
HAND, C. H.	7908150022	70-2623
HAND, C. H.	7908150722	70-2623
HANDLER, P.	7908170332*	COMMISSION
HANNON, J. N.	7908060133	50-324 S
HANSEN, L. J.	7907090294	71-9097
HANSELL, D.	7908160055	WASTE MGT
HANSEN, W. A.	7908150130*	50-483 G
HANSEN, W. A.	7908150176*	50-484 G
HANSON, N.	7908220327	50-466 G
HANSON, P.	7908140814*	50-295 S
HANSON, R. G.	7908020198	RES
HAPAR, H. K.	7908240365*	SECY
HARCKE, H. J.	7908020337	PRM
HARDIN, A. K.	7908170202*	50-348 G
HARDIN, A. K.	7907060448	50-269 H
HARDRATH, W. T.	7908140068	NUREG
HARDWICK, R. J.	7908240144*	50-390 G
HARDWICK, R. J.	7908030608*	50-327 G
HARDWICK, R. J.	7908240096*	50-395 G
HARGETT, D. J.	7908030381*	CONTRACT
HARGETT, D. J.	7908030369*	CONTRACT
HARGETT, D. J.	7908030396*	CONTRACT
HARGETT, D. J.	7908160540*	CONTRACT
HARGETT, D. J.	7908160544*	CONTRACT
HARGETT, D. J.	7908230096*	CONTRACT
HARGETT, D. J.	7908220330*	CONTRACT
HARGETT, D. J.	7908220682*	CONTRACT
HARGETT, D. J.	7908310135*	CONTRACT
HARGETT, D. J.	7908090610*	CONTRACT
HARGETT, D. J.	7908220533*	CONTRACT
HARGETT, D. J.	7908230150*	CONTRACT
HARGRAVE, J.	7908240622	40-8502
HARISTON, W. G.	7908010550*	50-348 S
HARLEY, D. E.	7908130406	PROJ
HARLEY, J. H.	7908090318	REGGD
HARLESS, B. L.	7908140531*	FOIA
HARMON, M.	7908220383	50-574 G
HARMON, M.	7908210540	50-574 G
HARMON, D. W.	7908030347	XPORTLIC
HARMON, D. W.	7908030553	XPORTLIC
HARMON, D. W.	7908150425	XPORTLIC
HARPER, R. G.	7908300436	XPORTLIC
HARRIS, J. L.	7908130176	50-445 M
HARRIS, J. L.	7908130215	50-445 M
HARRIS, J. L.	7908200269	50-445 M
HARRINGTON, T. P.	7908240056	NUREG
HARRINGTON, W.	7908200407*	PROJ
HARRIS, J. R.	7908170217*	50-400 G
HARRIS, J. R.	7908270262*	50-424 G
HARRIS, J. R.	7908010349*	50-424 G
HARRIS, J. R.	7908020089*	50-553 G
HARRIS, J. R.	7908300487*	50-491 G
HARRIS, J. R.	7908300583*	50-400 J
HARRISON, J. J.	7908100234*	50-341 G
HARRISON, J. J.	7908030587*	50-295 G
HARTER, E. S.	7908270375	71-92
HARTIGAN, J. P.	7908060439*	50-346 S
HARTLEY, G.	7908300523	50-522 G
HASHIMOTO, K.	7908070729	REGGD
HATCH, D. G.	7908030193*	COMMISSION
HATWAY, C. W.	7908100582	71-189
HAUES, D. W.	7908240314*	50-409 G
HAUGHNEY, C. J.	7908140143	50-201 H
HAUGHNEY, C. J.	7908070813	50-201 P
HAUPT, C. A.	7908230685	50-437 A
HAUSER, B.	7908090083	50-346 P
HAUTALA, R. L.	7908170227	40-6659
HAVERKOS, J. R.	7908210080	XPORTLIC
HAWKINS, F. C.	7908070340*	50-546 G
HAWLEY, S. C.	7908140717*	50-27 R
HAYES, P.	7908300340	50-574 A
HAYES, D. W.	7908070340*	50-546 G
HAYES, D. W.	7908030633*	50-329 G
HAYES, D. W.	7908080225*	50-358 G
HAYES, D. W.	7908150232*	50-266 G
HAYES, D. W.	7908010193*	50-373 G
HAYES, D. W.	7908150266*	50-315 G
HAYNES, J. G.	7908080394	50-206 P
HAYNES, J. G.	7908100490	50-206 P
HAYNES, J. G.	7908150253	50-206 P
HAYNES, J. G.	7908200153	50-206 P
HAYNES, R. C.	7908230449*	50-320 G
HAYNES, R. C.	7908140397*	50-528 G
HAYNES, R. C.	7908090703*	50-361 G
HAZLE, A. J.	7908270346	PROJ
HEAP, J. T.	7908280410	50-206 G
HEAD, J. T.	7908020219	50-206 G
HEARNE, T. J.	7908210324	50-486 G
HEARNE, T. J.	7908210326*	50-486 G
HECKMAN, R. A.	7908080408	NUREG
HEDGECOTH, L. J.	7908010242	50-574 G
HEGARTY, W.	7908300443*	XPORTLIC
HEIBEL, R. P.	7908100503*	50-317 S
HEIBEL, R. P.	7908230513*	50-318 S
HEIBEL, R. P.	7908270484*	50-317 S
HEIBEL, R. P.	7908270485*	50-318 S
HEIBEL, R. P.	7908280626*	50-317 S
HEIMAN, D.	7908150478	XPORTLIC
HEIMAN, D.	7908150490	XPORTLIC
HEISELBERG, E.	7908210412	50-387 D
HEISHMAN, R. F.	7908230494*	50-320 G
HEISHMAN, R. F.	7908160184	50-315 G
HEISHMAN, R. F.	7908150615*	50-358 G
HEISHMAN, R. F.	7908020548	50-10 G
HEISHMAN, R. F.	7908010223	50-10 G
HEISHMAN, R. F.	7908070819	50-295 G
HEISHMAN, R. F.	7908080180	50-373 G
HEISHMAN, R. F.	7908150357	50-315 G
HEISHMAN, R. F.	7908160117	50-282 G
HEISHMAN, R. F.	7908280204	50-155 G
HEISHMAN, R. F.	7908150080	50-282 G
HEISHMAN, R. F.	7908160313	50-346 G
HEISHMAN, R. F.	7908280228	50-255 G
HEISHMAN, R. F.	7908280188	50-305 G
HEISHMAN, R. F.	7908150286	50-237 G
HEISHMAN, R. F.	7908230132	50-315 G
HEISHMAN, R. F.	7908240640	50-254 G
HEISS	7908090470	PROJ
HELBERT, H. J.	7908080571	RES
HELFLING, R. K.	7908010662	70-2623
HELLEY, E. J.	7908070535	ORG
HELM, K.	7908080022	XPORTLIC
HELMS, R. E.	7908080372*	71-116
HELMS, R. E.	7908080375*	71-116
HELTEMES, C. J.	7906290039	50-320 G
HELTEMES, C. J.	7908150724	50-320 H
HELTEMES, C. J.	7908220545	50-312 H
HELTEMES, C. J.	7908270528	50-346 H
HELTEMES, C. J.	7908200029	50-289 G
HELTEMES, C. J.	7908200048	50-289 G
HELTEMES, C. J.	7908200014	50-289 G
HENDRIE, J. M.	7908230170*	SECY
HENDRIE, J. M.	7908230194*	SECY
HENDRIE, J. M.	7908230199*	SECY
HENDRIE, J. M.	7908230535*	COMMISSION
HENDRIE, J. M.	7908080658*	FOIA
HENDRIE, J. M.	7908010644*	10CFR
HENDRIE, J. M.	7908200406	COMMISSION
HENDRIE, J. M.	7908090459*	COMMISSION
HENDRIE, J. N.	7908010054	COMMISSION
HENDRIE, J. M.	7908010058*	COMMISSION
HENDRIE, J. M.	7908010033	10CFR
HENDRIE, J. M.	7908010175	50-293 U
HENDRIE, J. M.	7908010224	50-272 U
HENDRIE, J. M.	7908010636	10CFR
HENDRIE, J. M.	7908090501	COMMISSION
HENDRIE, J. M.	7908010040	COMMISSION
HENDRIE, J. M.	7908010047	COMMISSION
HENDRIE, J. M.	7908010658	10CFR
HENDRIE, J. M.	7908090451	COMMISSION
HENDRIE, J. M.	7908030249	COMMISSION
HENDRIE, J. M.	7908030260*	COMMISSION
HENDRIE, J. M.	7908030278*	COMMISSION
HENDRIE, J. M.	7908030321*	COMMISSION
HENDRIE, J. M.	7908030325*	COMMISSION
HENDRIE, J. M.	7908030339	COMMISSION
HENDRIE, J. M.	7908030343*	COMMISSION
HENDRIE, J. M.	7908030351*	COMMISSION
HENDRIE, J. M.	7908030359*	COMMISSION
HENDRIE, J. M.	7908030486*	COMMISSION
HENDRIE, J. M.	7908030376	COMMISSION

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HENDRIE, J. M.	7908030475	COMMISSION
HENDRIE, J. M.	7908240359*	SECY
HENDRIE, J. M.	7908030225	COMMISSION
HENDRIE, J. M.	7908030235	COMMISSION
HENDRIE, J. M.	7908030216	COMMISSION
HENDRIE, J. M.	7907030417	10CFR
HENDRIE, J. M.	7908010611	10CFR
HENDRIE, J. M.	7908030188	COMMISSION
HENDRIE, J. M.	7908030205	COMMISSION
HENDRIE, J. M.	7908080589	50-443 Q
HENDRIE, J. M.	7908030127	50-498 U
HENDRIE, J. M.	7908010620	50-312 T
HENDRIE, J. M.	7908020196	50-312 T
HENDRIE, J. M.	7908140275	COMMISSION
HENDRIE, J. M.	7908070794	COMMISSION
HENDRIE, J. M.	7908210164	COMMISSION
HENDRIE, J. M.	7908280415*	COMMISSION
HENDRIE, J. M.	7908080652	COMMISSION
HENDRIE, J. M.	7908140600	50-155 H
HENDRIE, J. M.	7908170427	COMMISSION
HENDRIE, J. M.	7908060454	COMMISSION
HENDRIE, J. M.	7908080536	10CFR
HENDRIE, J. M.	7908090625	SECY
HENDRIE, J. M.	7908060022	COMMISSION
HENDRIE, J. M.	7908080150	10CFR
HENDRIE, J. M.	7908090607	10CFR
HENDRIE, J. M.	7908100524	10CFR
HENDRIE, J. M.	7908170340	50-329 Q
HENDRIE, J. M.	7908210018	COMMISSION
HENDRIE, J. M.	7908280206*	COMMISSION
HENDRIE, J. M.	7908290144	COMMISSION
HENDRIE, J. M.	7908090614	10CFR
HENDRIE, J. M.	7908170502	50-289 P
HENDRIE, J. M.	7908100179	COMMISSION
HENDRIE, J. M.	7908100197*	COMMISSION
HENDRIE, J. M.	7908100203*	COMMISSION
HENDRIE, J. M.	7908170314	COMMISSION
HENDRIE, J. M.	7908170327	COMMISSION
HENDRIE, J. M.	7908170503	SECY
HENDRIE, J. M.	7908210364	10CFR
HENDRIE, J. M.	7908170286	COMMISSION
HENDRIE, J. M.	7908030336	10CFR
HENDRIE, J. M.	7908170587*	10CFR
HENDRIE, J. M.	7908210101	10CFR
HENDRIE, J. M.	7908220401	50-289 P
HENDRIE, J. M.	7908080139	50-289 T
HENDRIE, J. M.	7908170593	10CFR
HENDRIE, J. M.	7908240395	COMMISSION
HENDRIE, J. M.	7908170633	10CFR
HENDRIE, J. M.	7908090579	50-289 T
HENDRIE, J. M.	7908230515	COMMISSION
HENDRIE, J. M.	7908230528	COMMISSION
HENDRIE, J. M.	7908240293	COMMISSION
HENDRIE, J. M.	7908240398	COMMISSION
HENDRIE, J. M.	7908240473	COMMISSION
HENDRIE, J. M.	7908090583	10CFR
HENDRIE, J. M.	7908280287	COMMISSION
HENDRIE, J. M.	7908300769	COMMISSION
HENDRIE, J. M.	7908300773	COMMISSION
HENDRIE, J. M.	7908090566	10CFR
HENDRIE, J. M.	7908090604	10CFR
HENDRIE, J. M.	7908170309	10CFR
HENDRIE, J. M.	7908210067	50-289 T
HENDRIE, J. M.	7908210060	50-289 T
HENDRIE, J. M.	7908270247	COMMISSION
HENDRIE, J. M.	7908270254*	COMMISSION
HENDRIE, J. M.	7908270261*	COMMISSION
HENDRIE, J. M.	7908280001	COMMISSION
HENNEMAN, N.	7908240180	50-574 Q
HENRY, R. E.	7908010516	RES
HENRY, J. J.	7908170175	ORG
HENRY, J. J.	7908230454	PRM
HENSLEY, K. D.	7908140159	70-143
HENSLEY, K. D.	7908140327	70-143
HENSLEY, K. D.	7908150031	70-143
HENSLEY, K. D.	7908150043	70-143
HENSLEY, K. D.	7908140024	70-143
HENSLEY, K. D.	7908150242	70-143
HERBEIN, J. G.	7908230257*	50-320 P
HERBEIN, J. G.	7908150721	50-289 Q
HERBEIN, J. G.	7908150723	50-289 Q
HERBEIN, J. G.	7908070680	50-289 Q
HERBEIN, J. G.	7908150719	50-289 Q
HERBEIN, J. G.	7908010505	50-289 P
HERBEIN, J. G.	7908010260	50-320 P
HERBEIN, J. G.	7908010367	50-289 P
HERBEIN, J. G.	7908060251	50-289 P
HERBEIN, J. G.	7908100461	50-289 S
HERBEIN, J. G.	7908080486	50-289 P
HERBEIN, J. G.	7908090381	50-320 H
HERBEIN, J. G.	7908220010	50-320 H
HERBEIN, J. G.	7908130409	50-289 P
HERBEIN, J. G.	7908170426	50-289 S
HERBEIN, J. G.	7908230342	50-289 P
HERBEIN, J. G.	7908170354	50-289 P
HERBEIN, J. G.	7908210378	50-289 Q
HERBEIN, J. G.	7908270438	50-289 R
HERBEIN, J. G.	7908280549	50-289 P
HERBEIN, J. G.	7908280557	50-289 P
HERDT, A. R.	7908270310*	50-413 Q
HERDT, A. R.	7908280182*	50-281 Q
HERDT, A. R.	7908240284*	50-281 Q
HERDT, A. R.	7908240202*	50-281 Q
HERDT, A. R.	7908080720*	50-338 P
HERDT, A. R.	7908020544*	50-416 Q
HERDT, A. R.	7908020205*	50-566 Q
HERDT, A. R.	7908030584*	50-250 Q
HERDT, A. R.	7908210279*	50-250 Q
HERDT, A. R.	7908160341*	50-395 Q
HERDT, A. R.	7908240151*	50-281 Q
HERDT, A. R.	7908240366*	50-348 Q
HERDT, A. R.	7908240132*	50-302 Q
HERDT, A. R.	7908230684*	50-348 Q
HERDT, A. R.	7908240311*	50-269 Q
HERDT, A. R.	7908200221*	50-400 Q
HERDT, A. R.	7908240127*	50-302 Q
HERDT, A. R.	7908230662*	50-261 Q
HERLIHY, D. M.	7908310047	40-8728
HERNANDEZ, G.	7908090703*	50-361 Q
HERNANDEZ, G.	7908130199*	50-522 Q
HERRING, K. S.	7908020328*	50-70 P
HERSCH, M. M.	7908150141	XPORTLIC
HERSCH, M. M.	7908170220	XPORTLIC
HERSCH, M. M.	7908160051	XPORTLIC
HERSHEY, M. L.	7908160406	50-387 Q
HESS, L.	7908200137*	50-463 Q
HESS, G. L.	7908240331	70-1489
HESS, R. J.	7908220664	XPORTLIC
HESS, R. J.	7908220666*	XPORTLIC
HETTINGER, R. N.	7908300051*	50-522 Q
HEWARD, R. W.	7908230251*	50-320 P
HICKLE, B. J.	7908140758*	50-285 R
HIGGINBOTHAM, L.	7908030560*	27-39
HILBISH, J.	7908090372	50-320 R
HILLMAN, C. R.	7908210614	70-2623
HINCKLEY, D. G.	7908240336*	50-324 Q
HIND, J. A.	7908010415	50-295 Q
HIND, J. A.	7908010356*	50-151 Q
HIND, J. A.	7908090257*	50-295 Q
HIND, J. A.	7908090242	50-295 Q
HIND, J. A.	7908010353	50-151 Q
HIND, J. A.	7908070053	50-295 Q
HIND, J. A.	7908020263	50-305 Q
HIND, J. A.	7908020260*	70-1193
HIND, J. A.	7908020254	70-1193
HIND, J. A.	7908130127	50-295 Q
HIND, J. A.	7908010009*	50-409 Q
HIND, J. A.	7908010002	50-409 Q
HIND, J. A.	7908170099	50-151 Q
HINES, E.	7908020265	50-341 Q
HINES, E.	7908030602	50-341 Q
HINES, E.	7908280437	50-341 Q
HINES, E.	7908100177	50-341 Q
HINSON, E. W.	7908010486	50-510 Q
HIROSHIMA, K.	7908240524*	SECY
HIRT, C. W.	7908100387	NUREG
HITCHENS, D. C.	7908070496*	50-346 S
HITCHENS, D. C.	7908100501*	50-346 S
HOATSON, D. A.	7908150650	50-320 P
HOBSON, D. O.	7908020135	RES
HOBSON, D. O.	7908070694	NUREG
HODDER, M. H.	7908290073	50-389 Q
HODDER, M. H.	7908290073	50-389 Q
HODGES, C. W.	7908220383	50-574 Q
HODGES, C. W.	7908210540	50-574 Q
HODGES, F. R.	7908200134*	50-556 A
HODGES, F. R.	7908200295*	50-546 A
HOEFLING, R. K.	7905310454	50-322 Q
HOEFLING, R. K.	7906210363	70-2623
HOEFLING, R. K.	7908070104	70-2623
HOEFLING, R. K.	7908070160*	70-2623
HOEFLING, R. K.	7908130035	50-322 Q
HOEFLING, R. K.	7908020414	50-329 Q
HOEFLING, R. K.	7908020277	70-2623
HOEFLING, R. K.	7908150009	50-322 Q
HOEFLING, R. K.	7908080053	50-329 Q
HOEFLING, R. K.	7908220379	50-322 H
HOEFLING, R. K.	7908020382	50-322 A
HOELLER, J.	7908140588*	50-265 S
HOELSCHER, J.	7908170519	50-599 Q
HOFFMAN, D. P.	7908030597	50-255 Q
HOFFMAN, D. P.	7908030027	50-255 Q
HOFFMAN, D. P.	7908080107*	50-255 Q
HOFFMAN, D. P.	7908080309	50-255 Q
HOFFMAN, D. P.	7908100172*	50-155 Q
HOFFMAN, D. P.	7908070376	50-155 Q
HOFFMAN, D. P.	7908090654	50-255 Q
HOFFMAN, D. P.	7908030088	50-155 P
HOFFMAN, D. P.	7908090586	50-155 Q
HOFFMAN, D. P.	7908140099	50-255 Q
HOFFMAN, D. P.	7908010503	50-255 S
HOFFMAN, D. P.	7908200309	50-255 Q
HOFFMAN, D. P.	7908070606	50-255 P
HOFFMAN, D. P.	7908240530	50-255 Q
HOFFMAN, D. P.	7908030424	50-255 P
HOFFMAN, J. Q.	7908060421	50-255 S
HOFFMAN, D. P.	7908060432	50-255 S
HOFFMAN, D. P.	7908060349	50-155 P
HOFFMAN, D. P.	7908140773	50-155 H
HOFFMAN, D. P.	7908170387	50-155 P
HOFFMAN, D. P.	7908150503	50-155 H
HOFFMAN, D. P.	7908170401	50-255 S
HOFFMAN, D. P.	7908220311	50-255 Q
HOFFMAN, D. P.	7908230407	50-255 S
HOFFMAN, D. P.	7908230473	50-255 P
HOFFMAN, D. P.	7908270389	50-255 S
HOFFMAN, D. P.	7908270447	50-255 P
HOFFMAN, D. P.	7908280004	50-255 P
HOFFMAN, D. P.	7908280025	50-155 F
HOFFMAN, D. P.	7908280005	50-255 Q
HOFFMAN, D. P.	7908290663	50-255 S
HOGGATT, G. D.	7908240454	50-70 P
HOLLAND, K.	7908140291*	COMMISSION
HOLM, J. S.	7908210569*	TOPREP
HOLMES, M. H.	7908290616*	50-267 R
HOLOWAY, C. F.	7908140622	RES
HOOD, D.	7908020417*	50-329 Q
HOOD, D.	7908030155	50-329 A
HOOD, D.	7908100380	50-329 A
HOOD, D.	7908210049	50-329 A
HOOD, D.	7908230140	50-329 A
HOOPER, F. F.	7908090342	50-358 Q
HOOPER, C. M.	7908130657	70-33
HOOPER, C. M.	7908230252	70-33
HOOPER, J. L.	7908230686	NUREG
HOOPER, F. F.	7908300014	50-522 Q
HOOPER, F. F.	7908070283	50-522 T
HOOPER, F. F.	7908060056	50-522 T
HOOPER, F. F.	7908070277	50-522 T
HOOPER, F. F.	7908060086	50-522 T
HOOPER, F. F.	7908060037	50-522 T
HOOPER, F. F.	7908030272	50-522 T
HOOPER, F. F.	7908090644	50-522 T
HOOPER, F. F.	7908100401	50-522 T
HOOPER, F. F.	7908090619	50-522 T
HOOPER, F. F.	7908140141	50-358 T
HOOPER, F. F.	7908150026	50-358 T
HOOPER, F. F.	7908150727	50-358 T
HOOPER, F. F.	7908150725	50-358 T
HOPE, F. F.	7908280455	71-335
HOPE, F. F.	7908280460*	71-335
HOPKINS, J. P.	7908090208	50-346 P
HOPPER, C. M.	7908290626	70-33
HOPPER, C. M.	7908150517	70-33
HORAK, H.	7908030175	RES
HORNBACKER, T. E.	7908090525	PROJ
HOSEY, C. M.	7908160491*	50-321 Q
HOSEY, C. M.	7908160327*	50-321 Q
HOSKINSON, R. L.	7908080571	RES
HOSSLER, D. E.	7908270148*	50-289 Q
HOWARD, R. E.	7908100109*	GA999
HOWARD, R. E.	7908100097*	GA999
HOWARD, J. E.	7908290460	50-471 A
HOWARD, E. M.	7908230338	50-320 Q
HOWARD, E. M.	7908230340*	50-320 Q
HOWARD, E. M.	7908230481*	50-320 Q
HOWARD, E. M.	7908230476	50-320 Q
HOWARD, E. M.	7908230334	50-320 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HOWE, P. W.	7908160351	50-400 Q
HOWE, P. W.	7908200209	50-400 Q
HOWE, P. W.	7908300575	50-400 Q
HOWELL, S. H.	7908130758*	50-320 P
HOWELL, S. H.	7908090297	50-329 Q
HOWELL, S. H.	7908060212*	50-329 Q
HOWELL, S. H.	7908150418*	50-329 Q
HOWELL, S. H.	7908090632	50-329 Q
HOWELL, S. H.	7908230048	50-329 A
HOWELL, S. H.	7908130658	50-329 Q
HOWELL, S. H.	7908060236	50-329 A
HOWELL, S. H.	7908080124	50-329 K
HOWELL, S. H.	7908210447	50-329 S
HOWELL, S. H.	7908210477	50-329 S
HOWELL, S. H.	7908290402	50-329 S
HOWELL, S. H.	7908290560	50-329 S
HOWELL, S. H.	7908210421	50-329 S
HOWELL, S. H.	7908210447	50-329 S
HOWELL, S. H.	7908210477	50-329 S
HOWELL, S. H.	7908290402	50-329 S
HOWELL, S. H.	7908290560	50-329 S
HOWELL, J. C.	7908010356*	50-151 Q
HOWLETT, G. H.	7908160444*	50-336 R
HOWLETT, D. B.	7908030385*	50-220 F
HOYLE, A.	7908230081	CONTRACT
HOYLE, J. C.	7908030565	50-289 Q
HOYLE, J. C.	7908200017*	50-289 Q
HOYLE, J. C.	7908030512	PRM
HUBBARD, R. B.	7908170445	FOIA
HUBBARD, R. B.	7908220056	FOIA
HUEBSCH, J.	7908020425	RES
HUFHAM, J. W.	7908100[illegible]	50-413 Q
HUFHAM, J. W.	7908020[illegible]	50-824
HUFHAM, J. W.	7908[illegible]0573*	50-[illegible]24 Q
HUFHAM, J. W.	7908290221*	50-302 Q
HUFHAM, J. W.	7908280171*	50-280 Q
HUFHAM, J. W.	7908170283*	50-553 Q
HUGHES, D.	7908130261	50-445 M
HUGHES, J.	7908070210*	50-358 Q
HULMAN, L. G.	7908130315	50-293 P
HULMAN, L. G.	7908150768	50-320 P
HULMAN, L. G.	7908010130	PROJ
HUMPHREY, J. M.	7908150687*	TOPREP
HUNGERFORD, M.	7908080729	FOIA
HUNNICUTT, D. M.	7908070195*	QA999
HUNNICUTT, D. M.	7908100399*	QA999
HUNNICUTT, D. M.	7908100125*	QA999
HUNNICUTT, D. M.	7908220316*	QA999
HUNNICUTT, D. M.	7908220670*	QA999
HUNNICUTT, D. M.	7908090237*	QA999
HUNNICUTT, D. M.	7908090115*	QA999
HUNNICUTT, D. M.	7908090222*	QA999
HUNNICUTT, D. M.	7908100260*	QA999
HUNNICUTT, D. M.	7908100508*	QA999
HUNNICUTT, D. M.	7908100651*	QA999
HUNNICUTT, D. M.	7908200045*	QA999
HUNNICUTT, D. M.	7908130170*	QA999
HUNNICUTT, D. M.	7908080006*	QA999
HUNSTAD, A. A.	7908160440*	50-282 R
HUNSTAD, A. A.	7908200293*	50-282 S
HUNSTAD, A. A.	7908280542*	50-282 S
HUNSTAD, A. A.	7908280591*	50-282 S
HUNT, M. D.	7908170061*	50-369 Q
HUNT, M. D.	7908160349*	50-424 Q
HUNTER, R. S.	7908280572	50-315 F
HUNTER, R. S.	7908280610	50-315 H
HUNTER, D. R.	7908290630	50-320 T
HUNTER, D. R.	7908290720	50-320 T
HUNTER, D. R.	7908290615	50-320 T
HUNTER, D. R.	7908280645	50-320 T
HUNTER, D. R.	7908290425	50-320 T
HUNTER, D. R.	7908290524	50-320 T
HUNTER, D. R.	7908300216	50-320 T
HUNTER, D. R.	7908280696	50-320 T
HUNTER, D. R.	7908290640	50-320 T
HUNTER, D. R.	7908290431	50-320 T
HUNTER, D. R.	7908280802	50-320 T
HUNTER, D. R.	7908290376	50-320 T
HUNTER, D. R.	7908290503	50-320 T
HUNTER, D. R.	7908290515	50-320 T
HUNTER, D. R.	7908290539	50-320 T
HUNTER, D. R.	7908290610	50-320 T
HUNTER, W. T.	7908290123	50-320 T
HUNTER, D. R.	7908290170	50-320 T
HUNTER, D. R.	7908300229	50-320 T
HUNTER, D. R.	7908290191	50-320 T
HUNTER, D. R.	7908290195	50-320 T
HUNTER, D. R.	7908290149	50-320 T
HUNTER, D. R.	7908280772	50-320 T
HUNTER, D. R.	7908280779	50-320 T
HUNTER, D. R.	7908280787	50-320 T
HUNTER, D. R.	7908280795	50-320 T
HUNTER, D. R.	7908280813	50-320 T
HUNTER, D. R.	7908280852	50-320 T
HUNTER, D. R.	7908290052	50-320 T
HUNTER, D. R.	7908290224	50-320 T
HUNTER, D. R.	7908290043	50-320 T
HUNTER, D. R.	7908290059	50-320 T
HUNTER, V. H.	7908200032*	GA999
HUNTINGTON, M.	7908280583	50-387 Q
HURSH, G.	7908150276	50-312 Q
HUSSMAN, T. A.	7908230469	50-320 P
HU[illegible]	7908090286*	TOPREP
HUTSON, T. W.	7908140397*	50-528 Q
HUTSON, T. W.	7908150233*	50-275 Q
HUTSON, T. W.	7908200235*	50-275 Q
HUTTON, J. C.	7908100475*	50-244 S
HUTTON, P. H.	7908240056	NUREG
IANNI, P. W.	7908150687*	TOPREP
IANNI, P. W.	7908310446*	TOPREP
IANNI, P. W.	7908270385*	TOPREP
IHRIG, R.	7908270939	50-484 Q
IHRIG, R.	7908270545*	50-484 Q
IHRIG, R.	7908240549	50-484 Q
INDYKE, C. M.	7908300248*	50-596 Q
INDYKE, C. M.	7908300224	50-596 Q
INMAN, G. W.	7908020350	RES
INMAN, G. W.	7908020387	RES
IORII, J. A.	7908170407*	TOPREP
IPPOLITO, T. A.	7908060179	50-263 P
IPPOLITO, T. A.	7908060544	50-293 P
IPPOLITO, T. A.	7908130339	50-10 Q
IPPOLITO, T. A.	7908080073	50-271 P
IPPOLITO, T. A.	7908130298	50-220 P
IPPOLITO, T. A.	7908130303	50-333 P
IPPOLITO, T. A.	7908060191*	50-271 P
IPPOLITO, T. A.	7908300042	50-298 P
IPPOLITO, T. A.	7908300054	50-259 P
IPPOLITO, T. A.	7908170523	50-133 P
IPPOLITO, T. A.	7908170528*	50-133 P
IPPOLITO, T. A.	7908170536*	50-133 P
IPPOLITO, T. A.	7908210358	50-293 P
IPPOLITO, T. A.	7908170577	50-321 P
IPPOLITO, T. A.	7908170585*	50-321 P
IPPOLITO, T. A.	7908080303	50-293 Q
IPPOLITO, T. A.	7908080306	50-237 Q
IPPOLITO, T. A.	7908080314	50-324 Q
IPPOLITO, T. A.	7908080319	50-321 Q
IPPOLITO, T. A.	7908080320	50-331 Q
IPPOLITO, T. A.	7908080321	50-220 Q
IPPOLITO, T. A.	7908080324	50-298 Q
IPPOLITO, T. A.	7908080327	50-263 Q
IPPOLITO, T. A.	7908080329	50-333 Q
IPPOLITO, T. A.	7908080334	50-277 Q
IPPOLITO, T. A.	7908080336	50-133 Q
IPPOLITO, T. A.	7908080338	50-259 Q
IPPOLITO, T. A.	7908080340	50-271 Q
IPPOLITO, T. A.	7908150132	50-259 P
IPPOLITO, T. A.	7908170212	50-331 P
IPPOLITO, T. A.	7908300036	50-366 P
IPPOLITO, T. A.	7908300048	50-333 P
IPPOLITO, T. A.	7908300040	50-333 P
IPPOLITO, T. A.	7908220576	50-298 P
IPPOLITO, T. A.	7908220584*	50-298 P
IPPOLITO, T. A.	7908300213	50-259 P
IPPOLITO, T. A.	7908170552	50-366 P
IPPOLITO, T. A.	7908170561*	50-366 P
IPPOLITO, T. A.	7908170570*	50-366 P
IPPOLITO, T. A.	7908220373	50-220 P
IPPOLITO, T. A.	7908220378*	50-220 P
IPPOLITO, T. A.	7908220387*	50-220 P
IPPOLITO, T. A.	7908170602	50-254 P
IPPOLITO, T. A.	7908170604*	50-254 P
IPPOLITO, T. A.	7908170611*	50-254 P
IPPOLITO, T. A.	7908270101	50-321 P
IPPOLITO, T. A.	7908270107*	50-321 P
IPPOLITO, T. A.	7908270116*	50-321 P
IPPOLITO, T. A.	7908300610	50-293 P
IPPOLITO, T. A.	7908230690	50-261 P
IPPOLITO, T. A.	7908240041	50-333 P
IPPOLITO, T. A.	7908240047*	50-333 P
IPPOLITO, T. A.	7908240054*	50-333 P
IPPOLITO, T. A.	7908170069	50-10 Q
IPPOLITO, T. A.	7908170285	50-10 Q
IPPOLITO, T. A.	7908170292	50-10 Q
IPPOLITO, T. A.	7908170297	50-10 Q
IPPOLITO, T. A.	7908200010	50-10 Q
IPPOLITO, T. A.	7908200035	50-10 Q
IPPOLITO, T. A.	7908200039	50-10 Q
IPPOLITO, T. A.	7908210351	50-133 P
IPPOLITO, T. A.	7908210445	50-249 H
IPPOLITO, T. A.	7908210453	50-249 H
IPPOLITO, T. A.	7908290108	50-10 Q
IPPOLITO, T. A.	7908290319	50-133 P
IRVINE, R.	7908310043	FOIA
IRVING, S. M.	7908030418	50-382 Q
ISHERWOOD, D.	7908080408	NUREG
ISKANDER, S. K.	7908070781	NUREG
JABBOUR, K. N.	7908210161	50-255 P
JABLONSKI, F. J.	7908150266*	50-315 Q
JACKSON, F. D.	7908020029	40-4492
JACKSON, J. B.	7908130404	PROJ
JACKSON, J. F.	7908070803	NUREG
JACKSON, J. F.	7908140104	NUREG
JACKSON, L. L.	7908290093	50-320 T
JACKSON, R.	7908030109	70-1113
JACKSON, R.	7908030087	70-1151
JACKSON, R. E.	7908150223	50-553 A
JACKSON, R. E.	7908300605	40-7580
JACKSON, L. L.	7908290172	50-320 T
JACOBS, B.	7908300528	50-522 Q
JACOBS, C. B.	7908010629	REGOD
JACOBSON, B. S.	7908170575	70-597
JACOBSEN, G. W.	7908140544	50-522 A
JADERNAK, M.	7908150494*	50-320 Q
JAECH, J. L.	7908210569*	TOPREP
JAECH, J. L.	7908210577*	TOPREP
JANECEK, R. F.	7908010300	50-237 F
JANECEK, R. F.	7908010445	50-10 P
JANECEK, R. F.	7908010470	50-10 P
JANECEK, R. F.	7908060225	50-254 Q
JANECEK, R. F.	7908020419	50-10 P
JANECEK, R. F.	7908030302	50-237 P
JANECEK, R. F.	7908030478	50-237 P
JANECEK, R. F.	7908030140	50-237 P
JANECEK, R. F.	7908210284	50-10 P
JANECEK, R. F.	7908200267	50-10 P
JANECEK, R. F.	7908200336	50-10 P
JANECEK, R. F.	7908200358	50-10 P
JANECEK, R. F.	7908200380	50-10 P
JANECEK, R. F.	7908210256	50-10 P
JANECEK, R. F.	7908280392	50-237 P
JANECEK, R. F.	7908240447	50-10 P
JANECEK, R. F.	7908280575	50-237 P
JANECEK, R. F.	7908230420	50-10 P
JANINEK, M.	7908030625	AGREEMENT
JANINEK, M.	7908140346	AGREEMENT
JANINEK, M.	7908170631	AGREEMENT
JANINEK, M.	7908070193	AGREEMENT
JANINEK, M.	7908140029	AGREEMENT
JANKLOW, W. J.	7908170248	40-1341
JANSEN, T.	7908080405*	50-247 S
JANUSKA, A. Q.	7908150375*	50-254 Q
JAPE, F.	7908170515*	50-269 Q
JAPE, F.	7908300544*	50-269 Q
JARRELL, D. B.	7908080487	RES
JEFFERSON, R. M.	7908150243	PROJ
JEFFRIES, S.	7908020506	50-338 Q
JENCKES, T. A.	7908010614	REGOD
JENKINS, J. E.	7908300654	50-395 D
JENKINS, H. D.	7908240124*	50-335 Q
JENKINS, G. R.	7908280123*	50-338 Q
JENKINS, G. R.	7908160491*	50-321 Q
JENKINS, G. R.	7908160487*	50-348 Q
JENKINS, G. R.	7908150216*	50-280 Q
JENKINS, G. R.	7908160327*	50-321 Q
JENKINS, H. D.	7908170573*	50-321 Q
JENKINS, H. D.	7908240336*	50-324 Q
JENKS, M. C.	7908150065*	FOIA
JENNEKENS, J. H.	7908220097	50-320 P
JENS, W. H.	7908140624	50-16 A
JENSEN, C. E.	7908230529*	50-346 S
JEPPSEN, H. C.	7908140572	50-387 Q
JERNIGAN, E. P.	7908200060*	50-336 Q
JOHANNESON, O. H.	7908010576*	TOPREP
JOHN, D. F.	7908220094	50-445 M
JOHNSON, W. B.	7908130560	PRM
JOHNSRUD, J. H.	7908170224*	50-289 P
JOHNSON, J. H.	7908300341	50-387 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JOHNSON, J H	7908300353	50-387 Q
JOHNSON, J H	7908300369*	50-387 Q
JOHNSRUD, J H	7908300284	PROJ
JOHNSON, B	7908080156	50-454 Q
JOHNSON, B	7908030451	FOIA
JOHNSON, B	7908150341	50-454 Q
JOHNSON, B	7908150354*	50-454 Q
JOHNSON, J D	7908020350	RES
JOHNSON, J D	7908020387	RES
JOHNSON, N R	7908150148	XPORTLIC
JOHNSON, N R	7908310557	XPORTLIC
JOHNSON, R W	7908080067	50-344 Q
JOHNSON, R W	7908300302	50-344 Q
JOHNSON, M C	7908160280	50-395 Q
JOHNSON, M C	7908240087*	50-395 Q
JOHNSON, M C	7908160325	50-395 Q
JOHNSON, M C	7908230558	50-395 S
JOHNSON, J J	7908100406*	50-346 S
JOHNSON, E H	7908020581	50-298 Q
JOHNSON, W D	7908090691*	50-313 Q
JOHNSON, P	7908170123*	50-312 Q
JOHNSTON, G W	7908150443*	50-326 Q
JONES, B M	7908150493*	50-538 P
JONES, D W	7908150490	50-538 P
JONES, C C	7908010579	RES
JONES, D C	7908020275	RES
JONES, D C	7908020283	RES
JONES, G C	7908010545	RES
JORDAN, D S	7908280408	71-111
JORDAN, W S	7908300264	50-568 Q
JORDAN, W S	7908300281*	50-568 Q
JORDAN, W S	7908010539	50-443 Q
JORDAN, W S	7908010544*	50-443 Q
JORDAN, H	7908080617*	50-390 A
JORDAN, W H	7908080273*	50-596 Q
JORDAN, E L	7908130507	50-312 P
JORDAN, E L	7908020218	50-331 Q
JORDAN, E L	7908150161	TOPREP
JORDAN, E L	7908030136	50-331 P
JORDON, E L	7908300414	50-271 Q
JORGENSEN, B L	7908280233*	50-255 Q
JOSEPHS, B	7908160083	70-1426
JOY, D R	7908150427	70-143
JOY, W R	7908240180	50-574 Q
JOYNER, L L	7908210299*	TOPREP
JOYNER, J H	7908240040*	XPORTLIC
JOYNER, J H	7908210158*	70-135
JOYNER, J H	7908170093*	70-1143
JULIANO, D P	7908210091	50-320 H
JURY, M J	7908210353	50-155 F
KAFIN, R J	7908030007	50-596 Q
KAFIN, R J	7908300741	50-596 Q
KAHLE, J B	7908150609*	70-1151
KAHLE, J B	7908170158*	70-27
KAHLE, J B	7908290237*	70-824
KAHLE, J B	7908270282*	70-143
KAHLE, J B	7908300568*	70-143
KAHN, B	7908080416	NUREG
KALENEVITCH, B	7908280623	50-320 T
KALIVIANAKIS, N	7908010680	71-9111
KALIVIANAKIS, N	7908200192	71-9113
KALIVIANAKIS, N	7908200263*	71-9113
KALIVIANAKIS, N	7908210027	71-6574
KALIVIANAKIS, N	7908070617	50-254 P
KALIVIANAKIS, N	7908140680	50-254 S
KALIVIANAKIS, N	7908140604	50-265 S
KALIVIANAKIS, N	7908140582	50-265 S
KALIVIANAKIS, N	7908140623	50-265 S
KALIVIANAKIS, N	7908230431	50-254 R
KALIVIANAKIS, N	7908280570	50-254 R
KANE, W F	7908150761	50-320 P
KANE, W F	7908080141	FOIA
KANE, W F	7908060209	50-10 P
KAPLAN, A L	7908140157	70-1113
KAPLAN, A L	7908140236	70-1113
KAPLAN, A L	7908010710	71-9018
KAPLAN, A L	7908020107	71-9019
KAPLAN, A L	7908280782	71-5331
KAPLAN, A L	7908140486	70-1113
KAPLAN, A L	7908230651	70-1113
KAPLAN, D S	7908170293	50-312 Q
KAPPLE, A W	7908030221*	50-272 S
KAPPLE, A W	7908030463*	50-272 S
KAPPLE, A W	7908140820*	50-272 S
KAPPLE, A W	7908300517*	50-272 S
KAPPLE, A W	7908300636*	50-272 S
KARMAN, M	7908020558	50-599 Q
KARMAN, M	7908080195*	50-454 Q
KARULA, L	7908200345*	50-247 R
KEANE, S E	7908300612	50-309 Q
KEANE, S E	7908300616*	50-309 Q
KEBLUSEK, S	7908170149	50-263 P
KEE, E J	7908010437	RES
KEELER, C D	7908170500	RES
KEENAN, T	7908310037	FOIA
KEENAN, R P	7908030253*	XPORTLIC
KEENAN, R P	7908160106	XPORTLIC
KEENAN, R P	7908220424*	XPORTLIC
KEENAN, T D	7908220350	50-271 P
KEENEY, R L	7908090543	NUREG
KEENON, T D	7908010277	50-271 P
KEEPING, W	7908010691*	50-596 A
KEIMIG, R R	7908230640*	50-320 Q
KEIMIG, R R	7908080178*	50-286 Q
KEIMIG, R R	7908020121*	50-309 Q
KEIMIG, R R	7908020100*	50-247 Q
KEIMIG, R R	7908020154*	50-272 Q
KEIMIG, R R	7908130638*	50-29 Q
KELBER, C N	7908230006	50-320 P
KELLEY, R B	7908080452	TOPREP
KELLEY, R C	7908020338*	50-461 Q
KELLEY, R E	7908090576*	50-316 Q
KELLEHER, S A	7908100474	50-568 D
KELLEY, R J	7908030316	50-366 P
KELLEY, D L	7908020105*	50-285 Q
KELLEY, D L	7908030206*	50-285 Q
KELLEY, W D	7908130382*	QA999
KELLEY, C B	7908280819	50-320 T
KELLEY, C B	7908280827	50-320 T
KELLOGG, P J	7908010650*	50-302 Q
KELLOGG, P J	7908090025*	50-269 Q
KELLOGG, P J	7908150274*	50-280 Q
KELLOGG, P J	7908160457*	50-280 Q
KELLOGG, P J	7908220418*	50-338 Q
KELLOGG, P J	7908160194*	50-250 Q
KELLOGG, P J	7908240181*	50-324 Q
KELLOGG, P J	7908150533*	50-280 Q
KELLOGG, P J	7908240213*	50-280 Q
KELLOGG, P J	7908230598*	50-395 Q
KELLOGG, P J	7908240326*	50-280 Q
KELLOGG, P J	7908240336*	50-324 Q
KELLY, R J	7908030148	50-321 P
KELLY, R J	7908150679	50-321 H
KELLY, R J	7908160403	50-321 Q
KELLY, R J	7908210430	50-366 P
KELLY, R J	7908270468	50-321 F
KEMENY, J G	7908130486	50-320 T
KEMENY, J G	7908030392	50-320 T
KEMENY, J G	7908030604	50-320 T
KEMENY, J G	7908030609	50-320 T
KEMENY, J G	7908030613	50-320 T
KEMENY, J G	7908030616	50-320 T
KENBERGER, D L	7908230667*	50-460 Q
KENDRICK, J R	7908300110	50-338 Q
KENNAN, K P	7908300596	XPORTLIC
KENNAN, K P	7908030259*	XPORTLIC
KENNA, W B	7908030626*	50-269 Q
KENNA, W B	7908240277*	50-259 Q
KENNA, W B	7908240160*	70-143
KENNA, W B	7908210316*	50-321 Q
KENNA, W B	7908170479	70-143
KENNA, W B	7908270105	70-2842
KENNA, W B	7908270109*	70-2842
KENNA, W B	7908240107	50-250 Q
KENNA, W B	7908150543	70-143
KENNA, W B	7908240143	70-143
KENNA, W B	7908030611	50-269 Q
KENNA, W B	7908270115	70-143
KENNA, W B	7908230655*	70-1113
KENNA, W B	7908220054	50-259 F
KENNA, W B	7908220058	70-1113
KENNA, W B	7908160075	70-1113
KENNA, W B	7908170616	70-1151
KENNA, W B	7908240228	50-259 Q
KENNA, W B	7908210304	50-321 Q
KENNEDY, R T	7908020196	50-312 T
KENNEDY, W J	7908230602	50-495 B
KENNEDY, W J	7908010387	50-495 A
KENNEDY, E M	7908030193*	COMMISSION
KENNEDY, R T	7908010644*	10CFR
KENNEDY, R T	7908100315	10CFR
KENNEDY, R T	7908240359*	SECY
KENNEDY, R T	7908030589	50-443 Q
KENNEDY, R T	7908010620	50-312 T
KENNEDY, R T	7908080536	10CFR
KENNEDY, R T	7908090625	SECY
KENNEDY, R T	7908080150	10CFR
KENNEDY, R T	7908090607	10CFR
KENNEDY, R T	7908100524	10CFR
KENNEDY, R T	7908090614	10CFR
KENNEDY, R T	7908170502	50-289 P
KENNEDY, R T	7908210364	10CFR
KENNEDY, R T	7908030336	10CFR
KENNEDY, R T	7908170587*	10CFR
KENNEDY, R T	7908210101	10CFR
KENNEDY, R T	7908220401	50-289 P
KENNEDY, R T	7908080139	50-289 T
KENNEDY, R T	7908170593	10CFR
KENNEDY, R T	7908170633	10CFR
KENNEDY, R T	7908090579	50-289 T
KENNEDY, R T	7908090566	10CFR
KENNEDY, R T	7908090604	10CFR
KENNEDY, R T	7908170309	10CFR
KENNEDY, R T	7908210067	50-289 T
KENNEDY, R T	7908210060	50-289 T
KENNEKE, A	7908080649*	FOIA
KENNEKE, A P	7908010640*	10CFR
KEOHANE, H J	7908070399	50-568 D
KEPFORD, C	7908150483*	50-320 Q
KEPFORD, C	7908150485*	50-320 Q
KEPFORD, C	7908150769*	50-320 Q
KEPPLER, J G	7908090058*	50-331 S
KEPPLER, J G	7908160306*	50-346 P
KEPPLER, J G	7908070308	50-346 Q
KEPPLER, J G	7908020310	50-305 Q
KEPPLER, J G	7908010069	50-358 U
KEPPLER, J G	7908070203	50-358 Q
KEPPLER, J G	7908150358	50-358 Q
KEPPLER, J G	7908010085	50-373 Q
KEPPLER, J G	7908080212	50-358 Q
KEPPLER, J G	7908010304	50-373 Q
KEPPLER, J G	7908070639	70-925
KEPPLER, J G	7908070644	50-315 P
KEPPLER, J G	7908070652	50-10 P
KEPPLER, J G	7908070660	50-155 P
KEPPLER, J G	7908070666	50-409 P
KEPPLER, J G	7908070669	50-331 P
KEPPLER, J G	7908070674	50-263 P
KEPPLER, J G	7908070676	50-346 P
KEPPLER, J G	7908070679	50-266 P
KEPPLER, J G	7908070683	50-305 P
KEPPLER, J G	7908100365	50-346 A
KEPPLER, J G	7908070061	50-295 F
KEPPLER, J G	7908020208	50-263 P
KEPPLER, J G	7908130205	50-331 Q
KEPPLER, J G	7908090598	50-331 P
KEPPLER, J G	7908100488	50-305 F
KEPPLER, J G	7908100528	50-409 P
KEPPLER, J G	7908100534	50-266 P
KEPPLER, J G	7908130294	50-315 P
KEPPLER, J G	7908130306	50-263 P
KEPPLER, J G	7908130310	50-10 P
KEPPLER, J G	7908130323	50-155 P
KEPPLER, J G	7908130330	50-346 P
KEPPLER, J G	7908080719	50-10 P
KEPPLER, J G	7908290504	50-305 Q
KEPPLER, J G	7908070786	50-358 A
KEPPLER, J G	7908070790	50-440 A
KEPPLER, J G	7908070793	50-329 A
KEPPLER, J G	7908070796	50-341 A
KEPPLER, J G	7908070798	50-461 A
KEPPLER, J G	7908070801	50-367 A
KEPPLER, J G	7908070802	50-484 A
KEPPLER, J G	7908070807	50-546 A
KEPPLER, J G	7908070810	50-483 A
KEPPLER, J G	7908200131	50-556 A
KEPPLER, J G	7908160520	50-358 A
KEPPLER, J G	7908140092	50-346 F
KEPPLER, J G	7908160073	70-1379
KEPPLER, J G	7908080103	50-255 Q
KEPPLER, J G	7908070327	70-925
KEPPLER, J G	7908070329	50-315 P
KEPPLER, J G	7908070332	50-10 P
KEPPLER, J G	7908070336	50-155 P
KEPPLER, J G	7908070338	50-409 P
KEPPLER, J G	7908070342	50-331 P
KEPPLER, J G	7908070343	50-263 P
KEPPLER, J G	7908070346	50-346 P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KEPPLER, J. G.	7908070347	50-266 P
KEPPLER, J. G.	7908070349	50-305 P
KEPPLER, J. G.	7908090051	50-331 S
KEPPLER, J. G.	7908020330	50-409 Q
KEPPLER, J. G.	7908020333	50-341 Q
KEPPLER, J. G.	7908020334	50-331 Q
KEPPLER, J. G.	7908020335	50-461 Q
KEPPLER, J. G.	7908020340	50-367 Q
KEPPLER, J. G.	7908020342	50-263 Q
KEPPLER, J. G.	7908020343	50-484 Q
KEPPLER, J. G.	7908020349	50-580 Q
KEPPLER, J. G.	7908020352	50-546 Q
KEPPLER, J. G.	7908020355	50-346 Q
KEPPLER, J. G.	7908020358	50-483 Q
KEPPLER, J. G.	7908020359	50-266 Q
KEPPLER, J. G.	7908020363	50-305 Q
KEPPLER, J. G.	7908280582	50-546 A
KEPPLER, J. G.	7908030555	50-358 Q
KEPPLER, J. G.	7908290279	50-315 Q
KEPPLER, J. G.	7908290284	50-295 Q
KEPPLER, J. G.	7908290287	50-255 Q
KEPPLER, J. G.	7908290291	50-232 Q
KEPPLER, J. G.	7908290293	50-346 Q
KEPPLER, J. G.	7908290309	50-266 Q
KEPPLER, J. G.	7908290313	50-305 Q
KEPPLER, J. G.	7908290330	50-329 Q
KEPPLER, J. G.	7908290339	50-358 Q
KEPPLER, J. G.	7908290349	50-155 Q
KEPPLER, J. G.	7908290354	50-409 Q
KEPPLER, J. G.	7908290359	50-341 Q
KEPPLER, J. G.	7908290365	50-331 Q
KEPPLER, J. G.	7908290370	50-263 Q
KEPPLER, J. G.	7908290374	50-346 Q
KEPPLER, J. G.	7908290377	50-266 Q
KEPPLER, J. G.	7908290400	50-305 Q
KEPPLER, J. G.	7908290405	50-10 Q
KEPPLER, J. G.	7908300385	50-315 Q
KEPPLER, J. G.	7908300392	50-295 Q
KEPPLER, J. G.	7908300396	50-440 Q
KEPPLER, J. G.	7908300399	50-155 Q
KEPPLER, J. G.	7908300402	50-329 Q
KEPPLER, J. G.	7908300404	50-409 Q
KEPPLER, J. G.	7908300407	50-341 Q
KEPPLER, J. G.	7908300408	50-331 Q
KEPPLER, J. G.	7908300411	50-461 Q
KEPPLER, J. G.	7908300415	50-367 Q
KEPPLER, J. G.	7908300419	50-263 Q
KEPPLER, J. G.	7908300422	50-484 Q
KEPPLER, J. G.	7908300425	50-546 Q
KEPPLER, J. G.	7908300426	50-483 Q
KEPPLER, J. G.	7908300434	50-305 Q
KEPPLER, J. G.	7908300437	50-266 Q
KEPPLER, J. G.	7908300441	50-346 Q
KEPPLER, J. G.	7908300446	50-282 Q
KEPPLER, J. G.	7908300450	50-255 Q
KEPPLER, J. G.	7908300455	50-10 Q
KEPPLER, J. G.	7908150283	50-315 Q
KEPPLER, J. G.	7908150292	50-373 Q
KEPPLER, J. G.	7908150336	50-358 Q
KEPPLER, J. G.	7908150340	50-440 Q
KEPPLER, J. G.	7908150342	50-155 Q
KEPPLER, J. G.	7908150344	50-329 Q
KEPPLER, J. G.	7908150347	50-409 Q
KEPPLER, J. G.	7908150353	50-341 Q
KEPPLER, J. G.	7908150356	50-331 Q
KEPPLER, J. G.	7908150360	50-461 Q
KEPPLER, J. G.	7908150363	50-367 Q
KEPPLER, J. G.	7908150371	50-263 Q
KEPPLER, J. G.	7908150374	50-484 Q
KEPPLER, J. G.	7908150377	50-580 Q
KEPPLER, J. G.	7908150379	50-546 Q
KEPPLER, J. G.	7908150384	50-346 Q
KEPPLER, J. G.	7908150391	50-483 Q
KEPPLER, J. G.	7908150398	50-266 Q
KEPPLER, J. G.	7908150401	50-305 Q
KEPPLER, J. G.	7908170017	50-315 Q
KEPPLER, J. G.	7908170019	50-10 Q
KEPPLER, J. G.	7908170021	50-155 Q
KEPPLER, J. G.	7908170022	50-409 Q
KEPPLER, J. G.	7908170023	50-331 Q
KEPPLER, J. G.	7908170024	50-263 Q
KEPPLER, J. G.	7908170026	50-346 Q
KEPPLER, J. G.	7908170027	50-266 Q
KEPPLER, J. G.	7908170028	50-305 Q
KEPPLER, J. G.	7908300262	50-315 Q
KEPPLER, J. G.	7908300267	50-358 Q
KEPPLER, J. G.	7908300270	50-440 Q
KEPPLER, J. G.	7908300272	50-329 Q
KEPPLER, J. G.	7908300275	50-409 Q
KEPPLER, J. G.	7908300276	50-341 Q
KEPPLER, J. G.	7908300279	50-331 Q
KEPPLER, J. G.	7908300280	50-461 Q
KEPPLER, J. G.	7908300285	50-367 Q
KEPPLER, J. G.	7908300287	50-484 Q
KEPPLER, J. G.	7908300290	50-263 Q
KEPPLER, J. G.	7908300294	50-580 Q
KEPPLER, J. G.	7908300297	50-546 Q
KEPPLER, J. G.	7908300300	50-346 Q
KEPPLER, J. G.	7908300303	50-483 Q
KEPPLER, J. G.	7908300307	50-266 Q
KEPPLER, J. G.	7908300310	50-305 Q
KEPPLER, J. G.	7908300312	5C 10 Q
KEPPLER, J. G.	7908300483	50-155 Q
KERR, W.	7908030382	ACRS
KERR, W.	7908150060	ACRS
KERWIN, D. K.	7908240068	NUREG
KETCHEN, E. G.	7908130360	70-2623
KETCHEN, E. G.	7906070320	50-275 Q
KETCHEN, E. G.	7908020480	70-2623
KETCHEN, E. G.	7908220049	70-2623
KETZLACH, N.	7908020280	70-1201
KETZLACH, N.	7908070818	70-824
KEVERN, T. A.	7908220524*	50-272 Q
KEY, W. J.	7908090064*	50-331 S
KEY, W. J.	7908290529*	50-315 Q
KHATIB-RAHBAR, M.	7908140005	TOPREP
KING, B.	7908090464*	COMMISSION
KINNEAR, R. J.	7908140384	71-85
KINTIGH, A. E.	7908140522	50-596 B
KINTIGH, A. E.	7908310504	50-596 C
KIRK, W. F.	7908020229	71-6357
KIRKPATRICK, D. C.	7908290532	50-320 T
KIRKPATRICK, D. C.	7908290615	50-320 T
KIRKPATRICK, D. C.	7908280674	50-320 T
KIRKPATRICK, D. C.	7908290610	50-320 T
KIRKPATRICK, D.	7908290653	50-320 T
KIRKWOOD, C. W.	7908090543	NUREG
KIRSCH, D. F.	7908150233*	50-275 Q
KIRSCH, D. F.	7908200235*	50-275 Q
KIRSLIS, S. S.	7908150642	50-320 P
KISS, E.	7908150675*	TOPREP
KISTER, H. B.	7908280225*	50-311 Q
KISTER, H. B.	7908130660*	50-29 Q
KISTER, H. B.	7908200268*	50-311 Q
KISTER, H. B.	7908270122*	50-293 Q
KITZ, G. T.	7908170416	TOPREP
KLEIMOLA, F. W.	7908060481*	NUREG
KLEINSORGE, W. P.	7908010721*	50-281 Q
KLEINSORGE, W. P.	7908240151*	50-281 Q
KLEITMAN, D. J.	7908150487*	ORG
KLINE, J. B.	7908150338	50-466 Q
KLINGLER, G. R.	7908020044*	50-280 Q
KNAPP, P. L.	7908230621*	50-320 Q
KNIGHT, J. R.	7908200001	PROJ
KNIGHTON, G. W.	7908200138	50-266 P
KNOP, R. C.	7908070159*	50-454 Q
KNOP, R. C.	7908150627*	50-329 Q
KNOP, R. C.	7908070210*	50-358 Q
KNOP, R. C.	7908100234*	50-341 Q
KNOP, R. C.	7908230052*	50-358 Q
KNOP, R. C.	7908150130*	50-483 Q
KNOP, R. C.	7908150176*	50-484 Q
KNOP, R. C.	7908150482*	50-329 Q
KNOTTS, J. B.	7908130,88	50-445 M
KNOTTS, J. B.	7908130201*	50-145 M
KODNER, J. L.	7908280552	50-373 Q
KODNER, J. L.	7908080200	50-599 Q
KOESTER, G. L.	7908100553*	50-482 Q
KOESTER, G. L.	7908150138	50-482 Q
KOESTER, G. L.	7908140524	50-482 A
KOESTER, G. L.	7908150641	50-482 A
KOHLER, J. E.	7908070825*	50-295 Q
KONKLIN, J. E.	7908070159*	50-454 Q
KONKLIN, J. E.	7908170246*	50-440 Q
KOSKI, G.	7908020554*	50-271 Q
KOSTAL, K.	7908290328*	50-546 Q
KOTTAN, J. J.	7908090449*	AGREEMENT
KOTTAN, J. J.	7908010722*	50-220 Q
KOTTAN, J. J.	7908150760*	50-320 Q
KOVACS, F. B.	7908300412	71-9033
KRANISH, A.	7908140716	FOIA
KRAWCZAK, A. T.	7908140754*	50-304 S
KREGER, W. E.	7908020019	50-443 Q
KREGER, W. E.	7908150149	50-443 H
KREGER, W. E.	7908210072	50-443 Q
KRESS, T. S.	7908270100	NUREG
KREYSA, F. J.	7908010623	71-5364
KRIEG, D. M.	7908020039	71-9070
KUBO, H.	7908240527*	SECY
KUBO, H.	7908240530*	SECY
KUEHL, C. A.	7908090122	XPORTLIC
KUEHN, R. C.	7908220597	50-466 Q
KUMPURIS, T. M.	7908290652	FOIA
KUNIHIRO, D. M.	7908020370	50-341 A
KUSEK, L. T.	7908210465*	50-285 S
KUSHNER, A. S.	7908140695*	50-285 Q
KUSIK, L. T.	7908210450*	50-285 S
KWAST, C. Z.	7908150025	71-238
KWIRANT, E. M.	7908200196	71-9033
KWIRANT, E. M.	7908206202	71-6058
LACK, V.	7908210540	50-574 Q
LACK, V.	7908220383	50-574 Q
LACK, V.	7908240320	50-574 Q
LACKER, D. K.	7908010539	REGOD
LAGIEWSKI, J. S.	7908200333*	50-317 S
LAGIEWSKI, J. S.	7908220389*	50-317 S
LAGIEWSKI, J. S.	7908280639*	50-317 S
LAGIEWSKI, J. S.	7908280682*	50-317 S
LAHR, T. N.	7908310064	40-8305
LAINAS, G.	7908300223	50-346 P
LAINAS, G.	7908300194	50-263 P
LAINAS, G.	7908010303	50-313 P
LAINAS, G.	7908010307	50-247 P
LAINAS, G.	7908300185	50-244 P
LAINAS, G.	7908010319	50-244 P
LAINAS, G.	7908010594	50-315 P
LAINAS, G.	7908030311	50-302 P
LAINAS, G.	7908030306	50-338 P
LAINAS, G.	7908030076	50-309 P
LAINAS, G.	7908210069	50-344 P
LAINAS, G.	7908130119	50-155 P
LAINAS, G.	7908010294	50-280 P
LAINAS, G.	7908010345	50-155 P
LAINAS, G.	7908010351	50-334 P
LAINAS, G.	7908150613	50-320 P
LAINAS, G.	7908020038*	50-280 Q
LAINAS, G.	7908150742	50-289 P
LAINAS, G.	7908080106	GEN TEC IS
LAINAS, G.	7908140097	50-280 P
LAINAS, G.	7908100360	50-315 P
LAINAS, G.	7908030454	GEN TEC IS
LAINAS, G.	7908020036	50-280 Q
LAINAS, G.	7908160296	50-250 P
LAINAS, G.	7908270086	50-335 P
LAINAS, G.	7908270267	50-312 P
LAINAS, G.	7908270355	50-247 P
LAINAS, G.	7908270164	50-220 P
LAINAS, G.	7908270207*	50-220 P
LAINAS, G.	7908220489	50-309 P
LAINAS, G.	7908230171	50-409 P
LAINAS, G.	7908270190	50-409 P
LAINAS, G.	7908270303	50-282 P
LAINAS, G.	7908270482	50-321 P
LAINAS, G.	7908230193	GEN TEC IS
LAINAS, G.	7908270139	50-10 P
LAINAS, G.	7908230143	50-305 P
LAINAS, G.	7908170598	GEN TEC IS
LAINAS, G.	7908270089	50-259 P
LAINAS, G.	7908270228	50-271 P
LAINAS, G.	7908290180	50-29 P
LAINAS, G.	7908270092	50-269 P
LAINAS, G.	7908240207	50-321 P
LAINAS, G.	7908240635	50-250 P
LAJOIE, K. R.	7908070535	ORG
LAMB, J. C.	7908030287	50-272 T
LAMB, J. L.	7908030621	50-272 T
LAND, C. E.	7908150479*	ORG
LANDE, J. R.	7908160400	FOIA
LANDGRAF, L. C.	7908010564	50-341 K
LANDWEHR, J. M.	7908150466*	50-320 H
LANE, C. D.	7908030269	50-596 Q
LANNING, D. D.	7908230692	NUREG
LANTZ, R. B.	7908030034	NUREG
LANTZ, P. M.	7908140622	RES
LARSON, L. K.	7908080441	50-244 P
LARSON, J. R.	7908030075	RES
LASSILA, J. D.	7908220042	50-574 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LASSILA, J. D.	7908240166	50-574 G
LAUDIG, S.	7908210493	50-546 H
LAUGHLAND, S.	7908310367	50-387 G
LAVER, R. J.	7908170527*	70-572
LAWROSKI, S.	7908090523	ACRS
LAWTON, M. D.	7908010359	PR
LAZARUS, W. J.	7908130638*	50-29 G
LAZARUS, W. J.	7908020121*	50-309 G
LAZO, R. M.	7908220208*	50-237 G
LEAR, G.	7908100124	50-254 P
LEASE, R. S.	7908060430*	50-315 S
LEBO, C. D.	7908030158	CONTRACT
LEBO, C. D.	7908230099	CONTRACT
LEBO, C. D.	7908290662	CONTRACT
LEBO, C. D.	7908030368	CONTRACT
LEBO, C. D.	7908030465	CONTRACT
LEBO, C. D.	7908230188	CONTRACT
LEBO, C. D.	7908030429	CONTRACT
LEBO, C. D.	7908170060	CONTRACT
LEBO, C. D.	7908170291	CONTRACT
LEBO, G. D.	7908230124	CONTRACT
LEBO, C. D.	7908220260	CONTRACT
LEE, B.	7908160376	50-10 P
LEE, E. W.	7908030633*	50-329 G
LEE, E. W.	7908080737*	50-546 G
LEE, R.	7908290150*	COMMISSION
LEECH, K.	7908140612*	50-265 S
LEECH, P.	7908060288*	50-522 G
LEED, R. M.	7908070797	50-322 A
LEED, R. M.	7908150460	50-522 G
LEED, R. M.	7908080002	50-522 G
LEED, R. M.	7908300747	50-522 G
LEEDS, J. V.	7908060105	50-329 T
LEEDS, J. V.	7908060065	50-329 T
LEEDS, J. V.	7908080548	50-329 T
LEEDS, J. V.	7908080543	50-329 T
LEEF, P. M.	7908230284	50-320 P
LEFEVRE, H.	7908060288*	50-522 G
LEMANOWICZ, I.	7908020578*	50-387 G
LEMANOWICZ, I.	7906260390	50-387 G
LEMMER, R. N.	7908170534	50-466 G
LEMPGES, T. E.	7908070745	50-220 G
LEMPGES, T. E.	7908070661	50-220 G
LEMPGES, T. E.	7908140651	50-220 S
LEMPGES, T. E.	7908150630	50-220 R
LENAHAN, J. J.	7908020217*	50-338 G
LENAHAN, J. J.	7908210583*	50-566 G
LENAHAN, J. J.	7908300149*	50-491 G
LENHARD, J. A.	7908210501	50-320 P
LEONARD, J. D.	7908070501	50-333 G
LEONARD, J. D.	7908070808	50-333 G
LEONARD, J. D.	7908070650	50-333 G
LEONARD, J. D.	7908280828	50-333 G
LEONARD, J. D.	7908290673	50-333 G
LEONARD, J. D.	7908060479	50-333 S
LEONARD, J. D.	7908060521	50-333 S
LEONARD, J. D.	7908060441	50-333 S
LEONARD, J. D.	7908060461	50-333 S
LEONARD, J. D.	7908070593	50-333 R
LEONARD, J. D.	7908140626	50-333 G
LEONARD, J. D.	7908300646	50-333 R
LEONARD, J. D.	7908290456	50-333 S
LESSOR, L. C.	7908010555	50-298 S
LESSOR, L. C.	7908080596	50-298 S
LESSOR, L. C.	7908310436	50-298 S
LESSOR, L. C.	7908310415	50-298 S
LESSOR, L. C.	7908140761	50-298 R
LESSOR, L. C.	7908310357	50-298 S
LESSY, R. P.	7908090581	50-445 M
LESSY, R. P.	7908210612	50-445 M
LESSY, R. P.	7908130573	50-498 G
LESSY, R. P.	7908130223	50-445 M
LESSY, R. P.	7908310010	50-445 M
LETTIERI, V.	7908020519	50-213 E
LEUNG, J. C. M.	7908010516	RES
LEVINE, S. H.	7908030516*	PRM
LEVIN, H. A.	7908130286	GEN TEC IS
LEVIN, H. A.	7908160037	50-155 P
LEVIN, H. A.	7908100359*	50-10 P
LEWALD, G. H.	7908080328	50-471 G
LEWALD, G. H.	7908150392	50-[illegible]1 G
LEWIS, M. I.	7908010587	REGGD
LEWIS, N.	7908150017	50-361 G
LEWIS, M.	7908090437	PROJ
LEWIS, M. I.	7908230285	PR
LEWIS, L.	7908020211	71-6144
LEWIS, S. R.	7908060512*	50-269 S
LEWIS, S. R.	7908070656*	50-269 S
LEWIS, S. R.	7908160179*	50-269 S
LEWIS, S. R.	7908230327*	50-269 S
LEWIS, S. R.	7908240394*	50-269 S
LEWIS, S. R.	7908280635*	50-269 S
LEWIS, S. H.	7906060188	50-263 G
LEWIS, S. H.	7906070324	50-596 G
LEWIS, S. H.	7908080633	50-250 P
LEWIS, S. H.	7908010663	50-596 A
LEWIS, S. H.	7908210032	50-247 G
LEWIS, S. H.	7908030319	50-261 P
LEWIS, S. H.	7908300186	50-596 G
LEWIS, S. H.	7908080269	50-596 G
LEWIS, R. C.	7908170226	50-348 G
LEWIS, R. C.	7908270177	50-259 G
LEWIS, R. C.	7908170138	50-259 G
LEWIS, R. C.	7908070293*	50-364 G
LEWIS, R. C.	7908300088*	50-302 G
LEWIS, R. C.	7908150254*	50-280 G
LEWIS, R. C.	7908280808	50-302 G
LEWIS, R. C.	7908090018	50-269 G
LEWIS, R. C.	7908220410*	50-338 G
LEWIS, R. C.	7908160454	50-280 G
LEWIS, R. C.	7908160460	50-250 G
LEWIS, R. C.	7908160465*	50-250 G
LEWIS, R. C.	7908070139*	50-261 G
LEWIS, R. C.	7908200015*	50-335 G
LEWIS, R. C.	7908240174	50-324 G
LEWIS, R. C.	7908280145	50-327 G
LEWIS, R. C.	7908020536	50-259 G
LEWIS, R. C.	7908060001	50-259 G
LEWIS, R. C.	7908170195	50-348 G
LEWIS, R. C.	7908170456	50-261 G
LEWIS, R. C.	7908150400*	50-321 G
LEWIS, R. C.	7908230677	50-348 G
LEWIS, R. C.	7908240109*	50-335 G
LEWIS, R. C.	7908240343	50-338 G
LEWIS, R. C.	7908270193*	50-259 G
LEWIS, R. C.	7908150528	50-280 G
LEWIS, R. C.	7908170565*	50-321 G
LEWIS, R. C.	7908240208	50-280 G
LEWIS, R. C.	7908240187	50-280 G
LEWIS, R. C.	7908070276	50-364 G
LEWIS, R. C.	7908170541	50-335 G
LEWIS, R. C.	7908230586	50-395 G
LEWIS, R. C.	7908240317	50-280 G
LEWIS, R. C.	7908240291	50-302 G
LEWIS, R. C.	7908240201	50-369 G
LEWIS, R. C.	7908240302	50-327 G
LEWIS, R. C.	7908270281	50-250 G
LEWIS, R. C.	7908230571	50-259 G
LEWIS, R. C.	7908240323	50-324 G
LEWIS, R. C.	7908150238	50-280 G
LEWIS, R. C.	7908170555	50-321 G
LEWIS, R. C.	7908070124	50-261 G
LEWIS, R. C.	7908200011	50-335 G
LEWIS, R. C.	7908300534*	50-269 G
LEWIS, R. C.	7908220222	50-269 G
LEWIS, R. C.	7908240100	50-335 G
LEWIS, R. C.	7908200030	50-250 G
LEWIS, R. C.	7908300074	50-302 G
LEWIS, R. C.	7908280770	50-327 G
LIAO, C. K.	7908060117	NUREG
LIBRIZZI, F. P.	7908030151	50-272 R
LIBRIZZI, F. P.	7908030215	50-272 S
LIBRIZZI, F. P.	7908030455	50-272 S
LIBRIZZI, F. P.	7908100156	50-272 P
LIBRIZZI, F. P.	7908140404	50-272 P
LIBRIZZI, F. P.	7908140732	50-272 P
LIBRIZZI, F. P.	7908200298	50-272 H
LIBRIZZI, F. P.	7908140818	50-272 S
LIBRIZZI, F. P.	7908200339	50-272 P
LIBRIZZI, F. P.	7908200194	50-272 F
LIBRIZZI, F. P.	7908280636	50-272 R
LIBRIZZI, F. P.	7908300546	50-272 S
LIBRIZZI, F. P.	7908300628	50-272 S
LICHTENBERGER, H.	7908150221	70-1100
LICHTENBERGER, H.	7908070777	70-1100
LICHTENBERGER, H.	7908140165	70-1100
LICHTENBERGER, H.	7908220285	70-1100
LICITRA, E.	7908030168	50-471 A
LICITRA, E. A.	7908160035	50-471 A
LIDE, R. E.	7908170319*	TOPREP
LIEBERMAN, J.	7908300612	50-309 G
LIEBERMAN, J.	7908300616*	50-309 G
LIEBLER, G. E.	7908100446	TOPREP
LIEBLER, G. E.	7907250388	TOPREP
LIEBLER, G. E.	7908090491	TOPREP
LIEBLER, G. E.	7908100458	50-255 P
LIM, J. C.	7908150407*	50-321 G
LIM, T. M.	7908060359	50-224 P
LINDBERG, C.	7908140629*	50-249 S
LINDBLAD, W. J.	7908200316	50-344 P
LINDER, F.	7907190015	50-409 G
LINDER, F.	7908070175	50-409 G
LINDER, F.	7908080395	50-409 G
LINDER, F.	7908010696	50-409 P
LINDER, F.	7908130661	50-409 P
LINDER, F.	7908140642	50-409 S
LINDER, F.	7908030170	50-409 P
LINDER, F.	7908030468	50-409 S
LINDER, F.	7908150683	50-409 G
LINDER, F.	7908080613	50-409 H
LINDER, F.	7908150193	50-409 S
LINDER, F.	7908200334	50-409 P
LINDER, F.	7908210249	50-409 P
LINDER, F.	7908150419	50-409 R
LINDER, F.	7908160449	50-409 P
LINDER, F.	7908030319	50-409 H
LINDER, F.	7908210391	50-409 R
LINDER, F.	7908270413	50-409 P
LINDER, F.	7908220366	50-409 G
LINDER, F.	7908270453	50-409 F
LINDNER, T. P.	7908170194	XPORTLIC
LINEHAN, J. J.	7908130365	40-8452
LINEHAN, J. J.	7908170307	40-8693
LINEHAN, J. J.	7908230172	40-4492
LINEHAN, J. J.	7908210138	40-8102
LINENBERGER, G. A.	7908300014	50-522 G
LINENBERGER, G. A.	7908070283	50-522 T
LINENBERGER, G. A.	7908060056	50-522 T
LINENBERGER, G. A.	7908070277	50-522 T
LINENBERGER, G. A.	7908060086	50-522 T
LINENBERGER, G. A.	7908060037	50-522 T
LINENBERGER, G. A.	7908030272	50-522 T
LINENBERGER, G. A.	7908090644	50-522 T
LINENBERGER, G. A.	7908100401	50-522 T
LINENBERGER, G. A.	7908090619	50-522 T
LING, J.	7908010664	REGGD
LING, J.	7908010673	REGGD
LIPIRSKI, R. E.	7908210172*	NUREG
LISCO, R. K.	7908280290*	40-8728
LITTLE, D. S.	7908300004	50-522 G
LITTLE, M.	7908310130	CONTRACT
LITTLE, M.	7908090600	CONTRACT
LITTLE, W. S.	7908020572*	50-10 G
LITTMANN, M. F.	7908200052	50-358 H
LIVERMORE, H. H.	7908070159*	50-454 G
LO, R.	7908170164	ORG
LO, K.	7908090640	ORG
LOCHSTET, W. A.	7908300684	50-568 D
LOCHSTET, W. A.	7908280614	50-387 D
LOCHSTET, W. A.	7908170133	40-8721
LOCHSTET, W. A.	7908280546	50-395 D
LOCKE, R. F.	7908200047	50-133 G
LOCKMAN, D. M.	7908150329	71-131
LOCKMAN, D. M.	7908150333*	71-131
LOCKWOOD, C. A.	7908220159	50-574 G
LODGE, T. J.	7908160299*	50-346 P
LODGE, T. J.	7908160248*	50-346 P
LODGE, T. J.	7908160255*	50-346 P
LOFTUS, J.	7908060090	FOIA
LOHRMANN, A. A.	7908240391	50-244 H
LONG, D. G.	7908020445*	50-29 S
LONG, F. J.	7908150345*	50-438 G
LORENZ, R. W.	7908300722*	50-133 P
LORENZ, R. W.	7908300725*	50-133 P
LOSS, F. J.	7908020226	RES
LOSS, F. J.	7908020212	RES
LOW, L. D.	7908170553*	70-572
LOWENSTEIN, R.	7908210536	50-331 J
LOWERRE, R. W.	7907260001	50-510 G
LOWERRE, R. W.	7907260002*	50-510 G
LOWERRE, R. W.	7908080072	50-[illegible]66 G
LOWERRE, R. W.	7906130076	50-466 G
LOWERRE, R. W.	7908130089	50-466 G
LOWERRE, R. W.	7908230077	50-466 G
LUCK, A. D.	7908140195	40-8721
LUCK, A. D.	7908220215	40-8721
LUEBKE, E. A.	7908060105	50-329 T
LUEBKE, E. A.	7908060065	50-329 T

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LUEBKE, E. A.	7906080548	50-329 T
LUEBKE, E. A.	7908080543	50-329 T
LUEBKE, E. A.	7908150037	70-2623
LUEBKE, E. A.	7908150042	70-2623
LUEBKE, E. A.	7908150022	70-2623
LUEBKE, E. A.	7908150722	70-2623
LUMER, J. V.	7908290079	50-250 G
LUMER, J. V.	7908290079	50-250 G
LUNDIN, B. T.	7908150771	50-320 H
LUNDVALL, A. E.	7906020585	50-317 G
LUNDVALL, A. E.	7908070665	50-317 G
LUNDVALL, A. E.	7908070806	50-317 G
LUNDVALL, A. E.	7908070844	50-317 G
LUNDVALL, A. E.	7908170313	50-317 G
LUNDVALL, A. E.	7908290711	50-317 G
LUNDVALL, A. E.	7908080498	50-317 P
LUNDVALL, A. E.	7908080534	50-317 P
LUNDVALL, A. E.	7908200108	50-317 G
LUNDVALL, A. E.	7908100410	50-317 F
LUNDVALL, A. E.	7908140688	50-317 F
LUNDVALL, A. E.	7908280554	50-317 G
LUNDVALL, A. E.	7908310396	50-317 F
LUNDWALL, A. E.	7908300474	50-318 P
LYDON, J. L.	7908060238	50-471 F
LYNCH, D. A.	7908210229*	50-320 P
MACARTHUR, T. C.	7908020591*	70-824
MACBETH, P. J.	7908140462	NUREG
MACDONALD, C. E.	7908010600	71-257
MACDONALD, C. E.	7908240035*	XPORTLIC
MACDONALD, C. E.	7908290677*	FOIA
MACDONALD, C. E.	7908030070*	71-5597
MACDONALD, C. E.	7908150701*	71-131
MACDONALD, C. E.	7908280774	71-9021
MACDONALD, C. E.	7908080625	71-125
MACDONALD, C. E.	7908080629*	71-125
MACDONALD, C. E.	7908090252	71-93
MACDONALD, C. E.	7908090258*	71-93
MACDONALD, C. E.	7908090474	71-70
MACDONALD, C. E.	7908090479*	71-70
MACDONALD, C. E.	7908280285	71-66
MACDONALD, C. E.	7908280293*	71-66
MACDONALD, C. E.	7908280298	71-100
MACDONALD, C. E.	7908280313*	71-100
MACDONALD, C. E.	7908280333	71-33
MACDONALD, C. E.	7908280338*	71-33
MACDONALD, C. E.	7908280458	71-36
MACDONALD, C. E.	7908280463	71-36
MACDONALD, C. E.	7908280464	71-9079
MACDONALD, C. E.	7908280470*	71-9079
MACDONALD, C. E.	7908020557	71-5563
MACDONALD, C. E.	7909070334	71-5149
MACDONALD, C. E.	7908010605*	71-257
MACDONALD, C. E.	7908090274	71-302
MACDONALD, C. E.	7908090280*	71-302
MACDONALD, C. E.	7908290336	71-300
MACDONALD, C. E.	7908290341*	71-300
MACDONALD, C. E.	7908280776	71-9009
MACDONALD, C. E.	7908020332	71-10
MACDONALD, C. E.	7908280450*	71-6400
MACDONALD, C. E.	7908010100	71-181
MACDONALD, C. E.	7908010104*	71-181
MACDONALD, C. E.	7908010106	71-175
MACDONALD, C. E.	7908010109*	71-175
MACDONALD, C. E.	7908010114	71-220
MACDONALD, C. E.	7908010120*	71-220
MACDONALD, C. E.	7908010129	71-128
MACDONALD, C. E.	7908010135*	71-128
MACDONALD, C. E.	7908010145	71-99
MACDONALD, C. E.	7908010151*	71-99
MACDONALD, C. E.	7908010170	71-232
MACDONALD, C. E.	7908010177*	71-232
MACDONALD, C. E.	7908010188	71-243
MACDONALD, C. E.	7908010195*	71-243
MACDONALD, C. E.	7908010201	71-233
MACDONALD, C. E.	7908010209*	71-233
MACDONALD, C. E.	7908010217	71-247
MACDONALD, C. E.	7908010225*	71-247
MACDONALD, C. E.	7908010230	71-234
MACDONALD, C. E.	7908010237*	71-234
MACDONALD, C. E.	7908010378	71-272
MACDONALD, C. E.	7908010382*	71-272
MACDONALD, C. E.	7908010403	71-242
MACDONALD, C. E.	7908010[illegible]*	71-242
MACDONALD, C. E.	7908010406	71-221
MACDONALD, C. E.	7908010409*	71-221
MACDONALD, C. E.	7908010411	71-222
MACDONALD, C. E.	7908010413*	71-222
MACDONALD, C. E.	7908010452	71-223
MACDONALD, C. E.	7908010460*	71-223
MACDONALD, C. E.	7908010464	71-224
MACDONALD, C. E.	7908010466*	71-224
MACDONALD, C. E.	7908010473	71-229
MACDONALD, C. E.	7908010477*	71-229
MACDONALD, C. E.	7908010583	71-214
MACDONALD, C. E.	7908010586*	71-214
MACDONALD, C. E.	7908010588	71-253
MACDONALD, C. E.	7908010590*	71-253
MACDONALD, C. E.	7908010592	71-215
MACDONALD, C. E.	7908010595*	71-215
MACDONALD, C. E.	7908010598	71-213
MACDONALD, C. E.	7908010602*	71-213
MACDONALD, C. E.	7908020095	71-279
MACDONALD, C. E.	7908020098*	71-279
MACDONALD, C. E.	7908020138	71-212
MACDONALD, C. E.	7908020145*	71-212
MACDONALD, C. E.	7908070740	71-188
MACDONALD, C. E.	7908070746*	71-188
MACDONALD, C. E.	7908090132	71-81
MACDONALD, C. E.	7908090137*	71-81
MACDONALD, C. E.	7908090265	71-16
MACDONALD, C. E.	7908090269*	71-16
MACDONALD, C. E.	7908090492	71-270
MACDONALD, C. E.	7908090497*	71-270
MACDONALD, C. E.	7908090602	71-20
MACDONALD, C. E.	7908090608*	71-20
MACDONALD, C. E.	7908140757	71-44
MACDONALD, C. E.	7908140762*	71-44
MACDONALD, C. E.	7908200159	71-14
MACDONALD, C. E.	7908200161*	71-14
MACDONALD, C. E.	7908210192	71-237
MACDONALD, C. E.	7908210195*	71-237
MACDONALD, C. E.	7908280354	71-332
MACDONALD, C. E.	7908280360*	71-332
MACDONALD, C. E.	7908280366	71-329
MACDONALD, C. E.	7908280369*	71-329
MACDONALD, C. E.	7908280375	71-330
MACDONALD, C. E.	7908280380*	71-330
MACDONALD, C. E.	7908090127	71-91
MACDONALD, C. E.	7908160076	71-231
MACDONALD, C. E.	7908160081	71-190
MACDONALD, C. E.	7908010091	71-254
MACDONALD, C. E.	7908010095*	71-254
MACDONALD, C. E.	7908030441	71-6574
MACDONALD, C. E.	7908030446*	71-6574
MACDONALD, C. E.	7908150699	71-131
MACDONALD, C. E.	7908010706	71-9018
MACDONALD, C. E.	7908010711*	71-9018
MACDONALD, C. E.	7908020040	71-6400
MACDONALD, C. E.	7908020045*	71-6400
MACDONALD, C. E.	7908030352	71-9019
MACDONALD, C. E.	7908030358*	71-9019
MACDONALD, C. E.	7908280345	71-5331
MACDONALD, C. E.	7908280351*	71-5331
MACDONALD, C. E.	7908080386	71-92
MACDONALD, C. E.	7908080410	71-199
MACDONALD, C. E.	7908060555	71-5026
MACDONALD, C. E.	7908090307	71-30
MACDONALD, C. E.	7908090312*	71-30
MACDONALD, C. E.	7908090317	71-172
MACDONALD, C. E.	7908090324*	71-172
MACDONALD, C. E.	7908090329	71-280
MACDONALD, C. E.	7908090339*	71-280
MACDONALD, C. E.	7908090343	71-282
MACDONALD, C. E.	7908090347*	71-282
MACDONALD, C. E.	7908090349	71-285
MACDONALD, C. E.	7908090351*	71-285
MACDONALD, C. E.	7908090355	71-269
MACDONALD, C. E.	7908090358*	71-269
MACDONALD, C. E.	7908090362	71-209
MACDONALD, C. E.	7908090365*	71-209
MACDONALD, C. E.	7908090370	71-186
MACDONALD, C. E.	7908090373*	71-186
MACDONALD, C. E.	7908090377	71-158
MACDONALD, C. E.	7908090382*	71-158
MACDONALD, C. E.	7908090385	71-155
MACDONALD, C. E.	7908090390*	71-155
MACDONALD, C. E.	7908090395	71-149
MACDONALD, C. E.	7908090399*	71-149
MACDONALD, C. E.	7908090405	71-268
MACDONALD, C. E.	7908090407*	71-268
MACDONALD, C. E.	7908090411	71-286
MACDONALD, C. E.	7908090414*	71-286
MACDONALD, C. E.	7908090418	71-245
MACDONALD, C. E.	7908090421*	71-245
MACDONALD, C. E.	7908090426	71-276
MACDONALD, C. E.	7908090432*	71-276
MACDONALD, C. E.	7908090436	71-274
MACDONALD, C. E.	7908090439*	71-274
MACDONALD, C. E.	7908160499	71-311
MACDONALD, C. E.	7908160503	71-297
MACDONALD, C. E.	7908160505*	71-311
MACDONALD, C. E.	7908160509*	71-297
MACDONALD, C. E.	7908160510	71-315
MACDONALD, C. E.	7908160513	71-301
MACDONALD, C. E.	7908160515*	71-315
MACDONALD, C. E.	7908160517	71-313
MACDONALD, C. E.	7908160519*	71-301
MACDONALD, C. E.	7908160522*	71-313
MACDONALD, C. E.	7908160524	71-317
MACDONALD, C. E.	7908160525	71-312
MACDONALD, C. E.	7908160527*	71-317
MACDONALD, C. E.	7908160528*	71-312
MACDONALD, C. E.	7908160534	71-72
MACDONALD, C. E.	7908160536*	71-72
MACDONALD, C. E.	7908160538	71-146
MACDONALD, C. E.	7908160542*	71-146
MACDONALD, C. E.	7908160546	71-295
MACDONALD, C. E.	7908160550*	71-295
MACDONALD, C. E.	7908160554	71-299
MACDONALD, D. E.	7908160559*	71-299
MACDONALD, C. E.	7908160562	71-291
MACDONALD, C. E.	7908160564*	71-291
MACDONALD, C. E.	7908160572	71-309
MACDONALD, C. E.	7908160574*	71-309
MACDONALD, C. E.	7908170231	71-289
MACDONALD, C. E.	7908170233*	71-289
MACDONALD, C. E.	7908170242	71-288
MACDONALD, C. E.	7908170244*	71-288
MACDONALD, C. E.	7908170257	71-290
MACDONALD, C. E.	7908170262*	71-290
MACDONALD, C. E.	7908170288	71-303
MACDONALD, C. E.	7908170290*	71-303
MACDONALD, C. E.	7908230292	71-6058
MACDONALD, C. E.	7908280475	71-293
MACDONALD, C. E.	7908280481*	71-293
MACDONALD, C. E.	7908080429	71-9019
MACDONALD, C. E.	7908090701	71-9044
MACDONALD, C. E.	7908150663	71-6601
MACDONALD, C. E.	7908240197	71-341
MACDONALD, C. E.	7908240204	71-340
MACDONALD, C. E.	7908160552	71-9033
MACDONALD, C. E.	7908160560*	71-9033
MACDONALD, C. E.	7908200417	71-238
MACDONALD, C. E.	7908210051	71-258
MACDONALD, C. E.	7908280241	71-335
MACDONALD, C. E.	7908170605	71-6244
MACDONALD, C. E.	7908170613*	71-6244
MACDONALD, C. E.	7908200411	71-9
MACDONALD, C. E.	7908280064	71-5950
MACDONALD, C. E.	7908290318	71-9111
MACDONALD, C. E.	7908290321	71-9010
MACDONALD, C. E.	7908290323	71-6717
MACDONALD, C. E.	7908290433	71-5957
MACDONALD, C. E.	7908290437	71-9113
MACDONALD, C. E.	7908290440	71-9007
MACDONALD, C. E.	7908290443	71-6144
MACDONALD, C. E.	7908290448	71-6574
MACDONALD, C. E.	7908290454	71-9080
MACDONALD, C. E.	7908290460	71-6601
MACDONALD, C. E.	7908170323	71-4986
MACDONALD, C. E.	7908280435	71-333
MACDONALD, C. E.	7908280438*	71-333
MACDONALD, C. E.	7908230237*	71-6722
MACDONALD, C. E.	7908290628	71-9111
MACDONALD, C. E.	7908290634*	71-9111
MACDONALD, C. E.	7908090675	71-261
MACDONALD, C. E.	7908090676*	71-261
MACDONALD, C. E.	7908090679	71-318
MACDONALD, C. E.	7908090682*	71-318
MACDONALD, C. E.	7908100136	71-287
MACDONALD, C. E.	7908100142*	71-287
MACDONALD, C. E.	7908100146	71-111
MACDONALD, C. E.	7908100148*	71-111
MACDONALD, C. E.	7908230033	71-91
MACDONALD, C. E.	7908230037*	71-91
MACDONALD, C. E.	7908230092	71-67
MACDONALD, C. E.	7908230097	71-167
MACDONALD, C. E.	7908230098*	71-167

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MACDONALD, C. E.	7908230116*	71-67
MACDONALD, C. E.	7908230206	71-85
MACDONALD, C. E.	7908230209*	71-85
MACDONALD, C. E.	7908230432	71-117
MACDONALD, C. E.	7908230630	71-64
MACDONALD, C. E.	7908230632	71-147
MACDONALD, C. E.	7908230636	71-201
MACDONALD, C. E.	7908230638	71-53
MACDONALD, C. E.	7908270366	71-9113
MACDONALD, C. E.	7908270371*	71-9113
MACDONALD, C. E.	7908280315	71-336
MACDONALD, C. E.	7908280320*	71-336
MACDONALD, C. E.	7908280323	71-338
MACDONALD, C. E.	7908280349*	71-338
MACDONALD, C. E.	7908280424	71-31
MACDONALD, C. E.	7908280430*	71-31
MACDONALD, C. E.	7908280829	71-5796
MACDONALD, C. E.	7908230089	71-6581
MACDONALD, C. E.	7908230090*	71-6581
MACDONALD, C. F.	7908240199	71-264
MACMILLAN, J. H.	7908210475	50-320 F
MADEDA, T. J.	7908010009*	50-409 G
MADENOS, L.	7908210279*	50-250 G
MADISON, S. R.	7908300732	50-596 G
MADISON, W. R.	7908130355*	50-338 R
MADSEN, G. L.	7908230624*	50-146 G
MADSEN, G. L.	7908010679*	50-267 G
MADSEN, G. L.	7908080251*	50-252 G
MADSEN, G. L.	7908080448	50-313 G
MADSEN, G. L.	7908020105*	50-285 G
MADSEN, G. L.	7908020102	50-285 G
MADSEN, G. L.	7908080442	50-267 S
MADSEN, G. L.	7908030201	50-285 G
MADSEN, G. L.	7908090261	50-313 '
MADSEN, G. L.	79083000a0	50-267
MADSEN, G. L.	7908020367	50-313 G
MADSEN, G. L.	7908010667	50-267 G
MADSEN, G. L.	7908140177	50-368 G
MADSEN, G. L.	7908080244	50-252 G
MADSEN, G. L.	7908140055	50-298 G
MADSEN, G. L.	7908010694	50-313 S
MADSEN, G. L.	7908010700	50-298 S
MADSEN, G. L.	7908010703	50-285 S
MADSEN, G. L.	7908010705	50-267 S
MADSEN, G. L.	7908170370	50-445 A
MADSEN, G. L.	7908220162	50-298 G
MADSEN, G. L.	7908230668	50-285 G
MADSEN, G. L.	7908090594	50-445 H
MADSON, G. L.	7908090688	50-313 G
MAHART, A.	7908140333	PROJ
MAIER, J. B.	7908300401	71-5026
MAJOR, R. K.	7906290049*	50-320 D
MAJOR, R. K.	7908210327	50-320 D
MAKEPEACE, J. M.	7908140831*	50-247 S
MALEK, F. A.	7908170510	71-210
MALET, E. I.	7908310431	FOIA
MALICK, R.	7908210373	50-320 R
MALMROS, M. H.	7908090695*	50-344 G
MALONEY, G. P.	7908220357	50-315 P
MALSCH, M. G.	7908300226*	50-259 P
MALSON, H. A.	7908170547*	70-572
MANGUSI, J.	7908170417	70-1426
MANGUSI, J.	7908130630	70-1426
MANGUSI, J.	7908140018	70-1426
MANGUSI, J.	7908140021	70-1426
MANN, D.	7908210311	50-387 D
MANN, J.	7908010478	50-592 C
MANRY, M.	7908030389	50-321 S
MANRY, M.	7908020444	50-321 S
MANRY, M.	7908030444	50-356 S
MANRY, M.	7908020439	50-321 S
MANRY, M.	7908020427	50-321 S
MANRY, M.	7908020452	50-366 S
MANRY, M.	7908140678	50-321 S
MANRY, M.	7908020421	50-321 S
MANRY, M.	7908030506	50-321 S
MANRY, M.	7908060392	50-366 S
MANRY, M.	7908060443	50-366 S
MANRY, M.	7908060460	50-321 S
MANRY, M.	7908060469	50-321 S
MANRY, M.	7908150498	50-366 P
MANRY, M.	7908070483	50-366 S
MANRY, M.	7908070495	50-366 S
MANRY, M.	7908070695	50-321 S
MANRY, M.	7908130448	50-366 S
MANRY, M.	7908100413	50-366 S
MANRY, M.	7908130338	50-366 S
MANRY, M.	7908130436	50-366 S
MANRY, M.	7908130410	50-321 S
MANRY, M.	7908130423	50-366 S
MANRY, M.	7908130464	50-321 S
MANRY, M.	7908130476	50-321 S
MANRY, M.	7908130491	50-366 S
MANRY, M.	7908130497	50-366 S
MANRY, M.	7908140812	50-366 S
MANRY, M.	7908150651	50-321 S
MANRY, M.	7908130469	50-366 S
MANRY, M.	7908140635	50-366 S
MANRY, M.	7908140791	50-366 S
MANRY, M.	7908140802	50-321 S
MANRY, M.	7908140696	50-366 S
MANRY, M.	7908140833	50-366 S
MANRY, M.	7908150513	50-321 R
MANRY, M.	7908150531	50-366 R
MANRY, M.	7908200262	50-321 S
MANRY, M.	7908200281	50-321 S
MANRY, M.	7908200302	50-366 S
MANRY, M.	7908200320	50-366 S
MANRY, M.	7908200337	50-366 S
MANRY, M.	7908200351	50-366 S
MANRY, M.	7908200371	50-366 S
MANRY, M.	7908200377	50-366 S
MANRY, M.	7908240385	50-321 S
MANRY, M.	7908240436	50-366 S
MANRY, M.	7908200272	50-321 S
MANRY, M.	7908240367	50-321 S
MANRY, M.	7908270380	50-321 S
MANRY, M.	7908240399	50-321 S
MANRY, M.	7908240525	50-366 S
MANRY, M.	7908240324	50-321 S
MANRY, M.	7908240348	50-321 S
MANRY, M.	7908240417	50-321 S
MANRY, M.	7908240469	50-366 S
MANRY, M.	7908240472	50-321 S
MANRY, M.	7908240479	50-321 S
MANRY, M.	7908240490	50-321 S
MANRY, M.	7908280685	50-366 S
MANRY, M.	7908290408	50-321 S
MANRY, M.	7908310313	50-366 S
MANRY, M.	7908310318	50-366 S
MANRY, M.	7908310324	50-321 S
MANRY, M.	7908310401	50-321 S
MANSER, W. C.	7908130383*	70-143
MANSER, W. C.	7908160361*	70-143
MANSER, W. C.	7908130378	70-143
MANSER, W. C.	7908240157*	70-143
MANSER, W. C.	7908030605	70-143
MANSER, W. C.	7908140210	70-143
MANSER, W. C.	7908240152*	70-143
MANSER, W. C.	7908170067	70-143
MANSER, W. C.	7908270275	70-143
MANSER, W. C.	7908300506	70-143
MANSER, W. C.	7908210130*	70-143
MANSER, W. C.	7908300554	70-143
MARCUSON, W. F.	7908090031	REGGD
MAREK, K.	7908030449	FOIA
MARETIN, J. J.	7908270112	50-354 Q
MARK, R.	7906090634*	50-329 Q
MARK, J. C.	7908030382	ACRS
MARK, J. C.	7908220115	50-320 T
MARK, J. C.	7908220126	50-320 T
MARKEE, E. H.	7908240630	50-471 A
MARKOWITZ, R. I.	7908020337	PRM
MARKS, S.	79081504?5*	ORG
MARONEY, D. G.	7908230592	NUREG
MARONEY, D. G.	7908080437	NUREG
MARQUARDT, G. L.	7908010608	REGGD
MARSCHARK, E. D.	79082000A5*	50-280 H
MARSDEN, S.	7906300533	50-599 Q
MARSH, C.	7908080044	50-387 Q
MARSHALL, W. H.	7908090509*	50-329 A
MARSHALL, W. H.	7908150259	50-329 Q
MARSH, R. J.	7906060001	50-320 P
MARSH, R. J.	7906060006	50-320 P
MARSH, R. J.	7906060009	50-320 P
MARSH, R.	7906210434	50-320 P
MARSH, R.	7908290579	50-320 T
MARSH, R.	7908290603	50-320 T
MARSH, R.	7908290630	50-320 T
MARSH, R.	7908290709	50-320 T
MARSH, R.	7908300089	50-320 T
MARSH, B.	7908300111	50-320 T
MARSH, R.	7908290624	50-320 T
MARSH, B.	7908300120	50-320 T
MARSH, R.	7908290425	50-320 T
MARSH, R.	7908290441	50-320 T
MARSH, B.	7908290524	50-320 T
MARSH, B.	7908300101	50-320 T
MARSH, B.	7908300104	50-320 T
MARSH, R.	7908290485	50-320 T
MARSH, B.	7908300126	50-320 T
MARSH, R.	7908280745	50-320 T
MARSH, R.	7908280763	50-320 T
MARSH, R.	7908290431	50-320 T
MARSH, B.	7908280674	50-320 T
MARSH, R.	7908290476	50-320 T
MARSH, R.	7908290491	50-320 T
MARSH, R.	7908290539	50-320 T
MARSH, R.	7908290633	50-320 T
MARSH, R.	7908280739	50-320 T
MARSH, B.	7908290133	50-320 T
MARSH, R.	7908290186	50-320 T
MARSH, B.	7908290347	50-320 T
MARSH, R.	7908290357	50-320 T
MARSH, B.	7908290379	50-320 T
MARSH, R.	7908280632	50-320 T
MARSH, R.	7908290371	50-320 T
MARSH, R.	7908290384	50-320 T
MARSH, B.	7908280783	50-320 T
MARSH, B.	7908280787	50-320 T
MARSH, R.	7908290245	50-320 T
MARSH, R.	7908290568	50-320 T
MARTIN, T.	7908230263	PR
MARTIN, D. H.	7908200124*	50-400 A
MARTIN, T. J.	7908030187	50-354 Q
MARTIN, T. J.	7908170186	50-354 Q
MARTIN, T. J.	7908090002	50-354 Q
MARTIN, T. J.	7908240601*	50-311 S
MARTIN, T. J.	7908290705	50-354 Q
MARTINSON, Z. R.	7908030090	RES
MARTIN, B.	7906210445	50-320 P
MARTIN, T. T.	7908300082	50-320 T
MARTIN, T. T.	7908290630	50-320 T
MARTIN, T. T.	7908290720	50-320 T
MARTIN, T. T.	7908290465	50-320 T
MARTIN, T. T.	7908300067	50-320 T
MARTIN, T. T.	7908300111	50-320 T
MARTIN, T. T.	7908300120	50-320 T
MARTIN, T. T.	7908290733	50-320 T
MARTIN, T. T.	7908300104	50-320 T
MARTIN, T. T.	7908290149	50-320 T
MARTIN, T. T.	7908290273	50-320 T
MARTIN, T. T.	7908280795	50-320 T
MARTIN, T. T.	7908280813	50-320 T
MARTIN, T. T.	7908280823	50-320 T
MARTIN, T. T.	7908280837	50-320 T
MARTIN, T. T.	7908280852	50-320 T
MARTIN, R. D.	7908290059	50-320 T
MARTIN, W. G.	7908240037	XPORTLIC
MARTIN, W. G.	7908170091	70-1143
MARTIN, W. G.	7908210152	70-135
MARTIN, R. D.	7908290170	50-320 T
MARTIN, T. T.	7908290273	50-320 T
MARTIN, T. T.	7908280837	50-320 T
MARTIN, R. D.	7908070302*	50-364 Q
MARTIN, R. D.	7908280778*	50-327 Q
MARTIN, R. D.	7908280155*	50-327 Q
MARTIN, R. D.	7908170461*	50-261 Q
MARTIN, R. D.	7908240297*	50-302 Q
MARTIN, R. D.	7908240316*	50-327 Q
MARTIN, L. E.	7908100217*	50-382 Q
MARTIN, T. B.	7908020116*	27-39
MARTIN, J. B.	7908230180*	SECY
MARTIN, J. B.	7908160123	40-1341
MARTIN, B.	7906210425	50-320 P
MARTIN, J. A.	7908080241*	50-322 Q
MARTON, K. V.	7908290442*	CONTRACT
MASCHNER, R. A.	7908290246	70-754
MASON, V.	7908150579*	XPORTLIC
MASRI, S. F.	7908240673	NUREG
MASSE, R. E.	7908150382*	50-315 Q
MASSING, D.	7908140366*	50-329 S
MATALAS, N. C.	7908150466*	50-320 H
MATERS, B. R.	7908140560	50-341 A
MATHEWS, E. R.	7908090499	50-305 Q
MATHEWS, E. R.	7908070755	50-305 Q
MATHEWS, E. R.	7908020267*	50-305 Q
MATHEWS, E. R.	7908130427	50-305 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MATHEWS, E. R.	7908150434	50-305 G
MATHEWS, E. R.	7908010372	50-305 P
MATHEWS, E. R.	7908010569	50-305 S
MATHEWS, E. R.	7908210146	50-305 G
MATHEWS, E. R.	7908010457	50-305 H
MATHEWS, E. R.	7908080401	50-305 S
MATHEWS, E. R.	7908140382	50-305 R
MATHEWS, E. R.	7908230290	50-305 G
MATHEWS, E. R.	7908220326	50-305 F
MATHEWS, E. R.	7908310526	50-305 R
MATHIE, F. M.	7908300539*	50-267 S
MATHIS, C. J.	7908010309	50-293 S
MATHIS, C. J.	7908080398*	50-293 S
MATIAS, T. R.	7908150234	50-596 G
MATSON, V.	7908130078*	SECY
MATSON, V.	7908130109*	SECY
MATSON, V.	7908100514	XPORTLIC
MATSON, V.	7908100516*	XPORTLIC
MATSON, V.	7908100135	XPORTLIC
MATSON, V.	7908100139	XPORTLIC
MATSON, V.	7908150189	XPORTLIC
MATSON, V.	7908150197*	XPORTLIC
MATSON, V.	7908210558	XPORTLIC
MATSON, V.	7908300337	XPORTLIC
MATSON, V.	7908300342*	XPORTLIC
MATSON, V.	7908310456	XPORTLIC
MATTHEWS, E. R.	7908080695	50-305 G
MATTIMOE, J. J.	7908020222	50-312 G
MATTIMOE, J. J.	7908070470	50-312 G
MATTIMOE, J. J.	7908010350	50-312 P
MATTIMOE, J. J.	7908060252	50-312 P
MATTIMOE, J. J.	7908100331	50-312 S
MATTIMOE, J. J.	7908100478	50-312 S
MATTIMOE, J. J.	7908200370	50-312 S
MATTIMOE, J. J.	7908200219	50-312 F
MATTIMOE, J. J.	7908240388	50-312 P
MATTIA, M. J.	7908030069*	CONTRACT
MATTIA, M. J.	7908170070*	CONTRACT
MATTIA, M. J.	7908160344*	CONTRACT
MATTIA, M. J.	7908160361*	CONTRACT
MATTIA, M. J.	7908160395*	CONTRACT
MATTIA, M. J.	7908160391*	CONTRACT
MATTIA, M. J.	7908160385*	CONTRACT
MATTIA, M. J.	7908270322*	CONTRACT
MATTIA, M. J.	7908300615*	CONTRACT
MATTIA, M. J.	7908140379*	CONTRACT
MATTIA, M. J.	7908090397*	CONTRACT
MATTIA, M. J.	7908070464*	CONTRACT
MATTIA, M. J.	7908150402*	CONTRACT
MATTIA, M. J.	7908220642*	CONTRACT
MATTIA, J.	7908010060*	50-482 G
MATTIA, J.	7908020133*	50-485 G
MATTIA, J. C.	7908130495*	50-352 G
MATTSON, V.	7908150301	XPORTLIC
MATTSON, R. J.	7908300206*	50-346 M
MATTSON, R. J.	7908230352*	50-334 G
MATTSON, R. J.	7906280056	50-320 H
MATTSON, R. J.	7908210171	50-320 H
MATTSON, R. J.	7908160556	50-320 F
MATTSON, R. J.	7907180126	50-320 P
MATTSON, R. J.	7908150707*	50-320 P
MATTSON, R. J.	7908210397	50-320 P
MATTSON, R. J.	7908220153	50-320 P
MATTSON, R. J.	7908220148	50-320 H
MAURA, F. A.	7907150637*	50-358 G
MAUTNER, P. P.	7908160343*	50-309 F
MAXWELL, G. F.	7908170246*	50-440 G
MAY, E. L.	7908140666*	50-29 S
MAYER, C. H.	7908240191	70-1739
MAYER, L. O.	7908150335	50-263 P
MAYER, L. O.	7908130402	50-263 P
MAYER, L. O.	7908060516	71-6144
MAYER, L. O.	7908140309	50-263 P
MAYER, L. O.	7908010584	50-263 F
MAYER, L. O.	7908030482	50-263 G
MAYER, L. O.	7908060375	50-282 P
MAYER, L. O.	7908060534	50-262 S
MAYER, L. O.	7908080455	50-263 P
MAYER, L. O.	7908090560	50-263 S
MAYER, L. O.	7908100429	50-263 S
MAYER, L. O.	7908130439	50-263 G
MAYER, L. O.	7908220227	50-263 G
MAYER, L. O.	7908140766	50-263 R
MAYER, L. O.	7908140759	50-282 R
MAYER, L. O.	7908140775	50-263 S
MAYER, L. O.	7908210319	50-263 H
MAYER, L. O.	7908160437	50-282 R
MAYER, L. O.	7908200290	50-282 S
MAYER, L. O.	7908230311	50-282 F
MAYER, L. O.	7908230316	50-263 F
MAYER, L. O.	7908240508	50-263 S
MAYER, L. O.	7908280555	50-263 F
MAYER, L. O.	7908280540	50-282 S
MAYER, L. O.	7908280586	50-282 S
MAYER, L. O.	7908310544	50-263 R
MAZAND, A.	7908170627	50-574 G
MAZETIS, G. R.	7908220447*	50-320 P
MAZETIS, G. R.	7908220454*	50-320 P
MAZETIS, G. R.	7908220462*	50-320 P
MCAVOY, S.	7908270104*	50-10 D
MCCABE, E. C.	7908090694*	50-223 G
MCCABE, E. C.	7908020099*	50-245 G
MCCABE, E. C.	7908010712*	50-219 G
MCCARTHY, E.	7908080256	50-528 A
MCCLANAHAN, H. H.	7908140135	70-27
MCCLANAHAN, H. H.	7908140316	70-27
MCCLANAHAN, H. H.	7908210600	70-27
MCCLANAHAN, H. H.	7908210601*	70-27
MCCLANAHAN, H. H.	7908240392	70-27
MCCLANAHAN, H. H.	7908170624	70-27
MCCLINTOCK, R. O.	7908080505*	70-2684
MCCLINTOCK, R. O.	7908170367*	70-2319
MCCLINTOCK, R. O.	7908160545	40-7983
MCCLINTOCK, R. O.	7908170360	70-2319
MCCLINTOCK, R. O.	7908240099*	40-8002
MCCLINTOCK, R. O.	7908240082	40-8002
MCCORMACK, J. B.	7908220551	71-9033
MCCORKLE, G. N.	7908210134	70-734
MCCORMACK, T.	7908020528*	50-346 G
MCCORKLE, G. W.	7908140067	70-33
MCCORKLE, G. W.	7908140081	70-143
MCCORKLE, G. W.	7908140101	70-824
MCCORKLE, G. W.	7908140423	70-1143
MCCORKLE, G. W.	7908140457	70-1739
MCCORKLE, G. W.	7908060132	70-2623
MCCORKLE, G. W.	7908010116	70-1308
MCCORKLE, G. W.	7908150244	70-27
MCCORKLE, G. W.	7908010108	70-1308
MCCORKLE, G. W.	7908160533	70-371
MCCORKLE, G. W.	7908150296	70-33
MCCORKLE, G. W.	7908030537	50-201 F
MCCORKLE, G. W.	7908140500	70-1143
MCCORKLE, G. W.	7908080369	70-1257
MCCORKLE, G. W.	7908150321	70-820
MCCORKLE, G. W.	7908150309	70-1257
MCCORKLE, G. W.	7908140074	70-820
MCCORKLE, G. W.	7908140452	70-25
MCCORKLE, G. W.	7908150303	70-1308
MCCORKLE, G. W.	7908300719	70-364
MCCORKLE, G. W.	7908080120	70-8
MCCORKLE, G. W.	7908160209	70-135
MCCORKLE, G. W.	7908150532	70-1426
MCCORKLE, G. W.	7908140468	70-1426
MCCORKLE, G. W.	7908300072	70-1426
MCCORKLE, G. W.	7908300078	70-1739
MCCORKLE, G. W.	7908170182	70-371
MCCORKLE, G. W.	7908300065	70-33
MCCORKLE, G. W.	7908160027	70-1143
MCCORKLE, G. W.	7908210098	70-734
MCCORKLE, G. W.	7908150171	70-371
MCCORKLE, G. W.	7908170140	70-734
MCCORKLE, G. W.	7908170330	70-8
MCCORKLE, G. W.	7908170339	70-734
MCCORKLE, G. W.	7908170345	70-754
MCCORKLE, G. W.	7908300[illegible]	70-1143
MCCORKLE, G. W.	7908220347	70-135
MCCORKLE, G. W.	7908220358	70-364
MCCORKLE, G. W.	7908010255	70-371
MCCORKLE, G. W.	7908140287	70-820
MCCULLOUGH, E. R.	7908080528	50-373 A
MCDERMOTT, R. T.	7908230635*	50-146 G
MCDONALD, J. A.	7908010650*	50-302 G
MCDONALD, C. E.	7908150732	71-9132
MCDONALD, C. E.	7908170174	71-9130
MCDONALD, C. E.	7908230232	71-6722
MCDONALD, C. E.	7908240023	71-6478
MCDONALD, C. E.	7908280744	71-5971
MCDONALD, C. E.	7908220498	71-200
MCDONALD, C. E.	7908220504	71-84
MCDONALD, C. E.	7908230023	71-21
MCDONALD, C. E.	7908230024	71-197
MCDONALD, C. E.	7908230027	71-206
MCDONALD, C. E.	7908230030	71-196
MCDONALD, C. E.	7908230034	71-97
MCDONALD, C. E.	7908230039	71-58
MCDONALD, C. E.	7908230046	71-49
MCDONALD, C. E.	7908230051	71-129
MCDONALD, C. E.	7908230057	71-13
MCDONALD, C. E.	7908230062	71-176
MCDOWELL-BOYER	7908020379	RES
MCDOWELL-BOYER	7908140584	RES
MCDUFFIE, M. A.	7908070821	50-400 G
MCDUFFIE, M. A.	7908140302	50-400 G
MCDUFFIE, M. A.	7908290631	50-400 G
MCDUFFIE, M. A.	7908060263	50-400 R
MCDUFFIE, K. A.	7908090575	50-400 G
MCDUFFIE, M. A.	7908170055	50-400 G
MCDUFFIE, M. A.	7908070530	50-400 A
MCELTOY, J. W.	7908170274	50-171 P
MCFARLAND, C. R.	7908240118*	50-339 G
MCFARLAND, C. R.	7908230599*	50-395 G
MCGAUGHY, R.	7908020133*	50-485 G
MCGAUGHY, R. W.	7908200288*	50-387 G
MCGAUGHY, R. W.	7908130495*	50-352 G
MCGAUGHY, R. W.	7908130621*	50-423 G
MCGAUGHY, R. W.	7908270081*	50-363 G
MCGRATH, E. J.	7908140152	PROJ
MCGRATH, E. J.	7908090357	PROJ
MCGRATH, E. J.	7908080717	PROJ
MCGRATH, E. J.	7908220180	PROJ
MCGRATH, E. J.	7908170184	PROJ
MCGRATH, P. E.	7908270486	PROJ
MCGRATH, P. E.	7908280197*	FOIA
MCGREGOR, E. W.	7908010324	SECY
MCGREGOR, E. W.	7908090008	SECY
MCGUIRE, S. S.	7908220386	50-466 G
MCGUIRE, P. J.	7908200231	50-293 R
MCGUIRE, P. J.	7908290413	50-293 R
MCGUIRE, P. J.	7908080397	50-293 S
MCGUIRE, P. J.	7908170418	50-293 S
MCGUIRE, P. J.	7908280526	50-293 S
MCGUIRE, D. R.	7908150345*	50-438 G
MCGURREN, H. J.	7906010094	50-424 G
MCGURREN, H. J.	7906070005	50-382 G
MCGURREN, H. J.	7908070691	50-498 G
MCGURREN, H. J.	7908210042	50-382 G
MCGURREN, H. J.	7907110398	50-382 G
MCHENRY, M.	7908080591	50-574 G
MCHENRY, T. J.	7908300100*	50-302 G
MCINTYRE, R.	7908150735*	50-320 H
MCKAY, H. S.	7908020562	50-338 G
MCKAY, H. S.	7908020567*	50-338 G
MCMAHAN, J.	7908140534	FOIA
MCMILLIN, H. W.	7908010641	PR
MCMULLEN, R. B.	7908010699	50-327 A
MCNAIR, R. C.	7908080432*	50-219 S
MCNAIR, R. C.	7908140676*	50-219 S
MCNAMARA, A. E.	7908210370*	50-244 R
MCNATT, T. G.	7908130663*	50-387 G
MCNEILL, W. M.	7908220640*	GA999
MCNEILL, W. M.	7908070120*	71-6698
MCNEILL, W. M.	7908020181*	GA999
MCNULTY, A.	7908230136	CONTRACT
MCNULTY, A.	7908030363	CONTRACT
MCNULTY, A.	7908160535	CONTRACT
MCNULTY, A.	7908160537	CONTRACT
MCPHERSON, R. B.	7908130212*	70-754
MCRORIE, A. F.	7908160431	50-400 A
MCVAUGH, R. W.	7908030200	71-288
MEADOWS, R.	7908080508*	50-249 S
MEARS, L. N.	7908130625*	GA999
MECCA, J. E.	7908300024	50-522 G
MECKELNBURG, R. L.	7907090108	PR
MEDROW, L. K.	7908270320	CONTRACT
MEIEROTTO, L. E.	7908170258	PROJ
MEISS, R. L.	7908300032	PROJ
MELROSE, T. G.	7908280277	40-8728
MENCZER, W. B.	7908170054	CONTRACT
MERLINO, R. J.	7908280047*	50-471 F
MERRILL, D. N.	7908140535*	50-443 A
MERSON, A.	7908140087	40-1162
MERSON, S. D.	7908230344	50-317 R
MERSON, S. D.	7908230349*	50-317 R
MESSITT, B. R.	7908070155*	50-261 G
METZENBAUM, H. M.	7908230016	50-320 U
MEYER, H. J.	7908090128*	REGOD
MEYER, B.	7908140645*	50-295 S
MEYER, R. O.	7908030125	ORG

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MEYER, R. O.	7908150635	50-320 P
MICA, D. A.	7907260324*	50-320 U
MICHEL, R. L.	7908140182	PR
MICHEL, C. J.	7908020046*	71-6400
MICHEL, C. J.	7908220224	70-143
MICHEL, C. J.	7908210606	70-143
MIDURA, H. J.	7908010495	50-272 R
MIDURA, H. J.	7908010329	50-272 S
MIDURA, H. J.	7908010537	50-272 R
MIDURA, H. J.	7908010540	50-272 R
MIDURA, H. J.	7908010315	50-272 S
MIDURA, H. J.	7908010450	50-272 R
MIDURA, H. J.	7908200366	50-272 R
MIERNICKI, M. J.	7908100503*	50-317 S
MIERNICKI, M. J.	7908280639*	50-317 S
MILES, E.	7908200357*	50-522 H
MILHOLLIN, G. L.	7908030287	50-272 T
MILHOLLIN, G. L.	7908030621	50-272 T
MILLER, B. L.	7908220374	50-361 G
MILLER, C. L.	7908080352*	50-482 G
MILLER, G. E.	7908130428	50-326 R
MILLER, G. E.	7908130429*	50-326 R
MILLER, M. I.	7906280112*	50-329 G
MILLER, G. P.	7906150423	50-320 P
MILLER, D. R.	7908070552	50-344 G
MILLEN, C. K.	7908080399	50-267 G
MILLEN, C. K.	7908200381	50-267 P
MILLER, L. K.	7908200367*	50-272 R
MILLER, N. E.	7908210193*	50-320 A
MILLER, M. E.	7908010266	70-2623
MILLER, M. E.	7908130230	70-2623
MILLER, M. E.	7908060105	50-329 T
MILLER, M. E.	7908060065	50-329 T
MILLER, M. E.	7908080548	50-329 T
MILLER, M. E.	7908080543	50-329 T
MILLER, M. E.	7908150037	70-2623
MILLER, M. E.	7908150042	70-2623
MILLER, M. E.	7908150022	70-2623
MILLER, M. E.	7908150722	70-2623
MILLER, W. O.	7908140280	50-237 P
MILLER, W. O.	7908030525	71-5926
MILLER, W. O.	7908030527	70-25
MILLER, W. O.	7908070007	40-8712
MILLER, W. O.	7908030519	70-1151
MILLER, W. O.	7908030535	70-1257
MILLER, W. O.	7908060147	50-281 P
MILLER, W. O.	7908170447	70-143
MILLER, W. O.	7908290508	50-269 P
MILLER, W. O.	7908170143	50-334 G
MILLER, W. O.	7908080252	50-302 P
MILLER, W. O.	7908080281	50-302 P
MILLER, W. O.	7908020012	70-1113
MILLER, W. O.	7908020015	70-824
MILLER, W. O.	7908020017	70-143
MILLER, W. O.	7908150181	70-1143
MILLER, W. O.	7908150190	70-33
MILLER, W. O.	7908270271	50-315 P
MILLER, W. O.	7908140483	50-409 P
MILLER, W. O.	7908130498	50-259 P
MILLER, W. O.	7908080206	70-734
MILLER, W. O.	7908160249	50-295 F
MILLER, W. O.	7908200154	50-553 A
MILLER, W. O.	7908080175	40-8584
MILLER, W. O.	7908080189	50-312 A
MILLER, W. O.	7908080198	50-334 P
MILLER, W. O.	7908210102	70-1257
MILLER, W. O.	7908220592	70-1113
MILLER, W. O.	7908170228	50-271 P
MILLER, W. O.	7908220064	50-334 P
MILLER, W. O.	7908170318	50-282 P
MILLER, W. O.	7908170347	70-1201
MILLER, W. O.	7908220328	70-33
MILLER, W. O.	7908290361	50-266 P
MILLER, W. O.	7908200090	50-261 P
MILLER, W. H.	7908030606*	50-416 G
MILLER, W.	7908230674*	50-280 G
MILLER, D. W.	7908280508*	50-373 G
MILLER, W. O.	7908160088	70-143
MILLER, W. O.	7908130656	50-219 F
MILLER, J.	7908060004	50-133 P
MILLER, J. R.	7908030585	ORG
MILLER, J. R.	7908080165	50-382 A
MILLER, J. R.	7908080190	50-516 A
MILLER, J. R.	7908080204	50-580 A
MILLER, J. R.	7908080227	50-395 A
MILLER, J. R.	7908080230	50-445 A
MILLER, J. R.	7908080247	50-437 A
MILLER, J. R.	7908080140	50-528 A
MILLER, J. R.	7908080168	50-466 A
MILLER, J. R.	7908080182	50-482 A
MILLER, J. R.	7908080199	50-568 A
MILLER, J. R.	7908080209	50-387 A
MILLER, J. R.	7908080234	50-483 A
MILLER, J. R.	7908080237	50-397 A
MILLER, J. R.	7908080148	50-358 A
MILLER, J. R.	7908080153	50-440 A
MILLER, J. R.	7908080158	50-341 A
MILLER, J. R.	7908080164	50-458 A
MILLER, J. R.	7908080176	50-461 A
MILLER, J. R.	7908080196	50-416 A
MILLER, J. R.	7908080202	50-367 A
MILLER, J. R.	7908080211	50-546 A
MILLER, J. R.	7908080216	50-443 A
MILLER, J. R.	7908080219	50-556 A
MILLER, J. R.	7908080224	50-572 A
MILLIKEN, M. G.	7908140606*	50-155 H
MILLS, D.	7908170632*	AGREEMENT
MILLS, L. M.	7908020482	50-327 S
MILLS, L. M.	7908020488	50-390 S
MILLS, L. M.	7908030058	50-327 S
MILLS, L. M.	7908030074	50-390 S
MILLS, L. M.	7908020453	50-327 S
MILLS, L. M.	7908060142	50-327 G
MILLS, L. M.	7908140672	50-518 S
MILLS, L. M.	7908170610	70-2443
MILLS, L. M.	7908140334	50-259 G
MILLS, L. M.	7908080734	50-518 G
MILLS, L. M.	7908020023	50-259 G
MILLS, L. M.	7908280698	50-327 S
MILLS, L. M.	7908030086	50-327 S
MILLS, L. M.	7908030404	50-390 S
MILLS, L. M.	7908060235*	50-566 G
MILLS, L. M.	7908170208	50-390 G
MILLS, L. M.	7908030337	50-390 S
MILLS, L. M.	7908030427	50-438 S
MILLS, L. M.	7908010398	50-327 S
MILLS, L. M.	7908010388	50-390 S
MILLS, L. M.	7908010400	50-327 S
MILLS, L. M.	7908010434	50-438 S
MILLS, L. M.	7908170517	50-327 G
MILLS, L. M.	7908010341	50-327 S
MILLS, L. M.	7908140681	50-438 S
MILLS, L. M.	7908140803	50-327 S
MILLS, L. M.	7908290636	50-259 G
MILLS, L. M.	7908230475	50-259 G
MILLS, L. M.	7908030410	50-390 S
MILLS, L. M.	7908060286	50-438 S
MILLS, L. M.	7908060344	50-390 S
MILLS, L. M.	7908060427	50-327 F
MILLS, L. M.	7908060437	50-259 F
MILLS, L. M.	7908060510	50-390 S
MILLS, L. M.	7908070671	50-259 R
MILLS, L. M.	7908140838	50-438 S
MILLS, L. M.	7908160070	50-259 G
MILLS, L. M.	7908160304	50-259 G
MILLS, L. M.	7908060245	50-259 P
MILLS, L. M.	7908060417	50-259 P
MILLS, L. M.	7908130545	50-390 S
MILLS, L. M.	7908300516	50-553 G
MILLS, L. M.	7908080541	50-390 A
MILLS, L. M.	7908080572	50-390 A
MILLS, L. M.	7908150503	50-390 S
MILLS, L. M.	7908150526	50-327 S
MILLS, L. M.	7908070357	50-259 K
MILLS, L. M.	7908140706	50-327 S
MILLS, L. M.	7908080519	50-296 P
MILLS, L. M.	7908100487	50-259 G
MILLS, L. M.	7908140552	50-259 P
MILLS, L. M.	7908140563	50-438 S
MILLS, L. M.	7908140540	50-390 S
MILLS, L. M.	7908140565	50-259 P
MILLS, L. M.	7908150469	50-259 H
MILLS, L. M.	7908140731	50-438 S
MILLS, L. M.	7908150622	50-327 S
MILLS, L. M.	7908270272	50-390 G
MILLS, L. M.	7908140411	50-390 K
MILLS, L. M.	7908140532	50-259 R
MILLS, L. M.	7908170442	50-327 A
MILLS, L. M.	7908230566	50-390 S
MILLS, L. M.	7908280606	50-553 S
MILLS, L. M.	7908280611*	50-553 S
MILLS, L. M.	7908210301	50-553 A
MILLS, L. M.	7908280599	50-390 S
MILLS, L. M.	7908170334	50-259 P
MILLS, L. M.	7908210550	50-390 K
MILLS, L. M.	7908230384	50-518 S
MILLS, L. M.	7908230451	50-518 S
MILLS, L. M.	7908230589	50-518 S
MILLS, L. M.	7908300682	50-327 S
MILLS, L. M.	7908210314	50-259 F
MILLS, L. M.	7908270185*	50-259 G
MILLS, L. M.	7908290426	50-390 S
MILLS, L. M.	7908290502	50-438 G
MILLS, L. M.	7908280581	50-327 S
MILLS, L. M.	7908280556	50-327 A
MILLS, L. M.	7908300688	50-327 A
MILLSAP, W. J.	7908160487*	50-348 G
MINGLE, J. O.	7908230269	PR
MINNER, W.	7908150716	50-320 P
MINOGUE, R. B.	7908230519*	50-344 G
MINOGUE, R. B.	7908210156	SECY
MINOGUE, R. B.	7908080650*	10CFR
MINOGUE, R. B.	7908080604*	10CFR
MINOGUE, R. B.	7908140257	SECY
MINOGUE, R. B.	7908010666*	10CFR
MINOGUE, R. B.	7908160135	REGGD
MINOGUE, R. B.	7908020493	PR
MINOGUE, R. B.	7908240063	PRM
MINOGUE, R. B.	7908130139	NUREG
MINOGUE, R. B.	7908300321	ORG
MISHIMA, J.	7908130212*	70-754
MISHIMA, J.	7908140339	RES
MITCHELL, D. G.	7908100469*	50-289 S
MITCHELL, D. G.	7908170430*	50-289 S
MITCHELL, D. G.	7908270444*	50-289 R
MITCHELL, P.	7908220392	50-522 G
MITCHELL, P.	7908080025	50-522 G
MITTL, R. L.	7908100442	50-311 E
MITTL, R. L.	7908160442	50-311 G
MITTL, R. L.	7908300512	50-311 A
MITTL, R. L.	7908300520	50-311 A
MITTL, R. L.	7908300661	50-311 A
MIYABAYASHI, M.	7908030228	XPORTLIC
MIYABAYSHI, M.	7908240299	XPORTLIC
MIYASAKI, D. H.	7908070748	NUREG
MOBLEY, J. D.	7908220544	71-321
MODENOS, L.	7908240132*	50-302 G
MODENOS, L.	7908210565*	50-366 G
MOELLER, D. W.	7908090523	ACRS
MOHR, H. C.	7908220671	70-754
MONDEN, T.	7908130136*	SECY
MONDEN, T.	7908140370*	SECY
MONDEN, T.	7908150558	XPORTLIC
MONDER, T.	7908100364	XPORTLIC
MONDEN, T.	7908100367*	XPORTLIC
MONDEN, T.	7908310505	XPORTLIC
MONHUSEN, C.	7908030023	XPORTLIC
MONTGOMERY, L.	7908140262	50-574 G
MONTI, W. A.	7908070353	50-247 S
MONTI, W. A.	7908170399	50-3 R
MOOD, D. E.	7908020108	71-6574
MOODY, E. J.	7908090262*	TOPREP
MOODY, D. E.	7908020106*	50-309 G
MOODY, D. E.	7908020588	50-309 G
MOODY, D. E.	7908140770	50-309 R
MOODY, D. E.	7908210356	50-309 P
MOODY, D. E.	7908200419	50-271 G
MOODY, D. E.	7908080181	50-271 G
MOODY, D. E.	7908230130	50-271 G
MOODY, D. E.	7908240580	50-271 G
MOODY, D. E.	7908140429	50-271 R
MOODY, D. E.	7908030172	50-29 G
MOODY, D. E.	7908160563	50-29 G
MOODY, D. E.	7908070712	50-29 G
MOODY, D. E.	7908200004	50-29 G
MOODY, D. E.	7908030204	50-29 S
MOODY, D. E.	7908140365	50-29 R
MOON, B. T.	7908270209*	50-259 G
MOON, B. T.	7908150407*	50-321 G
MOON, C. W.	7908150501	50-466 G
MOONEY, F. S.	7908270519	40-8725
MOORE, G. W.	7908060213	50-334 R
MOORE, G. W.	7908080480	50-334 P
MOORE, G. W.	7908140665	50-334 P
MOORE, G. C.	7908170630	50-302 G
MOORE, G. C.	7908290688	50-302 G
MOORE, J. B.	7908090699*	50-361 G
MOORE, J. B.	7908150311*	50-361 G

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MOORE, J. B.	7908010577	50-361 S
MOORE, J. B.	7908130405	50-206 H
MOORE, J. B.	7908130467	50-361 S
MOORE, R. N.	7908210043	XPORTLIC
MOORE, R. N.	7908300592	XPORTLIC
MOORE, J. E.	7906020019	50-272 E
MOORE, J. E.	7905150673	50-286 P
MOORE, J. E.	7906250396	50-272 G
MOORE, J. E.	7908020336	50-272 P
MOORE, J. E.	7908220152	50-272 G
MOORE, J. A.	7908220508	50-272 G
MOORE, R. H.	7908220083*	FOIA
MOORE, R. H.	7908220086*	FOIA
MOORE, D. E.	7908280859	70-27
MOORE, D. E.	7908170486*	70-143
MOORE, D. E.	7908240110*	50-250 G
MORGAN, W. F.	7908230105	XPORTLIC
MORGAN, W. F.	7908230109*	XPORTLIC
MORIYAMA, H. I.	7908280647*	50-471 F
MORRISSEY, J. C.	7908200047	50-133 G
MORSE, A. P.	7908030113*	50-409 G
MORTON, K. V.	7908080411*	CONTRACT
MORTON, K. V.	7908080444*	CONTRACT
MORTON, K. V.	7908100286*	CONTRACT
MORTON, K. V.	7908080435*	CONTRACT
MORTON, K. V.	7908080418*	CONTRACT
MORTON, K. V.	7908010216*	CONTRACT
MORTON, K. V.	7908290647*	CONTRACT
MORTON, K. V.	7908100309*	CONTRACT
MORTON, K. V.	7908160425*	CONTRACT
MORTON, K. V.	7908170131*	CONTRACT
MORTON, K. V.	7908290719*	CONTRACT
MORTON, K. V.	7908290699*	CONTRACT
MORTON, K. V.	7908270362*	CONTRACT
MORTON, K. V.	7908290471*	CONTRACT
MORTON, K. V.	7908270305*	CONTRACT
MORTON, K. V.	7908080412	CONTRACT
MORTON, K. V.	7908090456	CONTRACT
MORTON, K. V.	7908070720*	CONTRACT
MORTON, K. V.	7908020160*	CONTRACT
MORTON, K. V.	7908020497*	CONTRACT
MORTON, K. V.	7908140444*	CONTRACT
MORTON, K. V.	7908020346*	CONTRACT
MORTON, K. V.	7908090562*	CONTRACT
MORTON, K. V.	7908100295*	CONTRACT
MORTON, K. V.	7908020390*	CONTRACT
MORTON, K. V.	7908100314*	CONTRACT
MORTON, K. V.	7908100346*	CONTRACT
MORTON, K. V.	7908200125*	CONTRACT
MORTON, K. V.	7908230210*	CONTRACT
MORTON, K. V.	7908210294	CONTRACT
MORTON, K. V.	7908280077*	CONTRACT
MORTON, K. V.	7908280093*	CONTRACT
MORTON, K. V.	7908210185	CONTRACT
MORTON, K. V.	7908210198*	CONTRACT
MORTON, K. V.	7908210298*	CONTRACT
MORTON, K. V.	7908230222*	CONTRACT
MORTON, K. V.	7908230106*	CONTRACT
MOSCHNER, R. A.	7908140335	70-754
MOSCHNER, R. A.	7908130607	70-754
MOSCHNER, R. A.	7908090466	70-754
MOSELEY, N. C.	7908090255*	50-346 P
MOSELEY, N. C.	7908090278*	50-346 F
MOSELEY, N. C.	7908030332*	50-261 P
MOSELEY, N. C.	7908150684	50-320 P
MOSELEY, N. C.	7908080718*	50-338 P
MOSELEY, N. C.	7908080724*	50-280 P
MOSELEY, N. C.	7908080732*	50-280 P
MOSELEY, N. C.	7908080701*	50-280 P
MOSES, L.	7908200363	50-387 G
MOWRY, W. R.	7908140108	70-734
MOWRY, W. R.	7908160048	70-734
MOWRY, W. R.	7908140127	70-734
MOWRY, W. R.	7908140493	50-89 P
MOWRY, W. R.	7908210392	70-734
MOWRY, W. R.	7908090239	XPORTLIC
MOWRY, W. R.	7908090250*	XPORTLIC
MOWRY, W. R.	7908020378	XPORTLIC
MOWRY, W. R.	7908240387	50-89 P
MRAZEK	7908010287*	50-516 G
MUELLER, E. E.	7908150019	50-466 G
MULKEY, M. E.	7905310456	50-596 G
MULKEY, M. E.	7908130064	50-471 G
MULKEY, M. E.	7906030210	50-471 H
MULKEY, M. E.	7906280061	50-596 G
MULKEY, M. E.	7908270299	50-471 G
MULKEY, M. E.	7908300186	50-596 G
MULLER, G. E.	7908240634	50-461 G
MULLER, D. C.	7908140359	50-596 A
MULLER, D. R.	7908210147	50-368 P
MULLER, D. R.	7908150182	50-338 P
MULLER, D. R.	7908100189	50-488 G
MULLER, D. R.	7908290161	REGOD
MUNKITTRICK, G. T.	7908270410	50-387 A
MUNRA, J. J.	7908290422	70-9021
MUNRO, J. J.	7908100373	71-40
MURDOCK, L. T.	7908150734	40-299
MURLEY, T. E.	7908230004	50-320 P
MURPHY, C. E.	7908030234*	50-316 S
MURPHY, C. E.	7908060316*	50-316 S
MURPHY, C. E.	7908160325*	50-316 S
MURPHY, C. E.	7908210527*	50-316 S
MURPHY, C. E.	7908210270	50-250 G
MURPHY, C. E.	7903280174	50-281 G
MURPHY, C. E.	7908080711*	50-338 P
MURPHY, C. E.	7908020193	50-390 G
MURPHY, C. E.	7908020185	50-327 G
MURPHY, C. E.	7908020210	50-338 G
MURPHY, C. E.	7908020539*	50-416 G
MURPHY, C. E.	7908020520*	50-416 G
MURPHY, C. E.	7908010340	50-424 G
MURPHY, C. E.	7908020200	50-566 G
MURPHY, C. E.	7908030576	50-250 G
MURPHY, C. E.	7908150385*	50-438 G
MURPHY, C. E.	7908020080*	50-553 G
MURPHY, C. E.	7908030594	50-327 G
MURPHY, C. E.	7908150378*	50-438 G
MURPHY, C. E.	7908010709*	50-281 G
MURPHY, C. E.	7908210562	50-366 G
MURPHY, C. E.	7908030599*	50-416 G
MURPHY, C. E.	7908210575	50-566 G
MURPHY, C. E.	7908070144	50-390 G
MURPHY, C. E.	7908170206	50-400 G
MURPHY, C. E.	7908240090*	50-395 G
MURPHY, C. E.	7908290131	50-438 G
MURPHY, C. E.	7908150294*	50-369 G
MURPHY, C. E.	7908020553	50-424 G
MURPHY, C. E.	7908060271*	50-566 G
MURPHY, C. E.	7908160331*	50-395 G
MURPHY, C. E.	7908170059*	50-369 G
MURPHY, C. E.	7908240114	50-339 G
MURPHY, C. E.	7908100149	50-400 G
MURPHY, C. E.	7908160475*	50-321 G
MURPHY, C. E.	7908230672	50-280 G
MURPHY, C. E.	7908240147	50-281 G
MURPHY, C. E.	7908300129*	50-491 G
MURPHY, C. E.	7908240159*	50-281 G
MURPHY, C. E.	7908290197	50-518 G
MURPHY, C. E.	7908240275	50-281 G
MURPHY, C. E.	7908240361	50-348 G
MURPHY, C. E.	7908240128	50-302 G
MURPHY, C. E.	7908270248*	50-424 G
MURPHY, C. E.	7908230682	50-348 G
MURPHY, C. E.	7908230688	50-281 G
MURPHY, C. E.	7908010698	50-281 G
MURPHY, C. E.	7908020066	50-553 G
MURPHY, C. E.	7908160411*	50-400 G
MURPHY, C. E.	7908200215*	50-400 G
MURPHY, C. E.	7908230595	50-395 G
MURPHY, C. E.	7908230657	50-261 G
MURPHY, C. E.	7908240123	50-302 G
MURPHY, C. E.	7908240194	50-281 G
MURPHY, C. E.	7908240210	50-327 G
MURPHY, C. E.	7908240303	50-269 G
MURPHY, C. E.	7908240136	50-390 G
MURPHY, C. E.	7908160338*	50-424 G
MURPHY, C. E.	7908150310	50-438 G
MURPHY, C. E.	7908150355	50-438 G
MURPHY, C. E.	7908270297*	50-369 G
MURPHY, C. E.	7908030591	50-416 G
MURPHY, C. E.	7908300480*	50-491 G
MURPHY, C. E.	7908270309*	50-413 G
MURPHY, C. E.	7908060062	50-566 G
MURPHY, C. E.	7908300578*	50-400 G
MURPHY, C. E.	7908170476	50-390 A
MURPHY, C. E.	7908240083	50-395 G
MURPHY, C. E.	7908240140	50-281 G
MURPHY, C. E.	7908270232	50-424 G
MURPHY, C. E.	7908280128	50-390 G
MURPHY, C. E.	7908300109	50-491 G
MURRAY, P. L.	7908090429*	50-309 G
MURRAY, P. L.	7908090434*	50-309 G
MURRAY, T. D.	7908070491	50-346 S
MURRAY, T. D.	7908070688	50-346 S
MURRAY, T. D.	7908060435	50-346 S
MURRAY, T. D.	7908060447	50-346 S
MURRAY, T. D.	7908060453	50-346 S
MURRAY, T. D.	7908100496	50-346 S
MURRAY, T. D.	7908100403	50-346 S
MURRAY, T. D.	7908100462	50-346 S
MURRAY, T. D.	7908090568	50-346 S
MURRAY, T. D.	7908230495	50-346 S
MURRAY, T. D.	7908140460	50-346 R
MURRAY, T. D.	7908140793	50-346 S
MURRAY, T. D.	7908150502	50-346 S
MURRAY, T. D.	7908210459	50-346 S
MURRAY, T. D.	7908210433	50-346 S
MURRAY, J. D.	7908210444	50-346 S
MURRAY, T. D.	7908230387	50-346 S
MURRAY, T. D.	7908230523	50-346 S
MURRAY, T. D.	7908280716	50-346 S
MURRAY, T. D.	7908310423	50-346 S
MURRAY, J. P.	7908090425*	50-309 G
MURRAY, J. P.	7908170221*	50-289 P
MYERS, L. L.	7908240437*	TOPREP
MYERS, D. D.	7908230173*	SECY
MYERS, S.	7908210142	50-320 P
MYNATT, F. R.	7908020329	RES
MYNATT, F. R.	7908020184	RES
MYNATT, F. R.	7908080504	RES
MYNATT, W. A.	7908080414	CONTRACT
MYNATT, W. A.	7908080453	CONTRACT
MYNATT, W. A.	7908290432	CONTRACT
MYNATT, W. A.	7908280085	CONTRACT
MYNATT, W. A.	7908290694	CONTRACT
MYNATT, W. A.	7908200123	CONTRACT
MYRABO, A. L.	7908140769*	50-263 R
NAPUDA, G.	7908270122*	50-293 G
NARDACCI, G. A.	7908210374*	50-320 R
NARDACCI, G. A.	7908090378*	50-320 R
NARNTHOUSE, L. W.	7908030231	RES
NARROW, L.	7908230494*	50-320 G
NARROW, L.	7908270081*	50-363 G
NAUGHTON, W. F.	7908130447	50-454 G
NAUGHTON, W. F.	7908100412	50-599 H
NAUGHTON, W. F.	7908100444	50-599 H
NAUGHTON, W. F.	7908030394	50-295 F
NAUGHTON, W. F.	7908060306	50-454 K
NAVORRO, J. P.	7908100323	50-322 F
NAYLOR, R. W.	7908070692*	50-346 S
NAYLOR, R. W.	7908060450*	50-346 S
NAYLOR, R. W.	7908140797*	50-346 S
NAYLOR, R. W.	7908210448*	50-346 S
NEAL, R. A.	7908140494*	50-206 R
NECHODOM, W. S.	7908300778	71-9022
NECHODOM, W. S.	7908310006	71-5768
NEEL, J. N.	7908020120*	07-22
NEHEMIAS, J. V.	7908030479*	FOIA
NEIGHBORS, J. D.	7908020268	50-280 P
NEIGHBORS, J. D.	7908070758	50-280 P
NEIGHBORS, J. D.	7908220263	50-280 P
NEIGHBORS, J. D.	7908160223	50-280 P
NEIGHBORS, J. D.	7908170157	50-280 P
NEIL, R. M.	7908020562	50-338 G
NEIL, R. M.	7908020567*	50-338 G
NEISLER, J. H.	7908170179*	50-373 G
NELSON, J. D.	7908140198	FROJ
NELSON, P. R.	7908230629	50-320 G
NELSON, P. R.	7908230614	50-320 G
NELSON, P. R.	7908230531	50-320 G
NELSON, C. C.	7908080223	50-309 P
NELSON, C. C.	7908300734	50-309 P
NEWMAN, J. R.	7908080075	50-466 G
NEWMAN, J. R.	7908080092	50-466 G
NEWMAN, J. R.	7908220304	50-466 G
NEWMAN, J. R.	7908220312	50-466 G
NEWMAN, J. R.	7908220334	50-498 G
NEWMAN, J. R.	7908200341	FOIA
NEWMAN, J. R.	7908150432	50-466 A
NICHOLAS, H. H.	7908130663*	50-387 G
NICHOLAS, H. H.	7908020154*	50-272 G
NICKELL, R. E.	7908140695*	50-285 G
NIJHAWAN, S.	7908140631	RES
NILSON, R.	7908070241	70-1257
NILSON, R.	7908140320	70-1257
NILSON, R.	7908140113	70-1257
NILSON, R.	7908230301	70-1257
NIX, P. [illegible]	7908070493*	50-366 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
NIX, R. T.	7908070498*	50-366	S
NIX, R. T.	7908070699*	50-321	S
NIX, R. T.	7908130453*	50-366	S
NIX, R. T.	7908130415*	50-321	S
NIX, R. T.	7908130435*	50-366	S
NIX, R. T.	7908130494*	50-366	S
NIX, R. T.	7908130502*	50-366	S
NIX, R. T.	7908130473*	50-366	S
NIX, R. T.	7908140646*	50-366	S
NIX, R. T.	7908140796*	50-366	S
NIX, R. T.	7908140702*	50-366	S
NIX, R. T.	7908200267*	50-321	S
NIX, R. T.	7908200352*	50-366	S
NIX, R. T.	7908200374*	50-366	S
NIX, R. T.	7908200379*	50-366	S
NIX, R.	7908310322*	50-366	S
NIX, R. T.	7908310327*	50-321	S
NIXON, W.	7908080616	40-2061	
NIXON, W. A.	7908210081	40-2061	
NIXON, W. A.	7908210085	40-2061	
NOIRHELM, L. J.	7908020154*	50-272	Q
NOLAN, L. L.	7908090565*	50-263	S
NOLAN, F.	7908020044*	50-280	Q
NOON, F.	7908090584*	50-316	Q
NORDERHAUG, L. R.	7908030575	50-192	Q
NORDERHAUG, L. R.	7908310102	70-2804	
NORDERHAUG, L. R.	7908280784	70-1768	
NORDERHAUG, L. R.	7908210261	50-275	Q
NORDERHAUG, L. R.	7908280789	50-326	Q
NORELIUS, C. E.	7908080229*	50-358	Q
NORGAARD, J. A.	7909010671	71-128	
NORTH, H. S.	7907160262	50-320	H
NORTON, B.	7908220030	50-275	Q
NOSENZO, L. V.	7908230424*	10CFR	
NOSENZO, L. V.	7908130653*	SECY	
NOSENZO, L. V.	7908020243	XPORTLIC	
NOSENZO, L. V.	7908080506	XPORTLIC	
NOSENZO, L. V.	7908010346	XPORTLIC	
NOSENZO, L. V.	7908020048	XPORTLIC	
NOSENZO, L. V.	7908020054	XPORTLIC	
NOSENZO, L. V.	7908020059	XPORTLIC	
NOSENZO, L. V.	7908020063	XPORTLIC	
NOSENZO, L. V.	7908020043	XPORTLIC	
NOSENZO, L. V.	7908020050	XPORTLIC	
NOSENZO, L. V.	7908100376	XPORTLIC	
NOSENZO, L. V.	7908100377	XPORTLIC	
NOSENZO, L. V.	7908240624	XPORTLIC	
NOSENZO, L. V.	7908100557	XPORTLIC	
NOSENZO, L. V.	7908150534	XPORTLIC	
NOSENZO, L. V.	7908230343	XPORTLIC	
NOSENZO, L. V.	7908230408	XPORTLIC	
NOSENZO, L. V.	7908130141*	SECY	
NOSENZO, L. V.	7908130157*	SECY	
NOSENZO, L. V.	7908080463	XPORTLIC	
NOSENZO, L. V.	7908010523	XPORTLIC	
NOSENZO, L. V.	7908010530	XPORTLIC	
NOSENZO, L. V.	7908240538*	SECY	
NOSENZO, L. V.	7908240553*	SECY	
NOSENZO, L. V.	7908160067	XPORTLIC	
NOSENZO, L. V.	7908160063	XPORTLIC	
NOVAK, T.	7908220425*	50-320	P
NOVAK, T. M.	7908220421	50-320	P
NOVARRO, J. P.	7908100100	50-322	Q
NOVARRO, J. P.	7908030208	50-322	Q
NOVARRO, J. P.	7908150010	50-322	A
NOVARRO, J. P.	7908070460	50-322	Q
NOVARRO, J. P.	7908090633	50-322	Q
NOVARRO, J. P.	7908010334	50-322	A
NOVARRO, J. P.	7908230095	50-322	Q
NOVARRO, J. P.	7908200197	50-322	F
NOVARRO, J. P.	7908280576	50-322	A
NOVARRO, J. P.	7908280651	50-322	Q
NOVICK, A. H.	7908240668	NUREG	
NOVIK, J. D.	7908160416	FOIA	
NOVI, S. J.	7908130500	50-155	P
NOVI, S. J.	7908230681	50-219	P
NOVS, C. R.	7908310420*	50-298	S
NOZENT, E. L.	7908310006	40-2259	
NYMAN, B. M.	7908060035	50-208	H
O'BRIEN, T. H.	7908210020*	COMMISSION	
O'CONNOR, J. M.	7908240659	NUREG	
O'HANLON, J. P.	7908080502	50-313	S
O'HANLON, J. P.	7908310381	50-313	S
O'HARA, W. J.	7908150143	XPORTLIC	
O'NEIL, R. A.	7908290254	50-496	M
O'NEIL, R. A.	7908290254	50-496	M
O'NEILL, J. J.	7908310425*	50-346	S
O'NEILL, J. J.	7908060455*	50-346	S
O'REILLY, J. P.	7908230581	50-320	Q
O'REILLY, J. P.	7908[illegible]	50-320	Q
O'REILLY, J. P.	7908[illegible]360	70-143	
O'REILLY, J. P.	7908010638	50-302	Q
O'REILLY, J. P.	7908150331*	50-438	Q
O'REILLY, J. P.	7908[illegible]0371	50-348	Q
O'REILLY, J. P.	7908160181*	50-250	Q
O'REILLY, J. P.	7908170628*	70-1151	
O'REILLY, J. P.	7908070126	50-261	Q
O'REILLY, J. P.	7908070131	50-413	Q
O'REILLY, J. P.	7908070142	50-321	Q
O'REILLY, J. P.	7908070150	50-259	Q
O'REILLY, J. P.	7908070178	50-280	Q
O'REILLY, J. P.	7908070187	50-437	Q
O'REILLY, J. P.	7908100243	50-321	S
O'REILLY, J. P.	7908080674	50-395	Q
O'REILLY, J. P.	7908080678	50-280	Q
O'REILLY, J. P.	7908270289	50-335	Q
O'REILLY, J. P.	7908020322	50-321	P
O'REILLY, J. P.	7908010024	50-348	Q
O'REILLY, J. P.	7908010025	50-261	Q
O'REILLY, J. P.	7908010026	50-269	Q
O'REILLY, J. P.	7908010028	50-302	Q
O'REILLY, J. P.	7908010029	50-250	Q
O'REILLY, J. P.	7908010031	50-321	Q
O'REILLY, J. P.	7908010032	50-259	Q
O'REILLY, J. P.	7908010035	50-280	Q
O'REILLY, J. P.	7908010078	50-62	Q
O'REILLY, J. P.	7908270284	50-491	A
O'REILLY, J. P.	7908160569	50-269	Q
O'REILLY, J. P.	7908220072	70-143	
O'REILLY, J. P.	7908030104	50-348	Q
O'REILLY, J. P.	7908030105	50-261	Q
O'REILLY, J. P.	7908030114	50-269	Q
O'REILLY, J. P.	7908030121	50-413	Q
O'REILLY, J. P.	7908030130	50-302	Q
O'REILLY, J. P.	7908030132	50-250	Q
O'REILLY, J. P.	7908030134	50-321	Q
O'REILLY, J. P.	7908030137	50-416	Q
O'REILLY, J. P.	7908030139	50-395	Q
O'REILLY, J. P.	7908030144	50-280	Q
O'REILLY, J. P.	7908030152	50-437	Q
O'REILLY, J. P.	7908010399	50-348	Q
O'REILLY, J. P.	7908010401	50-261	Q
O'REILLY, J. P.	7908010405	50-269	Q
O'REILLY, J. P.	7908010407	50-413	Q
O'REILLY, J. P.	7908010410	50-302	Q
O'REILLY, J. P.	7908010412	50-250	Q
O'REILLY, J. P.	7908010414	50-321	Q
O'REILLY, J. P.	7908010416	50-416	Q
O'REILLY, J. P.	7908010417	50-395	Q
O'REILLY, J. P.	7908010418	50-280	Q
O'REILLY, J. P.	7908010419	50-437	Q
O'REILLY, J. P.	7908060356	50-395	Q
O'REILLY, J. P.	7908060362	50-280	Q
O'REILLY, J. P.	7908230198	50-259	Q
O'REILLY, J. P.	7908020316	50-259	Q
O'REILLY, J. P.	7908020552	50-261	Q
O'REILLY, J. P.	7908030002	50-269	Q
O'REILLY, J. P.	7908030005	50-413	Q
O'REILLY, J. P.	7908030006	50-302	Q
O'REILLY, J. P.	7908030009	50-250	Q
O'REILLY, J. P.	7908030013	50-321	Q
O'REILLY, J. P.	7908030017	50-416	Q
O'REILLY, J. P.	7908030019	50-395	Q
O'REILLY, J. P.	7908030033	50-259	Q
O'REILLY, J. P.	7908030042	50-280	Q
O'REILLY, J. P.	7908030046	50-437	Q
O'REILLY, J. P.	7908080038	50-269	Q
O'REILLY, J. P.	7908080039	50-302	Q
O'REILLY, J. P.	7908080043	50-250	Q
O'REILLY, J. P.	7908080046	50-321	Q
O'REILLY, J. P.	7908080050	50-416	Q
O'REILLY, J. P.	7908080051	50-395	Q
O'REILLY, J. P.	7908080052	50-395	Q
O'REILLY, J. P.	7908080054	50-259	Q
O'REILLY, J. P.	7908080063	50-280	Q
O'REILLY, J. P.	7908130045	50-261	Q
O'REILLY, J. P.	7908130062	50-348	Q
O'REILLY, J. P.	7908130069	50-395	Q
O'REILLY, J. P.	7908130091	50-348	Q
O'REILLY, J. P.	7908130095	50-261	Q
O'REILLY, J. P.	7908130101	50-413	Q
O'REILLY, J. P.	7908130106	50-269	Q
O'REILLY, J. P.	7908130108	50-302	Q
O'REILLY, J. P.	7908130112	50-250	Q
O'REILLY, J. P.	7908130124	50-321	Q
O'REILLY, J. P.	7908130126	50-416	Q
O'REILLY, J. P.	7908130128	50-395	Q
O'REILLY, J. P.	7908130132	50-395	Q
O'REILLY, J. P.	7908130134	50-437	Q
O'REILLY, J. P.	7908130281	50-280	Q
O'REILLY, J. P.	7908070300	50-348	P
O'REILLY, J. P.	7908070305	50-261	P
O'REILLY, J. P.	7908070306	50-269	P
O'REILLY, J. P.	7908070309	50-302	P
O'REILLY, J. P.	7908070315	50-250	P
O'REILLY, J. P.	7908070316	50-321	P
O'REILLY, J. P.	7908070317	50-259	P
O'REILLY, J. P.	7908070322	50-280	P
O'REILLY, J. P.	7908220031	50-[illegible]61	W
O'REILLY, J. P.	7908070292	70-27	
O'REILLY, J. P.	7908070294	70-824	
O'REILLY, J. P.	7908070299	70-143	
O'REILLY, J. P.	7908210291	50-250	P
O'REILLY, J. P.	7908150368	50-261	P
O'REILLY, J. P.	7908060515	50-302	Q
O'REILLY, J. P.	7908060518	50-250	Q
O'REILLY, J. P.	7908060524	50-280	Q
O'REILLY, J. P.	7908070708	50-364	Q
O'REILLY, J. P.	7908070716	50-400	Q
O'REILLY, J. P.	7908070727	50-261	Q
O'REILLY, J. P.	7908070730	50-413	Q
O'REILLY, J. P.	7908070741	50-369	Q
O'REILLY, J. P.	7908070749	50-302	Q
O'REILLY, J. P.	7908070754	50-250	Q
O'REILLY, J. P.	7908070760	50-424	Q
O'REILLY, J. P.	7908070761	50-280	Q
O'REILLY, J. P.	7908070771	50-339	Q
O'REILLY, J. P.	7908080642	50-348	Q
O'REILLY, J. P.	7908080645	50-261	Q
O'REILLY, J. P.	7908080647	50-269	Q
O'REILLY, J. P.	7908080702	50-348	Q
O'REILLY, J. P.	7908080704	50-261	Q
O'REILLY, J. P.	7908080706	50-324	Q
O'REILLY, J. P.	7908080708	50-369	Q
O'REILLY, J. P.	7908080712	50-302	Q
O'REILLY, J. P.	7908080715	50-250	Q
O'REILLY, J. P.	7908080716	50-321	Q
O'REILLY, J. P.	7908080721	50-259	Q
O'REILLY, J. P.	7908080728	50-280	Q
O'REILLY, J. P.	7908080733	50-348	Q
O'REILLY, J. P.	7908080738	50-389	Q
O'REILLY, J. P.	7908080741	50-321	Q
O'REILLY, J. P.	7908080743	50-395	Q
O'REILLY, J. P.	7908080746	50-259	Q
O'REILLY, J. P.	7908080749	50-327	Q
O'REILLY, J. P.	7908090369	50-269	Q
O'REILLY, J. P.	7908170606	50-302	P
O'REILLY, J. P.	7908220403	50-338	Q
O'REILLY, J. P.	7908160197	50-348	Q
O'REILLY, J. P.	7908160201	50-261	Q
O'REILLY, J. P.	7908160207	50-269	Q
O'REILLY, J. P.	7908160214	50-413	Q
O'REILLY, J. P.	7908160229	50-302	Q
O'REILLY, J. P.	7908160232	50-250	Q
O'REILLY, J. P.	7908160236	50-321	Q
O'REILLY, J. P.	7908160244	50-416	Q
O'REILLY, J. P.	7908160245	50-395	Q
O'REILLY, J. P.	7908160247	50-395	Q
O'REILLY, J. P.	7908160252	50-259	Q
O'REILLY, J. P.	7908160276	50-280	Q
O'REILLY, J. P.	7908160283	50-437	Q
O'REILLY, J. P.	7908210348	50-280	P
O'REILLY, J. P.	7908270113	50-302	H
O'REILLY, J. P.	7908130039	50-269	Q
O'REILLY, J. P.	7908210346	50-302	P
O'REILLY, J. P.	7908300355	50-321	P
O'REILLY, J. P.	7908300607	50-395	F
O'REILLY, J. P.	7908160134	50-261	Q
O'REILLY, J. P.	7908160137	50-269	Q
O'REILLY, J. P.	7908160140	50-302	Q
O'REILLY, J. P.	7908160146	50-250	Q
O'REILLY, J. P.	7908160148	50-321	Q
O'REILLY, J. P.	7908160151	50-259	Q
O'REILLY, J. P.	7908220199	50-369	Q
O'REILLY, J. P.	7908220617	50-364	Q
O'REILLY, J. P.	7908220619	50-348	Q
O'REILLY, J. P.	7908220621	50-400	Q
O'REILLY, J. P.	7908220625	50-413	Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
O'REILLY, J. P.	7908220636	50-389	Q
O'REILLY, J. P.	7908220638	50-424	Q
O'REILLY, J. P.	7908220650	50-327	Q
O'REILLY, J. P.	7908220655	50-280	Q
O'REILLY, J. P.	7908220657	50-339	Q
O'REILLY, J. P.	7908170002	70-1201	
O'REILLY, J. P.	7908170003	70-27	
O'REILLY, J. P.	7908170004	70-1113	
O'REILLY, J. P.	7908170005	70-143	
O'REILLY, J. P.	7908170006	70-1151	
O'REILLY, J. P.	7908170007	50-348	Q
O'REILLY, J. P.	7908170008	50-324	Q
O'REILLY, J. P.	7908170009	50-261	Q
O'REILLY, J. P.	7908170010	50-269	Q
O'REILLY, J. P.	7908170011	50-302	Q
O'REILLY, J. P.	7908170012	50-250	Q
O'REILLY, J. P.	7908170013	50-321	Q
O'REILLY, J. P.	7908170015	50-259	Q
O'REILLY, J. P.	7908170016	50-280	Q
O'REILLY, J. P.	7908210428	50-261	Q
O'REILLY, J. P.	7908210435	70-115	
O'REILLY, J. P.	7908270268	50-259	H
O'REILLY, J. P.	7908290178	50-348	Q
O'REILLY, J. P.	7908290187	50-261	Q
O'REILLY, J. P.	7908290190	50-269	Q
O'REILLY, J. P.	7908290192	50-302	Q
O'REILLY, J. P.	7908290196	50-250	Q
O'REILLY, J. P.	7908290200	50-321	Q
O'REILLY, J. P.	7908290212	50-298	Q
O'REILLY, J. P.	7908290217	50-259	Q
O'REILLY, J. P.	7908290225	50-260	Q
O'REILLY, J. P.	7908210150	50-321	Q
O'REILLY, J. P.	7908130232	50-29	P
O'REILLY, J. P.	7908270334	50-320	Q
OBERG, C. R.	7908010060*	50-482	Q
OBERG, C. R.	7908010043*	50-458	Q
OBERG, C.	7908020133*	50-485	Q
OBERST, D.	7908070635	50-387	Q
ODDIS, C. E.	7908100593	71-6172	
ODDIS, C. E.	7908100538	71-5149	
ODEGAARDEN, R. H.	7906210370*	70-2623	
OEHLKERS, W. G.	7908090004*	50-354	Q
OESTMANN, M. J.	7908010074*	50-155	Q
OESTMANN, M. J.	7908080700*	50-295	Q
OH, I.	7908080423	NUREG	
OHRIG, R. E.	7908090537	50-335	Q
OHRIG, R. E.	7908090541	50-250	Q
OKRENT, D.	7908090523	ACRS	
OKRENT, D.	7908030364	ACRS	
OKRENT, D.	7908220115	50-320	T
OKUDA, H.	7908100378	XPORTLIC	
OLDHAM, W. A.	7908140459	50-201	P
OLLER, R. E.	7908090115*	GA999	
OLLER, R. E.	7908080006*	GA999	
OLLER, R. E.	7908030055*	50-320	P
OLMSTEAD, W. J.	7908170349*	COMMISSION	
OLMSTEAD, W. J.	7908080048	50-329	Q
OLSEN, A. F.	7908280751	71-5950	
OLSEN, A. F.	7908100561	70-824	
OLSEN, A. F.	7908060222	50-99	P
OLSEN, A. F.	7908310410	50-13	P
OLSEN, C. S.	7908240068	NUREG	
OLSHAN, L. N.	7908030484	50-305	P
OLSHINSKI, J. A.	7908030493	ORG	
OLSON, O. L.	7908080402	50-186	Q
OLSON, R. C.	7908100205	50-317	F
OLSON, W. G.	7908030082	RES	
ONSDORFF, K. A.	7908130251	50-272	Q
ONSDORFF, K. A.	7908220[illegible]	50-272	Q
ONSDORFF, K. A.	7908150023	50-272	Q
ONSDORFF, K. A.	7908090438	50-272	Q
OPEKA, J. F.	7908160455	50-336	S
OPEKA, J. F.	7908070711	50-336	S
OPEKA, J. F.	7908010674	71-6601	
OPEKA, J. F.	7908070573	50-245	S
OPEKA, J. F.	7908030299	50-336	S
OPEKA, J. F.	7908060528	50-336	S
OPEKA, J. F.	7908100445	50-245	S
OPEKA, J. F.	7908160409	50-245	S
OPEKA, J. F.	7908160441	50-336	R
OPEKA, J. F.	7908160471	50-245	S
OPEKA, J. F.	7908170410	50-336	S
OPEKA, J. F.	7908210549	50-245	R
OPEKA, J. F.	7908280711	50-245	S
OPLINGER, Q. Q.	7909130147*	SECY	
OPLINGER, Q. Q.	7908130659*	SECY	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
OPREA, G. W.	7908070393	50-498	S
ORTLOFF, G. D.	7908030016	40-8102	
OSANN, E. W.	7908030561	50-367	Q
OST, F.	7908140542*	50-295	S
OSTI, A. P.	7908150440	FOIA	
OTTOSON, H. L.	7908210395	50-206	R
OVERLID, T. W.	7908100435*	50-263	S
OVERLID, T. W.	7908240511*	50-263	S
OVERMAN, R. F.	7908210166*	50-320	P
OWSLEY, G. F.	7908210564	TOPREP	
OWSLEY, G. F.	7908210572	TOPREP	
PACE, J. V.	7908200001	PROJ	
PACK, D. R.	7908070748	NUREG	
PADGETT, E. V.	7908300047*	50-522	Q
PAGANO, A.	7908080352*	50-482	Q
PAGE, R. G.	7908170542*	70-572	
PAGLIARO, J. A.	7908280136*	70-572	
PAHWA, S. B.	7908030034	NUREG	
PALTIN, S.	7908310390	50-275	Q
PAPPAS, I.	7908100298	50-10	Q
PAPPAS, I.	7908020279	50-10	Q
PAPPAS, I.	7908020366	ORG	
PAPPAS, H.	7908300242	50-10	Q
PAPPAS, H.	7908300246	ORG	
PAPWORTH, L. G.	7908210393*	50-409	R
PAPWORTH, L. G.	7908140647*	50-409	S
PAPWORTH, L. G.	7908150214*	50-409	S
PAPWORTH, L. G.	7908150428*	50-409	R
PARAKAS, P.	7908200342	50-247	R
PARIKH, K.	7908080352*	50-482	Q
PARIS, O. .	7908080273*	50-596	Q
PARKER, J.	7908150465	ORG	
PARKER, T. M.	7908140555*	50-295	S
PARKER, W. O.	7908030197*	70-2623	
PARKER, W. O.	7908010265	50-269	Q
PARKER, W. O.	7908030038	50-269	Q
PARKER, W. O.	7908020513	50-369	Q
PARKER, W. O.	7908030620*	50-269	Q
PARKER, W. O.	7908030601	50-369	Q
PARKER, W. O.	7908070735	50-269	Q
PARKER, W. O.	7908080094	50-369	A
PARKER, W. O.	7908220281	50-269	Q
PARKER, W. O.	7908270307	50-369	Q
PARKER, W. O.	7908210379	50-269	Q
PARKER, W. O.	7908170171	50-369	Q
PARKER, W. O.	7908150295	50-369	Q
PARKER, W. O.	7908070805	50-269	Q
PARKER, W. O.	7908070815	50-269	Q
PARKER, W. O.	7908170057	50-369	Q
PARKER, W. O.	7908140501	50-270	S
PARKER, W. O.	7908140581	50-269	S
PARKER, W. O.	7908140608	50-269	S
PARKER, W. O.	7908140827	50-269	S
PARKER, W. O.	7908220673	50-269	Q
PARKER, W. O.	7908010467	50-269	P
PARKER, W. O.	7908150408	50-269	Q
PARKER, W. O.	7908010485	50-369	A
PARKER, W. O.	7908010371	50-269	P
PARKER, W. O.	7908010377	50-269	F
PARKER, W. O.	7908010441	50-269	P
PARKER, W. O.	7908020463	50-269	S
PARKER, W. O.	7908060508	50-269	S
PARKER, W. O.	7908220505	70-2623	
PARKER, W. O.	7908160271	50-269	Q
PARKER, W. O.	7908160287	50-369	Q
PARKER, W. O.	7908070646	50-269	S
PARKER, W. O.	7908060517	50-247	F
PARKER, W. O.	7908100270	50-259	P
PARKER, W. O.	7908100498	50-369	A
PARKER, W. O.	7908100499	50-269	S
PARKER, W. O.	7908300524	50-269	Q
PARKER, W. O.	7908270293	50-369	Q
PARKER, W. O.	7908160374	50-269	S
PARKER, W. O.	7908210529	50-269	R
PARKER, W. O.	7908280608	50-369	S
PARKER, W. O.	7908230487	50-269	H
PARKER, W. O.	7908210004	50-269	F
PARKER, W. O.	7908210006	50-369	F
PARKER, W. O.	7908220340	50-269	P
PARKER, W. O.	7908230323	50-269	S
PARKER, W. O.	7908230470	50-269	P
PARKER, W. O.	7908240389	50-269	S
PARKER, W. O.	7908280658	50-269	P
PARKER, W. O.	7908280669	50-269	P
PARKER, W. O.	7908300735	50-269	P
PARKER, W. O.	7908280630	50-269	S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
PARKER, H. M.	7908210115	ACRS	
PARR, O. D.	7908060088	50-568	A
PARR, O. D.	7908300062	50-311	A
PARR, O. D.	7908100518	50-482	A
PARR, O. D.	7908080549*	50-373	A
PARR, O. D.	7907100694	TOPREP	
PARR, O. D.	7908010635	TOPREP	
PARR, O. D.	7908080639	50-373	A
PARR, O. D.	7908160501	50-338	P
PARR, O. D.	7908030194	50-338	F
PARR, O. D.	7908300435	50-423	A
PARR, O. D.	7908300457	50-387	A
PARR, O. D.	7908170300	50-502	H
PARR, O. D.	7908170477	50-338	F
PARR, O. D.	7908080162	50-373	A
PARR, O. D.	7908080172	50-528	A
PARR, O. D.	7908080183	50-438	A
PARR, O. D.	7908080192	50-397	A
PARR, O. D.	7908080286	50-502	A
PARR, O. D.	7908090014	50-528	A
PARR, O. D.	7908090507	50-338	P
PARR, O. D.	7908100520	50-498	A
PARR, O. D.	7908100182	50-400	A
PARR, O. D.	7908150177	50-373	A
PARR, O. D.	7908160309	50-373	A
PARR, O. D.	7908200079	50-387	A
PARR, O. D.	7908200122	50-311	Q
PARR, O. D.	7908170127	50-339	A
PARR, O. D.	7908220061	50-339	A
PARR, O. D.	7908300277	50-338	P
PARR, O. D.	7908130544	50-498	A
PARR, O. D.	7908130546	50-311	A
PARR, O. D.	7908130549	50-438	A
PARR, O. D.	7908200025	50-339	A
PARR, O. D.	7908290329	50-338	P
PARR, O. D.	7908290343*	50-338	P
PARR, O. D.	7908290373*	50-338	P
PARR, O. D.	7908300295	50-373	A
PARSONS, W. B.	7908090151*	XPORTLIC	
PARSONS, W. B.	7908090145	XPORTLIC	
PARTLOW, J. G.	7908020538	70-1151	
PARTLOW, J. G.	7908130362	70-820	
PARTLOW, J. G.	7908150332	70-27	
PARTLOW, J. G.	7908010103	70-820	
PARTLOW, J. G.	7908020524	70-1201	
PARTLOW, J. G.	7908080409	70-1113	
PARTLOW, J. G.	7908080413	70-143	
PARTLOW, J. G.	7908080415	70-820	
PARTLOW, J. G.	7908210083	70-25	
PARTLOW, J. G.	7908170110	70-754	
PARTLOW, J. G.	7908290084	70-1113	
PARTLOW, J. G.	7908080101	70-33	
PARTLOW, J. G.	7908070820	70-824	
PARTLOW, J. G.	7908070823	70-25	
PARTLOW, J. G.	7908070826	70-1257	
PARTLOW, J. G.	7908070829	70-734	
PARTLOW, J. G.	7908070833	70-33	
PARTLOW, J. G.	7908070836	70-371	
PARTLOW, J. G.	7908070837	70-820	
PARTLOW, J. G.	7908070839	70-1143	
PARTLOW, J. G.	7908070840	70-1151	
PARTLOW, J. G.	7908170178	70-135	
PARTLOW, J. G.	7908200416	70-1201	
PARTLOW, J. G.	7908170156	70-371	
PARTLOW, J. G.	7908210139	70-820	
PARTLOW, J. G.	7908210144	70-27	
PARTLOW, J. G.	7908240606	70-1143	
PARTLOW, J. G.	7908160030	70-371	
PARTLOW, J. G.	7908220138	70-1201	
PARTLOW, J. G.	7908150730	70-754	
PARTLOW, J. G.	7908170146	70-1257	
PARTLOW, J. G.	7908140073	70-143	
PARTLOW, J. G.	7908220078	70-1257	
PARTLOW, J. G.	7908230100	70-1201	
PARTLOW, J. G.	7908090611	70-27	
PARTLOW, J. G.	7908160539	70-1100	
PARTLOW, J. G.	7908200249	70-33	
PARTLOW, J. G.	7908160532	70-1143	
PASCHEN, D.	7908140315	71-149	
PATE, R. J.	7908170114*	50-361	Q
PATON, W. D.	7905240759	50-389	Q
PATON, W. D.	7908100370	50-329	Q
PATTEN, T. W.	7908210577*	TOPREP	
PATTERSON, J. P.	7908090257*	50-295	Q
PATTERSON, J. P.	7908020260*	70-1193	
PAUL, R. A.	7908280136*	70-572	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PAYNE, H. J.	7908240142	NUREG
PEARLMAN, H.	7908010559	50-320 P
PEARLMAN, J.	7908030065	CONTRACT
PECK, C. H.	7908210524*	50-244 S
PECK, E. E.	7908020188*	70-8
PEDERSEN, K.	7908220120*	FOIA
PEDERSEN, K.	7908220127*	FOIA
PEDERSEN, K.	7908280059*	FOIA
PEDERSEN, K.	7908280087*	FOIA
PEDERSEN, K.	7908280070*	FOIA
PEDERSEN, K.	7908280063*	FOIA
PEDERSEN, K.	7908280081*	FOIA
PEERY, W. W.	7908170074*	70-143
PELTIER, I. A.	7908130334	50-522 A
PELTIER, I. A.	7908230082	50-522 A
PELTIER, I. A.	7908160206	50-358 A
PELTIER, I. A.	7908160215	50-358 A
PENGOV, C. A.	7908280765	71-5796
PERHAUCH, J. C.	7908160350	71-109
PERKINS, T. J.	7908150633*	50-220 R
PERLMAN, J. R.	7908030387	CONTRACT
PERLMAN, J.	7908230091*	CONTRACT
PERLMAN, J.	7908030373	CONTRACT
PERLMAN, J.	7908220324	CONTRACT
PERLMAN, J.	7908220672	CONTRACT
PERLMAN, J.	7908230094	CONTRACT
PERLMAN, J.	7908090662*	CONTRACT
PERLMAN, J.	7908090658	CONTRACT
PERLMAN, J.	7908220522	CONTRACT
PERNY, C. D.	7908210320*	50-321 G
PERROTTI, D. J.	7908280171*	50-280 G
PERRY, J. A.	7908210499	TOPREP
PERRY, J. C.	7908140795*	50-344 S
PERRY, J. C.	7908130389*	50-344 S
PERSON, L. S.	7908310055	40-8674
PETERSON, B. F.	7908150661*	50-320 P
PETERSON, J.	7908170609	FOIA
PETERS, W. H.	7908140068	NUREG
PETERSON, R. K.	7908230520*	COMMISSION
PETERSON, R. R.	7908240541*	SECY
PETERSON, R. R.	7908240556*	SECY
PETERSON, R. R.	7908080021	XPORTLIC
PETERSON, R. R.	7908160004	XPORTLIC
PETERSON, R. R.	7908170033	XPORTLIC
PETERSON, R. R.	7908170037	XPORTLIC
PETERSON, R. R.	7908170042	XPORTLIC
PETERSON, R. R.	7908300593	XPORTLIC
PETERSON, R. R.	7908020230	XPORTLIC
PETERSON, R. R.	7908010282	XPORTLIC
PETERSON, R. R.	7908010290	XPORTLIC
PETERSON, R. R.	7908020470	XPORTLIC
PETERSON, R. R.	7908010622	XPORTLIC
PETERSON, R. R.	7908010625	XPORTLIC
PETERSON, R. R.	7908020413	XPORTLIC
PETERSON, R. R.	7908070763	XPORTLIC
PETERSON, R. R.	7908030245	XPORTLIC
PETERSON, R. R.	7908150424	XPORTLIC
PETERSON, R. R.	7908150461	XPORTLIC
PETERSON, R. R.	7908160507	XPORTLIC
PETERSON, R. R.	7908170064	XPORTLIC
PETERSON, R. R.	7908150456	XPORTLIC
PETERSON, R. R.	7908150589	XPORTLIC
PETERSON, R. R.	7908120497	XPORTLIC
PETERSON, R. R.	7908160504	XPORTLIC
PETERSON, R. R.	7908100324	XPORTLIC
PETERSON, R. R.	7908100327	XPORTLIC
PETERSON, R. R.	7908100333	XPORTLIC
PETERSON, R. R.	7908100339	XPORTLIC
PETERSON, R. R.	7908080576	XPORTLIC
PETERSON, R. R.	7908100318	XPORTLIC
PETERSON, R. R.	7908100344	XPORTLIC
PETERSON, R. R.	7908150109	XPORTLIC
PETERSON, R. R.	7908150112*	XPORTLIC
PETERSON, R. R.	7908080567	XPORTLIC
PETERSON, R. R.	7908090069	XPORTLIC
PETERSON, R. R.	7908090082	XPORTLIC
PETERSON, R. R.	7908090101	XPORTLIC
PETERSON, R. R.	7908090118	XPORTLIC
PETERSON, R. R.	7908090154	XPORTLIC
PETERSON, R. R.	7908100348	XPORTLIC
PETERSON, R. R.	7908160308	XPORTLIC
PETERSON, R. R.	7908160312	XPORTLIC
PETERSON, R. R.	7908160317	XPORTLIC
PETERSON, R. R.	7908170134	XPORTLIC
PETERSON, R. R.	7908170141	XPORTLIC
PETERSON, R. R.	7908170145	XPORTLIC
PETERSON, R. R.	7908170249	XPORTLIC
PETERSON, R. R.	7908170263	XPORTLIC
PETERSON, R. R.	7908170269	XPORTLIC
PETERSON, R. R.	7908170287	XPORTLIC
PETERSON, R. R.	7908090663	XPORTLIC
PETERSON, R. R.	7908090657	XPORTLIC
PETERSON, R. R.	7908090666	XPORTLIC
PETERSON, R. R.	7908090668	XPORTLIC
PETERSON, R. R.	7908220262	XPORTLIC
PETERSON, R. R.	7908220264	XPORTLIC
PETERSON, R. R.	7908300371	XPORTLIC
PETERSON, R. R.	7908300375	XPORTLIC
PETERSON, R. R.	7908210097	XPORTLIC
PETERSON, R. R.	7908220417	XPORTLIC
PETERSON, R. R.	7908230071	XPORTLIC
PETERSON, R. R.	7908230075	XPORTLIC
PETERSON, R. R.	7908230083	XPORTLIC
PETERSON, R. R.	7908230087	XPORTLIC
PETERSON, R. R.	7908220427	XPORTLIC
PETERSON, R. R.	7908220510	XPORTLIC
PETERSON, R. R.	7908240212	XPORTLIC
PETERSON, R. R.	7908220518	XPORTLIC
PETERSON, R. R.	7908230065	XPORTLIC
PETERSON, R. R.	7908230069	XPORTLIC
PETRAREA, D. J.	7908140088	70-1143
PETRICK, N. A.	7908070526	50-482 G
PETRICK, N. A.	7908080332	50-482 G
PETRICK, N. A.	7908200006	50-482 G
PETZEL, D.	7908080210	50-341 G
PEVEAR, R. C.	7908090398*	50-443 H
PEVEAR, R. C.	7908090422*	50-443 H
PHILBRICK, S. S.	7908170237	ACRS
PHILBRICK, S. S.	7908170298	ACRS
PHILLIPS, D.	7908310364*	50-298 S
PHILLIPS, H. S.	7908100234*	50-341 G
PHILLIPS, H. S.	7908230052*	50-352 G
PHILLIP, G. A.	7908080290	50-483 A
PIANKI, F. J.	7908230240	70-1100
PICKFORD, A. E.	7908280550	TOPREP
PICKLE, J. J.	7908140506	50-466 U
PIERCE, S. M.	7908150414	FOIA
PILANT, J. M.	7908080451	50-298 G
PILANT, J. M.	7908170153	50-298 G
PILANT, J. M.	7908140057*	50-298 G
PILANT, J. M.	7908170161	50-298 G
PILANT, J. M.	7908100196	50-298 G
PILANT, J. M.	7908080396	50-298 P
PILANT, J. M.	7908160016	50-298 G
PILANT, J. M.	7908100200	50-298 G
PILANT, J. M.	7908160006	50-298 G
PILANT, J. M.	7908160034	50-298 G
PILANT, J. M.	7908140691	50-298 P
PILANT, J. M.	7908070509	50-298 J
PILANT, J. M.	7908080465	50-267 G
PILANT, J. M.	7908070625	50-298 P
PILANT, J. M.	7908140549	50-298 G
PILANT, J. M.	7908210508	50-298 P
PILANT, J. M.	7908210512	50-298 P
PISANESCHI, J.	7908090178	FOIA
PLANJE, T. J.	7908070540	50-123 G
PLANJE, T. J.	7908280497	50-123 G
PLASKON, R. E.	7908080484	50-516 G
PLASKON, R. E.	7908070784	50-516 G
PLASKON, R. E.	7908290732	50-516 G
PLASKON, R. E.	7908280579	50-516 F
PLATO, P.	7908090626	RES
PLATO, P.	7908070548	RES
PLATO, P.	7908300600	RES
PLATO, P.	7908300603*	RES
PLESZ, E. N.	7908140110*	71-255
PLESZ, E. N.	7908140103	71-255
PLUMLEE, K. E.	7908230565*	50-320 G
PLUMMER, A. M.	7908210193*	50-320 A
POCHAL, W. F.	7908150570	XPORTLIC
POCHAL, W. F.	7908150484	XPORTLIC
POCHAL, W. F.	7908310495	XPORTLIC
POHLER, P. E.	7908200150	FOIA
POINDEXTER, C. H.	7908010535	50-317 I
POIRER, M. R.	7908220092	50-445 M
POIRIER, M. R.	7908080525	50-445 M
POIRIER, M. R.	7908080535	50-445 M
POIRIER, M. R.	7908200097	50-445 M
POJE, G. V.	7908240659	NUREG
POLK, P. J.	7908020344	50-333 P
POLK, P. J.	7908210075	50-333 P
POLLOCK, R.	7908310300*	PR
POMPONIO, J. R.	7908210557	50-387 D
PORTER, W. L.	7908030190	70-2623
PORTER, W. L.	7908300352	50-488 G
POST, R. C.	7908010660*	TOPREP
POTAPOVS, U.	7908130225*	GA999
POTAPOVS, U.	7908130376*	GA999
POTAPOVS, U.	7908130213	GA999
POTAPOVS, U.	7908130366	GA999
POTAPOVS, U.	7908070188*	GA999
POTAPOVS, U.	7908100395*	GA999
POTAPOVS, U.	7908100114*	GA999
POTAPOVS, U.	7908220305*	GA999
POTAPOVS, U.	7908220667	GA999
POTAPOVS, U.	7908090232	GA999
POTAPOVS, U.	7908100252*	GA999
POTAPOVS, U.	7908220628	GA999
POTAPOVS, U.	7908090104*	GA999
POTAPOVS, U.	7908140071*	GA999
POTAPOVS, U.	7908140077*	GA999
POTAPOVS, U.	7908070177*	GA999
POTAPOVS, U.	7908070115	71-6698
POTAPOVS, U.	7908090209	GA999
POTAPOVS, U.	7908020178	GA999
POTAPOVS, U.	7908100104*	GA999
POTAPOVS, U.	7908130487*	GA999
POTAPOVS, K. D.	7908090183	GA999
POTAPOVS, U.	7908100506	GA999
POTAPOVS, U.	7908130634*	GA999
POTAPOVS, U.	7908100392*	GA999
POTAPOVS, U.	7908200040*	GA999
POTAPOVS, U.	7908200028*	GA999
POTAPOVS, U.	7908220292*	GA999
POTAPOVS, U.	7908220643*	GA999
POTAPOVS, U.	7908070165	GA999
POTAPOVS, U.	7908080010*	GA999
POTAPOVS, U.	7908130144*	GA999
POTAPOVS, U.	7908080013	GA999
POTAPOVS, U.	7908090087	GA999
POTAPOVS, U.	7908080001	GA999
POTAPOVS, U.	7908140064	GA999
POTAPOVS, U.	7908100091	GA999
POTAPOVS, U.	7908100209	GA999
POTAPOVS, U.	7908100388	GA999
POTAPOVS, U.	7908130615	GA999
POTAPOVS, U.	7908130133	GA999
POTAPOVS, U.	7908130482	GA999
POTAPOVS, U.	7908100577	71-6698
POTAPOVS, U.	7908080005	GA999
POTAPOVS, U.	7908200022	GA999
POTAPOVS, U.	7908200036	GA999
POTAPOVS, U.	7908080008	GA999
POTAPOVS, U.	7908220633	GA999
POTAPOVS, U.	7908220277	GA999
POTTER, J. P.	7908150609*	70-1151
POTTER, J. P.	7908170158*	70-27
POTTER, J. P.	7908130399*	50-332 G
POTTER, J. P.	7908290237*	70-824
POTTER, J. P.	7908210148*	70-143
POTTER, J. P.	7908270282*	70-143
POTTER, J. P.	7908300568*	70-143
POWER, D. F.	7908310589	FOIA
POWERS, H. A.	7908030586	40-8434
POWERS, H. A.	7908030593*	40-8434
PRASSINOS, P. G.	7908100394	NUREG
PRASSINOS, P. G.	7908060117	NUREG
PRATT, R.	7908210522	50-387 D
PRICE, J. C.	7908300784	FOIA
PRICE, D. S.	7908170147*	50-259 G
PRICE, E. R.	7908090513*	SECY
PROFFITT, W. L.	7908010718	71-6058
PROFFITT, W. L.	7908010431	50-281 J
PROFFITT, W. L.	7908090546	50-338 K
PROFFITT, W. L.	7908270462	50-338 P
PRYOR, C. W.	7908020516*	TOPREP
PRZEKOP, P. J.	7908100452*	50-245 S
PULS, M.	7908090544	PROJ
PURCELL, J. F.	7908230333	50-367 R
PUSCHEL, M. A.	7908030442	FOIA
PUSHEE, G. F.	7908070636	50-596 A
PYDYCH, J.	7908170085	FOIA
PYE, R.	7908030549	XPORTLIC
QUICK, D. R.	7908300100*	50-302 G
QUIGG, C.	7908080294*	50-295 G
QUINTENZ, T. E.	7908230355*	50-219 S
QUIRK, J. F.	7908090453*	TOPREP
QUIRK, J. F.	7908090277*	TOPREP

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RACINE, D.	7908230642	NUREG
RADER, R. M.	7908030556	27-39
RADER, R. M.	7908030579	27-39
RADER, R. M.	7908200269	50-445 M
RADNOR	7907190774	50-247 P
RAER, R. L.	7908100472	50-369 A
RAFFETY, S. J.	7908160453*	50-409 P
RAGONE, S.	7908030607*	50-339 A
RAINEY, J. L.	7908220192*	40-2061
RAMSEY, J.	7908150524	71-9006
RAMSEY, J.	7908200085	71-6387
RANDALL, J. D.	7908290421	50-128 P
RANDAZZA, J. B.	7908020418	50-309 H
RANDOLPH, J.	7907310621*	COMMISSION
RANSONE, J. W.	7908030566	40-1162
RASMUSSEN, K. H.	7908130571	40-8725
RATHJENS, G.	7908230306*	50-320 P
RATTA, A. D.	7908210158*	70-135
RATTA, A. D.	7908170093*	70-1143
RAUAN, R. G.	7908140416	NUREG
RAUSCH, J. K.	7908020544*	50-416 G
RAYMOND, J.	7908220170	FOIA
RAYMOND, J.	7908080745	FOIA
READ, J.	7908220071*	50-320 A
READ, J.	7908140176	NUREG
READER, D. W.	7908090160	50-321 G
REAL, C.	7908240482*	50-70 P
REAL, C.	7908300433*	50-18 P
REAVIS, J. A.	7908210532*	50-269 R
REBELOWSKI, T.	7908080178*	50-286 G
REBELOWSKI, T.	7908020100*	50-247 G
REDEMEYER, P. C.	7908220557	40-299
REED, C.	7908010309*	50-373 G
REED, C.	7908010631*	50-295 G
REED, C.	7908080424*	50-454 G
REED, C.	7908020237	50-373 G
REED, C.	7908020167	50-454 G
REED, C.	7908030037	50-373 G
REED, C.	7908030227*	50-454 G
REED, C.	7908280453	50-373 G
REED, C.	7908080523	50-10 G
REED, C.	7908150299*	50-237 G
REED, C.	7908080111	50-10 G
REED, C.	7908130161*	50-295 G
REED, C.	7908080703	50-237 G
REED, C.	7908080143	50-295 G
REED, C.	7908150349	50-10 G
REED, C.	7908150339	50-295 G
REED, C.	7908150439	50-373 G
REED, C.	7908130455	50-373 G
REED, C.	7908030167	50-295 F
REED, C.	7908020460	50-10 P
REED, C.	7908240513	50-10 G
REED, C.	7908200245	50-10 G
REED, C.	7908080530	50-237 G
REED, C.	7908100440	50-265 P
REED, C.	7908200338	50-373 F
REED, C.	7908210368	50-295 P
REED, C.	7908210469	50-295 P
REED, C.	7908200216	50-10 F
REED, C.	7908200223	50-456 F
REED, C.	7908200226	50-454 F
REED, C.	7908200250	50-295 F
REED, C.	7908200335	50-254 F
REED, C.	7908280010	50-295 P
REED, A. B.	7908300539*	50-267 S
REEDER, D. L.	7908010534	RES
REEVES, W. E.	7908300239*	50-346 P
REEVES, E.	7908170232	50-348 P
REEVES, E. A.	7908240206	50-409 P
REGAN, D. M.	7908020543	40-8721
REGAN, W. H.	7906110339	50-471 D
REGAN, W. H.	7908010615	50-424 A
REGAN, W. H.	7908060139	50-387 D
REGAN, W. H.	7908170155	50-313 P
REHM, T. A.	7908130372	COMMISSION
REHM, T. A.	7908010833	COMMISSION
REHM, T. A.	7908010698	COMMISSION
REHM, T. A.	7908100022	COMMISSION
REHM, T. A.	7908080558	COMMISSION
REHM, T. A.	7908150468	COMMISSION
REHM, T. A.	7908150729	50-320 H
REHM, T. A.	7908220250	COMMISSION
REHM, T. A.	7908310003	COMMISSION
REHM, T. A.	7908220336	COMMISSION
REHM, T. A.	7908280792	COMMISSION
REID, A. B.	7908220471	FOIA
REID, R. W.	7908010293	50-336 G
REID, R. W.	7908030542	50-192 P
REID, R. W.	7908030262	50-335 P
REID, R. W.	7908030588	50-313 P
REID, R. W.	7908070036	50-166 P
REID, R. W.	7908020187	50-157 P
REID, R. W.	7908070356	50-302 P
REID, R. W.	7908070365*	50-302 P
REID, R. W.	7908070403*	50-302 P
REID, R. W.	7908170089	50-269 P
REID, R. W.	7908090678	50-346 P
REID, R. W.	7908090680*	50-346 P
REID, R. W.	7908090686*	50-346 P
REID, R. W.	7908010257	50-70 P
REID, R. W.	7908130327	50-142 P
REID, R. W.	7908020323	50-70 P
REID, R. W.	7908080197	50-346 P
REID, R. W.	7908150153*	50-346 P
REID, R. W.	7908140219	50-264 F
REID, R. W.	7908140231*	50-264 F
REID, R. W.	7908080276	50-313 P
REID, R. W.	7908100123	50-313 P
REID, R. W.	7908130322	50-309 F
REID, R. W.	7908020593	50-27 P
REID, R. W.	7908020599*	50-27 P
REID, R. W.	7908030422	50-285 P
REID, R. W.	7908030428*	50-285 P
REID, R. W.	7908030438*	50-285 P
REID, R. W.	7908080213	50-346 P
REID, R. W.	7908030089	50-302 P
REID, R. W.	7908030094*	50-302 P
REID, R. W.	7908030098*	50-302 P
REID, R. W.	7908030101*	50-302 P
REID, R. W.	7908030304	50-302 P
REID, R. W.	7908030314*	50-302 P
REID, R. W.	7908290152*	50-302 G
REID, R. W.	7908370237	50-186 P
REID, R. W.	7908370252*	50-186 P
REID, R. W.	7908370270*	50-186 P
REID, R. W.	7908130649	50-317 P
REID, R. W.	7908140091	50-336 P
REID, R. W.	7908140114	50-335 P
REID, R. W.	7908140119	50-312 A
REID, R. W.	7908150743	50-219 P
REID, R. W.	7908220237*	50-346 P
REID, R. W.	7908080259	50-27 P
REID, R. W.	7908080367*	50-27 P
REID, R. W.	7908140242	50-70 P
REID, R. W.	7908080068	50-274 P
REID, R. W.	7908080091*	50-274 P
REID, R. W.	7908080111	50-269 P
REID, R. W.	7908080116*	50-269 P
REID, R. W.	7908080134*	50-269 P
REID, R. W.	7908100041	50-336 P
REID, R. W.	7908080266	50-269 P
REID, R. W.	7908080283*	50-269 P
REID, R. W.	7908080311*	50-269 P
REID, R. W.	7908140282	50-54 P
REID, R. W.	7908080331	50-269 P
REID, R. W.	7908080348*	50-269 P
REID, R. W.	7908080373*	50-269 P
REID, R. W.	7908140477	50-335 P
REID, R. W.	7908140481	50-313 P
REID, R. W.	7908150741	50-320 P
REID, R. W.	7908030502	50-309 P
REID, R. W.	7908170084	50-269 P
REID, R. W.	7908170267	50-228 F
REID, R. W.	7908170272*	50-228 F
REID, R. W.	7908150239	50-309 F
REID, R. W.	7908170081*	50-243 P
REID, R. W.	7908170223	50-243 P
REID, R. W.	7908170619	50-170 P
REID, R. W.	7908210052	50-269 P
REID, R. W.	7908210057*	50-269 P
REID, R. W.	7908210064*	50-269 P
REID, R. W.	7908010214	50-312 A
REID, T. W.	7908130003	50-269 P
REID, R. W.	7908170168	50-302 P
REID, R. W.	7908170170*	50-302 P
REID, R. W.	7908170177*	50-302 P
REID, R. W.	7908200055	50-302 P
REID, R. W.	7908200056	50-346 P
REID, R. W.	7908200094	50-352 P
REID, R. W.	7908200099	50-309 P
REID, R. W.	7908200102	50-336 P
REID, R. W.	7908200105	50-285 P
REID, R. W.	7908200107	50-312 P
REID, R. W.	7908200111	50-313 P
REID, R. W.	7908200136	50-335 P
REID, R. W.	7908220059	50-317 P
REID, R. W.	7908280578	50-317 P
REID, R. W.	7908220047	50-312 P
REID, R. W.	7908130033	50-335 G
REID, R. W.	7908130034	50-309 G
REID, R. W.	7908130036	50-285 G
REID, R. W.	7908220353	50-346 P
REID, R. W.	7908220360*	50-346 P
REID, R. W.	7908220367*	50-346 P
REID, R. W.	7908230110	50-302 P
REID, R. W.	7908230114*	50-302 P
REID, R. W.	7908230121*	50-302 P
REID, R. W.	7908220590	50-317 P
REID, R. W.	7908220602*	50-317 P
REID, R. W.	7908090635	50-317 P
REID, R. W.	7908090642*	50-317 P
REID, R. W.	7908090689*	50-317 P
REID, R. W.	7908170136	50-20 P
REID, R. W.	7908290665	50-346 P
REID, R. W.	7908290691*	50-346 P
REID, R. W.	7908130535	50-289 P
REID, R. W.	7908300618	50-269 P
REID, R. W.	7908270530	50-302 P
REID, R. W.	7908150256	50-313 P
REIDLINGER, B. A.	7908030223*	70-754
REINHARDT, P.	7908010618	REGGD
REIS, E.	7908230024	50-400 G
REIS, E. J.	7908030522	27-39
REIS, E. J.	7908200390*	FOIA
REITHER, L.	7908220586	50-247 P
REITLER, E. K.	7908140123	70-1151
REKEMEYER, P. C.	7908010161	PROJ
REKEMEYER, P. C.	7908310091	40-229
REKITO, W. A.	7908130390*	50-219 G
REMLEY, M. E.	7908090442	70-25
REMLEY, M. E.	7908020182	71-9033
REMLEY, M. E.	7908020221	71-6144
RENBERGER, D. L.	7908130340*	50-508 G
RENBERGER, D. L.	7908280387	50-397 G
RENBERGER, D. L.	7908070719	50-397 G
RENBERGER, D. L.	7908130431	50-460 G
RENBERGER, D. L.	7908130441	50-508 G
RENBERGER, D. L.	7908080326	REGGD
RENBERGER, D. L.	7908070714	50-508 G
RENBERGER, D. L.	7908070725	50-460 G
RENBERGER, D. L.	7908160015	50-508 G
RENBERGER, D. L.	7908010365	50-397 S
RENBERGER, D. L.	7908060364	50-397 K
RENBERGER, D. L.	7908080497	50-397 A
RENBERGER, D. L.	7908150560	50-397 S
RENBERGER, D. L.	7908200361	50-397 S
RENBERGER, D. L.	7908150682	50-397 S
RENBERGER, D. L.	7908140657	50-397 A
RENBERGER, D. L.	7908200362	50-397 A
RENENBERGER, D.	7908280387	50-397 G
RENNEKE, A.	7908140292*	SECY
RESNER, M. E.	7908290714	50-320 T
RESNER, M. E.	7908290729	50-320 T
RESNER, M. E.	7908300071	50-320 T
RESNER, M. E.	7908300067	50-320 T
RESNER, M. E.	7908290622	50-320 T
RESNER, M. E.	7908300260	50-320 T
RESNER, M. E.	7908300254	50-320 T
RESNER, M. E.	7908300160	50-320 T
RESNER, M. E.	7908290093	50-320 T
RESNER, M. E.	7908290635	50-320 T
RESNER, M. E.	7908290640	50-320 T
RESNER, M. E.	7908290692	50-320 T
RESNER, M. E.	7908280666	50-320 T
RESNER, M. E.	7908280775	50-320 T
RESNER, M. E.	7908300247	50-320 T
RESNER, M. E.	7908280733	50-320 T
RESNER, M. E.	7908280807	50-320 T
RESNER, M. E.	7908290099	50-320 T
RESNER, M. E.	7908290104	50-320 T
RESNER, M. E.	7908290170	50-320 T
RESNER, M. E.	7908300150	50-320 T
RESNER, M. E.	7908290140	50-320 T
RESNER, M. E.	7908290195	50-320 T
RESNER, M. E.	7908290215	50-320 T
RESNER, M. E.	7908290256	50-320 T
RESNER, M. E.	7908300274	50-320 T

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RESNER, M. E.	7908290149	50-320 T
RESNER, M. E.	7908290283	50-320 T
RESNER, M. E.	7908290316	50-320 T
RESNER, M. E.	7908290320	50-320 T
RESNER, M. E.	7908280813	50-320 T
RESNER, M. E.	7908280827	50-320 T
RESNER, M. E.	7908290202	50-320 T
RESNER, M. E.	7908290043	50-320 T
RESNER, M. E.	7908290766	50-320 T
RESTIVO, T.	7906020519	50-213 E
REYES, J. N.	7908150714	50-320 P
REYES, J. N.	7908150077	NUREG
REYNOLDS, W. B.	7908170289	50-282 Q
REYNOLDS, W. B.	7908060452	50-346 H
REYNOLDS, W. B.	7908070648	50-346 H
REYNOLDS, L. E.	7908010612	71-6601
REYNOLDS, L. E.	7908130049	71-6601
REYNOLDS, L. E.	7908200210	TOPREP
REYNOLDS, L. E.	7908200007	27-47
REYNOLDS, L. E.	7908200074	71-231
RHOADS, J. B.	7908170322*	COMMISSION
RHOADS, J. B.	7908170317*	COMMISSION
RHODE, G. K.	7908170080*	50-410 S
RHODE, G. K.	7908090192*	50-410 S
RHODE, G. K.	7908080497	50-410 Q
RHODE, G. K.	7908070040	50-410 Q
RHODE, G. K.	7908030024	50-410 Q
RHODE, G. K.	7908140660*	50-410 S
RHODE, G. K.	7908240225*	50-410 Q
RHODE, G. K.	7908210112*	50-410 S
RHODE, G. K.	7908170458	50-410 Q
RHODE, G. K.	7908230088	50-410 Q
RHODE, G. K.	7908010360	50-410 A
RHODE, G. K.	7908010362	50-220 P
RHODE, G. K.	7908010366	50-410 A
RHODE, G. K.	7908240583	50-220 Q
RHODE, G. K.	7908160450	50-410 A
RICE, S.	7908240482*	50-70 P
RICE, S.	7908300433*	50-18 P
RICHARDSON, H. D.	7908010297	71-10
RICHARDSON, H. D.	7908160150	71-10
RICHARDSON, H. D.	7908230560	71-9133
RICHARDSON, H. D.	7908230564*	71-9133
RICHINGS, H. J.	7908060462*	COMMISSION
RICHINGS, H. J.	7908060458*	COMMISSION
RICKFORD, A. E.	7908100238	TOPREP
RICKOVER, H. G.	7908210149	50-320 P
RIDDLE, D. H.	7908100325	71-9039
RIDEN, M. D.	7908020572*	50-10 Q
RIDGWAY, K. R.	7908280214*	50-155 Q
RIEDLINGER, B. A.	7908210044*	QA999
RILEY, J. L.	7908310535	70-2623
RILEY, R. W.	7908230540*	COMMISSION
RINACA, J. M.	7908020570*	50-338 Q
RISCHLING, J. L.	7908290439*	50-315 S
RISCHLING, J. L.	7908140637*	50-316 S
RISCHLING, J. L.	7908210521*	50-316 S
RISTAU, K. A.	7908090075*	50-331 S
RISTAGNO, C. V.	7908170130*	XPORTLIC
RISTAGNO, C. V.	7908170124	XPORTLIC
RITSHER, J. A.	7908100441	50-443 I
RITSHER, J. A.	7908140530	50-443 A
RITSHER, J. A.	7908210510	50-443 I
RITSHER, J. A.	7908210272	50-443 I
RITSHER, J. A.	7908280615	50-443 I
RITTS, F. H.	7908130130	50-445 M
RIX, S.	7908210159	50-574 A
RIZZO, P. G.	7908280682*	50-317 S
RIZZO, P. G.	7908080457*	50-318 S
RIZZO, P. G.	7908080512*	50-317 S
RIZZO, P. G.	7908220389*	50-317 S
RIZZO, P. G.	7908230386*	50-317 S
RIZZO, P. G.	7908230513*	50-318 S
RIZZO, P. G.	7908270484*	50-317 S
RIZZO, P. G.	7908270485*	50-318 S
RIZZO, P. G.	7908280626*	50-317 S
ROACH, K.	7908310478	50-286 P
ROACH, K.	7908310478	50-3 P
ROBERTSON, J.	7908170637	50-466 Q
ROBERTS, E. W.	7908030318*	50-302 P
ROBERTS, M. J.	7908140592	RES
ROBERTSON, J. S. C.	7908240164*	70-143
ROBERTS, J. P.	7908090520*	PROJ
ROBERTS, J. P.	7908160085	PROJ
ROBERTS, J. P.	7908170333	PROJ
ROBERTS, I. C.	7908220096*	FOIA
ROBINSON, J. H.	7908200050	50-466 Q
ROBINSON, D. E.	7908140725	50-387 D
ROBINSON, R. C.	7907300139	REVIEW GRP
RODRIGUEZ, R. J.	7908140473	50-312 R
ROE, L. E.	7908160113	50-346 P
ROE, L. E.	7908020442	50-346 P
ROE, L. E.	7908010361	50-346 P
ROE, L. E.	7908070595	50-346 P
ROE, L. E.	7908100453	50-346 P
ROE, L. E.	7908140478	50-346 P
ROE, L. E.	7908100195	50-346 H
ROE, L. E.	7908140527	50-346 P
ROE, L. E.	7908210526	50-346 F
ROE, L. E.	7908170412	50-346 F
ROE, L. E.	7908220432	50-346 P
ROGERS, M. L.	7908230644	PR
ROGERS, W. H.	7908102764	50-516 Q
ROGERS, W. H.	7908080239*	50-322 A
ROGERS, A. E.	7908150675*	TOPREP
ROGERS, A. E.	7908270385*	TOPREP
ROGERS, W. L.	7908090430	40-8725
ROGERS, W. L.	7908170252	40-8725
ROGERS, W. H.	7908100416*	50-366 S
ROGERS, W. H.	7908200323*	50-366 S
ROGERS, W. H.	7908280690*	50-366 S
ROGERS, G. M.	7908010447	RES
ROGOW, B. S.	7908140488*	50-250 U
ROHRER, D.	7908300358	WASTE MGT
ROISMAN, A. Z.	7908230298*	50-320 P
ROISMAN, A. Z.	7908200387*	FOIA
ROISMAN, A. Z.	7908200076	70-2623
ROISMAN, A. Z.	7908030413	50-269 P
ROLEY, P.	7908240180	50-574 Q
ROLLINS, J. D.	7908100567	71-18
ROLLINS, J. D.	7908100590*	71-18
ROLLINS, J. D.	7908070788	71-18
ROLLINS, J. D.	7908200088	71-6698
ROMERO, R. L.	7908200026*	QA999
ROMERO, N. C.	7908100387	NUREG
ROOD, H.	7908020041	50-275 A
ROOD, H.	7908030117	50-361 A
ROOD, H.	7908070742	50-361 A
ROOD, H.	7908160198	50-361 A
ROONEY, V. L.	7908160265	50-298 F
ROONEY, V. L.	7908230085	50-298 F
ROONEY, V. L.	7908170597*	50-321 P
ROONEY, V. L.	7908220593*	50-298 P
ROOT, L. D.	7908090506	50-331 Q
ROOT, L. D.	7908100130	50-331 Q
ROOT, L. D.	7908100164	50-331 Q
ROOT, L. D.	7908140150	50-331 Q
ROOT, L. D.	7908140160	50-331 Q
ROOT, L. D.	7908150245	50-331 Q
ROOT, L. D.	7908030505	50-331 F
ROOT, L. D.	7908020438	50-331 H
ROOT, L. D.	7908070557	50-331 P
ROOT, L. D.	7908230627	50-331 Q
ROOT, L. D.	7908210473	50-331 P
ROOT, L. D.	7908270443	50-331 P
ROOT, L. D.	7908210509	50-331 F
ROOT, L. D.	7908270426	50-331 P
ROSALIE, E.	7908300758	50-344 Q
ROSENFIELD, A. R.	7908020239	RES
ROSOLIE, E.	7908300761*	50-344 Q
ROSS, D. M.	7908280832	71-5971
ROSS, D. A.	7908280111*	50-219 Q
ROSS, D. A.	7908280106*	50-219 Q
ROSS, D. A.	7908070643	50-219 Q
ROSS, D. A.	7908070845	50-219 Q
ROSS, D. A.	7908070584	50-219 S
ROSS, D. A.	7908070589*	50-219 S
ROSS, D. A.	7908060247	50-219 R
ROSS, D. A.	7908060255*	50-219 R
ROSS, D. A.	7908060229*	50-219 S
ROSS, D. A.	7908240539	50-219 P
ROSS, D. A.	7908270399	50-219 P
ROSS, D. A.	7908280689	50-219 S
ROSS, D. A.	7908280701*	50-219 S
ROSS, D. A.	7908210340	50-219 P
ROSS, W. J.	7908020163	50-272 Q
ROSS, W. J.	7908220266	50-272 P
ROSS, W. J.	7908160039	50-272 S
ROSS, W. J.	7908230689	50-286 P
ROSS, D. F.	7908220468*	50-320 P
ROSS, D. F.	7908070809	50-312 A
ROSS, D. F.	7908230056	50-269 P
ROSS, D. F.	7908150720	50-269 P
ROSS, D. F.	7908160157	50-313 P
ROSSb#CH, L. W.	7908130236	40-2259
ROTH, N.	7908150409*	50-309 P
ROTH, J.	7908090449*	AGREEMENT
ROTHE, P. H.	7908010240	RES
ROTHE, P. H.	7908010352	RES
ROTHE, R. E.	7908060423	NUREG
ROTHFLEISCH, J.	7908150539	40-8721
ROTHFLEISCH, J.	7908290097	40-8698
ROUSE, L. C.	7908090488*	40-3453
ROUSE, L. C.	7908230147*	50-358 Q
ROUSE, L. C.	7908230152*	50-358 Q
ROUSE, L. C.	7908130599	70-1257
ROUSE, L. C.	7908170310	70-364
ROUSE, L. C.	7908150571	70-364
ROUSE, L. C.	7908080026	70-1143
ROUSE, L. C.	7908030508	50-201 P
ROUSE, L. C.	7908130219	70-8
ROUSE, L. C.	7908150388	70-8
ROUSE, L. C.	7908150648	70-1257
ROUSE, L. C.	7908220079	70-25
ROUSE, L. C.	7908030497	70-1257
ROWDEN, M. A.	7908220154*	FOIA
ROWE, B.	7908140399	71-24
ROY, D.	7908080019	70-143
RUBENSTEIN, L.	7908140089	50-498 A
RUBENSTEIN, L. S.	7908280571	50-322 A
RUBENSTEIN, L. S.	7908100550	50-466 E
RUBENSTEIN, L. S.	7908140117	50-367 A
RUBENSTEIN, L. S.	7908160333	50-327 A
RUBENSTEIN, L. S.	7908140495	50-424 A
RUBENSTEIN, L. S.	7908170612	50-443 I
RUBENSTEIN, L. S.	7908150059	50-367 D
RUBENSTEIN, L. S.	7908080167	50-546 A
RUBENSTEIN, L. S.	7908080270	50-322 U
RUBENSTEIN, L. S.	7908130554	50-454 A
RUBENSTEIN, L. S.	7908130557	50-329 A
RUBENSTEIN, L. S.	7908130579	50-413 A
RUBENSTEIN, L. S.	7908130561	50-546 A
RUBENSTEIN, L. S.	7908130563	50-327 A
RUBENSTEIN, L. S.	7908170222	50-327 A
RUBENSTEIN, L. S.	7908210040	50-390 A
RUBINSTEIN, D.	7908220089*	FOIA
RUBY, L.	7908130353	PRM
RUBY, R.	7908140811	FOIA
RUDLEY, W. W.	7908240286*	71-67
RUDOLPH, J. E.	7908310451	50-320 H
RUDOLPH, J. P.	7908230390*	50-346 S
RUDOLPH, J. P.	7908280721*	50-346 S
RUFF, A. B.	7908280138*	50-390 Q
RUFF, A. B.	7908240214*	50-327 Q
RUHLMAN, W. A.	7908010650*	50-302 Q
RUHLMAN, W. A.	7908090025*	50-269 Q
RUHLMAN, W. A.	7908070155*	50-261 Q
RUHLMAN, W. A.	7908150407*	50-321 Q
RUHLMAN, W. A.	7908240124*	50-335 Q
RUHLMAN, W. A.	7908170573*	50-321 Q
RUHLMAN, W. A.	7908230683*	50-348 Q
RUHLMAN, W. A.	7908240196*	50-280 Q
RUHLMAN, W. A.	7908240353*	50-338 Q
RUHLMAN, W. A.	7908270209*	50-259 Q
RUITER, G. H.	7908010572*	50-305 S
RUITER, G. H.	7908080403*	50-305 S
RUSHTON, J.	7908080207*	50-599 Q
RUSHMORE, J. W.	7908030305	50-220 I
RUSSELL, L. B.	7908100486	50-317 S
RUSSELL, L. B.	7908100500	50-317 S
RUSSELL, L. B.	7908080450	50-318 S
RUSSELL, L. B.	7908080509	50-317 S
RUSSELL, L. B.	7908200328	50-317 S
RUSSELL, L. B.	7908220385	50-317 S
RUSSELL, L. B.	7908230383	50-317 S
RUSSELL, L. B.	7908230518	50-317 S
RUSSELL, L. B.	7908230361	50-317 S
RUSSELL, L. B.	7908230500	50-318 S
RUSSELL, L. B.	7908270476	50-318 S
RUSSELL, L. B.	7908270478	50-317 S
RUSSELL, L. B.	7908280620	50-317 S
RUSSELL, L. B.	7908280628	50-317 S
RUSSELL, L. B.	7908280675	50-317 S
RUTBERG, J.	7908300323	PROJ
RYALL, R. K.	7908310412*	50-335 P
RYAN, D. J.	7908220349	50-466 Q
RYAN, R. Q.	7908280055*	FOIA
RYAN, R. Q.	7908010661*	10CFR

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RYAN, R. G.	7908200109	50-518 P
RYAN, R. G.	7908010271	50-516 Q
RYAN, R. G.	7908070052	AGREEMENT
RYAN, R. G.	7908130504	NUREG
RYAN, R. G.	7908130506	NUREG
RYAN, R. G.	7908130509	NUREG
RYAN, R. G.	7908130510	NUREG
RYAN, R. G.	7908130511	NUREG
RYAN, R. G.	7908130512	NUREG
RYAN, R. G.	7908130514	NUREG
RYAN, R. G.	7908160368	AGREEMENT
SABOL, A. R.	7908200277*	50-387 Q
SACKETT, K. E.	7908070748	NUREG
SADOFSKI, J. J.	7908080597*	50-390 A
SAGAN, L. A.	7908150471*	ORG
SAKE, R. F.	7908170380	50-297 R
SALTZMAN, J.	7908010541*	50-317 I
SALTZMAN, J.	7908170261	50-346 M
SALTZMAN, J.	7908210073	50-346 M
SALTZMAN, J.	7908210078*	50-346 M
SANDERS, B. S.	7908150491*	ORG
SANDERS, W. F.	7908200668*	50-245 Q
SANDERS, W. F.	7908280182*	50-281 Q
SANDOZ, S. A.	7908240437*	TOPREP
SANDS, F.	7908150017	50-361 Q
SANTASUCCI, A.	7908150157*	50-443 H
SANTASUCCI, A.	7908210077*	50-443 Q
SANTORO, M. P.	[illegible]50522	71-264
SATTERFIELD, R. M.	[illegible]0037	50-413 A
SAXE, R. F.	[illegible]08210181*	50-320 H
SAXE, R. F.	[illegible]08210174*	50-320 H
SCARANO, R. A.	[illegible]9030094	40-8693
SCARANO, R. A.	[illegible]130043	40-3453
SCARANO, R. A.	[illegible]210031	40-8722
SCARANO, R. A.	7908210034*	40-8722
SCARANO, R. A.	7908010310	PROJ
SCARANO, R. A.	7908020134*	40-8721
SCARANO, R. A.	7908020128	40-8721
SCARANO, R. A.	7908030590	40-6659
SCARANO, R. A.	7908030517	40-8693
SCARANO, R. A.	7908160109*	40-8714
SCARANO, R. A.	7908160115*	40-8714
SCARANO, R. A.	7908200415	40-8681
SCARANO, R. A.	7908130037	40-4492
SCARANO, R. A.	7908020007	40-2259
SCARANO, R. A.	7908290546	40-4492
SCARANO, R. A.	7908170185*	40-8698
SCHACK, S.	7908220374	50-361 Q
SCHAEFER, J.	7908150107*	50-155 H
SCHAEFER, J.	7908150139*	50-155 H
SCHAEFER, J.	7908150195*	50-155 H
SCHAFFER, S. G.	7908080491	50-412 Q
SCHEFFEY, T. B.	7908310300	PR
SCHEFFER, J. C.	7908010356*	50-131 Q
SCHEFFER, J. C.	7908010009*	50-409 Q
SCHENDEL, K. R.	7908140027	40-8502
SCHENDEL, K. R.	7908200071	40-8502
SCHENDEL, K. R.	7908240623*	40-8502
SCHENCER, A.	7908060538	50-286 P
SCHERER, A. E.	7908070324*	50-220 Q
SCHERER, A. E.	7908070687*	50-363 Q
SCHERER, A. E.	7908280444*	50-341 Q
SCHERER, A. E.	7908280849*	50-333 Q
SCHERER, A. E.	7908240444	TOPREP
SCHERER, A. E.	7908080389*	50-315 Q
SCHERER, A. E.	7908170428	50-255 P
SCHERER, A. E.	7908150603	50-470 K
SCHERER, A. E.	7908210538	TOPREP
SCHERER, A. E.	7908290697	TOPREP
SCHERER, A. E.	7908290463	TOPREP
SCHIMMEL, R. L.	7908170516	70-572
SCHLAPPER, G. A.	7908310512*	50-186 P
SCHMACHER, M. C.	7908150346*	50-315 Q
SCHMIDT, R. W.	7908020392	50-596 Q
SCHMIDT, A. D.	7908070510	50-251 S
SCHMIDT, A. D.	7908070499	50-335 S
SCHMIDT, A. D.	7908140616	50-250 S
SCHMIDT, A. D.	7908140713	50-335 S
SCHMIDT, A. D.	7908200279	50-250 S
SCHMIDT, A. D.	7908200284	50-251 S
SCHMIDT, A. D.	7908160463	50-251 S
SCHMIDT, A. D.	7908200344	50-335 S
SCHMIDT, A. D.	7908300675	50-250 S
SCHMIDT, A. D.	7908290424	50-250 S
SCHMIDT, A. D.	7908300708	50-335 S
SCHMIDT, H. C.	7908220337	50-445 K
SCHNAUTZ, C. E.	7908020560	XPORTLIC
SCHNAUTZ, C. E.	7908220253	XPORTLIC
SCHNEIDERS, G.	7908080670*	COMMISSION
SCHNEIDER, R. R.	7908070311	50-220 Q
SCHNEIDER, R. R.	7908210175	50-213 Q
SCHNEIDER, R. R.	7908010449	50-220 K
SCHNEIDER, R. R.	7908150630	50-220 R
SCHNEIDER, F. W.	7908020057*	50-272 Q
SCHNEIDER, F. W.	7908010149	50-272 Q
SCHNEIDER, F. W.	7908080277	50-272 Q
SCHNEIDER, F. W.	7908070785	50-272 Q
SCHNEIDER, F. W.	7908170471	50-272 Q
SCHNEIDER, F. W.	7908220634	50-272 Q
SCHNEIDER, F. W.	7908220631	50-272 Q
SCHNEIDER, F. W.	7908140738*	50-272 P
SCHNEIDER, F. W.	7908310395	50-272 Q
SCHOPPMAN, M. A.	7908070517*	50-251 S
SCHOPPMAN, M. A.	7908070505*	50-335 S
SCHOPPMAN, M. A.	7908140625*	50-250 S
SCHOPPMAN, M. A.	7908140726*	50-335 S
SCHOPPMAN, M. A.	7908200282*	50-250 S
SCHOPPMAN, M. A.	7908200286*	50-251 S
SCHOPPMAN, M. A.	7908160468*	50-251 S
SCHOPPMAN, M. A.	7908200347*	50-335 S
SCHOPPMAN, M. A.	7908300681*	50-250 S
SCHOPPMAN, M. A.	7908290429*	50-250 S
SCHOPPMAN, M. A.	7908300711*	50-335 S
SCHREINER, W.	7908080579*	50-390 A
SCHREIBER, D. L.	7908140682*	50-522 Q
SCHREIBER, D. L.	7908220075*	FOIA
SCHROEDER, F.	7908150726	50-320 H
SCHROEDER, F.	7908150756	50-320 P
SCHROEDER, F.	7908220495*	50-320 P
SCHUESSLER, W. J.	7908140169	50-466 Q
SCHULTZ, W. B.	7908310300*	PR
SCHULTZ, W. R.	7908310296	PR
SCHUMACHER, D.	7908240437*	TOPREP
SCHUTT, P. F.	7908100590*	71-18
SCHWAB, J. C.	7908020561*	50-599 Q
SCHWARZ, H. A.	7908230008	50-320 P
SCHWARZ, C. E.	7908010545	RES
SCHWEICKART, R. L.	7908090505*	COMMISSION
SCHWENCER, A.	7908160408	50-250 P
SCHWENDIMAN, L.	7908130212*	70-754
SCHWEITZER, D. G.	7908020372	RES
SCHWEIBINZ, E. R.	7908080737*	50-546 Q
SCHWEIBINZ, E. R.	7908150130*	50-483 Q
SCHWEIBINZ, E. R.	7908150176*	50-484 Q
SCHWENCER, A.	7908020155	50-348 P
SCHWENCER, A.	7908140734	50-272 P
SCHWENCER, A.	7908080305	50-334 Q
SCHWENCER, A.	7908090266	50-250 P
SCHWENCER, A.	7908090271*	50-250 P
SCHWENCER, A.	7908100579	50-261 P
SCHWENCER, A.	7908030045	50-315 P
SCHWENCER, A.	7908030048*	50-315 P
SCHWENCER, A.	7908030056*	50-315 P
SCHWENCER, A.	7908020281	50-272 Q
SCHWENCER, A.	7908130640	50-334 P
SCHWENCER, A.	7908270508	50-295 P
SCHWENCER, A.	7908200218	50-247 P
SCHWENCER, A.	7908200225*	50-247 P
SCHWENCER, A.	7908080640	50-344 P
SCHWENCER, A.	7908100589	50-348 P
SCHWENCER, A.	7908170[illegible]2	50-272 P
SCHWENCER, A.	7908240044	50-272 P
SCHWENCER, A.	7908080186	50-247 P
SCHWENCER, A.	7908080191*	50-247 P
SCHWENCER, A.	7908080644*	50-247 P
SCHWENCER, A.	7908080614	50-305 P
SCHWENCER, A.	7908100586	50-334 P
SCHWENCER, A.	7908130093	50-315 P
SCHWENCER, A.	7908220229	50-286 P
SCHWENCER, A.	7908220235*	50-286 P
SCHWENCER, A.	7908220239*	50-286 P
SCHWENCER, A.	7908220302	50-3 P
SCHWENCER, A.	7908220309*	50-3 P
SCHWENCER, A.	7908220314*	50-3 P
SCHWENCER, A.	7908[illegible]0027	50-315 P
SCHWENCER, A.	7908210066	50-334 P
SCHWENCER, A.	7908210071*	50-334 P
SCHWENCER, A.	7908070724	50-281 P
SCHWENCER, A.	7908160082	50-344 P
SCHWENCER, A.	7908060007	50-315 P
SCHWENCER, A.	7908150737	50-272 P
SCHWENCER, A.	7908140463	50-280 P
[illegible]R, A.	7908200016	50-280 P
[illegible]R, A.	7908200019*	50-280 P
SCHWENCER, A.	7908130044	50-247 P
SCHWENCER, A.	7908220288	50-286 P
SCHWENCER, A.	7908300094	50-280 P
SCHWENCER, A.	7908300108*	50-280 P
SCHWENCER, A.	7908290646	50-282 P
SCHWENCER, A.	7908290655	50-272 P
SCHWENCER, A.	7908290531	50-348 P
SCHWENCER, A.	7908[illegible]0536*	50-348 P
SCHWENCER, A.	7908220542*	50-348 P
SCHWENCER, A.	7908290280	50-315 P
SCHWENCER, A.	7908290290*	50-315 P
SCHWENCER, A.	7908290315*	50-315 P
SCHWENCER, A.	7908290642	50-334 P
SCHWENCER, A.	7908130569	50-295 P
SCHWENCER, A.	7908130570	50-247 P
SCHWENCER, A.	7908130572	50-261 P
SCHWENCER, A.	7908130574	50-334 P
SCHWENCER, A.	7908130576	50-250 P
SCHWENCER, A.	7908130577	50-315 P
SCHWENCER, A.	7908130579	50-286 P
SCHWENCER, A.	7908130581	50-344 P
SCHWENCER, A.	7908130582	50-272 P
SCHWENCER, A.	7908130583	50-280 P
SCHWENCER, A.	7908130584	50-266 P
SCHWENCER, A.	7908130587	50-305 P
SCHWENCER, A.	7908220488	50-280 P
SCHWENCER, A.	7908240645	50-261 P
SCHWENCER, A.	7908300589	50-315 P
SCHWENCER, A.	7908290260	50-282 P
SCHWENCER, A.	7908290269*	50-282 P
SCHWENCER, A.	7908290303*	50-282 P
SCHWENCER, A.	7908160118	50-282 P
SCHWENCER, A.	7908160129*	50-282 P
SCHWENCER, A.	7908160143*	50-282 P
SCHWENCER, A.	7908210329	50-266 Q
SCHWENCER, A.	7908300791	50-295 P
SCHWENCER, A.	7908300789	50-266 Q
SCHWENCER, A.	7908210037	50-315 P
SCHWENCER, A.	7908020161*	50-348 P
SCHWENCER, A.	7908020546	50-295 P
SCHWENCER, A.	7908030614	50-272 P
SCHWENCER, A.	7908020177	50-247 P
SCHWENCER, A.	7908020168	50-344 P
SCHWENCER, A.	7908010270	50-266 P
SCHWENCER, A.	7908160561	50-266 P
SCHWENCER, A.	7908030554	50-315 Q
SCHWENCER, A.	7908060542	50-266 P
SCHWENCER, A.	7908020285	50-266 P
SCHWENCER, A.	7908030356	50-25[illegible] P
SCHWEN[illegible]R, A.	7908160286	50-305 P
SCHWEN[illegible]ER, A.	7908210169	50-250 P
SCINTO, J. F.	7908280156*	FOIA
SCINTO, J. F.	7908140052*	50-275 Q
SCOPELITIS, C. P.	7908060533*	50-336 S
SCOTT, B.	7908200167	FOIA
SCOTT, G. R.	7908150281	50-546 Q
SCOTT, W. J.	7908030561	50-367 Q
SCOTT, W. J.	7908030528	27-39
SCOTT, R. L.	7908230679	NUREG
SEALE, R. L.	7908170306	ACRS
SEELINGER, [illegible]	7908070079	50-289 S
SEELINGER, J. L.	7908130472	50-289 S
SEIDLE, W. C.	7908010036	50-458 Q
SEIDLE, W. C.	7908100210	50-382 Q
SEIDLE, W. C.	7908100227	50-556 Q
SEIDLE, W. C.	7908010051	50-482 Q
SEIDLE, W. C.	7908070125	50-445 Q
SEIDLE, W. C.	7908030004	50-458 Q
SEIDLE, W. C.	7908270118	50-445 Q
SEIDLE, W. C.	7908230665	50-445 Q
SEIDLE, W. C.	7908310115	50-445 Q
SEIDLE, W. C.	7908100544	[illegible] Q
SEIDLE, W. C.	7908010708	50-458 S
SEID[illegible], W. C.	7908010714	50-498 S
SEIDLE, W. C.	7908010715	50-482 S
SEIDLE, W. C.	7908010717	50-382 S
SEIDLE, W. C.	7908010719	50-445 S
SEISS, C. P.	7908220126	5[illegible]-320 T
SEKULER, S. N.	7907110499	50-237 Q
SEKULER, S. N.	7908030528	27-39
SEKULER, S. N.	7908030536	27-3[illegible]
SELLS, D. E.	7908150731	50-[illegible]0 H
SELL[illegible]	7908080562*	50-387 D
SELLS, D. E.	7908080560	50-387 D

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
SELLS, D. E.	7908080601	50-522	D
SELLS, D. E.	7908200119	50-400	A
SELLS, D. E.	7908030102	50-549	H
SELLS, D. E.	7908150267*	50-556	A
SELLS, D. E.	7908230403	50-59[illegible]	A
SELLS, D. E.	7908240078	50-553	A
SELLS, D. E.	7908240086*	50-553	A
SEME, J. A.	7908090092*	QA999	
SENERER, A. E.	7908090549	TOPREP	
SERATH, E. D.	7908130115	50-445	M
SERPAN, C. Z.	7908230078	GEN TEC	IB
SEWELL, R. B.	7908010655	40-8698	
SEWELL, R. B.	7908140368	40-8698	
SEWELL, R. B.	7908010659	40-8698	
SEWELL, R. B.	7908310068	40-8674	
SEWELL, R. B.	7908310081*	40-8674	
SEWELL, R. B.	7908300710	40-8674	
SEWELL, R. B.	7908140368	40-8698	
SEYFRIT, K. V.	7908020307	50-317	G
SEYFRIT, K. V.	7908020313	50-334	G
SEYFRIT, K. V.	7908020288	QA999	
SEYFRIT, K. V.	7908020259	50-498	A
SEYFRIT, K. V.	7908010003	50-285	G
SEYFRIT, K. V.	7908010005	50-267	G
SEYFRIT, K. V.	7908010006	50-262	G
SEYFRIT, K. V.	7908010010	50-284	G
SEYFRIT, K. V.	7908010012	50-188	G
SEYFRIT, K. V.	7908010013	50-59	G
SEYFRIT, K. V.	7908010017	50-148	G
SEYFRIT, K. V.	7908010018	50-252	G
SEYFRIT, K. V.	7908010019	50-112	G
SEYFRIT, K. V.	7908010020	50-192	G
SEYFRIT, K. V.	7908010021	50-72	G
SEYFRIT, K. V.	7908270292	50-482	A
SEYFRIT, K. V.	7908010316	50-458	G
SEYFRIT, K. V.	7908010321	50-498	G
SEYFRIT, K. V.	7908010323	50-482	G
SEYFRIT, K. V.	7908010325	50-382	G
SEYFRIT, K. V.	7908010328	50-445	G
SEYFRIT, K. V.	7908020393	50-313	G
SEYFRIT, K. V.	7908020394	50-458	G
SEYFRIT, K. V.	7908020395	50-498	G
SEYFRIT, K. V.	7908020396	50-482	G
SEYFRIT, K. V.	7908020397	50-382	G
SEYFRIT, K. V.	7908020398	50-298	G
SEYFRIT, K. V.	7908020399	50-285	G
SEYFRIT, K. V.	7908020400	50-267	G
SEYFRIT, K. V.	7908020402	50-445	G
SEYFRIT, K. V.	7908070355	50-313	P
SEYFRIT, K. V.	7908070358	50-285	P
SEYFRIT, K. V.	7908070359	50-267	P
SEYFRIT, K. V.	7908060019	50-313	G
SEYFRIT, K. V.	7908060021	50-285	G
SEYFRIT, K. V.	7908060038	50-313	G
SEYFRIT, K. V.	7908060041	50-298	G
SEYFRIT, K. V.	7908060043	50-285	G
SEYFRIT, K. V.	7908060045	50-267	G
SEYFRIT, K. V.	7908060123	50-313	G
SEYFRIT, K. V.	7908060127	50-298	G
SEYFRIT, K. V.	7908060128	50-285	G
SEYFRIT, K. V.	7908060131	50-267	G
SEYFRIT, K. V.	7908160121	50-482	G
SEYFRIT, K. V.	7908160122	50-458	G
SEYFRIT, K. V.	7908160125	50-498	G
SEYFRIT, K. V.	7908160128	50-382	G
SEYFRIT, K. V.	7908160131	50-445	G
SEYFRIT, K. V.	7908160045	50-274	G
SEYFRIT, K. V.	7908160048	50-131	G
SEYFRIT, K. V.	7908160049	50-313	G
SEYFRIT, K. V.	7908160053	50-285	G
SEYFRIT, K. V.	7908160054	50-267	G
SEYFRIT, K. V.	7908160059	50-262	G
SEYFRIT, K. V.	7908160060	50-284	G
SEYFRIT, K. V.	7908160062	50-188	G
SEYFRIT, K. V.	7908160087	50-59	G
SEYFRIT, K. V.	7908160091	50-148	G
SEYFRIT, K. V.	7908160093	50-252	G
SEYFRIT, K. V.	7908160094	50-112	G
SEYFRIT, K. V.	7908160097	50-192	G
SEYFRIT, K. V.	7908160098	50-72	G
SEYFRIT, K. V.	7908290142	50-458	G
SEYFRIT, K. V.	7908290151	50-498	G
SEYFRIT, K. V.	7908290154	50-482	G
SEYFRIT, K. V.	7908290157	50-382	G
SEYFRIT, K. V.	7908290162	50-[illegible]45	G
SEYFRIT, K. V.	7908290693	50-4[illegible]	G
SEYFRIT, K. V.	7908290698	50-498	G
SEYFRIT, K. V.	7908290700	50-482	G
SEYFRIT, K. V.	7908290701	50-382	G
SEYFRIT, K. V.	7908290703	50-445	G
SEYFRIT, K. V.	7908060465	50-498	G
SHACKLETON, D. C.	7906210429	50-320	P
SHACKLETON, D. C.	7906210440	50-320	P
SHACKLETON, D. C.	7908300082	50-320	T
SHACKLETON, D. C.	7908290557	50-320	T
SHACKLETON, D. C.	7908290587	50-320	T
SHACKLETON, D. C.	7908290618	50-320	T
SHACKLETON, D. C.	7908290645	50-320	T
SHACKLETON, D. C.	7908290724	50-320	T
SHACKLETON, D. C.	7908300174	50-320	T
SHACKLETON, D. C.	7908290465	50-320	T
SHACKLETON, D. C.	7908300061	50-320	T
SHACKLETON, D. C.	7908290574	50-320	T
SHACKLETON, D. C.	7908290615	50-320	T
SHACKLETON, D. C.	7908290622	50-320	T
SHACKLETON, D. C.	7908280720	50-320	T
SHACKLETON, D. C.	7908290550	50-320	T
SHACKLETON, D. C.	7908290733	50-320	T
SHACKLETON, D. C.	7908300216	50-320	T
SHACKLETON, D. C.	7908280705	50-320	T
SHACKLETON, D. C.	7908280707	50-320	T
SHACKLETON, D. C.	7908280715	50-320	T
SHACKLETON, D. C.	7908280727	50-320	T
SHACKLETON, D. C.	7908290453	50-320	T
SHACKLETON, D. C.	7908290593	50-320	T
SHACKLETON, D. C.	7908290635	50-320	T
SHACKLETON, D. C.	7908280802	50-320	T
SHACKLETON, D. C.	7908290503	50-320	T
SHACKLETON, D. C.	7908290515	50-320	T
SHACKLETON, D. C.	7908290519	50-320	T
SHACKLETON, D. C.	7908290610	50-320	T
SHACKLETON, D. C.	7908300229	50-320	T
SHACKLETON, D. C.	7908290210	50-320	T
SHACKLETON, D. C.	7908290232	50-320	T
SHACKLETON, D. C.	7908290264	50-320	T
SHACKLETON, D. C.	7908290324	50-320	T
SHACKLETON, D. C.	7908280786	50-320	T
SHACKLETON, D. C.	7908280819	50-320	T
SHACKLETON, D. C.	7908280837	50-320	T
SHACKLETON, D. C.	7908290048	50-320	T
SHACKLETON, D. C.	7908290059	50-320	T
SHACKLETON, D. C.	7908280623	50-320	T
SHAH, M. M.	7908010645	REGGD	
SHAH, S. J.	7908170319*	TOPREP	
SHALLER, D. V.	7908150314	50-315	S
SHALLER, D. V.	7908030224	50-316	S
SHALLER, D. V.	7908060312	50-316	S
SHALLER, D. V.	7908060416	50-315	S
SHALLER, D. V.	7908140632	50-316	S
SHALLER, D. V.	7908140650	50-315	S
SHALLER, D. V.	7908170341	50-316	R
SHALLER, D. V.	7908310335	50-315	R
SHALLER, D. V.	7908210511	50-31[illegible]	S
SHALLER, D. V.	7908210517	50-315	S
SHALLER, D. V.	7908290423	50-315	S
SHANBAKY, M. M.	7908020070*	50-272	G
SHAPAR, H. K.	7908080692*	50-280	P
SHAPAR, H. K.	7908200378*	FOIA	
SHAPAR, H. K.	7908240350	SECY	
SHAPAR, H. K.	7908030598	50-556	Q
SHAPAR, H. K.	7908170505*	50-289	F
SHAPAR, H. K.	7908200239	50-255	U
SHAPAR, H. K.	7908140433	RM	
SHAPAR, H. K.	7908200021	50-361	M
SHAPAR, H. K.	7908270543	50-361	M
SHAPAR, H. K.	7908240443	50-568	M
SHAPIRA, R.	7908300393	50-322	G
SHAPIRO, B.	7908300403*	50-322	G
SHAW, G.	7908210[illegible]59	50-574	A
SHEA, J. R.	7908130655	SECY	
SHEA, J. R.	7908140620	SECY	
SHEA, J. R.	7908090557	SECY	
SHEA, J. R.	7908130041	SECY	
SHEA, J. R.	7908100504	SECY	
SHEA, J. R.	7908130618	SECY	
SHEA, J. R.	7908090009*	SECY	
SHEA, J. R.	7908090512	SECY	
SHEA, J. R.	7908200265*	FOIA	
SHEA, J. R.	7908010358	XPORTLIC	
SHEA, J. R.	7908130070	SECY	
SHEA, J. R.	7908130090	SECY	
SHEA, J. R.	7908140364	SECY	
SHEA, J. R.	7908200260*	FOIA	
SHEA, J. R.	7908130129	SECY	
SHEA, J. R.	7908130151	SECY	
SHEA, J. R.	7908130053	SECY	
SHEA, J. R.	7908010330*	SECY	
SHEA, J. R.	7908130100	SECY	
SHEA, J. R.	7908220158	50-320	P
SHEA, J. R.	7908240520	SECY	
SHEA, J. R.	7908240545	SECY	
SHEA, J. R.	7908090241	XPORTLIC	
SHEA, J. R.	7908220255	XPORTLIC	
SHEA, J. J.	7908170251	50-244	P
SHEA, J. J.	7908230678	50-409	P
SHEDLOSKY, J. T.	7908020099*	50-245	G
SHEETS, M. W.	7908160472*	50-280	P
SHELDON, K. P.	7908300264	50-568	G
SHELDON, K. P.	7908[illegible]00281*	50-568	G
SHELDON, K. P.	7908[illegible]105444*	50-443	G
SHELLY, F. L.	7908240535	50-387	D
SHELLEY, W. J.	7908220184	40-2061	
SHELLEY, W. J.	7908140502	40-8027	
SHELLEY, W. J.	7908310109	40-8727	
SHELLEY, W. J.	7908310540*	40-8727	
SHELLEY, W. J.	7908090638	40-8027	
SHELLEY, W. J.	7908140507*	40-8027	
SHELLEY, W. J.	7908010071	40-8027	
SHELLEY, W. J.	7908010656	REGGD	
SHELLEY, W. J.	7908290218	70-925	
SHEMANSKI, P.	7908030232	50-213	P
SHEMANSKI, P.	7908210143	TOPREP	
SHEPARD, A. M.	7908[illegible]90516	50-443	G
SHEPARD, A. M.	7908070344	50-443	G
SHEPARD, A. M.	7908080353	50-443	G
SHEPARD, A. M.	7908240589	50-443	G
SHEPHERD, T. A.	7908140198	PROJ	
SHEPPARD, S.	7908030549	XPORTLIC	
SHER, J. R.	7908090652	XPORTLIC	
SHERMAN, B. M.	7908280047*	50-471	F
SHERMAN, F. L.	7908140016	70-33	
SHERWOOD, G. G.	7907120319	REGGD	
SHERWOOD, G. G.	7908010599	REGGD	
SHERWOOD, G. G.	7908290184*	REGGD	
SHERWOOD, G. G.	7908160462	NUREG	
SHERWOOD, G. G.	7908280563	TOPREP	
SHEWMON, P.	7908090641	50-437	D
SHEWMON, P.	7908030317	ACRS	
SHEWMON, P.	7908030364	ACRS	
SHIELDS, S. W.	7908170398	50-546	H
SHIELDS, S. W.	7908290500	50-546	S
SHIFFMAN, D. T.	7908150279*	50-275	H
SHIVELY, C. N.	7908310393*	50-313	S
SHIVELY, C. N.	7908020459*	50-313	S
SHIVELY, C. N.	7908020492*	50-368	S
SHIVELY, C. N.	7908060472*	50-368	S
SHIVELY, C. N.	7908060475*	50-368	S
SHIVELY, C. N.	7908060480*	50-368	S
SHIVELY, C. N.	7908060482*	50-368	S
SHIVELY, C. N.	7908060487*	50-368	S
SHIVELY, C. N.	7908080511*	50-313	S
SHIVELY, C. N.	7908070551*	50-368	S
SHIVELY, C. N.	7908070576*	50-368	S
SHIVELY, C. N.	7908070592*	50-368	S
SHIVELY, C. N.	7908070605*	50-368	S
SHIVELY, C. N.	7908070623*	50-368	S
SHIVELY, C. N.	7908200308*	50-368	S
SHIVELY, C. N.	7908230371*	50-313	R
SHIVELY, C. N.	7908230373*	50-368	R
SHIVELY, C. N.	7908300571*	50-313	S
SHIVLEY, C. N.	7908020475*	50-313	S
SHON, F.	7908030287	50-272	T
SHON, F.	7908030621	50-272	T
SHON, F.	7908090653	50-312	T
SHORB, J. G.	7908070757	50-367	G
SHORB, E. M.	7908090305	50-367	G
SHORB, E. M.	7908140323	50-367	G
SHORB, E. M.	7908160426	50-367	A
SHORTZ, S.	7908270495	50-387	H
SHORTRIDGE, E. W.	7908170211	40-299	
SHORT, T. E.	7908080406	50-285	G
SHORT, T. E.	7908230671*	50-285	G
SHORT, T. E.	7908080459	50-285	G
SHORT, T. E.	7908170239	50-285	G
SHORT, T. E.	7908160041	50-285	G
SHORT, T. E.	7908290244	50-285	G
SHORT, T. E.	7908160039	50-285	G
SHORT, T. E.	7908170524	50-285	G
SHORT, T. E.	7908010498	50-285	P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
SHORT, T. E.	7908010553	50-285	H
SHORT, T. E.	7908070631	50-285	P
SHORT, T. E.	7908070651	50-285	P
SHORT, T. E.	7908080531	50-285	G
SHORT, T. E.	7908140603	50-285	P
SHORT, T. E.	7908140683	50-285	G
SHORT, T. E.	7908140755	50-285	R
SHORT, T. E.	7908140394	50-285	P
SHORT, T. E.	7908160439	50-285	G
SHORT, T. E.	7908270405	50-285	P
SHORT, T. E.	7908220300	50-285	P
SHORT, T. E.	7908270415	NUREG	
SHORT, T. E.	7908300650	50-285	P
SHRIVER, B. L.	7908020515	50-62	S
SHRIVER, B. L.	7908310547	50-62	F
SHUM, E. Y.	7908240489	70-2064	
SICKEL, J. V.	7908310377*	50-331	S
SIEGEL, S. M.	7908300230*	50-206	S
SIEMANN, D. L.	7908170081*	50-245	P
SIESS, C.	7908090641	50-437	O
SIESS, C. P.	7908150053	ACRS	
SILBERG, J. E.	7908150762	50-320	P
SILBERG, J. E.	7908080011	50-387	G
SILBERG, J. E.	7908080029	50-387	G
SILBERG, J. E.	7908080060	50-387	G
SILBERG, J. E.	7908300021	50-387	G
SILBERG, J. E.	7908220026	50-387	G
SILVER, R. D.	7908070013	50-155	P
SILVER, R. D.	7908280168*	50-155	P
SILVER, R. D.	7908170506	50-255	P
SILVER, R. D.	7908100173*	50-409	P
SILVER, R. D.	7908230663*	50-255	P
SIMONIS, J. C.	7908010660*	TOPREP	
SIMPSON, G. H.	7908150078*	FOIA	
SINCLAIR, J. R.	7908290721	50-320	T
SINCLAIR, J. R.	7908300029	50-320	T
SINCLAIR, J. R.	7908300075	50-320	T
SINCLAIR, J. R.	7908290720	50-320	T
SINCLAIR, J. R.	7908300045	50-320	T
SINCLAIR, J. R.	7908290622	50-320	T
SINCLAIR, J. R.	7908300202	50-320	T
SINCLAIR, J. R.	7908300265	50-320	T
SINCLAIR, D. C.	7908280645	50-320	T
SINCLAIR, J. R.	7908300140	50-320	T
SINCLAIR, J. R.	7908280756	50-320	T
SINCLAIR, J. R.	7908280688	50-320	T
SINCLAIR, J. R.	7908280696	50-320	T
SINCLAIR, J. R.	7908290635	50-320	T
SINCLAIR, J. R.	7908290692	50-320	T
SINCLAIR, J. R.	7908280680	50-320	T
SINCLAIR, J. R.	7908280657	50-320	T
SINCLAIR, J. R.	7908280772	50-320	T
SISTER LEONILE	7908060249*	50-574	G
SISTER M. THERES	7908060445	50-574	G
SISTER NORMA	7908170363*	70-2319	
SITERBURN, T.	7908220159	50-574	G
SJOGREN, R. M.	7908140774*	50-309	R
SJOGREN, R. M.	7908140437*	50-271	R
SJOGREN, R. M.	7908140373*	50-29	R
SKARITKA, J.	7908170407*	TOPREP	
SKARUPA, J. D.	7908020383	XPORTLIC	
SKARUPA, J. D.	7908150565	XPORTLIC	
SKELLY, R. E.	7908300317	50-522	G
SKINNER, L. W.	7908140735	FOIA	
SKOLDS, J. L.	7908230588*	50-395	G
SKOLDS, J. O.	7908240326*	50-280	G
SKOVHOLT, D. J.	7908130066	NUREG	
SLAWSON, R. N.	7908160295	50-574	A
SLEMMONS, D. B.	7908210530	50-70	H
SMITH, J. M.	7908150014	50-522	G
SMITH, P.	7908220042	50-574	G
SMITH, J.	7908280246*	50-312	A
SMITH, E. H.	7908300521	50-522	G
SMITH, K. R.	7908230469	50-320	P
SMITH, C. V.	7908240488	50-243	P
SMITH, C. W.	7908140068	NUREG	
SMITH, L. J.	7908100393*	QA999	
SMITH, L. J.	7908100390*	QA999	
SMITH, N. P.	7908160456	50-237	P
SMITH, R. I.	7908080149*	50-311	A
SMITH, R. H.	7908010364	RES	
SMITH, P. A.	7908160430	CONTRACT	
SMITH, P. A.	7908230176	CONTRACT	
SMITH, S. H.	7908250396	50-272	G
SMITH, B. H.	7908280858	50-471	G
SMITH, B. H.	7908080130	50-272	G
SMITH, B. H.	7908100162	50-272	G
SMITH, B. H.	7908100153	50-272	G
SMITH, B. H.	7908220152	50-272	G
SMITH, B. H.	7908220157*	50-272	G
SMITH, B. H.	7908080315	50-471	G
SMITH, B. H.	7908220546	50-471	G
SMITH, J. T.	7908230640*	50-320	G
SMITH, T. H.	7908140051*	50-336	G
SMITH, G. H.	7908240117*	40-8002	
SMITH, G. H.	7908090441	AGREEMENT	
SMITH, G. H.	7908010720	50-220	G
SMITH, G. H.	7908150754	50-320	G
SMITH, G. H.	7908010136*	ORG	
SMITH, G. H.	7908010141*	ORG	
SMITH, G. H.	7908270058	50-271	G
SMITH, T. H.	7908130390*	50-219	G
SMITH, J. D.	7908290516*	50-305	G
SMITH, C. V.	7908210162*	SECY	
SMITH, C. V.	7908230163	SECY	
SMITH, R. D.	7908080385	27-47	
SMITH, H.	7908100322	50-10	P
SMITS, C. J.	7908290614	71-9010	
SNAPP, B. A.	7908300038	50-387	G
SNIEZEK, J. H.	7908010690*	10CFR	
SNOW, B. A.	7908210437	50-244	S
SNOW, B. A.	7908270521	50-244	S
SNOW, B. A.	7908210369	50-244	R
SNYDER, L. M.	7908240288*	FOIA	
SNYDER, L. M.	7908240185	FOIA	
SNYDER, L.	7908080697	FOIA	
SNYDER, G. L.	7908220675	50-219	G
SNYDER, B. J.	7908030099	XPORTLIC	
SOBON, L. J.	7908090254*	TOPREP	
SOBON, L. J.	7908280548	TOPREP	
SOBON, L. J.	7908030370	TOPREP	
SOBON, L. J.	7908130450	TOPREP	
SOBON, L. J.	7908150670	TOPREP	
SOBON, L. J.	7908150681	TOPREP	
SOBON, L. J.	7908090559	TOPREP	
SOBON, L. J.	7908270379	TOPREP	
SOBON, L. J.	7908310441	TOPREP	
SOBON, L. J.	7908240409	TOPREP	
SOBON, L. J.	7908280648	TOPREP	
SOBON, L. J.	7908280596	TOPREP	
SOENEN, E. A.	7908290611	71-9033	
SOHINKI, S. M.	7905140562	50-592	G
SOHINKI, S. M.	7905140571	50-452	G
SOHINKI, S. M.	7905150034	50-485	G
SOHINKI, S. M.	7908020290	50-437	G
SOHINKI, S. M.	7908160104	50-466	G
SOHINKI, S. M.	7906020258	50-592	G
SOHINKI, S. M.	7908090164	50-437	A
SOHINKI, S. M.	7908220320	50-466	G
SOHINKI, S. M.	7908220346	50-466	G
SOHINKI, S. M.	7908220352*	50-466	G
SOIRTA, V.	7908240166	50-574	G
SOKOLOWSKI, A.	7908310249	XPORTLIC	
SOKOLOWSKI, A.	7908310291*	XPORTLIC	
SOKOLOWSKI, A.	7908310254*	XPORTLIC	
SOKOLOWSKI, A.	7908310422	XPORTLIC	
SOLBERG, D. E.	7908160347	REVIEW GRP	
SOONG, A. L.	7908240492	70-1852	
SOONG, A. L.	7908210048*	40-8027	
SOUDER, J. L.	7908010286	50-269	H
SOUDER, J. L.	7908270324	50-269	S
SOUDER, J. L.	7908210039	50-546	A
SOWERS, G. W.	7908230667	NUREG	
SPALLONE, K.	7908220257	50-320	H
SPANGLER, R. G.	7908090691*	50-313	G
SPARKS, D. T.	7908010364	RES	
SPARKS, E.	7908010253	40-8477	
SPECTOR, S.	7908280731*	50-244	S
SPELMAN, H. J.	7908070824	40-2061	
SPENCER, W. C.	7908060003	50-280	G
SPENCER, W. C.	7908020478	50-280	P
SPENCER, W. C.	7908310018	50-280	G
SPENCER, W. C.	7908230467	50-280	P
SPENCER, G. S.	7908140385*	50-528	G
SPENCER, G. S.	7908090700*	50-361	G
SPENCER, G. S.	7908150222	50-275	G
SPENCER, G. S.	7908230053	50-460	G
SPENCER, G. S.	7908140363	50-528	G
SPENCER, G. S.	7908090697	50-361	G
SPENCER, G. S.	7908150235	50-361	G
SPENCER, G. S.	7908150188	50-522	G
SPENCER, G. S.	7908150202	50-397	G
SPENCER, G. S.	7908170107	50-361	G
SPENCER, G. S.	7908200229	50-275	G
SPENCER, G. S.	7908150304	50-361	G
SPENCER, G. S.	7908150246*	50-275	G
SPENCER, G. S.	7908230064*	50-460	G
SPESSARD, R. L.	7908230635*	50-146	G
SPESSARD, R. L.	7908230624*	50-146	G
SPESSARD, R. L.	7908010231*	50-10	G
SPESSARD, R. L.	7908070825*	50-295	G
SPESSARD, R. L.	7908080194*	50-373	G
SPIELES, P.	7908210084	40-8380	
SPIELES, P.	7908230035	40-8697	
SPIELES, P.	7908230227	40-8697	
SPINDEL, N. W.	7908170337	50-596	G
SPITALNY, B. S.	7908030472*	70-2623	
SPITALNY, B. S.	7908130169	70-2623	
SPITZNOGLE, A. E.	7908140525*	50-334	R
SPODAK, W. M.	7908200251	FOIA	
SPRAUL, J. G.	7908160173	50-250	G
SRENIAWSKI, D. J.	7908280136*	70-572	
STACHON, E.	7908300309	50-522	G
STACHON, E.	7908300018*	50-522	G
STADE, R. L.	7908160017	50-466	G
STAFFA, R. W.	7908020361	50-321	G
STAFFA, R. W.	7908020251	50-321	G
STAFFA, R. W.	7908080570	50-321	G
STAFFA, R. W.	7908030495	50-321	G
STAFFA, R. W.	7908140528	50-424	G
STAFFA, R. W.	7908230426	50-321	G
STAFFA, R. W.	7908210310*	50-321	G
STAFFA, R. W.	7908300729	50-321	G
STAFFA, R. W.	7908310027	50-424	G
STAFFA, R. W.	7908310042	50-321	G
STAFFA, R. W.	7908160488*	50-321	G
STAFFA, R. W.	7908150390	50-321	G
STAFFA, R. W.	7908170562*	50-321	G
STAFFA, R. W.	7908160469	50-321	G
STAHLE, C. R.	7908010699	50-327	A
STAHLE, C.	7908160032	50-424	A
STALCUP, W. C.	7908130142*	QA999	
STALLINGS, C. M.	7908030595	50-338	S
STALLINGS, C. M.	7908220025	50-280	G
STALLINGS, C. M.	7908010701*	50-281	G
STALLINGS, C. M.	7908060172	50-338	G
STALLINGS, C. M.	7908150247*	50-280	G
STALLINGS, C. M.	7908080109	50-338	G
STALLINGS, C. M.	7908220406*	50-338	G
STALLINGS, C. M.	7908150200*	50-280	G
STALLINGS, C. M.	7908090427	50-338	G
STALLINGS, C. M.	7908070743	50-280	G
STALLINGS, C. M.	7908080151	50-280	G
STALLINGS, C. M.	7908240156*	50-281	G
STALLINGS, C. M.	7908010515	50-260	H
STALLINGS, C. M.	7908030348	50-280	P
STALLINGS, C. M.	7908060369	50-338	P
STALLINGS, C. M.	7908030448	50-280	S
STALLINGS, C. M.	7908070494	50-338	S
STALLINGS, C. M.	7908070577	50-338	S
STALLINGS, C. M.	7908090569	50-338	P
STALLINGS, C. M.	7908280559	50-338	S
STALLINGS, C. M.	7908100305	50-338	S
STALLINGS, C. M.	7908100454	50-280	G
STALLINGS, C. M.	7908130352	50-338	R
STALLINGS, C. M.	7908130454	50-338	S
STALLINGS, C. M.	7908130465	50-280	P
STALLINGS, C. M.	7908130452	50-280	P
STALLINGS, C. M.	7908140438	50-280	P
STALLINGS, C. M.	7908280588	50-281	P
STALLINGS, C. M.	7908160348	50-280	R
STALLINGS, C. M.	7908160354	50-281	P
STALLINGS, C. M.	7908160429	50-338	S
STALLINGS, C. M.	7908160479	50-280	S
STALLINGS, C. M.	7908160445	50-338	P
STALLINGS, C. M.	7908200368	50-280	S
STALLINGS, C. M.	7908210309	50-338	P
STALLINGS, C. M.	7908210410	50-338	P
STALLINGS, C. M.	7908210002	50-280	F
STALLINGS, C. M.	7908210003	50-338	F
STALLINGS, C. N.	7908210420	50-280	F
STALLINGS, C. M.	7908240422	50-338	S
STALLINGS, C. M.	7908240485	50-338	S
STALLINGS, C. M.	7908240506	50-338	P
STALLINGS, C. M.	7908280649	50-338	S
STALLINGS, C. M.	7908280660	50-280	S
STALLINGS, C. M.	7908280750	50-338	S
STALTER, L. C.	7908230507*	50-320	S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STAMPLEY, N. L.	7908160486*	50-416 K
STAMPLEY, N. L.	7908160473	50-416 K
STAMPLEY, N. L.	7908210007	50-416 F
STANDERFER, F. R.	7908210383	50-320 P
STANLEY, L. A.	7908010278*	50-309 H
STANLEY, C. J.	7908030090	RES
STARKS, S. J.	7908310446*	TOPREP
STARKEY, R. B.	7908210422*	50-261 S
STARKEY, R. B.	7908290449*	50-261 S
STARKEY, R. B.	7908300663*	50-261 S
STEELE, W. F.	7908280417*	71-126
STEEL, W. F.	7908030091	71-111
STELLO, V.	7908020236	50-482 G
STELLO, V.	7908020246*	50-482 G
STELLO, V.	7908150748	50-320 H
STELLO, V.	7908130392	50-482 G
STELLO, V.	7908130394	50-482 G
STELLO, V.	7908130400	50-482 G
STELLO, V.	7908170522	50-482 G
STELLO, V.	7908170075	70-820
STELLO, V.	7908140223	50-482 G
STELLO, V.	7908140261	50-482 G
STELLO, V.	7908150085	50-482 G
STELLO, V.	7908150098	50-482 G
STELLO, V.	7908150106	50-482 G
STELLO, V.	7908150114	50-482 G
STELLO, V.	7908150121	50-482 G
STELLO, V.	7908150127	50-482 G
STELLO, V.	7908150156	50-482 G
STELLO, V.	7908300345	50-482 G
STELLO, V.	7908230440	50-320 P
STELLO, V.	7908270534	50-482 H
STELLO, V.	7908240594	50-281 G
STELLO, V.	7908080456*	50-250 P
STELLO, V.	7908030324*	50-261 P
STELLO, V.	7908030156	50-3 P
STELLO, V.	7908220105*	FOIA
STEPHENS, J. V.	7905170553	TOPREP
STEPHENS, E.	7908240482*	50-70 P
STEPHEN, E.	7908300433*	50-18 P
STEPHENSON, B. B.	7908170053	50-237 G
STEPHENSON, B. B.	7908080404	50-249 S
STEPHENSON, B. B.	7908080383	50-237 S
STEPHENSON, B. B.	7908080500	50-249 S
STEPHENSON, B. B.	7908140615	50-249 S
STEPHENSON, B. B.	7908220397	50-237 S
STEPHENSON, B. B.	7908300459	50-10 R
STEPHENSON, B. B.	7908280640	50-237 S
STEPHENS, A. G.	7908020489	RES
STEPTOE, P.	7908080179	50-599 G
STEPTOE, P. P.	7908150056	50-295 G
STEPTOE, P. P.	7908080378	50-295 G
STEPTOE, P.	7908080170	50-599 G
STERNBERG, D. M.	7908090695*	50-344 G
STERNBERG, D. M.	7908270011*	50-275 G
STETKA, T. F.	7908090694*	50-223 G
STETSON, D.	7908210157	50-320 P
STEVENSON, M. G.	7908070803	NUREG
STEVENSON, M. G.	7908140104	NUREG
STEVENSON, R. L.	7908150170	70-36
STEVENSON, R. L.	7908150180	70-1113
STEVENSON, R. L.	7908210047	70-1257
STEVENSON, R. L.	7908240492	70-1852
STEWART, J. H.	7908200115*	50-518 F
STEWART, W. P.	7908280754	50-302 P
STEWART, W. P.	7908030572	50-302 G
STEWART, W. P.	7908030040	50-302 G
STEWART, W. P.	7908300087*	50-302 G
STEWART, W. P.	7908170259	50-302 G
STEWART, W. P.	7908300080*	50-302 G
STEWART, W. P.	7908150709	50-302 G
STEWART, W. P.	7908030399	50-302 S
STEWART, W. P.	7908020473	50-302 H
STEWART, W. P.	7908060072	50-302 G
STEWART, W. P.	7908060506	50-302 S
STEWART, W. P.	7908070383	50-302 P
STEWART, W. P.	7908100455	50-302 S
STEWART, W. P.	7908170001	50-302 G
STEWART, W. P.	7908100343	50-302 S
STEWART, W. P.	7908090387	50-302 P
STEWART, N. P.	7908090457	50-302 P
STEWART, W. P.	7908100301	50-302 P
STEWART, W. P.	7908140447	50-302 P
STEWART, W. P.	7908170409	50-302 R
STEWART, W. P.	7908170397	50-302 P
STEWART, W. P.	7908210361	50-302 S
STEWART, W. P.	7908200206	50-302 F
STEWART, W. P.	7908230415	50-302 P
STEWART, W. P.	7908230541	50-302 S
STEWART, W. P.	7908270445	50-302 S
STEWART, W. P.	7908290450	50-302 S
STEWART, W. P.	7908310303	50-302 S
STEWART, W. P.	7908310378	50-302 F
STEWART, W. P.	7908310466	50-302 S
STEWART, W. P.	7908310518	50-302 R
STEWART, W. P.	7908270312	50-302 G
STEWART, W. P.	7908200264	50-302 G
STEWART, W. P.	7908280693	50-302 S
STEWART, W. L.	7908170160	50-280 G
STEWART, W. L.	7908070789	50-280 G
STEWART, W. L.	7908230239	50-280 G
STEWART, W. L.	7908090489	50-280 G
STEWART, W. L.	7908030456*	50-280 S
STEWART, W. L.	7908160484*	50-280 S
STEWART, W. L.	7908200376*	50-280 S
STEWART, W. L.	7908280667*	50-280 S
STOHR, J. P.	7908230590*	50-320 G
STOHR, J. P.	7908230611*	50-320 G
STOHR, J. P.	7908010125	ORG
STOHR, J. P.	7908230659*	50-320 G
STOHR, J. P.	7908230544*	50-320 G
STOHR, J. P.	7908090449*	AGREEMENT
STOHR, J. P.	7908020070*	50-272 G
STOHR, J. P.	7908010722*	50-220 G
STOHR, J. P.	7908150760*	50-320 G
STOICK, A. F.	7908090364	40-8663
STOICK, A. F.	7908140188	40-8663
STOKES, L. W.	7908170629*	PROJ
STOLZ, J. F.	7908130359	50-255 P
STOLZ, J. F.	7908010302	50-416 A
STOLZ, J. F.	7908060092	50-275 A
STOLZ, J. F.	7908060101*	50-275
STOLZ, J. F.	7908080146	50-358
STOLZ, J. F.	7908080155	50-364
STOLZ, J. F.	7908200318	50-275 A
STOLZ, J. F.	7908090578	50-358 F
STOLZ, J. F.	7908150715	50-275 S
STOLZ, J. F.	7908170102	50-358 A
STOLZ, J. F.	7908160324	50-368 G
STOLZ, J. F.	7908130536	50-368 P
STOLZ, J. F.	7908130540	50-275 A
STOLZ, J. F.	7908170353	50-275 A
STOLZ, J. F.	7908170356	TOPREP
STOLZ, J. F.	7908210323	50-364 A
STOLZ, J. F.	7908210334	50-416 A
STOLZ, J. F.	7908210342	50-275 A
STOLZ, J. F.	7908230687	50-275 A
STONE, R.	7908140470	50-250 U
STOODLEY, D. G.	7908080004	50-471 G
STRAIT, R. A.	7908140408	40-8721
STRANG, J. P.	7908220430	50-187 J
STRATTON, L. E.	7908310065*	27-39
STRAUSS, P. L.	7908220686	FOIA
STRELCZYK, P. J.	7908130370*	GA999
STUDDS, G. E.	7908010204*	50-293 U
STUKENBROEKER, G.	7908240031	XPORTLIC
STUKENBROEKER, G.	7908140011	71-244
STULBERG, R. B.	7908150735*	50-320 H
SU, T. M.	7908170240	GEN TEC IS
SULLIVAN, R. F.	7908230578*	50-259 G
SULLIVAN, R. F.	7908060002*	50-259 G
SUNDARAM, R. K.	7908140631	RES
SUTHERLAND, J. T.	7908020587	70-824
SUTHERLAND, J. T.	7908150597*	70-1151
SUTHERLAND, J. T.	7908210567	50-124 G
SUTHERLAND, J. T.	7908100384*	50-413 G
SUTHERLAND, J. T.	7908170152	70-27
SUTHERLAND, J. T.	7908150590*	70-1151
SUTHERLAND, J. T.	7908290094	50-338 G
SUTHERLAND, J. T.	7908160480*	50-348 G
SUTHERLAND, J. T.	7908160490*	50-321 G
SUTHERLAND, J. T.	7908170074*	70-143
SUTHERLAND, J. T.	7908170071*	70-143
SUTHERLAND, J. T.	7908290213	50-302 G
SUTHERLAND, J. T.	7908130397*	50-332 G
SUTHERLAND, J. T.	7908150206*	50-280 G
SUTHERLAND, J. T.	7908280162	50-280 G
SUTHERLAND, J. T.	7908290228	70-824
SUTHERLAND, J. T.	7908100381	50-413 G
SUTHERLAND, J. T.	7908100382*	50-413 G
SUTHERLAND, J. T.	7908160319*	50-321 G
SUTHERLAND, J. T.	7908150187	50-280 G
SUTHERLAND, J. T.	7908150583	70-1151
SUTHERLAND, J. T.	7908170277	50-553 G
SUTHERLAND, J. T.	7908270278*	70-143
SUTHERLAND, J. T.	7908160470	50-348 G
SUTHERLAND, J. T.	7908160481	50-321 G
SUTHERLAND, J. T.	7908300563*	70-143
SUTHERLAND, J. T.	7908210126	70-143
SUTHERLAND, J. T.	7908210137*	70-143
SUTTON, J. W.	7908090188*	GA999
SUTTON, J. W.	7908080014*	GA999
SUTTON, J. W.	7908080003*	GA999
SWAN, W. B.	7908290208*	50-518 G
SWANBY, G. T.	7908280706	40-3453
SWANBY, G. T.	7908090473	40-3453
SWANSON, D. T.	7908160529*	50-338 P
SWANSON, D. T.	7908140045	50-338 G
SWANSON, D. T.	7908010637	50-338 G
SWART, F. E.	7908010066	50-267 G
SWART, F. E.	7908140199	50-267 G
SWART, F. E.	7908010480	50-267 P
SWART, F. E.	7908290605	50-267 R
SWETNAM, R. L.	7908230621*	50-320 G
SWICK, C. B.	7908030457	FOIA
SWITZER, D. C.	7908210183*	50-213 G
SWITZER, D. C.	7908300642	50-336 P
SYED, A.	7908080471	FOIA
SZABO, R.	7908020375	XPORTLIC
TADA, H.	7908070659	NUREG
TALWANI, P.	7908010357*	50-395 A
TAMBLING, T. N.	7908160322*	50-346 G
TANNER, M. E.	7908310446*	TOPREP
TAPIA, J. I.	7908100235*	50-556 G
TARAS, D. W.	7908020126	71-6639
TAYLOR, P.	7908160386	FOIA
TAYLOR, M. J.	7908060285	40-1162
TAYLOR, P.	7908160386	FOIA
TAYLOR, J. H.	7908030619*	50-346 G
TAYLOR, J. H.	7908090587	TOPREP
TAYLOR, J. H.	7908010649	TOPREP
TAYLOR, J. H.	7908020508	TOPREP
TAYLOR, J. H.	7908170316	TOPREP
TAYLOR, J. H.	7908220098	TOPREP
TAYLOR, J. H.	7908140398	TOPREP
TAYLOR, J. H.	7908080461	TOPREP
TAYLOR, J. H.	7908070588	TOPREP
TAYLOR, J. H.	7908080468	TOPREP
TAYLOR, J. H.	7908080481	TOPREP
TAYLOR, J. H.	7908290166	REGGD
TAYLOR, J. H.	7908240632	TOPREP
TAYLOR, J. H.	7908220342	TOPREP
TAYLOR, J. H.	7908240363	TOPREP
TAYLOR, J. H.	7908210296	TOPREP
TAYLOR, J. H.	7908240400	TOPREP
TAYLOR, R. R.	7908080357	71-248
TAYLOR, P. A.	7908240196*	50-280 G
TAYLOR, P. A.	7908240353*	50-338 G
TAYLOR, P. A.	7908230683*	50-348 G
TAYLOR, R. G.	7908070130*	50-445 G
TAYLOR, R. G.	7908270123*	50-445 G
TAYLOR, R. G.	7908230666*	50-445 G
TAYLOR, R. G.	7908310116*	50-445 G
TEDESCO, R. L.	7906060192*	50-263 G
TEDESCO, R. L.	7908220502*	50-320 P
THAMER, B. J.	7908140462	NUREG
THEOFANOUS, T. G.	7908130031	ACRS
THIERER, I.	7908070663	50-361 A
THOM, T.	7908140451*	50-259 R
THOMAS, J. D.	7908280428*	COMMISSION
THOMAS, J. D.	7908280400*	COMMISSION
THOMAS, J. D.	7908280378*	COMMISSION
THOMAS, R. H.	7908210336*	50-213 S
THOMAS, W. N.	7908140450	50-339 A
THOMAS, C. O.	7908010693	50-556 A
THOMAS, C. O.	7908170591	50-556 A
THOMAS, C. O.	7908240666	50-416 A
THOMAS, C. O.	7908210170	50-416 A
THOMPSON, D. D.	7908150092	70-734
THOMPSON, F.	7908270390	50-387 G
THOMPSON, T.	7908080666	FOIA
THOMPSON, S.	7908160078	XPORTLIC
THOMPSON, O. O.	7908200008	50-400 A
THOMSON, J.	7908200060*	50-280 H
THOMSEN, F. T.	7908150012	50-522 G
THOMSEN, F. T.	7908300004	50-522 G
THOMSEN, F. T.	7908170350	50-522 G
THOMSEN, F. T.	7908300724	50-522 G

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
THOMSEN, F. T.	7908170326	50-522 G
THONUS, L. H.	7908270069*	50-271 G
THOREN, D. E.	7908020516*	TOPREP
THOREN, D. E.	7908010660*	TOPREP
THORNBURGH, R.	7908300779*	COMMISSION
THORNBERRY, R.	7908080617*	50-390 A
THORNBURG, H. D.	7908150582	50-320 P
THORNBURG, H. D.	7908220067	50-320 H
THORNBURG, H. D.	7908000730*	50-280 P
THORNBURG, H. D.	7908080693*	50-280 P
THURLOW, E. W.	7908220437	50-309 P
TIBBITTS, D. L.	7908100292	50-352 A
TIBBITTS, D. L.	7908130054	50-352 A
TIBBITS, D. L.	7908220241	50-395 A
TIERNEY, M. S.	7908030044	NUREG
TIETZ, G.	7908140628*	50-265 S
TILLINGHAST, J.	7908140526*	FOIA
TIRONA, N. J. T.	7908030189*	50-574 G
TOALSTON, A.	7908000161	50-482 M
TOALSTON, A.	7908030434	50-445 M
TOALSTON, A. L.	7908300195	50-316 M
TOALSTON, A.	7908270280	50-390 M
TOBIAS, M. L.	7908270100	NUREG
TOBIN, W. J.	7908280859	70-27
TOBIN, W. J.	7908240110*	50-250 G
TOBIN, W. J.	7908030632*	50-269 G
TOBIN, W. J.	7908030632*	50-269 G
TOBIN, W. J.	7908210320*	50-321 G
TOBIN, W. J.	7908170486*	70-143
TODD, G. A.	7908150553*	70-143
TODD, G. A.	7908230658*	70-1113
TOLLISON, A. C.	7908020441	50-324 S
TOLLISON, A. C.	7908030498*	50-324 S
TOLLISON, A. C.	7908030313*	50-325 S
TOLLISON, A. C.	7908030423*	50-324 S
TOLLISON, A. C.	7908060415*	50-324 S
TOLLISON, A. C.	7908060543*	50-325 S
TOLLISON, A. C.	7908060545*	50-325 S
TOLLISON, A. C.	7908060501*	50-325 S
TOLLISON, A. C.	7908140700*	50-324 S
TOLLISON, A. C.	7908150680*	50-324 S
TOLLISON, A. C.	7908200299*	50-325 S
TOLLISON, A. C.	7908200306*	50-324 S
TOLLISON, A. C.	7908230380*	50-325 S
TOLLISON, A. C.	7908230382*	50-324 S
TOLLISON, A. C.	7908230404*	50-324 S
TOLLISON, A. C.	7908210399*	50-324 S
TOLLISON, A. C.	7908210434*	50-324 S
TOLLISON, A. C.	7908230459*	50-324 S
TOLLISON, A. C.	7908230547*	50-325 S
TOLLINSON, A. C.	7908230561*	50-324 S
TOLLISON, A. C.	7908270441*	50-324 S
TOLLISON, A. C.	7908240406*	50-325 S
TOLLISON, A. C.	7908240412*	50-325 S
TOLLISON, A. C.	7908240462*	50-324 S
TOLLISON, A. C.	7908300700*	50-324 S
TOLLISON, A. C.	7908290514*	50-325 S
TOLLISON, A. C.	7908290563*	50-324 S
TOLLISON, A. C.	7908310459*	50-325 S
TOMANTO, J. R.	7908310412*	50-335 P
TONG, L. S.	7908220232	WASH
TOOR, H. M.	7908150733	50-320 H
TOPP, A. A.	7908020401	40-8726
TOPP, A. A.	7908060484	40-8726
TOPP, A. A.	7908230029	40-8726
TORREY, M. D.	7908100387	NUREG
TOTH, A. D.	7908130621*	50-423 G
TOTH, A. D.	7908300046	50-322 G
TOURTELLOTTE, J.	7905150711	50-389 G
TOWNSEND, H. E.	7908150675*	TOPREP
TOWNSEND, J. E.	7908140590*	70-1207
TOWSE, D. F.	7908080408	NUREG
TOY, H. L.	7908210556	70-8
TOY, H. L.	7908240344	70-8
TOY, H. L.	7908280871	70-8
TRAMMELL, C. M.	7908230465*	50-344 G
TRAMMELL, C. M.	7908030338	50-301 P
TRAMMELL, C. M.	7908090502	50-305 P
TRAMMELL, C. M.	7908210076*	50-334 P
TRAVIS, C. C.	7908020379	RES
TRAVIS, C. C.	7908140584	RES
TREADWELL, J. R.	7908070591	50-387 D
TRIGILIO, G.	7908090484	71-6574
TRIMBLE, D. C.	7908080456*	50-313 G
TRIMBLE, D. C.	7908010038	50-313 P
TRIMBLE, D. C.	7908090275*	50-313 G
TRIMBLE, D. C.	7908140186*	50-368 G
TRIMBLE, D. C.	7908280757	50-313 P
TRIMBLE, D. C.	7908160021	50-313 G
TRIMBLE, D. C.	7908160025	50-313 G
TRIMBLE, D. C.	7908160009	50-368 G
TRIMBLE, D. C.	7908080157	50-368 G
TRIMBLE, D. C.	7908030113	50-313 G
TRIMBLE, D. C.	7908100320	50-313 P
TRIMBLE, D. C.	7908160028	50-313 G
TRIMBLE, D. C.	7908170371	50-313 G
TRIMBLE, D. C.	7908150512	50-313 P
TRIMBLE, D. C.	7908170538	50-313 P
TRIMBLE, D. C.	7908150493	50-313 P
TRIMBLE, D. C.	7908150542	50-313 P
TRIMBLE, D. C.	7908010461	50-313 P
TRIMBLE, D. C.	7908020424	50-368 S
TRIMBLE, D. C.	7908080496	50-368 S
TRIMBLE, D. C.	7908020430	50-313 R
TRIMBLE, D. C.	7908020449	50-313 S
TRIMBLE, D. C.	7908020476	50-313 P
TRIMBLE, D. C.	7908020484	50-368 S
TRIMBLE, D. C.	7908060468	50-368 S
TRIMBLE, D. C.	7908080491	50-267 G
TRIMBLE, D. C.	7908080495	50-313 S
TRIMBLE, D. C.	7908310386	50-313 S
TRIMBLE, D. C.	7908070537	50-368 S
TRIMBLE, D. C.	7908100254	50-368 P
TRIMBLE, D. C.	7908140580	50-368 G
TRIMBLE, D. C.	7908150514	50-313 R
TRIMBLE, D. C.	7908160459	50-313 G
TRIMBLE, D. C.	7908200305	50-368 S
TRIMBLE, D. C.	7908230370	50-313 R
TRIMBLE, D. C.	7908230372	50-368 R
TRIMBLE, D. C.	7908230394	50-313 F
TRIMBLE, D. C.	7908280656	50-368 P
TRIMBLE, D. C.	7908290420	50-313 P
TRIMBLE, D. C.	7908290512	50-313 R
TRIMBLE, D. C.	7908300569	50-313 S
TRIMBLE, D. C.	7908300670	50-313 P
TRIPLETT, P.	7908130275*	TOPREP
TRIPP, L. E.	7908170082*	50-333 G
TRIPP, L. E.	7908200060*	50-336 G
TRIPP, L. E.	7908200066*	50-245 G
TRIPP, L. E.	7908280182*	50-281 G
TROFFER, G. J.	7908010454	50-320 R
TROFFER, G. J.	7908010500	50-320 R
TROFFER, G. J.	7908010558	50-320 R
TROUP, G. L.	7908160487*	50-348 G
TSUJI, K.	7908130629*	SECY
TSUJI, K.	7908090010*	SECY
TUCHFELD, G.	7908090352	PROJ
TURKANIS, M. M.	7908100335	71-6144
TURNER, E. A.	7908170372	50-498 G
TURNER, E. A.	7908090386	50-498 S
TURNER, E. A.	7908090526	50-498 G
TURNER, E. A.	7908090532	50-498 G
TURNER, E. A.	7908170358	50-498 A
TURNER, E. A.	7908310489	50-498 G
TURNER, E. A.	7908140441	50-498 A
TURNER, E. A.	7908140668	50-498 A
TURNER, E. A.	7908150442*	50-466 A
TURNER, E. A.	7908230418	50-498 S
TUTHILL, S. J.	7908150328	50-331 P
TWISDALE, L. A.	7908170493	PROJ
TWISDALE, L. A.	7908160435*	50-338 S
TYLER, P. E.	7908240450	50-170 P
TYLER, P. E.	7908100439	50-170 S
TYLER, P. E.	7908100479	50-170 S
TYLER, P. E.	7908100457	50-170 P
TYLER, P. E.	7908100493	50-170 P
UDALL, M. K.	7907310621*	COMMISSION
UGOLINI, D.	7908140785*	50-295 S
UHRIG, R. E.	7907260035	50-250 P
UHRIG, R. E.	7908020354	50-250 G
UHRIG, R. E.	7908030627	50-335 P
UHRIG, R. E.	7908140729	50-250 G
UHRIG, R. E.	7908270302	50-335 G
UHRIG, R. E.	7908100117	50-250 G
UHRIG, R. E.	7908140710	50-335 G
UHRIG, R. E.	7908090141	50-335 G
UHRIG, R. E.	7908300745	50-389 G
UHRIG, R. E.	7908090238	50-250 G
UHRIG, R. E.	7908300743	50-335 G
UHRIG, R. E.	7908310032	50-250 G
UHRIG, R. E.	7908200013*	50-335 G
UHRIG, R. E.	7908200034*	50-250 G
UHRIG, R. E.	7908160458	50-250 G
UHRIG, R. E.	7908210386	50-335 G
UHRIG, R. E.	7908240104*	50-335 G
UHRIG, R. E.	7908210119	50-250 G
UHRIG, R. E.	7908010571	50-335 F
UHRIG, R. E.	7908030330	50-250 P
UHRIG, R. E.	7908030171	50-250 P
UHRIG, R. E.	7908070375	50-250 I
UHRIG, R. E.	7908070395	50-335 P
UHRIG, R. E.	7908220548	50-389 G
UHRIG, R. E.	7908170049	50-250 G
UHRIG, R. E.	7908140372	50-251 P
UHRIG, R. E.	7908240146	50-335 G
UHRIG, R. E.	7908100466	50-335 P
UHRIG, R. E.	7908140459	50-250 P
UHRIG, R. E.	7908140435	50-250 P
UHRIG, R. E.	7908170352	50-251 P
UHRIG, R. E.	7908160362	50-250 P
UHRIG, R. E.	7908210265	50-250 P
UHRIG, R. E.	7908240467	50-250 G
UHRIG, R. E.	7908220005	50-250 F
UHRIG, R. E.	7908230093	50-335 R
UHRIG, R. E.	7908280562	50-335 P
UHRIG, R. E.	7908280681	50-251 G
UHRIG, R. E.	7908280027	50-250 F
UHRIG, R. E.	7908280662	50-335 P
UHRIG, R. E.	7908300645	50-335 P
UHRIG, R. E.	7908310408	50-335 P
UHRIG, R. E.	7908310454	50-335 F
ULLRICH, W. T.	7908010456	50-277 S
ULLRICH, W. T.	7908010312	50-277 S
ULLRICH, W. T.	7908130461	50-278 S
ULMAN, M. B.	7908090540	50-498 G
ULMAN, M. B.	7908080742	50-498 G
ULMAN, M. B.	7908080085	50-498 G
ULMAN, M. B.	7908080088*	50-498 G
ULMAN, M. B.	7908150006	50-445 G
ULMAN, M. B.	7908150007	50-445 G
ULMAN, M. B.	7908150008	50-445 G
UMBLE, D. G.	7908090286*	TOPREP
UPRIGHT, C. M.	7908080713*	50-338 P
USHKA, A. J.	7908100220*	QA999
UTLEY, R. M.	7908060050*	NUREG
UTLEY, E. E.	7908130295	50-261 G
UTLEY, E. E.	7908060326	50-324 G
UTLEY, E. E.	7908160356	50-261 G
UTLEY, E. E.	7908080135	50-324 G
UTLEY, E. E.	7908160142	50-261 G
UTLEY, E. E.	7908170121	50-324 G
UTLEY, E. E.	7908060006	50-324 G
UTLEY, E. E.	7908010269	50-261 H
UTLEY, E. E.	7908060335	50-261 S
UTLEY, E. E.	7908100163	50-261 F
UTLEY, E. E.	7908160100	50-261 P
UTLEY, E. E.	7908240478	71-345
UTLEY, E. E.	7908060457	50-261 P
UTLEY, E. E.	7908300590	50-324 G
UTLEY, E. E.	7908130357	50-261 P
UTLEY, E. E.	7908200383	50-324 H
UTLEY, E. E.	7908230399	50-261 F
UTLEY, E. E.	7908230608	50-324 G
UTLEY, E. E.	7908270446	50-261 P
UTLEY, E. E.	7908280561	50-324 P
UTLEY, E. E.	7908290566	50-324 P
UTLEY, E. E.	7908200258	50-261 G
VALLISH, E. J.	7908160478*	50-321 G
VALLISH, E.	7908020526*	50-416 G
VALLISH, E. J.	7908150394*	50-438 G
VALLISH, E.	7908210279*	50-250 G
VALORE, C.	7908080007	50-272 G
VAMES, G. J.	7908020516*	TOPREP
VAN BRUNT, E. E.	7908140375*	50-528 G
VAN BRUNT, E. E.	7908150034	50-592 B
VAN DOORN, P. K.	7908160341*	50-395 G
VAN ROOYEN, D.	7908020362	RES
VAN SICKEL, J.	7908210516*	50-331 R
VAN SICKEL, J.	7908310498*	50-331 S
VAN WINKLE, W.	7908020462	RES
VAN WINKLE, W.	7908030231	RES
VANBENBERG, L.	7905070024	50-320 H
VANDERVELDEN, M.	7908150268	50-312 G
VANDENBURG, D. D.	7908210409	50-387 D
VANDENBURGH, D. E.	7908130457	50-309 P
VANDENBURGH, D. E.	7908140443	50-271 F
VANDENBURGH, D.	7908220306	50-271 F
VANDENBURGH, D.	7908230436	50-271 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VANDENBURGH, D.	7908240460	50-29 P
VANDEL, T. E.	7908150628*	50-358 G
VANDEL, T. E.	7908070210*	50-358 G
VANDEL, T. E.	7908150601	50-358 G
VANDEL, T. E.	7908150606*	50-358 G
VANDEL, T. F.	7908230052*	50-358 G
VANDOORN, P. K.	7908270310*	50-413 G
VANHAN, K. V.	7908220609	PR
VANNESS, S. C.	7908220039	50-272 G
VANSICKEL, J.	7908100423*	50-331 S
VANSICKEL, J.	7908150050*	50-331 S
VARACALLE, D. J.	7908020474	RES
VARANINI, E. E.	7908030612	50-312 G
VARELA, A. A.	7908230649*	50-320 G
VARELA, A. A.	7908200054*	50-410 G
VARGA, S. A.	7908170483*	50-482 G
VARGA, S. A.	7908080016	50-320 H
VARGA, S. A.	7908080246	50-471 A
VARGA, S. A.	7908300057	50-338 P
VARGA, S. A.	7908270220	PROJ
VARGA, S. A.	7908300266	50-482 H
VARGA, S. A.	7908220509*	50-320 P
VARGA, S. A.	7908070030	50-458 A
VARGA, S. A.	7908150137	50-466 H
VASSALLO, D. B.	7908300257*	50-367 G
VASSALLO, D. B.	7908090290	GEN TEC IS
VASSALLO, D. B.	7908200321*	50-275 A
VASSALLO, D. B.	7908030292	50-10 P
VASSALLO, D. B.	7908140489	PROJ
VASSALLO, D. B.	7908160040	50-327 A
VASSALLO, D. B.	7908150435	50-382 G
VASSALLO, D. B.	7908150441*	50-382 G
VASSALLO, D. B.	7908150201	50-275 H
VASSALLO, D. B.	7908150260	50-556 A
VASSALLO, D. B.	7908240081*	50-553 A
VASSALLO, D. B.	7908070310	50-341 A
VASSALLO, D. B.	7908030263	50-275 A
VASSALLO, D. B.	7908030581	50-482 H
VASSALLO, D. B.	7908030284	50-367 A
VASSALLO, D. B.	7908060096*	50-275 A
VAUGHAN, R. C.	7908140301	50-201 G
VERDERY, E. H.	7908160465*	50-250 G
VERDERY, E. H.	7908280817*	50-302 G
VERDERY, E. H.	7908200020*	50-335 G
VERDERY, E. H.	7908170202*	50-348 G
VERDERY, E. H.	7908170545*	50-335 G
VETTER, W. E.	7908030055*	50-320 P
VIDUKA, R. V.	7908280227	71-337
VIDUKA, R. V.	7908280230*	71-337
VILLALVA, I.	7908150625	50-320 P
VILLALVA, I.	7908170162	TOPREP
VINCELETTE, M. D.	7908010439*	40-8675
VINCK, W.	7908220415	50-320 P
VIOLET, S. A.	7908080556	50-568 D
VISSING, Q. S.	7908030159	50-346 P
VITO, D. J.	7908140723	50-269 S
VOELZKE, D.	7908290527	50-142 P
VOGLER, B. H.	7908030215	50-346 M
VOGLER, B. H.	7908070008	50-346 M
VOGLER, B. H.	7908020582	PROJ
VOGLER, B. H.	7908070226	PROJ
VOGLER, B. H.	7908300323	PROJ
VOGT, J. F.	7908080368	71-116
VOGT, J. F.	7908140439	70-1207
VOIGHT, H. H.	7908030217	GEN TEC IS
VOIGHT, H. H.	7908150738	50-320 P
VOIGHT, W. R.	7908170236*	ORG
VOLLEN, R. J.	7908030561	50-367 G
VOLLMER, H.	7908030123	50-259 P
VOLLMER, R.	7908030217	GEN TEC IS
VOLLMER, R. H.	7908150738	50-320 P
VON ZELLEN, B. W.	7908130102	50-454 G
VON ZELLEN, B. W.	7908020031*	50-10 P
VORDERBRUEGGEN	7908140397*	50-528 G
VORDERBRUEGGEN	7908150212*	50-397 G
VRUNNER, E. J.	7908200259	50-311 G
WACHTER, L. J.	7908150090*	50-282 G
WACHTER, L. J.	7908070048	50-282 G
WACHTER, L. J.	7908020214*	50-263 P
WACHTER, L. J.	7908080538	50-282 G
WACHTER, L. J.	7908070370	50-263 G
WACHTER, L. J.	7908100160	50-263 G
WACHTER, L. J.	7908140319	50-282 G
WACHTER, L. J.	7908090595	50-282 G
WACHTER, L. J.	7908130407	50-282 G
WACHTER, L. J.	7908240628	50-263 G
WACHTER, L. J.	7908160363	50-282 G
WACHTER, L. J.	7908130444*	50-263 G
WACHTER, L. J.	7908220243*	50-263 G
WACHTER, L. J.	7908270463	50-263 G
WADE, G. E.	7908150687*	TOPREP
WAGNER, A. H.	7908220418*	50-338 G
WAGNER, A. G.	7908070302*	50-364 G
WAITE, R. T.	7908170607	70-1319
WALACHA, E.	7908020381*	50-275 G
WALBRIDGE, W. C.	7908070521	50-312 P
WALKER, R. S.	7908210215	50-320 U
WALKER, R. S.	7908150013	50-463 U
WALKER, R. D.	7908080194*	50-373 G
WALKER, E. A.	7908170520*	70-572
WALL, L.	7908240051	71-338
WALL, L.	7908240055*	71-338
WALLACE, T. J.	7908280600	50-223 J
WALLACE, J. J.	7908140387*	50-305 R
WALLIS, J. R.	7908150466*	50-320 H
WALLIS, J. R.	7908150463*	50-320 H
WALTON, G. A.	7908200060*	50-336 G
WANDKE, N. E.	7908070064*	50-295 F
WANDKE, N. E.	7908140156	50-304 G
WANDKE, N. E.	7908140537	50-295 S
WANDKE, N. E.	7908140551	50-295 S
WANDKE, N. E.	7908140780	50-295 S
WANDKE, N. E.	7908140771	50-304 S
WANDKE, N. E.	7908140810	50-295 S
WANDKE, N. E.	7908140748	50-304 S
WANDKE, N. E.	7908300398	71-9094
WANDKE, N. E.	7908140643	50-295 S
WARD, W. H.	7908150298	50-482 G
WARD, E. C.	7908010554	50-263 R
WARD, E. C.	7908060267	50-282 R
WARD, K. D.	7908100127*	50-305 G
WARD, K. D.	7908100356*	50-305 G
WARD, K. D.	7908030587*	50-295 G
WAREMBOURG, D.	7908080445*	50-267 S
WAREMBOURG, D.	7908010448	50-267 P
WAREMBOURG, D.	7908070500	50-267 S
WAREMBOURG, D.	7908070684	50-267 S
WAREMBOURG, D.	7908130430	50-267 R
WAREMBOURG, D.	7908140597	50-267 P
WAREMBOURG, D.	7908140499	50-267 R
WAREMBOURG, D.	7908140599	50-267 P
WAREMBOURG, D.	7908160337	50-267 R
WAREMBOURG, D.	7908310328	50-267 S
WAREMBOURG, D.	7908310347	50-267 S
WAREMBOURG, D.	7908200392	50-267 S
WAREMBOURG, D.	7908220370	50-267 S
WAREMBOURG, D.	7908240499	50-267 F
WAREMBOURG, D.	7908310320	50-267 S
WAREMBOURG, D.	7908220296	50-267 P
WAREMBOURG, D.	7908310404	50-267 P
WAREMBOURG, D.	7908300529	50-267 S
WARNER, M. R.	7908150712	50-466 G
WARNICK, R. F.	7908160322*	50-346 G
WARNICK, R. F.	7908160130*	50-282 G
WARNICK, R. F.	7908280193*	50-305 G
WARNICK, R. F.	7908290516*	50-305 G
WATANABE, J. T.	7908200332	TOPREP
WATANBE, N.	7908130646*	SECY
WATANBEE, N.	7908090011*	SECY
WATANABE, N.	7908310520	XPORTLIC
WATFORD, M. L.	7908200360*	50-261 R
WATSON, A. P.	7908020379	RES
WATSON, A. P.	7908140584	RES
WEAVER, M. L.	7908270368	71-141
WEAVER, E. A.	7908060098	FOIA
WEBB, R. E.	7908080136	50-272 G
WEBB, R. E.	7908080144*	50-272 G
WEBER, S.	7908290418	50-485 G
WEBER, S.	7908310387	50-410 A
WEBSTER, D. A.	7908100590*	71-18
WEBSTER, E. H.	7908220418*	50-338 G
WEBSTER, E. H.	7908170545*	50-335 G
WEEKS, E. D.	7908210384	50-133 R
WEHMANN, G.	7908140462	NUREG
WEHRLE, R. R.	7908290552	71-9033
WEIGAND, J. G.	7908030010*	50-458 G
WEIGAND, J. G.	7908070238	50-458 G
WEIGAND, J. G.	7908090401	50-458 G
WEIGAND, J. G.	7908090527	50-458 G
WEIGAND, J. G.	7908150099	50-458 G
WEINREB-KUEHM, R.	7908220343	50-466 G
WEISMAN, S. A.	7908080301	50-592 G
WEISS, E. R.	7908080585	FOIA
WEISS, E. R.	7908220243*	50-263 G
WEISS, E. R.	7908270463	50-263 G
WEISS, A. J.	7908070773	TOPREP
WEISS, D.	7908100355	70-364
WEISS, D.	7908130381*	70-143
WEISS, D.	7908130388*	70-364
WEISS, D.	7908010609	40-8434
WEISS, D.	7908010268	70-1113
WEISS, D.	7908010669	70-820
WEISS, D.	7908210603*	70-820
WEISS, D.	7908270136*	70-1151
WEISS, D.	7908150728	70-824
WEISS, D.	7908140137	70-364
WEISS, D.	7908140147	40-8502
WEISS, D.	7908150209*	71-9081
WEISS, D.	7908150140	70-27
WEISS, D.	7908090615	70-364
WEISS, D.	7908210135	70-1100
WEISS, D.	7908150697	70-1143
WELLS, C. E.	7908130299	70-1379
WENNER, S.	7908080273*	50-596 G
WERLING, J. A.	7908030022	50-334 S
WERLING, J. A.	7908010318	50-334 S
WERLING, J. A.	7908010497	50-334 S
WERLING, J. A.	7908010502*	50-334 S
WERLING, J. A.	7908010440	50-334 S
WERLING, J. A.	7908060275	50-334 S
WERLING, J. A.	7908130419	50-334 S
WERLING, J. A.	7908130424*	50-334 S
WERLING, J. A.	7908130426*	50-334 S
WERLING, J. A.	7908130434*	50-334 S
WERLING, J. A.	7908130438*	50-334 S
WERLING, J. A.	7908130442*	50-334 S
WERLING, J. A.	7908130445*	50-334 S
WERLING, J. A.	7908130458	50-334 S
WERLING, J. A.	7908130462*	50-334 S
WERLING, J. A.	7908100449	50-334 S
WERLING, J. A.	7908100451*	50-334 S
WERLING, J. A.	7908140749	50-334 S
WERLING, J. A.	7908140768*	50-334 S
WERLING, J. A.	7908140821	50-334 S
WERLING, J. A.	7908140828*	50-334 S
WERLING, J. A.	7908230430	50-334 S
WERLING, J. A.	7908230435*	50-334 S
WERLING, J. A.	7908230438*	50-334 S
WERLING, J. A.	7908230510	50-334 S
WERLING, J. A.	7908230517*	50-334 S
WERLING, J. A.	7908280422	50-334 S
WERLING, J. A.	7908290461	50-334 S
WERLING, J. A.	7908290472*	50-334 S
WERLING, J. A.	7908290492*	50-334 S
WERNER, L. T.	7908210182	XPORTLIC
WERNER, L. T.	7908210188	XPORTLIC
WERNER, R.	7908090514	50-445 A
WESCOTT, B. M.	7908150628*	50-358 G
WESCOTT, H. M.	7908150606*	50-358 G
WESTERMAN, T. F.	7908020581	50-298 G
WESTERMAN, T. F.	7908090691*	50-313 G
WESTERMAN, T. F.	7908030206*	50-285 G
WESTERMAN, F. F.	7908300069*	50-267 G
WESTERMAN, T. F.	7908020105*	50-285 G
WETMORE, J.	7908310004	50-155 P
WETTERHAHN, M. J.	7908030529	50-272 G
WETTERHAHN, M. J.	7908090419	50-272 P
WETTERHAHN, M. J.	7908220113	50-272 G
WETTERHAHN, M. J.	7908220144*	50-272 G
WETTERHAHN, M. J.	7908080226	50-358 G
WETTERHAHN, M. J.	7908280659	50-311 G
WHEELER, L. W.	7908150437	XPORTLIC
WHEELER, L. W.	7908150444	XPORTLIC
WHITE, C. E.	7908140084	NUREG
WHITE, C. E.	7908140116	NUREG
WHITE, J. R.	7908170500	RES
WHITE, M.	7908130076	50-466 G
WHITE, M.	7908130089	50-466 G
WHITE, J. P.	7908030491*	COMMISSION
WHITE, L. D.	7908090330	50-244 G
WHITE, L. D.	7908080671	50-244 G
WHITE, L. D.	7908070634	50-244 G
WHITE, L. D.	7908070652	50-244 G
WHITE, L. D.	7908010496	50-244 H
WHITE, L. D.	7908010551	50-244 F
WHITE, L. D.	7908010379	50-244 P
WHITE, L. D.	7908230107	50-244 G
WHITE, L. D.	7908290174	50-244 G

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WHITE, L. D.	7908030383	50-244 F
WHITE, L. D.	7908230093	50-244 G
WHITE, L. D.	7908080446*	50-244 P
WHITE, L. D.	7908090511*	50-244 G
WHITE, L. D.	7908100471	50-244 S
WHITE, L. D.	7908140788	50-244 S
WHITE, L. D.	7908140570	50-244 J
WHITE, L. G.	7908200346	50-244 P
WHITE, L. D.	7908170385	50-244 P
WHITE, L. D.	7908210490	50-244 P
WHITE, L. D.	7908210515	50-244 S
WHITE, L. D.	7908210001	50-244 F
WHITE, L. D.	7908280725	50-244 S
WHITE, J. R.	7908010437	RES
WHITENER, H. L.	7908170461*	50-261 G
WHITESELL, D. E.	7908130382*	GA999
WHITESELL, D. E.	7908070120*	71-6698
WHITESELL, D. E.	7908020181*	GA999
WHITESELL, D. E.	7908090188*	GA999
WHITESELL, D. E.	7908200032*	GA999
WHITESELL, D. E.	7908080014*	GA999
WHITESELL, D. E.	7908080003*	GA999
WHITMER, C. F.	7908240442	50-424 A
WHITMER, C. F.	7908240446*	50-424 A
WIDNER, W. A.	7908230669	50-321 G
WIDNER, W. A.	7908160031	50-366 G
WIDNER, W. A.	7908160310	50-321 G
WIDNER, W. A.	7908220684	50-321 G
WIEDERHOLD, P. R.	7908220073*	COMMISSION
WIGGINS, E.	7908140374	CONTRACT
WIGGINS, E.	7908160543	CONTRACT
WIGGINS, E.	7908160328	CONTRACT
WIGGINS, E.	7908160377	CONTRACT
WIGGINS, E.	7908160393	CONTRACT
WIGGINS, E.	7908170066	CONTRACT
WIGGINS, E.	7908160389	CONTRACT
WIGGINS, E.	7908160383	CONTRACT
WIGGINS, E.	7908150397	CONTRACT
WIGGINTON, D.	7908030327	50-316 G
WIGGINTON, D. L.	7908210178	50-334 G
WILBORN, L.	7908240172*	40-8102
WILBURN, L.	7908020201*	40-4492
WILCOX, K.	7908080709	PROJ
WILCOX, J. D.	7908240168*	50-281 G
WILCOX, J. D.	7908030584*	50-250 G
WILEY, P. J.	7908030481*	50-409 S
WILKINS, T. D.	7908170434*	70-1151
WILLIAMSON, M.	7908010684	50-338 Q
WILLIAMS, F. S.	7908100016	REGGD
WILLIAMS, R. E.	7908010173	PROJ
WILLIAMS, A. W.	7908010575	50-502 G
WILLIAMS, C. E.	7908140297	71-9023
WILLIAMS, J.	7908140834*	FOIA
WILLIAMS, E. F.	7908140355*	AGREEMENT
WILLIAMS, C. F.	7908210113	50-320 P
WILLIAMS, C. E.	7908280853	71-9134
WILLIS, E.	[illegible]900356*	50-324 R
WILLIAMS, C. C.	7 390071*	50-331 S
WILLIAMS, C. C.	[illegible]8150370*	50-358 G
WILLIAMS, C. C.	7908080737*	50-546 G
WILLIAMS, C. C.	7908170246*	50-440 Q
WILLIAMS, C. C.	7908170179*	50-373 Q
WILLIAMS, F. J.	7908290368	50-320 G
WILLIAMS, P. M.	7908280801	50-163 P
WILLIAMS, F. J.	7908150656	50-320 P
WILLSEY, W. B.	7908020431	50-277 R
WILLSEY, W. B.	7908020436*	50-277 R
WILSON, R.	7908240494*	COMMISSION
WILSON, W. E.	7908140712	50-27 R
WILSON, W. R.	7908140386	50-498 M
WILSON, W. R.	7908170336	50-498 M
WILSON, B. D.	7908090589*	SECY
WILSON, B. D.	7908080748	XPORTLIC
WILSON, B. D.	7908020380	XPORTLIC
WILSON, B. D.	7908150152	XPORTLIC
WILSON, B. D.	7908240551*	SECY
WILSON, B. D.	7908090561*	SECY
WILSON, B. D.	7908090570*	SECY
WILSON, B. D.	7908140272	XPORTLIC
WILSON, B. D.	7908080024	XPORTLIC
WILSON, R.	7908280632	50-320 T
WILSON, J.	7908060243	50-280 G
WILSON, J. N.	7908160029	50-546 A
WINGET, R. H.	7908220541	71-200
WINTERS, T. L.	7908080263*	50-522 G
WISLA, S. F.	7908020166	71-6574
WISLA, S. F.	7908020189	71-6144
WITHERS, B. D.	7908140790	50-344 S
WITHERS, B. D.	7908080469	50-344 R
WITHERS, B. D.	7908130387	50-344 S
WOHLSEN, A. B.	7908230455*	50-320 H
WOLFE, S. J.	7908020224	50-437 Q
WOLFE, S. J.	7908070736	50-382 Q
WOLFE, S. J.	7908220365	50-466 Q
WOLFE, S. J.	7908220368	50-466 Q
WOLFF, T. A.	7908200398	PROJ
WOLFF, T. A.	7908200399*	PROJ
WOLLETT, S. A.	7908080431	CONTRACT
WOLLETT, S. A.	7908290712	CONTRACT
WOLLETT, S. A.	7908290638	CONTRACT
WOLLETT, S. A.	7908010202	CONTRACT
WOLLETT, S.	7908010213	CONTRACT
WOLLETT, S. A.	7908100302	CONTRACT
WOLLETT, S. A.	7908100300	CONTRACT
WONG, T.	7908130586	40-299
WONG, T.	7908210407	40-299
WOO, C. W.	7908240119	NUREG
WOOD, L. O.	7908170281	XPORTLIC
WOOD, E. C.	7908010561	50-309 S
WOOD, E. C.	7908030248	50-309 S
WOOD, R. S.	7908100408	NUREG
WOODFORD, J. V.	7908060403*	50-278 P
WOODHEAD, C. P.	7905240754	50-510 Q
WOODHEAD, C. P.	7908080664	50-409 Q
WOODHEAD, C. P.	7908080065	50-510 Q
WOODLAND, I. F.	7908090016	PROJ
WOODRUFF, R. L.	7907160257	50-320 H
WOODS, B.	7908010582	REGGD
WOODS, P. D.	7908070185*	GA999
WOODS, P. D.	7908070182*	GA999
WOODS, P. D.	7908070171*	GA999
WOOLEVER, E. J.	7908030178	50-412 Q
WOOLEVER, E. J.	7908070753	50-412 Q
WOOLEVER, E. J.	7908070812	50-334 Q
WOOLEVER, E. J.	7908200009	50-412 Q
WOOLEVER, E. J.	7908150669	50-412 A
WOOLEVER, E. J.	7908160438	50-412 S
WOOLF, S. W.	7908200289	50-424 Q
WORSHAM, J. I.	7908130188	50-445 M
WORSHAM, J. I.	7908130201*	50-445 M
WORZEWSKI, W.	7908090256	71-6291
WRAY, J. R.	7908160327*	50-321 Q
WRIGHT, R. L.	7908100400	50-287 P
WRIGHT, R. W.	7908290138*	50-438 Q
WRINKLE, H. H.	7908220559*	50-312 H
WRINKLE, H. H.	7908300273*	50-312 H
WRINKLE, H. H.	7908220572*	50-312 H
WRINKLE, H. H.	7908300263*	50-312 H
WULLER, G. E.	7908020318	50-461 Q
WULLER, G. E.	7908070747	50-461 Q
WULLER, G. E.	7908290361	50-461 Q
WULLER, G. E.	7908150458	50-461 Q
YAGER, D.	7908150287*	50-275 H
YAMAZAKI, M.	7908160320	XPORTLIC
YBARRONDO, L. J.	7908010563	RES
YEAGER, L. L.	7908020266	RES
YELLIN, J.	7908290167*	REGGD
YORE, J. R.	7908080599*	10CFR
YOUNGBLOOD, J. A.	7908010478	50-592 C
YOUNGDAHL, R. C.	7908090354*	50-255 P
YOUNG, R. H.	7908070579*	50-245 S
YOUNG, R. H.	7908160413*	50-245 S
YOUNG, R. H.	7908210552*	50-245 R
YOUNG, R. H.	7908160477*	50-245 S
YOUNG, T.	7908270011*	50-275 Q
YUHAS, G. P.	7906210434	50-320 P
YUHAS, G. P.	7908290587	50-320 T
YUHAS, G. P.	7908290645	50-320 T
YUHAS, G. P.	7908290721	50-320 T
YUHAS, G. P.	7908300039	50-320 T
YUHAS, G. P.	7908300052	50-320 T
YUHAS, G. P.	7908300075	50-320 T
YUHAS, G. P.	7908290709	50-320 T
YUHAS, G. P.	7908290729	50-320 T
YUHAS, G. P.	7908300043	50-320 T
YUHAS, G. P.	7908300071	50-320 T
YUHAS, G. P.	7908290574	50-320 T
YUHAS, G. P.	7908300265	50-320 T
YUHAS, G. P.	7908290524	50-320 T
YUHAS, G. P.	7908290550	50-320 T
YUHAS, G. P.	7908300160	50-320 T
YUHAS, G. P.	7908290093	50-320 T
YUHAS, G. P.	7908280688	50-320 T
YUHAS, G. P.	7908290453	50-320 T
YUHAS, G. P.	7908290593	50-320 T
YUHAS, G. P.	7908290692	50-320 T
YUHAS, G. P.	7908280657	50-320 T
YUHAS, G. P.	7908280775	50-320 T
YUHAS, G. P.	7908300247	50-320 T
YUHAS, G. P.	7908280733	50-320 T
YUHAS, G. P.	7908280799	50-320 T
YUHAS, G. P.	7908280807	50-320 T
YUHAS, G. P.	7908280860	50-320 T
YUHAS, G. P.	7908290232	50-320 T
YUHAS, G. P.	7908290179	50-320 T
YUHAS, G. P.	7908290264	50-320 T
YUHAS, G. P.	7908290316	50-320 T
YUHAS, G. P.	7908290320	50-320 T
YUHAS, G. P.	7908280783	50-320 T
YUHAS, G. P.	7908280856	50-320 T
YUHAS, G. P.	7908290245	50-320 T
YUHAS, G. P.	7908280766	50-320 T
YUSPEH, A. R.	7908080029	50-387 Q
ZAFFIRO, C.	7908220408	50-320 P
ZALPPELLINI, G.	7908170469*	FOIA
ZARAKAS, P.	7908020596	50-247 Q
ZARAKAS, P.	7908080507	50-247 Q
ZARAKAS, P.	7908070198	50-3 Q
ZARAKAS, P.	7908220391	50-3 R
ZARAKAS, P.	7908210015	50-3 F
ZARSKY, L.	7908290367*	50-574 Q
ZAVADOSKI, R. W.	7908280123*	50-338 Q
ZEFF, D. W.	7908130530	70-1201
ZEFF, D. W.	7908290538	71-5768
ZEFF, D. W.	7908220496	70-1201
ZEFF, D. W.	7908290623	70-1201
ZELLER, H. D.	7908220268	50-327 A
ZIEMANN, D. L.	7908130647	50-255 P
ZIEMANN, D. L.	7908100211	50-219 P
ZIEMANN, D. L.	7908100214*	50-219 P
ZIEMANN, D. L.	7908100223*	50-219 P
ZIEMANN, D. L.	7908070822	50-206 P
ZIEMANN, D. L.	7908070827*	50-206 P
ZIEMANN, D. L.	7908070832*	50-206 P
ZIEMANN, D. L.	7908060688	50-155 P
ZIEMANN, D. L.	7908230104	50-29 F
ZIEMANN, D. L.	7908080064	50-219 P
ZIEMANN, D. L.	7908080682	50-255 P
ZIEMANN, D. L.	7908090012	50-255 P
ZIEMANN, D. L.	7908080081	50-244 P
ZIEMANN, D. L.	7908080129	50-155 E
ZIEMANN, D. L.	7908160096	50-409 P
ZIEMANN, D. L.	7908090648	50-245 P
ZIEMANN, D. L.	7908160050	50-237 P
ZIEMANN, D. L.	7908160057	50-245 P
ZIEMANN, D. L.	7908280569	50-219 P
ZIEMANN, D. L.	7908020034	50-219 P
ZIEMANN, D. L.	7908160092	50-10 P
ZIEMANN, D. L.	7908160303	50-409 P
ZIEMANN, D. L.	7908160335	50-155 P
ZIEMANN, D. L.	7908280154	50-155 P
ZIEMANN, D. L.	7908280580	50-245 P
ZIEMANN, D. L.	7908160210	50-206 P
ZIEMANN, D. L.	7908160216*	50-206 P
ZIEMANN, D. L.	7908160226*	50-206 P
ZIEMANN, D. L.	7908160367	50-10 P
ZIEMANN, D. L.	7908170076	50-245 P
ZIEMANN, D. L.	7908170086*	50-245 P
ZIEMANN, D. L.	7908170090	50-206 P
ZIEMANN, D. L.	7908170092*	50-206 P
ZIEMANN, D. L.	7908170097*	50-206 P
ZIEMANN, D. L.	7908080295	50-155 Q
ZIEMANN, D. L.	7908080299	50-409 Q
ZIEMANN, D. L.	7908080300	50-219 Q
ZIEMANN, D. L.	7908160161	50-219 P
ZIEMANN, D. L.	7908160169*	50-219 P
ZIEMANN, D. L.	7908160189*	50-219 P
ZIEMANN, D. L.	7908170193	50-206 P
ZIEMANN, D. L.	7908170196	50-244 P
ZIEMANN, D. L.	7908170201	50-29 P
ZIEMANN, D. L.	7908170210	50-213 P
ZIEMANN, D. L.	7908220529	50-213 P
ZIEMANN, D. L.	7908160329	50-255 Q
ZIEMANN, D. L.	7908080222	50-29 P
ZIEMANN, D. L.	7908170095	50-155 P
ZIEMANN, D. L.	7908170098*	50-155 P
ZIEMANN, D. L.	7908170106*	50-155 P
ZIEMANN, D. L.	7908230070	50-244 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
ZIEMANN, D. L.	7908230072*	50-244	P
ZIEMANN, D. L.	7908230076*	50-244	P
ZIEMANN, D. L.	7908100157	50-409	P
ZIEMANN, D. L.	7908100165*	50-409	P
ZIEMANN, D. L.	7908220523	50-244	P
ZIEMANN, D. L.	7908230646	50-255	P
ZIEMANN, D. L.	7908230654*	50-255	P
ZIEMANN, D. L.	7908300776	50-409	P
ZIEMANN, D. L.	7908170088	50-29	P
ZIEMANN, D. L.	7908170198	50-206	P
ZIEMANN, D. L.	7908230246	50-409	P
ZIEMANN, D. L.	7908290114	50-409	P
ZIEMANN, D. L.	7908200176	50-244	P
ZIEMANN, D. L.	7908230676	50-10	P
ZIEMANN, D. L.	7908300620	50-219	P
ZIEMANN, D. L.	7908300621*	50-219	P
ZIEMANN, D. L.	7908300634*	50-219	P
ZIEMANN, D. L.	7908300780	50-206	G
ZIEMANN, D. L.	7908300782	50-29	G
ZIEMANN, D. L.	7908210033	50-219	F
ZIEMANN, D. L.	7908210068	50-155	P
ZIEMANN, D. L.	7908210165	50-155	P
ZIEMANN, D. L.	7908030355	50-219	P
ZIEMANN, D. L.	7908030571	50-255	P
ZIEMANN, D. L.	7908030617	50-245	P
ZIMMERMANN, F. L.	7908140116	NUREG	
ZIMMERMAN, J. C.	7908130420*	50-331	S
ZIMMER, G. A.	7908010579	RES	
ZIMMERMAN, R. P.	7908280225*	50-311	G
ZIMMERMAN, R. P.	7908130660*	50-29	G
ZIMMERMAN, R. P.	7908200268*	50-311	G
ZINN, P. K.	7908020241*	50-280	U
ZITTEL, H. E.	7908010472	RES	
ZITTEL, H. E.	7908030244	RES	
ZITTEL, H. E.	7908140568	RES	
ZITTEL, H. E.	7908140575	RES	
ZITZER, P.	7908300050	50-272	G
ZU'BI, S. M.	7908080577*	70-2684	
ZUBER, N.	7908010314	REVIEW GRP	
ZUBER, N.	7908300591	REVIEW GRP	
ZUFELT, E.	7908070599*	50-333	R

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index titled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
3M Co., Minnesota Mining & Mfg. Co.	7908310064*	40-8305
AMCO International, Inc.	7908150143	XPORTLIC
Accuracy in Media	7908310043	FOIA
Acton Environ. Testing Corp.	7908080579*	50-390 A
Advisory Council on Historic Preservation	7908060050*	NUREG
Aerospace Corp.	7908230469	50-320 P
Agriculture, Dept. of	7908150025	71-238
	7908150030*	71-238
	7908210409	50-387 D
	7908270410	50-387 A
Air Products & Chemicals, Inc.	7908020368	XPORTLIC
Akin, Gump, Hauer & Feld	7908220094	50-445 M
Alabama Power Co.	7908010380	50-348 P
	7908010543	50-348 S
	7908010547*	50-348 S
	7908010550*	50-348 S
	7908020389	50-348 G
	7908020429	50-348 P
	7908020466	50-348 H
	7908030507	50-348 G
	7908070284*	50-364 Q
	7908070485	50-348 S
	7908070492*	50-348 S
	7908070817	50-348 G
	7908080240	50-348 G
	7908140543	50-348 R
	7908140546*	50-348 R
	7908140569	50-348 P
	7908140662	50-348 S
	7908140673*	50-348 S
	7908140733	50-348 S
	7908140745*	50-348 S
	7908160424	50-348 H
	7908160476*	50-348 G
	7908200311	50-348 S
	7908200315*	50-348 S
	7908200327	50-348 F
	7908230309	50-348 G
	7908230664	50-348 G
	7908280780	50-348 P
	7908280785	50-348 P
Alabama, State of	7908220566	PROJ
Albert Einstein Medical Center	7908240068*	40-8002
	7908240113*	40-8002
Allied General Nuclear Services	7908130393	50-332 G
	7908300401	71-5026
Allied Inspection Services, Inc.	7908280487	71-330
	7908280492*	71-330
Allis-Chalmers Corp.	7908060287	50-312 A
American Civil Liberties Union	7908160416	FOIA
American Electric Power Co., Inc.	7908140526*	FOIA
	7908160193*	50-315 G
American Friends Service Committee	7908170609	FOIA
American Geophysical Union	7908150463*	50-320 H
American Nuclear Insurers	7908010491	50-320 J
	7908170607	70-1319
	7908210440	50-219 J
	7908220289	50-320 J
American Society of Mechanical Engineers	7908010664	REGOD
	7908010673	REGOD
	7908160452*	50-410 A
Americans for Nuclear Energy	7908090178	FOIA
Amoco Corp.	7908010671	71-128
Amstar Corp., Enviro Clear	7908070831	PROJ
Anti-Nuclear Group Representing York	7908210400	50-320 Q
	7908210404*	50-320 Q
Argonne National Laboratory	7908010152	PROJ
	7908010516	RES
	7908080205*	ORG
	7908140198	PROJ
	7908140689*	50-522 Q
	7908200196	71-9033
	7908200202	71-6058
	7908270077	NUREG
Arizona Public Service Co.	7908140375*	50-528 Q
	7908150034	50-592 R
Arizona, State of	7908010478	50-592 C
	7908140832*	FOIA
	7908140834*	FOIA
	7908140836*	FOIA
	7908240404*	COMMISSION
Arizona, Univ. of	7908170306	ACRS
	7908230667	NUREG
Arkansas Power & Light Co.	7908010038	50-313 P
	7908010461	50-313 P
	7908020424	50-368 S
	7908020430	50-313 R
	7908020449	50-313 S
	7908020459*	50-313 S
	7908020473*	50-313 S
	7908020476	50-313 P
	7908020484	50-368 S
	7908020492*	50-368 S
	7908030111	50-313 Q
	7908060468	50-368 S
	7908060472*	50-368 S
	7908060475*	50-368 S
	7908060480*	50-368 S
	7908060482*	50-368 S
	7908060487*	50-368 S
	7908070537	50-368 S
	7908070551*	50-368 S
	7908070576*	50-368 S
	7908070592*	50-368 S
	7908070605*	50-368 S
	7908070623*	50-368 S
	7908080157	50-368 Q
	7908080456*	50-313 Q
	7908080491	50-368 Q
	7908080495	50-313 S
	7908080496	50-368 S
	7908080502	50-313 S
	7908080511*	50-313 S
	7908090275*	50-313 Q
	7908090580	50-313 H
	7908100254	50-368 P
	7908100320	50-313 P
	7908140186*	50-368 Q
	7908140580	50-368 Q
	7908150493	50-313 P
	7908150493	50-313 P
	7908150493	50-313 P
	7908150512	50-313 P
	7908150512	50-313 P
	7908150514	50-313 R
	7908150542	50-313 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908150542	50-313 P
	7908160009	50-368 Q
	7908160021	50-313 Q
	7908160021	50-313 Q
	7908160025	50-313 Q
	7908160025	50-313 Q
	7908160028	50-313 Q
	7908160459	50-313 Q
	7908170371	50-313 Q
	7908170538	50-313 P
	7908170538	50-313 P
	7908200305	50-368 S
	7908200308*	50-368 S
	7908230370	50-313 R
	7908230371*	50-313 R
	7908230372	50-368 R
	7908230373*	50-368 R
	7908230394	50-313 F
	7908280656	50-368 P
	7908280757	50-313 P
	7908290419	50-368 P
	7908290420	50-313 P
	7908290512	50-313 R
	7908290517*	50-313 R
	7908300569	50-313 S
	7908300571*	50-313 S
	7908300670	50-313 P
	7908310[illegible]	50-313 S
	7908310386	50-313 S
	7908310393*	50-313 S
Army, Dept. of	7908020126	71-6639
	7908100457	50-170 P
	7908100479	50-170 S
	7908100483*	50-170 S
	7908100493	50-170 P
	7908170537*	50-482 Q
Army, Dept. of, Corps of Engineers	7908010370	50-395 D
	7908090031	REGGD
	7908300597	50-482 A
Arnold & Porter	7908170346*	50-329 Q
Asher, T. R. PC	7908160300*	50-574 A
Association of Community Organizations for Reform Now-IA	7908300543*	50-599 Q
Atlas Minerals	7908010627	40-3453
	7908090473	40-3453
	7908090481*	40-3453
	7908280706	40-3453
Austin, TX	7908200068	50-445 M
Australia	7908020487	XPORTLIC
	7908210159	50-574 A
Automation Industries, Inc.	7908150522	71-264
	7908150527*	71-264
Babcock & Wilcox Co.	7908010649	TOPREP
	7908010660*	TOPREP
	7908020158	71-9033
	7908020508	TOPREP
	7908020516*	TOPREP
	7908030619*	50-346 Q
	7908060222	50-99 P
	7908070588	TOPREP
	7908070597*	TOPREP
	7908080461	TOPREP
	7908080468	TOPREP
	7908080481	TOPREP
	7908090582	70-135
	7908090582	70-135
	7908090587	TOPREP
	7908090590*	70-135
	7908090590*	70-135
	7908090592*	TOPREP
	7908100287*	50-269 P
	7908100561	70-824
	7908130383*	70-143
	7908130384	70-364
	7908130385*	70-364
	7908130530	70-1201
	7908130620	70-135
	7908140095	70-135
	7908140135	70-27
	7908140312	70-135
	7908140316	70-27
	7908140398	TOPREP
	7908150275	70-135
	7908170316	TOPREP
	7908170319*	TOPREP
	7908170624	70-27

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908210296	TOPREP
	7908210299*	TOPREP
	7908210475	50-320 F
	7908210600	70-27
	7908210601*	70-27
	7908220098	TOPREP
	7908220300	70-364
	7908220342	TOPREP
	7908220493	70-1201
	7908240363	TOPREP
	7908240375	70-135
	7908240381	70-364
	7908240392	70-27
	7908240400	TOPREP
	7908240632	TOPREP
	7908280751	71-5950
	7908290166	REGGD
	7908290538	71-5768
	7908290623	70-1201
	7908310410	50-13 P
Babcock & Wilcox Operating Plants Owners Group	7908020443*	50-346 P
Baker & Botts	7908080075	50-466 Q
	7908080079	50-466 Q
	7908080092	50-466 Q
	7908220304	50-466 Q
	7908220312	50-466 Q
	7908220315	50-466 Q
Balough, R. C.	7908080058	50-70 Q
Baltimore Gas & Electric Co.	7908010535	50-317 I
	7908020228	50-317 Q
	7908020585	50-317 Q
	7908070665	50-317 Q
	7908070678	50-317 S
	7908070806	50-317 Q
	7908070844	50-317 Q
	7908070844	50-317 Q
	7908080450	50-318 S
	7908080457*	50-318 S
	7908080498	50-317 P
	7908080509	50-317 S
	7908080512*	50-317 S
	7908080534	50-317 P
	7908080534	50-317 P
	7908100205	50-317 F
	7908100410	50-317 F
	7908100410	50-317 F
	7908100486	50-317 S
	7908100491*	50-317 S
	7908100500	50-317 S
	7908100503*	50-317 S
	7908140688	50-317 F
	7908140698	50-317 F
	7908170313	50-317 Q
	7908170313	50-317 Q
	7908200108	50-317 Q
	7908200108	50-317 Q
	7908200200	50-317 F
	7908200200	50-317 F
	7908200328	50-317 S
	7908200333*	50-317 S
	7908210280	50-317 E
	7908210290	50-317 E
	7908220385	50-317 S
	7908220389*	50-317 S
	7908230344	50-317 R
	7908230344	50-317 R
	7908230349*	50-317 R
	7908230349*	50-317 R
	7908230361	50-317 S
	7908230366*	50-317 S
	7908230383	50-317 S
	7908230386*	50-317 S
	7908230500	50-318 S
	7908230513*	50-318 S
	7908230518	50-317 S
	7908230518	50-317 S
	7908230530*	50-317 S
	7908270476	50-318 S
	7908270478	50-317 S
	7908270484*	50-317 S
	7908270485*	50-318 S
	7908280554	50-317 Q
	7908280620	50-317 S
	7908280626*	50-317 S
	7908280628	50-317 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908280639*	50-317 S
	7908280675	50-317 S
	7908280682*	50-317 S
	7908290711	50-317 Q
	7908300474	50-318 P
	7908300624	50-317 S
	7908310396	50-317 F
Barry, David N. III	7908090016	PROJ
Battelle Memorial Institute, Columbus Laboratories	7908020179	71-6144
	7908020239	RES
	7908080557	RES
	7908150551	71-6357
	7908160172	RES
	7908160188*	RES
	7908200199	71-9081
	7908210186	50-320 A
	7908210193*	50-320 A
	7908210556	70-8
	7908240344	70-8
	7908270342	RES
Battelle Memorial Institute, Pacific Northwest Laboratory	7908010342	RES
	7908020317	RES
	7908020454	RES
	7908030452*	50-269 P
	7908030452*	50-269 P
	7908030452*	50-269 P
	7908030462*	50-269 P
	7908030462*	50-287 P
	7908030462*	50-269 P
	7908030462*	50-269 P
	7908030488*	50-369 A
	7908030513	70-984
	7908030523*	70-984
	7908030533*	70-984
	7908090530	NUREG
	7908140659	RES
	7908150475*	ORO
	7908170302	ACRS
	7908210115	ACRS
	7908230122	70-984
	7908230126*	70-984
	7908230686	NUREG
	7908230692	NUREG
	7908240056	NUREG
Baystate Medical Center MA/BP	7908080577*	70-2684
Bear Creek Uranium Co.	7908010322	40-8452
	7908010331*	40-8452
Bechtel Associates Professional Corp.	7908140366*	50-329 S
Bechtel Power Corp. (subs. of Bechtel Corp.)	7908030118*	50-313 Q
	7908060410*	50-329 S
	7908080352*	50-482 Q
	7908090634*	50-329 Q
	7908170558*	50-329 Q
	7908220639*	GA999
	7908230443	TOPREP
Bergen-Patterson Pipe	7908130220*	GA999
Bethlehem Steel Corp.	7908290598	71-9033
Beveridge, Fairbanks, & Diamond	7908240219	FOIA
Biotronic Sales, Inc.	7908090256	71-6291
Bisco, Brand Industrial Svcs. Inc.	7908210357*	50-309 P
Blum & Shelley	7908240170	70-2623
Boeing Co.	7908230105	XPORTLIC
	7908230109*	XPORTLIC
Borg Warner Corp., Byron Jackson Pump Div.	7908200026*	GA999
Boston Edison Co.	7908010309	50-293 S
	7908010444	50-293 Q
	7908020416	50-293 S
	7908030236	50-293 Q
	7908060238	50-471 F
	7908070702	50-293 Q
	7908080004	50-471 Q
	7908080397	50-293 S
	7908080398*	50-293 S
	7908080510	50-293 P
	7908090445	50-471 F
	7908100128	50-293 P
	7908100565	71-6601
	7908100568	71-9113
	7908100574	71-5026
	7908130363	50-293 S
	7908130443	50-471 A
	7908170418	50-293 S
	7908170423*	50-293 S
	7908200204	50-293 F
	7908200231	50-293 R
	7908200233*	50-293 R
	7908210424	REGOD
	7908220648	50-293 Q
	7908270454	50-293 P
	7908280035	50-471 F
	7908280526	50-293 S
	7908280533*	50-293 S
	7908280539	50-293 P
	7908280592	50-293 Q
	7908290413	50-293 R
	7908290415*	50-293 R
	7908290480	50-471 A
Brand Industrial Services, Inc.	7908270369*	50-344 P
	7908270374*	50-344 P
	7908270378*	50-344 P
Brazos Electric Power Cooperative, Inc.	7908030450*	50-445 M
Broad Top Bulletin BA, Pennsylvania	7908160044	50-146 H
Brookhaven National Laboratory	7908010555	RES
	7908010579	RES
	7908010591	RES
	7908020152	RES
	7908020275	RES
	7908020283	RES
	7908020292	RES
	7908020362	RES
	7908020372	RES
	7908020519	50-213 E
	7908020600	RES
	7908070773	NUREG
	7908100185*	50-409 P
	7908130212*	70-754
	7908140005	TOPREP
	7908140339	RES
	7908230008	50-320 P
Brooklyn, NY	7908280308*	COMMISSION
Brown & Bettencourt	7908090140	FOIA
Brown & Root Corp. (subs. of Halliburton Corp.)	7908070553	TOPREP
	7908070677	TOPREP
C-E Operating Plants Owners Group	7907250388	TOPREP
	7908090491	TOPREP
	7908100458	50-255 P
C-E Power Systems	7908070777	70-1100
	7908070782*	70-1100
	7908090549	TOPREP
	7908090555*	TOPREP
	7908140165	70-1100
	7908140222	70-36
	7908150221	70-1100
	7908150603	50-470 K
	7908150612*	50-470 K
	7908170428	50-255 P
	7908210380	70-36
	7908210538	TOPREP
	7908220285	70-1100
	7908220293*	70-1100
	7908230240	70-1100
	7908290463	TOPREP
	7908290697	TOPREP
	7908290707*	TOPREP
C. F. Braun & Co.	7908100238	TOPREP
	7908280550	TOPREP
CBI Nuclear Co.	7908090004*	50-354 Q
California, State of	7908030612	50-312 Q
	7908080301	50-592 Q
	7908090505*	COMMISSION
	7908100568	PROJ
	7908240482*	50-70 P
	7908300421	50-18 P
	7908300433*	50-18 P
California, Univ. of, Berkeley	7908060359	50-224 P
California, Univ. of, Irvine	7908130428	50-326 R
	7908130429*	50-326 R
California, Univ. of, Santa Barbara	7908080745	FOIA
Calumet Testing Services, Inc.	7908280227	71-337
	7908280230*	71-337
Cammer & Shapiro	7908300393	50-322 Q
	7908300403*	50-322 Q
Canada	7908170331	50-522 Q
	7908170331	50-522 Q
	7908230248	50-522 Q
	7908230248	50-522 Q
	7908300517	50-522 Q
Canada, Atomic Energy Control Board	7908220097	50-320 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Carolina Environmental Study Group	7908310535	70-2623
Carolina Power & Light Co.	7908010269	50-261 H
	7908020441	50-324 S
	7908030312	50-325 S
	7908030313*	50-325 S
	7908030415	50-324 S
	7908030423*	50-324 S
	7908030492	50-324 S
	7908030498*	50-324 S
	7908060006	50-324 G
	7908060263	50-400 R
	7908060326	50-324 G
	7908060335	50-261 S
	7908060398	50-324 S
	7908060415*	50-324 S
	7908060457	50-261 P
	7908060466	50-325 S
	7908060501*	50-325 S
	7908060522	50-325 S
	7908060540	50-325 S
	7908060543*	50-325 S
	7908060545*	50-325 S
	7908070133*	50-261 G
	7908070530	50-400 A
	7908070821	50-400 G
	7908080135	50-324 G
	7908080135	50-324 G
	7908[illegible]0412	50-261 G
	7908090573	50-400 G
	7908090575	50-400 G
	7908090375	50-400 G
	7908090575	50-400 G
	7908100163	50-261 F
	7908100163	50-261 F
	7908100389	50-400 S
	7908100391*	50-400 S
	7908130295	50-261 G
	7908130357	50-261 P
	7908140302	50-400 G
	7908140693	50-324 S
	7908140700*	50-324 S
	7908150671	50-324 S
	7908150680*	50-324 S
	7908160100	50-261 P
	7908160100	50-261 P
	7908160142	50-261 G
	7908160351	50-400 G
	7908160351	50-400 G
	7908160351	50-400 G
	7908160351	50-400 G
	7908160356	50-261 G
	7908160369	50-261 G
	7908170055	50-400 G
	7908170055	50-400 G
	7908170055	50-400 G
	7908170055	50-400 G
	7908170062	50-261 G
	7908170121	50-324 G
	7908170121	50-324 G
	7908170493	PROJ
	7908200209	50-400 G
	7908200209	50-400 G
	7908200209	50-400 G
	7908200209	50-400 G
	7908200296	50-325 S
	7908200299*	50-325 S
	7908200303	50-324 S
	7908200306*	50-324 S
	7908200353	50-324 R
	7908200356*	50-324 R
	7908200356*	50-324 R
	7908200359	50-261 R
	7908200360*	50-261 R
	7908200[illegible]23	50-324 H
	7908200383	50-324 H
	7908210385	50-324 S
	7908210399*	50-324 S
	7908210419	50-261 S
	7908210422*	50-261 S
	7908210432	50-324 S
	7908210434*	50-324 S
	7908230379	50-325 S
	7908230380*	50-325 S
	7908230381	50-324 S
	7908230382*	50-324 S
	7908230399	50-261 F
	7908230399	50-261 F
	7908230399	50-261 F
	7908230400	50-324 S
	7908230404*	50-324 S
	7908230428	50-324 R
	7908230428	50-324 R
	7908230450	50-324 S
	7908230459*	50-324 S
	7908230537	50-325 S
	7908230547*	50-325 S
	7908230556	50-324 S
	7908230561*	50-324 S
	7908230585	50-261 G
	7908230608	50-324 G
	7908230608	50-324 G
	7908240057	50-324 P
	7908240401	50-325 S
	7908240406*	50-325 S
	7908240408	50-325 S
	7908240412*	50-325 S
	7908240457	50-324 S
	7908240462*	50-324 S
	7908240478	71-345
	7908270432	50-324 S
	7908270441*	50-324 S
	7908270446	50-261 P
	7908270446	50-261 P
	7908270446	50-261 P
	7908280561	50-324 P
	7908290388	50-261 J
	7908290436	50-261 S
	7908290449*	50-261 S
	7908290505	50-325 S
	7908290514*	50-325 S
	7908290548	50-324 S
	7908290563*	50-324 S
	7908290566	50-324 P
	7908290566	50-324 P
	7908290631	50-400 G
	7908300575	50-400 G
	7908300588	50-324 G
	7908300588	50-324 G
	7908300590	50-324 G
	7908300655	50-261 S
	7908300663*	50-261 S
	7908300689	50-324 S
	7908300700*	50-324 S
	7908310421	50-261 P
	7908310449	50-325 S
	7908310459*	50-325 S
Carpenter Technology Corp.	7908140664	XPORTLIC
	7908140669*	XPORTLIC
Carson Nondestructive Testing	7908030200	71-288
Center for Development Policy	7908030449	FOIA
Center for Law in the Public Interest	7908150035*	FOIA
	7908150046*	FOIA
	7908160307	FOIA
Central Michigan Univ.	7908170575	70-597
Chem-Nuclear Systems, Inc.	7908010612	71-6601
	7908020117	71-6144
	7908130049	71-6601
	7908140146	71-9081
	7908140475	71-9111
	7908150204	71-9081
	7908150215*	71-9081
	7908150219*	71-9081
	7908170181	27-47
	7908200007	27-47
	7908200074	71-231
	7908200210	TOPREP
	7908200211*	TOPREP
	7908290607	71-6601
Chicago Bridge & Iron Co.	7908020338*	50-461 G
	7908090576*	50-316 G
	7908220551	71-9033
	7908290552	71-9033
Cincinnati Gas & Electric Co.	7908030303	50-358 A
	7908030567*	50-358 G
	7908130047	50-358 G
	7908230128*	50-358 G
	7908230164*	50-358 G
	7908230186*	50-358 G
	7908230192*	50-358 G
	7908230197*	50-358 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908230202*	50-358 Q
	7908230330	50-358 A
	7908270556	50-358 Q
	7908290368	50-358 Q
	7908310448	70-2838
Citizens Against Nuclear Dangers	7906260390	50-387 Q
	7908020578*	50-387 Q
	7908230488	50-387 D
	7908300756	50-387 Q
Citizens Against Nuclear Power	7908170068	50-373 A
Citizens Committee for Protection of the Environment	7908160114*	50-3 Q
Citizens for Energy & Employment	7908080210	50-341 Q
Citizens for Non Nuclear Future	7908160407	FOIA
Cleveland Electric Illuminating Co	7908010348	50-440 S
	7908010510	50-440 S
	7908060329	50-440 S
	7908080260	50-440 Q
	7908090591	50-440 Q
	7908100170	50-440 Q
	7908230113*	50-440 Q
Cleveland X-Ray Inspection, Inc	7908240045	71-336
	7908240048	71-336
Clinton Mills	7908210236*	50-269 H
Coalition for Safe Power	7908300018*	50-322 Q
	7908300758	50-344 Q
	7908300761*	50-344 Q
Coast Guard, Transportation, Dept. of	7908090475	50-437 A
Colorado, State of	7908270346	PROJ
Columbia County, NY	7908030275*	50-596 Q
Combustion Engineering, Inc.	7908070324*	50-220 Q
	7908070687*	50-363 Q
	7908100465*	50-255 P
	7908240444	TOPREP
	7908240449*	TOPREP
	7908280444*	50-341 Q
	7908280849	50-333 Q
Combustion Engineering, Inc., C-E Minerals Div	7908080389*	50-315 Q
Commerce, Dept of	7908210545	50-568 D
Commerce, Dept of, National Bureau of Standards	7908010301	RES
	7908010333	RES
	7908290490	50-184 P
	7908310553	50-184 F
Committee for Application of Nuremberg Principles to US Nuclear Power Production	7908300050	50-272 Q
Common Ground	7908220170	FOIA
Commonwealth Assoc., Inc. (subs. of Wilbert Assoc., Inc.)	7908140069*	QA999
Commonwealth Edison Co	7908010300	50-237 F
	7908010308*	50-373 Q
	7908010445	50-10 P
	7908010445	50-10 P
	7908010470	50-10 P
	7908010470	50-10 P
	7908010631*	50-295 Q
	7908010680	71-9111
	7908020167	50-454 Q
	7908020237	50-373 Q
	7908020419	50-10 P
	7908020450	50-10 P
	7908020460	50-10 P
	7908020460	50-10 P
	7908020460	50-10 P
	7908020460	50-10 P
	7908020460	50-10 P
	7908020460	50-10 P
	7908020596	50-247 Q
	7908030037	50-373 Q
	7908030140	50-237 P
	7908030167	50-295 F
	7908030167	50-295 F
	7908030227*	50-454 Q
	7908030302	50-237 P
	7908030302	50-237 P
	7908030394	50-295 F
	7908030394	50-295 F
	7908030478	50-237 F
	7908060111	50-10 Q
	7908060225	50-254 Q
	7908060231*	50-254 Q
	7908060306	50-454 K
	7908070064*	50-295 F
	7908070617	50-254 P
	7908070617	50-254 P
	7908080143	50-295 Q
	7908080383	50-237 S
	7908080387*	50-237 S
	7908080404	50-249 S
	7908080405*	50-249 S
	7908080424*	50-454 Q
	7908080500	50-249 S
	7908080508*	50-249 S
	7908080523	50-10 Q
	7908080530	50-237 Q
	7908080530	50-237 Q
	7908080530	50-237 Q
	7908090703	50-237 Q
	7908090344	50-373 A
	7908090558	50-373 I
	7908100412	50-599 H
	7908100412	50-599 H
	7908100440	50-265 P
	7908100444	50-599 H
	7908100444	50-599 H
	7908130161*	50-295 Q
	7908130447	50-454 Q
	7908130455	50-373 Q
	7908140156	50-304 Q
	7908140537	50-295 S
	7908140542*	50-295 S
	7908140551	50-295 S
	7908140555*	50-295 S
	7908140582	50-265 S
	7908140588*	50-265 S
	7908140604	50-265 S
	7908140612*	50-265 S
	7908140615	50-249 S
	7908140623	50-265 S
	7908140628*	50-265 S
	7908140629*	50-249 S
	7908140643	50-295 S
	7908140645*	50-295 S
	7908140680	50-254 S
	7908140690*	50-254 S
	7908140748	50-304 S
	7908140754*	50-304 S
	7908140771	50-304 S
	7908140778*	50-304 S
	7908140780	50-295 S
	7908140785*	50-295 S
	7908140810	50-295 S
	7908140814*	50-295 S
	7908150299*	50-237 Q
	7908150339	50-295 Q
	7908150349	50-10 Q
	7908150349	50-10 Q
	7908150439	50-373 Q
	7908160376	50-10 P
	7908160376	50-10 P
	7908160376	50-10 P
	7908160376	50-10 P
	7908160376	50-10 P
	7908160376	50-10 P
	7908160456	50-237 P
	7908170053	50-237 Q
	7908200192	71-9113
	7908200216	50-10 F
	7908200216	50-10 F
	7908200223	50-456 F
	7908200226	50-454 F
	7908200245	50-10 Q
	7908200245	50-10 Q
	7908200245	50-10 Q
	7908200250	50-295 F
	7908200263*	71-9113
	7908200287	50-10 P
	7908200287	50-10 P
	7908200287	50-10 P
	7908200335	50-254 F
	7908200336	50-10 P
	7908200338	50-373 F
	7908200358	50-10 P
	7908200380	50-10 P
	7908200380	50-10 P
	7908200380	50-10 P
	7908210027	71-0374
	7908210256	50-10 P
	7908210284	50-10 F
	7908210368	50-295 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908210469	50-295 P
	7908210469	50-295 P
	7908210482*	50-295 P
	7908210482*	50-295 P
	7908210571	50-358 A
	7908220397	50-237 S
	7908220400*	50-237 S
	7908230420	50-10 P
	7908230431	50-254 R
	79082 431	50-254 R
	7908230439*	50-254 R
	7908230439*	50-254 R
	7908240447	50-10 P
	7908240513	50-10 Q
	7908240513	50-10 Q
	7908240513	50-10 Q
	7908240513	50-10 Q
	7908240512	50-10 Q
	7908280010	50-295 P
	7908280392	50-237 P
	7908280453	50-373 Q
	7908280570	50-254 R
	7908280570	50-254 R
	7908280573*	50-254 R
	7908280573*	50-254 R
	7908280575	50-237 P
	7908280640	50-237 S
	7908280646*	50-237 S
	7908300398	71-9094
	7908300459	50-10 R
	7908300466*	50-10 R
Community Supported Television LA, California	7908080666	FOIA
Conax Corp	7908080668	XPORTLIC
Concerned Citizens Reactor Export Review Board	7908290363*	50-574 Q
	7908300340	50-574 A
Connecticut Yankee Atomic Power Co.	7908010529	50-213 P
	7908030015	50-213 F
	7908060304	50-213 S
	7908060311*	50-213 S
	7908060477	50-213 Q
	7908070542	50-213 P
	7908080343	50-213 Q
	7908100438	50-213 S
	7908200322	50-213 R
	7908200325*	50-213 R
	7908210183*	50-213 Q
	7908210333	50-213 S
	7908210336*	50-213 S
	7908240458	50-213 P
	7908240459*	50-213 P
	7908280686	50-213 S
	7908280692*	50-213 S
Conner, Moore & Corber	7908020021	50-358 Q
	7908030529	50-272 Q
	7908030543	27-39
	7908030552*	27-39
	7908030556	27-39
	7908030579	27-39
	7908080226	50-358 Q
	7908090419	50-272 P
	7908220113	50-272 Q
	7908220144*	50-272 Q
	7908280659	50-311 Q
Conservation Council of North Carolina	7908200124*	50-400 A
Conservative Law Foundation of Rhode Island	7908080556	50-568 D
Consolidated Edison Co. of New York	7908010343	50-3 P
	7908020166	71-6574
	7908020189	71-6144
	7908030174	50-247 P
	7908070043	50-247 Q
	7908070198	50-3 Q
	7908070353	50-247 S
	7908070475	50-247 P
	7908070598	50-3 F
	7908070598	50-3 F
	7908070609	50-247 Q
	7908070775	50-3 Q
	7908070778*	50-3 Q
	7908070778*	50-3 Q
	7908080501	50-3 Q
	7908080507	50-247 Q
	7908080527	50-3 P
	7908080529*	50-3 P
	7908080529*	50-3 P
	7908090375	50-3 J
	7908090375	50-3 J
	7908090392	50-247 P
	7908090404*	50-247 P
	7908090671	50-3 Q
	7908140826	50-247 S
	7908140831*	50-247 S
	7908170368	50-3 Q
	7908170399	50-3 R
	7908200342	50-247 R
	7908200345*	50-247 R
	7908210015	50-3 F
	7908220391	50-3 R
	7908240372	50-3 P
	7908280704	50-247 P
	7908280707*	50-247 P
	7908290584	50-3 Q
	7908290584	50-3 Q
	7908290592*	50-3 Q
Construction Technology Laboratories (div. of Portland Cement Assoc.)	7908270388*	50-344 P
	7908270398*	50-344 P
Consumer's Assoc. of Canada (B.C.)	7908300523	50-522 Q
Consumers Power Co.	7908010436	50-155 P
	7908010436	50-155 P
	7908010503	50-255 S
	7908010507	50-155 P
	7908010508*	50-255 S
	7908020272	50-155 Q
	7908030027	50-255 Q
	7908030088	50-155 P
	7908030424	50-255 P
	7908030430*	50-255 P
	7908030442	FOIA
	7908030597	50-255 Q
	7908060212*	50-329 Q
	7908060212*	50-329 Q
	7908060236	50-329 A
	7908060349	50-155 P
	7908060405	50-329 S
	7908060421	50-255 S
	7908060428*	50-255 S
	7908060432	50-255 S
	7908060438*	50-255 S
	7908070376	50-155 Q
	7908070382*	50-155 Q
	7908070536	50-255 P
	7908070561*	50-255 P
	7908070606	50-255 P
	7908080107*	50-255 Q
	7908080124	50-329 K
	7908080124	50-329 K
	7908080133*	50-329 K
	7908080133*	50-329 K
	7908080309	50-255 Q
	7908090297	50-329 Q
	7908090350	50-255 P
	7908090354*	50-255 P
	7908090586	50-155 Q
	7908090632	50-329 Q
	7908090637*	50-329 Q
	7908090654	50-255 Q
	7908100172*	50-155 Q
	7908100454	50-329 K
	7908100454	50-329 K
	7908130658	50-329 Q
	7908140099	50-255 Q
	7908140360	50-329 S
	7908140360	50-329 S
	7908140536	50-255 R
	7908140538*	50-255 R
	7908140539	50-155 Q
	7908140773	50-155 H
	7908140773	50-155 H
	7908150418*	50-329 Q
	7908150418*	50-329 Q
	7908150593	50-155 H
	7908150593	50-155 H
	7908150758*	50-320 P
	7908160359	50-155 Q
	7908170165	50-155 Q
	7908170169*	50-155 Q
	7908170387	50-155 P
	7908170387	50-155 P
	7908170390	50-329 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908170390	50-329 S
	7908170393*	50-329 S
	7908170401	50-255 S
	7908170402*	50-255 S
	7908200309	50-255 Q
	7908200386	50-255 P
	7908210353	50-155 P
	7908210421	50-329 S
	7908210421	50-329 S
	7908210431*	50-329 S
	7908210447	50-329 S
	7908210447	50-329 S
	7908210477	50-329 S
	7908210477	50-329 S
	7908220311	50-255 Q
	7908220321	50-155 P
	7908230048	50-329 A
	7908230407	50-255 S
	7908230410*	50-255 S
	7908230473	50-255 P
	7908240165	50-155 Q
	7908240455	50-255 P
	7908240501	50-155 Q
	7908240523	50-155 Q
	7908240529	50-155 Q
	7908240533	50-255 Q
	7908270345	50-329 R
	7908270389	50-255 S
	7908270394*	50-255 S
	7908270396*	50-255 S
	7908270447	50-255 P
	7908280004	50-255 P
	7908280005	50-255 Q
	7908280007	50-155 P
	7908280025	50-155 F
	7908280025	50-155 F
	7908280566	50-155 P
	7908280663	50-255 S
	7908280668*	50-255 S
	7908290402	50-329 S
	7908290402	50-329 S
	7908290560	50-329 S
	7908290560	50-329 S
	7908290567*	50-329 S
	7908290567*	50-329 S
	7908300406	71-5901
	7908300449	50-155 P
	7908310012	71-6601
	7908310013	71-6144
Cooper Industries, Cooper-Bessemer Co. Div.	7908080684	50-387 S
Corner & Lada Co., Inc.	7908220282*	GA999
	7908220301*	GA999
Creare, Inc.	7908010240	RES
	7908010352	RES
Critical Mass Energy Project	7908150733	50-320 H
	7908310300*	PR
D'Appolonia Consulting Engineers, Inc.	7908010305	PROJ
	7908030001	PROJ
	7908070350	50-155 P
	7908070523	PROJ
	7908070594	PROJ
Daedalean Associates, Inc.	7908020266	RES
Dairyland Power Cooperative	7907190015	50-409 Q
	7908010696	50-409 P
	7908030170	50-409 P
	7908030468	50-409 S
	7908030481*	50-409 S
	7908070175	50-409 Q
	7908080395	50-409 Q
	7908080613	50-409 H
	7908130661	50-409 P
	7908140642	50-409 S
	7908140647*	50-409 S
	7908150193	50-409 S
	7908150214*	50-409 S
	7908150419	50-409 R
	7908150428*	50-409 R
	7908150683	50-409 Q
	7908160439	50-409 P
	7908160453*	50-409 P
	7908200334	50-409 P
	7908210249	50-409 P
	7908210391	50-409 R
	7908210393*	50-409 R
	7908220366	50-409 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908230319	50-409 H
	7908270413	50-409 P
	7908270453	50-409 F
	7908280603	50-409 J
Dames & Moore	7908090352	PROJ
	7908130589*	40-299
	7908150734	40-299
	7908220220*	40-8721
	7908300503*	50-367 A
Dart Environment & Services Co. ERC/LANCY Div.	7908060285	40-1162
DeKalb Area Alliance for Responsible Energy	7908130102	50-454 Q
Debevoise & Lieberman	7908130188	50-445 M
	7908130201*	50-445 M
Defense, Dept. of	7908100439	50-170 S
	7908100448*	50-170 S
	7908170535*	50-482 Q
Defense, Dept. of, Defense Nuclear Agency	7908240450	50-170 P
Delaware Medical Laboratories, Inc. WI, Delaware	7907090108	PR
Detroit Edison Co.	7908010566*	50-341 K
	7908020265	50-341 Q
	7908030602	50-341 Q
	7908080515	50-341 S
	7908100177	50-341 Q
	7908140560	50-341 A
	7908140573	50-341 S
	7908140624	50-16 A
	7908280437	50-341 Q
District of Columbia	7908240295*	COMMISSION
Dow Chemical Co.	7908080631*	50-329 A
Downwind Alliance	7908280246*	50-312 A
Duke Power Co.	7908010265	50-269 Q
	7908010371	50-269 P
	7908010371	50-269 P
	7908010371	50-269 P
	7908010377	50-269 F
	7908010377	50-269 F
	7908010377	50-269 F
	7908010441	50-269 P
	7908010441	50-269 P
	7908010467	50-269 P
	7908010467	50-269 P
	7908010467	50-269 P
	7908010474*	50-269 P
	7908010474*	50-269 P
	7908010474*	50-269 P
	7908010485	50-369 A
	7908020211	71-6144
	7908020428	50-270 S
	7908020463	50-269 S
	7908020513	50-369 Q
	7908030038	50-269 Q
	7908030190	70-2623
	7908030197*	70-2623
	7908030601	50-369 Q
	7908030620*	50-269 Q
	7908060005	50-413 Q
	7908060220	50-369 A
	7908060508	50-269 S
	7908060512*	50-269 S
	7908060517	50-269 F
	7908070646	50-269 S
	7908070646	50-269 S
	7908070646	50-269 S
	7908070656*	50-269 S
	7908070656*	50-269 S
	7908070656*	50-269 S
	7908070735	50-269 Q
	7908070805	50-269 Q
	7908070805	50-269 Q
	7908070805	50-269 Q
	7908070815	50-269 Q
	7908070815	50-269 Q
	7908070815	50-269 Q
	7908080094	50-369 A
	7908080203	50-413 Q
	7908100270	50-269 P
	7908100275*	50-269 P
	7908100383*	50-413 Q
	7908100472	50-369 A
	7908100472	50-369 A
	7908100472	50-369 A
	7908100473*	50-369 A
	7908100473*	50-369 A

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908100473*	50-369 A
	7908100498	50-369 A
	7908100499	50-269 S
	7908130446	50-413 A
	7908140501	50-270 S
	7908140581	50-269 S
	7908140608	50-269 S
	7908140671	50-413 S
	7908140679*	50-413 S
	7908140723	50-269 S
	7908140827	50-269 S
	7908150285	50-369 G
	7908150408	50-269 G
	7908150408	50-269 G
	7908150408	50-269 G
	7908150462	50-413 A
	7908160271	50-269 G
	7908160287	50-369 G
	7908160371	50-491 G
	7908160374	50-269 S
	7908160379*	50-269 S
	7908170057	50-369 G
	7908170171	50-369 G
	7908210004	50-269 F
	7908210004	50-269 F
	7908210004	50-269 F
	7908210006	50-369 F
	7908210114	50-488 G
	7908210379	50-269 G
	7908210529	50-269 R
	7908210529	50-269 R
	7908210529	50-269 R
	7908210532*	50-269 R
	7908210532*	50-269 R
	7908210532*	50-269 R
	7908220281	50-269 G
	7908220340	50-269 P
	7908220340	50-269 P
	7908220340	50-269 P
	7908220503	70-2623
	7908220673	50-269 G
	7908230230	50-413 G
	7908230280	PR
	7908230320	50-269 S
	7908230327*	50-269 S
	7908230470	50-269 P
	7908230470	50-269 P
	7908230470	50-269 P
	7908230487	50-269 H
	7908230648	50-488 G
	7908240389	50-269 S
	7908240394*	50-269 S
	7908240603	50-491 G
	7908270293	50-369 G
	7908270306	50-413 G
	7908270307	50-369 G
	7908280608	50-369 S
	7908280621	50-413 S
	7908280627*	50-413 S
	7908280630	50-269 S
	7908280635*	50-269 S
	7908280658	50-269 P
	7908280658	50-269 P
	7908280658	50-269 P
	7908280669	50-269 P
	7908280669	50-269 P
	7908280669	50-269 P
	7908280672*	50-269 P
	7908280672*	50-269 P
	7908280672*	50-269 P
	7908300119*	50-491 G
	7908300352	50-488 G
	7908300470	50-491 G
	7908300524	50-239 G
	7908300735	50-269 P
Duquesne Light Co.	7908010318	50-334 S
	7908010440	50-334 S
	7908010497	50-334 S
	7908010502*	50-334 S
	7908010574	50-334 P
	7908030022	50-334 S
	7908030178	50-412 G
	7908030251	50-334 G
	7908060213	50-334 R
	7908060275	50-334 S
	7908060354	50-334 G
	7908070303	50-334 G
	7908070753	50-412 G
	7908070812	50-334 G
	7908080480	50-334 P
	7908080494	50-412 G
	7908090480	50-334 P
	7908100449	50-334 S
	7908100451*	50-334 S
	7908130273	50-334 G
	7908130419	50-334 S
	7908130424*	50-334 S
	7908130426*	50-334 S
	7908130434*	50-334 S
	7908130438*	50-334 S
	7908130442*	50-334 S
	7908130445*	50-334 S
	7908130458	50-334 S
	7908130462*	50-334 S
	7908130595	50-334 G
	7908140518	50-334 R
	7908140525*	50-334 R
	7908140578	50-334 G
	7908140665	50-334 P
	7908140749	50-334 S
	7908140768*	50-334 S
	7908140821	50-334 S
	7908140828*	50-334 S
	7908140839	50-334 P
	7908140841*	50-334 P
	7908150669	50-412 A
	7908150677*	50-412 A
	7908150718	50-334 G
	7908160147	50-334 S
	7908160438	50-412 S
	7908160443*	50-412 S
	7908170355	50-334 G
	7908200009	50-412 G
	7908220007	50-334 F
	7908230430	50-334 S
	7908230435*	50-334 S
	7908230438*	50-334 S
	7908230510	50-334 S
	7908230517*	50-334 S
	7908240587	50-334 G
	7908280422	50-334 S
	7908290461	50-334 S
	7908290472*	50-334 S
	7908290492*	50-334 S
E. I. du Pont de Nemours & Co., Inc.	7908210166*	50-320 P
EG & G, Inc.	7908010563	RES
	7908030318*	50-302 P
	7908070748	NUREG
	7908080487	RES
	7908080537	RES
	7908080571	RES
	7908080583	RES
	7908100394	NUREG
	7908140084	NUREG
	7908140116	NUREG
	7908140128	NUREG
	7908170500	RES
	7908200230*	50-247 P
	7908200326	50-266 P
	7908230647	50-282 P
	7908230650*	50-282 P
ESB, Inc., Exide Industrial Battery Div.	7908100220*	QA999
Eastern Airlines, Inc.	7908200101	71-91
	7908200103*	71-91
	7908300431	71-9033
Eastman Kodak Co.	7908270375	71-92
Ebasco Services, Inc. (subs. of Enserch Corp.)	7908100470*	50-335 P
Eberline Instrument Corp.	7908150148	XPORTLIC
	7908310557	XPORTLIC
Eckert, Seamans, Cherin & Mellott	7908300110	50-338 G
Ecology Action of Oswego	7908290418	50-485 G
	7908310387	50-410 A
	7908310387	50-410 A
Ecology Audits, Inc.	7908210233*	40-1162
Edgerton, Inc. (subs. of Formac International, Inc.)	7908300666	TOPREP
	7908300672*	TOPREP
Edlow International Co.	7908010607	XPORTLIC
	7908030347	XPORTLIC
	7908030553	XPORTLIC

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908150425	XPORTLIC
	7908230445	PRM
Elbert P. Epler	7908210093	ACRS
Electric Power Research Institute	7908150471*	ORG
Emojean Kerber Girard	7908140824	FOIA
Energy Fuels Nuclear, Inc.	7908010439*	40-8675
	7908130408	40-8681
	7908130412*	40-8681
	7908140512	40-8681
	7908140514*	40-8681
	7908210209	40-8681
Energy Research & Development Admin. (Presently DOE)	7908010205	ORG
Energy, Dept. of	7908070399	50-568 D
	7908080307*	50-522 Q
	7908090318	REGGD
	7908100538	71-5149
	7908100593	71-6172
	7908160295	50-574 A
	7908170236*	ORG
	7908210110	50-320 P
	7908210113	50-320 P
	7908210121	50-320 P
	7908210128	50-320 H
	7908210142	50-320 P
	7908210149	50-320 P
	7908210383	50-320 P
	7908230133	PROJ
	7908230173*	SECY
	7908270226*	PROJ
	7908280832	71-5971
	7908280853	71-9134
	7908290614	71-9010
	7908300165	PROJ
	7908300204	PROJ
	7908310451	50-320 H
Energy, Dept. of, Savannah River Operations	7908210157	50-320 P
	7908280749	71-6478
Engineering Decision Analysis Company, Inc.	7908130600*	70-1257
Environmental Coalition on Nuclear Power	7908150769*	50-320 Q
	7908170133	40-8721
	7908170224*	50-289 P
	7908300284	PROJ
	7908300341	50-387 Q
	7908300341	50-387 Q
	7908300353	50-387 Q
	7908300353	50-387 Q
	7908300369*	50-387 Q
	7908300369*	50-387 Q
Environmental Policy Center	7908030457	FOIA
Environmental Protection Agency	7908030334*	COMMISSION
	7908030631	PROJ
	7908140087	40-1162
	7908210557	50-387 D
	7908220161	50-320 P
	7908220268	50-327 A
	7908280173*	FOIA
	7908280209*	FOIA
	7908280222*	FOIA
	7908280252*	FOIA
	7908280260*	FOIA
	7908280271*	FOIA
	7908300641	50-395 D
Environmental Research & Technology, Inc.	7908280047*	50-471 F
European Communities, Commission of	7908160002	XPORTLIC
	7908160003	XPORTLIC
	7908220415	50-320 P
	7908220419*	50-320 P
	7908240053	XPORTLIC
Exam Co.	7908220544	71-321
Exxon Minerals Co., USA	7908030016	40-8102
	7908130580	40-8064
	7908170150	40-8064
	7908270502	40-8064
Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)	7908070241	70-1257
	7908070257*	70-1257
	7908090535	70-1257
	7908090624	70-1257
	7908140113	70-1257
	7908140320	70-1257
	7908150258	70-1257
	7908150263*	70-1257
	7908150269*	70-1257
	7908200106	70-1257

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908210499	TOPREP
	7908210503*	TOPREP
	7908210564	TOPREP
	7908210569*	TOPREP
	7908210572	TOPREP
	7908210577*	TOPREP
	7908300778	71-9022
	7908310008	71-5768
	7908020029	40-4492
Federal American Partners	7908230354	50-320 P
Federal Bureau of Investigation	7908230359*	50-320 P
	7908080363	71-167
Finley Testing Laboratories	7907260035	50-250 P
Florida Power & Light Co.	7908010571	50-335 F
	7908020354	50-250 Q
	7908030171	50-250 P
	7908030171	50-250 P
	7908030330	50-250 P
	7908030330	50-250 P
	7908030627	50-335 P
	7908070375	50-250 I
	7908070375	50-250 I
	7908070395	50-335 P
	7908070497	50-335 S
	7908070505*	50-335 S
	7908070510	50-251 S
	7908070517*	50-251 S
	7908090141	50-335 Q
	7908090238	50-250 Q
	7908090537	50-335 Q
	7908090541	50-250 Q
	7908090541	50-250 Q
	7908100117	50-250 Q
	7908100446	TOPREP
	7908100466	50-335 P
	7908140372	50-251 P
	7908140435	50-250 P
	7908140458	50-250 P
	7908140616	50-250 S
	7908140625*	50-250 S
	7908140710	50-335 Q
	7908140713	50-335 S
	7908140726*	50-335 S
	7908140729	50-250 Q
	7908160362	50-250 P
	7908160362	50-250 P
	7908160408	50-250 P
	7908160408	50-250 P
	7908160458	50-250 Q
	7908160465	50-251 S
	7908160468*	50-251 S
	7908170049	50-250 Q
	7908170302	50-251 P
	7908200013*	50-335 Q
	7908200034*	50-250 Q
	7908200264	50-302 Q
	7908200279	50-250 S
	7908200282*	50-250 S
	7908200284	50-251 S
	7908200286*	50-251 S
	7908200344	50-335 S
	7908200347*	50-335 S
	7908210119	50-250 Q
	7908210265	50-250 P
	7908210265	50-250 P
	7908210386	50-335 Q
	7908220005	50-250 F
	7908220548	50-389 Q
	7908230393	50-335 R
	7908230396*	50-335 R
	7908240104*	50-335 Q
	7908240146	50-335 Q
	7908240467	50-250 Q
	7908270302	50-335 Q
	7908270312	50-302 Q
	7908280027	50-250 F
	7908280562	50-335 P
	7908280662	50-335 P
	7908280681	50-251 Q
	7908280693	50-302 S
	7908280699*	50-302 S
	7908290073	50-389 Q
	7908290079	50-250 Q
	7908290424	50-250 S
	7908290429*	50-250 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908300645	50-335 P
	7908300675	50-250 S
	7908300681*	50-250 S
	7908300708	50-335 S
	7908300711*	50-335 S
	7908300743	50-335 Q
	7908300745	50-389 Q
	7908310032	50-250 Q
	7908310032	50-250 Q
	7908310408	50-335 P
	7908310412*	50-335 P
	7908310454	50-335 P
Florida Power Corp.	7908020170	71-6144
	7908020473	50-302 H
	7908020510	71-5026
	7908030040	50-302 Q
	7908030399	50-302 S
	7908030408*	50-302 S
	7908030572	50-302 Q
	7908060072	50-302 Q
	7908060506	50-302 S
	7908060514*	50-302 S
	7908070383	50-302 P
	7908070386*	50-302 P
	7908090387	50-302 P
	7908090457	50-302 P
	7908100301	50-302 P
	7908100343	50-302 S
	7908100351*	50-302 S
	7908100455	50-302 S
	7908100459*	50-302 S
	79C_140447	50-302 P
	7908140511	50-302 H
	7908150709	50-302 Q
	7908170001	50-302 Q
	7908170259	50-302 Q
	7908170397	50-302 P
	7908170409	50-302 R
	7908170413*	50-302 R
	7908170630	50-302 Q
	7908200206	50-302 F
	7908200258	50-261 Q
	7908210361	50-302 S
	7908210363*	50-302 S
	7908210405	50-302 P
	7908230415	50-302 P
	7908230541	50-302 S
	7908230548*	50-302 S
	7908270445	50-302 S
	7908270450*	50-302 S
	79082b0584	50-302 S
	7908280594	50-302 S
	7908280754	50-302 P
	7908290450	50-302 S
	7908290457*	50-302 S
	7908290499	50-302 P
	7908290506*	50-302 P
	7908290688	50-302 Q
	7908300080*	50-302 Q
	7908300087*	50-302 Q
	7908300775	50-302 Q
	7908310303	50-302 S
	7908310309*	50-302 S
	7908310378	50-302 F
	7908310466	50-302 S
	7908310481*	50-302 S
	7908310518	50-302 R
	7908310522*	50-302 R
Florida, State of	7908150751*	50-320 H
Foley & Lardner	7908010575	50-502 Q
Folks United to Thwart Unsafe Radiation Emission (FUTURE)	7908090544	PROJ
Ford Bacon & Davis Utah, Inc.	7908140462	NUREG
	7908170465	PROJ
	7908200403*	PROJ
	7908200404*	PROJ
Forelaws on Board	7908300018*	50-522 Q
	7908300309	50-522 Q
Foster Wheeler Corp.	7908300412	71-9033
France	7908220102	50-320 U
Franklin Institute	7908100447*	50-311 E
Friends of the Earth	7908150268	50-312 Q
GPU Service Corp.	7908200247	50-289 J
	7908230251*	50-320 P
	7908230257*	50-320 P
	7908230266*	50-320 P
	7908230272*	50-320 P
	7908230375	50-219 J
Gamma Corp.	7908160150	71-10
	7908160156*	71-10
Gardiner, NY	7908010691*	50-596 A
General Atomic Co. (subs. of Gulf Oil Corp.)	7908010568	TOPREP
	7908020378	XPORTLIC
	7908090239	XPORTLIC
	7908090250*	XPORTLIC
	7908140108	70-734
	7908140127	70-734
	7908140493	50-89 P
	7908160048	70-734
	7908210134	70-734
	7908210392	70-734
	7908240387	50-89 P
	7908300771*	COMMISSION
General Dynamics Corp., Electric Boat Div.	7908230225	71-6717
General Eastern Instruments Corp.	7908220073*	COMMISSION
General Electric Co.	7907120319	REGGD
	7908010256	RES
	7908010283	RES
	7908020380	XPORTLIC
	7908070664	TOPREP
	7908080524*	50-296 P
	7908080748	XPORTLIC
	7908090007*	50-354 Q
	7908090254*	TOPREP
	7908090262*	TOPREP
	7908090453*	TOPREP
	7908090458*	TOPREP
	7908090589*	SECY
	7908130142*	GA999
	7908130153*	SECY
	7908130449	TOPREP
	7908130451*	TOPREP
	7908140131	70-1308
	7908140335	70-754
	7908150152	XPORTLIC
	7908150687*	TOPREP
	7908200037*	GA999
	7908210065	70-1308
	7908230511*	50-344 Q
	7908230580	50-73 S
	7908240089	TOPREP
	7908240338	70-1308
	7908240433	TOPREP
	7908240437*	TOPREP
	7908240644	NUREG
	7908280548	TOPREP
	7908280838*	50-333 Q
General Electric Co., Nuclear Energy Products Div.	7908010570	TOPREP
	7908010576*	TOPREP
	7908010599	REGGD
	7908010710	71-9018
	7908020107	71-9019
	7908020486	50-70 P
	7908030370	TOPREP
	7908030393	50-320 U
	7908060403*	50-278 P
	7908060407*	50-278 P
	7908070446	TOPREP
	7908070641	TOPREP
	7908080024	XPORTLIC
	7908090277*	TOPREP
	7908090286*	TOPREP
	7908090466	70-754
	7908090559	TOPREP
	7908090561*	SECY
	7908090570*	SECY
	7908130450	TOPREP
	7908130607	70-754
	7908140060	70-1308
	7908140066	70-754
	7908140157	70-1113
	7908140236	70-1113
	7908140272	XPORTLIC
	7908140486	70-1113
	7908150670	TOPREP
	7908150675*	TOPREP
	7908150681	TOPREP
	7908160421	TOPREP
	7908160462	NUREG
	7908160472*	50-280 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908170601	70-1968
	7908200332	TOPREP
	7908210535	70-754
	7908220671	70-754
	7908230582	70-754
	7908230651	70-1113
	7908240060	71-5274
	7908240409	TOPREP
	7908240454	50-70 P
	7908240475	50-70 P
	7908240505*	50-155 Q
	7908240548*	SECY
	7908240551*	SECY
	7908270379	TOPREP
	7908270385*	TOPREP
	7908280563	TOPREP
	7908280596	TOPREP
	7908280633	50-70 P
	7908280648	TOPREP
	7908280652*	TOPREP
	7908280782	71-5331
	7908290184*	REGGD
	7908290246	70-754
	7908300733	TOPREP
	7908300737*	TOPREP
	7908310354	50-70 F
	7908310441	TOPREP
	7908310446*	TOPREP
General Motors Corp	7908310249	XPORTLIC
	7908310254*	XPORTLIC
	7908310291*	XPORTLIC
	7908310422	XPORTLIC
General Public Utilities	7908280003	50-320 P
General Services Administration	7908010065*	10CFR
Georgia Institute of Technology	7908080416	NUREG
Georgia Power Co	7908010373	50-302 P
	7908020251	50-321 Q
	7908020361	50-321 Q
	7908020361	50-321 Q
	7908020421	50-321 S
	7908020426*	50-321 S
	7908020427	50-321 S
	7908020434*	50-321 S
	7908020439	50-321 S
	7908020444	50-321 S
	7908020452	50-366 S
	7908020456*	50-366 S
	7908030031	50-424 Q
	7908030148	50-321 P
	7908030148	50-321 P
	7908030316	50-366 P
	7908030389	50-321 S
	7908030444	50-366 S
	7908030495	50-321 Q
	7908030506	50-321 S
	7908030511*	50-321 S
	7908060376	50-424 S
	7908060376	50-424 S
	7908060392	50-366 S
	7908060411*	50-366 S
	7908060443	50-366 S
	7908060451*	50-366 S
	7908060460	50-321 S
	7908060463*	50-321 S
	7908060469	50-321 S
	7908060474*	50-321 S
	7908070483	50-366 S
	7908070493*	50-366 S
	7908070495	50-366 S
	7908070498*	50-366 S
	7908070695	50-321 S
	7908070699*	50-321 S
	7908080570	50-321 Q
	7908100413	50-366 S
	7908100416*	50-366 S
	7908130338	50-366 S
	7908130345*	50-366 S
	7908130410	50-321 S
	7908130415*	50-321 S
	7908130423	50-366 S
	7908130435*	50-366 S
	7908130436	50-366 S
	7908130437*	50-366 S
	7908130448	50-366 S
	7908130453*	50-366 S
	7908130464	50-321 S
	7908130469	50-366 S
	7908130473*	50-366 S
	7908130476	50-321 S
	7908130491	50-366 S
	7908130494*	50-366 S
	7908130497	50-366 S
	7908130502*	50-366 S
	7908140528	50-424 Q
	7908140635	50-366 S
	7908140646*	50-366 S
	7908140678	50-321 S
	7908140696	50-366 S
	7908140702*	50-366 S
	7908140719	50-424 S
	7908140719	50-424 S
	7908140791	50-366 S
	7908140796*	50-366 S
	7908140805	50-321 S
	7908140826*	50-321 S
	7908140812	50-366 S
	7908140823*	50-366 S
	7908140833	50-366 S
	7908140837*	50-366 S
	7908150390	50-321 Q
	7908150498	50-366 P
	7908150500	50-366 P
	7908150513	50-321 R
	7908150519*	50-321 R
	7908150531	50-366 R
	7908150538*	50-366 R
	7908150651	50-321 S
	7908150679	50-321 H
	7908150679	50-321 H
	7908160031	50-366 Q
	7908160310	50-321 Q
	7908160310	50-321 Q
	7908160334	50-424 Q
	7908160334	50-424 Q
	7908160403	50-321 Q
	7908160403	50-321 Q
	7908160469	50-321 Q
	7908160488*	50-321 Q
	7908170562*	50-321 Q
	7908200262	50-321 S
	7908200267*	50-321 S
	7908200272	50-321 S
	7908200273*	50-321 S
	7908200281	50-321 S
	7908200285*	50-321 S
	7908200302	50-366 S
	7908200320	50-366 S
	7908200323*	50-366 S
	7908200337	50-366 S
	7908200340*	50-366 S
	7908200351	50-366 S
	7908200352*	50-366 S
	7908200355*	50-366 S
	7908200371	50-366 S
	7908200374*	50-366 S
	7908200377	50-366 S
	7908200379*	50-366 S
	7908210310*	50-321 Q
	7908210430	50-366 P
	7908220684	50-321 Q
	7908220684	50-321 Q
	7908230426	50-321 Q
	7908230669	50-321 Q
	7908230669	50-321 Q
	7908240324	50-321 S
	7908240339*	50-321 S
	7908240348	50-321 S
	7908240362*	50-321 S
	7908240367	50-321 S
	7908240377*	50-321 S
	7908240385	50-321 S
	7908240393*	50-321 S
	7908240399	50-321 S
	7908240411*	50-321 S
	7908240417	50-321 S
	7908240424*	50-321 S
	7908240436	50-366 S
	7908240440*	50-366 S
	7908240442	50-424 A
	7908240442	50-424 A

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908240446*	50-424 A
	7908240446*	50-424 A
	7908240469	50-366 S
	7908240472	50-321 S
	7908240476*	50-321 S
	7908240479	50-321 S
	7908240480*	50-366 S
	7908240486*	50-321 S
	7908240490	50-321 S
	7908240495*	50-321 S
	7908240525	50-366 S
	7908240528*	50-366 S
	7908270242*	50-424 Q
	7908270242*	50-424 Q
	7908270380	50-321 S
	7908270468	50-321 F
	7908270468	50-321 F
	7908280685	50-366 S
	7908280690*	50-366 S
	7908290408	50-321 S
	7908290409*	50-321 S
	7908290620	50-424 Q
	7908290620	50-424 Q
	7908300729	50-321 Q
	7908310027	50-424 Q
	7908310042	50-321 Q
	7908310313	50-366 S
	7908310316*	50-366 S
	7908310318	50-366 S
	7908310322*	50-366 S
	7908310324	50-321 S
	7908310327*	50-321 S
	7908310401	50-321 S
	7908310406*	50-321 S
Gibbs & Hill, Inc. (subs. of Dravo Corp.)	7908020035*	40-4492
Gibson, Dunn & Crutcher	7908090016	PROJ
Goldberg, Fieldman & Latham, P.C.	7908230308	50-346 M
Goodyear Aerospace Corp. (subs. of Goodyear Tire & Rubber Co.)	7908240331	70-1489
Gould, Inc.	7908100390*	GA999
	7908100393*	GA999
Gray, Plant, Mooty, Mooty & Bennett	7908160400	FOIA
Groun/Water Technology, Inc.	7908300503*	50-367 A
	7908300514*	50-367 A
Gulf Nuclear, Inc.	7908170510	71-210
Gulf Oil Corp., Gulf Mineral Resources Co.	7908090430	40-8725
	7908130571	40-8725
	7908170252	40-8725
	7908270519	40-8725
	7908270523*	40-8725
	7908270531*	40-8725
	7908270536*	40-8725
	7908270546*	40-8725
Gulf States Utilities Co.	7908030010*	50-458 Q
	7908030010*	50-458 Q
	7908070238	50-458 Q
	7908070238	50-458 Q
	7908090401	50-458 Q
	7908090401	50-458 Q
	7908090527	50-458 Q
	7908150099	50-458 Q
	7908200269	50-445 M
HEW, Dept. of, US Public Health Service	7908150479*	ORO
Hanford Conversion Project	7908030150	PR
Harper-Grace Hosps. Detroit, MI	7908290652	FOIA
Harvard Univ.	7908240494*	COMMISSION
	7908290167*	REGOD
Health, Education & Welfare, Dept. of	7908170603	PROJ
	7908300676	50-368 D
Hittman Nuclear & Development Corp. (subs. of Hittman Corp.)	7908090484	71-6574
	7908140399	71-24
	7908140406*	71-24
Hodder, M. H.	7908290073	50-389 Q
Hoke, Inc.	7908150476	XPORTLIC
	7908170194	XPORTLIC
Homestake Mining Co.	7908030586	40-8434
	7908030593*	40-8434
House of Rep.	7907260305*	50-320 U
	7907260324*	50-320 U
	7907310621*	COMMISSION
	7908010204*	50-293 U
	7908030384*	COMMISSION
	7908080275*	50-322 U
	7908140291*	COMMISSION
	7908210215	50-320 U
House of Rep., Government Operations	7908150013	50-463 U
House of Rep., Ways and Means	7908140506	50-466 U
Housing & Urban Development, Dept. of	7908070591	50-387 D
Houston Lighting & Power Co.	7908070393	50-498 S
	7908070393	50-498 S
	7908070400*	50-498 S
	7908070400*	50-498 S
	7908090386	50-498 S
	7908090526	50-498 Q
	7908090526	50-498 Q
	7908090532	50-498 Q
	7908090532	50-498 Q
	7908140441	50-498 A
	7908140441	50-498 A
	7908140668	50-498 A
	7908140668	50-498 A
	7908150104	50-498 Q
	7908150442*	50-466 A
	7908170358	50-498 A
	7908170372	50-498 Q
	7908230418	50-498 S
	7908230418	50-498 S
	7908230422*	50-498 S
	7908230422*	50-498 S
	7908290254	50-498 M
	7908310489	50-498 Q
Howmet Turbine Components Corp. (Subs. Pechiney Ugine Kuhlmann)	7908240531	71-329
	7908240534*	71-329
Huber, Magill, Lawrence & Farrell	7908170337	50-596 Q
Hunton & Williams	7908020570*	50-338 Q
	7908080040	50-338 Q
	7908080040	50-338 Q
	7908150252	50-338 Q
	7908150252	50-338 Q
	7908170563	50-338 Q
	7908170563	50-338 Q
	7908170569*	50-338 Q
	7908170569*	50-338 Q
IBM Corp.	7908150466*	50-320 H
ITT Grinnell Industrial Piping, Inc. (subs. of ITT Grinnell)	7908130625*	GA999
Ichthyological Associates, Inc.	7908090378*	50-320 R
	7908210373	50-320 R
	7908210374*	50-320 R
Idaho National Engineering Laboratory	7908010364	RES
	7908010375	RES
	7908010437	RES
	7908010447	RES
	7908010458	RES
	7908010534	RES
	7908020198	RES
	7908020474	RES
	7908020489	RES
	7908020576	RES
	7908030075	RES
	7908030082	RES
	7908030090	RES
	7908060117	NUREG
	7908240069	NUREG
Idaho, State of	7908170625	PROJ
	7908170629*	PROJ
Idaho, Univ. of	7908010173	PROJ
Ihrig, R.	7908240549	50-484 Q
	7908270539	50-484 Q
	7908270545*	50-484 Q
Illinois Environmental Council	7908270104*	50-10 D
Illinois Power Co.	7908020318	50-461 Q
	7908020318	50-461 Q
	7908070747	50-461 Q
	7908070747	50-461 Q
	7908080422*	50-461 Q
	7908150458	50-461 Q
	7908240634	50-461 Q
	7908290361	50-461 Q
Illinois Safe Energy Alliance	7908080294*	50-295 Q
Illinois, State of	7907110499	50-237 Q
	7908030528	27-39
	7908030536	27-39
	7908030561	50-367 Q
	7908090525	PROJ
	7908140032*	AGREEMENT
	7908160055	WASTE MGT
Illinois, State of, Dept. of Public Health	7908310065*	27-39

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
India	7908220609	PR
Indiana & Michigan Power Co.	7908010562	50-315 P
	7908030224	50-316 S
	7908030234*	50-316 S
	7908060233	50-315 P
	7908060233	50-315 P
	7908060241	50-315 H
	7908060241	50-315 H
	7908060312	50-316 S
	7908060316*	50-316 S
	7908060325*	50-316 S
	7908060345	50-315 P
	7908060345	50-315 P
	7908060416	50-315 S
	7908060422*	50-315 S
	7908060430*	50-315 S
	7908060433	50-316 I
	7908080366	50-315 Q
	7908080376	50-315 Q
	7908090311	50-316 Q
	7908090508	50-315 P
	7908130403	50-315 Q
	7908140558	50-315 P
	7908140558	50-315 P
	7908140559*	50-315 P
	7908140559*	50-315 P
	7908140632	50-316 S
	7908140637*	50-316 S
	7908140650	50-315 S
	7908140656*	50-315 S
	7908140750*	50-315 S
	7908150314	50-315 S
	7908150320*	50-315 S
	7908170341	50-316 R
	7908170343*	50-316 R
	7908170464	50-315 Q
	7908210511	50-316 S
	7908210517	50-315 S
	7908210521*	50-316 S
	7908210525*	50-315 S
	7908210527*	50-316 S
	7908210534*	50-315 S
	7908210541*	50-315 S
	7908210546*	50-315 S
	7908210551*	50-315 S
	7908220357	50-315 P
	7908230138*	50-315 Q
	7908240518	50-315 Q
	7908280572	50-315 F
	7908280572	50-315 F
	7908280610	50-315 H
	7908280610	50-315 H
	7908280664	50-315 P
	7908280664	50-315 P
	7908280671*	50-315 P
	7908280671*	50-315 P
	7908290423	50-315 S
	7908290439*	50-315 S
	7908310147	50-315 P
	7908310335	50-315 R
	7908310338*	50-315 R
Industrial Inspection Tr-st	7908220541	71-200
Inspection Services Corp.	7908270461	71-246
	7908270467*	71-246
Interior, Dept. of, U.S. Geological Survey	7908150466*	50-320 H
Interior, Dept. of	7908130215	50-445 M
	7908170258	PROJ
Interior, Dept. of, Bureau of Reclamation	7908200083	40-8721
Interior, Dept. of, Fish & Wildlife Service	7908020543	40-8721
	7908070636	50-596 A
	7908200077	40-8698
Interior, Dept. of, Geological Survey	7908010652	REGQD
	7908070535	DRQ
Interior, Dept. of, National Park Service	7908140408	40-8721
Interra Environmental Consultants, Inc.	7908030034	NUREG
Intervenor J.F. Doherty	7908220614	50-466 Q
	7908220662*	50-466 Q
Iowa Electric Light & Power Co.	7906210050*	PR
	7908010443	50-331 S
	7908020438	50-331 H
	7908030066	50-331 P
	7908030505	50-331 F
	7908070557	50-331 P
	7908090506	50-331 Q
	7908100130	50-331 Q
	7908100164	50-331 Q
	7908100418	50-331 S
	7908100423*	50-331 S
	7908130414	50-331 S
	7908130420*	50-331 E
	7908140150	50-321 Q
	7908140160	50-331 Q
	7908150045	50-331 S
	7908150050*	50-331 C
	7908150245	50-331 Q
	7908150328	50-331 P
	7908150328	50-331 P
	7908210473	50-331 P
	7908210502	50-331 F
	7908210514	50-331 R
	7908210516*	50-331 R
	7908230627	50-331 Q
	7908270426	50-331 P
	7908270443	50-331 P
	7908310370	50-331 S
	7908310377*	50-331 S
	7908310487	50-331 S
	7908310498*	50-331 S
Iowa Power	7908070513*	50-298 J
Iowa Public Interest Research Group	7908020561*	50-599 Q
Iowa Socialist Party	7908300533	50-599 Q
Isham, Lincoln & Beale	7906280112*	50-329 Q
	7908080170	50-599 Q
	7908080179	50-599 Q
	7908080378	50-295 Q
	7908150056	50-295 Q
	7908150420	50-329 Q
	7908170549	50-329 Q
	7908170549	50-329 Q
	7908220298	50-329 Q
	7908220298	50-329 Q
Isomedix, Inc. (subs. of Maesfield Enterprises, Inc.)	7908070838	71-9
	7908070843*	71-9
Isotope Products Laboratories	7908080022	XPORTLIC
Italy	7908170469*	FOIA
	7908220408	50-320 P
J. T. Baker Chemical Co. (subs. of Richardson-Merrell, Inc.)	7908020375	XPORTLIC
Japan	7908030228	XPORTLIC
	7908240299	XPORTLIC
Jersey Central Power & Light Co.	7908010686*	50-219 Q
	7908030503	50-363 A
	7908060223	50-219 S
	7908060229*	50-219 S
	7908060247	50-219 R
	7908060255*	50-219 R
	7908070584	50-219 S
	7908070589*	50-219 S
	7908070643	50-219 Q
	7908070675	50-363 Q
	7908070830	50-363 Q
	7908070845	50-219 Q
	7908080428	50-219 S
	7908080432*	50-219 S
	7908080489	50-363 Q
	7908090408	50-219 H
	7908130253	50-363 Q
	7908130259	50-219 Q
	7908140378	50-219 P
	7908140391*	50-219 P
	7908140670	50-219 S
	7908140676*	50-219 S
	7908160436	50-219 Q
	7908210012	50-219 F
	7908210300	50-219 P
	7908210307*	50-219 P
	7908210426	50-219 R
	7908230154	50-363 Q
	7908230353	50-219 S
	7908230355*	50-219 S
	7908240519	50-219 P
	7908240522*	50-219 P
	7908240539	50-219 P
	7908240543*	50-219 P
	7908270399	50-219 P
	7908270402*	50-219 P
	7908270469	50-219 P
	7908280017	50-219 F
	7908280106*	50-219 Q
	7908280111*	50-219 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908280689	50-219 S
	7908280701*	50-219 S
	7908310340	50-219 P
	7908310343*	50-219 P
Johns Hopkins Univ.	7908280002*	COMMISSION
Justice, Dept. of	7908130176	50-445 M
	7908130215	50-445 M
	7908130240	50-445 M
	7908130240	50-445 M
	7908130240	50-445 M
	7908130240	50-445 M
	7908130246	50-445 M
	7908130246	50-445 M
	7908130246	50-445 M
	7908130246	50-445 M
	7908200269	50-445 M
Kansas Gas & Electric Co.	7908100553*	50-482 G
	7908140524	50-482 A
	7908150138	50-482 G
	7908150641	50-482 A
Kansas State Univ.	7908230269	PR
Kentucky, State of	7908170632*	AGREEMENT
Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.)	7908220184	40-2061
	7908220192*	40-2061
Kerr-McGee Corp.	7908090638	40-8027
	7908140502	40-8027
	7908140507*	40-8027
	7908310109	40-8727
	7908310540*	40-8727
	7908310551*	40-8727
Kerr-McGee Nuclear Corp.	7908010071	40-8027
	7908010656	REGGD
	7908290218	70-925
Keystone Center for Continuing Education	7908280226	PROJ
Kingston, NY	7908170639	50-596 G
Kumpe & Associates, P.C.	7908210244*	40-1162
L. Bard - Intervenor	7908080293	50-592 G
	7908090292	50-592 G
Lake Michigan Federation	7908150107*	50-155 H
	7908150125*	50-155 H
	7908150139*	50-155 H
Laudig, S.	7908210483	50-546 H
Lawrence Livermore Laboratory	7908020425	RES
	7908030126	50-201 P
	7908080408	NUREG
	7908130292*	GEN TEC IS
	7908300239*	50-346 P
	7908300595	ORG
	7908310009	71-9033
LeBoeuf, Lamb, Leiby & MacRae	7908010564	50-341 K
	7908080441	50-244 P
	7908090510	50-244 G
	7908200142	50-452 G
League of Women Voters of Massachusetts	7908090285	50-471 G
League of Women Voters of Rockford, IL	7908030451	FOIA
	7908080156	50-454 G
	7908150341	50-454 G
	7908150341	50-454 G
	7908150354*	50-454 G
	7908150354*	50-454 G
Lead, Roger M.	7908070797	50-522 A
	7908080002	50-522 G
	7908150460	50-522 G
	7908300008	50-522 G
	7908300747	50-522 G
	7908300763	50-522 G
Lehigh Univ.	7908140631	RES
Long Island Lighting Co.	7908010334	50-322 A
	7908030208	50-322 G
	7908070460	50-322 G
	7908070784	50-516 G
	7908080484	50-516 G
	7908090633	50-322 G
	7908100100	50-322 G
	7908100323	50-322 F
	7908150010	50-322 A
	7908200197	50-322 F
	7908210020*	COMMISSION
	7908230093	50-322 G
	7908280576	50-322 A
	7908280579	50-516 F
	7908280651	50-322 G
	7908290732	50-516 G
Looney, Nichols, Johnson & Hayes	7908290254	50-498 M
Lorain Journal, Ohio	7908090083	50-346 P
Los Alamos Scientific Laboratory	7908030175	RES
	7908070803	NUREG
	7908080346	PROJ
	7908080355*	PROJ
	7908080358*	PROJ
	7908100387	NUREG
	7908140104	NUREG
	7908140649	RES
	7908150524	71-9006
	7908200085	71-6387
	7908220560	PROJ
	7908230079	PROJ
	7908290233	RES
Louisa County, VA	7908080733*	50-338 P
Louisiana Power & Light Co.	7908020276	50-382 G
	7908130398	50-382 A
	7908150111	50-382 G
	7908150145	50-382 G
	7908150150	50-382 G
	7908170487	50-382 S
	7908270465	50-382 K
	7908270472*	50-382 K
	7908310475	50-382 G
Lowell Technological Institute	7908280600	50-223 J
Lowell, Univ. of	7908010533	50-223 S
Lowenstein, Newman, Reis, Axelrad & Toll	7908070074	50-498 M
	7908080075	50-466 G
	7908080092	50-466 G
	7908150414	FOIA
	7908150432	50-466 A
	7908200341	FOIA
	7908210536	50-331 J
	7908220304	50-466 G
	7908220312	50-466 G
	7908220334	50-498 G
	7908300302	50-344 G
Lower Alloways Creek, NJ	7908080136	50-272 G
	7908080144*	50-272 G
Lucky Mc Uranium Corp.	7908010187	PROJ
Lumer, J.V.	7908290079	50-250 G
M.A.N. - Germany	7908090128*	REGGD
MHB Technical Associates	7908170445	FOIA
	7908220056	FOIA
MPR Associates, Inc.	7908010512*	50-155 P
Magnaflux Corp. (subs. of Peabody Caliou Corp.)	7908070804	71-5
	7908290036	71-5
	7908290040*	71-5
Maine Yankee Atomic Power Co.	7908010561	50-309 S
	7908010567*	50-309 S
	7908020106*	50-309 G
	7908020418	50-309 H
	7908020588	50-309 G
	7908030248	50-309 S
	7908030266*	50-309 S
	7908080313	50-309 G
	7908080710	50-309 G
	7908130457	50-309 P
	7908130460*	50-309 P
	7908140770	50-309 R
	7908140774*	50-309 R
	7908170362	50-309 G
	7908170364	50-309 F
	7908210356	50-309 P
	7908220437	50-309 P
	7908220637	50-309 G
	7908230325	50-309 F
	7908270517	50-309 G
Malcolm & Purnie, Inc.	7908310478	50-3 P
Marathon Oil Co.	7908160567	71-318
Marsh & McLennan, Inc.	7908140618	50-89 J
Marubeni America Corp. (subs. of Marubeni Corp.)	7906100378	XPORTLIC
	7908240524*	SECY
	7908240527*	SECY
	7908240530*	SECY
Maryland Shipbuilding & Drydock Co. (Subs. of Fruehauf Corp)	7908090177	71-31
	7908090179*	71-31
Maryland, Univ. of	7908010069	RES
	7908030191	RES
	7908170395	50-166 R
	7908290150*	COMMISSION
Massachusetts Institute of Technology	7908100570	71-6601
	7908150487*	ORG
	7908310402	50-20 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Massachusetts, State of	7908070629	50-471 Q
	7908100505	FOIA
	7908280045	FOIA
Materials Testing Laboratory	7908030091	71-111
	7908030097*	71-111
	7908280417*	71-126
Mathematical Applications, Inc.	7908140640	RES
	7908170077	FOIA
Matheson Gas Products	7908170281	XPORTLIC
Matthews, Nowlin, Macfarlane & Barnett	7908140386	50-498 M
	7908140386	50-498 M
	7908170336	50-498 M
	7908170336	50-498 M
Maynard Steel Casting Co.	7908020037	71-188
	7908020042*	71-188
McCullough, E. R.	7908080528	50-373 A
McCutchen, Doyle, Brown & Emerson	7908300032	PROJ
McGrath, E. J.	7908080717	PROJ
	7908090357	PROJ
	7908140152	PROJ
	7908170184	PROJ
	7908220180	PROJ
Medi-Physics, Inc.	7908240282	71-67
	7908240286*	71-67
Media Communications, Inc.	7908200408*	COMMISSION
Memphis State Univ.	7908150690	50-538 P
	7908150693*	50-538 P
Metals Testing Co., Inc.	7908150168	71-137
	7908150174*	71-137
Metils, Inc.	7908240051	71-338
	7908240055*	71-338
Metropolitan Edison Co.	7906150423	50-320 P
	7908010260	50-320 P
	7908010260	50-320 P
	7908010367	50-289 P
	7908010454	50-320 R
	7908010500	50-320 R
	7908010505	50-289 P
	7908010558	50-320 R
	7908010558	50-320 R
	7908060251	50-289 P
	7908070079	50-289 S
	7908070680	50-289 G
	7908080486	50-289 P
	7908090372	50-320 R
	7908090381	50-320 H
	7908100461	50-289 S
	7908100469*	50-289 S
	7908130409	50-289 P
	7908130472	50-289 S
	7908140515	50-320 H
	7908140515	50-320 H
	7908150719	50-289 G
	7908150721	50-289 G
	7908150723	50-289 G
	7908170354	50-289 F
	7908170354	50-289 F
	7908170426	50-289 S
	7908170430*	50-289 S
	7908170533	COMMISSION
	7908210378	50-289 G
	7908220010	50-320 H
	7908220010	50-320 H
	7908230329	50-320 P
	7908230331	50-320 P
	7908230342	50-289 P
	7908270438	50-289 R
	7908270444*	50-289 R
	7908280549	50-289 P
	7908280557	50-289 P
	7908280623	50-320 T
	7908280632	50-320 T
Michigan, State of	7908070201*	AGREEMENT
	7908130311*	50-329 A
	7908130317*	50-329 A
	7908140606*	50-155 H
	7908210210	50-320 H
	7908210355*	50-155 P
	7908300665	50-341 A
Michigan, Univ. of	7908070548	RES
	7908090342	50-358 Q
	7908090626	RES
	7908300600	RES
	7908300603*	RES
Micro Display Systems	7908170124	XPORTLIC
	7908170130*	XPORTLIC
Mid-America Coalition for Energy Alternatives	7908150298	50-482 Q
Midwest Environmental Protection Association	7908090509*	50-329 A
	7908150259	50-329 Q
Midwest Inspection Services, Inc.	7908140315	71-149
	7908140329*	71-149
Miller, Mannix, Lemery & Kafin	7908030007	50-596 Q
	7908300741	50-596 Q
Mississippi Power & Light Co.	7908020517	50-416 Q
	7908020517	50-416 Q
	7908020533	50-416 Q
	7908020533	50-416 Q
	7908030071	50-416 Q
	7908030071	50-416 Q
	7908030596*	50-416 Q
	7908080391	50-416 A
	7908140424	50-416 A
	7908140634	50-416 S
	7908140704	50-416 P
	7908140704	50-416 P
	7908160473	50-416 K
	7908160486*	50-416 K
	7908160486*	50-416 K
	7908160557	50-416 Q
	7908210007	50-416 F
	7908280687	50-416 A
	7908290445	50-416 S
	7908290586	50-416 Q
Missouri, State of	79_8210324	50-486 Q
	7908210326*	50-486 Q
Missouri, Univ. of, Columbia	7908140377	50-186 P
	7908150496	71-6697
Missouri, Univ. of, at Rolla	7908030540	50-123 Q
	7908080402	50-186 Q
	7908280497	50-123 Q
	7908310507	50-186 P
	7908310512*	50-186 P
	7908310516*	50-186 P
Mitsubishi International Corp. (subs. of Mitsubishi Corp.)	7908090010*	SECY
	7908090011*	SECY
	7908130629*	SECY
	7908130646*	SECY
	7908310520	XPORTLIC
	7908310525*	XPORTLIC
Mitsui & Co., Ltd.	7908100364	XPORTLIC
	7908100367*	XPORTLIC
	7908130136*	SECY
	7908140370*	SECY
	7908150558	XPORTLIC
	7908310505	XPORTLIC
Mitsuiline Travel Service of America, Inc.	7908160320	XPORTLIC
Monsanto Co.	7908170518	70-572
	7908170547*	70-572
	7908170557*	70-572
	7908170564*	70-572
	7908170567*	70-572
	7908170572*	70-572
Monsanto Research Corp.	7908080357	71-248
Morgan, Lewis & Bockius	7908080061	50-70 Q
Morrison Knudsen Company, Inc.	7908020123	71-9033
Murray, Plumb & Murray	7908090429*	50-309 Q
	7908090434*	50-309 Q
Myer, Baumann, Stroup & Flack	7908070621	50-424 A
N.M. Newmark Consulting Engineering Services	7908030521*	50-201 P
NL Industries, Inc.	7908240031	XPORTLIC
NL Industries, NL Nuclear Div.	7908140011	71-244
	7908140297	71-9023
NUS Corp.	7908010582	REGGD
National Academy of Sciences	7908170332*	COMMISSION
National Archives & Records Service	7908170317*	COMMISSION
	7908170322*	COMMISSION
National Evaluation Systems, Inc.	7908170085	FOIA
National Treasury Employee Union	7908280187	COMMISSION
	7908280378*	COMMISSION
	7908280400*	COMMISSION
	7908280428*	COMMISSION
Natural Resources Defense Council	7908030411	FOIA
	7908030413	50-269 P
	7908080610	FOIA
	7908080697	FOIA
	7908200076	70-2623

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908200387*	FOIA
	7908230298*	50-320 P
Navy, Dept of	7908010641	PR
	7908020212	RES
	7908020226	RES
	7908080372*	71-116
	7908080375*	71-116
	7908140384	71-85
	7908230673	71-261
	7908230675*	71-261
	7908270314	71-261
	7908270317*	71-261
Navy, Dept. of, Naval Nuclear Power Unit	7908080368	71-116
	7908140439	70-1207
	7908140590*	70-1207
Nebraska Public Power District	7908010555	50-298 S
	7908010557*	50-298 S
	7908070509	50-298 J
	7908070625	50-298 P
	7908080396	50-298 P
	7908080451	50-298 Q
	7908080465	50-298 Q
	7908080596	50-298 S
	7908080602*	50-298 S
	7908100196	50-298 Q
	7908100200	50-298 Q
	7908140557*	50-298 Q
	7908140549	50-298 Q
	7908140691	50-298 P
	7908140761	50-298 R
	7908140764*	50-298 R
	7908160006	50-298 Q
	7908160012	50-298 Q
	7908160034	50-298 Q
	7908170153	50-298 Q
	7908170161	50-298 Q
	7908210508	50-298 P
	7908210512	50-298 P
	7908310357	50-298 S
	7908310364*	50-298 S
	7908310415	50-298 S
	7908310420*	50-298 S
	7908310436	50-298 S
	7908310444*	50-298 S
Nebraska, State of	7908080437	NUREG
Nebraska, Univ. of	7908230592	NUREG
Nesco Electrical Products Corp.	7908020120*	27-39
Neutron Products, Inc.	7908010623	71-5364
	7908100335	71-6144
New Castle County, DE.	7908170433	50-272 Q
New Hampshire, State of	7908090398*	50-443 H
	7908090422*	50-443 H
New Jersey, State of	7908020386*	50-311 H
	7908090438	50-272 Q
	7908130251	50-272 Q
	7908150023	50-272 Q
	7908220039	50-272 Q
New Mexico, State of	7908020401	40-8726
	7908020404*	40-8726
	7908060484	40-8726
	7908060511	40-8726
	7908090464*	COMMISSION
	7908200398	PROJ
	7908200399*	PROJ
	7908200401*	PROJ
	7908230029	40-8726
New York State Electric & Gas Corp.	7908140522	50-596 B
	7908310504	50-596 C
	7908310504	50-596 C
	7908310508*	50-596 C
	7908310508*	50-596 C
New York Univ. Medical Center	7908240659	NUREG
New York, State Univ. of, Buffalo	7908150643	50-57 R
	7908150647*	50-57 R
New York, State of	7908010483	50-596 C
	7908010646	50-596 C
	7908030269	50-596 Q
	7908150011	50-596 Q
	7908150011	50-596 Q
	7908150076	50-596 Q
	7908150234	50-596 Q
	7908170253	50-596 Q
	7908210061	50-596 Q
	7908230256	50-596 Q
	7908300007	50-596 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908300224	50-596 Q
	7908300224	50-596 Q
	7908300248*	50-596 Q
	7908300248*	50-596 Q
	7908300732	50-596 Q
New York, NY	7908210091	50-320 H
Niagara Mohawk Power Corp.	7908010360	50-410 A
	7908010362	50-220 P
	7908010366	50-410 A
	7908010449	50-220 K
	7908010451*	50-220 K
	7908030024	50-410 Q
	7908030305	50-220 I
	7908030309*	50-220 I
	7908030377	50-220 F
	7908030385*	50-220 F
	7908030500	50-220 P
	7908030500	50-220 P
	7908070040	50-410 Q
	7908070311	50-220 Q
	7908070620	50-220 P
	7908070657	50-220 Q
	7908070661	50-220 Q
	7908070745	50-220 Q
	7908070795	50-410 Q
	7908080497	50-410 Q
	7908090192*	50-410 S
	7908130364	50-220 P
	7908140651	50-220 S
	7908140655*	50-220 S
	7908140660*	50-410 S
	7908150630	50-220 R
	7908150633*	50-220 R
	7908160450	50-410 A
	7908170080*	50-410 S
	7908170458	50-410 Q
	7908210112*	50-410 S
	7908210175	50-213 Q
	7908220381	50-220 P
	7908220381	50-220 P
	7908230088	50-410 Q
	7908240225*	50-410 Q
	7908240464	50-220 F
	7908240496	50-220 F
	7908240583	50-220 Q
	7908310414	50-220 P
	7908310416*	50-220 P
North Carolina State Univ.	7908090393	50-111 P
	7908170380	50-297 R
	7908170382*	50-297 R
	7908210174*	50-320 H
	7908210181*	50-320 H
	7908280390	50-111 P
	7908280390	50-111 P
	7908280396*	50-111 P
	7908280396*	50-111 P
	7908280403*	50-111 P
	7908280403*	50-111 P
North Carolina, State of	7908160431	50-400 A
	7908170215	PROJ
	7908280455	71-335
	7908280460*	71-335
North Carolina, Univ. of	7908020350	RES
	7908020387	RES
Northcutt Ely	7908130130	50-445 M
	7908200395	50-445 M
Northeast Nuclear Energy Co. (Northeast Utilities)	7908020083*	50-245 Q
	7908130046	50-245 Q
	7908160455	50-336 S
	7908160461*	50-336 S
	7908210587	50-213 P
	7908310384	50-245 Q
Northeast Utilities	7908010674	71-6601
	7908020590	50-423 Q
	7908030196	50-245 Q
	7908030299	50-336 S
	7908030300*	50-336 S
	7908060528	50-336 S
	7908060533*	50-336 S
	7908070573	50-245 S
	7908070579*	50-245 S
	7908070711	50-336 S
	7908080476	50-213 F
	7908080677	50-336 Q
	7908100263	50-423 A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908100445	50-245 S
	7908100452*	50-245 S
	7908140720	50-336 P
	7908140724	50-336 P
	7908160409	50-245 S
	7908160413*	50-245 S
	7908160428	50-336 P
	7908160441	50-336 R
	7908160444*	50-336 R
	7908160446	50-245 P
	7908160471	50-245 S
	7908160477*	50-245 S
	7908160575	50-423 Q
	7908170365	50-336 Q
	7908170410	50-336 S
	7908170415*	50-336 S
	7908200253	50-213 Q
	7908200369	50-336 P
	7908200373*	50-336 P
	7908210401	50-213 F
	7908210401	50-213 F
	7908210549	50-245 R
	7908210552*	50-245 R
	7908210579	50-336 P
	7908220613	50-213 Q
	7908220613	50-213 Q
	7908220613	50-213 Q
	7908220618*	50-213 Q
	7908220618*	50-213 Q
	7908220618*	50-213 Q
	7908220622*	50-213 Q
	7908220622*	50-213 Q
	7908220622*	50-213 Q
	7908270525	50-245 Q
	7908280568	50-245 P
	7908280711	50-245 S
	7908280724*	50-245 S
	7908290597	50-336 P
	7908300642	50-336 P
	7908310400	50-336 P
	7908310502	50-336 P
Northern Illinois Univ.	7908020031*	50-10 P
Northern Indiana Public Service Co.	7908030147	50-367 R
	7908070757	50-367 Q
	7908070768*	50-367 Q
	7908070305	50-367 Q
	7908140320	50-367 Q
	7908140491	50-367 R
	7908160426	50-367 A
	7908220270	50-367 R
	7908220333	50-367 R
	7908230333	50-367 R
	7908230341*	50-367 R
	7908300494	50-367 A
Northern States Power Co.	7908010518	50-484 A
	7908010554	50-263 R
	7908010560*	50-263 R
	7908010584	50-263 F
	7908020214*	50-263 P
	7908030482	50-263 Q
	7908030489*	50-263 Q
	7908060267	50-282 R
	7908060267	50-282 R
	7908060375	50-282 P
	7908060379*	50-282 P
	7908060516	71-6144
	7908060534	50-262 S
	7908060541*	50-262 S
	7908070048	50-282 Q
	7908070370	50-263 Q
	7908080455	50-263 P
	7908080455	50-263 P
	7908080538	50-282 Q
	7908090560	50-263 S
	7908090565*	50-263 S
	7908090595	50-282 Q
	7908090595	50-282 Q
	7908100160	50-263 Q
	7908100429	50-263 S
	7908100435*	50-263 S
	7908130402	50-263 P
	7908130407	50-282 Q
	7908130407	50-282 Q
	7908130439	50-263 Q
	7908130444*	50-263 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908140309	50-263 P
	7908140319	50-263 Q
	7908140759	50-282 R
	7908140759	50-282 R
	7908140765*	50-282 R
	7908140766	50-263 R
	7908140769*	50-263 R
	7908140775	50-263 S
	7908140783*	50-263 S
	7908150090*	50-282 Q
	7908150335	50-263 P
	7908160363	50-282 Q
	7908160363	50-282 Q
	7908160437	50-282 R
	7908160440*	50-282 R
	7908160440*	50-282 R
	7908200290	50-282 S
	7908200293*	50-282 S
	7908210319	50-263 H
	7908210319	50-263 H
	7908210319	50-263 H
	7908210321*	50-263 H
	7908220227	50-263 Q
	7908220243*	50-263 Q
	7908230311	50-282 F
	7908230316	50-263 F
	7908240508	50-263 S
	7908240511*	50-263 S
	7908240628	50-263 Q
	7908270463	50-263 Q
	7908280540	50-282 S
	7908280540	50-282 S
	7908280542*	50-282 S
	7908280542*	50-282 S
	7908280555	50-263 F
	7908280586	50-282 S
	7908280591*	50-282 S
	7908310544	50-263 R
	7908310549*	50-263 R
Northrop Corp.	7908220430	50-187 J
NucleDyne Engineering Corp.	7908030570*	NUREG
	7908030592*	NUREG
	7908060481*	NUREG
	7908060485*	NUREG
Nuclear Assurance Corp.	7908070788	71-18
	7908070792*	71-18
	7908100587	71-18
	7908100590*	71-18
	7908200088	71-6698
	7908200092*	71-6698
Nuclear Dynamics	7908090364	40-8663
	7908140191*	40-8663
Nuclear Energy Liability Insurance Association	7908230205*	50-358 Q
Nuclear Energy Service, Inc.	7908020216	71-9007
Nuclear Engineering Co.	7908090498	27-48
	7908300368	71-6144
	7908300376	71-6272
	7908300383	71-6400
	7908300389	71-6058
	7908300395	71-6679
Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.)	7908020046*	71-6400
	7908020049*	71-6400
	7908030605	70-143
	7908090448	71-198
	7908130378	70-143
	7908140024	70-143
	7908140159	70-143
	7908140210	70-143
	7908140327	70-143
	7908140367	50-201 F
	7908140459	50-201 P
	7908150031	70-143
	7908150043	70-143
	7908150242	70-143
	7908160361*	70-143
	7908170067	70-143
	7908210130*	70-143
	7908210606	70-143
	7908220224	70-143
	7908220224	70-143
	7908220679	50-201 R
	7908230301	70-1257
	7908240152*	70-143
	7908240157*	70-143

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908270275	70-143
	7908290511	50-201 J
	7908300506	70-143
	7908300554	70-143
Nuclear Fuel Services, Inc., West Valley Reprocessing Plant	7908230653	50-201 R
	7908230656*	50-201 R
Nuclear Packaging, Inc.	7908090294	71-9097
Nuclear Systems, Gamma Industries Div.	7908230560	71-9133
	7908230564*	71-9133
Nuclear Systems, Inc., Gamma Industries, Inc. Div.	7908010297	71-10
	7908100325	71-9039
Nucor Corp.	7908140188	40-8663
Oak Ridge National Laboratory	7905160395	50-568 D
	7908010472	RES
	7908020135	RES
	7908020184	RES
	7908020329	RES
	7908020379	RES
	7908020462	RES
	7908030231	RES
	7908030244	RES
	7908070694	NUREG
	7908070781	NUREG
	7908080102	50-471 Q
	7908080504	RES
	7908090536	NUREG
	7908140349	RES
	7908140356*	RES
	7908140568	RES
	7908140575	RES
	7908140584	RES
	7908140592	RES
	7908140610	RES
	7908140622	RES
	7908200001	PROJ
	7908210109	ACRS
	7908210197	50-320 A
	7908210501	50-320 P
	7908230679	NUREG
	7908240668	NUREG
	7908270100	NUREG
	7908270273	RES
Office of Management & Budget	7908030491*	COMMISSION
	7908230520*	COMMISSION
Ogle Petroleum, Inc.	7908080258	40-8693
Ohio, State of	7908020528*	50-346 Q
	7908090208	50-346 P
Omaha Public Power District	7908010498	50-285 P
	7908010553	50-285 H
	7908070631	50-285 P
	7908070651	50-285 P
	7908080406	50-285 Q
	7908080459	50-285 Q
	7908080531	50-285 Q
	7908140394	50-285 P
	7908140603	50-285 P
	7908140683	50-285 Q
	7908140755	50-285 R
	7908140758*	50-285 R
	7908160038	50-285 Q
	7908160041	50-285 Q
	7908160439	50-285 Q
	7908170239	50-285 Q
	7908170524	50-285 Q
	7908210441	50-285 S
	7908210450*	50-285 S
	7908210465*	50-285 S
	7908210587	50-285 S
	7908220300	50-285 F
	7908230671*	50-285 Q
	7908270405	50-285 F
	7908270415	NUREG
	7908290244	50-285 Q
	7908300650	50-285 P
Oregon State Univ.	7908240488	50-243 P
Oregon, State of	7908080709	PROJ
Oregon, Univ. of, School of Law	7908080751	FOIA
Originala, Inc.	7908210182	XPORTLIC
	7908210188	XPORTLIC
Orincon Corp.	7908240119	NUREG
	7908240125	NUREG
	7908240135	NUREG
	7908240142	NUREG
Osann, E. W.	7908030561	50-367 Q
Oswego, NY	7908020392	50-596 Q
Our Lady of the Lourdes Hosp., Camden, NJ	7908170363*	70-2319
PRC Sys Svcs Co.	7908220402	50-320 P
Pacific Gas & Electric Co.	7908010462	50-133 P
	7908010531	50-344 H
	7908010614	REGGD
	7908080675	50-275 Q
	7908090227*	50-275 S
	7908100175	50-133 Q
	7908130421	50-275 Q
	7908150241*	50-275 Q
	7908150520	50-133 P
	7908150520	50-133 P
	7908160018	50-275 Q
	7908170359	50-344 *
	7908170526*	50-275 S
	7908200047	50-133 Q
	7908200316	50-344 P
	7908200319*	50-344 P
	7908210384	50-133 R
	7908210387*	50-133 R
	7908220428	50-275 F
	7908230612	50-275 K
	7908230612	50-275 K
	7908230615*	50-275 K
	7908230619*	50-275 K
	7908280427	50-133 Q
	7908300032	PROJ
	7908300713	50-133 P
	7908300718*	50-133 P
	7908300722*	50-133 P
	7908300725*	50-133 P
Pacifica Technology	7908140695*	50-285 Q
Paddlewheel Alliance	7908160024	50-546 Q
Painesville, OH	7908010222	50-440 Q
Par Systems Corp.	7908090145	XPORTLIC
	7908090151*	XPORTLIC
Parameter, Inc.	7908090075*	50-331 S
Parkwell Laboratories, Inc.	7908130299	70-1379
PathFinder Mines Corp.	7908080265	40-2259
	7908310006	40-2259
Patton, Boggs & Blow	7908060047	FOIA
Pennsylvania Power & Light Co.	7908030340	50-387 A
	7908060256	50-387 A
	7908060256	50-387 A
	7908070288	50-387 Q
	7908070462	50-387 Q
	7908070668	50-387 K
	7908070668	50-387 K
	7908070682*	50-387 K
	7908070682*	50-387 K
	7908080011	50-387 Q
	7908080060	50-387 Q
	7908080060	50-387 Q
	7908140430	50-387 S
	7908140430	50-387 S
	7908140630	50-387 A
	7908140630	50-387 A
	7908140753*	50-387 S
	7908150655	50-387 A
	7908200277*	50-387 Q
	7908280032	50-387 F
	7908280670	50-387 A
	7908290660	50-387 Q
	7908290660	50-387 Q
	7908300038	50-387 Q
	7908300038	50-387 Q
Pennsylvania State Univ.	7908030516*	PRM
	7908280546	50-395 D
	7908310350	50-5 F
Pennsylvania, State of	7908080015	50-387 Q
	7908080015	50-387 Q
	7908080018*	50-387 Q
	7908080018*	50-387 Q
	7908090470	PROJ
	7908230455*	50-320 H
	7908300779*	COMMISSION
Pequea, PA.	7908200137*	50-463 Q
Perkins, Coie, Stone, Olsen & Williams	7908150012	50-522 Q
	7908150012	50-522 Q
	7908170326	50-522 Q
	7908170350	50-522 Q
	7908170350	50-522 Q
	7908300004	50-522 Q
	7908300004	50-522 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908300724	50-522 Q
	7908300724	50-522 Q
Petrotomics, Inc.	7908170227	40-6659
Pfizer, Inc.	7908150440	FOIA
Philadelphia Electric Co.	7907240386	50-278 S
	7908010312	50-277 S
	7908010432	50-277 P
	7908010456	50-277 S
	7908010456	50-277 S
	7908010536	50-277 S
	7908010536	50-277 S
	7908010546*	50-277 S
	7908010546*	50-277 S
	7908020431	50-277 R
	7908020431	50-277 R
	7908020436*	50-277 R
	7908020436*	50-277 R
	7908020465	50-277 S
	7908020465	50-277 S
	7908020469*	50-277 S
	7908020469*	50-277 S
	7908030133	50-277 P
	7908030141*	50-277 P
	7908030141*	50-277 P
	7908060387	50-278 P
	7908060397*	50-278 P
	7908070698	50-277 Q
	7908080628	50-277 Q
	7908100494	50-278 S
	7908100492	50-277 S
	7908130277	50-277 Q
	7908130461	50-278 S
	7908140454	50-277 F
	7908150506	50-277 S
	7908150506	50-277 S
	7908150511*	50-277 S
	7908150511*	50-277 S
	7908150581	50-277 P
	7908150581	50-277 P
	7908150588*	50-277 P
	7908150588*	50-277 P
	7908150600	50-277 S
	7908160447	50-277 R
	7908160447	50-277 R
	7908160451*	50-277 R
	7908160451*	50-277 R
	7908160565	50-277 Q
	7908160576	50-352 Q
	7908170274	50-171 P
	7908170274	50-171 P
	7908200002	50-277 Q
	7908200002	50-277 Q
	7908200005	50-352 Q
	7908200301*	50-352 Q
	7908210531	50-278 S
	7908230135	50-277 Q
	7908230135	50-277 Q
	7908230335	50-277 F
	7908230335	50-277 F
	7908230479	50-277 P
	7908230479	50-277 P
	7908230482*	50-277 P
	7908230482*	50-277 P
	7908240405	50-277 P
	7908240466	50-277 P
	7908240466	50-277 P
	7908240470*	50-277 P
	7908240470*	50-277 P
	7908290444	50-277 S
	7908290444	50-277 S
	7908290455*	50-277 S
	7908290571*	50-277 P
	7908290571*	50-277 P
	7908290575	50-277 P
	7908290583	50-171 P
	7908290589*	50-171 P
	7908300691	50-171 R
Philippines	7908030189*	50-574 Q
	7908090683*	50-574 Q
	7908090683*	50-574 Q
Picker Corp.	7908280765	71-5796
Pittsburgh, Univ. of	7908170295*	COMMISSION
Plateau Resources, Ltd.	7908010655	40-8698
	7908010659	40-8698
	7908140368	40-8698
	7908300710	40-8674
	7908310068	40-8674
	7908310081*	40-8674
Portland General Electric Co.	7908010492	50-344 P
	7908060389	50-344 F
	7908070371	50-344 F
	7908070552	50-344 Q
	7908080020	50-344 Q
	7908080067	50-344 Q
	7908080467	50-344 P
	7908080469	50-344 R
	7908080473*	50-344 R
	7908090601	50-344 Q
	7908130387	50-344 S
	7908130389*	50-344 S
	7908140790	50-344 S
	7908140795*	50-344 S
	7908150618	50-344 P
	7908150623*	50-344 P
	7908170424	50-344 P
	7908210480	50-344 F
	7908220030	50-275 Q
	7908270363	50-344 P
	7908270401	50-344 P
	7908270411*	50-344 P
	7908280022	50-344 F
	7908280683	50-344 P
	7908300302	50-344 Q
Potomac Alliance	7908300754	50-338 Q
Power Authority State of New York	7908010489	50-286 F
	7908020420	50-286 Q
	7908020422	50-333 F
	7908020435	50-333 P
	7908060441	50-333 S
	7908060448*	50-333 S
	7908060461	50-333 S
	7908060471*	50-333 S
	7908060479	50-333 S
	7908060500*	50-333 S
	7908060521	50-333 S
	7908060527*	50-333 S
	7908070362	50-286 S
	7908070501	50-333 Q
	7908070593	50-333 R
	7908070599*	50-333 R
	7908070650	50-333 Q
	7908070808	50-333 Q
	7908140510	50-286 R
	7908140516*	50-286 R
	7908140564	50-286 Q
	7908140626	50-333 Q
	7908150676	50-333 P
	7908160568	50-286 Q
	7908160570	50-286 Q
	7908170324	50-286 P
	7908170324	50-286 P
	7908170328*	50-286 P
	7908170328*	50-286 P
	7908170432	50-286 S
	7908170435*	50-286 S
	7908200314	50-333 P
	7908210539	50-286 Q
	7908210544	50-333 P
	7908220359	50-333 P
	7908220364	50-333 J
	7908230360	50-286 Q
	7908280013	50-333 F
	7908280020	50-286 F
	7908280551	50-286 Q
	7908280601	50-333 P
	7908280700	50-286 P
	7908280828	50-333 Q
	7908290436	50-333 S
	7908290464*	50-333 S
	7908290673	50-333 Q
	7908300646	50-333 R
	7908300649*	50-333 R
	7908310564	50-286 P
	7908310568*	50-286 P
President of US & Executive Offices	7908020241*	50-280 U
	7908080670*	COMMISSION
President's Commission on the Accident at Three Mile Island	7908130486	50-320 T
	7908150771	50-320 H
Princeton Univ.	7908170280*	50-10 P
Public Citizen Litigation Group	7908150735*	50-320 H

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908310300*	PR
Public Law Utilities Group	7908030418	50-382 Q
Public Service Co. of Colorado	7908010066	50-267 Q
	7908010448	50-267 P
	7908010480	50-267 P
	7908010501	50-267 P
	7908070500	50-267 S
	7908070518*	50-267 S
	7908070684	50-267 S
	7908070686*	50-267 S
	7908080399	50-267 Q
	7908080445*	50-267 S
	7908080470	50-267 Q
	7908130430	50-267 R
	7908130432*	50-267 R
	7908140199	50-267 Q
	7908140499	50-267 R
	7908140504*	50-267 R
	7908140597	50-267 P
	7908140599	50-267 P
	7908160337	50-267 R
	7908160345*	50-267 R
	7908200381	50-267 P
	7908200388*	50-267 P
	7908200392	50-267 S
	7908200394	50-267 S
	7908210050	50-267 P
	7908220296	50-267 P
	7908220370	50-267 S
	7908220376*	50-267 S
	7908240499	50-267 F
	7908290605	50-267 R
	7908300529	50-267 S
	7908300539*	50-267 S
	7908310320	50-267 S
	7908310325*	50-267 S
	7908310328	50-267 S
	7908310331*	50-267 S
	7908310347	50-267 S
	7908310353*	50-267 S
	7908310404	50-267 P
	7908310458	50-267 P
	7908310464*	50-267 P
Public Service Co. of Indiana, Inc.	7908060180*	50-456 Q
	7908060189*	50-456 Q
	7908080514	50-546 Q
	7908080546	50-546 Q
	7908150445	50-546 Q
	7908170398	50-546 H
	7908200134*	50-556 A
	7908200291	50-546 A
	7908200295*	50-546 A
	7908200295*	50-546 A
	7908280565*	50-546 Q
	7908290304	50-546 Q
	7908290304	50-546 Q
	7908290500	50-546 S
Public Service Co. of New Hampshire	7908070344	50-443 Q
	7908070705	50-443 Q
	7908080353	50-443 Q
	7908080516	50-443 Q
	7908090368	50-443 A
	7908140535*	50-443 A
	7908240589	50-443 Q
	7908270471	50-443 I
Public Service Co. of Oklahoma	7908010573	50-556 A
	7908150481	50-556 A
Public Service Electric & Gas Co. of New Jersey	7908010149	50-272 Q
	7908010315	50-272 S
	7908010329	50-272 S
	7908010336	50-272 S
	7908010450	50-272 R
	7908010495	50-272 R
	7908010495	50-272 R
	7908010537	50-272 R
	7908010537	50-272 R
	7908010540	50-272 R
	7908010540	50-272 R
	7908020057*	50-272 Q
	7908030151	50-272 R
	7908030163*	50-272 R
	7908030187	50-354 Q
	7908030215	50-272 S
	7908030221*	50-272 S
	7908030455	50-272 S
	7908030463*	50-272 S
	7908070785	50-272 Q
	7908070785	50-272 Q
	7908080149*	50-311 A
	7908080277	50-272 Q
	7908090002	50-354 Q
	7908100156	50-272 P
	7908100442	50-311 E
	7908140404	50-272 P
	7908140419*	50-272 P
	7908140732	50-272 P
	7908140738*	50-272 P
	7908140818	50-272 S
	7908140820*	50-272 S
	7908160442	50-311 Q
	7908170186	50-354 Q
	7908170471	50-272 Q
	7908170471	50-272 Q
	7908200194	50-272 F
	7908200298	50-272 H
	7908200339	50-272 P
	7908200366	50-272 R
	7908200367*	50-272 R
	7908220631	50-272 Q
	7908220634	50-272 Q
	7908230112	50-354 Q
	7908240601*	50-311 S
	7908280636	50-272 R
	7908280643*	50-272 R
	7908290705	50-354 Q
	7908300512	50-311 A
	7908300520	50-311 A
	7908300546	50-272 S
	7908300557*	50-272 S
	7908300628	50-272 S
	7908300636*	50-272 S
	7908300661	50-311 A
	7908310395	50-272 Q
Puget Sound Power & Light Co.	7908140544	50-522 A
	7908140682*	50-522 Q
	7908300024	50-522 Q
	7908300024	50-522 Q
	7908300028*	50-522 Q
	7908300028*	50-522 Q
	7908300034*	50-522 Q
	7908300034*	50-522 Q
	7908300047*	50-522 Q
	7908300047*	50-522 Q
	7908300051*	50-522 Q
	7908300051*	50-522 Q
	7908300617	50-522 Q
Pullman, Inc., Pullman Power Products Div.	7908100097*	QA999
	7908100109*	QA999
Purdue Univ.	7908130031	ACRS
	7908130612	70-152
Reactor Experiments, Inc.	7908150478	XPORTLIC
	7908150490	XPORTLIC
Reilly, Like & Schneider	7908090433	50-322 A
Research Triangle Institute	7908160435*	50-338 S
Resources for The Future, Inc.	7908200400*	PROJ
Reuter-Stokes, Inc.	7908020383	XPORTLIC
	7908150565	XPORTLIC
	7908160056	XPORTLIC
Rhode Island, State of	7908070057*	AGREEMENT
	7908100474	50-568 D
	7908310533	50-193 F
	7908310536*	50-193 F
Rochester Gas & Electric Corp.	7908010379	50-244 P
	7908010496	50-244 H
	7908010551	50-244 F
	7908030383	50-244 F
	7908070049	50-485 Q
	7908070452	50-244 Q
	7908070634	50-244 Q
	7908080446*	50-244 P
	7908080671	50-244 Q
	7908090330	50-244 Q
	7908090511*	50-244 Q
	7908100471	50-244 S
	7908100475*	50-244 S
	7908140570	50-244 J
	7908140788	50-244 S
	7908140800*	50-244 S
	7908170385	50-244 P
	7908200346	50-244 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908210001	50-244 F
	7908210369	50-244 R
	7908210370*	50-244 R
	7908210437	50-244 S
	7908210490	50-244 P
	7908210515	50-244 S
	7908210524*	50-244 S
	7908230093	50-244 G
	7908230107	50-244 G
	7908240391	50-244 H
	7908270521	50-244 S
	7908280725	50-244 S
	7908280731*	50-244 S
	7908290174	50-244 G
	7908290177*	REGGD
Rockwell International Corp.	7908010559	50-320 P
	7908020039	71-9070
	7908020182	71-9033
	7908020221	71-6144
	7908080423	NUREG
	7908090442	70-25
	7908150437	XPORTLIC
	7908150444	XPORTLIC
	7908270368	71-141
Rocky Mountain Energy Co.	7908030003	40-8452
	7908030006*	40-8452
	7908060503	40-8452
	7908100584	40-8452
	7908140195	40-8721
	7908210084	40-8380
	7908210087*	40-8380
	7908220215	40-8721
	7908230035	40-8697
	7908230227	40-8697
	7908230233*	40-8697
Rogow, B.	7908140488*	50-250 U
Ropes & Gray	7908080328	50-471 G
	7908100441	50-443 I
	7908140530	50-443 A
	7908150392	50-471 G
	7908210272	50-443 I
	7908210510	50-443 I
	7908280615	50-443 I
SNUPPS-Standardized Nuclear Unit Power Plant System	7908070526	50-482 G
	7908080332	50-482 G
	7908200006	50-482 G
SPEX Industries, Inc.	7908080661	XPORTLIC
Sacramento Municipal Utility District	7908010350	50-312 P
	7908020222	50-312 G
	7908060252	50-312 P
	7908070470	50-312 G
	7908070521	50-312 P
	7908100331	50-312 S
	7908100337*	50-312 S
	7908100478	50-312 S
	7908100482*	50-312 S
	7908140473	50-312 R
	7908140482*	50-312 R
	7908150276	50-312 G
	7908170293	50-312 G
	7908200219	50-312 F
	7908200370	50-312 S
	7908200372*	50-312 S
	7908240388	50-312 P
Sandia Laboratories	7908010274	RES
	7908020301	RES
	7908030034	NUREG
	7908030044	NUREG
	7908080521	RES
	7908090543	NUREG
	7908100296	RES
	7908100304	RES
	7908150243	PROJ
	7908270486	PROJ
Sandvik Special Metals Corp.	7908300380	XPORTLIC
	7908300384	XPORTLIC
	7908300420	XPORTLIC
Santa Barbara County, CA	7908150279*	50-275 H
	7908150287*	50-275 H
Sargent & Lundy, Inc.	7908060120*	50-10 G
	7908170416	TOPREP
	7908290328*	50-546 G
	7908300503*	50-367 A
Savannah River Ecology Laboratory	7908300366*	WASTE MGT
Save the Valley - Save Marble Hill	7908150281	50-546 G
	7908150306	50-546 H
Schultz, W.B.	7908310296	PR
	7908310300*	PR
Science Applications, Inc.	7908150423	FOIA
Self Powered Lighting,Ltd.	7908300436	XPORTLIC
	7908300443*	XPORTLIC
Senate	7907310621*	COMMISSION
	7908140470	50-250 U
	7908230016	50-320 U
Senate, Governmental Affairs	7908210056	50-358 U
Senate,Committee on Human Resources	7908030193*	COMMISSION
Shaw, Pittman, Potts, & Trowbridge	7908060452	50-346 M
	7908070648	50-346 M
	7908080011	50-387 G
	7908080029	50-387 G
	7908080029	50-387 G
	7908080060	50-387 G
	7908080060	50-387 G
	7908150383	50-484 G
	7908150762	50-320 P
	7908160260*	50-346 P
	7908170289	50-282 G
	7908220026	50-387 G
	7908230238	50-320 P
	7908240554*	50-484 G
	7908300021	50-387 G
	7908300021	50-387 G
Sheldon, Harmon, Roisman & Weiss	7908010538	50-443 G
	7908010538	50-443 G
	7908010544*	50-443 G
	7908010544*	50-443 G
	7908080585	FOIA
	7908150083	FOIA
	7908300264	50-568 G
	7908300264	50-568 G
	7908300281*	50-568 G
	7908300281*	50-568 G
	7908310437	50-320 P
	7908310586	FOIA
Sierra Club	7908210365	50-387 D
	7908210522	50-387 D
Skagitonians Concerned About Nuclear Plants	7908300008	50-522 G
	7908300010*	50-522 G
Snell & Wilmer	7908130028	50-592 -
Soiltest, Inc.	7908210080	XPORTLIC
South Carolina Electric & Gas Co.	7908010355	50-395 A
	7908080099	50-395 G
	7908160280	50-395 G
	7908160325	50-395 G
	7908210359	50-395 D
	7908230234	50-395 G
	7908230391	50-395 F
	7908230558	50-395 S
	7908240087*	50-395 G
	7908280638	50-395 P
	7908280642*	50-395 P
	7908310111	50-395 G
South Carolina, State of	7908140355*	AGREEMENT
	7908230540*	COMMISSION
	7908300654	50-395 D
South Carolina, Univ. of	7908010357*	50-395 A
South Dakota, State of	7908170248	40-1341
Southern California Edison Co.	7908010577	50-361 S
	7908010577	50-361 S
	7908010585*	50-361 S
	7908010585*	50-361 S
	7908020219	50-206 G
	7908030160	50-206 P
	7908030182	50-206 P
	7908030186*	50-206 P
	7908070739	50-361 G
	7908080394	50-206 P
	7908090699*	50-361 G
	7908100490	50-206 P
	7908130405	50-206 H
	7908130405	50-206 H
	7908130467	50-361 S
	7908130467	50-361 S
	7908140487	50-206 R
	7908140494*	50-206 R
	7908150253	50-206 P
	7908150311*	50-361 G
	7908160358	50-361 M
	7908160358	50-361 M
	7908160358	50-361 M

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908160427	50-361 S
	7908160427	50-361 S
	7908160432*	50-361 S
	7908160432*	50-361 S
	7908170384	50-361 A
	7908170434	50-361 A
	7908200153	50-206 P
	7908210395	50-206 R
	7908210398*	50-206 R
	7908230376	50-206 H
	7908280410	50-206 Q
	7908280433	50-361 Q
	7908290474	50-206 F
	7908300215*	50-206 S
Southern California, Univ. of	7908240673	NUREG
Southwest Econometrics, Inc.	7908010629	REGGD
	7908080452	TOPREP
Space Science Services, Inc.	7908010015	71-215
Spain	7908130375	XPORTLIC
Spiegel & McDiarmid	7908080525	50-445 M
	7908080535	50-445 M
	7908200097	50-445 M
	7908220092	50-445 M
Spraying Systems Co.	7908140736	TOPREP
	7908140752*	TOPREP
Stanford Univ.	7908060090	FOIA
State, Dept. of	7908010346	XPORTLIC
	7908020043	XPORTLIC
	7908020048	XPORTLIC
	7908020050	XPORTLIC
	7908020054	XPORTLIC
	7908020059	XPORTLIC
	7908020063	XPORTLIC
	7908020245	XPORTLIC
	7908080506	XPORTLIC
	7908100376	XPORTLIC
	7908100377	XPORTLIC
	7908100557	XPORTLIC
	7908130653*	SECY
	7908150534	XPORTLIC
	7908220165	50-320 P
	7908220171*	50-320 P
	7908230284	50-320 P
	7908230306*	50-320 P
	7908230343	XPORTLIC
	7908230408	XPORTLIC
	7908230424*	10CFR
	7908240624	XPORTLIC
State, Dept. of, Bureau of Oceans & Internatl Environ. & Scientific Affairs	7908010520	XPORTLIC
	7908010530	XPORTLIC
	7908080463	XPORTLIC
	7908130141*	SECY
	7908130157*	SECY
	7908160063	XPORTLIC
	7908160067	XPORTLIC
	7908240538*	SECY
	7908240553*	SECY
Steptoe & Johnson	7908090120	FOIA
Stone & Webster Engineering Corp.	7908010387	50-495 A
	7908010580*	50-334 P
	7908020481*	50-280 P
	7908090483*	50-334 P
Stone & Webster, Inc.	7908090518	PROJ
	7908130485*	QA999
	7908230602	50-495 B
	7908230605*	50-495 B
Suffolk County, NY	7908010276*	50-516 Q
	7908010287*	50-516 Q
	7908080239*	50-322 A
Susquehanna Alliance	7908210311	50-387 D
Sweden	7908030023	XPORTLIC
Swepco Tube Corp.	7908090092*	QA999
Syracuse Univ., College of Law	7908080729	FOIA
TERA Corp.	7908150393*	70-8
	7908150652*	70-1257
	7908220084*	70-25
Tech/Ops (Technical Operations, Inc.)	7908100373	71-40
	7908100374*	71-40
	7908290422	70-9021
Teledyne Engineering Services	7908290267*	50-285 Q
Teledyne Geotech	7908230642	NUREG
Tennessee State Univ.	7908200115*	50-518 F
Tennessee Valley Authority	7908010158	50-259 Q
	7908010320	70-1622
	7908010332*	70-1622
	7908010341	50-327 S
	7908010341	50-327 S
	7908010347*	50-327 S
	7908010347*	50-327 S
	7908010388	50-390 S
	7908010388	50-390 S
	7908010390	50-296 S
	7908010393*	50-296 S
	7908010395*	50-390 S
	7908010395*	50-390 S
	7908010398	50-327 S
	7908010398	50-327 S
	7908010400	50-327 S
	7908010400	50-327 S
	7908010402*	50-327 S
	7908010402*	50-327 S
	7908010408*	50-327 S
	7908010408*	50-327 S
	7908010434	50-438 S
	7908010434	50-438 S
	7908010438*	50-438 S
	7908010438*	50-438 S
	7908010548	50-259 S
	7908010552*	50-259 S
	7908010692	50-327 Q
	7908020023	50-259 Q
	7908020075*	50-553 Q
	7908020432	50-390 S
	7908020432	50-390 S
	7908020447	50-260 S
	7908020451*	50-260 S
	7908020453	50-327 S
	7908020453	50-327 S
	7908020455*	50-327 S
	7908020455*	50-327 S
	7908020482	50-327 S
	7908020482	50-327 S
	7908020485*	50-327 S
	7908020485*	50-327 S
	7908020488	50-390 S
	7908020488	50-390 S
	7908020490*	50-390 S
	7908020490*	50-390 S
	7908020496	50-260 S
	7908020502*	50-260 S
	7908030020	71-6375
	7908030058	50-327 S
	7908030058	50-327 S
	7908030062*	50-327 S
	7908030062*	50-327 S
	7908030074	50-390 S
	7908030074	50-390 S
	7908030081*	50-390 S
	7908030081*	50-390 S
	7908030086	50-327 S
	7908030086	50-327 S
	7908030092*	50-327 S
	7908030092*	50-327 S
	7908030337	50-390 S
	7908030344*	50-390 S
	7908030376	50-259 S
	7908030404	50-390 S
	7908030404	50-390 S
	7908030410	50-390 S
	7908030410	50-390 S
	7908030417*	50-390 S
	7908030417*	50-390 S
	7908030419*	50-390 S
	7908030419*	50-390 S
	7908030427	50-438 S
	7908030427	50-438 S
	7908030432*	50-438 S
	7908030432*	50-438 S
	7908060142	50-327 Q
	7908060142	50-327 Q
	7908060142	50-327 Q
	7908060142	50-327 Q
	7908060142	50-327 Q
	7908060142	50-327 Q
	7908060142	50-327 Q
	7908060235*	50-566 Q
	7908060245	50-259 P
	7908060245	50-259 P
	7908060245	50-259 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908060286	50-438 S
	7908060286	50-438 S
	7908060344	50-390 S
	7908060344	50-390 S
	7908060417	50-259 P
	7908060417	50-259 P
	7908060417	50-259 P
	7908060427	50-327 F
	7908060437	50-259 F
	7908060437	50-259 F
	7908060437	50-259 F
	7908060510	50-390 S
	7908060510	50-390 S
	7908060519*	50-390 S
	7908070149*	50-390 Q
	7908070357	50-259 K
	7908070357	50-259 K
	7908070357	50-259 K
	7908070366*	50-259 K
	7908070366*	50-259 K
	7908070366*	50-259 K
	7908070671	50-259 R
	7908070671	50-259 R
	7908070671	50-259 R
	7908080519	50-296 P
	7908080541	50-390 A
	7908080541	50-390 A
	7908080572	50-390 A
	7908080572	50-390 A
	7908080597*	50-390 A
	7908080734	50-518 Q
	7908090494	40-1341
	7908100425	50-259 S
	7908100432*	50-259 S
	7908100487	50-259 Q
	7908100487	50-259 Q
	7908100487	50-259 Q
	7908140163	70-2443
	7908140166*	70-2443
	7908140334	50-259 Q
	7908140411	50-390 K
	7908140411	50-390 K
	7908140414*	50-390 K
	7908140414*	50-390 K
	7908140445	50-259 R
	7908140451*	50-259 R
	7908140451*	50-259 R
	7908140451*	50-259 R
	7908140532	50-259 R
	7908140540	50-390 S
	7908140540	50-390 S
	7908140548*	50-390 S
	7908140548*	50-390 S
	7908140552	50-259 P
	7908140552	50-259 P
	7908140552	50-259 P
	7908140556*	50-259 P
	7908140556*	50-259 P
	7908140556*	50-259 P
	7908140563	50-438 S
	7908140565	50-259 P
	7908140565	50-259 P
	7908140565	50-259 P
	7908140672	50-518 S
	7908140672	50-518 S
	7908140672	50-518 S
	7908140672	50-518 S
	7908140672	50-518 S
	7908140672	50-518 S
	7908140681	50-438 S
	7908140681	50-438 S
	7908140684*	50-518 S
	7908140684*	50-518 S
	7908140684*	50-518 S
	7908140684*	50-518 S
	7908140684*	50-518 S
	7908140684*	50-518 S
	7908140685*	50-438 S
	7908140685*	50-438 S
	7908140706	50-327 S
	7908140706	50-327 S
	7908140715*	50-327 S
	7908140715*	50-327 S
	7908140731	50-438 S
	7908140731	50-438 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908140803	50-327 S
	7908140803	50-327 S
	7908140807	50-259 S
	7908140808*	50-327 S
	7908140808*	50-327 S
	7908140816*	50-259 S
	7908140838	50-438 S
	7908140838	50-438 S
	7908140843*	50-438 S
	7908140843*	50-438 S
	7908150322*	50-438 Q
	7908150322*	50-438 Q
	7908150372*	50-438 Q
	7908150372*	50-438 Q
	7908150469	50-259 H
	7908150469	50-259 H
	7908150469	50-259 H
	7908150469	50-259 H
	7908150469	50-259 H
	7908150503	50-390 S
	7908150503	50-390 S
	7908150508*	50-390 S
	7908150508*	50-390 S
	7908150526	50-327 S
	7908150526	50-327 S
	7908150535*	50-327 S
	7908150535*	50-327 S
	7908150545	50-390 S
	7908150545	50-390 S
	7908150550*	50-390 S
	7908150550*	50-390 S
	7908150622	50-327 S
	7908160070	50-259 Q
	7908160070	50-259 Q
	7908160070	50-259 Q
	7908160112	71-6722
	7908160304	50-259 Q
	7908160304	50-259 Q
	7908160304	50-259 Q
	7908170208	50-390 Q
	7908170334	50-259 P
	7908170442	50-327 A
	7908170442	50-327 A
	7908170442	50-327 A
	7908170449*	50-327 A
	7908170454*	50-327 A
	7908170517	50-327 Q
	7908170517	50-327 Q
	7908170517	50-327 Q
	7908170517	50-327 Q
	7908170517	50-327 Q
	7908170610	70-2443
	7908210301	50-550 A
	7908210314	50-259 F
	7908210425	50-296 S
	7908210429*	50-296 S
	7908210550	50-390 K
	7908230384	50-518 S
	7908230384	50-518 S
	7908230384	50-518 S
	7908230384	50-518 S
	7908230402*	50-518 S
	7908230402*	50-518 S
	7908230402*	50-518 S
	7908230402*	50-518 S
	7908230451	50-518 S
	7908230451	50-518 S
	7908230451	50-518 S
	7908230451	50-518 S
	7908230451	50-518 S
	7908230460*	50-518 S
	7908230460*	50-518 S
	7908230460*	50-518 S
	7908230460*	50-518 S
	7908230460*	50-518 S
	7908230460*	50-518 S
	7908230475	50-259 Q
	7908230475	50-259 Q
	7908230566	50-390 S
	7908230566	50-390 S
	7908230575*	50-390 S
	7908230575*	50-390 S
	7908230589	50-518 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908230589	50-518 S
	7908230589	50-518 S
	7908230589	50-518 S
	7908230589	50-518 S
	7908230589	50-518 S
	7908230596*	50-518 S
	7908230596*	50-518 S
	7908230596*	50-518 S
	7908230596*	50-518 S
	7908230596*	50-518 S
	7908230596*	50-518 S
	7908240177	50-390 A
	7908240177	50-390 A
	7908240183*	50-390 A
	7908240183*	50-390 A
	7908240243*	50-259 G
	7908240254*	50-259 G
	7908270185*	50-259 G
	7908270272	50-390 G
	7908270272	50-390 G
	7908270272	50-390 G
	7908270326	50-259 G
	7908280556	50-327 A
	7908280556	50-327 A
	7908280581	50-327 S
	7908280581	50-327 S
	7908280581	50-327 S
	7908280581	50-327 S
	7908280585*	50-327 S
	7908280585*	50-327 S
	7908280585*	50-327 S
	7908280585*	50-327 S
	7908280599	50-390 S
	7908280606	50-553 S
	7908280606	50-553 S
	7908280611*	50-553 S
	7908280611*	50-553 S
	7908280691	50-296 S
	7908280695*	50-296 S
	7908280698	50-327 S
	7908280698	50-327 S
	7908280702*	50-327 S
	7908280702*	50-327 S
	7908280732	50-260 S
	7908280742*	50-260 S
	7908290421	50-390 S
	7908290426	50-390 S
	7908290438*	50-390 S
	7908290438*	50-390 S
	7908290502	50-438 G
	7908290636	50-259 G
	7908290636	50-259 G
	7908300516	50-553 G
	7908300682	50-327 S
	7908300682	50-327 S
	7908300688	50-327 A
	7908300688	50-327 A
	7908300707*	50-327 S
	7908300707*	50-327 S
Tennessee, Univ. of	7908140182	PR
Teton Exploration Drilling Co., Inc.	7908280277	40-8728
	7908280290*	40-8728
	7908280299*	40-8728
	7908310047	40-8728
Texas A & M Univ.	7908290421	50-128 P
Texas Instruments, Inc.	7908130657	70-33
	7908140016	70-33
	7908150517	70-33
	7908160466	50-247 R
	7908230252	70-33
	7908290626	70-33
Texas Utilities Co.	7908130115	50-445 M
Texas Utilities Generating Co.	7908020225	50-445 G
	7908020225	50-445 G
	7908020271	50-445 G
	7908020271	50-445 G
	7908030440*	50-445 M
	7908090524	50-445 G
	7908090524	50-445 G
	7908140427	50-445 K
	7908140427	50-445 K
	7908140432*	50-445 K
	7908140432*	50-445 K
	7908140446	50-445 S
	7908140446	50-445 S
	7908140541	50-445 S
	7908140541	50-445 S
	7908150134	50-445 G
	7908160001	50-445 S
	7908160357	50-445 G
	7908170112	50-445 S
	7908170112	50-445 S
	7908170120	50-445 S
	7908200324	50-445 F
	7908200324	50-445 F
	7908210295	50-445 S
	7908210295	50-445 S
	7908210377	50-445 S
	7908220327	50-445 K
	7908220623	50-445 G
	7908220623	50-445 G
	7908310021	50-445 G
	7908310021	50-445 G
Texas Utilities Services, Inc.	7908010490	50-445 A
	7908090467	50-445 A
	7908090514	50-445 A
	7908090515	50-445 A
Texas, State of	7907260001	50-510 G
	7907260001	50-510 G
	7907260002*	50-510 G
	7907260002*	50-510 G
	7908010539	REGGD
	7908080072	50-466 G
	7908080072	50-466 G
	7908130076	50-466 G
	7908130089	50-466 G
	7908130261	50-445 M
	7908130406	PROJ
	7908230077	50-466 G
The Stanwick Corp.	7908280408	71-111
The Sun Baltimore, MD	7908140811	FOIA
The Tribune Chronicle, Warren, OH	7908210406	50-320 G
The Washington Journalism Center	7908210168*	COMMISSION
The Washington Monitor	7908310037	FOIA
Thorne Ecological Institute	7908290616*	50-267 R
Todd Shipyards	7908100582	71-189
Toledo Coalition for Safe Energy	7908160248*	50-346 P
	7908160255*	50-346 P
	7908160299*	50-346 P
Toledo Edison Co.	7908010313	50-346 G
	7908010361	50-346 P
	7908020442	50-346 P
	7908030610	50-346 G
	7908060435	50-346 S
	7908060439*	50-346 S
	7908060447	50-346 S
	7908060450*	50-346 S
	7908060453	50-346 S
	7908060455*	50-346 S
	7908070491	50-346 S
	7908070496*	50-346 P
	7908070595	50-346 P
	7908070688	50-346 S
	7908070692*	50-346 S
	7908080093	50-346 G
	7908090568	50-346 S
	7908090573*	50-346 S
	7908100195	50-346 H
	7908100198*	50-346 H
	7908100403	50-346 S
	7908100406*	50-346 S
	7908100453	50-346 P
	7908100462	50-346 S
	7908100467*	50-346 S
	7908100496	50-346 S
	7908100501*	50-346 S
	7908100583	50-346 G
	7908130416	50-346 G
	7908140109	50-346 G
	7908140460	50-346 R
	7908140465*	50-346 R
	7908140478	50-346 P
	7908140527	50-346 P
	7908140602	50-346 P
	7908140611*	50-346 P
	7908140793	50-346 S
	7908140797*	50-346 S
	7908150502	50-346 S
	7908150504*	50-346 S
	7908160113	50-346 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908170412	50-346 F
	7908200113	50-346 G
	7908210433	50-346 S
	7908210439*	50-346 S
	7908210444	50-346 S
	7908210448*	50-346 S
	7908210459	50-346 S
	7908210460*	50-346 S
	7908210526	50-346 F
	7908220432	50-346 P
	7908220434*	50-346 P
	7908230387	50-346 S
	7908230390*	50-346 S
	7908230495	50-346 S
	7908230499	50-320 S
	7908230499	50-320 S
	7908230507*	50-320 S
	7908230507*	50-320 S
	7908230523	50-346 S
	7908230529*	50-346 S
	7908280716	50-346 S
	7908280721*	50-346 S
	7908310423	50-346 S
	7908310425*	50-346 S
Touche Ross & Co.	7908230245*	50-320 P
Toward Utility Rate Normalization	7908300230*	50-206 S
Trans World Airlines, Inc.	7908290611	71-9033
Transnuclear, Inc.	7908100135	XPORTLIC
	7908100139	XPORTLIC
	7908100514	XPORTLIC
	7908100516*	XPORTLIC
	7908130078*	SECY
	7908130084*	SECY
	7908130109*	SECY
	7908130630	70-1426
	7908140018	70-1426
	7908140021	70-1426
	7908150189	XPORTLIC
	7908150197*	XPORTLIC
	7908150301	XPORTLIC
	7908150574	XPORTLIC
	7908150579*	XPORTLIC
	7908160083	70-1426
	7908170417	70-1426
	7908210558	XPORTLIC
	7908300337	XPORTLIC
	7908300342*	XPORTLIC
	7908310456	XPORTLIC
Transportation, Dept of	7908140299*	COMMISSION
	7908170394	50-387 D
Trends Publishing, Inc.	7908140716	FOIA
Tri-State Motor Transit Co. (subs. of Georgia Pacific Corp.)	7908240191	70-1739
URS/John A. Blume & Assoc. Engineers (subs. of URS)	7908070709	NUREG
US Steel Corp.	7908210229*	50-320 P
Union Carbide Corp.	7908010161	PROJ
	7908130586	40-299
	7908160350	71-109
	7908160353*	71-109
	7908170211	40-299
	7908210407	40-299
	7908210411*	40-299
	7908220557	40-299
	7908310091	40-229
	7908310333	50-54 F
Union Electric Co.	7908020255	50-483 G
	7908020255	50-483 G
	7908020261	50-483 G
	7908020261	50-483 G
	7908130118*	50-483 G
	7908200292	50-483 S
	7908200294*	50-483 S
Union Minerals	7908130290	40-8636
	7908160005	40-8584
	7908170191	40-8636
Union Pump Co.	7908070171*	GA999
	7908070182*	GA999
	7908070185*	GA999
United Kingdom	7908160078	XPORTLIC
United Nuclear Corp.	7908020229	71-6357
	7908090528	70-820
	7908090567*	70-820
	7908140476	71-241
	7908140479*	71-241
	7908200413	71-9019

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908220169	70-371
United Nuclear Corp., UNC Recovery Systems Div.	7908090367	70-820
	7908090374*	70-820
	7908170218	70-820
	7908170619	70-820
	7908210602	70-820
	7908080009*	GA999
Unitime Corp.	7908010181	PROJ
Utah, State of	7908060491	40-8681
	7908170344*	COMMISSION
Valentine B. Deale*	7908080007	50-272 G
Valore, C.	7908130370*	GA999
Velan Valve Co.	7908130373*	GA999
Ventron Corp. (subs. of Thiokol Corp.)	7908020374	XPORTLIC
Ventura Safe Energy Council	7908090096	FOIA
Vermont Yankee Nuclear Power Corp.	7908010277	50-271 P
	7908010581	50-271 H
	7908060440	50-271 S
	7908060444*	50-271 S
	7908070653	50-271 G
	7908080181	50-271 G
	7908090001	50-271 G
	7908130440	50-271 P
	7908140429	50-271 R
	7908140437*	50-271 R
	7908140443	50-271 F
	7908140648	50-271 S
	7908140658*	50-271 S
	7908200419	50-271 G
	7908210414	50-271 S
	7908210417*	50-271 S
	7908220306	50-271 F
	7908220350	50-271 P
	7908230130	50-271 G
	7908230436	50-271 P
	7908240580	50-271 G
	7908280604	50-271 S
	7908280616*	50-271 S
Virginia Electric & Power Co.	7908010354	50-280 P
	7908010354	50-280 P
	7908010396	50-339 S
	7908010431	50-281 J
	7908010515	50-280 H
	7908010683	50-404 G
	7908010701*	50-281 G
	7908010718	71-6058
	7908020269	50-404 G
	7908020478	50-280 P
	7908020562	50-338 G
	7908020562	50-338 G
	7908020567*	50-338 G
	7908020567*	50-338 G
	7908030345	50-338 S
	7908030348	50-280 P
	7908030348	50-280 P
	7908030348	50-280 P
	7908030367	50-338 S
	7908030448	50-280 S
	7908030456*	50-280 S
	7908030595	50-338 S
	7908030607*	50-339 A
	7908060003	50-280 G
	7908060172	50-338 G
	7908060243	50-280 G
	7908060278	50-339 S
	7908060292*	50-438 S
	7908060301*	50-339 S
	7908060369	50-338 S
	7908070494	50-338 S
	7908070497*	50-338 S
	7908070577	50-338 S
	7908070583*	50-338 S
	7908070743	50-280 G
	7908070743	50-280 G
	7908070743	50-280 G
	7908070743	50-280 G
	7908070789	50-280 G
	7908090104	50-338 G
	7908080109	50-338 G
	7908080151	50-280 G
	7908080151	50-280 G
	7908080151	50-280 G
	7908080151	50-280 G
	7908090427	50-338 G
	7908090489	50-280 G

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7908090546	50-338 K
	7908090546	50-338 K
	7908090550*	50-338 K
	7908090550*	50-338 K
	7908090569	50-338 P
	7908090571*	50-338 P
	7908100305	50-338 S
	7908100312*	50-338 S
	7908100407	50-339 S
	7908100464	50-280 Q
	7908130352	50-338 R
	7908130355*	50-338 R
	7908130452	50-280 P
	7908130452	50-280 P
	7908130454	50-338 S
	7908130459*	50-338 S
	7908130465	50-280 P
	7908140438	50-280 P
	7908140438	50-280 P
	7908140450	50-339 A
	7908140553	50-339 S
	7908150192	50-339 S
	7908150200*	50-280 Q
	7908150247*	50-280 Q
	7908150365	50-339 Q
	7908150578	50-339 A
	7908150673	50-404 A
	7908160348	50-280 R
	7908160348	50-280 R
	7908160352*	50-280 R
	7908160354	50-281 P
	7908160355*	50-281 P
	7908160429	50-338 S
	7908160433*	50-338 S
	7908160445	50-338 P
	7908160445	50-338 P
	7908160467	50-280 P
	7908160467	50-280 P
	7908160479	50-280 S
	7908160479	50-280 S
	7908160484*	50-280 S
	7908160484*	50-280 S
	7908170058	50-404 Q
	7908170160	50-280 Q
	7908200118	50-339 S
	7908200368	50-280 S
	7908200376*	50-280 S
	7908210002	50-280 F
	7908210002	50-280 F
	7908210003	50-338 F
	7908210003	50-338 F
	7908210309	50-338 P
	7908210309	50-338 P
	7908210410	50-338 P
	7908210420	50-280 F
	7908210420	50-280 F
	7908220025	50-280 Q
	7908220406*	50-338 Q
	7908230239	50-280 Q
	7908230448	50-339 S
	7908230467	50-230 P
	7908240156*	50-281 Q
	7908240422	50-338 S
	7908240427*	50-338 S
	7908240452	50-404 A
	7908240485	50-338 S
	7908240493*	50-338 S
	7908240498*	50-338 S
	7908240506	50-338 P
	7908240506	50-338 P
	7908270462	50-338 P
	7908270462	50-338 P
	7908280558	50-404 A
	7908280558	50-404 A
	7908280559	50-338 S
	7908280560	50-404 A
	7908280560	50-404 A
	7908280588	50-281 P
	7908280649	50-338 S
	7908280653*	50-338 S
	7908280660	50-280 S
	7908280667*	50-280 S
	7908280750	50-338 S
	7908280759*	50-338 S
	7908300727	50-339 S
Virginia Polytechnic Institute & State Univ.	7908310018	50-280 Q
	7908010494	RES
Virginia, State of	7908140068	NUREG
	7908080726*	50-338 P
	7908130404	PROJ
	7908140521*	FOIA
	7908170496*	50-280 H
Virginia, Univ. of	7908020515	50-62 S
	7908310547	50-62 F
Vollen, R. J.	7908030561	50-367 Q
W. J. Woolley Co.	7908090122	XPORTLIC
Walworth Co. (subs. of IU International Corp.)	7908140103	71-255
	7908140110*	71-255
Washington Public Power Supply System	7908010365	50-397 S
	7908010369*	50-397 S
	7908060364	50-397 K
	7908070714	50-508 Q
	7908070715*	50-397 Q
	7908070725	50-460 Q
	7908070725	50-460 Q
	7908080326	REGGD
	7908080492	50-397 A
	7908090499	50-305 Q
	7908130340*	50-508 Q
	7908130431	50-460 Q
	7908130431	50-460 Q
	7908130441	50-508 Q
	7908140657	50-397 A
	7908150560	50-397 S
	7908150568*	50-397 S
	7908150682	50-397 S
	7908150688*	50-397 S
	7908160015	50-508 Q
	7908200361	50-397 S
	7908200362	50-397 A
	7908200365*	50-397 S
	7908230067*	50-460 Q
	7908280387	50-397 Q
Washington State Univ.	7908140712	50-27 R
	7908140717*	50-27 R
Washington Univ.	7908070659	NUREG
Washington, State of	7908140333	PROJ
Washington, Univ. of	7908020433	RES
	7908310405	50-139 P
Waters, McPherson, Hudzin & McNeill	7908140835	FOIA
Welding Institute of Alaska	7908150329	71-131
	7908150333*	71-131
West Chicago, IL	7908070824	40-2061
West Valley Nuclear Wastes	7908140301	50-201 Q
Western Nuclear, Inc. (subs. of Phelps Dodge Corp.)	7908030566	40-1162
	7908170176	40-1162
	7908210204	40-1162
	7908210217*	40-1162
	7908210221*	40-1162
	7908210225*	40-1162
	7908210228*	40-1162
	7908210230*	40-1162
	7908210240*	40-1162
Westinghouse Electric Corp.	7907190672	REGGD
	7908010465	TOPREP
	7908010471*	TOPREP
	7908010481*	TOPREP
	7908010487*	TOPREP
	7908010488*	TOPREP
	7908020113	71-9009
	7908020560	XPORTLIC
	7908030253*	XPORTLIC
	7908030259*	XPORTLIC
	7908060098	FOIA
	7908090493	71-6400
	7908090584*	50-316 Q
	7908100029	50-275 S
	7908130040	PT21
	7908130531	70-1151
	7908130542	70-1151
	7908140088	70-1143
	7908140123	70-1151
	7908140139	70-1143
	7908140170	70-1151
	7908140471	TOPREP
	7908140594	71-5450
	7908150048	71-6272
	7908150141	XPORTLIC

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	7908150169*	TOPREP	
	7908150484	XPORTLIC	
	7908150570	XPORTLIC	
	7908150587*	70-1151	
	7908150654	TOPREP	
	7908160051	XPORTLIC	
	7908160106	XPORTLIC	
	7908160571	70-1143	
	7908160571	70-1143	
	7908170220	XPORTLIC	
	7908170403	TOPREP	
	7908170407*	TOPREP	
	7908170623*	70-1151	
	7908200251	FOIA	
	7908200304	TOPREP	
	7908200307*	TOPREP	
	7908200310*	TOPREP	
	7908200313*	TOPREP	
	7908200317*	FOIA	
	7908210594	70-1143	
	7908210598*	70-1143	
	7908220253	XPORTLIC	
	7908220424*	XPORTLIC	
	7908220664	XPORTLIC	
	7908220666*	XPORTLIC	
	7908270131	70-1151	
	7908290664*	FOIA	
	7908300110	50-338	Q
	7908300596	XPORTLIC	
	7908310493	TOPREP	
	7908310495	XPORTLIC	
Wheatley & Wolleson	7908290254	50-498	M
White Rock & District Council of Women (B.C.)	7908300521	50-522	Q
Widoff, Reager, Selkowitz & Adler	7908090160	50-321	Q
Wisconsin Electric Power Co.	7908010381	50-301	S
	7908010383	50-266	P
	7908010385*	50-301	S
	7908020423	50-266	H
	7908020437	50-266	F
	7908020437	50-266	F
	7908020471	50-502	I
	7908060537	50-266	G
	7908070412	50-596	C
	7908080475	50-266	Q
	7908080475	50-266	Q
	7908080553	50-266	Q
	7908090416	50-266	Q
	7908140330	50-301	Q
	7908140401	50-266	R
	7908140401	50-266	R
	7908140409*	50-266	R
	7908140409*	50-266	R
	7908140687	50-266	P
	7908140760	50-266	P
	7908150230	50-266	Q
	7908150230	50-266	Q
	7908150547	50-266	P
	7908160448	50-266	R
	7908160448	50-266	R
	7908210313	50-502	C
	7908270420	50-266	S
	7908270427*	50-266	S
	7908270434*	50-266	S
	7908270470	50-502	A
	7908270473	50-266	P
	7908290411	50-266	F
	7908300740	50-266	Q
Wisconsin Industrial Testing, Inc.	7908240483	71-342	
	7908240484*	71-342	
Wisconsin Public Service Corp.	7908010372	50-305	P
	7908010457	50-305	H
	7908010569	50-305	S
	7908010572*	50-305	S
	7908020267*	50-305	Q
	7908070755	50-305	Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	7908080401	50-305	S
	7908080403*	50-305	S
	7908080695	50-305	Q
	7908130427	50-305	Q
	7908140382	50-305	R
	7908140387*	50-305	R
	7908150434	50-305	Q
	7908210146	50-305	Q
	7908220326	50-305	F
	7908230290	50-305	Q
	7908300612	50-309	Q
	7908300616*	50-309	Q
	7908310526	50-305	R
	7908310530*	50-305	R
Wisconsin, State of	7908270417	50-502	C
Wisconsin, Univ. of, Madison	7908010542	50-156	R
	7908010549*	50-156	R
	7908010681	REGD	
	7908140607	50-156	P
	7908310298	50-156	P
Wold Nuclear Co.	7908010675	40-8636	
Woodward-Clyde Consultants	7908010665*	40-8698	
	7908010672*	40-8698	
	7908170438*	50-361	A
	7908300714	40-8674	
	7908300784	FOIA	
Worsham, Forsythe & Sampels	7908130188	50-445	M
	7908130201*	50-445	M
	7908080714	PT21	
Wright State Univ.	7908080617*	50-390	A
Wyle Laboratories			
Wyoming Mineral Corp.	7908140027	40-8502	
	7908200071	40-8502	
	7908240622	40-8502	
	7908240623*	40-8502	
Wyoming Outdoor Council	7908230275	40-8721	
Wyoming, State of	7908010306	PROJ	
	7908140175	40-8693	
X-Ray, Inc.	7908090490	71-234	
	7908090495*	71-234	
Yankee Atomic Electric Co.	7908010326	50-309	F
	7908020108	71-6574	
	7908020440	50-29	S
	7908020445*	50-29	S
	7908030172	50-29	Q
	7908030204	50-29	S
	7908070673	50-29	Q
	7908070712	50-29	Q
	7908080317*	50-271	P
	7908140365	50-29	R
	7908140373*	50-29	R
	7908140550	50-29	P
	7908140661	50-29	S
	7908140666*	50-29	S
	7908160563	50-29	Q
	7908170421	50-29	F
	7908200304	50-29	Q
	7908240460	50-29	P
	7908240463*	50-29	P
	7908270511	50-29	Q

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index titled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY		OTHER REPORT NUMBER
10348-5	7908080579*	50-390	A	
43522-1	7908080617*	50-390	A	
44T-1844	7908160435*	50-338	S	
491HA689	7908160472*	50-280	P	
507	7908080597*	50-390	A	
79-2	7908010357*	50-395	A	
7908010069	7908010069	RES		
7908010240	7908010240	RES		
7908010256	7908010256	RES		
7908010274	7908010274	RES		
7908010283	7908010283	RES		
7908010301	7908010301	RES		
7908010333	7908010333	RES		
7908010342	7908010342	RES		
7908010352	7908010352	RES		
7908010364	7908010364	RES		TFBP-TR-321
7908010375	7908010375	RES		CAAP-TR-052
7908010437	7908010437	RES		20-100
7908010447	7908010447	RES		SEMI-TR-005
7908010458	7908010458	RES		CDAP-TR-056
7908010472	7908010472	RES		ORNL/ED/EIS-94
7908010494	7908010494	RES		
7908010516	7908010516	RES		
7908010534	7908010534	RES		GLR-L2-3
7908010545	7908010545	RES		BNL-NUREG-26325
7908010563	7908010563	RES		
7908010579	7908010579	RES		BNL-NUREG-26051
7908010591	7908010591	RES		BNL-NUREG-26162
7908020135	7908020135	RES		ORNL/NUREG/TM-3
7908020152	7908020152	RES		BNL-NUREG-26237
7908020184	7908020184	RES		
7908020198	7908020198	RES		SEMI-TR-007
7908020212	7908020212	RES		
7908020226	7908020226	RES		
7908020239	7908020239	RES		
7908020266	7908020266	RES		
7908020275	7908020275	RES		
7908020283	7908020283	RES		
7908020292	7908020292	RES		
7908020301	7908020301	RES		
7908020317	7908020317	RES		
7908020329	7908020329	RES		
7908020350	7908020350	RES		
7908020362	7908020362	RES		
7908020372	7908020372	RES		
7908020379	7908020379	RES		ORNL/HASRD-41
7908020387	7908020387	RES		
7908020425	7908020425	RES		
7908020433	7908020433	RES		
7908020454	7908020454	RES		
7908020462	7908020462	RES		
7908020474	7908020474	RES		TFBP-TR-320
7908020476	7908020576	RES		
7908020489	7908020489	RES		SEMI-TR-006
7908020519	7908020519	50-213	E	BNL-NUREG-26171
7908020600	7908020600	RES		
7908030075	7908030075	RES		CAAP-TR-048
7908030082	7908030082	RES		RE-P-79-043
7908030090	7908030090	RES		TFBP-TR-323
7908030175	7908030175	RES		WX-8-2986
7908030191	7908030191	RES		
7908030231	7908030231	RES		
7908030244	7908030244	RES		ORNL/ED/EIS-93
7908070548	7908070548	RES		
7908070548	7908070547*	RES		
7908080487	7908080487	RES		GLR-L3-0
7908080504	7908080504	RES		ORNL/FTR-645
7908080521	7908080521	RES		
7908080537	7908080537	RES		CAAP-TR-047
7908080557	7908080557	RES		
7908080571	7908080571	RES		LTR-141-103
7908080583	7908080583	RES		
7908090626	7908090626	RES		
7908100296	7908100296	RES		
7908100304	7908100304	RES		
7908140339	7908140339	RES		
7908140356	7908140356*	RES		
7908140568	7908140568	RES		ORNL/ED/EIS-95
7908140575	7908140575	RES		ORNL/ED/EIS-96
7908140584	7908140584	RES		ORNL/HASRD-44
7908140592	7908140592	RES		ORNL/FTR-646
7908140610	7908140610	RES		ORNL/ED/EAS-79/
7908140622	7908140622	RES		ORNL/HASRD-43
7908140631	7908140631	RES		
7908140640	7908140640	RES		
7908140649	7908140649	RES		
7908140659	7908140659	RES		
7908160172	7908160172	RES		
7908160172	7908160188*	RES		
7908170500	7908170500	RES		LTR 20-103
7908270273	7908270273	RES		ORNL/FTR-628
7908270342	7908270342	RES		
7908290233	7908290233	RES		WX-8-2984
7908300600	7908300600	RES		
7908300600	7908300603*	RES		
BAW-10038A	7908010660*	TOPREP		
BAW-10051A	7908020516*	TOPREP		
BAW-1552	7908100287*	50-269	P	
BAW-1564	7908210299*	TOPREP		
BNL-NUREG-26429	7908140005	TOPREP		
CEN-114-P	7908100465*	50-255	P	
CEN-114-P A 01	7908100465*	50-255	P	
CENPD-225	7908240449*	TOPREP		
CENPD-252-NP-A	7908090555*	TOPREP		
EDR-1	7908300672*	TOPREP		
EPRI-N4-768	7908170493	PROJ		NP-768
F-C5115	7908100447*	50-311	E	
FBDU 218-1	7908170465	PROJ		
GEAP-NUREG-21304-12	7908240089	TOPREP		
LAC-TR-070	7908160453*	50-409	P	
LAC-TR-071	7908210393*	50-409	R	
NEDO-21052-A	7908090262*	TOPREP		
NEDO-21363-2A	7908060403*	50-278	P	79NED102
NEDO-21864	7908310446*	TOPREP		79NED73
NEDO-21943	7908150687*	TOPREP		79NED70
NEDO-23631	7908010576*	TOPREP		77NED106
NEDO-24057-2	7908070286*	TOPREP		
NEDO-24076-1	7908090458*	TOPREP		
NEDO-24199	7908080524*	50-296	P	
NEDO-24204-A	7908060407*	50-278	P	79NED103
NEDO-24640	7908150675*	TOPREP		79NED94
NEDO-25100	7908270385*	TOPREP		79NED104
NUREG-0060	7908130148*	NUREG		
NUREG-0060	7908130156*	NUREG		
NUREG-0103	7908140707	NUREG		
NUREG-0170 V1	7908140306*	COMMISSION		
NUREG-0170 V2	7908140326*	COMMISSION		
NUREG-0217	7908070628	PHM		

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY		OTHER REPORT NUMBER
NUREG-0217	7908140416	NUREG		PB-263 890
NUREG-0309	7908140205	NUREG		
NUREG-0332	7908090521*	PROJ		
NUREG-0332	7908090522*	PROJ		
NUREG-0424	7908080474	50-568	E	
NUREG-0430 V1 N3	7908240198	NUREG		
NUREG-0452 REV 2	7908140153	NUREG		
NUREG-0462	7908080380	NUREG		
NUREG-0472	7908080087	NUREG		
NUREG-0515	7908090225	50-466	E	
NUREG-0533	7908140176	NUREG		
NUREG-0534	7908070272*	50-395	D	
NUREG-0535	7908140299*	COMMISSION		
NUREG-0540 V1 N6	7908240106	NUREG		
NUREG-0564	7908080565*	50-387	D	
NUREG-0573	7908150077	NUREG		
NUREG-0582	7908150088	NUREG		
NUREG-0583	7908170187*	40-8698		
NUREG-0584	7908100408	NUREG		
NUREG-0603	7908140343	NUREG		
NUREG-0690	7908100387	NUREG		LA-7725-MS
NUREG/CR-0330	7908090530	NUREG		PNL-2696
NUREG/CR-0407	7908090543	NUREG		SAND78-1284
NUREG/CR-0424	7908030034	NUREG		SAND78-1267
NUREG/CR-0458	7908030044	NUREG		SAND78-0029
NUREG/CR-0516	7908140084	NUREG		TREE-1236
NUREG/CR-0522	7908070003	NUREG		LA-7567-PR
NUREG/CR-0578	7908080408	NUREG		UCRL-52633
NUREG/CR-0606	7908060117	NUREG		TREE-1244
NUREG/CR-0609	7908140068	NUREG		TREE-1331
NUREG/CR-0640	7908140068	NUREG		ORNL/SUB/7015-2
NUREG/CR-0707	7908070773	NUREG		BNL-NUREG 50965
NUREG/CR-0723	7908200001	PROJ		ORNL/NUREG/TM-3
NUREG/CR-0752	7908270100	NUREG		ORNL/NUREG/TM-3
NUREG/CR-0757	7908140128	NUREG		TREE-1333
NUREG/CR-0765	7908140116	NUREG		TREE-1271
NUREG/CR-0767	7908070781	NUREG		ORNL/NUREG-57
NUREG/CR-0792	7908100394	NUREG		TREE-1326
NUREG/CR-0810	7908070694	NUREG		ORNL/NUREG/TM-3
NUREG/CR-0815	7908070748	NUREG		TREE-1229
NUREG/CR-0827	7908080423	NUREG		RFP2932
NUREG/CR-0832	7908090536	NUREG		ORNL/NUREG/CSD/
NUREG/CR-0834	7908240644	NUREG		GEAP-10207-46
NUREG/CR-0838	7908070657	NUREG		NRC-03-78-135
NUREG/CR-0848	7908230679	NUREG		ORNL/NUREG/NSIC
NUREG/CR-0855	7908230686	NUREG		PNL-3040-1
NUREG/CR-0860	7908270077	NUREG		ANL-79-37
NUREG/CR-0865	7908230692	NUREG		PNL-2948
NUREG/CR-0868	7908140104	NUREG		LA-7867-PR
NUREG/CR-0876	7908080437	NUREG		
NUREG/CR-0894	7908240659	NUREG		
NUREG/CR-0901	7908240668	NUREG		ORNL/NUREG/TM-3
NUREG/CR-0910	7908240056	NUREG		PNL-3052
NUREG/CR-0922	7908240119	NUREG		SAND 78-8197
NUREG/CR-0923	7908240125	NUREG		SAND 78-8196
NUREG/CR-0924	7908240135	NUREG		SAND 78-8177
NUREG/CR-0925	7908240142	NUREG		
NUREG/CR-0926	7908230642	NUREG		AL-79-1
NUREG/CR-0931	7908080416	NUREG		
NUREG/CR-0948	7908070709	NUREG		
NUREG/CR-0949	7908240673	NUREG		
NUREG/CR-0951	7908230667	NUREG		
NUREG/CR-6080	7908140462	NUREG		
PGE-1021	7908270411*	50-344	P	
PGE-1022	7908200319*	50-344	P	LCA 26

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY		OTHER REPORT NUMBER
PR-I-79-012	7908280853	71-9134		
PT-U79-0357	7908140695*	50-285	G	
RM77-419	7908070523	PROJ		
RM77-419	7908070594	PROJ		
SECY-78-256	7908230163	SECY		
SECY-78-311A	7908210156	SECY		
SECY-78-671B	7908140364	SECY		
SECY-78-678C	7908090557	SECY		
SECY-78-682-A	7908080595*	10CFR		
SECY-79-038	7908080650*	10CFR		
SECY-79-072B	7908130151	SECY		
SECY-79-077B	7908100504	SECY		
SECY-79-160A	7908010330*	SECY		
SECY-79-163	7908210372*	10CFR		
SECY-79-182A	7908130053	SECY		
SECY-79-187A	7908210104*	10CFR		
SECY-79-218A	7908130100	SECY		
SECY-79-222B	7908240520	SECY		
SECY-79-249C	7908240545	SECY		
SECY-79-282A	7908130618	SECY		
SECY-79-294	7908140257	SECY		
SECY-79-319	7908010640*	10CFR		
SECY-79-327	7908130401	SECY		
SECY-79-328A	7908130090	SECY		
SECY-79-330	7908200330	SECY		
SECY-79-330C	7908200391	SECY		
SECY-79-330D	7908200393	SECY		
SECY-79-343	7908010661*	10CFR		
SECY-79-344	7908030436*	50-320	P	
SECY-79-351	7908010057*	10CFR		
SECY-79-364	7908090009*	SECY		
SECY-79-382	7908200265*	FOIA		
SECY-79-394	7908130070	SECY		
SECY-79-397	7908240350	SECY		
SECY-79-425	7908220158	50-320	P	
SECY-79-427	7908100527*	10CFR		
SECY-79-427	7908280867	SECY		
SECY-79-443	7908170507*	10CFR		
SECY-79-655B	7908130129	SECY		
SECY-9-330B	7908200389	SECY		
SECY-A-79-041	7908080638*	50-443	G	
SECY-A-79-042	7908010039*	10CFR		
SECY-A-79-051	7908080612*	50-312	G	
SECY-A-79-051	7908080620*	50-312	G	
SECY-A-79-051B	7908080627*	50-312	G	
UCRL-52485	7908030126	50-201	P	
WCAP-8183	7908170407*	TOPREP		
WCAP-9500 V1	7908010471*	TOPREP		
WCAP-9500 V2	7908010481*	TOPREP		
WCAP-9500 V3	7908010487*	TOPREP		
WCAP-9500 V4	7908010488*	TOPREP		
WCAP-9601 V1	7908200310*	TOPREP		
WCAP-9601 V2	7908200307*	TOPREP		
WCAP-9601 V3	7908200313*	TOPREP		
XN-NF-1A	7908210503*	TOPREP		
XN-NF-512 (NP)	7908210577*	TOPREP		
XN-NF-79-6 (NP)	7908210569*	TOPREP		

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7906060192	7906060188	79/04/18	50-263 Q
7906110210	7906110206	79/05/15	50-344 Q
7906210050	7906210049	79/05/01	PR
7906210370	7906210363	79/05/21	70-2623
7906280112	7906280109	79/06/20	50-329 Q
7906290049	7906290039	79/05/25	50-320 Q
7907190641	7907130134	79/05/30	50-219 P
7907260002	7907260001	79/06/20	50-510 Q
7907260305	7907260295	79/06/13	50-320 U
7907260324	7907260314	79/06/12	50-320 U
7907310599	7907310573	77/12/27	FOIA
7907310621	7907310606	79/06/06	COMMISSION
7908010009	7908010002	79/07/23	50-409 Q
7908010039	7908010033	79/06/05	10CFR
7908010043	7908010036	79/06/15	50-458 Q
7908010045	7908010033	79/06/05	10CFR
7908010050	7908010033	79/06/05	10CFR
7908010057	7908010033	79/06/05	10CFR
7908010058	7908010054	79/06/01	COMMISSION
7908010060	7908010051	79/06/14	50-482 Q
7908010065	7908010033	79/06/05	10CFR
7908010074	7908010072	79/06/13	50-155 Q
7908010095	7908010091	79/07/06	71-254
7908010104	7908010100	79/06/29	71-181
7908010109	7908010106	79/06/29	71-175
7908010120	7908010114	79/06/29	71-220
7908010135	7908010129	79/06/29	71-128
7908010136	7908010125	79/06/26	ORG
7908010141	7908010125	79/06/26	ORG
7908010151	7908010145	79/06/29	71-99
7908010177	7908010170	79/06/29	71-232
7908010193	7908010085	79/06/12	50-373 Q
7908010195	7908010188	79/06/29	71-243
7908010204	7908010175	79/06/05	50-293 U
7908010209	7908010201	79/06/29	71-233
7908010216	7908010213	79/06/18	CONTRACT
7908010225	7908010217	79/06/29	71-247
7908010227	7908010223	79/06/15	50-10 Q
7908010231	7908010223	79/06/15	50-10 Q
7908010237	7908010230	79/06/29	71-234
7908010276	7908010271	79/06/14	50-516 Q
7908010278	7908010273	79/06/18	50-309 H
7908010287	7908010271	79/06/14	50-516 Q
7908010308	7908010304	79/06/21	50-373 Q
7908010311	7908010307	79/06/15	50-247 P
7908010327	7908010319	79/06/20	50-244 P
7908010330	7908010324	79/06/12	SECY
7908010331	7908010322	79/02/28	40-8452
7908010332	7908010320	79/06/20	70-1622
7908010344	7908010340	79/05/24	50-424 Q
7908010347	7908010341	79/07/24	50-327 S
7908010349	7908010340	79/05/24	50-424 Q
7908010356	7908010353	79/06/20	50-151 Q
7908010357	7908010355	79/07/27	50-395 A
7908010365	7908010365	79/07/20	50-397 S
7908010382	7908010372	79/06/29	71-272
7908010385	7908010381	79/07/24	50-301 S
7908010393	7908010390	79/07/26	50-296 S
7908010395	7908010388	79/07/20	50-390 S
7908010402	7908010398	79/07/18	50-327 S
7908010404	7908010403	79/06/29	71-242
7908010408	7908010400	79/07/20	50-327 S
7908010409	7908010406	79/06/29	71-221
7908010413	7908010411	79/06/29	71-222
7908010438	7908010434	79/07/20	50-438 S
7908010439	7908010433	79/05/31	40-8675
7908010442	7908010433	79/05/31	40-8675
7908010446	7908010433	79/05/31	40-8675
7908010451	7908010449	79/07/30	50-220 K
7908010453	7908010433	79/05/31	40-8675
7908010460	7908010452	79/06/29	71-223
7908010466	7908010464	79/06/29	71-224
7908010471	7908010465	79/07/30	TOPREP
7908010474	7908010467	79/07/24	50-269 P
7908010477	7908010473	79/06/29	71-229
7908010481	7908010465	79/07/30	TOPREP
7908010487	7908010465	79/07/30	TOPREP
7908010488	7908010465	79/07/30	TOPREP
7908010502	7908010497	79/07/24	50-334 S
7908010508	7908010503	79/07/26	50-255 S
7908010512	7908010507	79/07/25	50-155 P
7908010541	7908010535	79/07/25	50-317 I
7908010544	7908010538	79/07/30	50-443 Q
7908010546	7908010536	79/07/20	50-277 S
7908010547	7908010543	79/07/26	50-348 S
7908010549	7908010542	79/07/25	50-156 R
7908010550	7908010543	79/07/26	50-348 S
7908010552	7908010548	79/07/27	50-259 S
7908010557	7908010555	79/06/26	50-298 S
7908010560	7908010554	79/07/27	50-263 R
7908010566	7908010564	79/07/31	50-341 K
7908010567	7908010561	79/07/24	50-309 S
7908010572	7908010569	79/07/24	50-305 S
7908010576	7908010570	79/07/20	TOPREP
7908010580	7908010574	79/07/27	50-334 P
7908010585	7908010577	79/07/27	50-361 S
7908010586	7908010583	79/06/29	71-214
7908010590	7908010588	79/06/29	71-253
7908010595	7908010592	79/06/29	71-215
7908010602	7908010598	79/06/29	71-213
7908010603	7908010594	79/06/20	50-315 P
7908010605	7908010600	79/06/29	71-257
7908010631	7908010415	79/06/01	50-295 Q
7908010640	7908010636	79/06/05	10CFR
7908010643	7908010638	79/05/24	50-302 Q
7908010644	7908010636	79/06/05	10CFR
7908010650	7908010638	79/05/24	50-302 Q
7908010660	7908010649	79/06/30	TOPREP
7908010661	7908010658	79/06/07	10CFR
7908010665	7908010655	79/06/06	40-8698
7908010666	7908010658	79/06/07	10CFR
7908010672	7908010655	79/06/06	40-8698
7908010679	7908010667	79/07/10	50-267 Q
7908010682	7906070658	79/06/07	10CFR
7908010686	7908010678	79/07/03	50-219 Q
7908010687	7908010658	79/06/07	10CFR
7908010690	7908010658	79/06/07	10CFR
7908010691	7908010663	79/05/25	50-596 A
7908010695	7908010658	79/06/07	10CFR
7908010697	7908010678	79/07/03	50-219 Q
7908010701	7908010688	79/07/10	50-281 Q
7908010702	7908010658	79/06/07	10CFR
7908010704	7908010678	79/07/03	50-219 Q
7908010709	7908010688	79/07/10	50-281 Q
7908010711	7908010706	79/07/12	71-9016
7908010712	7908010678	79/07/03	50-219 Q
7908010713	7908010688	79/07/10	50-281 Q
7908010721	7908010688	79/07/10	50-281 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908010722	7908010720	79/06/11	50-220	G
7908020027	7908020025	79/07/25	50-10	P
7908020031	7908020025	79/07/25	50-10	P
7908020035	7908020029	79/06/14	40-4492	
7908020038	7908020036	79/07/18	50-280	G
7908020042	7908020037	79/06/08	71-188	
7908020044	7908020036	79/07/18	50-280	G
7908020045	7908020040	79/07/12	71-6400	
7908020046	7908020040	79/07/12	71-6400	
7908020049	7908020040	79/07/12	71-6400	
7908020057	7908020052	79/06/27	50-272	G
7908020060	7908020052	79/06/27	50-272	G
7908020064	7908020052	79/06/27	50-272	G
7908020070	7908020052	79/06/27	50-272	G
7908020075	7908020066	79/07/10	50-553	G
7908020080	7908020066	79/07/10	50-553	G
7908020083	7908020076	79/07/06	50-245	G
7908020084	7908020066	79/07/10	50-553	G
7908020088	7908020076	79/07/06	50-245	G
7908020089	7908020066	79/07/10	50-553	G
7908020094	7908020076	79/07/06	50-245	G
7908020098	7908020095	79/06/29	71-279	
7908020099	7908020076	79/07/06	50-245	G
7908020100	7908020092	79/06/04	50-247	G
7908020105	7908020102	79/05/25	50-285	G
7908020106	7908020103	79/06/28	50-309	G
7908020110	7908020103	79/06/28	50-309	G
7908020114	7908020103	79/06/28	50-309	G
7908020116	7908020111	79/06/25	27-39	
7908020120	7908020111	79/06/25	27-39	
7908020121	7908020103	79/06/28	50-309	G
7908020133	7908020127	79/06/05	50-485	G
7908020134	7908020128	79/06/20	40-8721	
7908020145	7908020138	79/06/29	71-212	
7908020154	7908020139	79/06/01	50-272	G
7908020160	7908020156	79/04/01	CONTRACT	
7908020161	7908020155	79/06/25	50-346	P
7908020181	7908020178	79/05/22	GA999	
7908020188	7908020175	79/06/11	70-8	
7908020190	7908020185	79/05/16	50-327	G
7908020197	7908020193	79/05/14	50-390	G
7908020201	7908020194	79/06/15	40-4492	
7908020203	7908020196	79/06/26	50-312	T
7908020205	7908020200	79/05/24	50-566	G
7908020209	7908020196	79/06/26	50-312	T
7908020214	7908020208	79/07/02	50-263	P
7908020217	7908020210	79/05/16	50-338	G
7908020241	7908020232	79/06/06	50-280	U
7908020246	7908020236	79/06/18	50-482	G
7908020260	7908020254	79/07/10	70-1193	
7908020264	7908020256	79/05/24	50-341	G
7908020267	7908020263	79/07/05	50-305	G
7908020302	7908020290	79/04/25	50-437	G
7908020328	7908020323	79/06/27	50-70	P
7908020338	7908020318	79/05/29	50-461	G
7908020346	7908020341	78/10/01	CONTRACT	
7908020360	7908020353	79/06/29	50-395	D
7908020371	7908020365	79/05/25	50-295	G
7908020381	7908020376	79/06/14	50-275	G
7908020386	7908020384	79/07/02	50-311	H
7908020390	7908020388	79/07/17	CONTRACT	
7908020404	7908020401	79/06/11	40-8726	
7908020417	7908020414	79/05/31	50-329	G
7908020426	7908020421	79/07/27	50-321	S
7908020434	7908020427	79/07/26	50-321	S
7908020436	7908020431	79/07/25	50-277	R
7908020443	7908020442	79/07/26	50-346	P
7908020445	7908020440	79/07/30	50-29	S
7908020451	7908020447	79/07/27	50-260	S
7908020455	7908020453	79/07/05	50-327	S
7908020456	7908020452	79/07/26	50-366	S
7908020459	7908020449	79/07/27	50-313	S
7908020469	7908020465	79/07/26	50-277	S
7908020475	7908020449	79/07/27	50-313	S
7908020481	7908020478	79/08/01	50-280	P
7908020485	7908020482	79/07/03	50-327	S
7908020490	7908020488	79/07/03	50-390	S
7908020492	7908020484	79/07/27	50-368	S
7908020497	7908020356	79/06/01	CONTRACT	
7908020502	7908020496	79/07/30	50-260	S
7908020516	7908020508	79/06/18	TOPREP	
7908020520	7908020517	79/06/18	50-416	G
7908020526	7908020517	79/06/18	50-416	G
7908020528	7908020522	79/06/01	50-346	G
7908020539	7908020533	79/06/18	50-416	G
7908020544	7908020533	79/06/18	50-416	G

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908020554	7908020550	79/06/14	50-271	G
7908020555	7908020548	79/05/10	50-10	G
7908020561	7908020558	79/06/20	50-399	G
7908020566	7908020548	79/05/10	50-10	G
7908020567	7908020562	79/06/20	50-338	G
7908020570	7908020562	79/06/20	50-338	G
7908020572	7908020548	79/05/10	50-10	G
7908020578	7908020574	79/05/21	50-387	G
7908020591	7908020587	79/05/30	70-824	
7908020599	7908020593	79/07/02	50-27	P
7908020603	7908020593	79/07/02	50-27	P
7908030006	7908030003	79/06/22	40-8452	
7908030010	7908030004	79/06/27	50-458	G
7908030048	7908030045	79/07/03	50-315	P
7908030049	7908030041	79/04/13	71-5597	
7908030052	7908030045	79/07/03	50-315	P
7908030054	7908030041	79/04/13	71-5597	
7908030055	7908030011	79/07/13	50-320	P
7908030056	7908030045	79/07/03	50-315	P
7908030057	7908030041	79/04/13	71-5597	
7908030061	7908030041	79/04/13	71-5597	
7908030062	7908030058	79/07/03	50-327	S
7908030064	7908030041	79/04/13	71-5597	
7908030069	7908030065	79/06/29	CONTRACT	
7908030070	7908030041	79/04/13	71-5597	
7908030079	7908030041	79/04/13	71-5597	
7908030080	7908030076	79/06/22	50-309	F
7908030081	7908030074	79/07/03	50-390	S
7908030083	7908030041	79/04/13	71-5597	
7908030092	7908030086	79/07/12	50-327	S
7908030095	7908030089	79/07/03	50-302	P
7908030097	7908030091	79/07/05	71-111	
7908030098	7908030089	79/07/03	50-302	P
7908030101	7908030099	79/07/03	50-302	P
7908030113	7908030108	79/06/19	50-409	G
7908030118	7908030111	79/07/06	50-313	G
7908030129	7908030125	79/06/04	ORG	
7908030135	7908030131	79/06/27	REGOD	
7908030141	7908030133	79/07/31	50-277	P
7908030142	7907030417	79/06/15	10CFR	
7908030143	7908030131	79/06/27	REGOD	
7908030163	7908030151	79/07/20	50-272	R
7908030164	7908030158	79/07/05	CONTRACT	
7908030186	7908030182	79/07/31	50-206	P
7908030189	7908030184	79/06/21	50-574	G
7908030193	7908030188	79/06/15	COMMISSION	
7908030197	7908030190	79/05/18	70-2623	
7908030206	7908030201	79/06/08	50-285	G
7908030211	7908030209	79/05/01	70-754	
7908030221	7908030215	79/07/30	50-272	S
7908030223	7908030209	79/05/01	70-754	
7908030227	7908030214	79/07/12	50-454	G
7908030234	7908030224	79/07/27	50-316	S
7908030253	7908030245	79/06/29	XPORTLIC	
7908030256	7908030232	79/06/12	50-213	P
7908030259	7908030245	79/06/29	XPORTLIC	
7908030260	7908030249	79/06/08	COMMISSION	
7908030264	7908030262	79/06/19	50-335	P
7908030266	7908030248	79/07/27	50-309	S
7908030275	7908030269	79/05/14	50-596	G
7908030278	7908030249	79/06/08	COMMISSION	
7908030300	7908030299	79/07/27	50-336	S
7908030307	7908030304	79/07/03	50-302	P
7908030308	7908030304	79/07/03	50-302	P
7908030309	7908030305	79/07/31	50-220	I
7908030310	7908030304	79/07/03	50-302	P
7908030313	7908030312	79/07/31	50-[illegible]	S
7908030314	7908030304	79/07/03	50-302	P
7908030315	7908030311	79/06/20	50-302	P
7908030318	7908030311	79/06/20	50-302	P
7908030321	7908030249	79/06/08	COMMISSION	
7908030324	7908030319	79/06/04	50-261	P
7908030325	7908030249	79/06/08	COMMISSION	
7908030328	7908030319	79/06/04	50-261	P
7908030332	7908030319	79/06/04	50-261	P
7908030334	7908030249	79/06/08	COMMISSION	
7908030343	7908030339	79/06/08	COMMISSION	
7908030344	7908030337	79/07/16	50-390	S
7908030351	7908030339	79/06/08	COMMISSION	
7908030358	7908030352	79/07/12	71-9019	
7908030359	7908030339	79/06/08	COMMISSION	
7908030369	7908030363	79/07/13	CONTRACT	
7908030375	7908030368	79/06/04	CONTRACT	
7908030381	7908030373	79/07/13	CONTRACT	
7908030384	7908030376	79/06/11	COMMISSION	
7908030385	7908030377	79/07/31	50-220	F

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908030396	7908030387	79/07/20	CONTRACT	
7908030408	7908030399	79/07/30	50-302	S
7908030417	7908030410	79/07/30	50-390	S
7908030419	7908030404	79/07/12	50-390	S
7908030423	7908030415	79/07/31	50-324	S
7908030428	7908030422	79/07/02	50-285	P
7908030430	7908030424	79/07/31	50-255	P
7908030432	7908030427	79/07/	50-438	S
7908030433	7908030422	79/07/02	50-285	P
7908030436	7908030425	79/07/25	50-320	P
7908030438	7908030422	79/07/02	50-285	P
7908030439	7908030429	79/07/23	CONTRACT	
7908030440	7908030434	79/08/01	50-445	M
7908030446	7908030441	79/07/10	71-6574	
7908030450	7908030434	79/08/01	50-445	M
7908030452	7908030435	79/07/19	50-269	P
7908030456	7908030448	79/08/01	50-280	S
7908030461	7908030435	79/07/19	50-269	P
7908030462	7908030435	79/07/19	50-269	P
7908030463	7908030455	79/07/30	50-272	S
7908030464	7908030458	79/07/26	FOIA	
7908030470	7908030465	79/06/04	CONTRACT	
7908030472	7908030435	79/07/19	70-2623	
7908030474	7908030435	79/07/19	50-269	P
7908030479	7908030435	79/07/19	FOIA	
7908030480	7908030473	79/07/20	FOIA	
7908030481	7908030468	79/07/27	50-409	S
7908030485	7908030473	79/07/20	FOIA	
7908030486	7908030475	79/06/11	COMMISSION	
7908030488	7908030435	79/07/19	50-369	A
7908030489	7908030482	79/07/27	50-263	G
7908030491	7908030475	79/06/11	COMMISSION	
7908030498	7908030492	79/07/16	50-324	S
7908030511	7908030506	79/07/30	50-321	S
7908030516	7908030512	79/07/05	PRM	
7908030521	7908030508	79/06/20	50-201	P
7908030523	7908030513	79/05/09	70-984	
7908030533	7908030513	79/05/09	70-984	
7908030534	7908030508	79/06/20	50-201	P
7908030552	7908030540	79/07/19	27-39	
7908030559	7908030554	79/06/22	50-315	G
7908030560	7908030543	79/07/19	27-39	
7908030567	7908030555	79/07/25	50-358	G
7908030568	7908030543	79/07/19	27-39	
7908030570	7908030562	79/06/20	NUREG	
7908030580	7908030571	79/06/21	50-255	P
7908030584	7908030576	79/05/30	50-250	G
7908030587	7908030582	79/06/27	50-295	G
7908030592	7908030562	79/06/20	NUREG	
7908030593	7908030586	79/05/30	40-8434	
7908030596	7908030591	79/07/19	50-416	G
7908030599	7908030591	79/07/19	50-416	G
7908030603	7908030591	79/07/19	50-416	G
7908030606	7908030591	79/07/19	50-416	G
7908030607	7908030600	79/06/13	50-339	A
7908030608	7908030594	79/05/31	50-327	G
7908030619	7908030610	79/05/31	50-346	G
7908030620	7908030611	79/07/09	50-269	G
7908030622	7908030614	79/06/06	50-272	P
7908030626	7908030611	79/07/09	50-269	G
7908030629	7908030623	79/06/06	50-329	G
7908030632	7908030611	79/07/09	50-269	G
7908030632	7908030611	79/07/09	50-269	G
7908030633	7908030623	79/06/06	50-329	G
7908060002	7908060001	79/06/21	50-259	G
7908060050	7908060026	79/06/26	NUREG	
7908060096	7908060092	79/07/11	50-275	A
7908060101	7908060092	79/07/11	50-275	A
7908060106	7908060092	79/07/11	50-275	A
7908060120	7908060111	79/07/05	50-10	G
7908060180	7908060171	79/07/18	50-456	G
7908060182	7908060176	79/07/09	50-271	P
7908060186	7908060176	79/07/09	50-271	P
7908060189	7908060171	79/07/18	50-456	G
7908060191	7908060176	79/07/09	50-271	P
7908060212	7908060199	79/07/18	50-329	G
7908060229	7908060223	79/08/02	50-219	S
7908060231	7908060225	79/07/25	50-254	G
7908060235	7908060062	79/07/23	50-566	G
7908060249	7908060204	79/06/21	50-574	G
7908060255	7908060247	79/08/01	50-219	R
7908060271	7908060062	79/07/23	50-566	G
7908060288	7908060062	79/07/23	50-566	G
7908060292	7908060286	79/07/30	50-438	S
7908060301	7908060278	79/08/03	50-339	S
7908060308	7908060062	79/07/23	50-566	G

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908060311	7908060304	79/07/31	50-213	S
7908060316	7908060312	79/07/31	50-316	S
7908060305	7908060312	79/07/31	50-316	S
7908060379	7908060375	79/08/01	50-282	P
7908060397	7908060387	79/08/02	50-278	P
7908060403	7908060387	79/08/02	50-278	P
7908060407	7908060387	79/08/02	50-278	P
7908060410	7908060405	79/08/01	50-329	S
7908060411	7908060392	79/07/30	50-366	S
7908060415	7908060398	79/08/01	50-324	S
7908060422	7908060416	79/07/31	50-315	S
7908060428	7908060421	79/07/31	50-255	S
7908060430	7908060416	79/07/31	50-315	S
7908060438	7908060432	79/07/31	50-255	S
7908060439	7908060435	79/08/02	50-346	S
7908060444	7908060440	79/08/03	50-271	S
7908060445	7908060445	79/06/21	50-574	G
7908060448	7908060441	79/08/03	50-333	S
7908060450	7908060447	79/08/02	50-346	S
7908060451	7908060443	79/07/30	50-366	S
7908060455	7908060453	79/08/02	50-346	S
7908060458	7908060454	79/07/11	COMMISSION	
7908060462	7908060454	79/07/11	COMMISSION	
7908060463	7908060460	79/07/30	50-321	S
7908060471	7908060461	79/08/03	50-333	S
7908060472	7908060468	79/07/31	50-368	S
7908060474	7908060469	79/07/30	50-321	S
7908060475	7908060468	79/07/31	50-368	S
7908060480	7908060468	79/07/31	50-368	S
7908060481	7908060197	79/06/20	NUREG	
7908060482	7908060468	79/07/31	50-368	S
7908060486	7908060197	79/06/20	NUREG	
7908060487	7908060468	79/07/31	50-368	S
7908060500	7908060479	79/08/02	50-333	S
7908060501	7908060466	79/08/03	50-325	S
7908060512	7908060508	79/07/30	50-269	S
7908060514	7908060506	79/08/01	50-302	S
7908060519	7908060510	79/07/30	50-390	S
7908060527	7908060521	79/08/02	50-333	S
7908060533	7908060528	79/08/01	50-336	S
7908060541	7908060534	79/08/01	50-262	S
7908060543	7908060540	79/08/02	50-325	S
7908060545	7908060522	79/08/02	50-325	S
7908070057	7908070052	79/06/25	AGREEMENT	
7908070064	7908070061	79/06/29	50-293	F
7908070120	7908070115	79/05/18	71-6698	
7908070130	7908070125	79/06/18	50-445	G
7908070133	7908070124	79/07/23	50-261	G
7908070138	7908070127	79/05/30	50-454	G
7908070139	7908070124	79/07/23	50-261	G
7908070145	7908070124	79/07/23	50-261	G
7908070149	7908070144	79/06/08	50-390	G
7908070155	7908070124	79/07/23	50-261	G
7908070159	7908070127	79/05/30	50-454	G
7908070160	7908070104	79/05/25	70-2623	
7908070171	7908070165	79/06/14	GA999	
7908070177	7908070165	79/06/14	GA999	
7908070182	7908070165	79/06/14	GA999	
7908070185	7908070165	79/06/14	GA999	
7908070188	7908070165	79/06/14	GA999	
7908070191	7908070165	79/06/14	GA999	
7908070195	7908070165	79/06/14	GA999	
7908070201	7908070193	79/07/18	AGREEMENT	
7908070207	7908070203	79/06/11	50-358	G
7908070210	7908070203	79/06/11	50-358	G
7908070252	7908070237	79/07/05	50-186	P
7908070257	7908070241	79/05/31	70-1257	
7908070261	7908070237	79/07/05	50-186	P
7908070270	7908070237	79/07/05	50-186	P
7908070272	7908070265	79/06/29	50-395	D
7908070284	7908070276	79/06/28	50-364	G
7908070293	7908070276	79/06/28	50-364	G
7908070297	7908070276	79/06/28	50-364	G
7908070302	7908070276	79/06/28	50-364	G
7908070319	7908070308	79/05/29	50-346	G
7908070324	7908070311	79/06/28	50-220	G
7908070340	7908070308	79/05/29	50-346	G
7908070365	7908070356	79/07/03	50-302	P
7908070366	7908070357	79/08/02	50-259	K
7908070382	7908070376	79/07/06	50-155	G
7908070386	7908070383	79/08/02	50-302	P
7908070394	7908070356	79/07/03	50-302	P
7908070400	7908070393	79/07/30	50-498	S
7908070403	7908070356	79/07/03	50-302	P
7908070464	7908070458	79/07/01	CONTRACT	
7908070487	7908070481	79/06/23	50-320	P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908070488	7908070481	79/06/23	50-320	P
7908070492	7908070485	79/08/03	50-348	S
7908070493	7908070483	79/08/01	50-366	S
7908070496	7908070491	79/08/01	50-346	S
7908070497	7908070494	79/08/03	50-338	S
7908070498	7908070495	79/08/01	50-366	S
7908070505	7908070499	79/07/27	50-335	S
7908070513	7908070509	79/08/01	50-298	J
7908070517	7908070510	79/07/23	50-251	S
7908070518	7908070500	79/08/01	50-267	S
7908070551	7908070537	79/08/02	50-368	S
7908070561	7908070536	79/08/03	50-255	P
7908070567	7908070548	79/07/06	RES	
7908070576	7908070537	79/08/02	50-368	S
7908070579	7908070573	79/07/26	50-245	S
7908070583	7908070577	79/08/03	50-338	S
7908070589	7908070584	79/07/27	50-219	S
7908070592	7908070537	79/08/02	50-368	S
7908070597	7908070588	79/08/01	TOPREP	
7908070599	7908070593	79/08/03	50-333	R
7908070605	7908070537	79/08/02	50-368	S
7908070623	7908070537	79/08/02	50-368	S
7908070656	7908070646	79/08/02	50-269	S
7908070682	7908070668	79/07/31	50-387	K
7908070686	7908070684	79/08/01	50-267	S
7908070687	7908070675	79/06/29	50-363	Q
7908070692	7908070688	79/08/01	50-346	S
7908070699	7908070695	79/08/01	50-321	S
7908070720	7908070717	78/12/15	CONTRACT	
7908070746	7908070740	79/06/29	71-188	
7908070768	7908070757	79/06/29	50-367	Q
7908070778	7908070775	79/06/07	50-3	Q
7908070782	7908070777	79/06/08	70-1100	
7908070792	7908070788	79/07/05	71-18	
7908070825	7908070[illegible]	79/06/19	50-295	Q
7908070827	7908070822	79/07/06	50-206	P
7908070832	7908070822	79/07/06	50-206	P
7908070843	7908070838	79/06/28	71-9	
7908070846	7908070842	79/07/31	REGGD	
7908080003	7908080001	79/06/27	GA999	
7908080006	7908080005	79/07/18	GA999	
7908080009	7908080008	79/07/19	GA999	
7908080010	7908080008	79/07/19	GA999	
7908080012	7908080008	79/07/19	GA999	
7908080014	7908080013	79/06/20	GA999	
7908080017	7908080016	79/07/27	50-320	H
7908080018	7908080015	79/06/29	50-387	Q
7908080088	7908080085	79/07/02	50-498	Q
7908080091	7908080068	79/07/10	50-274	P
7908080096	7908080068	79/07/10	50-274	P
7908080107	7908080103	79/07/18	50-255	Q
7908080116	7908080111	79/07/10	50-269	P
7908080122	7908080104	79/07/05	50-338	Q
7908080126	7908080111	79/07/10	50-269	P
7908080133	7908080124	79/07/31	50-329	K
7908080134	7908080111	79/07/10	50-269	P
7908080137	7908080130	79/06/19	50-272	Q
7908080144	7908080136	79/02/27	50-272	Q
7908080149	7908080142	79/07/11	50-311	A
7908080160	7908080152	79/07/06	50-286	Q
7908080166	7908080152	79/07/06	50-286	Q
7908080171	7908080152	79/07/06	50-286	Q
7908080178	7908080152	79/07/06	50-286	Q
7908080191	7908080186	79/07/10	50-247	P
7908080194	7908080180	79/06/19	50-373	Q
7908080195	7908080188	79/07/03	50-454	Q
7908080205	7908080201	79/07/12	DRG	
7908080207	7908080200	79/07/06	50-599	Q
7908080220	7908080212	79/06/12	50-358	Q
7908080229	7908080212	79/06/12	50-358	Q
7908080239	7908080232	79/07/05	50-322	A
7908080241	7908080233	79/06/29	50-322	Q
7908080249	7908080233	79/06/29	50-322	Q
7908080251	7908080244	79/07/17	50-252	Q
7908080255	7908080233	79/06/29	50-322	Q
7908080263	7908080233	79/06/29	50-322	Q
7908080267	7908080259	79/07/09	50-27	P
7908080273	7908080269	79/07/10	50-596	Q
7908080275	7908080270	79/07/25	50-322	U
7908080283	7908080266	79/07/12	50-269	P
7908080288	7908080280	79/07/02	50-322	Q
7908080294	7908080289	79/07/10	50-295	Q
7908080298	7908080266	79/07/12	50-269	P
7908080307	7908080280	79/07/02	50-322	Q
7908080311	7908080266	79/07/12	50-269	P
7908080317	7908080073	79/07/03	50-271	P

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908080348	7908080331	79/07/16	50-269	P
7908080351	7908080344	79/07/06	50-599	Q
7908080352	7908080332	79/07/05	50-482	Q
7908080355	7908080346	79/06/27	PROJ	
7908080358	7908080346	79/06/27	PROJ	
7908080362	7908080331	79/07/16	50-269	P
7908080372	7908080368	79/07/16	71-116	
7908080373	7908080331	79/07/16	50-269	P
7908080375	7908080368	79/07/16	71-116	
7908080387	7908080383	79/08/03	50-237	S
7908080389	7908080376	79/07/03	50-315	Q
7908080398	7908080397	79/08/02	50-293	S
7908080403	7908080401	79/08/03	50-305	S
7908080405	7908080404	79/08/01	50-249	S
7908080411	7908080407	79/07/10	CONTRACT	
7908080418	7908080414	79/06/04	CONTRACT	
7908080422	7908080417	79/07/13	50-461	Q
7908080424	7908080420	79/06/14	50-454	Q
7908080426	7908080412	79/07/12	CONTRACT	
7908080432	7908080428	79/06/14	50-219	S
7908080435	7908080431	79/07/10	CONTRACT	
7908080444	7908080440	79/04/01	CONTRACT	
7908080445	7908080442	79/06/04	50-267	S
7908080446	7908080441	79/08/03	50-244	P
7908080456	7908080448	79/05/23	50-313	Q
7908080457	7908080450	79/08/03	50-318	S
7908080473	7908080469	79/08/02	50-344	R
7908080505	7908080482	79/08/02	70-2684	
7908080508	7908080500	79/08/03	50-249	S
7908080511	7908080495	79/08/01	50-313	S
7908080512	7908080509	79/08/06	50-317	S
7908080524	7908080519	79/08/06	50-296	P
7908080529	7908080527	79/07/20	50-3	P
7908080549	7908080540	79/07/30	50-373	A
7908080562	7908080560	79/06/28	50-387	D
7908080565	7908080560	79/06/28	50-387	D
7908080566	7908080482	79/08/02	70-2684	
7908080577	7908080482	79/08/02	70-2684	
7908080579	7908080572	79/08/01	50-390	A
7908080595	7908080589	79/06/21	10CFR	
7908080597	7908080572	79/08/01	50-390	A
7908080599	7908080589	79/06/21	10CFR	
7908080600	7908080593	79/07/24	FOIA	
7908080602	7908080596	79/07/19	50-298	S
7908080604	7908080589	79/06/21	10CFR	
7908080607	7908080589	79/06/21	10CFR	
7908080612	7908080589	79/06/21	50-312	Q
7908080617	7908080572	79/08/01	50-390	A
7908080620	7908080589	79/06/21	50-312	Q
7908080626	7908080618	79/07/30	FOIA	
7908080627	7908080589	79/06/21	50-312	Q
7908080629	7908080625	79/06/11	71-125	
7908080631	7908080623	79/07/13	50-329	A
7908080635	7908080618	79/07/30	FOIA	
7908080637	7908080186	79/07/10	50-247	P
7908080638	7908080589	79/06/21	50-443	Q
7908080644	7908080186	79/07/10	50-247	P
7908080649	7908080618	79/07/30	FOIA	
7908080650	7908080589	79/06/21	10CFR	
7908080656	7908080633	79/04/25	50-250	P
7908080657	7908080589	79/06/21	10CFR	
7908080658	7908080618	79/07/30	FOIA	
7908080662	7908080589	79/06/21	10CFR	
7908080670	7908080652	79/07/03	COMMISSION	
7908080692	7908080683	79/08/03	50-280	P
7908080693	7908080683	79/08/03	50-280	P
7908080700	7908080680	79/06/19	50-295	Q
7908080701	7908080683	79/08/03	50-280	P
7908080705	7908080683	79/08/03	50-338	P
7908080711	7908080683	79/08/03	50-338	P
7908080713	7908080683	79/08/03	50-338	P
7908080718	7908080683	79/08/03	50-338	P
7908080720	7908080683	79/08/03	50-338	P
7908080724	7908080683	79/08/03	50-280	P
7908090726	7908080683	79/08/03	50-338	P
7908080730	7908080683	79/08/03	50-280	P
7908080732	7908080683	79/08/03	50-280	P
7908080733	7908080683	79/08/03	50-338	P
7908080737	7908080722	79/06/19	50-546	Q
7908090004	7908090002	79/07/06	50-354	Q
7908090007	7908090002	79/07/06	50-354	Q
7908090009	7908090008	79/06/12	SECY	
7908090010	7908090008	79/06/12	SECY	
7908090011	7908090008	79/06/12	SECY	
7908090020	7908090018	79/06/07	50-269	Q
7908090025	7908090018	79/06/07	50-269	Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908090058	7908090051	79/07/19	50-331	S
7908090064	7908090051	79/07/19	50-331	S
7908090071	7908090051	79/07/19	50-331	S
7908090075	7908090051	79/07/19	50-331	S
7908090079	7908090051	79/07/19	50-331	S
7908090092	7908090087	79/06/22	QA999	
7908090104	7908090087	79/06/22	QA999	
7908090109	7908090087	79/06/22	QA999	
7908090114	7908090100	79/05/31	REGGD	
7908090115	7908090087	79/06/22	QA999	
7908090128	7908090100	79/05/31	REGGD	
7908090137	7908090132	79/06/29	71-81	
7908090151	7908090145	79/06/18	XPORTLIC	
7908090179	7908090177	79/06/18	71-31	
7908090188	7908090183	79/05/25	QA999	
7908090192	7908090181	79/06/05	50-410	S
7908090222	7908090209	79/05/21	QA999	
7908090227	7908090200	79/06/08	50-275	S
7908090237	7908090232	79/05/11	QA999	
7908090249	7908090242	79/06/15	50-295	Q
7908090250	7908090239	79/07/10	XPORTLIC	
7908090254	7908090247	79/07/13	TOPREP	
7908090255	7908090217	79/07/23	50-346	P
7908090257	7908090242	79/06/15	50-295	Q
7908090258	7908090252	79/06/11	71-93	
7908090262	7908090247	79/07/13	TOPREP	
7908090263	7908090217	79/07/23	50-346	P
7908090269	7908090265	79/06/29	71-16	
7908090271	7908090266	79/06/29	50-250	P
7908090275	7908090261	79/06/14	50-313	Q
7908090277	7908090270	79/07/13	TOPREP	
7908090278	7908090217	79/07/23	50-346	P
7908090279	7908090266	79/06/29	50-250	P
7908090280	7908090274	79/06/20	71-302	
7908090284	7908090268	79/07/03	CONTRACT	
7908090286	7908090270	79/07/13	TOPREP	
7908090301	7908090299	79/07/11	GEN TEC	IB
7908090312	7908090307	79/07/19	71-30	
7908090324	7908090317	79/07/19	71-172	
7908090333	7908090304	79/04/13	40-6659	
7908090339	7908090329	79/07/19	71-280	
7908090347	7908090343	79/07/19	71-282	
7908090351	7908090349	79/07/19	71-285	
7908090354	7908090350	79/08/03	50-255	P
7908090356	7908090355	79/07/19	71-269	
7908090365	7908090362	79/07/19	71-209	
7908090373	7908090370	79/07/19	71-186	
7908090374	7908090367	79/06/05	70-820	
7908090378	7908090372	79/08/03	50-320	R
7908090382	7908090377	79/07/19	71-158	
7908090390	7908090385	79/07/19	71-155	
7908090397	7908090299	79/05/30	CONTRACT	
7908090398	7908090384	79/06/26	50-443	H
7908090399	7908090395	79/07/19	71-149	
7908090404	7908090392	79/07/27	50-247	P
7908090407	7908090405	79/07/19	71-268	
7908090414	7908090411	79/07/19	71-286	
7908090417	7908090409	79/06/26	50-309	Q
7908090421	7908090418	79/07/19	71-245	
7908090422	7908090384	79/06/26	50-443	H
7908090425	7908090409	79/06/26	50-309	Q
7908090429	7908090409	79/06/26	50-309	Q
7908090432	7908090426	79/07/19	71-276	
7908090434	7908090409	79/06/26	50-309	Q
7908090439	7908090436	79/07/19	71-274	
7908090449	7908090441	79/06/04	AGREEMENT	
7908090453	7908090440	79/07/13	TOPREP	
7908090456	7908090440	79/07/13	TOPREP	
7908090459	7908090451	79/06/07	COMMISSION	
7908090464	7908090451	79/06/07	COMMISSION	
7908090479	7908090474	79/06/11	71-70	
7908090481	7908090473	79/06/26	40-3453	
7908090483	7908090480	79/08/07	50-334	P
7908090485	7908090456	79/07/12	CONTRACT	
7908090488	7908090473	79/06/26	40-3453	
7908090495	7908090490	79/06/01	71-234	
7908090497	7908090492	79/06/29	71-270	
7908090505	7908090501	79/06/05	COMMISSION	
7908090509	7908090503	79/07/05	50-329	A
7908090511	7908090510	79/08/03	50-244	Q
7908090513	7908090512	79/06/11	SECY	
7908090520	7908090518	79/05/23	PROJ	
7908090521	7908090518	79/05/23	PROJ	
7908090522	7908090518	79/05/23	PROJ	
7908090533	7908090529	79/06/26	50-331	Q
7908090550	7908090546	79/07/31	50-338	K

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908090555	7908090549	79/07/31	TOPREP	
7908090561	7908090557	79/05/18	SECY	
7908090562	7908090556	79/07/11	CONTRACT	
7908090563	7908090560	79/08/06	50-263	S
7908090567	7908090528	79/06/20	70-820	
7908090570	7908090557	79/05/18	SECY	
7908090571	7908090569	79/08/06	50-338	P
7908090573	7908090568	79/08/06	50-346	S
7908090576	7908090311	79/06/01	50-316	Q
7908090577	7908090574	79/07/18	CONTRACT	
7908090584	7908090311	79/06/01	50-316	Q
7908090589	7908090557	79/05/18	SECY	
7908090590	7908090582	79/06/21	70-135	
7908090592	7908090587	79/05/08	TOPREP	
7908090608	7908090602	79/06/29	71-20	
7908090610	7908090600	79/07/18	CONTRACT	
7908090621	7908090614	79/07/16	10CFR	
7908090629	7908090620	79/07/29	CONTRACT	
7908090634	7908090632	79/07/03	50-329	Q
7908090637	7908090632	79/07/03	50-329	Q
7908090642	7908090635	79/07/31	50-317	P
7908090645	7908090635	79/07/31	50-317	P
7908090649	7908090647	79/06/19	50-312	P
7908090662	7908090658	79/07/18	CONTRACT	
7908090664	7908090660	79/07/02	50-346	P
7908090676	7908090675	79/08/03	71-261	
7908090680	7908090678	79/06/07	50-346	P
7908090682	7908090679	79/08/03	71-318	
7908090683	7908090677	79/06/21	50-574	Q
7908090683	7908090677	79/06/21	50-574	Q
7908090684	7908090678	79/06/07	50-346	P
7908090686	7908090678	79/06/07	50-346	P
7908090689	7908090635	79/07/31	50-317	P
7908090691	7908090688	79/05/31	50-313	Q
7908090692	7908090690	79/06/13	50-344	Q
7908090694	7908090693	79/06/22	50-223	Q
7908090695	7908090690	79/06/13	50-344	Q
7908090699	7908090697	79/06/26	50-361	Q
7908090700	7908090697	79/06/26	50-361	Q
7908090702	7908090697	79/06/26	50-361	Q
7908090703	7908090697	79/06/26	50-361	Q
7908100066	7908100055	79/05/09	50-280	H
7908100097	7908100091	79/07/06	QA999	
7908100104	7908100091	79/07/06	QA999	
7908100109	7908100091	79/07/06	QA999	
7908100114	7908100091	79/07/06	QA999	
7908100118	7908100091	79/07/06	QA999	
7908100125	7908100091	79/07/06	QA999	
7908100127	7908100120	79/07/03	50-305	Q
7908100134	7908100120	79/07/03	50-305	Q
7908100140	7908100124	79/07/16	50-254	P
7908100142	7908100136	79/08/03	71-287	
7908100148	7908100146	79/08/03	71-111	
7908100165	7908100157	79/07/27	50-409	P
7908100168	7908100157	79/07/27	50-409	P
7908100172	7908100155	79/07/19	50-155	Q
7908100173	7908100157	79/07/27	50-409	P
7908100185	7908100157	79/07/27	50-409	P
7908100197	7908100179	79/07/18	COMMISSION	
7908100198	7908100195	79/08/08	50-346	H
7908100203	7908100179	79/07/18	COMMISSION	
7908100214	7908100211	79/06/29	50-219	P
7908100216	7908100208	79/06/11	50-341	Q
7908100217	7908100210	79/06/20	50-382	Q
7908100218	7908100211	79/06/29	50-219	P
7908100220	7908100209	79/07/06	QA999	
7908100223	7908100211	79/06/29	50-219	P
7908100234	7908100208	79/06/11	50-341	Q
7908100235	7908100227	79/06/20	50-556	Q
7908100252	7908100209	79/07/06	QA999	
7908100256	7908100209	79/07/06	QA999	
7908100257	7908100251	79/07/09	CONTRACT	
7908100260	7908100209	79/07/06	QA999	
7908100271	7908100264	79/07/03	CONTRACT	
7908100275	7908100270	79/08/06	50-267	P
7908100286	7908100280	79/07/02	CONTRACT	
7908100287	7908100270	79/08/06	50-269	P
7908100295	7908100277	79/07/11	CONTRACT	
7908100307	7908100300	79/07/17	CONTRACT	
7908100309	7908100302	79/07/10	CONTRACT	
7908100312	7908100305	79/08/07	50-338	S
7908100314	7908100310	79/06/01	CONTRACT	
7908100321	7908100189	79/07/17	50-488	Q
7908100337	7908100331	79/08/02	50-312	S
7908100346	7908100340	79/07/17	CONTRACT	
7908100351	7908100343	79/08/03	50-302	S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908100356	7908100120	79/07/03	50-305	Q
7908100359	7908100322	79/04/19	50-10	P
7908100361	7908100358	79/06/29	27-47	
7908100367	7908100364	79/07/05	XPORTLIC	
7908100374	7908100373	79/07/09	71-40	
7908100382	7908100381	79/07/06	50-413	Q
7908100383	7908100381	79/07/06	50-413	Q
7908100384	7908100381	79/07/06	50-413	Q
7908100385	7908100381	79/07/06	50-413	Q
7908100386	7908100381	79/07/06	50-413	Q
7908100390	7908100388	79/07/09	QA999	
7908100391	7908100389	79/08/03	50-400	S
7908100392	7908100388	79/07/09	QA999	
7908100393	7908100388	79/07/09	QA999	
7908100395	7908100388	79/07/09	QA999	
7908100396	7908100388	79/07/09	QA999	
7908100399	7908100388	79/07/09	QA999	
7908100406	7908100403	79/08/03	50-346	S
7908100416	7908100413	79/08/02	50-366	S
7908100423	7908100418	79/08/03	50-331	S
7908100432	7908100425	79/08/06	50-259	S
7908100435	7908100429	79/08/07	50-263	S
7908100447	7908100442	79/08/07	50-311	E
7908100448	7908100439	79/08/01	50-170	S
7908100451	7908100449	79/08/03	50-334	S
7908100452	7908100445	79/08/06	50-245	S
7908100459	7908100455	79/08/02	50-302	S
7908100465	7908100458	79/08/03	50-255	P
7908100467	7908100462	79/08/03	50-346	S
7908100469	7908100461	79/07/26	50-289	S
7908100470	7908100466	79/08/07	50-335	P
7908100473	7908100472	79/08/02	50-369	A
7908100475	7908100471	79/08/07	50-244	S
7908100482	7908100478	79/08/02	50-312	S
7908100483	7908100479	79/07/31	50-170	S
7908100491	7908100486	79/07/26	50-317	S
7908100501	7908100496	79/08/02	50-346	S
7908100503	7908100500	79/07/26	50-317	S
7908100508	7908100506	79/05/29	QA999	
7908100516	7908100514	79/07/06	XPORTLIC	
7908100527	7908100524	79/07/12	10CFR	
7908100553	7908100544	79/07/16	50-482	Q
7908100590	7908100587	79/07/02	71-18	
7908130023	7908130021	79/07/26	50-255	Q
7908130078	7908130070	79/06/15	SECY	
7908130084	7908130070	79/06/15	SECY	
7908130109	7908130100	79/07/02	SECY	
7908130118	7908130111	79/07/18	50-483	Q
7908130122	7908130119	79/06/28	50-155	F
7908130136	7908130129	79/06/18	SECY	
7908130141	7908130129	79/06/18	SECY	
7908130142	7908130133	79/07/10	QA999	
7908130144	7908130133	79/07/10	QA999	
7908130147	7908130129	79/06/18	SECY	
7908130148	7908130139	79/07/27	NUREG	
7908130153	7908130151	79/06/19	SECY	
7908130156	7908130139	79/07/27	NUREG	
7908130157	7908130151	79/06/19	SECY	
7908130161	7908130127	79/07/17	50-295	Q
7908130163	7908130151	79/06/19	SECY	
7908130166	7908130133	79/07/10	QA999	
7908130170	7908130133	79/07/10	QA999	
7908130186	7908130179	79/06/29	70-754	
7908130190	7908130179	79/06/29	70-754	
7908130197	7908130179	79/06/29	70-754	
7908130201	7908130188	79/07/09	50-445	M
7908130203	7908130179	79/06/29	70-754	
7908130212	7908130179	79/06/29	70-754	
7908130220	7908130213	79/07/10	QA999	
7908130225	7908130213	79/07/10	QA999	
7908130228	7908130213	79/07/10	QA999	
7908130235	7908130213	79/07/10	QA999	
7908130275	7908130269	79/07/02	TOPREP	
7908130291	7908130288	79/06/21	50-271	Q
7908130292	7908130286	79/07/03	GEN TEC	IS
7908130311	7908130309	79/07/11	50-329	A
7908130317	7908130309	79/07/11	50-329	A
7908130324	7908130315	79/06/25	50-293	P
7908130340	7908130335	79/06/26	50-508	Q
7908130345	7908130338	79/08/02	50-366	S
7908130355	7908130352	79/08/08	50-338	R
7908130370	7908130366	79/07/16	QA999	
7908130373	7908130366	79/07/16	QA999	
7908130376	7908031366	79/07/16	QA999	
7908130379	7908130366	79/07/16	QA999	
7908130381	7908130378	79/05/01	70-143	

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908130382	7908130366	79/07/16	QA999	
7908130383	7908130378	79/05/01	70-143	
7908130385	7908130384	79/05/01	70-364	
7908130388	7908130384	79/05/01	70-364	
7908130389	7908130387	79/08/02	50-344	S
7908130390	7908130386	79/06/21	50-219	Q
7908130397	7908130393	79/06/25	50-332	Q
7908130399	7908130393	79/06/25	50-332	Q
7908130412	7908130408	79/07/06	40-6681	
7908130415	7908130410	79/08/03	50-321	S
7908130420	7908130414	79/08/03	50-331	S
7908130422	7908130417	79/06/21	50-219	Q
7908130424	7908130419	79/08/01	50-334	S
7908130426	7908130419	79/08/01	50-334	S
7908130429	7908130428	79/08/06	50-326	R
7908130432	7908130430	79/08/03	50-267	P
7908130434	7908130419	79/08/01	50-334	S
7908130435	7908130423	79/08/03	50-366	S
7908130437	7908130436	79/08/02	50-366	S
7908130438	7908130419	79/08/01	50-334	S
7908130442	7908130419	79/08/01	50-334	S
7908130444	7908130439	79/08/07	50-263	Q
7908130445	7908130419	79/08/01	50-334	S
7908130451	7908130449	79/07/31	TOPREP	
7908130453	7908130440	79/08/01	50-366	S
7908130459	7908130454	79/08/08	50-338	S
7908130460	7908130457	79/08/07	50-309	P
7908130462	7908130458	79/08/02	50-334	S
7908130473	7908130469	79/08/06	50-366	S
7908130485	7908130482	79/07/10	QA999	
7908130487	7908130482	79/07/10	QA999	
7908130488	7908130482	79/07/10	QA999	
7908130490	7908130482	79/07/10	QA999	
7908130494	7908130491	79/08/03	50-366	S
7908130495	7908130492	79/06/21	50-352	Q
7908130502	7908130497	79/08/03	50-366	S
7908130513	7908130507	79/06/05	50-312	P
7908130589	7908130586	79/07/13	40-299	
7908130600	7908130599	79/06/11	70-1257	
7908130621	7908130609	79/06/21	50-423	Q
7908130625	7908130615	79/07/09	QA999	
7908130629	7908130618	79/06/01	SECY	
7908130634	7908130615	79/07/09	QA999	
7908130638	7908130626	79/06/20	50-29	Q
7908130641	7908130615	79/07/09	QA999	
7908130646	7908130618	79/06/01	SECY	
7908130651	7908130615	79/07/09	QA999	
7908130653	7908130618	79/06/01	SECY	
7908130659	7908130618	79/06/01	SECY	
7908130660	7908130652	79/06/22	50-29	Q
7908130663	7908130662	79/06/22	50-387	Q
7908140032	7908040029	79/08/02	AGREEMENT	
7908140051	7908140049	79/06/22	50-336	Q
7908140052	7908140048	79/06/29	50-275	Q
7908140057	7908140055	79/07/19	50-498	Q
7908140069	7908140064	79/07/05	QA999	
7908140071	7908140064	79/07/05	QA999	
7908140077	7908140064	79/07/05	QA999	
7908140105	7908140097	79/07/10	50-280	P
7908140110	7908140103	79/07/11	71-255	
7908140166	7908140163	79/05/29	70-2443	
7908140186	7908140177	79/07/12	50-368	Q
7908140187	7908140175	79/07/05	40-8693	
7908140191	7908140188	79/07/13	40-8663	
7908140204	7908140197	79/06/21	50-556	A
7908140226	7908140064	79/07/05	QA999	
7908140231	7908140219	79/06/28	50-264	F
7908140268	7908140257	79/04/26	SECY	
7908140277	7908140257	79/04/26	SECY	
7908140285	7908140275	79/06/30	COMMISSION	
7908140291	7908140275	79/06/30	COMMISSION	
7908140292	7908140257	79/04/26	SECY	
7908140299	7908140275	79/06/30	COMMISSION	
7908140306	7908140275	79/06/30	COMMISSION	
7908140326	7908140275	79/06/30	COMMISSION	
7908140329	7908140315	79/06/30	71-149	
7908140355	7908140346	79/07/10	AGREEMENT	
7908140356	7908140349	79/06/21	RES	
7908140366	7908140360	79/08/07	50-329	S
7908140370	7908140364	79/06/15	SECY	
7908140373	7908140365	79/08/10	50-29	R
7908140375	7908140363	79/06/25	50-528	Q
7908140379	7908140374	79/06/15	CONTRACT	
7908140385	7908140363	79/06/25	50-528	Q
7908140387	7908140382	79/08/08	50-305	R
7908140389	7908140364	79/06/15	SECY	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908140391	7908140378	79/08/07	50-219	P
7908140392	7908140363	79/06/25	50-528	Q
7908140397	7908140363	79/06/25	50-528	Q
7908140406	7908140399	79/07/09	71-24	
7908140409	7908140401	79/08/09	50-266	R
7908140414	7908140411	79/08/09	50-390	K
7908140419	7908140404	79/08/08	50-272	P
7908140432	7908140427	79/07/31	50-445	K
7908140437	7908140429	79/08/10	50-271	R
7908140444	7908140440	79/06/01	CONTRACT	
7908140451	7908140445	79/08/10	50-259	R
7908140465	7908140460	79/08/07	50-346	R
7908140467	7908140463	79/07/[illegible]	50-280	P
7908140479	7908140476	79/07/03	71-241	
7908140482	7908140473	79/08/07	50-312	R
7908140488	7908140470	79/07/05	50-250	U
7908140494	7908140487	79/08/09	50-206	R
7908140504	7908140499	79/08/09	50-267	R
7908140507	7908140502	79/06/06	40-8027	
7908140514	7908140512	79/07/16	40-8681	
7908140516	7908140510	79/08/08	50-286	R
7908140521	7908140517	79/08/08	FOIA	
7908140525	7908140518	79/08/10	50-334	R
7908140526	7908140517	79/06/08	FOIA	
7908140531	7908140517	79/08/08	FOIA	
7908140535	7908140530	79/08/10	50-443	A
7908140538	7908140536	79/08/07	50-255	R
7908140542	7908140537	79/07/24	50-295	S
7908140546	7908140543	79/08/09	50-346	R
7908140548	7908140540	79/08/07	50-390	S
7908140555	7908140551	79/07/26	50-295	S
7908140556	7908140552	79/08/06	50-259	P
7908140559	7908140558	79/08/09	50-315	P
7908140588	7908140582	79/08/03	50-265	S
7908140590	7908140439	79/07/18	70-1207	
7908140606	7908140600	79/07/05	50-155	H
7908140611	7908140602	79/08/08	50-346	P
7908140612	7908140604	79/08/01	50-265	S
7908140625	7908140616	79/07/31	50-250	S
7908140628	7908140623	79/08/03	50-265	S
7908140629	7908140615	79/08/06	50-249	R
7908140637	7908140632	79/08/08	50-316	S
7908140645	7908140643	79/08/06	50-295	S
7908140646	7908140635	79/08/07	50-366	S
7908140647	7908140642	79/07/25	50-409	S
7908140655	7908140651	79/08/1[illegible]	50-220	S
7908140656	7908140650	79/08/0[illegible]	50-315	S
7908140658	7908140648	79/08/09	50-271	S
7908140660	7908140652	79/07/02	50-410	S
7908140665	7908140661	79/08/10	50-29	S
7908140669	7908140664	79/06/19	XPORTLIC	
7908140673	7908140662	79/08/09	50-348	S
7908140676	7908140670	79/08/07	50-219	S
7908140679	7908140671	79/07/20	50-413	S
7908140682	7908140677	79/06/01	50-522	Q
7908140684	7908140672	79/07/05	50-518	S
7908140685	7908140681	79/07/26	50-438	S
7908140689	7908140677	79/06/01	50-522	Q
7908140690	7908140680	79/07/30	50-254	S
7908140695	7908140683	79/08/08	50-285	Q
7908140700	7908140693	79/08/08	50-324	S
7908140702	7908140696	79/08/08	50-366	S
7908140715	7908140706	79/08/02	50-327	S
7908140717	7908140712	79/08/08	50-27	R
7908140724	7908140720	79/08/10	50-336	P
7908140726	7908140713	79/08/01	50-335	S
7908140738	7908140732	79/08/09	50-272	P
7908140741	7908140734	79/06/25	50-272	P
7908140742	7908140736	79/08/03	TOPREP	
7908140745	7908140733	79/08/08	50-348	S
7908140747	7908140736	79/08/03	TOPREP	
7908140750	7908140650	79/08/08	50-315	S
7908140752	7908140736	79/08/03	TOPREP	
7908140753	7908140746	79/06/06	50-387	S
7908140754	7908140748	79/08/02	50-304	S
7908140758	7908140755	79/08/09	50-285	R
7908140762	7908140757	79/06/29	71-44	
7908140764	7908140761	79/08/03	50-298	R
7908140765	7908140759	79/08/10	50-282	R
7908140768	7908140749	79/08/07	50-334	S
7908140769	7908140766	79/05/08	50-263	R
7908140774	7908140770	79/08/10	50-309	R
7908140778	7908140771	79/07/31	50-304	S
7908140783	7908140775	79/08/10	50-263	S
7908140785	7908140780	79/07/30	50-295	S
7908140795	7908140790	79/06/22	50-344	S

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908140796	7908140791	79/08/07	50-366	S
7908140797	7908140793	79/08/09	50-346	S
7908140800	7908140788	79/08/08	50-244	S
7908140806	7908140802	79/08/07	50-321	S
7908140808	7908140803	79/07/26	50-327	S
7908140814	7908140810	79/07/31	50-295	S
7908140816	7908140807	79/08/08	50-259	S
7908140820	7908140818	79/08/10	50-272	S
7908140823	7908140812	79/08/03	50-366	S
7908140828	7908140821	79/08/09	50-334	S
7908140831	7908140826	79/08/03	50-247	S
7908140832	7908140829	79/08/08	FOIA	
7908140834	7908140829	79/08/08	FOIA	
7908140836	7908140829	79/08/08	FOIA	
7908140837	7908140833	79/08/08	50-366	S
7908140841	7908140839	79/08/10	50-334	P
7908140845	7908140838	79/07/30	50-438	S
7908150002	7908150001	79/06/29	50-250	Q
7908150030	7908150025	79/07/03	71-238	
7908150035	7908150032	79/08/09	FOIA	
7908150046	7908150039	79/08/09	FOIA	
7908150050	7908150045	79/08/08	50-331	S
7908150063	7908150059	79/07/20	50-367	Q
7908150065	7908150058	79/08/08	FOIA	
7908150072	7908150068	79/07/03	50-201	U
7908150078	7908150071	79/08/09	FOIA	
7908150090	7908150080	79/06/29	50-282	Q
7908150107	7908150084	79/07/26	50-155	H
7908150112	7908150109	79/07/18	XPORTLIC	
7908150125	7908150084	79/07/26	50-155	H
7908150130	7908150120	79/06/25	50-483	Q
7908150136	7908150128	79/07/20	70-754	
7908150139	7908150084	79/07/26	50-155	H
7908150146	7908150142	79/06/27	50-346	P
7908150153	7908150142	79/06/27	50-346	P
7908150157	7908150149	79/07/20	50-443	H
7908150162	7908150142	79/06/27	50-346	P
7908150167	7908150159	79/06/27	REGOD	
7908150169	7908150161	79/07/09	TOPREP	
7908150172	7908150159	79/06/27	REGOD	
7908150174	7908150168	79/06/11	71-137	
7908150176	7908150160	79/06/25	50-484	Q
7908150179	7908150159	79/06/27	REGOD	
7908150196	7908150178	79/06/29	50-361	Q
7908150197	7908150189	79/07/17	XPORTLIC	
7908150199	7908150188	79/06/27	50-522	Q
7908150200	7908150187	79/07/12	50-280	Q
7908150206	7908150187	79/07/12	50-280	Q
7908150209	7908150204	79/07/17	71-9081	
7908150210	7908150187	79/07/12	50-280	Q
7908150212	7908150202	79/06/29	50-397	Q
7908150214	7908150193	79/08/06	50-409	S
7908150215	7908150204	79/07/17	71-9081	
7908150216	7908150187	79/07/12	50-280	Q
7908150219	7908150204	79/07/17	71-9081	
7908150226	7908150222	79/06/01	50-275	Q
7908150232	7908150225	79/06/25	50-266	Q
7908150233	7908150222	79/06/01	50-275	Q
7908150241	7908150222	79/06/01	50-275	Q
7908150246	7908150222	79/06/01	50-275	Q
7908150247	7908150238	79/07/17	50-280	Q
7908150251	7908150235	79/06/26	50-361	Q
7908150254	7908150238	79/07/17	50-280	Q
7908150263	7908150258	79/05/29	70-1257	
7908150264	7908150238	79/07/17	50-280	Q
7908150266	7908150255	79/06/25	50-315	Q
7908150267	7908150260	79/07/24	50-556	A
7908150269	7908150258	79/05/29	70-1257	
7908150274	7908150238	79/07/17	50-280	Q
7908150279	7908150273	79/07/23	50-275	H
7908150287	7908150273	79/07/23	50-275	H
7908150290	7908150280	79/06/25	50-315	Q
7908150294	7908150285	79/07/12	50-369	Q
7908150299	7908150296	79/07/23	50-237	Q
7908150302	7908150285	79/07/12	50-369	Q
7908150311	7908150304	79/07/12	50-361	Q
7908150320	7908150314	79/06/22	50-315	S
7908150322	7908150310	79/07/13	50-438	Q
7908150331	7908150310	79/07/13	50-438	Q
7908150333	7908150329	79/05/25	71-131	
7908150337	7908150310	79/07/13	50-438	Q
7908150345	7908150310	79/07/13	50-438	Q
7908150346	7908150280	79/06/25	50-315	Q
7908150348	7908150338	79/06/05	50-466	Q
7908150354	7908150341	79/06/29	50-454	Q
7908150362	7908150358	79/06/11	50-358	Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908150367	7908150357	79/06/25	50-315	Q
7908150370	7908150358	79/06/11	50-358	Q
7908150372	7908150355	79/07/13	50-438	Q
7908150375	7908150364	79/06/29	50-254	Q
7908150378	7908150355	79/07/13	50-438	Q
7908150382	7908150357	79/06/25	50-315	Q
7908150385	7908150355	79/07/13	50-438	Q
7908150393	7908150388	79/07/09	70-8	
7908150394	7908150355	79/07/13	50-438	Q
7908150400	7908150390	79/07/13	50-321	Q
7908150402	7908150397	79/07/27	CONTRACT	
7908150407	7908150390	79/07/13	50-321	Q
7908150409	7908150405	79/07/23	50-309	P
7908150418	7908150412	79/07/23	50-329	Q
7908150428	7908150419	79/08/08	50-409	R
7908150441	7908150435	79/07/19	50-382	Q
7908150442	7908150432	79/08/10	50-466	A
7908150443	7908150431	79/06/29	50-326	Q
7908150447	7908150435	79/07/19	50-382	Q
7908150454	7908150435	79/07/19	50-382	Q
7908150457	7908150450	79/06/19	50-329	Q
7908150463	7908150449	79/07/26	50-320	H
7908150466	7908150449	79/07/26	50-320	H
7908150471	7908150465	78/01/26	ORG	
7908150473	7908150470	79/07/16	50-320	P
7908150475	7908150465	78/01/26	ORG	
7908150479	7908150465	78/01/26	ORG	
7908150482	7908150450	79/06/19	50-329	Q
7908150483	7908150477	79/07/06	50-320	Q
7908150485	7908150477	79/07/06	50-320	Q
7908150487	7908150465	78/01/26	ORG	
7908150488	7908150477	79/07/06	50-320	Q
7908150491	7908150465	78/01/26	ORG	
7908150494	7908150492	79/06/29	50-320	Q
7908150500	7908150498	79/07/31	50-366	P
7908150504	7908150502	79/08/10	50-346	S
7908150506	7908150503	79/08/01	50-390	S
7908150511	7908150506	79/08/07	50-277	S
7908150519	7908150513	79/08/08	50-321	R
7908150527	7908150522	79/07/09	71-264	
7908150533	7908150528	79/06/26	50-280	Q
7908150535	7908150526	79/08/01	50-327	S
7908150538	7908150531	79/08/08	50-366	R
7908150550	7908150545	79/07/31	50-390	S
7908150553	7908150543	79/07/06	70-143	
7908150568	7908150560	79/08/02	50-397	S
7908150579	7908150574	79/07/18	XPORTLIC	
7908150587	7908150583	79/07/12	70-1151	
7908150588	7908150581	79/08/10	50-277	P
7908150590	7908150583	79/07/12	70-1151	
7908150594	7908150583	79/07/12	70-1151	
7908150597	7908150583	79/07/12	70-1151	
7908150602	7908150583	79/07/12	70-1151	
7908150606	7908150601	79/06/04	50-358	Q
7908150608	7908150613	79/07/02	50-320	P
7908150609	7908150583	79/07/12	70-1151	
7908150612	7908150603	79/08/13	50-470	R
7908150615	7908150601	79/06/04	50-358	Q
7908150619	7908150601	79/06/04	50-358	Q
7908150620	7908150614	79/05/30	50-329	Q
7908150623	7908150618	79/08/13	50-344	P
7908150627	7908150614	79/05/30	50-329	Q
7908150628	7908150601	79/06/04	50-358	Q
7908150633	7908150630	79/08/10	50-220	R
7908150637	7908150601	79/06/04	50-358	Q
7908150647	7908150643	79/08/07	50-57	R
7908150652	7908150648	79/07/09	70-1257	
7908150661	7908150656	79/07/16	50-320	P
7908150675	7908150670	79/07/30	TOPREP	
7908150677	7908150669	79/07/23	50-412	A
7908150680	7908150671	79/08/10	50-324	S
7908150687	7908150681	79/08/01	TOPREP	
7908150688	7908150682	79/08/07	50-397	S
7908150693	7908150690	79/08/03	50-538	P
7908150701	7908150699	79/07/10	71-131	
7908150707	7908150684	79/07/16	50-320	P
7908150735	7908150733	79/07/09	50-320	H
7908150739	7908150738	79/07/16	50-320	P
7908150751	7908150748	79/06/25	50-320	H
7908150753	7908150750	79/07/20	50-289	Q
7908150758	7908150755	79/07/10	50-320	P
7908150760	7908150754	79/06/21	50-320	Q
7908150769	7908150764	79/07/06	50-320	Q
7908160022	7908160020	79/07/19	PRM	
7908160026	7908160023	79/07/17	70-1379	
7908160101	7908160096	79/07/13	50-409	P

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908160103	7908160096	79/07/13	50-409	P
7908160108	7908160096	79/07/13	50-409	P
7908160109	7908160102	79/06/29	40-8714	
7908160114	7908160111	79/07/25	50-3	Q
7908160115	7908160102	79/06/29	40-8714	
7908160120	7908160117	79/06/27	50-282	Q
7908160129	7908160118	79/08/03	50-282	P
7908160130	7908160117	79/06/27	50-282	Q
7908160138	7908160118	79/08/03	50-282	P
7908160143	7908160118	79/08/03	50-282	P
7908160156	7908160150	79/07/16	71-10	
7908160169	7908160161	79/07/23	50-219	P
7908160179	7908160161	79/07/23	50-219	P
7908160181	7908160175	79/07/02	50-250	Q
7908160185	7908160175	79/07/02	50-250	Q
7908160188	7908160172	79/07/16	RES	
7908160189	7908160161	79/07/23	50-219	P
7908160193	7908160184	79/06/28	50-315	Q
7908160194	7908160175	79/07/02	50-250	Q
7908160216	7908160210	79/07/19	50-206	P
7908160217	7908160209	79/06/29	70-135	
7908160220	7908160210	79/07/19	50-206	P
7908160226	7908160210	79/07/19	50-206	P
7908160235	7908160225	79/06/27	50-346	P
7908160241	7908160225	79/06/27	50-346	P
7908160248	7908160225	79/06/27	50-346	P
7908160255	7908160225	79/06/27	50-346	P
7908160257	7908160240	79/06/25	50-346	M
7908160260	7908160225	79/06/27	50-346	P
7908160264	7908160240	79/06/25	50-346	M
7908160267	7908160225	79/06/27	50-346	P
7908160272	7908160240	79/06/25	50-346	M
7908160281	7908160240	79/06/25	50-346	M
7908160284	7908160225	79/06/27	50-346	P
7908160291	7908160225	79/06/27	50-346	P
7908160297	7908160240	79/06/25	50-346	M
7908160299	7908160225	79/06/27	50-346	P
7908160300	7908160295	79/07/26	50-374	A
7908160306	7908160225	79/06/27	50-346	P
7908160315	7908160313	79/06/29	50-346	Q
7908160319	7908160310	79/07/27	50-321	Q
7908160322	7908160313	79/06/29	50-346	Q
7908160327	7908160310	79/07/27	50-321	Q
7908160331	7908160325	79/07/20	50-395	Q
7908160338	7908160334	79/07/30	50-424	Q
7908160341	7908160325	79/07/20	50-395	Q
7908160343	7908160339	79/06/11	50-309	F
7908160344	7908160328	79/07/10	CONTRACT	
7908160345	7908160337	79/08/10	50-267	R
7908160349	7908160334	79/07/30	50-424	Q
7908160352	7908160348	79/08/13	50-280	R
7908160353	7908160350	79/07/18	71-109	
7908160355	7908160354	79/08/13	50-281	P
7908160361	7908160360	78/12/12	70-143	
7908160364	7908160360	78/12/12	70-143	
7908160379	7908160374	79/08/10	50-269	S
7908160381	7908160377	79/07/10	CONTRACT	
7908160385	7908160383	79/07/13	CONTRACT	
7908160391	7908160389	79/07/13	CONTRACT	
7908160395	7908160393	79/07/10	CONTRACT	
7908160411	7908160351	79/07/18	50-400	Q
7908160413	7908160409	79/08/09	50-245	S
7908160415	7908160351	79/07/18	50-400	Q
7908160425	7908160422	79/07/09	CONTRACT	
7908160432	7908160427	79/08/10	50-361	S
7908160433	7908160429	79/08/13	50-338	S
7908160434	7908160430	79/07/23	CONTRACT	
7908160435	7908160429	79/08/13	50-338	S
7908160440	7908160437	79/08/13	50-282	R
7908160443	7908160438	79/08/10	50-412	S
7908160444	7908160441	79/08/10	50-336	R
7908160451	7908160447	79/08/10	50-277	R
7908160452	7908160450	79/08/09	50-410	A
7908160453	7908160449	79/08/08	50-409	P
7908160457	7908160454	79/06/12	50-280	Q
7908160461	7908160455	79/08/10	50-336	S
7908160465	7908160460	79/06/15	50-250	Q
7908160468	7908160463	79/08/06	50-251	S
7908160472	7908160467	79/08/14	50-280	P
7908160475	7908160469	79/07/18	50-321	Q
7908160476	7908160470	79/07/19	50-348	Q
7908160477	7908160471	79/08/10	50-245	S
7908160478	7908160469	79/07/18	50-321	Q
7908160480	7908160470	79/07/19	50-348	Q
7908160483	7908160470	79/07/19	50-348	Q
7908160484	7908160479	79/08/13	50-280	S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908160486	7908160473	79/08/15	50-416	K
7908160487	7908160470	79/07/19	50-348	G
7908160488	7908160481	79/07/19	50-321	G
7908160489	7908160481	79/07/19	50-321	G
7908160490	7908160481	79/07/19	50-321	G
7908160491	7908160481	79/07/19	50-321	G
7908160505	7908160499	79/07/19	71-311	
7908160509	7908160503	79/07/19	71-297	
7908160515	7908160510	79/07/19	71-315	
7908160519	7908160513	79/07/19	71-301	
7908160522	7908160517	79/07/19	71-313	
7908160527	7908160524	79/07/19	71-317	
7908160528	7908160525	79/07/19	71-312	
7908160529	7908160501	79/06/28	50-338	P
7908160531	7908160501	79/06/28	50-338	P
7908160536	7908160534	79/07/19	71-72	
7908160540	7908160537	79/07/25	CONTRACT	
7908160542	7908160538	79/07/19	71-146	
7908160544	7908160535	79/07/25	CONTRACT	
7908160548	7908160543	79/07/09	CONTRACT	
7908160550	7908160546	79/07/19	71-295	
7908160559	7908160554	79/07/19	71-299	
7908160560	7908160552	79/07/25	71-9033	
7908160564	7908160562	79/07/19	71-291	
7908160566	7908160561	79/06/20	50-266	P
7908160574	7908160572	79/07/19	71-309	
7908170056	7908170054	79/07/23	CONTRACT	
7908170059	7908170057	79/07/13	50-369	G
7908170061	7908170057	79/07/13	50-369	G
7908170063	7908170060	79/07/24	CONTRACT	
7908170070	7908170066	79/07/10	CONTRACT	
7908170071	7908170067	79/07/11	70-143	
7908170074	7908170067	79/07/11	70-143	
7908170080	7908170072	79/07/26	50-410	S
7908170081	7908170076	79/07/19	50-245	P
7908170082	7908170079	79/06/18	50-333	G
7908170086	7908170076	79/07/19	50-245	P
7908170092	7908170090	79/07/19	50-206	P
7908170093	7908170091	79/06/19	70-1143	
7908170094	7908170090	79/07/19	50-206	P
7908170097	7908170090	79/07/19	50-206	P
7908170098	7908170095	79/07/26	50-155	P
7908170101	7908170095	79/07/26	50-155	P
7908170106	7908170095	79/07/26	50-155	P
7908170114	7908170107	79/07/06	50-361	G
7908170122	7908170115	79/07/03	CONTRACT	
7908170123	7908170117	79/06/19	50-312	G
7908170129	7908170119	79/06/19	70-984	
7908170130	7908170124	79/07/16	XPORTLIC	
7908170131	7908170126	79/07/24	CONTRACT	
7908170147	7908170138	79/06/12	50-259	G
7908170158	7908170152	79/06/12	70-27	
7908170169	7908170165	79/07/18	50-155	G
7908170170	7908170168	79/07/23	50-302	P
7908170172	7908170168	79/07/23	50-302	P
7908170177	7908170168	79/07/23	50-302	P
7908170179	7908170173	79/06/27	50-373	G
7908170185	7908170183	79/07/31	40-8698	
7908170187	7908170183	79/07/31	40-8698	
7908170202	7908170195	79/06/22	50-348	G
7908170217	7908170206	79/06/14	50-400	G
7908170221	7908170216	79/07/20	50-289	P
7908170224	7908170216	79/07/20	50-289	P
7908170233	7908170231	79/07/19	71-289	
7908170234	7908170226	79/06/19	50-348	G
7908170236	7908170175	79/07/23	ORG	
7908170241	7908170235	79/06/19	50-440	G
7908170244	7908170242	79/07/19	71-288	
7908170246	7908170235	79/06/19	50-440	G
7908170262	7908170257	79/07/19	71-290	
7908170266	7908170261	79/07/16	50-346	M
7908170271	7908170265	79/07/25	50-10	P
7908170272	7908170267	79/07/18	50-228	F
7908170275	7908170265	79/07/25	50-10	P
7908170280	7908170265	79/07/25	50-10	P
7908170283	7908170277	79/07/12	50-553	G
7908170290	7908170288	79/07/19	71-303	
7908170295	7908170286	79/07/23	COMMISSION	
7908170303	7908170291	79/07/24	CONTRACT	
7908170308	7908170305	79/07/18	COMMISSION	
7908170312	7908170307	79/02/16	40-8693	
7908170317	7908170314	79/07/18	COMMISSION	
7908170319	7908170316	79/07/02	TOPREP	
7908170322	7908170314	79/07/18	COMMISSION	
7908170328	7908170324	79/08/13	50-286	P
7908170332	7908170327	79/07/18	COMMISSION	

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908170343	7908170341	79/08/13	50-316	R
7908170344	7908170340	79/07/12	COMMISSION	
7908170346	7908170340	79/07/12	50-329	G
7908170349	7908170340	79/07/12	COMMISSION	
7908170363	7908170360	79/07/02	70-2319	
7908170367	7907170360	79/07/02	70-2319	
7908170369	7908170360	79/07/02	70-2319	
7908170382	7908170380	79/08/07	50-297	R
7908170393	7908170390	79/08/10	50-329	B
7908170402	7908170401	79/08/14	50-255	S
7908170407	7908170403	79/07/12	TOPREP	
7908170413	7908170409	79/08/10	50-302	R
7908170415	7908170410	79/08/10	50-336	B
7908170423	7908170418	79/08/09	50-293	B
7908170430	7908170426	79/08/09	50-289	B
7908170435	7908170432	79/08/13	50-286	B
7908170438	7908170434	79/08/15	50-361	A
7908170449	7908170442	79/08/09	50-327	A
7908170454	7908170442	79/08/09	50-327	A
7908170457	7908170450	79/08/06	FOIA	
7908170461	7908170456	79/06/22	50-261	G
7908170462	7908170450	79/08/06	FOIA	
7908170469	7908170450	79/08/06	FOIA	
7908170472	7908170466	79/05/30	50-89	G
7908170483	7908170522	79/07/12	50-482	G
7908170486	7908170479	79/06/12	70-143	
7908170496	7908170488	79/07/24	50-280	H
7908170505	7908170502	79/07/17	50-289	P
7908170507	7908170503	79/07/19	10CFR	
7908170515	7908170485	79/06/15	50-269	G
7908170520	7908170518	79/07/16	70-572	
7908170525	7908170518	79/07/16	70-572	
7908170526	7908170144	79/08/01	50-275	B
7908170527	7908170518	79/07/16	70-572	
7908170528	7908170523	79/07/13	50-133	P
7908170530	7908170522	79/07/12	50-482	G
7908170531	7908170518	79/07/16	70-572	
7908170532	7908170523	79/07/13	50-133	P
7908170535	7908170522	79/07/12	50-482	G
7908170536	7908170523	79/07/13	50-133	P
7908170539	7908170522	79/07/12	50-482	G
7908170542	7908170518	79/07/16	70-572	
7908170545	7908170541	79/06/29	50-335	G
7908170547	7908170518	79/07/16	70-572	
7908170548	7908170522	79/07/12	50-482	G
7908170553	7908170518	79/07/16	70-572	
7908170557	7908170518	79/07/16	70-572	
7908170558	7908170549	79/07/16	50-329	G
7908170561	7908170552	79/07/26	50-366	P
7908170562	7908170555	79/07/20	50-321	G
7908170564	7908170518	79/07/16	70-572	
7908170565	7908170555	79/07/20	50-321	G
7908170566	7908170552	79/07/26	50-366	P
7908170567	7908170518	79/07/16	70-572	
7908170568	7908170555	79/07/20	50-321	G
7908170569	7908170563	79/07/17	50-338	G
7908170570	7908170552	79/07/26	50-366	P
7908170572	7908170518	79/07/16	70-572	
7908170573	7908170555	79/07/20	50-321	G
7908170585	7908170577	79/07/17	50-321	P
7908170587	7908170576	79/07/31	10CFR	
7908170590	7908170577	79/07/17	50-321	P
7908170597	7908170577	79/07/17	50-321	P
7908170604	7908170602	79/07/27	50-254	P
7908170608	7908170602	79/07/27	50-254	P
7908170611	7908170602	79/07/27	50-254	P
7908170613	7908170605	79/07/30	71-6244	
7908170623	7908170616	79/07/26	70-1151	
7908170628	7908170616	79/07/26	70-1151	
7908170629	7908170625	79/07/23	PROJ	
7908170632	7908170631	79/07/17	AGREEMENT	
7908170634	7908170616	79/07/26	70-1151	
7908200013	7908200011	79/07/25	50-335	G
7908200015	7908200011	79/07/25	50-335	G
7908200017	7908200014	79/08/06	50-389	G
7908200018	7908200011	79/07/25	50-335	G
7908200019	7908200016	79/07/25	50-280	P
7908200020	7908200011	79/07/25	50-335	G
7908200024	7908200016	79/07/25	50-280	P
7908200026	7908200022	79/07/18	GA999	
7908200027	7908200016	79/07/25	50-280	P
7908200028	7908200022	79/07/18	GA999	
7908200031	7908200022	79/07/18	GA999	
7908200032	7908200022	79/07/18	GA999	
7908200034	7908200030	79/08/01	50-250	G
7908200037	7908200036	79/07/18	GA999	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908200040	7908200036	79/07/18	QA999	
7908200041	7908200036	79/07/18	QA999	
7908200045	7908200036	79/07/18	QA999	
7908200046	7908200012	79/05/17	50-280	H
7908200054	7908200051	79/06/26	50-410	Q
7908200060	7908200058	79/06/26	50-336	Q
7908200063	7908200012	79/05/17	50-280	H
7908200065	7908200012	79/05/17	50-280	H
7908200066	7908200062	79/06/25	50-245	Q
7908200070	7908200012	79/05/17	50-280	H
7908200073	7908200012	79/05/17	50-280	H
7908200078	7908200012	79/05/17	50-280	H
7908200080	7908200012	79/05/17	50-280	H
7908200084	7908200079	79/07/23	50-387	A
7908200087	7908200012	79/05/17	50-280	H
7908200091	7908200012	79/05/17	50-280	H
7908200092	7908200088	79/07/26	71-6698	
7908200103	7908200101	79/07/17	71-91	
7908200115	7908200109	79/05/23	5C-518	F
7908200124	7908200119	79/07/19	50-400	A
7908200125	7908200123	79/07/25	CONTRACT	
7908200128	7908200122	79/06/23	50-311	Q
7908200134	7908200131	79/07/13	50-556	A
7908200137	7908200129	79/07/25	50-463	Q
7908200161	7908200159	79/06/29	71-14	
7908200211	7908200210	79/07/20	TOPREP	
7908200215	7908200209	79/07/18	50-400	Q
7908200221	7908200209	79/07/18	50-400	Q
7908200225	7908200218	79/07/06	50-247	P
7908200230	7908200218	79/07/06	50-247	P
7908200233	7908200231	79/08/01	50-293	R
7908200235	7908200229	79/07/06	50-275	Q
7908200260	7908200255	79/08/14	FOIA	
7908200263	7908200192	79/07/05	71-9113	
7908200265	7908200255	79/08/14	FOIA	
7908200267	7908200262	79/08/10	50-321	S
7908200268	7908200259	79/06/29	50-311	Q
7908200273	7908200272	79/08/13	50-321	S
7908200277	7908200274	79/07/24	50-387	Q
7908200280	7908200274	79/07/24	50-387	Q
7908200282	7908200279	79/08/03	50-250	S
7908200283	7908200274	79/07/24	50-387	Q
7908200285	7908200281	79/08/10	50-321	S
7908200286	7908200284	79/08/03	50-251	S
7908200288	7908200274	79/07/24	50-387	Q
7908200293	7908200290	79/08/15	50-282	S
7908200294	7908200292	79/08/10	50-483	S
7908200295	7908200291	79/07/18	50-546	A
7908200299	7908200296	79/08/14	50-325	S
7908200301	7908200297	79/07/20	50-352	Q
7908200306	7908200303	79/08/14	50-324	S
7908200307	7908200304	79/08/17	TOPREP	
7908200308	7908200305	79/08/14	50-368	S
7908200310	7908200304	79/08/17	TOPREP	
7908200313	7908200304	79/08/17	TOPREP	
7908200315	7908200311	79/08/14	50-348	S
7908200317	7908200255	79/08/14	FOIA	
7908200319	7908200316	79/08/14	50-344	P
7908200321	7908200318	79/07/11	50-275	A
7908200323	7908200320	79/08/10	50-366	S
7908200325	7908200322	79/08/10	50-213	R
7908200333	7908200328	79/08/10	50-317	S
7908200340	7908200337	79/08/10	50-366	S
7908200345	7908200342	79/08/13	50-247	R
7908200347	7908200344	79/08/06	50-335	S
7908200350	7908200348	79/08/17	FOIA	
7908200352	7908200302	79/08/10	50-366	S
7908200355	7908200351	79/08/10	50-366	S
7908200356	7908200353	79/08/10	50-324	R
7908200357	7908200354	79/08/07	50-522	H
7908200360	7908200359	79/08/10	50-261	R
7908200364	7908200297	79/07/20	50-352	Q
7908200365	7908200361	79/08/02	50-397	S
7908200367	7908200366	79/08/10	50-272	R
7908200372	7908200370	79/08/09	50-312	S
7908200373	7908200369	79/08/10	50-336	P
7908200374	7908200371	79/08/10	50-366	S
7908200375	7908200348	79/08/17	FOIA	
7908200376	7908200368	79/08/15	50-280	S
7908200378	7908200348	79/08/17	FOIA	
7908200379	7908200377	79/08/10	50-366	S
7908200382	7908200348	79/08/17	FOIA	
7908200384	7908200348	79/08/17	FOIA	
7908200387	7908200348	79/08/17	FOIA	
7908200388	7908200381	79/08/13	50-267	P
7908200390	7908200348	79/08/17	FOIA	

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908200399	7908200398	79/07/05	PROJ	
7908200401	7908200398	79/07/05	PROJ	
7908200403	7908200398	79/07/05	PROJ	
7908200404	7908200398	79/07/05	PROJ	
7908200407	7908200398	79/07/05	PROJ	
7908200408	7908200406	79/05/08	COMMISSION	
7908210020	7908210018	79/07/12	COMMISSION	
7908210034	7908210031	79/06/06	40-8722	
7908210044	7908210038	79/07/25	QA999	
7908210046	7908210042	79/05/30	50-382	Q
7908210048	7908210041	79/07/20	40-8027	
7908210057	7908210052	79/07/20	50-269	P
7908210062	7908210052	79/07/20	50-269	P
7908210064	7908210052	79/07/20	50-269	P
7908210071	7908220066	79/07/17	50-334	P
7908210074	7908220066	79/07/17	50-334	P
7908210076	7908220066	79/07/17	50-334	P
7908210077	7908210072	79/07/26	10-443	Q
7908210078	7908210073	79/07/16	50-346	M
7908210082	7908210067	79/07/31	50-289	T
7908210087	7908210084	79/07/31	40-8380	
7908210089	7908210067	79/07/31	50-289	T
7908210096	7908210069	79/06/22	50-344	P
7908210104	7908210101	79/07/24	10CFR	
7908210112	7908210106	79/07/17	50-410	S
7908210127	7908210122	79/06/29	50-409	Q
7908210130	7908210126	79/08/10	70-143	
7908210131	7908210122	79/06/29	50-409	Q
7908210137	7908210126	79/08/10	70-143	
7908210141	7908210126	79/08/10	70-143	
7908210148	7908210126	79/08/10	70-143	
7908210158	7908210152	79/06/19	70-135	
7908210162	7908210156	78/11/09	SECY	
7908210166	7908210157	79/05/25	50-320	P
7908210168	7908210164	79/07/02	COMMISSION	
7908210172	7908210163	79/04/14	NUREG	
7908210174	7908210171	79/06/06	50-320	H
7908210181	7908210171	79/06/06	50-320	H
7908210183	7908210175	79/07/12	50-213	Q
7908210193	7908210186	73/04/09	50-320	A
7908210195	7908210192	79/06/29	71-237	
7908210198	7908210185	79/08/01	CONTRACT	
7908210217	7908210204	79/07/05	40-1162	
7908210221	7908210204	79/07/03	40-1162	
7908210225	7908210204	79/07/05	40-1162	
7908210228	7908210204	79/07/05	40-1162	
7908210229	7908210220	79/04/30	50-320	P
7908210230	7908210204	79/07/05	40-1162	
7908210233	7908210204	79/07/05	40-1162	
7908210236	7908210223	79/06/14	50-269	H
7908210240	7908210204	79/07/05	40-1162	
7908210244	7908210204	79/07/05	40-1162	
7908210279	7908210270	79/06/11	50-250	Q
7908210298	7908210294	79/07/31	CONTRACT	
7908210299	7908210296	79/08/17	TOPREP	
7908210307	7908210300	79/08/14	50-219	P
7908210310	7908210304	79/08/03	50-321	Q
7908210316	7908210304	79/08/03	50-321	Q
7908210320	7908210304	79/08/03	50-321	Q
7908210321	7908210319	79/08/10	50-263	H
7908210326	7908210324	79/08/14	50-486	Q
7908210336	7908210333	79/08/14	50-213	S
7908210355	7908210353	79/08/16	50-155	P
7908210357	7908210356	79/08/16	50-309	P
7908210363	7908210361	79/08/13	50-302	S
7908210370	7908210369	79/08/13	50-244	R
7908210372	7908210364	79/07/22	10CFR	
7908210374	7908210373	79/07/18	50-320	R
7908210387	7908210384	79/08/13	50-133	R
7908210393	7908210391	79/08/14	50-409	R
7908210398	7908210395	79/08/15	50-206	R
7908210399	7908210385	79/08/17	50-324	S
7908210404	7908210400	79/08/17	50-320	Q
7908210411	7908210407	79/08/01	40-299	
7908210417	7908210414	79/08/16	50-271	S
7908210422	7908210419	79/08/15	50-261	S
7908210429	7908210425	79/08/13	50-296	S
7908210431	7908210421	79/08/10	50-329	S
7908210434	7908210432	79/08/17	50-324	S
7908210439	7908210433	79/08/16	50-346	S
7908210448	7908210444	79/08/16	50-346	S
7908210450	7908210441	79/08/17	50-285	S
7908210460	7908210459	79/08/13	50-346	S
7908210465	7908210587	79/08/17	50-285	S
7908210482	7908210469	79/08/13	50-295	P
7908210503	7908210499	79/08/14	TOPREP	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908210516	7908210514	79/08/14	50-331	R
7908210521	7908210511	79/08/15	50-316	S
7908210524	7908210515	79/08/16	50-244	S
7908210525	7908210517	79/08/15	50-315	S
7908210527	7908210511	79/08/15	50-316	S
7908210532	7908210529	79/08/15	50-269	R
7908210534	7908210517	79/08/15	50-315	S
7908210541	7908210517	79/08/15	50-315	S
7908210546	7908210517	79/08/15	50-315	S
7908210551	7908210517	79/08/15	50-315	S
7908210552	7908210549	79/08/15	50-245	R
7908210565	7908210562	79/06/04	50-366	G
7908210569	7908210564	79/07/19	TOPREP	
7908210573	7908210567	79/06/04	50-124	G
7908210577	7908210572	79/07/20	TOPREP	
7908210583	7908210575	79/06/05	50-366	G
7908210598	7908210594	79/07/18	70-1143	
7908210601	7908210600	79/07/11	70-27	
7908210603	7908210602	79/06/11	70-820	
7908220071	7908220068	79/08/20	50-320	A
7908220073	7908220069	79/06/26	COMMISSION	
7908220075	7908220068	79/08/20	FOIA	
7908220077	7908220069	79/08/20	FOIA	
7908220083	7908220068	79/08/20	FOIA	
7908220084	7908220079	79/07/09	70-25	
7908220086	7908220068	79/08/20	FOIA	
7908220089	7908220068	79/08/20	FOIA	
7908220093	7908220087	79/06/08	50-320	G
7908220096	7908220068	79/08/20	FOIA	
7908220100	7908220068	79/08/20	FOIA	
7908220105	7908220068	79/08/20	FOIA	
7908220110	7908220068	79/08/20	FOIA	
7908220120	7908220068	79/08/20	FOIA	
7908220127	7908220068	79/08/20	FOIA	
7908220143	7908220068	79/08/20	FOIA	
7908220144	7908220113	79/07/06	50-272	G
7908220146	7908220068	79/08/20	FOIA	
7908220150	7908220068	79/08/20	FOIA	
7908220154	7908220068	79/08/20	FOIA	
7908220157	7908220152	79/06/29	50-272	G
7908220171	7908220165	79/05/23	50-320	P
7908220192	7908220184	79/07/20	40-2061	
7908220208	7908220204	79/08/07	50-237	G
7908220218	7908220212	79/08/20	50-320	P
7908220220	7908220215	79/07/16	40-8721	
7908220221	7908220212	79/08/20	50-320	P
7908220231	7908220228	79/07/06	50-346	P
7908220235	7908220229	79/07/11	50-286	P
7908220237	7908220228	79/07/06	50-346	P
7908220239	7908220229	79/07/11	50-286	P
7908220243	7908220227	79/08/07	50-263	G
7908220265	7908220260	79/08/14	CONTRACT	
7908220282	7908220277	79/07/25	GA999	
7908220292	7908220277	79/07/25	GA999	
7908220293	7908220285	79/07/30	70-1100	
7908220301	7908220277	79/07/25	GA999	
7908220305	7908220277	79/07/25	GA999	
7908220308	7908220277	79/07/25	GA999	
7908220309	7908220302	79/07/11	50-3	P
7908220314	7908220302	79/07/11	50-3	P
7908220316	7908220277	79/07/25	GA999	
7908220330	7908220324	79/07/27	CONTRACT	
7908220352	7908220346	79/07/06	50-466	G
7908220360	7908220353	79/07/26	50-346	P
7908220363	7908220353	79/07/26	50-346	P
7908220367	7908220353	79/07/26	50-346	P
7908220376	7908220370	79/08/17	50-267	S
7908220378	7908220373	79/07/26	50-220	P
7908220382	7908220373	79/07/26	50-220	P
7908220387	7908220373	79/07/26	50-220	P
7908220389	7908220385	79/08/10	50-317	S
7908220400	7908220397	79/08/10	50-237	S
7908220406	7908220403	79/07/26	50-338	G
7908220410	7908220403	79/07/26	50-338	G
7908220412	7908220403	79/07/26	50-338	G
7908220418	7908220403	79/07/26	50-338	G
7908220419	7908220415	79/07/12	50-320	P
7908220424	7908220417	79/08/10	XPORTLIC	
7908220425	7908220421	79/08/06	50-320	P
7908220434	7908220432	79/08/17	50-346	P
7908220440	7908220421	79/08/06	50-320	P
7908220444	7908220421	79/08/06	50-320	P
7908220447	7908220421	79/08/06	50-320	P
7908220450	7908220421	79/08/06	50-320	P
7908220454	7908220421	79/08/06	50-320	P
7908220460	7908220421	79/08/06	50-320	P

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908220462	7908220421	79/08/06	50-320	P
7908220466	7908220421	79/08/06	50-320	P
7908220468	7908220421	79/08/06	50-320	P
7908220472	7908220421	79/08/06	50-320	P
7908220495	7908220421	79/08/06	50-320	P
7908220499	7908220421	79/08/06	50-320	P
7908220502	7908220421	79/08/06	50-320	P
7908220503	7908220421	79/08/06	50-320	P
7908220509	7908220421	79/08/06	50-320	P
7908220514	7908220421	79/08/06	50-320	P
7908220524	7908220508	79/07/06	50-272	G
7908220533	7908220522	79/08/14	CONTRACT	
7908220536	7908220531	79/07/31	50-348	P
7908220540	7908220531	79/07/31	50-348	P
7908220542	7908220531	79/07/31	50-348	P
7908220555	7908220545	79/07/27	50-312	H
7908220559	7908220545	79/07/27	50-312	H
7908220572	7908220545	79/07/27	50-312	H
7908220584	7908220576	79/07/23	50-298	P
7908220588	7908220576	79/07/23	50-298	P
7908220593	7908220576	79/07/23	50-298	P
7908220602	7908220590	79/07/30	50-317	P
7908220618	7908220613	79/07/06	50-213	G
7908220622	7908220613	79/07/06	50-213	G
7908220639	7908220633	79/07/24	GA999	
7908220640	7908220628	79/05/11	GA999	
7908220642	7908220616	79/08/07	CONTRACT	
7908220643	7908220633	79/07/24	GA999	
7908220646	7908220633	79/07/24	GA999	
7908220662	7908220614	79/06/26	50-466	G
7908220666	7908220664	79/07/31	XPORTLIC	
7908220670	7908220667	79/05/02	GA999	
7908220682	7908220672	79/07/27	CONTRACT	
7908230037	7908230033	79/08/03	71-91	
7908230047	7908230042	79/06/25	50-358	G
7908230052	7908230042	79/06/25	50-358	G
7908230058	7908230053	79/06/22	50-460	G
7908230061	7908230053	79/06/22	50-460	G
7908230064	7908230053	79/06/22	50-460	G
7908230067	7908230053	79/06/22	50-460	G
7908230072	7908230070	79/07/26	50-244	P
7908230074	7908230070	79/07/26	50-244	P
7908230076	7908230070	79/07/26	50-244	P
7908230090	7908230089	79/08/13	71-6581	
7908230091	7908230081	79/08/01	CONTRACT	
7908230096	7908230094	79/07/27	CONTRACT	
7908230098	7908230097	79/08/03	71-167	
7908230102	7908230099	79/06/04	CONTRACT	
7908230103	7908230100	79/07/27	70-1201	
7908230106	7908230101	79/08/14	CONTRACT	
7908230109	7908230105	79/07/25	XPORTLIC	
7908230113	7908230108	79/08/03	50-440	G
7908230114	7908230110	79/07/27	50-302	P
7908230116	7908230092	79/08/03	71-67	
7908230117	7908230110	79/07/27	50-302	P
7908230121	7908230110	79/07/27	50-302	P
7908230126	7908230122	79/07/02	70-984	
7908230128	7908230120	79/08/03	50-358	G
7908230129	7908230125	79/07/03	50-358	G
7908230134	7908230125	79/07/03	50-358	G
7908230138	7908230132	79/07/30	50-315	G
7908230139	7908230125	79/07/03	50-358	G
7908230144	7908230125	79/07/03	50-358	G
7908230147	7908230125	79/07/03	50-358	G
7908230150	7908230136	79/08/09	CONTRACT	
7908230152	7908230125	79/07/03	50-358	G
7908230156	7908230124	79/08/09	CONTRACT	
7908230157	7908230125	79/07/03	50-358	G
7908230164	7908230125	79/07/03	50-358	G
7908230170	7908230163	79/05/12	SECY	
7908230173	7908230163	79/05/12	SECY	
7908230179	7908230179	79/07/12	40-4492	
7908230180	7908230163	79/05/12	SECY	
7908230182	7908230176	79/07/26	CONTRACT	
7908230184	7908230163	79/05/12	SECY	
7908230186	7908230125	79/07/03	50-358	G
7908230189	7908230163	79/05/12	SECY	
7908230192	7908230125	79/07/03	50-358	G
7908230194	7908230163	79/05/12	SECY	
7908230195	7908230188	79/07/20	CONTRACT	
7908230197	7908230125	79/07/03	50-358	G
7908230199	7908230163	79/05/12	SECY	
7908230202	7908230125	79/07/03	50-358	G
7908230205	7908230125	79/07/03	50-358	G
7908230209	7908230206	79/08/03	71-85	
7908230210	7908230203	79/08/09	CONTRACT	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908230222	7908230215	79/08/13	CONTRACT	
7908230233	7908230227	79/07/31	40-8697	
7908230237	7908230232	79/08/01	71-6722	
7908230245	7908230238	79/07/20	50-320	P
7908230251	7908230238	79/07/20	50-320	P
7908230257	7908230238	79/07/20	50-320	P
7908230266	7908230238	79/07/20	50-320	P
7908230272	7908230238	79/07/20	50-320	P
7908230289	7908230284	79/08/21	50-320	P
7908230298	7908230284	79/08/21	50-320	P
7908230306	7908230284	79/08/21	50-320	P
7908230327	7908230323	79/08/17	50-269	S
7908230340	7908230338	72/11/03	50-320	G
7908230341	7908230333	79/08/15	50-367	R
7908230349	7908230344	79/08/15	50-317	R
7908230352	7908230348	79/08/08	50-334	G
7908230355	7908230353	79/08/08	50-219	S
7908230357	7908230348	79/08/08	50-334	G
7908230359	7908230354	79/08/02	50-320	P
7908230365	7908230354	79/08/02	50-320	P
7908230366	7908230361	79/08/16	50-317	S
7908230371	7908230370	79/08/14	50-313	R
7908230373	7908230372	79/08/14	50-368	R
7908230380	7908230379	79/08/15	50-325	S
7908230382	7908230381	79/08/15	50-324	S
7908230386	7908230383	79/08/14	50-317	S
7908230390	7908230387	79/08/17	50-346	S
7908230396	7908230393	79/08/20	50-335	R
7908230402	7908230384	79/08/15	50-518	S
7908230404	7908230400	79/08/15	50-324	S
7908230410	7908230407	79/08/16	50-255	S
7908230417	7908230315	79/07/05	10CFR	
7908230422	7908230418	79/08/15	50-498	S
7908230424	7908230315	79/07/05	10CFR	
7908230435	7908230430	79/08/17	50-334	S
7908230438	7908230430	79/08/17	50-334	S
7908230439	7908230431	79/08/06	50-254	R
7908230455	7908230449	79/06/15	50-320	H
7908230459	7908230450	79/08/20	50-324	S
7908230460	7908230451	79/08/16	50-518	S
7908230465	7908230456	79/07/09	50-344	G
7908230471	7908230456	79/07/09	50-344	G
7908230480	7908230367	79/08/04	TOPREP	
7908230481	7908230476	72/09/19	50-320	G
7908230482	7908230479	79/08/20	50-277	P
7908230484	7908230456	79/07/09	50-344	G
7908230489	7908230486	79/06/03	50-320	G
7908230490	7908230456	79/07/09	50-344	G
7908230491	7908230456	79/07/09	50-344	G
7908230494	7908230486	76/06/03	50-320	G
7908230496	7908230456	79/07/09	50-344	G
7908230504	7908230456	79/07/09	50-344	G
7908230507	7908230499	77/10/07	50-320	S
7908230511	7908230456	79/07/09	50-344	G
7908230513	7908230500	79/08/17	50-318	S
7908230517	7908230510	79/08/17	50-334	S
7908230519	7908230456	79/07/09	50-344	G
7908230520	7908230515	79/07/27	COMMISSION	
7908230524	7908230516	79/01/15	50-320	G
7908230525	7908230456	79/07/09	50-344	G
7908230529	7908230523	79/08/17	50-346	S
7908230530	7908230518	79/08/15	50-317	S
7908230532	7908230456	79/07/09	50-344	G
7908230534	7908230531	78/05/31	50-320	G
7908230535	7908230528	79/07/27	COMMISSION	
7908230539	7908230456	79/07/09	50-344	G
7908230540	7908230528	79/07/27	COMMISSION	
7908230543	7908230456	79/07/09	50-344	G
7908230544	7908230531	78/05/31	50-320	G
7908230547	7908230537	79/08/20	50-325	S
7908230548	7908230541	79/08/17	50-302	S
7908230549	7908230456	79/07/09	50-344	G
7908230554	7908230456	79/07/09	50-344	G
7908230557	7908230552	79/04/23	50-320	G
7908230561	7908230556	79/08/20	50-324	S
7908230564	7908230560	79/07/09	71-9133	
7908230565	7908230552	79/04/23	50-320	G
7908230573	7908230570	74/01/31	50-320	G
7908230575	7908230566	79/08/13	50-390	S
7908230577	7908230570	74/01/31	50-320	G
7908230578	7908230571	79/07/11	50-259	G
7908230584	7908230581	74/03/29	50-320	G
7908230588	7908230586	79/07/02	50-395	G
7908230590	7908230581	74/03/29	50-320	G
7908230596	7908230589	79/08/16	50-518	S
7908230597	7908230594	76/11/05	50-320	G

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908230599	7908230595	79/07/10	50-395	G
7908230601	7908230594	76/11/05	50-320	G
7908230605	7908230602	79/08/17	50-495	B
7908230607	7908230604	76/09/15	50-320	G
7908230611	7908230604	76/09/15	50-320	G
7908230615	7908230612	79/08/20	50-275	K
7908230617	7908230614	76/09/21	50-320	G
7908230621	7908230614	76/09/21	50-320	G
7908230624	7908230619	79/07/16	50-146	G
7908230629	7908230625	76/09/16	50-320	G
7908230634	7908230625	76/09/16	50-320	G
7908230635	7908230619	79/07/16	50-146	G
7908230640	7908230637	77/02/01	50-320	G
7908230649	7908230643	75/01/15	50-320	G
7908230650	7908230647	79/06/27	50-282	P
7908230654	7908230646	79/07/27	50-255	P
7908230655	7908230651	79/07/16	70-1113	
7908230656	7908230653	79/07/24	50-201	R
7908230658	7908230651	79/07/16	70-1113	
7908230659	7908230652	77/10/05	50-320	G
7908230660	7908230646	79/07/27	50-255	P
7908230662	7908230657	79/07/10	50-261	G
7908230663	7908230646	79/07/27	50-255	P
7908230666	7908230665	79/07/06	50-445	G
7908230671	7908230668	79/07/26	50-285	G
7908230674	7908230672	79/06/25	50-280	G
7908230675	7908230673	79/07/10	71-261	
7908230680	7908230676	79/08/01	50-10	P
7908230683	7908230677	79/06/25	50-348	G
7908230684	7908230682	79/07/06	50-348	G
7908230691	7908230688	79/07/09	50-281	G
7908240035	7908240031	79/06/22	XPORTLIC	
7908240040	7908240037	79/06/15	XPORTLIC	
7908240047	7908240041	79/08/01	50-333	P
7908240048	7908240045	79/07/02	71-336	
7908240049	7908240041	79/08/01	50-333	P
7908240054	7908240041	79/08/01	50-333	P
7908240055	7908240051	79/07/16	71-338	
7908240069	7908240063	79/07/05	PRM	
7908240072	7908240063	79/07/05	PRM	
7908240081	7908240078	79/08/06	50-353	A
7908240086	7908240078	79/08/06	50-353	A
7908240087	7908240083	79/07/30	50-395	G
7908240088	7908240082	79/06/15	40-8002	
7908240090	7908240083	79/07/30	50-395	G
7908240091	7908240083	79/07/30	50-395	G
7908240096	7908240083	79/07/30	50-395	G
7908240099	7908240082	79/06/15	40-8002	
7908240104	7908240100	79/07/31	50-335	G
7908240109	7908240100	79/07/31	50-335	G
7908240110	7908240107	79/07/03	50-250	G
7908240112	7908240100	79/07/31	50-335	G
7908240113	7908240082	79/06/15	40-8002	
7908240117	7908240082	79/06/15	40-8002	
7908240118	7908240114	79/06/22	50-339	G
7908240120	7908240100	79/07/31	50-335	G
7908240122	7908240082	79/06/15	40-8002	
7908240124	7908240100	79/07/31	50-335	G
7908240127	7908240123	79/07/10	50-302	G
7908240132	7908240128	79/07/05	50-302	G
7908240144	7908240136	79/07/11	50-390	G
7908240151	7908240147	79/06/26	50-281	G
7908240152	7908240143	79/07/06	70-143	
7908240156	7908240140	79/07/30	50-281	G
7908240157	7908240143	79/07/06	70-143	
7908240159	7908240140	79/07/30	50-281	G
7908240160	7908240143	79/07/06	70-143	
7908240162	7908240140	79/07/30	50-281	G
7908240164	7908240143	79/07/06	70-143	
7908240168	7908240140	79/07/30	50-281	G
7908240172	7908240169	79/04/30	40-8102	
7908240181	7908240174	79/06/20	50-324	G
7908240182	7908240175	79/08/03	50-334	P
7908240183	7908240177	79/06/08	50-390	A
7908240188	7908240175	79/08/03	50-334	P
7908240196	7908240187	79/06/27	50-280	G
7908240202	7908240194	79/07/10	50-261	G
7908240205	7908240201	79/07/06	50-369	G
7908240213	7908240208	79/06/26	50-280	G
7908240214	7908240210	79/07/10	50-327	G
7908240225	7908240220	79/07/20	50-410	G
7908240243	7908240228	79/07/30	50-259	G
7908240254	7908240228	79/07/30	50-259	G
7908240256	7908240251	79/07/27	50-255	P
7908240277	7908240228	79/07/30	50-259	G
7908240284	7908240275	79/07/02	50-281	G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7908240286	7908240282	79/07/19	71-67
7908240288	7908240185	79/07/25	FOIA
7908240290	7908240228	79/07/30	50-259 G
7908240295	7908240293	79/07/27	COMMISSION
7908240297	7908240291	79/07/05	50-302 G
7908240311	7908240303	79/07/10	50-269 G
7908240314	7908240161	79/07/16	50-409 G
7908240316	7908240302	79/07/06	50-327 G
7908240326	7908240317	79/07/02	50-280 G
7908240336	7908240323	79/07/11	50-324 G
7908240339	7908240324	79/08/17	50-321 S
7908240353	7908240343	79/06/25	50-338 G
7908240359	7908240350	79/06/18	SECY
7908240362	7908240348	79/08/17	50-321 S
7908240365	7908240354	79/06/18	SECY
7908240366	7908240361	79/07/02	50-348 G
7908240370	7908240350	79/06/18	SECY
7908240377	7908240367	79/08/15	50-321 S
7908240393	7908240385	79/08/10	50-321 S
7908240394	7908240389	79/08/20	50-269 S
7908240404	7908240398	79/07/27	COMMISSION
7908240406	7908240401	79/08/21	50-325 S
7908240411	7908240399	79/08/16	50-321 S
7908240412	7908240408	79/08/21	50-325 S
7908240424	7908240417	79/08/17	50-321 S
7908240427	7908240422	79/08/21	50-338 S
7908240437	7908240433	79/08/17	TOPREP
7908240440	7908240436	79/08/10	50-366 S
7908240446	7908240442	79/08/21	50-424 A
7908240449	7908240444	79/08/02	TOPREP
7908240459	7908240458	79/08/17	50-213 P
7908240462	7908240457	79/08/21	50-324 S
7908240463	7908240460	79/08/21	50-29 P
7908240470	7908240466	79/08/21	50-277 P
7908240476	7908240472	79/08/17	50-321 S
7908240480	7908240469	79/08/17	50-366 S
7908240482	7908240475	79/08/21	50-70 P
7908240484	7908240483	79/07/12	71-342
7908240486	7908240479	79/08/17	50-321 S
7908240493	7908240485	79/08/21	50-338 S
7908240494	7908240473	79/07/27	COMMISSION
7908240495	7908240490	79/08/17	50-321 S
7908240498	7908240485	79/08/21	50-338 S
7908240505	7908240501	79/07/31	50-155 G
7908240511	7908240508	79/08/21	50-263 S
7908240522	7908240519	79/08/14	50-219 P
7908240524	7908240520	79/07/24	SECY
7908240527	7908240520	79/07/24	SECY
7908240528	7908240525	79/08/16	50-366 S
7908240530	7908240520	79/07/24	SECY
7908240534	7908240531	79/06/08	71-329
7908240538	7908240520	79/07/24	SECY
7908240541	7908240520	79/07/24	SECY
7908240543	7908240539	79/08/10	50-219 P
7908240548	7908240545	79/07/24	SECY
7908240551	7908240545	79/07/24	SECY
7908240553	7908240545	79/07/24	SECY
7908240554	7908240549	79/08/15	50-484 G
7908240556	7908240545	79/07/24	SECY
7908240558	7908240549	79/08/15	50-484 G
7908240598	7908240594	79/08/15	50-281 G
7908240600	7908240594	79/08/15	50-281 G
7908240601	7908240597	79/07/30	50-311 S
7908240610	7908240606	79/07/12	70-1143
7908240623	7908240622	79/07/31	40-8502
7908270009	7908270006	79/07/06	50-275 G
7908270011	7908270006	79/07/06	50-275 G
7908270069	7908270058	79/07/02	50-271 G
7908270081	7908270074	79/07/02	50-363 G
7908270095	7908270089	79/08/02	50-259 P
7908270104	7908270098	79/07/31	50-10 D
7908270107	7908270101	79/07/31	50-321 P
7908270109	7908270105	79/06/25	70-2842
7908270112	7908270101	79/07/31	50-321 P
7908270116	7908270101	79/07/31	50-321 P
7908270122	7908270117	79/06/29	50-293 G
7908270123	7908270118	79/07/02	50-445 G
7908270136	7908270131	79/05/02	70-1151
7908270148	7908270140	79/08/06	50-289 G
7908270150	7908270141	79/08/31	REGGD
7908270185	7908270177	79/08/07	50-259 G
7908270193	7908270177	79/08/07	50-259 G
7908270199	7908270177	79/08/07	50-259 G
7908270207	7908270164	79/07/19	50-220 P
7908270209	7908270177	79/08/07	50-259 G
7908270226	7908270220	79/07/31	PROJ

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7908270242	7908270232	79/08/03	50-424 G
7908270248	7908270232	79/08/03	50-424 G
7908270253	7908270232	79/08/03	50-424 G
7908270254	7908270247	79/08/09	COMMISSION
7908270261	7908270247	79/08/09	COMMISSION
7908270262	7908270232	79/08/03	50-424 G
7908270278	7908270275	79/07/31	70-143
7908270282	7908270275	79/07/31	70-143
7908270297	7908270293	79/08/09	50-369 G
7908270300	7908270293	79/08/09	50-369 G
7908270305	7908270294	79/07/25	CONTRACT
7908270309	7908270306	79/08/01	50-413 G
7908270310	7908270306	79/08/01	50-413 G
7908270317	7908270314	79/07/10	71-261
7908270318	7908270313	79/07/25	CONTRACT
7908270322	7908270320	79/08/07	CONTRACT
7908270362	7908270357	79/08/08	CONTRACT
7908270369	7908270363	79/08/22	50-344 P
7908270371	7908270366	79/08/03	71-9113
7908270374	7908270363	79/08/22	50-344 P
7908270378	7908270363	79/08/22	50-344 P
7908270385	7908270379	79/08/13	TOPREP
7908270388	7908270363	79/08/22	50-344 P
7908270394	7908270389	79/08/20	50-255 S
7908270396	7908270389	79/08/20	50-255 S
7908270398	7908270363	79/08/22	50-344 P
7908270402	7908270399	79/08/21	50-219 P
7908270411	7908270401	79/08/14	50-344 P
7908270427	7908270420	79/08/20	50-266 S
7908270434	7908270420	79/08/20	50-266 S
7908270441	7908270432	79/08/20	50-324 S
7908270444	7908270438	79/08/15	50-289 R
7908270450	7908270445	79/08/20	50-302 S
7908270467	7908270461	79/07/24	71-246
7908270472	7908270465	79/08/21	50-382 K
7908270484	7908270478	79/08/17	50-317 S
7908270485	7908270476	79/08/17	50-318 S
7908270515	7908270508	79/07/05	50-295 P
7908270523	7908270519	79/08/02	40-8725
7908270531	7908270519	79/08/02	40-8725
7908270536	7908270519	79/08/02	40-8725
7908270545	7908270539	79/06/25	50-484 G
7908270546	7908270519	79/08/02	40-8725
7908280002	7908280001	79/08/10	COMMISSION
7908280047	7908280035	79/08/17	50-471 F
7908280055	7908280052	79/08/23	FOIA
7908280059	7908280052	79/08/23	FOIA
7908280063	7908280052	79/08/23	FOIA
7908280070	7908280052	79/08/23	FOIA
7908280076	7908280052	79/08/23	FOIA
7908280077	7908280072	79/07/20	CONTRACT
7908280081	7908280052	79/08/23	FOIA
7908280087	7908280052	79/08/23	FOIA
7908280092	7908280052	79/08/23	FOIA
7908280093	7908280085	79/07/31	CONTRACT
7908280106	7908280100	79/07/23	50-219 G
7908280109	7908280100	79/07/23	50-219 G
7908280111	7908280100	79/07/23	50-219 G
7908280114	7908280052	79/08/23	FOIA
7908280123	7908280094	79/06/14	50-338 G
7908280127	7908280118	79/07/06	70-572
7908280136	7908280118	79/07/06	70-572
7908280138	7908280128	79/06/19	50-390 G
7908290146	7908280052	79/08/23	FOIA
7908280155	7908280145	79/06/20	50-327 G
7908280156	7908280052	79/08/23	FOIA
7908280163	7908280052	79/08/23	FOIA
7908280168	7908280154	79/07/17	50-155 P
7908280171	7908280162	79/06/20	50-280 G
7908280173	7908280052	79/08/23	FOIA
7908280182	7908280174	79/06/20	50-281 G
7908280185	7908280052	79/08/23	FOIA
7908280193	7908280188	79/07/02	50-305 G
7908280197	7908280052	79/08/23	FOIA
7908280206	7908280187	79/07/17	COMMISSION
7908280209	7908280052	79/08/23	FOIA
7908280214	7908280204	79/06/27	50-155 G
7908280218	7908280052	79/08/23	FOIA
7908280222	7908280052	79/08/23	FOIA
7908280225	7908280221	79/06/19	50-311 G
7908280229	7908280052	79/08/23	FOIA
7908280230	7908280227	79/06/08	71-337
7908280233	7908280228	79/06/29	50-255 G
7908280234	7908280052	79/08/23	FOIA
7908280240	7908280052	79/08/23	FOIA
7908280246	7908280239	79/07/16	50-312 A

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908280252	7908280052	79/08/23	FOIA	
7908280260	7908280052	79/08/23	FOIA	
7908280264	7908280242	79/07/25	50-10	P
7908280271	7908280052	79/08/23	FOIA	
7908280290	7908280277	79/07/30	40-8728	
7908280293	7908280285	79/06/11	71-66	
7908280299	7908280277	79/07/30	40-8728	
7908280308	7908280287	79/07/30	COMMISSION	
7908280313	7908280298	79/06/11	71-100	
7908280320	7908280315	79/08/03	71-336	
7908280338	7908280333	79/06/11	71-33	
7908280349	7908280323	79/08/03	71-338	
7908280351	7908280345	79/07/12	71-5331	
7908280360	7908280354	79/06/29	71-332	
7908280369	7908280366	79/06/29	71-329	
7908280370	7908280359	79/06/18	50-522	Q
7908280378	7908280187	79/07/17	COMMISSION	
7908280380	7908280375	79/06/29	71-330	
7908280396	7908280390	79/06/13	50-111	P
7908280400	7908280187	79/07/17	COMMISSION	
7908280403	7908280390	79/06/13	50-111	P
7908280415	7908280187	79/07/17	COMMISSION	
7908280417	7908280408	79/06/26	71-126	
7908280428	7908280187	79/07/17	COMMISSION	
7908280430	7908280424	79/08/03	71-31	
7908280438	7908280435	79/07/31	71-333	
7908280444	7908280437	79/06/27	50-341	Q
7908280450	7908280446	79/06/26	71-6400	
7908280460	7908280455	79/03/16	71-335	
7908280470	7908280464	79/06/14	71-9079	
7908280481	7908280475	79/07/19	71-293	
7908280492	7908280487	79/06/15	71-330	
7908280508	7908280503	79/06/29	50-373	Q
7908280533	7908280526	79/08/22	50-293	S
7908280542	7908280540	79/08/24	50-282	S
7908280553	7908280552	79/08/21	50-373	Q
7908280565	7908280513	79/07/24	50-546	Q
7908280573	7908280570	79/08/21	50-254	R
7908280585	7908280581	79/08/22	50-327	S
7908280591	7908280586	79/08/24	50-282	S
7908280611	7908280606	79/08/13	50-553	S
7908280616	7908280604	79/08/23	50-271	S
7908280626	7908280620	79/08/17	50-317	S
7908280627	7908280621	79/08/14	50-413	S
7908280635	7908280630	79/08/23	50-269	S
7908280639	7908280628	79/08/23	50-317	S
7908280642	7908280638	79/08/21	50-395	P
7908280643	7908280636	79/08/20	50-272	R
7908280646	7908280[illegible]	79/08/21	50-237	S
7908280652	7908280648	79/08/21	TOPREP	
7908280653	7908280[illegible]49	79/08/23	50-338	S
7908280667	7908280660	79/08/23	50-280	S
7908280668	7908280663	79/08/24	50-255	S
7908280671	7908280664	79/08/24	50-315	P
7908280672	7908280669	79/08/22	50-269	P
7908280676	7908280664	79/08/24	50-315	P
7908280682	7908280675	79/08/23	50-317	S
7908280690	7908280685	79/08/20	50-366	S
7908280692	7908280686	77/12/06	50-213	S
7908280695	7908280691	79/08/22	50-296	S
7908280699	7908280693	79/08/21	50-302	S
7908280701	7908280689	79/08/21	50-219	S
7908280702	7908280698	79/07/11	50-327	S
7908280707	7908280704	79/08/23	50-247	P
7908280721	7908280716	79/08/21	50-346	S
7908280724	7908280711	79/08/22	50-245	S
7908280731	7908280725	79/08/21	50-244	S
7908280742	7908280732	79/08/24	50-260	S
7908280759	7908280750	79/08/24	50-338	S
7908280778	7908280770	79/06/06	50-327	Q
7908280817	7908280808	79/06/06	50-302	Q
7908280838	7908280828	79/07/09	50-333	Q
7908280849	7908280828	79/07/09	50-333	Q
7908290040	7908290036	79/07/27	71-5	
7908290138	7908290131	79/06/18	50-438	Q
7908290139	7908290127	79/07/03	50-302	Q
7908290150	7908290144	79/07/12	COMMISSION	
7908290152	7908290127	79/07/03	50-302	Q
7908290167	7908290161	79/07/31	REGOD	
7908290177	7908290166	79/08/04	REGOD	
7908290184	7908290166	79/08/04	REGOD	
7908290208	7908290197	79/06/29	50-518	Q
7908290221	7908290213	79/06/19	50-302	Q
7908290237	7908290228	79/06/27	70-824	
7908290267	7908290244	79/07/06	50-285	Q
7908290269	7908290260	79/08/02	50-282	P

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908290290	7908290280	79/07/31	50-315	P
7908290294	7908290260	79/08/02	50-282	P
7908290303	7908290260	79/08/02	50-282	P
7908290306	7908290280	79/07/31	50-315	P
7908290315	7908290280	79/07/31	50-315	P
7908290328	7908290304	79/07/03	50-546	Q
7908290343	7908290336	79/08/20	71-300	
7908290343	7908290329	79/08/03	50-338	P
7908290358	7908290329	79/08/03	50-338	P
7908290363	7908290352	79/06/27	50-574	Q
7908290373	7908290329	79/08/03	50-338	P
7908290409	7908290408	79/08/21	50-321	S
7908290415	7908290413	79/08/01	50-293	R
7908290429	7908290424	79/08/10	50-250	S
7908290438	7908290423	79/08/20	50-390	S
7908290439	7908290423	79/08/22	50-315	S
7908290442	7908290432	79/07/30	CONTRACT	
7908290449	7908290436	79/08/23	50-261	S
7908290455	7908290444	79/08/20	50-277	S
7908290457	7908290450	79/08/21	50-302	S
7908290464	7908290456	79/08/24	50-333	S
7908290471	7908290467	79/08/08	CONTRACT	
7908290472	7908290461	79/08/23	50-334	S
7908290492	7908290461	79/08/23	50-334	S
7908290506	7908290499	79/05/30	50-302	P
7908290509	7908290504	79/07/10	50-305	Q
7908290514	7908290505	79/08/24	50-325	S
7908290516	7908290504	79/07/10	50-305	Q
7908290517	7908290512	79/08/23	50-313	R
7908290523	7908290520	79/07/03	50-315	Q
7908290529	7908290520	79/07/03	50-315	Q
7908290554	7908290546	79/07/23	40-4492	
7908290563	7908290548	79/08/24	50-324	S
7908290567	7908290560	79/08/23	50-329	S
7908290571	7908290575	79/08/27	50-277	P
7908290589	7908290583	79/08/17	50-171	P
7908290592	7908290584	79/08/23	50-3	Q
7908290616	7908290605	79/08/22	50-267	R
7908290634	7908290628	79/08/01	71-9111	
7908290647	7908290638	79/08/03	CONTRACT	
7908290664	7908290658	79/08/28	FOIA	
7908290674	7908290665	79/08/01	50-346	P
7908290677	7908290658	79/08/28	FOIA	
7908290680	7908290665	79/08/01	50-346	P
7908290685	7908290665	79/08/01	50-346	P
7908290686	7908290662	79/06/04	CONTRACT	
7908290691	7908290665	79/08/01	50-346	P
7908290699	7908290694	79/08/02	CONTRACT	
7908290707	7908290697	79/08/15	TOPREP	
7908290719	7908290712	79/07/25	CONTRACT	
7908300010	7908300008	79/07/11	50-522	Q
7908300018	7908300014	79/07/18	50-522	Q
7908300028	7908300024	79/06/29	50-522	Q
7908300034	7908300024	79/06/29	50-522	Q
7908300047	7908300024	79/06/29	50-522	Q
7908300051	7908300024	79/06/29	50-522	Q
7908300064	7908300060	79/06/29	50-267	Q
7908300069	7908300060	79/06/29	50-267	Q
7908300080	7908300074	79/08/01	50-302	Q
7908300087	7908300074	79/08/01	50-302	Q
7908300088	7908300074	79/08/01	50-302	Q
7908300091	7908300074	79/08/01	50-302	Q
7908300100	7908300074	79/08/01	50-302	Q
7908300108	7908300096	79/07/27	50-280	P
7908300119	7908300109	79/08/02	50-491	Q
7908300129	7908300109	79/08/02	50-491	Q
7908300136	7908300109	79/08/02	50-491	Q
7908300148	7908300096	79/07/27	50-280	P
7908300149	7908300109	79/08/02	50-491	Q
7908300164	7908300096	79/07/27	50-280	P
7908300206	7908300195	79/08/06	50-346	M
7908300215	7908300154	79/07/20	50-206	S
7908300226	7908300213	79/07/25	50-259	P
7908300230	7908300154	79/07/20	50-206	S
7908300231	7908300223	79/06/12	50-346	P
7908300239	7908300223	79/06/12	50-346	P
7908300244	7908300237	76/04/02	PRM	
7908300248	7908300224	79/06/27	50-596	Q
7908300251	7908300237	76/04/02	PRM	
7908300257	7908300268	79/07/10	50-367	Q
7908300263	7908300253	79/07/23	50-312	H
7908300273	7908300253	79/07/23	50-312	H
7908300281	7908300264	79/07/13	50-568	Q
7908300316	7908300313	79/08/02	TOPREP	
7908300342	7908300337	79/07/31	XPORTLIC	
7908300366	7908300358	79/06/25	WASTE MGT	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908300369	7908300353	79/06/29	50-387	Q
7908300403	7908300393	79/06/28	50-322	Q
7908300433	7908300421	79/08/16	50-18	P
7908300443	7908300436	79/08/06	XPORTLIC	
7908300452	7908300445	79/07/05	GEN TEC IS	
7908300466	7908300459	79/08/14	50-10	R
7908300480	7908300470	79/08/01	50-491	Q
7908300487	7908300470	79/08/01	50-491	Q
7908300503	7908300494	79/08/27	50-367	A
7908300514	7908300494	79/08/27	50-367	A
7908300534	7908300524	79/08/06	50-269	Q
7908300539	7908300529	79/08/24	50-267	S
7908300543	7908300533	79/06/23	50-599	Q
7908300544	7908300524	79/08/06	50-269	Q
7908300557	7908300546	79/08/23	50-272	S
7908300563	7908300554	79/08/06	70-143	
7908300568	7908300554	79/08/06	70-143	
7908300571	7908300569	79/08/23	50-313	S
7908300578	7908300575	79/07/31	50-400	Q
7908300583	7908300575	79/07/31	50-400	Q
7908300603	7908300600	79/07/30	RES	
7908300608	7908300605	79/08/08	40-7580	
7908300615	7908300611	79/08/03	CONTRACT	
7908300616	7908300612	79/07/05	50-309	Q
7908300621	7908300620	79/08/06	50-219	P
7908300629	7908300620	79/08/06	50-219	P
7908300634	7908300620	79/08/06	50-219	P
7908300636	7908300628	79/08/23	50-272	S
7908300649	7908300646	79/08/15	50-333	R
7908300663	7908300655	79/08/23	50-261	S
7908300672	7908300666	79/08/22	TOPREP	
7908300681	7908300675	79/08/06	50-250	S
7908300700	7908300689	79/08/23	50-324	S
7908300707	7908300682	79/08/16	50-327	S
7908300711	7908300708	79/08/17	50-335	S
7908300718	7908300713	79/08/28	50-133	P
7908300722	7908300713	79/08/28	50-133	P
7908300725	7908300713	79/08/28	50-133	P
7908300737	7908300733	79/08/24	TOPREP	
7908300761	7908300758	79/06/29	50-344	Q
7908300771	7908300769	79/07/30	COMMISSION	
7908300774	7908300773	79/08/30	COMMISSION	
7908300779	7908300773	79/07/30	COMMISSION	
7908310065	7908080689	79/06/01	72-39	
7908310081	7908319068	79/06/12	40-8674	

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908310116	7908310115	79/07/11	50-445	Q
7908310135	7908310130	79/08/07	CONTRACT	
7908310254	7908310249	79/08/07	XPORTLIC	
7908310291	7908310422	79/08/13	XPORTLIC	
7908310300	7908310296	79/07/25	PR	
7908310309	7908310303	79/08/27	50-302	S
7908310316	7908310313	79/08/23	50-366	S
7908310322	7908310319	79/08/24	50-366	S
7908310325	7908310320	79/08/17	50-267	S
7908310327	7908310324	79/08/24	50-321	S
7908310331	7908310328	79/08/10	50-267	S
7908310338	7908310335	79/08/13	50-315	R
7908310343	7908310340	79/08/21	50-219	P
7908310353	7908310347	79/08/10	50-267	S
7908310364	7908310357	79/08/03	50-298	S
7908310377	7908310370	79/08/24	50-321	S
7908310393	7908310386	79/08/01	50-313	S
7908310406	7908310401	79/08/24	50-321	S
7908310412	7908310408	79/08/24	50-335	P
7908310416	7908310414	79/08/27	50-220	P
7908310420	7908310415	79/08/02	50-298	S
7908310425	7908310423	79/08/22	50-346	S
7908310444	7908310436	79/08/01	50-298	S
7908310446	7908310441	79/08/13	TOPREP	
7908310459	7908310449	79/08/27	50-325	S
7908310464	7908310458	79/08/28	50-267	P
7908310481	7908310466	79/08/27	50-302	S
7908310498	7908310487	79/08/27	50-331	S
7908310508	7908310504	79/08/23	50-596	C
7908310512	7908310507	79/08/15	50-186	P
7908310516	7908310507	79/08/15	50-186	P
7908310522	7908310518	79/08/29	50-302	R
7908310525	7908310520	79/07/31	XPORTLIC	
7908310530	7908310526	79/08/24	50-305	R
7908310536	7908310533	79/08/17	50-193	F
7908310540	7908310109	79/06/06	40-8727	
7908310549	7908310544	79/08/29	50-263	R
7908310551	7908300109	79/06/06	40-8727	
7908310568	7908310564	79/06/24	50-286	P

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. Application/Construction Stage Documents and Correspondence

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Correspondence and documents relating to unresolved design and construction issues.
2. Meeting announcements and summaries of meeting discussions on issues of item 1.
3. Correspondence regarding Preliminary and Final Safety Analysis Reports.
4. NRC questions, requests for additional information, and applicant responses.
5. Applicant's Quality Assurance Manual.
6. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
7. Federal Register notices that do not apply to other categories.
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Scheduling of license application submission or review.
10. Reports of site visits.
11. Backup technical documents (i.e., topical reports) submitted in support of the application.
12. Early site review information.
13. Construction Permit, amendments and correspondence relating to construction permit.
14. Environmental review information.
15. Construction permit.

B. Utility Preliminary Safety Analysis Report (PSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt.
5. Hazards Summary Report submitted by utility (now designated PSAR).

6. Safety Analysis Report submitted by utility (now designated PSAR).

7. Certificates of Service of PSAR.

C. Utility Environmental Report (ER), Amendments and Correspondence

1. Environmental Report (ER) submitted by the utility.

2. Amendments and supplements to the ER.

3. Transmittal letters.

4. Information on scheduling of submittal or review of ER.

5. NRC questions, requests for additional information, and applicant responses.

6. Federal Register notice citing availability of items 1 and 2.

7. Correspondence relating to the review of ER.

8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), Supplements and Correspondence

1. Draft and Final Environmental (Impact) Statements (DES and FES).

2. Supplements to DES and FES.

3. Correspondence relating to the DES or FES.

4. Comments from other federal, state, and local government agencies.

5. Transmittal letters.

6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.

7. Backup technical documents submitted in connection with above.

8. Notices of availability of above.

9. Draft of detailed statement.

E. NRC Safety Evaluation Report (SER), Supplements and Correspondence

1. Safety Evaluation Report (SER).

2. Supplements to SER.

3. Correspondence relating to SER.

4. Notices advising of the availability of 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the safety review or safety evaluation.
8. Transmittal letters.
9. Comments from other agencies relative to safety review.
10. NRC-AEC Hazard Analysis Reports (now designated SER).

F. Security, Medical, Emergency, and Fire-Protection Plans

All plans in this category are submitted separately. Information submitted for the PSAR or FSAR is excluded.

1. Correspondence relating to plans.
2. Supplements, changes, and revisions to plans.
3. Fire Hazard Protection Plan and Surveys.

G. Adjudicatory Correspondence

This category contains all documents on hearings, Atomic Safety and Licensing Board (ASLB) review, and opposition except word-for-word transcripts of ASLB hearings (Category T) and anti-trust hearings (Category N).

1. ASLB hearing and review documents.
2. Correspondence to and from intervenors.
3. Correspondence to and from persons writing in opposition to the facility. Those writing for information or in support of the facility are in category H.
4. Board orders and decisions.
5. Requests to make appearances at hearings.
6. Transmittal of supporting documents (i.e., SER, FES) to the board.
7. Federal Register notices regarding hearings.
8. Requests for a hearing.
9. Petitions from participants (including petition for request for extension).
10. Corrections to transcripts.
11. Professional qualifications, if presented at a hearing.

12. Memorandums and orders authorizing issuance of license, changes, and other issuances by the Atomic Safety and Licensing Board.

13. Hearing index.

H. General correspondence

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Qualification statements of new employees.

2. Change of address notifications.

3. Changes in organization.

4. Changes in service lists, "Certificate of Service" documents (without a document attached).

5. NRC requests to applicant for additional copies of documents.

6. Correspondence from the public in support of or requesting information about the facility.

7. Letters of "concern" (NOT "opposition") and response thereto.

8. Correspondence on strictly administrative matters.

9. Correspondence regarding the local Public Document Room.

10. Memoranda to Public Document Room regarding withholding a document (unaccompanied by that document).

11. Press releases from applicant.

12. Any other material that fits the criteria given above.

13. Professional qualifications (resumes).

I. Financial Information

1. Company annual reports.

2. Separately submitted financial information and related correspondence.

J. Insurance and Idemnity Information

1. All correspondence and documentation regarding indemnity and insurance.

2. Endorsements to insurance policies.

3. NELPIA – Nuclear Energy Liability Property Insurance information.

K. Utility Final Safety Analysis Report (FSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR).
2. Amendments and changes to the FSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of items.
5. Hazards Final Summary Report (now designated FSAR).
6. Certificates of Service of FSAR.

L. Limited Work Authorization and Related Correspondence

This category is limited to items issued before the construction permit is granted.

1. Limited Work Authorizations.
2. Environmental exemptions.
3. Correspondence relating to 1 and 2.
4. All information concerning site preparation prior to the issuance of a construction permit.

M. Antitrust Correspondence

1. All material concerning antitrust except hearing transcripts (category N)
2. All material marked with an A immediately following the docket number. The A signifies antitrust proceedings.

N. Antitrust Hearing Transcripts

This category contains only word-for-word transcripts of hearings in antitrust matters. In most cases they will be marked with an A following the docket number. Related correspondence falls in category M.

O. Advisory Committee on Reactor Safeguards (ACRS) Reports and Correspondence

1. Correspondence and letter reports relating to ACRS reviews
2. Correspondence from ACRS
3. Announcements of ACRS meetings

4. Transmittal letters to ACRS

5. ACRS reports.

P. Operating License Stage Documents and Correspondence

This file assumes the position of the application file for general technical items dated on or after the issuance of the operating license. It includes:

1. Operating license, amendments, proposed amendments, and changes.
2. Technical specifications and changes.
3. Announcements of issuance of 1 and 2.
4. Transmittal letters.
5. All general technical correspondence relating to technical specifications or operating license.
6. License conditions.
7. Operator licenses or administrative information bearing on the licensing of operators.
8. Meeting announcements or summaries of discussions where the main subject is technical specifications, operating license, or any technical issue arising after the issuance of the operating license.
9. Correspondence regarding codes (ASME), regulations, laws, or changes in policy that may affect plant operation or bear on the operating license.
10. Information on the Standard Review Plan (SRP).
11. Results of surveys or tests conducted in accordance with the technical specifications (NOT periodic reports, which fall in category R).
12. Requests for issuance of operating license.
13. Requests for copies of items 1 and 2 and responses.
14. Correspondence on generic technical issues.
15. Owner's group meeting announcements and reports.
16. Orders for modification of license.
17. Requests for extension date of license or license modification.
18. Quality assurance information.
19. Environmental matters (technical).
20. Emergency core cooling system.
21. Radioactive waste information.

Q. Inspection Reports, IE Bulletins and Correspondence

1. Inspection reports.
2. Bulletins and Circulars of NRC Office of Inspection and Enforcement (IE).
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Any correspondence relating to inspection and enforcement that does not specifically relate to incidents as defined in category S.
7. In-service inspections.
8. Regulatory Operations (RO) Bulletins.

R. Periodic Operating Reports and Related Correspondence

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual reports (other than financial).
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Gray Book Information.
4. Operational Logbooks:

   Logbooks on Environmental Data
   Logbooks of Radiological Data
   Operations Log on Plant Systems Core
   Plant Status Summary Sheets

5. Correspondence or other documents relating to the above listed items.

S. Reportable Occurrences, LERs and Related Correspondence

This category contains all materials relating to abnormal, unusual, reportable, nonroutine, or 10 CFR 50.55e occurrences. This includes:

1. All 24-hour, 10-day, 30-day, interim, final, and followup reports on these events.
2. Other related documents.

NOTE: Also called licensee event reports, incident reports, etc.

T. Hearing Transcripts on Non-Antitrust Matters

This category contains word-for-word transcripts, corrections to the transcript, attachments and Vu-Graphs. Examples of non-antitrust matters include:

1. ASLB hearings.
2. Commission Meetings.
3. Commission Briefings.
4. Telephone conversations.

U. Congressional/Executive Correspondence

1. Testimony before Congress.
2. Preparatory and backup documents for Congressional testimony.
3. Letters to and from Congress and the Executive Branch.
4. Responses to letters from members of Congress and the Executive Branch.
5. Correspondence to and from the NRC Office of Congressional Affairs.

V. Operator Examinations

1. NRC Examination Results.
2. Power Plant Examination Summary Sheet.
3. Related correspondence.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

AGREEMENT – State Agreements and Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:

   a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.

   b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.

2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.

3. State Legislative Reports.

4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.

3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).

2. Solicitations (RFP or IFB) issued by the NRC.

3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.

4. Contractual documents and contract modifications, if any.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year–numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.

2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.

3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.

2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

3. Meeting notifications and minutes.

4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.

2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.

3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.

4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:

a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.

b. They present the results of Commission licensing and policy decisions.

c. They present the results of technical research conducted for the Commission.

2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.

3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG – Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.

2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.

3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.

4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.

2. Text of the Proposed Rule (PR).

3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.

4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.
3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling

criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
   a. model documentation reports
   b. code documentation reports
   c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.

7. Letter reports of foreign travel and site visits by contractors.

8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.

9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.

10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.

2. Summary minutes of review group meetings representing views expressed, including dissenting views.

3. Research plans and predicted results of major experiments; presentations by research contractors.

4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.

5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.

2. Notifications of hearing board meetings.

3. Petitions, motions, testimony and statements submitted by parties to the hearings.

4. Hearing board orders and rulings.

5. Technical reports submitted as evidence in the proceeding.

6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.

2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.

2. Revisions, modifications and amendments to topical reports.

3. Correspondence between NRC and vendors pertaining to the review of submittals.

4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.

2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.

4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 (7-77) U.S. NUCLEAR REGULATORY COMMISSION

BIBLIOGRAPHIC DATA SHEET

1. REPORT NUMBER (Assigned by DDC): NUREG-0540 Vol.1 No.8

4. TITLE AND SUBTITLE (Add Volume No., if appropriate): Title List of Documents Made Publicly Available

2. (Leave blank)

3. RECIPIENT'S ACCESSION NO.

7. AUTHOR(S)

5. DATE REPORT COMPLETED: MONTH October, YEAR 1979

9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

DATE REPORT ISSUED: MONTH October, YEAR 1979

6. (Leave blank)

8. (Leave blank)

12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

same as #9

10. PROJECT/TASK/WORK UNIT NO.

11. CONTRACT NO.

13. TYPE OF REPORT: Monthly

PERIOD COVERED (Inclusive dates): August 1-31, 1979

15. SUPPLEMENTARY NOTES

14. (Leave blank)

16. ABSTRACT (200 words or less)

This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through U.S. DOE's Technical Information Center under the title Power Reactor Docket Information (PRDI). This document replaces PRDI, which will no longer be prepared. It is indexed by a Personal Author Index, Corporate Source Index , and Report Number Index.

17. KEY WORDS AND DOCUMENT ANALYSIS

17a. DESCRIPTORS

17b. IDENTIFIERS/OPEN-ENDED TERMS

18. AVAILABILITY STATEMENT: Unlimited

19. SECURITY CLASS (This report): Unclassified

21. NO. OF PAGES

20. SECURITY CLASS (This page): Unclassified

22. PRICE: $

NRC FORM 335 (7-77)

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE, $300

POSTAGE AND FEES PAID
U.S. NUCLEAR REGULATORY
COMMISSION

U.S. MAIL

120555031837 2 ANA5
US NRC
SECY PUBLIC DOCUMENT ROOM
BRANCH CHIEF
HST LOBBY
WASHINGTON DC 20555