All of the individuals in the control room at the time of the accident had served in the U. S. Navy on nuclear ships after successfully completing the appropriate nuclear training programs.

The service dates indicate 8 years, 5 years and 4 years of nuclear navy experience.

All have been employed by Metropolitan Edison Company since 1973.

In preparation for their NRC examinations, the individuals received between 8-9 weeks simulator training as part of a comprehensive training program.

We believe the individuals exceeded the minimum experience and training requirements to sit for examinations and that they demonstrated their competence during the examinations prior to our issuing their licenses.

8002190588