NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: - (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | PATMI2 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T
01 | REPORT SOURCE L (6) | 05000320 (7) | 012980 (8) | 022880 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During modes operation, Emergency Diesel Generator DF-X-1B failed on a manual
03 start signal (failed to reach 250 rpm or 10 psig oil pressure within 7 seconds).
04 Continued core cooling was unaffected; since offsite power was available, both
05 BOP diesels and DF-X-1A were operable and the 13-2 kV line was available.
06
07
08

09 | SYSTEM CODE EE (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE ENGINE (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 002 | / | OCCURRENCE CODE 99 | REPORT TYPE X | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER F010 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The speed switch/tachometer drive assembly was disassembled, and the driven
11 pinion (a Fairbanks & Morse part) was found sheared. The shaft sheared due to
12 binding caused by the coupling not vibrating loose. The driven pinion was
13 replaced and the coupling nut will be staked to prevent recurrence.
14

15 | FACILITY STATUS G (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Start Failure Alarm Activated

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

8003110679

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER S. D. Chaplin PHONE: (717) 948-8461

POOR ORIGINAL