LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1–6)

(PLEASE PRINT ALL REQUIRED INFORMATION)

	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01	CARSS1	00-00000-00	4111 1	01
(7–8, 9–14)		(15–25)	(26–30)	(31–32)

	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01 CON'T	DI	T	L	050-0312	111877	120677
(7–8)	(57–58)	(59)	(60)	(61–68)	(69–74)	(75–80)

EVENT DESCRIPTION

02 On November 18, during a return to power following a 2-hour shutdown, the reactor was
03 operated in the restricted region of Tech Spec Figure 3.5.2-1 for 8-1/4 hours and in
04 the restricted region of Figure 3.5.2-5 for 5-1/2 hours. Operation in the restricted
05 regions is permitted only for a 2-hour period. (RO-77-18)
06

	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07	RC	A	ZZZZZZ	Z	Z999	Y
(7–8, 9–10)		(11)	(12–17)	(43)	(44–47)	(48)

CAUSE DESCRIPTION

08 Operators felt that required action (reduce power) would have aggravated the situation,
09 eventually resulting in a trip. The Plant Superintendent issued a directive stating
10 that Tech Specs must be followed, even if a shutdown results.

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	C	090	NA	A	NA
(7–8, 9)		(10–12)	(13–44)	(45)	(46–80)

	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z	Z	NA	NA
(7–8, 9)		(10)	(11–44)	(45–80)

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION
13	000	Z	NA
(7–8, 9–11)		(12)	(13–80)

PERSONNEL INJURIES

	NUMBER	DESCRIPTION
14	000	NA
(7–8, 9–11)		(12–80)

OFFSITE CONSEQUENCES

15 Minimal to none.

LOSS OR DAMAGE TO FACILITY

	TYPE	DESCRIPTION
16	Z	NA
(7–8, 9)		(10–80)

PUBLICITY

17 Local newspapers and wire services notified November 29, 1977.

ADDITIONAL FACTORS

18 A training program detailing how to prevent the situation experienced and how to
19 correct the situation will be given to management and licensed personnel by 12/31/77.

NAME: R. W. Colombo/F. T. Eisenhuth PHONE: (916) 452-3211

GPO 881-667

8004070680