LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

P A B V S 1 (2) LICENSEE CODE | 0 0 - 0 0 0 0 0 - 0 0 (3) LICENSE NUMBER | 4 1 1 1 1 (4) LICENSE TYPE | CAT (5)

REPORT SOURCE L (6) | 0 5 0 0 0 3 3 4 (7) DOCKET NUMBER | 0 7 2 4 8 0 (8) EVENT DATE | 0 7 2 4 8 0 (9) REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

As a result of our investigation of IE Bulletin 79-14, as-built piping, it has been determined that a significant overstress condition would exist during a seismic event on the "B" low head safety injection pump recirculation (2" SI-37) line. Loss of this line could result in a partial loss of flow from the safety injection pump during accident conditions. The redundant system remains in service; therefore, no danger is posed to the health and safety of the public.

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
Z Z (11)	B (12)	A (13)	Z Z Z Z Z Z (14)	Z (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
8 0	—	0 5 1	/	0 1	T	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
Y (18)	Y (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	Z (25)	Z 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

No cause description is known at this time for the pipe hangers being under-sized. The necessary support modifications are being made at this time and will be completed prior to station startup as part of Design Change Package 305. If any of the above changes, a supplemental report will be submitted.

FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
X (28)	0 0 0 (29)	Design modification outage	D (31)	Notification from architect-engineer

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION (39)
0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

NUMBER	DESCRIPTION (41)
0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE	DESCRIPTION
Z (42)	N/A

PUBLICITY

ISSUED	DESCRIPTION (45)
N (44)	N/A

NRC USE ONLY

NAME OF PREPARER W. S. Lacey PHONE: 412-643-8525

8007300388