NRC FORM 366 (7 77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | CAHMBI (2) | 00-000000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 05000133 (7) | 071180 (8) | 081080 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | With the nuclear unit shutdown, a breaker supplying electrical power to one of four
03 | screen wash pumps in adjacent fossil units failed. The tips of two of nine stationary
04 | contacts had broken off, jamming the breaker operating mechanism, preventing the
05 | breaker from closing. These pumps are backup sources of cooling water to the Suppres-
06 | sion Pool Cooler. All four pumps have the same type breaker. This is reportable under
07 | T.S. IX.I.2.b.(2). There were no adverse effects from this event; alternate cooling
08 | sources were available even though not needed because of the length of shutdown (4 years).

09 | SYSTEM CODE EB (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE CKTBRK (14) | COMP. SUBCODE B (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 80 — SEQUENTIAL REPORT NO. 003 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION C (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER G080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Contacts are believed to have failed from shock of repeated cycling (breaker was over
11 | 22 years old). Breaker is G.E. type AK-1-15; contact part number 6372777G1. Contacts
12 | were burnished. Temporary corrective action was to remove the bottom 1/8" of the arc
13 | shutes where the contacts strike, per G.E. recommendation. Final action is to replace
14 | all such breakers with newer model prior to power operation.

15 | FACILITY STATUS G (28) | % POWER 000 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) N/A

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION N/A

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A

NRC USE ONLY

8008180480

NAME OF PREPARER B.C. Getty PHONE (707) 443-2787