LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	NYJAF1 (2)	00-0000-000 (3)	41111 (4)	(5)	
	LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT	

CON'T

01	REPORT SOURCE L (6)	05000333 (7)	081480 (8)	082780 (9)	
		DOCKET NUMBER	EVENT DATE	REPORT DATE	

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operations and while inerting primary containment, Standby Gas Treatment

03 Systems A and B were found inoperable when required by TS 3.7.B.

04 See attachment for additional details.

05

06

07

08

09

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
SH (11)	X (12)	Z (13)	ZZZZZZ (14)	Z (15)	Z (16)

(17) LER RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
80	—	065	/	03	T	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X (18)	X (19)	Z (20)	Z (21)	0000	Y (23)	N (24)	Z (25)	Z999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A blocked drain line allowed water to accumulate in the Standby Gas Treatment discharge

11 line until the fans were not capable of discharging through the line. Draining of

12 water, blowdown of drain line and surveillance restored the system to operable

13 status.

14 See attachment for additional details.

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
15	F (28)	013 (29)	NA	A (31)	Operator Observation

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
16	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
17	000 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
18	000 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
19	Z (42)	NA

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
20	N (44)	NA	

8009030414

NAME OF PREPARER W. Verne Childs PHONE 315-342-3840