LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Field	Value
01 Licensee Code (2)	W I L B R 1
License Number (3)	00-00000-00
License Type (4)	4 1 1 1 1
CAT (5)	
CON'T 01 Report Source (6)	L
Docket Number (7)	050-0409
Event Date (8)	080680
Report Date (9)	081880

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 DURING OPERATION, VALVE ADDITION TO SHUTDOWN CONDENSER SHELL GAGE TAP FO
03 UND WITHOUT DESIGN CHANGE, NO CHECK LIST IDENTIFIED VALVE. POTENTIAL EX
04 ISTED FOR INCORRECT VALVE STATUS AND SUBSEQUENT REDUCED CONTAINMENT INTE
05 GRITY. SUCCESSFUL CLASS A LEAK RATE TESTS ACHIEVED WHILE VALVE INSTALLE
06 D.
07
08

09	System Code (11)	Cause Code (12)	Cause Subcode (13)	Component Code (14)	Comp. Subcode (15)	Valve Subcode (16)
	CE	A	D	VALVEX	F	D

(17) LER/RO REPORT NUMBER

Event Year		Sequential Report No.		Occurrence Code	Report Type		Revision No.
80	—	005	/	01	T	—	0

Action Taken (18)	Future Action (19)	Effect on Plant (20)	Shutdown Method (21)	Hours (22)	Attachment Submitted (23)	NPRD-4 Form Sub. (24)	Prime Comp. Supplier (25)	Component Manufacturer (26)
F	Z	Z	Z	0000	Y	N	L	C665

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 PERSONNEL ERROR. SYSTEM MODIFICATION WITHOUT DESIGN CHANGE APPROVAL.
11 VALVE REMOVED, PIPE CAP INSTALLED AND TESTED WITH ACCEPTABLE RESULTS.
12
13
14

15	Facility Status (28)	% Power (29)	Other Status (30)	Method of Discovery (31)	Discovery Description (32)
	E	085	NA	D	NRC RESIDENT INSPECTOR OBSERVATION

16	Activity Released (33)	Content of Release (34)	Amount of Activity (35)	Location of Release (36)
	Z	Z	NA	NA

17 PERSONNEL EXPOSURES — Number (37): 000 Type (38): Z Description (39): NA

18 PERSONNEL INJURIES — Number (40): 000 Description (41): NA

19 LOSS OF OR DAMAGE TO FACILITY — Type (42): Z Description (43): NA

20 PUBLICITY — Issued (44): N Description (45): NA

8009030457

NRC USE ONLY

NAME OF PREPARER L. S. GOODMAN PHONE 608-689-2331

GPO 917-926