NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N E C P R 1 (2) | 0 0 - 0 0 0 0 - 0 0 0 (3) | 4 1 1 1 1 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 2 9 8 (7) | 0 7 2 5 8 0 (8) | 0 8 2 2 8 0 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During performance of surveillance procedure 6.2.2.2.1, ADS Water Level Functional/
03 Calibration Test, a HPCI isolation occurred at about the same time as NRI-LIS-83A
04 was returned to service. The isolation was immediately reset and HPCI was operable.
05 All remaining ECCS Systems were operable. This event had no effect on public health
06 and safety.
07
08
7 8 9 80

09 | SYSTEM CODE S F (11) | CAUSE CODE X (12) | CAUSE SUBCODE C (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE S (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 8 0 | — | SEQUENTIAL REPORT NO. 0 3 2 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN H (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER Y 0 1 0 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the occurrence may have been caused by a transient in the common sens-
11 ing line introduced by opening the isolation valve prior to the pressurizing valve
12 or by opening the pressurizing valve to quickly. A definite cause for this occur-
13 rence could not be determined.
14
7 8 9 80

15 | FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 9 11 12 13 80

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA
7 8 9 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA
7 8 9 10 80

20 | PUBLICITY ISSUED Z (44) | DESCRIPTION (45) NA | NRC USE ONLY
7 8 9 10 68 69 80

POOR ORIGINAL

NAME OF PREPARER L. I. Lawrence PHONE: 402-825-3811

8009050203