NRC FORM 366 (7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | MAYKR1 (2) | 00-0000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) LICENSE NUMBER (15–25) LICENSE TYPE (26–30) CAT (57–58)

CON'T 01 REPORT SOURCE | L (6) | 05000292 (7) | 073180 (8) | 082980 (9)
DOCKET NUMBER (60–68) EVENT DATE (69–74) REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During shutdown conditions, while performing fire protection system modi
03 fications, the cable tray house sprinkler system was taken out of servic
04 e for eight hours. This system is required to be operable by T.S.3.7.10.
05 2.a. This is the first occurrence of this nature. Other fire systems are
06 to be modified in the near future. A manual hose line and continuous fi
07 re watch were provided at the scene throughout the modification, therefo
08 re, no adverse effects upon the public health or safety existed.

09 SYSTEM CODE: AB (11) | CAUSE CODE: X (12) | CAUSE SUBCODE: Z (13) | COMPONENT CODE: PIPEXX (14) | COMP. SUBCODE: A (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 016 | / | OCCURRENCE CODE 99 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN: F (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0000 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: L (25) | COMPONENT MANUFACTURER: X999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The root cause was removal of the system from service for modification t
11 o improve the system as determined by the Yankee Atomic Electric Co. Fir
12 e Hazard Survey and the USNRC SER. The system was installed by Automatic
13 Sprinkler Corp. The system was changed, tested and returned to service.
14 Further planned outages will be reported in a final supplemental report.

15 FACILITY STATUS: G (28) | % POWER: 000 (29) | OTHER STATUS (30): N/A | METHOD OF DISCOVERY: A (31) | DISCOVERY DESCRIPTION (32): System Modification

16 ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): N/A | LOCATION OF RELEASE (36): N/A

17 PERSONNEL EXPOSURES NUMBER: 000 (37) | TYPE: Z (38) | DESCRIPTION (39): N/A

18 PERSONNEL INJURIES NUMBER: 000 (40) | DESCRIPTION (41): N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) | DESCRIPTION (43): N/A

20 PUBLICITY ISSUED: N (44) | DESCRIPTION (45): N/A

NRC USE ONLY

8009110334

NAME OF PREPARER: BRUCE L. DRAWBRIDGE PHONE: (413) 625-6140

GPO 917-926