1DC

Wisconsin Electric POWER COMPANY
231 W. MICHIGAN, P.O. BOX 2046, MILWAUKEE, WI 53201

August 29, 1980

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NOS. 50-266 AND 50-301
REPLY TO IE BULLETIN 80-19
POINT BEACH NUCLEAR PLANT UNITS 1 AND 2

Your letter of July 31, 1980 forwarded IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protection Systems of Operating Nuclear Power Plants Designed by Combustion Engineering". Revision 1 of IE Bulletin 80-19 was forwarded by your letter of August 15, 1980. Review of the Point Beach Nuclear Plant Reactor Protection System confirms that no C. P. Clare Model HG2X-1011 mercury-wetted relays are used.

Very truly yours,

C. W. Fay

C. W. Fay, Director
Nuclear Power Department

Copies to NRC Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C.

NRC Resident Inspector
Point Beach Nuclear Plant

8009180158

9

SEP 02 1980