(7-77)

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | CO F S V 1 (2) | 00 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 2 0 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 0 5 0 0 0 2 6 7 (7) | 0 8 1 6 8 0 (8) | 0 9 1 5 8 0 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On August 16, 1980, during a plant shutdown, a fitting on a hydraulic oil line for
03 PV-2244, reheat steam bypass valve, ruptured. The hydraulic oil sprayed on the hot
04 steam pipes produced thick and heavy smoke; the local fire department was called for
05 assistance. The leak resulted in the 91 system Loop 2 group 2 being isolated, the
06 secondary Loop 2 being shutdown and isolated, and a manual scram being inserted. No
07 affect on public health or safety. No related events.
08

09 SYSTEM CODE A D (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE P I P E X X (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 8 0 | — | SEQUENTIAL REPORT NO. 0 4 5 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT A (20) | SHUTDOWN METHOD B (21) | HOURS (22) 0 1 0 3 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G 0 6 3 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The fitting ruptured at the beginning of the threaded area due to normal usage and was
11 replaced. The valve group was isolated to prevent further oil loss, and the secon-
12 dary loop was shutdown as required per LCO 4.3.7. A firewatch was stationed in the
13 area and cleanup began as soon as area temperatures allowed.
14

15 FACILITY STATUS X (28) | % POWER 0 2 8 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Personnel Observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A

8009230 604

NRC USE ONLY

NAME OF PREPARER [signature] PHONE: (303) 785-2253

GPO 917-926