NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 CARSS1 (2) 0 0 - 0 0 0 0 - 0 0 (3) 4 1 1 1 1 (4) (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 REPORT SOURCE L (6) 0 5 0 0 0 3 1 2 (7) 0 8 2 3 8 0 (8) 0 9 2 2 8 0 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On August 23, 1980, while performing SP 206.03B, Diesel Generator "B"
03 Synchronization Surveillance Test, it was noted that the unit did not
04 achieve rated voltage. The unit reached 4100V. However, rated voltage
05 for the unit is 4160V.
06
07
08

09 SYSTEM CODE EE (11) CAUSE CODE X (12) CAUSE SUBCODE X (13) COMPONENT CODE INSTRU (14) COMP. SUBCODE C (15) VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 80 — SEQUENTIAL REPORT NO. 041 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN E (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS (22) 0000 ATTACHMENT SUBMITTED Y (23) NPRD-4 FORM SUB Y (24) PRIME COMP. SUPPLIER A (25) COMPONENT MANUFACTURER B093 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the occurrence was attributed to the voltage regulator. A
11 work request was initiated and the voltage regulator was reset. The unit
12 was successfully retested on August 26, 1980. Since there have been no
13 similar occurrences in the past, further action concerning the regulator
14 is unwarranted.

15 FACILITY STATUS G (28) POWER 000 (29) OTHER STATUS (30) N/A — METHOD OF DISCOVERY B (31) — DISCOVERY DESCRIPTION (32) Routine Surveillance

16 ACTIVITY RELEASED Z (33) CONTENT OF RELEASE Z (34) AMOUNT OF ACTIVITY (35) N/A — LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES
17 NUMBER 000 (37) TYPE Z (38) DESCRIPTION (39) N/A

PERSONNEL INJURIES
18 NUMBER 000 (40) DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY
19 TYPE Z (42) DESCRIPTION N/A

PUBLICITY
20 ISSUED Y (44) DESCRIPTION (45) Local newspapers & wire service.

NRC USE ONLY

8010060306

NAME OF PREPARER R. W. Colombo PHONE 916-452-3211