NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | CAHMBI (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000133 (7) | 092680 (8) | 102680 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | With the nuclear plant shutdown, water was observed coming up through cracks in
03 | pavement 4' above a 10" line connecting screen wash pumps in 2 fossil units to
04 | screen wash pumps in the nuclear unit. These pumps provide shutdown heat
05 | removal for the reactor. This is reportable under T.S. IX.I.2.b.(2). There
06 | were no adverse effects; alternate cooling sources were available even though
07 | not needed due to the length of the current shutdown (4 yrs.). Reference
08 | LER-80-006/03L-0.

09 | SYSTEM CODE WB (11) | CAUSE CODE B (12) | CAUSE SUBCODE C (13) | COMPONENT CODE PIPEXX (14) | COMP. SUBCODE C (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 005 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION A (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER X999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Failure was due to improper installation. The 10" line crossed over a 39" line
11 | with less than 1" clearance filled in by concrete. Settling of the 10" line
12 | caused a circumferential crack. Temporary repairs are to use flexible hose
13 | clamp and hydrostatically test. The broken section of 10" line will be replaced
14 | prior to startup.

15 | FACILITY STATUS G (28) | % POWER 000 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) N/A

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION N/A (43)

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A

NRC USE ONLY

8010280471

NAME OF PREPARER P. W. Baum PHONE: 707/443-2787

GPO 617-928