(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: [1] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0 1] N Y J A F 1 [2] 0 0 - 0 0 0 0 - 0 0 0 [3] 4 1 1 1 1 [4] [5]
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T [0 1] REPORT SOURCE L [6] 0 5 0 0 0 3 3 3 [7] 0 8 0 5 8 0 [8] 0 1 1 2 8 0 [9]
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES [10]

[0 2] During normal shutdown, while conducting Instrument Surveillance Procedure F-ISP-8,
[0 3] Core Soray System pipe break detection switches 14-DPIS-43A and 43B were found set
[0 4] at 1.5 and 2.05 PSID respectively when required to be set at less than or equal to
[0 5] 0.5 PSID by TS Table 3.2-2. Instrument 14-DPIS-43B was also found set at 0.93 PSID
[0 6] on August 18, 1980 and at 0.5088 PSID on August 30, 1980.
[0 7]
[0 8]

[0 9] SYSTEM CODE: S F [11] | CAUSE CODE: E [12] | CAUSE SUBCODE: E [13] | COMPONENT CODE: I N S T R U [14] | COMP SUBCODE: S [15] | VALVE SUBCODE: Z [16]

[17] LER/RO REPORT NUMBER: EVENT YEAR 8 0 | — | SEQUENTIAL REPORT NO. 0 6 6 | / | OCCURRENCE CODE 0 3 | REPORT TYPE X | — | REVISION NO. 2

ACTION TAKEN: X [18] | FUTURE ACTION: F [19] | EFFECT ON PLANT: Z [20] | SHUTDOWN METHOD: Z [21] | HOURS [22]: 0 0 0 0 | ATTACHMENT SUBMITTED: N [23] | NPRD-4 FORM SUB.: Y [24] | PRIME COMP. SUPPLIER: N [25] | COMPONENT MANUFACTURER: B 0 8 0 [26]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS [27]

[1 0] Caused by instrument drift. In each case the instrument was calibrated and returned
[1 1] to service. Surveillance frequency was increased to once each week. New switches,
[1 2] on which the set point is near mid-range, were installed in December, 1980 as
[1 3] permanent corrective action. No additional action is required.
[1 4]

[1 5] FACILITY STATUS: G [28] | % POWER: 0 0 0 [29] | OTHER STATUS [30]: NA | METHOD OF DISCOVERY: B [31] | DISCOVERY DESCRIPTION [32]: Surveillance

[1 6] ACTIVITY RELEASED: Z [33] | CONTENT OF RELEASE: Z [34] | AMOUNT OF ACTIVITY [35]: NA | LOCATION OF RELEASE [36]: NA

[1 7] PERSONNEL EXPOSURES NUMBER: 0 0 0 [37] | TYPE: Z [38] | DESCRIPTION [39]: NA

[1 8] PERSONNEL INJURIES NUMBER: 0 0 0 [40] | DESCRIPTION [41]: NA

[1 9] LOSS OF OR DAMAGE TO FACILITY TYPE: Z [42] | DESCRIPTION: NA

[2 0] PUBLICITY ISSUED: N [44] | DESCRIPTION [45]: NA

NRC USE ONLY

8101100564

W. Verne Childs (315) 342-3840 X207