(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | TNSNP1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 05000327 (7) | 071980 (8) | 081980 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During low power testing in mode 2, hydrogen analyzer H2AN-43-200 was declared
03 inoperable due to low sample flow. This is contrary to LCO-3.6.4.1. Previous
04 Occurrences - 1, ref. LER NO. 80133. Probable consequences - None, as the other
05 hydrogen analyzer was operable. There was no effect upon public health or safety.
06
07
08

09 SYSTEM CODE SE (11) | CAUSE CODE B (12) | CAUSE SUBCODE B (13) | COMPONENT CODE MOTORX (14) | COMP SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 80 — SEQUENTIAL REPORT NO. 124 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION F (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP SUPPLIER N (25) | COMPONENT MANUFACTURER W120

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The sample pump motor thermal overload tripped due to the ambient temperature in the
11 annulus. The motor thermal overload heater was replaced. The replacement has a
12 higher temperature rating, and based on its performance evaluation the other hydrogen
13 analyzer (H2AN-43-2103) sample pump motor thermal overload heater may be changed.
14

15 FACILITY STATUS B (28) | % POWER 000 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

Name of Preparer Larry H. Coots Phone 615-842-8317

8008250638