NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | MAPPS1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 REPORT SOURCE | L (6) | 050-0293 (7) | 043081 (8) | 052881 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At approximately 0700 hours on April 30, 1981 while performing routine surveillance
03 testing on the RCIC system, RCIC outboard isolation valve MO 1301-17 failed to close
04 on demand following control switch actuation. The system was declared inoperable,
05 the NRC immediately notified and a maintenance request initiated. The valve was
06 repaired, tested and the system returned to service at approximately 1535 hours
07 the same day.
08

09 SYSTEM CODE CE (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE VALVOP (14) | COMP. SUBCODE F (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 81 (21 22) | — (23) | SEQUENTIAL REPORT NO. 016 (24 26) | / (27) | OCCURRENCE CODE 03 (28 29) | REPORT TYPE L (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN B (18) (33) | FUTURE ACTION Z (19) (34) | EFFECT ON PLANT Z (20) (35) | SHUTDOWN METHOD Z (21) (36) | HOURS 0000 (22) (37 40) | ATTACHMENT SUBMITTED N (23) (41) | NPRD-4 FORM SUB. N (24) (42) | PRIME COMP. SUPPLIER N (25) (43) | COMPONENT MANUFACTURER L200 (26) (44 47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Maintenance personnel upon investigation determined that the packing had deteriorated
11 and jammed between the valve's stem and the packing gland binding the valve's
12 drive mechanism . The packing was replaced and the valve returned to normal
13 operation.
14

15 FACILITY STATUS E (28) (9) | % POWER 100 (29) (10 12) | OTHER STATUS (30) N.A. (13 44) | METHOD OF DISCOVERY B (31) (45) | DISCOVERY DESCRIPTION (32) Routine Testing (46 80)

16 ACTIVITY RELEASED Z (33) (9) | CONTENT OF RELEASE Z (34) (10) | AMOUNT OF ACTIVITY (35) N.A. (11 44) | LOCATION OF RELEASE (36) N.A. (45 80)

17 PERSONNEL EXPOSURES NUMBER 000 (37) (9 11) | TYPE Z (38) (12) | DESCRIPTION (39) N.A. (13 80)

18 PERSONNEL INJURIES NUMBER 000 (40) (9 11) | DESCRIPTION (41) N.A. (12 80)

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) (9) | DESCRIPTION (43) N.A. (10 80)

20 PUBLICITY ISSUED N (44) (9) | DESCRIPTION (45) N.A. (10 68) | NRC USE ONLY (69 80)

8106080313

NAME OF PREPARER M. Thomas McLoughlin PHONE: 617-746-7900

GPO 917-924