NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M A P P S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 | REPORT SOURCE L (6) | 0 5 0 - 0 2 9 3 (7) | 0 4 0 3 8 1 (8) | 0 5 0 1 8 1 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On April 3, 1981 at approximately 1703 hours a reactor operator while performing
0 3 | routine keep fill checks on the low pressure ECCS systems inadvertently closed 4KV
0 4 | breaker A507 which feeds Core Spray Pump P215A. The operator immediately tripped
0 5 | the breaker. However, operating personnel could not recharge the breakers close mech-
0 6 | anism so they immediately issued a maintenance request and initiated required sur-
0 7 | veillance testing. The problem was resolved, surveillances terminated and the Core
0 8 | Spray System returned to normal by 2100 hrs. the same day.
7 8 9 80

0 9 | SYSTEM CODE S F (11) | CAUSE CODE A (12) | CAUSE SUBCODE A (13) | COMPONENT CODE Z Z Z Z Z Z (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER RO REPORT NUMBER | EVENT YEAR 8 1 | — | SEQUENTIAL REPORT NO. 0 1 2 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER Z 9 9 9 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The action taken by the operator approximated the automatic sequence which occurs
1 1 | during a "trip free" breaker operation. However, the close/trip sequence timing was
1 2 | different resulting in a charging motor cam incomplete cycle which required manual
1 3 | intervention to correct. This is an isolated event.
1 4 |
7 8 9 80

1 5 | FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) N.A. | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Routine Operational Check
7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N.A. | LOCATION OF RELEASE (36) N.A.
7 8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N.A.
7 8 9 11 12 13 80

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N.A.
7 8 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION N.A.
7 8 9 10 80

2 0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) N.A. | NRC USE ONLY
7 8 9 10 68 69 80

NAME OF PREPARER M. Thomas McLoughlin PHONE: 617-746-7900

8105110314