NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 LICENSEE CODE (2)	I L Z I S 1
LICENSE NUMBER (3)	0 0 - 0 0 0 0 0 - 0 0
LICENSE TYPE (4)	4 1 1 1 1
CAT (5)	
CON'T 01 REPORT SOURCE (6)	L
DOCKET NUMBER (7)	0 5 0 0 0 2 9 5
EVENT DATE (8)	1 1 2 0 8 0
REPORT DATE (9)	1 2 1 9 8 0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, the Unit 1 Class I Pipe Tunnel particulate and
03 Iodine Radiation Monitor (1RT-PR07A&B) failed and could not be reset.
04 The monitor was taken O.O.S. and shiftly grab samples were taken as re-
05 quired by T.S. 3.14.1.c. There were no safety implications and the
06 health and safety of the general public were not affected.
07
08

09 SYSTEM CODE (11)	B B
CAUSE CODE (12)	A
CAUSE SUBCODE (13)	X
COMPONENT CODE (14)	I N S T R U
COMP. SUBCODE (15)	C
VALVE SUBCODE (16)	Z
(17) LER/RO REPORT NUMBER — EVENT YEAR	8 0
	—
SEQUENTIAL REPORT NO.	0 5 2
	/
OCCURRENCE CODE	0 3
REPORT TYPE	L
	—
REVISION NO.	0
ACTION TAKEN (18)	E
FUTURE ACTION (19)	Z
EFFECT ON PLANT (20)	Z
SHUTDOWN METHOD (21)	Z
HOURS (22)	0 0 0 0
ATTACHMENT SUBMITTED (23)	N
NPRD-4 FORM SUB. (24)	N
PRIME COMP. SUPPLIER (25)	A
COMPONENT MANUFACTURER (26)	N 3 0 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The failure was due to high flow through the magnahelic. According to
11 the IM Dept., an unknown individual changed the setting on the magnahelic
12 (NMC P/N C000030) causing the high flow to occur. The magnahelic was re-
13 set, the monitor tested and returned to service. This is the first inci-
14 dence of this occurrence, and no further action is necessary.

15 FACILITY STATUS (28)	E
% POWER (29)	0 9 8
OTHER STATUS (30)	NA
METHOD OF DISCOVERY (31)	A
DISCOVERY DESCRIPTION (32)	Operator Observation
16 ACTIVITY RELEASED (33)	Z
CONTENT OF RELEASE (34)	Z
AMOUNT OF ACTIVITY (35)	NA
LOCATION OF RELEASE (36)	NA
17 PERSONNEL EXPOSURES NUMBER (37)	0 0 0
TYPE (38)	Z
DESCRIPTION (39)	NA
18 PERSONNEL INJURIES NUMBER (40)	0 0 0
DESCRIPTION (41)	NA
19 LOSS OF OR DAMAGE TO FACILITY TYPE (42)	Z
DESCRIPTION (43)	NA
20 PUBLICITY ISSUED (44)	N
DESCRIPTION (45)	NA
NRC USE ONLY	

NAME OF PREPARER Rock E. Aker PHONE: 312-746-2084 Ext 238

8106090515