LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: (1)

0 1 | I L Q A D 1 (2) | 0 0 0 - 0 0 0 - 0 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 2 5 4 (7) | 1 1 2 4 8 0 (8) | 1 2 1 1 8 0 (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing QIS-20, Main Steam Line Low Pressure Calibration Test, pressure

0 3 | switch PS-1-261-30D tripped at 843 psig. Technical Specification Table 3.2-1

0 4 | requires a setpoint of greater than or equal to 850 psig. The three redundant

0 5 | pressure switches were found to trip within the Technical Specification Limit.

0 6 | Thus, the one out of two taken twice logic system would have isolated the main

0 7 | steam system had the need arisen.

0 8 |

0 9 | SYSTEM CODE: C D (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: E (13) | COMPONENT CODE: I N S T R U (14) | COMP. SUBCODE: E (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 0 | — | SEQUENTIAL REPORT NO. 0 3 1 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN: E (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: Y (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER: B 0 6 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this occurrence is instrument setpoint drift. Pressure switch PS-1-

1 1 | 261-30D was recalibrated to 870 psig and was tested satisfactorily. Pressure

1 2 | switch 1-261-30D is model number B2T-A12SS manufactured by Barksdale.

1 3 |

1 4 |

1 5 | FACILITY STATUS: H (28) | % POWER: 0 0 0 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Routine Surveillance

1 6 | ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 (40) | DESCRIPTION (41): NA

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) | DESCRIPTION: NA

2 0 | PUBLICITY ISSUED: N (43) | DESCRIPTION (45): NA | NRC USE ONLY

8106090546

Curt Steffes

PHONE 309-654-2241, ext. 175