NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C T M N S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 2 4 5 (7) | 0 4 1 7 8 1 (8) | (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On April 17, 1981, at 0430 hours while performing routine surveillance,

0 3 | Reactor Building Exhaust Duct and Refuel Floor High Radiation Monitor Functional

0 4 | Test, one of the two ventilation duct radiation monitors was found to trip

0 5 | outside its allowable setpoint range (T.S.3.2.E.3). There were no consquences.

0 6 | See attachment.

0 7 |

0 8 | 80

7 8 9

0 9 | SYSTEM CODE M C (11) | CAUSE CODE E (12) | CAUSE SUBCODE G (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE E (15) | VALVE SUBCODE Z (16)

9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 1 (21 22) | — (23) | SEQUENTIAL REPORT NO. 0 0 6 (24 26) | / (27) | OCCURRENCE CODE 0 3 (28 29) | REPORT TYPE L (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 (37 40) | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G 0 8 0 (26)

33 34 35 36 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Failure of the radiation monitor in question to trip at its desired setpoint was

1 1 | attributed to setpoint drift due to failure of the sensor converter. The sensor

1 2 | converter was replaced and calibrated and the radiation monitor was satisfactorily

1 3 | tested.

1 4 | 80

7 8 9

1 5 | FACILITY STATUS H (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY (31) | DISCOVERY DESCRIPTION (32) Routine surveillance

9 10 12 13 44 45 46 80

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

9 10 11 44 45 80

PERSONNEL EXPOSURES

1 7 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

9 11 12 13 80

PERSONNEL INJURIES

1 8 | NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

9 11 12 80

LOSS OF OR DAMAGE TO FACILITY

1 9 | TYPE Z (42) | DESCRIPTION NA

9 10 80

PUBLICITY

2 0 | ISSUED N (44) | DESCRIPTION (45) NA

9 10 68 69 80

NRC USE ONLY

8105120336

POOR ORIGINAL

M. J. Bigiarelli

PHONE: (203)447-1791