(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C A H M B I (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 0 5 0 0 0 1 3 3 (7) | 0 6 1 9 8 1 (8) | 0 7 1 9 8 1 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With the nuclear plant shutdown, the stem of #6 screen wash pump's discharge valve
03 to the screen wash header separated from its valve seat. This is reportable under
04 T.S. IX.I.2.b.(2). The #6 pump is one of six pumps that provide shutdown heat
05 removal for the reactor. There were no adverse effects; alternate sources were
06 available even though not needed due to the length of the current shutdown (almost
07 5 years). Reference LER 80-005-03L-0, 80-006-03L-0, and 81-001-03L-0.
08

09 SYSTEM CODE W B (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE V A L V E X (14) | COMP. SUBCODE E (15) | VALVE SUBCODE D (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 1 | — | SEQUENTIAL REPORT NO. 0 0 2 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION A (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER W 0 3 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The stem had detached from the valve seat. Investigation revealed the yolk of the
11 valve seat had corroded away. The valve had been in service for 19 years. A temp-
12 orary repair has been made to the valve by machining a new yolk and attaching it to
13 the seat. The valve will be replaced prior to returning the unit to power operation
14

FACILITY STATUS G (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

8107270038 810720
PDR ADOCK 05000133
S PDR

.Getty PHONE: (707) 443-2787

GPO 917-928