NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS2 (2) | 00-000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000311 (7) | 060381 (8) | 082681 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On June 3 and again on June 27 an inadvertent safety injection occurred following a
03 turbine/reactor trip. Both SIs were initiated by high steam flow conditions coinci-
04 dence with low reactor coolant average temperature. In both cases procedures were
05 followed and the SIs were determined to be inadvertent and were terminated with no
06 detrimental effects on the unit.
07
08

09 SYSTEM CODE CH (11) | CAUSE CODE D (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE MECFUN (14) | COMP SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 81 | — | SEQUENTIAL REPORT NO 082 | / | OCCURRENCE CODE 99 | REPORT TYPE X | — | REVISION NO 0

ACTION TAKEN G (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT A (20) | SHUTDOWN METHOD C (21) | HOURS 0023 (22) | ATTACHMENT SUBMITTED (23) | NPRD-4 FORM SUB N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER W290 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The inadvertent SIs were caused by high steam line flow conditions set up by the
11 No. 23 steam driven auxiliary feedwater pump speed oscillations due to improper
12 governor venting. Procedures have been revised to ensure the governor is vented
13 properly.
14

15 FACILITY STATUS B (28) | % POWER 020 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) NA

8109080183 810826
PDR ADOCK 05000311
S PDR

NRC USE ONLY

NAME OF PREPARER R. MacWatters PHONE 609-935-5100