Appendix A

NOTICE OF VIOLATION

Mercer County Hospital License No. 34-18954-01

As a result of the inspection conducted on August 18, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

Condition No. 15 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in application dated May 5, 1980.

The license application dated May 5, 1980, states that daily GM surveys shall be performed of all elution, preparation and injection areas.

Contrary to this requirement, daily GM surveys of the injection areas were not performed since the date of license issuance.

This is a Severity Level V violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation. Consideration may be given to extending your response time for good cause shown.

Dated 9/3/81

for S. L. Sasuk
D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

8109150389 810908
NMS LIC30
34-18954-01 PDR