LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	M	I	D	D	C	1	(2)	0	0	0	0	0	0	0	0	0	0	0	(3)	4	1	1	1	1	(4)			(5)
7 8	9 LICENSEE CODE 14						15 LICENSE NUMBER 25												26 LICENSE TYPE 30						57 CAT 58			

CON'T

0 1	REPORT SOURCE	L	(6)	0	5	0	0	0	3	1	5	(7)	0	7	2	1	8	1	(8)	0	9	1	8	8	1	(9)						
7 8	60		61 DOCKET NUMBER 68									69 EVENT DATE 74							75 REPORT DATE 80													

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING ROUTINE TOUR, A SUPPLY BREAKER FOR HEAT TRACE CIRCUITS WAS FOUND TRIPPED. THIS

0 3 BREAKER SUPPLIES POWER TO TRAIN "B" HEAT TRACE CIRCUITS FOR THE BORON INJECTION TANK.

0 4 ON TWO OTHER OCCASSIONS, THIS BREAKER HAS BEEN FOUND TRIPPED. THESE CONDITIONS ARE

0 5 NON-CONSERVATIVE WITH REGARDS TO T.S. 3.5.4.2. THE FIRST EVENT ON 7-21-81 WAS NOT

0 6 DETERMINED REPORTABLE UNTIL 9-17-81.

0 7

0 8 7 8 9 80

0 9	SYSTEM CODE						(11)	CAUSE CODE			(12)	CAUSE SUBCODE			(13)	COMPONENT CODE						(14)	COMP. SUBCODE			(15)	VALVE SUBCODE			(16)		
8	9		10					11				12				13						18	19				20					

(17)	LER/RO REPORT NUMBER	EVENT YEAR								SEQUENTIAL REPORT NO.						OCCURRENCE CODE				REPORT TYPE				REVISION NO.								
		8	1		—			0	3	9		/				0	3			L			—		0							
		21		22	23			24			26	27				28			29	30			31	32								

ACTION TAKEN		FUTURE ACTION			EFFECT ON PLANT			SHUTDOWN METHOD			HOURS (22)				ATTACHMENT SUBMITTED			NPRD-4 FORM SUB.			PRIME COMP. SUPPLIER			COMPONENT MANUFACTURER							
X	(18)	X	(19)		Z	(20)		Z	(21)		0	0	0	0	N	(23)		N	(24)		Z	(25)		Z	9	9	9	(26)			
33		34			35			36			37			40	41			42			43			44			47					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 INVESTIGATION HAS BEEN UNABLE TO DETERMINE THE CAUSE OF THE BREAKER TRIPPING. CON-

1 1 TINUED MONITORING OF THE PANEL TO INSURE THE PANEL IS OPERABLE WILL ENDURE UNTIL THE

1 2 CAUSE CAN BE DETERMINED. UPDATED LER WILL FOLLOW WHEN CAUSE IS DETERMINED.

1 3

1 4 7 8 9 80

1 5	FACILITY STATUS						(28)	% POWER				(29)	OTHER STATUS (30)						METHOD OF DISCOVERY			(31)	DISCOVERY DESCRIPTION (32)									
	H							0	0	0			NA						B				OPERATOR OBSERVATION									
7 8	9							10			12	13					44	45				46										80

1 6	ACTIVITY RELEASED						(33)	CONTENT OF RELEASE				(34)	AMOUNT OF ACTIVITY (35)												LOCATION OF RELEASE (36)						
	Z							Z					NA												NA							
7 8	9							10				11					44	45														80

1 7	PERSONNEL EXPOSURES NUMBER						(37)	TYPE			(38)	DESCRIPTION (39)																				
	0	0	0					Z					NA																			
7 8	9							11			12	13																				80

1 8	PERSONNEL INJURIES NUMBER						(40)	DESCRIPTION (41)																								
	0	0	0					NA																								
7 8	9							11			12																					80

1 9	LOSS OF OR DAMAGE TO FACILITY TYPE						(42)	DESCRIPTION (43)																								
	Z							NA																								
7 8	9							10																								80

2 0	PUBLICITY ISSUED						(44)	DESCRIPTION (45)																								
	N							NA																								
7 8	9							10																								80

NRC USE ONLY

8109290292 810918
PDR ADOCK 05000315
S PDR

NAME OF PREPARER R. A. PALMER PHONE: 616-465-5901

GPO 917-926